PHASE I ENVIRONMENTAL SITE ASSESSMENT

Belltown Tower
Seattle, Washington
King County Tax Parcel 0654000065

Project No. T-8819

Terra Associates, Inc.

Prepared for:

Cavatina GW
Krakow, Poland

November 1, 2022

TERRA ASSOCIATES, Inc.
Consultants in Geotechnical Engineering, Geology
and
Environmental Earth Sciences

November 1, 2022
Project No. T-8819

Mr. Michal Dzuida
Cavatina GW sp 2 o.o
Wielicka Street 2B
30-552 Krakow, Poland

Subject: Phase I Environmental Site Assessment
Belltown Tower
Seattle, Washington
King County Tax Parcel 0654000065

Dear Mr. Dzuida:

We have completed a Phase I Environmental Site Assessment (ESA) for the Belltown Tower project, located at 2729 2nd Avenue in Seattle, Washington. Our study found two Recognized Environmental Conditions (RECs) associated with the site.

The attached report describes our study in detail. We trust the information presented is sufficient for your current needs. If you have any questions or require additional information, please call.

Respectfully Submitted,
TERRA ASSOCIATES, INC.



Nicolas R. Hoffman L.G.
Senior Project Geologist

12220 113th Avenue NE, Ste. 130, Kirkland, Washington 98034
Phone (425) 821-7777 • Fax (425) 821-4334

TABLE OF CONTENTS

Page No.

1.0 Executive Summary 1
2.0 Introduction 1
2.1 Purpose 1
2.2 Scope of Work 3
2.3 Significant Assumptions 3
2.4 Special Terms and Conditions 3
2.5 Limitations 4
3.0 Site Conditions 4
3.1 Site Description 4
3.2 Adjacent Land Use 4
3.3 Soil Conditions 5
3.4 Hydrogeologic Conditions 5
4.0 Site History Research 5
4.1 Aerial Photography Review 5
4.2 Map Review 6
4.2.1 USGS Maps 6
4.2.2 Sanborn Maps 7
4.2.3 Government Land Office and Bureau of Land Management (BLM) Records 8
4.2.4 Commercial Real Estate Maps 8
4.3 City Directory Review 9
4.4 Tax Records 10
4.5 Title Review 11
4.6 Activity and Use Limitation 11
4.7 Interviews 11
4.7.1 User Questionnaire 11
4.7.2 Owner Interview 11
4.7.3 King Health District Records 11
4.7.4 City of Seattle 11
4.8 Previous Reports by Others 12
5.0 Regulatory Document Review 12
5.1 Federal Records 12
5.1.1 National Priority List (NPL or Superfund Sites) 12
5.1.2 Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS) and CERCLIS – No Further Action Planned (CERCLIS-NFRAP) 13
5.1.3 Resource Conservation Recovery Act Information System – Treatment, Storage, and Disposal (RCRA-TSD) 13
5.1.4 Resource Conservation Recovery Act (RCRA) – Generators 13
5.1.5 Emergency Response Notification System (ERNS) 14
5.1.6 US Brownfields 14
5.2 State Records 14
5.2.1 Confined or Suspected Contaminated Sites List (CSCSL) and CSCS No Further Action (NFA) 14
5.2.2 Solid Waste Facilities/Landfills (SWF/LF) 15
5.2.3 Underground Storage Tank (UST) List 15
5.2.4 Leaking Underground Storage Tank (LUST) List 16

TABLE OF CONTENTS

(Continued)

Page No.

6.0 Other Hazards 16
6.1 PCBs and Transformers 17
6.2 Onsite USTs/ASTs 17
6.3 Clandestine Drug Laboratories (CDL-Meth Labs) 17
6.4 Wells 17
6.5 Area-Wide Smelter Contamination 17
6.6 Vapor Migration 17
6.7 Property Valuation 17
7.0 Summary 18
7.1 Current Site Use 18
7.2 Historical Site Use 18
7.3 Offsite Parcels 18
7.4 Deviations (Data Gaps For This Study) 18
8.0 Conclusions 18
9.0 Qualifications/Statements 19
10.0 References 19
10.1 Documents and Publications 19
10.2 Websites 19

Figures

Vicinity Map ..... Figure 1
Topographic Vicinity Map ..... Figure 2
Vertical Aerial Photo ..... Figure 3
Site Photographs ..... Figures 4-6

Appendices

ERIS Fire Insurance Map Report ..... Appendix A
ERIS City Directory Report ..... Appendix B
Archived Taxes ..... Appendix C
Current Taxes ..... Appendix D
Title Documents ..... Appendix E
User Questionnaire ..... Appendix F
King County Records ..... Appendix G
City of Seattle Records ..... Appendix H
ERIS Database Report ..... Appendix I

Phase I Environmental Site Assessment
Belltown Tower
Seattle, Washington
King County Tax Parcel 0654000065

1.0 EXECUTIVE SUMMARY

This report presents the findings of our Phase I Environmental Site Assessment (ESA) of the Belltown Tower project located in Seattle, Washington. The site location is shown on Figures 1 through 3. This report was prepared in general accordance with American Society for Testing and Materials (ASTM) E-1527-2021.

The site consists of a single tax parcel totaling 0.30 acres. The parcel is currently developed with a single-story commercial building occupied by Lighting Supply. Tax records indicate the building was constructed in 1948.

Our study identified two Recognized Environmental Conditions (RECs) associated with the subject site:

- A dry-cleaning facility currently operates adjacent to the northwest side of Clay Street to the northwest of the subject site. City directory records indicate a dry cleaner has operated at this same location for about 40 years. Current and historic dry-cleaning activities on the adjacent parcel is an REC associated with the subject site.

- Historic maps and aerial photographs indicate that three small apartment buildings were present on the eastern portion of the subject site from at least 1905 to 1969. Oil burning furnaces were a common heat source for buildings in this time frame. Additionally, archived tax records and Sanborn maps indicate commercial printing operations historically occur. Halogenated solvents were commonly utilized in printing processes during this time-period. Historic site use is an REC for the subject site.

The following sections of this report present the details of our study.

2.0 INTRODUCTION

2.1 Purpose

American Society for Testing and Materials (ASTM) E-1527-21 states: “The purpose of this practice is to define good commercial and customary practice in the United States of America for conducting an environmental site assessment of a parcel of commercial real estate with respect to the range of contaminants within the scope of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) (42 U.S.C. §9601) and petroleum products. As such, this practice is intended to permit a user to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner, or bona fide prospective purchaser limitations on CERCLA liability (hereinafter, the “landowner liability protections,” or “LLPs”): that is, the practice that constitutes all appropriate inquiries into the previous ownership and uses of the property consistent with good commercial and customary practice as defined at 42 U.S.C. §9601(35)(B).

Controlled substances are not included within the scope of this standard. Persons conducting an environmental site assessment as part of an EPA Brownfields Assessment and Characterization Grant awarded under CERCLA 42 U.S.C. §9604(k)(2)(B) must include controlled substances as defined in the Controlled Substances Act (21 U.S.C. §802) within the scope of the assessment investigations to the extent directed in the terms and conditions of the specific grant or cooperative agreement. Additionally, an evaluation of business environmental risk associated with a parcel of commercial real estate may necessitate investigation beyond that identified in this practice." American Society for Testing and Materials (ASTM) E-1527-21 provides the following definitions for RECs in this practice.

RECs are defined as the presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: (1) due to release to the environment; (2) under conditions indicative of a release to the environment; or (3) under conditions that pose a material threat of a future release to the environment. De minimis conditions are not recognized environmental conditions.

Historical Recognized Environmental Conditions (HRECs) are defined as a past release of any hazardous substances or petroleum products that has occurred in connection with the property and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted use criteria established by a regulatory authority, without subjecting the property to any required controls (for example, property use restrictions, activity and use limitations, institutional controls, or engineering controls). Before calling the past release a REC, the Environmental Professional (EP) must determine whether the past release was a REC condition at the time the Phase I Environmental Site Assessment is conducted (for example, if there has been a change in the regulatory criteria). If the EP considers the past release to be a REC at the time the Phase I ESA is conducted, the condition shall be on the conclusions section of the report as a REC.

A de minimis condition is defined as a condition that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. Conditions determined to be de minimis conditions are not REC, nor controlled RECs.

A Controlled Recognized Environmental Condition (CREC) is defined as a REC resulting from a past release of hazardous substances or petroleum products addressed to the satisfaction of the applicable regulatory authority (for example, as evidenced by the issuance of a no further action letter or equivalent, or meeting risk-based criteria established by regulatory authority), with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls (for example, property use restrictions, activity and use limitations, institutional controls, or engineering controls). A condition considered by the EP to be a CREC shall be listed in the findings section of the Phase I ESA report, and as a REC in the conclusions section of the Phase I Environmental Site Assessment report.

A Business Environmental Risk (BER) is a risk which can have a material environmental or environmentally driven impacts on the business associated with the current or planned use of a parcel of commercial real estate, not necessarily limited to those environmental issues required to be investigated in this practice discussed above."

2.2 Scope of Work

Our scope of work for this project included:

- Review of geologic information from public sources.
- Review of a radius map report prepared by Environmental Risk Information Services (ERIS).
- Review of current online databases of environmental information maintained by the Washington State Department of Ecology (Ecology).
- Site reconnaissance to observe existing conditions and to review potential risks to the subject site from on and offsite activities.
- Review of Ecology's online well-log database for the site vicinity.
- Review of standard historical documents including tax assessor records for the site, fire insurance maps, real estate atlases, and aerial photographs of the area.
- Review of available current tax information for the subject site.
- Contacts with the local jurisdictions regarding environmental issues on the project.
- Preparation of this report.

We performed the research for this project and report in general accordance with ASTM Test Designation E-1527-21: *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process.*

2.3 Significant Assumptions

In the preparation of this report, it is assumed it will be used for due diligence purposes.

2.4 Special Terms and Conditions

Our work did not include non-scope elements, such as the following tasks:

- Wildlife assessments.
- Asbestos, radon, or lead paint sampling on the site.
- Wetlands evaluation.

2.5 Limitations

We conducted no testing for this report. The findings, conclusions, and recommendations presented in this report are based on our documented site observations, review of historical and regulatory information, interviews, and review of the referenced historic resources. Other information related to past site uses or current site conditions may exist. Our conclusions are based in part on information provided or prepared by others.

If the existing site uses change, or if further information on the site becomes available, Terra Associates, Inc. should review the information, as it may affect our conclusions.

We prepared our conclusions and recommendations in accordance with generally accepted professional engineering practices. We make no other warranty, either expressed, or implied. This report is the copyrighted property of Terra Associates, Inc. and is intended for specific application to the Belltown Tower project in Seattle, Washington. This report is for the exclusive use of Cavatina and their authorized representatives.

3.0 SITE CONDITIONS

3.1 Site Description

The site consists of one tax parcel totaling 0.30 acres, located at 2729– 2nd Avenue in Seattle, Washington. The site lies within the northwest quarter of Section 31, Township 25 North, Range 4 East of the Willamette Meridian of the Public Land Survey System (PLSS). The approximate location of the property is shown on Figures 1 and 2. Figure 3 is an oblique aerial photo showing the site. Typical site photos are shown on Figures 4 through 7.

The approximate northwest half of the site is covered with a single-story masonry building. A split-level basement is present on the south end of the building. The building is currently occupied by Lighting Supply, a lighting fixture supplier. The northern and northwest portions of the building interior are utilized as showroom and office space. The eastern portion of the building and southern basement space are utilized for storage of various lighting supplies. A small amount of household cleaning supplies is stored near the back entrance the building and adjacent to the bathroom. Several partially filled one gallon or less cans of paint are stored in the basement space. An approximately 2'X2' patch in the floor slab is present near the back entrance to the building. Additional floor patches were noted on the floor slab in the storage area in the eastern portion of the building.

The eastern half of the parcel is currently a gravel parking lot. The parking lot and adjacent site grades slope gently to the west-southwest.

We did not observe any unusual odors, staining, or distressed vegetation on or within the subject site. We did not observe any common indicators of USTs such as fill ports or vent lines.

3.2 Adjacent Land Use

The subject site is located within an area that is commercial/multi- family residential in nature. Figure 3 shows the site and the adjacent parcels. Adjacent property use is summarized in the following table:

North	2nd Avenue, Clay Street, Commercial multi-use mixed residential, Crescent Arms Dry Cleaners on 1st floor
East	Paved Parking, small single-story commercial building.
West	Clay Street, Commercial building, vacant.
South	Alleyway, vacant lot covered with concrete slab.

3.3 Soil Conditions

We reviewed the *Geologic map of Seattle – A Progress Report by K.G. Troost, D.B. Booth, A.P. Wisher, and S.A. Shimel, 2005*. The map shows the site as being mostly underlain by pre-Fraser glacial deposits (Qpf). The glacial unit is described as a very dense mixture of sand, gravel, and silt. The site lies within an area mapped as regraded land. The mapped geology is consistent with soils noted in the logs of recent geotechnical explorations by Geoengineers on the eastern portion of the subject site and logs of prior explorations by Terra Associates and others in the near vicinity.

3.4 Hydrogeologic Conditions

For the purpose of this study, it is reasonable to assume near-surface groundwater gradients are strongly controlled by topography and/or surface features. Based on available topographic information and our local experience, it appears that the direction of onsite shallow groundwater flow beneath the subject site is generally to the west-southwest toward Elliott Bay. Well logs in the vicinity of the site indicated groundwater is likely present at approximately 6-20 feet below site grades. Local variations in groundwater gradients will occur as a result of man-made features, such as drainage ditches, sewers, and roads. The topography of the area is shown on Figure 2.

4.0 SITE HISTORY RESEARCH

4.1 Aerial Photography Review

We reviewed historical aerial photographs of the site and vicinity online at the USGS, King County IMAP, Historic Photos (NETR website), and Google Earth. The aerial photos are vertical photos showing the footprints of the buildings and other details visible from that point of view. Dense forest cover can obscure small buildings such as houses and small outbuildings. The actual use of the buildings is usually not ascertainable from the photographs alone. Conclusions of the use of the buildings contained in the following description are based on research from other sources.

1936 The existing framework of roads is shown in the site vicinity. A small building consistent with a residence is shown on the northwest portion of the subject site. A small structure consistent with a detached garage is shown fronting the alleyway to the southwest. The site vicinity is developed with a mix of residential and commercial buildings.

1968 The existing commercial building on the northwest portion of the site is present. Three small apartment buildings are shown on the southeast portion of the site. Small buildings consistent with mixed-use residential and light commercial line the existing framework of roads in the site vicinity. A bulk fuel facility with several large above ground storage tanks is shown along the Elliot Bay waterfront about three blocks to the northwest of the subject site.

1972 Conditions on the subject site and vicinity resemble those shown on the 1968 photograph. The southwest of the three former apartments on the subject site is no longer present.

1975 Conditions shown on the subject site resemble those shown in the 1972 photo. The adjacent property to the northwest is a paved parking lot.

1980 Conditions shown on the subject site and vicinity resemble those shown on the 1975 photograph.

1990 Conditions shown on the subject site and vicinity resemble existing conditions. The existing building located on the adjacent northwest parcel is shown. A commercial building covers most of the adjacent site to the southwest.

1998 The picture quality is poor. Conditions shown on the subject site and vicinity resemble those shown on the 1990 photograph.

2002 Conditions shown on the subject site and vicinity resemble conditions shown on the 1998 photograph.

2005 Conditions shown on the subject site and vicinity resemble those shown on the 2002 photograph.

2010 Conditions shown on the subject site and vicinity resemble those shown on the 2005 photograph.

2015 The subject site and vicinity resemble existing conditions.

2021 The subject site and vicinity resemble existing conditions.

2022 The former building adjacent to the southwest of the site is undergoing demolition.

The aerial photographs did not present any information that contradicted other historical information we reviewed.

4.2 Map Review

4.2.1 USGS Maps

1895 Snohomish Quadrangle

The basic existing framework of roads in the site vicinity are shown. None of the roads are labeled. Most of the roads are lined with small buildings. A rail line is shown along the waterfront of Elliott Bay.

1897 Seattle Land Classification Sheet

The 1895 Snohomish quadrangle is the base image for the map. The basic existing framework of roads in the site vicinity are shown. None of the roads are labeled. Most of the roads are lined with small buildings. A rail line is shown along the waterfront of Elliott Bay.

1908 15 Minute Seattle Quadrangle

A small building is shown on the west side of the subject site. Small buildings are shown on the southwest and northeast margins of the block. Small buildings line most of the roads in the site vicinity.

1949 7.5 Minute Seattle South Quadrangle

No buildings or land use are shown on the subject site and immediate vicinity.

1968 7.5 Minute Seattle South Quadrangle

The base image is the 1949 map with photo revisions from 1968 shown in purple. The subject site and vicinity are shown within an area highlighted red, indicating that only landmark buildings are shown.

1973 7.5 Minute Seattle South Quadrangle

The base image is the 1949 map with photo revisions from 1968 and 1973 shown in purple. The subject site and vicinity are shown within an area highlighted red, indicating that only landmark buildings are shown. 2nd Avenue is shown in purple indicating regrading of the right of way may have occurred since 1968.

2011 7.5 Minute Seattle South Quadrangle

This map shows the existing framework of roads adjacent to and in the vicinity of the subject site.

2017 7.5 Minute Seattle South Quadrangle

This map shows the existing framework of roads adjacent to and in the vicinity of the subject site.

2020 7.5 Minute Seattle South Quadrangle

This map shows the same details as the previous map and shows the site and vicinity as they currently exist.

No potential items of environmental concern were noted in our review of available topographic maps for the subject site and vicinity.

4.2.2 Sanborn Maps

Sanborn Maps were created to aid in underwriting fire insurance policies in urbanized areas. The maps were generally updated until the 1960s. They typically show the types of buildings and their use for the areas of coverage. We have reviewed coverage for this area in the past. Rural areas were typically not mapped by the Sanborn Fire Insurance Company or other insurance agencies. We reviewed a Historic Fire Insurance Map report prepared by ERIS for the subject site and vicinity. The report found maps for the years 1888, 1893, 1905, 1949, 1950, and 1967. The ERIS report is attached as Appendix A. A brief description of conditions shown for each year is provided below:

1888: The existing framework of roads is shown in the immediate vicinity. Clay Street to the west is labeled *Cliff.* 1st Avenue to the south is labeled *Front.* The subject site is vacant. Three residences are shown on the adjacent parcels to the southeast. Two residences are shown on the adjacent block to the north. Several residences are shown on the surrounding blocks in the near vicinity.

1893: A residence is shown on the central portion of the subject site. Residences are still shown on the adjacent parcels to the east and the adjacent block to the north. The northeast quadrant of the block directly north of the subject site is labeled Empire Wood and Coal Yard. Clay Street is now labeled *Clay Street.*

1905: Three small buildings consistent with residential structures and one small structure consistent with a shed or garage are shown on the subject site. The northeast quadrant of the block directly north of the subject site is labeled *Wood Yard*. The blocks in the vicinity are becoming more developed with residences, a church, and a hospital.

1949: A building segmented in to four sections is shown on the northwest portion of the subject site. The building is segmented in to four sections. One of the sections is labeled *PRINT'G.* Two four unit apartments and one single unit apartment cover the eastern portion of the subject site. The adjacent building to the northwest is labeled as a restaurant. A small triangular parcel at the intersection of 3rd Street, Denny Street, and Broad Street is labeled *oils.* The wood yard noted in the prior maps is labeled *Feather Renovating.* An office building and associated parking labeled *Union Hall* is shown on the adjacent parcel to the south. A gasoline station is shown approximately one block west-southwest of the subject site. An auto repair shop is shown about one block east of the subject site.

1950: Conditions shown for the subject site and vicinity resemble those shown on the 1949 map.

1967: The existing commercial building and three former apartment buildings are shown on the subject site. The eastern two-thirds of the block directly north of the subject site is covered with a building labeled *K.I.R.O Radio and TV Station.* Conditions shown in the immediate vicinity resemble those shown on the 1949 and 1950 maps.

4.2.3 Government Land Office and Bureau of Land Management (BLM) Records

We reviewed the land records maintained by the Government Land Office. The area surrounding the parcel was originally surveyed by the U.S. Government in January 1856. No buildings or settlements are shown on the subject site and immediate vicinity. A road is shown connecting Lake Union to Elliot Bay. Three land claims are shown in the site vicinity. The subject site appears to be a portion of Bell's Claim with the Denny and Boren claims to the south.

The BLM land grant records show that the site is within large tracts of land originally granted to the Boren, Denny, and Bill families in 1866 and 1867.

4.2.4 Commercial Real Estate Maps

Real estate maps have been published for the greater Seattle Area for more than 100 years. They record subdivisions of land and were updated on a regular basis. For some years, the maps would show the type of building present on the parcel of land.

1907 Anderson Map Company

This map shows the subject site within a larger parcel of land labeled Bell and Dennys Additions. No roads, buildings, or land use are shown on or adjacent to the subject site.

1912 Kroll Map Company

This map shows the subject site as a portion of Section 31. No property lines, roads are shown. A post office is shown in the greater vicinity to the southeast.

1926 Kroll Map Company

This map shows the subject site within a broad area of downtown labeled *Business District.* The Bell, Denny, and Boren land claims are outlined in the site vicinity.

1936 Metsker Map Company

This map shows the existing framework of blocks and streets around the subject site and vicinity. No land use or ownership are shown for the subject site and adjacent properties.

4.3 City Directory Review

City Directories have listings by address of the persons or businesses that owned or leased properties within cities and towns. We reviewed the City Directory Report (CDR) provided by ERIS, dated October 1, 2022. The city directory report is Appendix B.

The report had listings for the site and vicinity for the years: 1928, 1934, 1939, 1942, 1946, 1950, 1956, 1960, 1965, 1970-1971, 1975, 1980-1981, 1984-1985, 1990, 1994, 2000, 2003 2008, 2012, 2016 and 2020. The subject site is listed under *Lighting Supply* between the years 1965-2020. Prior to the listing of Lighting Supply, the following tenants are listed: *Marchant Div of Smith* (1960)*, Corona Marchant* (1960), *Frank C. Leigh and Universal Tab Co.* (1956), *W.F. Heine Supply Co., metal moldings* (1950).

Listings of note on adjacent and near vicinity parcels are provided below:

2801 2nd Avenue-Adjacent parcel to northwest, northwest of Clay Street

1990-2016 Crescent Arms Dry Cleaners

1984 Fletchers Cleaners

2611 2nd Avenue-About 2 blocks southeast of the subject site

1928 LS Finch Chemical Co.

2603 2nd Avenue-About 2 blocks southeast of the subject site

1939-1956 Corl Chemical Co.

2503 2nd Avenue-Approximately three blocks southeast of the subject site

1960 Bud's Union Service

1956 Nick's Union Service

2324 2nd Avenue-Approximately 4 blocks southeast of the subject site

1950-1956 Master Auto Service

2nd and Wall-About 4 blocks southeast of the subject site

1950 Union Oil Service

The listing of a dry- cleaning service on the adjacent parcel to the northwest for over 30 year is an REC for the subject site.

Based on the status and distance from the site, and local hydrogeologic conditions, it is our opinion that the other listings of note in the city directory report are not REC's for the subject site.

4.4 Tax Records

4.4.1 Archived taxes

We reviewed available King County archived tax records for the subject site. The archived taxes for the subject site span from 1948 to 1996. Appendix C comprises the archived tax records for the subject site. The archived tax records for the site are summarized below:

The existing building was constructed in 1948. The first listed owner is Gibbs and Hudson in 1948. Heat is supplied to the building with a suspended gas system. A small room on the south side of the building is labeled *Printing* on the 1948 tax card. No other pertinent information was identified in the arched tax records.

4.4.2 Current Taxes

The current online tax records list the following ownership and information:

Current Owner	Site Address	Tax Parcel #	Size/Development
MGM Properties LLC	2729 2nd Avenue	065400-0065	0.3 Acres/Commercial service developed with 6,096 square foot masonry retail building constructed in 1948.

The archived and current tax record summary is attached in Appendix D.

4.5 Title Review

We reviewed a title report for the subject site prepared by Stewart Title dated August of 2022. No environmental covenants or restrictions were noted in the title documents. The title report is attached as Appendix E.

4.6 Activity and Use Limitation

Activity and Use Limitations (AULs) are commonly placed on sites that have undergone partial cleanups and have residual levels of contamination that remain in place. In the State of Washington, this is normally accomplished through the creation of a covenant that spells out the environmental issues and limitations onsite use. To review for the possible presence of AULs, we reviewed the current Environmental Covenant Registry maintained by Ecology. We also reviewed the King County Auditor's website for recorded documents that would address environmental covenants. No AULs were noted.

Our review of the Ecology records found no environmental covenants for the site.

4.7 Interviews

4.7.1 User Questionnaire

We received a completed user questionnaire. The questionnaire is attached in Appendix F. Nothing in the user questionnaire is considered to be a REC.

4.7.2 Owner Interview

On October 12, 2022, we interviewed Mr. Mark Munday, current owner of the subject site. Mr. Munday provided the following information regarding his knowledge of the subject site:

- The property was purchased from his family about 25-30 years ago.
- A lighting supply store has operated out of the existing building since the 1960's.
- He has a vague memory of an apartment building being demolished on the portion of the property currently utilized as a parking lot.
- They do not store or use any hazardous material onsite.
- He has no knowledge of past hazardous materials storage on the subject site.
- He is unaware of any underground storage tanks currently or historically being present on the subject site.
- Mr. Munday did not know the nature of the floor patch resembling an old floor drain on the southeast portion of the floor slab inside the building.

4.7.3 King County Health Department Records

We submitted a records request to King County Public Health on July 26, 2022. We requested documents that addressed past soil or hazardous waste releases or complaints, or of fuel releases. The county responded that our request had been received and that they expected to release records within 6-8 weeks from the time the request was received. Our correspondence with the health department is attached as Appendix G.

4.7.4 City of Seattle

We submitted a public records request to the City of Seattle online for the subject site. We received responsive records from the Fire Marshall's office and the DCI microfilm office. The documents are attached as Appendix H. We did not identify any RECs for the subject site in the responsive documents.

4.8 Previous Report by Others

We were not provided with any previous environmental reports for the subject site. No prior environmental reports for the subject site were identified during this assessment.

5.0 REGULATORY DOCUMENT REVIEW

We reviewed the database report prepared by Environmental Risk Information Services (ERIS), dated September 29, 2022. ERIS searches U.S. Environmental Protection Agency and Ecology databases for sites within a specified radius of a subject property that may pose a risk to that property.

The ERIS report contains reports from numerous databases maintained by Ecology. This includes general stormwater permits for temporary erosion control monitoring on construction projects. The general permits for offsite projects are not issues related to the subject property, nor are they a required database from the ASTM guidance. General stormwater permits are not discussed further in this report.

We evaluate relative elevations and locations of listed sites based on our site reconnaissance and review of relevant topographic and geologic maps. The center of the search radius is the approximate boundary of the property. The subject site is listed in the HMIRS database. The listing is related to a 0.125-gallon of an organic peroxide on the subject site. The report indicates that a hazmat team cleaned up the release. The listing is not considered an REC for the subject site.

The ERIS report is attached as Appendix I. The ERIS report is summarized below.

5.1 Federal Records

5.1.1 National Priority List (NPL or Superfund Sites)

Section 8.2.1 of the ASTM standards requires a review of federal and state lists of hazardous waste sites identified as NPL or Superfund sites within a one-mile radius of the subject property. The ERIS search found no NPL or Superfund sites within a one-mile radius of the boundaries of the subject site.

5.1.2 Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS) and CERCLIS – No Further Action Planned (CERCLIS-NFRAP)

Section 8.2.1 of the ASTM standards requires a review of federal and state lists of hazardous waste sites identified as CERCLIS sites within a half-mile radius of the subject property. The ERIS search found one CERCLIS and one CERCLIS-NFRAP sites within a half-mile radius of the boundaries of the subject site. The listing is the same for both databases. The site is summarized in the table below:

Site Name/Address	Location	Notes
Seattle Post Intelligencer 521 Wall Street Seattle, Washington 98121	About one-quarter mile northeast and cross-gradient of the subject site.	The site was suspected of having a release of halogenated solvents to groundwater. The site received an NFA from Ecology in 1995. The site is also in the VCP, LUST, CSCSL-NFA, ICR, and SEMS ARCHIVE databases.

Based on the status and distance from the site, and local hydrogeologic conditions, it is our opinion the CERCLIS and CERCLIS-NFRAP site is not an REC for the subject site.

5.1.3 Resource Conservation Recovery Act Information System – Treatment, Storage, and Disposal (RCRA-TSD)

Section 8.2.1 of the ASTM standards requires a review of RCRA Treatment, Storage, or Disposal (TSD) lists to a half-mile radius. The ERIS search found one RCRA-TSD site within a half-mile radius of the boundaries of the subject site.

Section 8.2.1 of the ASTM standards requires a review of RCRA TSD CORRACTS lists to a one-mile radius. CORRACTS sites are TSD facilities that have had violations in the past. The ERIS search found no CORRACTS sites within a one-mile radius of the boundaries of the subject site.

The RCRA TSD site is summarized below:

Site Name/Address	Location	Notes
BRE Properties 552 Denny Way and 553 John Street Seattle, Washington 98109	Approximately one-quarter mile northeast and up or cross-gradient of the	The site had a confirmed release of non-halogenated petroleum products to soil. A NFA letter from 2008 for the site is available on Ecology's website. The NFA letter does not discuss contaminates or the remedial effort that took place.

Based on the status and distance from the site, and local hydrogeologic conditions, it is our opinion that these RCRA and RCRA CORRACTS sites are not RECs for the site.

5.1.4 Resource Conservation Recovery Act (RCRA) – Generators

Section 8.2.1 of the ASTM standards requires a review of federal RCRA generators on the property and adjoining properties. The ERIS search found no RCRA generators on or adjacent to the site.

5.1.5 Emergency Response Notification System (ERNS)

Section 8.2.1 of the ASTM standards requires a review of federal ERNS listings on the property. The ERNS database stores information on reported releases of oil and hazardous substances. The ERIS search found ERNS ERNS sites on or adjacent to the site.

5.1.6 US Brownfields

The Brownfields database records and stores information on abandoned, idle, or underused commercial or industrial properties with confirmed and/or suspected contamination. The ERIS search found no US Brownfields site within a mile of the boundaries of the subject property.

5.2 State Records

5.2.1 Confirmed or Suspected Contaminated Sites List (CSCSL) and CSCSL No Further Action (NFA)

Section 8.2.1 of the ASTM standards requires a review of state lists of hazardous waste sites identified for investigation or remediation within a one-mile radius of the subject property. ERIS conducted a records search for listed CSCSL sites within a one-mile radius and for CSCSL – NFA sites within one half mile of the boundaries of the subject property. Within a one-mile radius of the boundaries of the site, 148 CSCSL sites are listed. The ERIS search found 38 CSCSL – NFA sites listed within a one-half mile radius of the boundaries of the site. The closest CSCL and CSCL – NFA sites are summarized in the table below:

Site Name/Address	Location	Notes
The Olympus 2801 Western Avenue Seattle, Washington 98121	About one-tenth mile southwest and down or cross-gradient of the subject site.	The site had a confirmed release to of petroleum products to site soil. The site received an NFA from Ecology in August of 2001. The site is also in the ICR, VCP, UST, and LUST databases.
Vine Building 2607 Western Avenue Seattle, Washington 98121	About one-tenth mile south and downgradient of the subject site.	The site had a confirmed release of petroleum to site soil related to a heating oil UST above applicable cleanup levels. The site received an NFA from Ecology in July of 2001. The site is also in the ICR and VCP databases.
Martin Selig Property 2601 4th Avenue Seatle, Washington 98121	About one-tenth mile NE and up or cross-gradient of the subject site.	The site has confirmed releases of petroleum products and non-halogenated solvents to both soil and groundwater related to past site use as a gasoline and service station. The site is listed as cleanup started.
Cottage Properties Vine Street Seattle, Washington 98121	About one-tenth mile southeast and down or cross-gradient of the subject site.	The site had a confirmed release of metals to site soil. The site received an NFA from Ecology in September of 2008.

Site Name/Address	Location	Notes
Sailors Union of the Pacific Building 2505 1st Avenue Seattle, Washington 98121	About one-ninth mile southeast and down or cross-gradient of the subject site.	The site had a confirmed release of petroleum products to site soil Related to a UST. The site received an NFA from Ecology in October of 2011. The site is also in the ICR, UST, and LUST databases.
Edwards on 5th 2619 5thAvenue Seattle, Washington 98121	About one-fifth mile northeast and up or cross-gradient of the subject site.	The site has a confirmed release of heating oil to site soils and groundwater, and impacts from a PCE plume from an upgradient site. RI reports available on Ecology's website indicate the plumes associated with the contaminates have not migrated to the subject site. The site is also in the HSL, ICR, and VCP databases.

Based on the status and distance from the site, and local hydrogeologic conditions, it is our opinion that these CSCSL and CSCL NFA sites are not RECs for the site.

5.2.2 Solid Waste Facilities/Landfills (SWF/LF)

Section 8.2.1 of the ASTM standards requires a review of state lists identifying landfill and solid waste disposal facilities within a half-mile radius of the subject property. Six active, abandoned, or inactive landfills was listed as being present within a half-mile radius of the boundaries of the site. The closes SWF/LF sites are summarized in the table below:

Site Name/Address	Location	Notes
Konankada Inc dba Seattle Micro 2310 4th Avenue Seattle, Washington 98121	About one-quarter mile east and cross-gradient of the subject site.	The site is listed as a non-regulated recycler. No other information is provided in the report.
Action Small Appliance 2125 2nd Avenue Seattle, Washington 98121	About two-fifths mile southeast and cross-gradient of the subject site.	The site is listed as a non-regulated recycler. No other information is provided in the report.

Based on the status and distance from the site, and local hydrogeologic conditions, it is our opinion that these SWF/LF sites are not RECs for the site.

5.2.3 Underground Storage Tank (UST) List

Section 8.2.1 of the ASTM standards requires a review of state UST lists for underground tanks listed on the subject site or adjoining properties. No UST's are listed as being present on or adjacent to the underlying tax parcels. Residential heating oil USTs are not registered with the State of Washington. Residential heating oil USTs are discussed in Section 6.2 of this report.

5.2.4 Leaking Underground Storage Tank (LUST) List

Section 8.2.1 of the ASTM standards requires a review of state LUST lists for possible contaminated sites within a half-mile radius of the subject property. Many LUST sites are listed under the Independent Cleanup Report (ICR) database or the Voluntary Cleanup Program (VCP) Database. Our search found 33 LUST sites within a one-half mile radius of the boundaries of the site. The closest LUST sites are summarized in the table below:

Site Name/Address	Location	Notes
The Olympus 2801 Western Avenue Seattle, Washington 98121	About one-tenth mile southwest and down or cross-gradient of the subject site.	The site is discussed above in Section 5.2.1 of this report.
Sailors Union of the Pacific Building 2505 1st Avenue Seattle, Washington 98121	About one-ninth mile southeast and down or cross-gradient of the subject site.	The site is discussed above in Section 5.2.1 of this report.
Northwest Protective Services 2700 Elliott Avenue Seattle, Washington 98121	About one-eighth mile southwest and down or cross-gradient of the subject site.	The site had confirmed releases of petroleum products and benzene to site soil. The site received an NFA from Ecology in October of 2011. The site is also in t he ICR, CSCSL-NFA, and UST databases.

Based on the status and distance from the site, and local hydrogeologic conditions, it is our opinion that these LUST sites are not RECs for the site.

5.2.5 SPILLS

Section 8.2.1 of the ASTM standards requires a review of federal ERNS listings on the property. The state SPILLS database stores information on reported releases of oil and hazardous substances equivalent to the ERNS database. The ERIS search found five SPILLS events on or adjacent to the site.

6.0 OTHER HAZARDS

6.1 PCBs and Transformers

Polychlorinated biphenyls (PCBs) are associated with electrical transformer fluids and ballasts in older fluorescent light fixtures. The use of PCBs in transformer fluids was discontinued in units manufactured after 1977. Transformers are the property of the local utility that is generally responsible for leakage or spills from the transformers. We did not observe any transformers on the subject site.

6.2 Onsite USTs/ASTs

We did not observe any evidence of USTs being present on the subject site during our site observations. No evidence of former UST/AST's on site was identified in our assessment.

6.3 Clandestine Drug Laboratories (CDL-Meth Labs)

We did not uncover any evidence indicating a clandestine drug laboratory has ever been present onsite, either during our site visit, interviews with contractors and site ownership, or reviews of current and historical documentation for the subject site. The King County public health data base of drug labs did not list the site or any nearby sites as being clandestine drug labs. The data base was last updated on September 30, 2022.

6.4 Wells

We reviewed the online well-log database on the Department of Ecology's website. No water wells are listed as being present within the boundaries of the subject site. Terra Associates installed 2 groundwater monitoring wells on the eastern portion of the adjacent southern parcel in 2008 as part of a geotechnical study. At that time groundwater was measured between 6-20 feet below existing site grades.

6.5 Area-Wide Smelter Contamination

We reviewed the current map from Ecology showing the extent of suspected and known impacts from the area-wide Tacoma Smelter Plume (TSP) and Everett Smelter projects. This parcel is shown within the distal plume of the Tacoma smelter. Arsenic and lead are predicted to be below state cleanup levels. Area-wide smelter contamination is not considered a REC for the subject site.

6.6 Vapor Migration

There are several known plumes of volatile organic compounds within one-quarter mile of the subject site. The site soils have a low permeability to both air and water. Based on their status and relative location to the subject site, we do not anticipate these sites have adversely affected the subject site. A dry-cleaning facility has operated on the adjacent northwest property for about 40 years. We did not identify any past assessments of the adjacent property in the course of our research. Current and historic dry-cleaning activities on the adjacent parcel is a REC associated with the subject site.

6.7 Property Valuation

Answers provided in the user questionnaire discussed in Section 4.7.1 above indicate the purchase price of the property is fair market value.

7.0 SUMMARY

7.1 Current Site Use

The site consists of one tax parcel. The parcel is developed with one commercial building and associated gravel parking. Based on the information summarized in this report, the current site use is not a REC.

7.2 Historical Site Use

The site has historically been residential and commercial. Three small apartment buildings were formerly present on the eastern portion of the parcel from approximately 1905 to 1969. It was typical during this time-period for small apartment buildings to be heated utilizing oil burning furnaces. Both the archived tax records and microfiche drawings have images labeling the southern portion of the existing building as *Printing.* Halogenated solvents were commonly utilized in printing processes during this time-period. Historic site use is a REC for the subject site.

7.3 Offsite Parcels

Our reconnaissance of the vicinity and the site indicates there is the potential for soil and/or groundwater contamination within a one-mile radius of the site. Potential impacts from the adjacent parcel to the northwest relating to historic use as a dry-cleaning facility is a REC for the subject site.

7.4 Deviations (Data Gaps For This Study)

There are no data gaps for this study.

8.0 CONCLUSIONS

We have performed a Phase I ESA in conformance with the scope and limitations of ASTM Practice E-1527-21, which satisfies all appropriate inquiry for purposes of 42 USC §960(35)(B) and 40 CFR Part 312, of the Belltown Tower project as described in the title report appended to this report. Any exceptions to, or deletions from, this practice are described in Section 7.4 of this report. Our study identified two Recognized Environmental Conditions (RECs) associated with the subject site:

- A dry-cleaning facility currently operates adjacent to the northwest side of Clay Street to the northwest of the subject site. City directory records indicate a dry cleaner has operated at this same location for about 40 years. Current and historic dry-cleaning activities on the adjacent parcel is a REC associated with the subject site.

- Historic maps and aerial photographs indicate that three small apartment buildings were present on the eastern portion of the subject site from at least 1905 to 1969. Oil burning furnaces were a common heat source for buildings in this time frame. Additionally, archived tax records and Sanborn maps indicate commercial printing operations historically occur. Halogenated solvents were commonly utilized in printing processes during this time-period. Historic site use is a REC for the subject site.

9.0 QUALIFICATIONS/STATEMENTS

I declare that, to the best of my professional knowledge and belief, I meet the definition of Environmental Professional as defined in §312.10 or 40 CFR Part 312.

I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. I have developed and performed all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR 312.

Project work was performed by Nicolas R. Hoffman. The following brief biography summarizes the experiences of Mr. Hoffman:

Nicolas R. Hoffman L.G., Senior Project Geologist, has 13 years of experience in the assessment of sites ranging from Phase I ESAs of rural-residential properties to remediation of parcels such as corner gasoline stations and former dry-cleaning facilities. Mr. Hoffman has more than 17 years of experience performing hydrogeologic and engineering geologic field assessments of sites ranging from large rural tracts to downtown urban properties. His project work has included detailed reviews of historical records, aerial photograph interpretation, geophysical surveys, monitoring well installation, and sampling aquifer testing. Mr. Hoffman has a Bachelor of Science in Geology and is a licensed Geologist in the States of Washington and Oregon. He previously worked as an intern in the Earthquake and Volcano Hazards program at the U.S. Geological Survey. Mr. Hoffman is a certified Asbestos Building Inspector and UST Site Assessor.

10.0 REFERENCES

10.1 Documents and Publications

American Society for Testing and Materials (ASTM). 2021. *E-1527-21 Standard Practice for Environmental Site Assessments – Phase I Environmental Site Assessment Process.*

Environmental Risk Information Services (ERIS). September 29, 2022. *Database Report: prepared for Terra Associates, Inc.*

10.2 Websites

Google Earth, accessed on October 11, 2022.

King County Assessor Office Property Map Viewer, accessed on June 20, 2022.
https://blue.kingcounty.com/Assessor/eRealProperty/default.aspx

USGS Earth Explorer, accessed October 2, 2022.
https://earthexplorer.usgs.gov/

USGS TopoView, accessed on October 2, 2022.
https://ngmdb.usgs.gov/topoview/viewer/#15/47.5648/-122.3454

GLO Land Patents, accessed on October 22, 2022.
https://glorecords.blm.gov/results/default.aspx?

BLM/GLO Land Records, accessed on October 21, 2022.
https://www.blm.gov/or/landrecords/survey/

Historic Aerials (NETR), accessed on October 1, 2022.
https://www.historicaerials.com/viewer

Historic Mapworks, accessed on October 1, 2022.
http://www.historicalmapworks.com/Browse/Maps/


Washington State Department of Ecology Well Log Data Base, accessed on October 20, 2022.
https://appswr.ecology.wa.gov/wellconstruction/map/WCLSWebMap/WellConstructionMapSearch.aspx

Washington State Department of Ecology Cleanup Site Summary, accessed on October 17, 2022.
https://apps.ecology.wa.gov/neighborhood/

Washington State Department of Ecology, Environmental Covenants Registry, accessed on October 3 2022.
https://fortress.wa.gov/ecy/tcpwebreporting

Washington State Department of Ecology Everett and Tacoma Smelter Search, accessed on October 5, 2022.
https://apps.ecology.wa.gov/dirtalert/

USGS National Geologic Map Database, accessed October 7, 2022.
https://ngmdb.usgs.gov/mapview/?center=-122.335,47.559&zoom=15



Base Image: Bing Maps image dated 2022.

TERRA ASSOCIATES
Geotechnical Consultants

SITE VICINITY MAP
BELLTOWN TOWER
SEATTLE, WASHINGTON

Proj. No T-8819	Date OCT 2022	Figure 1



Base Image: USGS 7.5 Minute Series Topographic Maps of the Seattle North and South Quadrangles (2020).

TERRA ASSOCIATES
Geotechnical Consultants

TOPOGRAPHIC VICINITY MAP
BELLTOWN TOWER
SEATTLE, WASHINGTON

Proj. No T-8819	Date OCT 2022	Figure 2



Base Image: Pictometry Online Photograph dated July 2021.

TERRA ASSOCIATES
Geotechnical Consultants

OBLIQUE AERIAL PHOTOGRAPH
BELLTOWN TOWER
SEATTLE, WASHINGTON

Proj. No T-8819	Date OCT 2022	Figure 3



East side of site viewed looking from the south.



North end of site viewed looking to the south.

TERRA ASSOCIATES
Geotechnical Consultants

SITE PHOTOGRAPHS
BELLTOWN TOWER
SEATTLE, WASHINGTON

Proj. No T-8819	Date OCT 2022	Figure 4



Typical interior storage in the east portion of the building.



Floor patch at south end of building near south entrance.

TERRA ASSOCIATES
Geotechnical Consultants

SITE PHOTOGRAPHS
BELLTOWN TOWER
SEATTLE, WASHINGTON

Proj. No T-8819	Date OCT 2022	Figure 5



Typical paint storage in the southern basement portion of building.

APPENDIX A

ERIS HISTORIC FIRE INSURANCE MAP REPORT

APPENDIX B

FIRE INSURANCE MAPS

Project Property:	Belltown Tower Belltown Tower Seattle WA 98121
Project No:	8819
Requested By:	Terra-Associates, Inc.
Order No:	22092804724
Date Completed:	September 29, 2022


Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Listed below, please find the results of our search for historic fire insurance maps from our in-house collection, performed in conjuction with your ERIS report.

Date	City	State	Volume	Sheet Number(s)
1969	Seattle	Washington	2	125, 126, 131, 132, 217, 218
1950	Seattle	Washington	2	125, 126, 131, 132, 217, 218
1949	Seattle	Washington	2	125, 126, 131, 132, 217, 218
1905	Seattle	Washington	2	125, 126, 131, 132, 217, 218
1893	Seattle	Washington	2	61, 62, 63
1888	Seattle	Washington		26, 28, 29


Individual Fire Insurance Maps for the subject property and/or adjacent sites are included with the ERIS environmental database report to be used for research purposes only and cannot be resold for any other commercial uses other than for use in a Phase I environmental assessment.

Fire Insurance Map



1969

Address: Belltown Tower Seattle WA 98121



Map sheet(s):
Volume 2: 125,126,131,132,217,218;

N


0 87.5 175 350 525 700

Feet

Order Number 22092804724


ERIS

Fire Insurance Map



1950

Address: Belltown Tower Seattle WA 98121



Map sheet(s):
Volume 2: 125,126,131,132,217,218;

N


0 87.5 175 350 525 700

Feet

Order Number 22092804724


ERIS

Fire Insurance Map



1949

Address: Belltown Tower Seattle WA 98121



Map sheet(s):
Volume 2: 125,126,131,132,217,218;


N

0 87.5 175 350 525 700
Feet


Order Number 22092804724

ERIS

Fire Insurance Map




Fire Insurance Map



1893

Address: Belltown Tower Seattle WA 98121



Map sheet(s):
Volume 2: 61,62,63;

N


0 87.5 175 350 525 700

Feet

Order Number 22092804724


ERIS

Fire Insurance Map



1888

Address: Belltown Tower Seattle WA 98121



Map sheet(s):
Volume NA: 26,28,29;

N

0 87.5 175 350 525 700
Feet

Order Number 22092804724

ERIS

ERIS CITY DIRECTORY REPORT

ERIS

CITY
DIRECTORY

Project Property:	*Belltown Tower* *Belltown Tower* *Seattle,WA 98121*
Project No:	*8819*
Requested By:	*Terra-Associates, Inc.*
Order No:	*22092804724*
Date Completed:	*October 01, 2022*

Environmental Risk Information Services
A division of Glacier Media Inc.

October 01, 2022
RE: CITY DIRECTORY RESEARCH
Belltown Tower
Seattle,WA 98121

Thank you for contacting ERIS for an City Directory Search for the site described above. Our staff has conducted a reverse listing City Directory search to determine prior occupants of the subject site and adjacent properties. We have provided the nearest addresses(s) when adjacent addresses are not listed. If we have searched a range of addresses, all addresses in that range found in the Directory are included.

Note: Reverse Listing Directories generally are focused on more highly developed areas. Newly developed areas may be covered in the more recent years, but the older directories will tend to cover only the "central" parts of the city. To complete the search, we have either utilized the ACPL, Library of Congress, State Archives, and/or a regional library or history center as well as multiple digitized directories. These do not claim to be a complete collection of all reverse listing city directories produced.

ERIS has made every effort to provide accurate and complete information but shall not be held liable for missing, incomplete or inaccurate information. To complete this search we used the general range(s) below to search for relevant findings. If you believe there are additional addresses or streets that require searching please contact us at 866-517-5204.

Search Criteria:
2600-END of 2nd Ave
ALL of Clay St
Search Notes:

Search Results Summary

Date	Source	Comment
2020	DIGITAL BUSINESS DIRECTORY	
2016	DIGITAL BUSINESS DIRECTORY	
2012	DIGITAL BUSINESS DIRECTORY	
2008	DIGITAL BUSINESS DIRECTORY	
2003	DIGITAL BUSINESS DIRECTORY	
2000	DIGITAL BUSINESS DIRECTORY	
1994	COLE	
1990	COLE	
1984-85	COLE	
1980-81	COLE	
1975	COLE	
1970-71	COLE	
1965	PACIFIC NORTHWEST BELL	
1960	PACIFIC TELEPHONE	
1956	PACIFIC TELEPHONE	
1950	PACIFIC TELEPHONE	
1946	PACIFIC TELEPHONE	
1942	PACIFIC TELEPHONE	
1939	POLKS	
1934	STREET ADDRESS DIRECTORY	
1928	STREET ADDRESS DIRECTORY	

327 total records. Part 1 of 5

2600 **ACHAL KAPOOR**...*RESIDENTIAL*
2600 **ALICE PICHT**...*RESIDENTIAL*
2600 **ANDERSEN SANDRA**...*RESIDENTIAL*
2600 **ANDREW MALM**...*RESIDENTIAL*
2600 **ANGELL THOMPSON**...*RESIDENTIAL*
2600 **ANJU NUNDY**...*RESIDENTIAL*
2600 **ANN WITTKOWSKY**...*RESIDENTIAL*
2600 **AVIV ROM**...*RESIDENTIAL*
2600 **BETTY KNUDSON**...*RESIDENTIAL*
2600 **BRIAN NASH**...*RESIDENTIAL*
2600 **CARMEN ORANGE**...*RESIDENTIAL*
2600 **CAROL ABODEELY**...*RESIDENTIAL*
2600 **CATHERINE HALL**...*RESIDENTIAL*
2600 **CHRIS BOSCH**...*RESIDENTIAL*
2600 **CHRIS CRAIG**...*RESIDENTIAL*
2600 **CHRISTOPHER RAMSEY**...*RESIDENTIAL*
2600 **COLLEEN DINKEL**...*RESIDENTIAL*
2600 **DAN PAZ**...*RESIDENTIAL*
2600 **DEONNE MILLER**...*RESIDENTIAL*
2600 **DOUGLAS DAVI ANDERSON**...*RESIDENTIAL*
2600 **ELIZABETH LOCATELL**...*RESIDENTIAL*
2600 **ELIZABETH SATO**...*RESIDENTIAL*
2600 **ELLA SONNENBERG**...*RESIDENTIAL*
2600 **EUNICE CHAN**...*RESIDENTIAL*
2600 **EYRING ASSOC**...*NONCLASSIFIED ESTABLISHMENTS*
2600 **FAITH PLASS**...*RESIDENTIAL*
2600 **FRANCES WU**...*RESIDENTIAL*
2600 **GABA, DAVID**...*OFFICES OF LAWYERS*
2600 **GAIL JOHNSTON**...*RESIDENTIAL*
2600 **GARY DOUSSON**...*RESIDENTIAL*
2600 **GARY TABASINSKE**...*RESIDENTIAL*
2600 **GAY GIBSON**...*RESIDENTIAL*
2600 **HARDIK DOSHI**...*RESIDENTIAL*
2600 **HOWARD MEEKS**...*RESIDENTIAL*
2600 **JAMES KEMPER**...*RESIDENTIAL*
2600 **JAMIE YAUCH**...*RESIDENTIAL*
2600 **JANET GALER**...*RESIDENTIAL*
2600 **JEH WANG**...*RESIDENTIAL*
2600 **JENNIFER ALLEY**...*RESIDENTIAL*
2600 **JERRI LAYMAN**...*RESIDENTIAL*
2600 **JESSICA TONANI**...*RESIDENTIAL*
2600 **JOHN NELSON**...*RESIDENTIAL*
2600 **JOHN RUDOLF**...*RESIDENTIAL*
2600 **JULIUS SINKEVICIUS**...*RESIDENTIAL*
2600 **KAREN FELTON**...*RESIDENTIAL*
2600 **KAREN TORELLI**...*RESIDENTIAL*
2600 **KATHLEEN STILINOVIC**...*RESIDENTIAL*
2600 **KATIE URSINO**...*RESIDENTIAL*
2600 **KATY BUTLER**...*RESIDENTIAL*
2600 **KEN LENHARDT**...*RESIDENTIAL*
2600 **KEREM KARADAYI**...*RESIDENTIAL*
2600 **KEVIN JONES**...*RESIDENTIAL*
2600 **KOHJI KAMIYA**...*RESIDENTIAL*
2600 **KRISHNA MENON**...*RESIDENTIAL*
2600 **LAURIE GRIFFITH**...*RESIDENTIAL*
2600 **LINDSAY OBERTO**...*RESIDENTIAL*
2600 **LOIS LEE**...*RESIDENTIAL*
2600 **LORIS VALEROS**...*RESIDENTIAL*
2600 **LYNN VANLIEROP**...*RESIDENTIAL*
2600 **MAN LAU**...*RESIDENTIAL*
2600 **MARILYN WIDLAN**...*RESIDENTIAL*
2600 **MARK GWYTHER**...*RESIDENTIAL*
2600 **MARK LONG**...*RESIDENTIAL*
2600 **MERLE SHERMAN**...*RESIDENTIAL*
2600 **MICHAEL LOCATELL**...*RESIDENTIAL*
2600 **NADINE LAPIRA-WOLOS**...*RESIDENTIAL*
2600 **NANCY GROTE**...*RESIDENTIAL*
2600 **NICHOLAS NOH**...*RESIDENTIAL*

2020 2ND AVE
SOURCE: DIGITAL BUSINESS DIRECTORY

Part 2 of 5

2600 **NORA TABLER**...*RESIDENTIAL*
2600 **OPEN ORGANIZATION**...*CHURCHES*
2600 **PAMELA FUKAI**...*RESIDENTIAL*
2600 **PAUL OKER**...*RESIDENTIAL*
2600 **PAUL ONAKOYA**...*RESIDENTIAL*
2600 **PAULINE DEHART**...*RESIDENTIAL*
2600 **PETER WIELAND**...*RESIDENTIAL*
2600 **PRECISION GLOBAL HEALTH**...*HEALTH SERVICES*
2600 **RANDALL PROSISE**...*RESIDENTIAL*
2600 **RICHANNE OLSON**...*RESIDENTIAL*
2600 **ROBERT DOUROUX**...*RESIDENTIAL*
2600 **RONALD HOLDEN**...*RESIDENTIAL*
2600 **RUMIO TAKAGI**...*RESIDENTIAL*
2600 **SAMANTHA SHERMAN**...*RESIDENTIAL*
2600 **SEATTLE HEIGHTS CONDO OWNERS**...*CONDOMINIUMS*
2600 **SHELDON WIDLAN**...*RESIDENTIAL*
2600 **SOOJIN KIM**...*RESIDENTIAL*
2600 **STEVE SCHWEICKERT**...*RESIDENTIAL*
2600 **STEVEN BROWN**...*RESIDENTIAL*
2600 **SUE PARTRIDGE**...*RESIDENTIAL*
2600 **THOMAS RILEY**...*RESIDENTIAL*
2600 **TIMOTHY CHAN**...*RESIDENTIAL*
2600 **TOM THOMAS**...*RESIDENTIAL*
2600 **TORSTEN REINL**...*RESIDENTIAL*
2600 **VERA KOCH**...*RESIDENTIAL*
2600 **VERONICA LUONGO**...*RESIDENTIAL*
2600 **VLADIMIR EREMENKOV**...*RESIDENTIAL*
2600 **XIN LI**...*RESIDENTIAL*
2602 **ANTOINE SAMPLE**...*RESIDENTIAL*
2602 **AXTION CLUB**...*CLUBS*
2602 **INTERNATIONAL KITCHENS**...*KITCHEN CABINETS & EQUIPMENT-HOUSEHOLD*
2606 **ARTITRON LLC**...*WEBSITE DESIGN SERVICE*
2606 **ESCALATED MARKETING CONSLTNG**...*MARKETING CONSULTANTS*
2606 **ESCALATED MARKETING CONSLTNG**...*MARKETING CONSULTING SERVICES*
2606 **FOLIA**...*NONCLASSIFIED ESTABLISHMENTS*
2606 **HOME OFFICE**...*OFFICE SUPPLIES*
2606 **INTERPERSONAL SKILL COACHING**...*NONCLASSIFIED ESTABLISHMENTS*
2606 **N W FURNITURE RESOURCE**...*FURNITURE-DEALERS-RETAIL*
2606 **RUSSELL HUSTON**...*NONCLASSIFIED ESTABLISHMENTS*
2606 **STORBINS TECHNOLOGY INC**...*MOVERS*
2606 **STORBINS TECHNOLOGY INC**...*STORAGE-HOUSEHOLD & COMMERCIAL*
2606 **STUDIO GIOIA**...*NONCLASSIFIED ESTABLISHMENTS*
2606 **WORK WELL WITH OTHERS**...*CONSULTANTS-BUSINESS NEC*
2607 **BROOK II LLC**...*REAL ESTATE*
2607 **EVERYMOVE INC**...*NONCLASSIFIED ESTABLISHMENTS*
2607 **THIRD & WALL ART GROUP LLC**...*ART GALLERIES & DEALERS*
2607 **YEAR UP**...*SOCIAL SERVICE & WELFARE ORGANIZATIONS*
2608 **24 HOUR LOCKSMITH**...*TAXICABS & TRANSPORTATION SERVICE*
2608 **24 HOUR LOCKSMITH**...*LOCKS & LOCKSMITHS*
2608 **A FIRST IMPRESSION LIMOUSINE**...*LIMOUSINE SERVICE*
2608 **BCI CORP**...*NONCLASSIFIED ESTABLISHMENTS*
2608 **BELLTOWN COMMUNITY COUNCIL**...*NONCLASSIFIED ESTABLISHMENTS*
2608 **BLACK OPAL VENTURES LLC**...*EVENTS-SPECIAL*
2608 **CAR ADVISORY NETWORK INC**...*DATA PROCESSING, HOSTING & RELATED SERVICES*
2608 **CONCIERGE CARE ADVISORS**...*SENIOR CITIZENS SERVICE*
2608 **CRTV VENTURE**...*NONCLASSIFIED ESTABLISHMENTS*
2608 **FOCUS CLEANING SVC**...*CLEANERS*
2608 **FOOD THERAPY**...*NONCLASSIFIED ESTABLISHMENTS*
2608 **HARRIETTE KANE**...*RESIDENTIAL*
2608 **KELLY READE**...*RESIDENTIAL*
2608 **MORGAN MARKETING SYSTEMS**...*MARKETING PROGRAMS & SERVICES*
2608 **RELIABLE MOVING**...*MOVERS*
2608 **SEATTLE GLEE CLUBS**...*CLUBS*
2608 **SEATTLE GUTTER-PRESSURE WSHNG**...*NONCLASSIFIED ESTABLISHMENTS*
2608 **SEATTLE SEO CONSULTANT**...*ADVERTISING MARKETING*

Part 3 of 5

2608 STEM PATHS INNOVATION NETWORK...NONCLASSIFIED ESTABLISHMENTS
2608 STRONG PAINTING & CARPENTRY...PAINTERS
2608 STRONG PAINTING & CARPENTRY...CARPENTERS
2608 VIEOSOFT...NONCLASSIFIED ESTABLISHMENTS
2608 WHALE BONE PRODUCTIONS...NONCLASSIFIED ESTABLISHMENTS
2609 PARADISO MECHANICAL LLC...PLUMBING CONTRACTORS
2616 TANDOORI HUT...RESTAURANTS
2618 REAL PROPERTY INVESTORS LLC...REAL ESTATE INVESTMENTS
2620 PACIFIC FACILITY SVC LLC...LANDSCAPE DESIGNERS
2620 ROOSEVELT SQUARE...MISCELLANEOUS PERSONAL SERVICES NEC
2620 TRF PACIFIC LLC...REAL ESTATE MANAGEMENT
2620 TRF PACIFIC LLC...REAL ESTATE
2621 ALBERT BERGER...RESIDENTIAL
2621 ANNE FOCKE...RESIDENTIAL
2621 ATROCIOUS RECORDS...BUSINESS RECORDS & DOCUMENTS-STORAGE
2621 CAROL BAILEY...RESIDENTIAL
2621 CHRIS RIGOS...RESIDENTIAL
2621 CHRISTINE JANIKOWSKI...RESIDENTIAL
2621 COREY SCANLON...RESIDENTIAL
2621 DAVID MORRIS...RESIDENTIAL
2621 EAGLE ROCK VENTURES LLC...OFFICES OF REAL ESTATE AGENTS & BROKERS
2621 ERIC GOEHLE...RESIDENTIAL
2621 ERIC NEWELL...RESIDENTIAL
2621 FRED DRUMMOND...RESIDENTIAL
2621 GEORGE LEMONNIER...RESIDENTIAL
2621 HARBOUR HEIGHTS HOA...CONDOMINIUMS
2621 JANELLE KINGSLEY...RESIDENTIAL
2621 JENA THORNTON...RESIDENTIAL
2621 JENNIFER KILDUFF...RESIDENTIAL
2621 JILL DEVINE...RESIDENTIAL
2621 JOHN CONNORS...RESIDENTIAL
2621 JUSTIN BERNIER...RESIDENTIAL
2621 KATHLYN MARRONE...RESIDENTIAL
2621 LAWRENCE OBERTO...RESIDENTIAL
2621 LEONA DOLAN...RESIDENTIAL
2621 LOREN MELL...RESIDENTIAL
2621 MARIANN ROBINSON...RESIDENTIAL
2621 MARIBEL FIGUERA...RESIDENTIAL
2621 MARICEL BALADAD...RESIDENTIAL
2621 NINA NOLAN...RESIDENTIAL
2621 PAULA HOLMES...RESIDENTIAL
2621 REIKO MANAKA...RESIDENTIAL
2621 ROBERT BUKOWSKI...RESIDENTIAL
2621 ROBERT KOEHLER...RESIDENTIAL
2621 ROBINSON, MARIANNE...PSYCHOANALYSTS
2621 RYAN WHITE...RESIDENTIAL
2621 SCOTT SHAPIRO...RESIDENTIAL
2621 SEATTLE MAYTAG REPAIR...APPLIANCES-HOUSEHOLD-MAJOR-REPAIRING
2621 SHELBY PATIENT...RESIDENTIAL
2621 SQUEEGEE CONSTRUCTION CLEANUP...FEDERAL GOVERNMENT CONTRACTORS
2621 SQUEEGEE CONSTRUCTION CLEANUP...JANITOR SERVICE
2621 STEPHEN DUNCAN...RESIDENTIAL
2621 THERESA SLECHTA...RESIDENTIAL
2621 VALENTINA ZASLAVSKY...RESIDENTIAL
2621 WILLIAM CALDERHEAD...RESIDENTIAL
2621 WILLIAM FARLEY...RESIDENTIAL
2623 INTERPACIFIC INVESTORS SVC INC...CONSTRUCTION COMPANIES
2623 INTERPACIFIC INVESTORS SVC INC...STOCK & BOND BROKERS
2623 INTERPACIFIC INVESTORS SVC INC...FEDERAL GOVERNMENT CONTRACTORS
2623 INTERPACIFIC INVESTORS SVC INC...FINANCIAL ADVISORY SERVICES
2701 EASTERN MERCHANDISE CO...JEWELERS-WHOLESALE
2701 EASTERN MERCHANDISE CO...IMPORTERS (WHLS)
2701 EASTERN MERCHANDISE CO...JEWELRY-MANUFACTURERS
2729 LIGHTING SUPPLY INC...LIGHT BULBS & TUBES (WHLS)
2729 LIGHTING SUPPLY INC...TANNING SALONS EQUIP & SUPPLIESWHLS

2020 2ND AVE
SOURCE: DIGITAL BUSINESS DIRECTORY

Part 4 of 5

2815 ABIERTO Y A MENUDO...NON-PROFIT ORGANIZATIONS
2815 AMALGAMATED TRANSIT UNION...NON-PROFIT ORGANIZATIONS
2815 AMALGAMATED TRANSIT UNION...ASSOCIATIONS
2815 AMALGAMATED TRANSIT UNION...LABOR ORGANIZATIONS
2815 AMERICAN FINANCIAL SOLUTIONS...CREDIT & DEBT COUNSELING SERVICES
2815 AMERICAN FINANCIAL SOLUTIONS...FINANCIAL ADVISORY SERVICES
2815 BAY VISTA...NONCLASSIFIED ESTABLISHMENTS
2815 BOARD OF INDL INS APPEALS...INSURANCE
2815 CLEANWORKFORCE.COM...ADVERTISING-COMPUTER
2815 CLOUDENTITY...SECURITY SYSTEMS
2815 COMMITTEE FOR CHILDREN...FEDERAL GOVERNMENT CONTRACTORS
2815 COMMITTEE FOR CHILDREN...ASSOCIATIONS
2815 COMMITTEE FOR CHILDREN...EDUCATIONAL SERVICE-BUSINESS
2815 DEX ONE...ADVERTISING-DIRECTORY & GUIDE
2815 INDUSTRIAL INSURANCE APPEALS...EMPLOYMENT AGENCIES & OPPORTUNITIES
2815 INDUSTRIAL INSURANCE APPEALS...GOVERNMENT OFFICES-STATE
2815 INDUSTRIAL INSURANCE APPEALS...STATE GOVERNMENT-LICENSING & INSPECTION
2815 INDUSTRIAL INSURANCE APPEALS...ENGINEERSAERONAUTICAL
2815 KKMO...RADIO STATIONS & BROADCASTING COMPANIES
2815 NORTH SEATTLE CMNTY CLG FNDTN...FOUNDATION-EDUC PHILANTHROPIC RESEARCH
2815 NORTH SEATTLE CMNTY CLG FNDTN...NON-PROFIT ORGANIZATIONS
2815 NORTHWEST MARINE RETIRE TRUST...MARINE EQUIPMENT & SUPPLIES
2815 PRINCESS CRUISES TOURS...TOURS-OPERATORS & PROMOTERS
2815 PUCHANT SOUND CREDIT UNION...CREDIT UNIONS
2815 SALEM COMMUNICATIONS CORP...FEDERAL GOVERNMENT CONTRACTORS
2815 SALEM COMMUNICATIONS CORP...RADIO STATIONS & BROADCASTING COMPANIES
2815 SATORI SOFTWARE...ELECTRONIC STORES
2815 SATORI SOFTWARE...DATA PROCESSING SOFTWARE
2815 SEATTLE CUSTOM FRAMING LLC...PICTURE FRAMES-DEALERS
2815 SPECIAL OLYMPICS WASHINGTON...NON-PROFIT ORGANIZATIONS
2815 STEPHERSON ASSOC COMMS INC...COMMUNICATIONS SERVICES NEC
2815 TEAM SOAPBOX...COMMUNICATIONS
2815 US EQUAL EMPLOYMENT OPPORTUNTY...GOVERNMENT OFFICES-US
2815 VOTIV...FILM STUDIO PRODUCTION FACILITIES
2815 WELFARE PENSION ADMIN...PENSION & PROFIT SHARING PLANS
2815 WPAS INC...INSURANCE ADJUSTERS
2815 WPAS INC...EMPLOYEE BENEFIT & COMPENSATION PLANS
2819 WORLD CUP COFFEE...RESTAURANTS
2821 BAY VISTA TOWER CONDOMINIUMS...CONDOMINIUMS
2821 BAY VISTA TOWER CONDOMINIUMS...REAL ESTATE BUYERS & BROKERS
2821 BEGINNINGS GUIDES...MEDICAL INFORMATION SERVICES
2821 BRAZIER LUMBER CO INC...SAWMILLS & PLANING MILLS-GENERAL (MFRS)
2821 CENTER FOR HEALTH LITERACY...HEALTH SERVICES
2821 CENTER FOR HEALTH LITERACY...PROMOTIONS & FUND RAISING
2821 CILLY KAMINOFF...RESIDENTIAL
2821 CRETE CONSULTING INC...BUSINESS MANAGEMENT CONSULTANTS
2821 DAHLI BENNETT...RESIDENTIAL
2821 DALE BLOOMQUIST...RESIDENTIAL
2821 DANIEL SADLER...RESIDENTIAL
2821 DAVID MATTSON...RESIDENTIAL
2821 EPIMETRICS GROUP LLC...NONCLASSIFIED ESTABLISHMENTS
2821 EUGENE KELLER...RESIDENTIAL
2821 GRETCHE MUELLER...RESIDENTIAL
2821 INA JOSEPHSON...RESIDENTIAL
2821 JAN SCHOLTE...RESIDENTIAL
2821 KRISTIN RICH...RESIDENTIAL
2821 LARRY SMITH...RESIDENTIAL
2821 LUCINDA KELLY...RESIDENTIAL
2821 LYNNE DODSON...RESIDENTIAL
2821 PIPER HUGHES...RESIDENTIAL
2821 SABOL, JOHN...FEDERAL GOVERNMENT CONTRACTORS
2821 SABOL, JOHN...ARCHAEOLOGISTS
2821 SAMUEL SELINGER...RESIDENTIAL
2821 SHELL...SERVICE STATIONS-GASOLINE & OIL

2020 2ND AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

Part 5 of 5

2821 **SIGEKI STAHL**...*RESIDENTIAL*
2821 **SUSAN SHELDON**...*RESIDENTIAL*
2821 **TIMOTHY O DONOVAN**...*RESIDENTIAL*
2827 **COMPUTER CARE**...*COMPUTER & EQUIPMENT DEALERS*
2827 **SEATTLE BANK**...*BANKS*
2827 **SEATTLE BANK**...*REAL ESTATE LOANS*
2901 **BANNER BANK**...*BANKS*
2901 **BANNER BANK**...*REAL ESTATE LOANS*
2901 **FERRIES ADM OFFICE**...*FERRIES*
2901 **FERRIES ADM OFFICE**...*TRANSPORTATION*
2911 **ALAN BRYANT**...*RESIDENTIAL*
2911 **BRANDSY CANNABIS CREATIVE**...*WEBSITE DESIGN SERVICE*
2911 **CHARLES COMSTOCK**...*RESIDENTIAL*
2911 **CHRISTO DEVARAJ**...*RESIDENTIAL*
2911 **CHRISTOPHER ROBIN-FRIENDS**...*NONCLASSIFIED ESTABLISHMENTS*
2911 **DANIEL GORAY**...*RESIDENTIAL*
2911 **DANIELLE WALTERS**...*RESIDENTIAL*
2911 **DAVID SHIM**...*RESIDENTIAL*
2911 **DESIGNS BY VYSHALI**...*JEWELERS-RETAIL*
2911 **DOUGLAS GREENSWAG**...*RESIDENTIAL*
2911 **DOUGLAS LINDNER**...*RESIDENTIAL*
2911 **EUGENE CHA**...*RESIDENTIAL*
2911 **HEATHER MORADO**...*RESIDENTIAL*
2911 **HO LEUNG**...*RESIDENTIAL*
2911 **INDEPENDENT APPRAISALS**...*REAL ESTATE APPRAISERS*
2911 **JAEL BURNS**...*RESIDENTIAL*
2911 **JENNIFER PAN**...*RESIDENTIAL*
2911 **JENNIFER PETERSON**...*RESIDENTIAL*
2911 **JOANN LACANFORA**...*RESIDENTIAL*
2911 **JOHN FORREST**...*RESIDENTIAL*
2911 **JONATHAN EAST**...*RESIDENTIAL*
2911 **JOSEPH KLINEFELTER**...*RESIDENTIAL*
2911 **JULIE ANDERSON**...*RESIDENTIAL*
2911 **JULIE REPASS**...*RESIDENTIAL*
2911 **KELLY WRIGHT**...*RESIDENTIAL*
2911 **KYONG SWOPE**...*RESIDENTIAL*
2911 **LEE, DANIEL G DDS**...*DENTISTS*
2911 **MARK WHITMELL**...*RESIDENTIAL*
2911 **NANDY CURATOLO**...*RESIDENTIAL*
2911 **OREN TRAUB**...*RESIDENTIAL*
2911 **PATRICIA PEAQUIN**...*RESIDENTIAL*
2911 **PETER PILKINGTON**...*RESIDENTIAL*
2911 **RALPH EICKHOF**...*RESIDENTIAL*
2911 **RICHARD INGBER**...*RESIDENTIAL*
2911 **ROBERT MAHONEY**...*RESIDENTIAL*
2911 **RUSSELL DICKER**...*RESIDENTIAL*
2911 **SEATTLE ZEROREZ CARPET CLEAN**...*CARPET & RUG CLEANERS*
2911 **SIMEON SARAIVANOV**...*RESIDENTIAL*
2911 **SMILE SPACE**...*DENTISTS*
2911 **STEPHANIE DAVIS**...*RESIDENTIAL*
2911 **STEVEN PAN**...*RESIDENTIAL*
2911 **TONY TSE**...*RESIDENTIAL*
2911 **WASHINGTON STATE FERRIES**...*INFORMATION & REFERRAL SVCS*
2911 **YA WEN**...*RESIDENTIAL*
2911 **YVONNE BERKOVICH**...*RESIDENTIAL*
2933 **ALICE WINSHIP**...*RESIDENTIAL*
2933 **CHRISTINE MC QUAID**...*RESIDENTIAL*
2933 **HOWELL STREET BAKERY**...*BAKERS-RETAIL*
2933 **MATT STACEY**...*RESIDENTIAL*
2933 **WINDERMERE APARTMENTS**...*APARTMENTS*
2933 **WINDERMERE APARTMENTS**...*APARTMENT FINDING & RENTAL SERVICE*

2020 CLAY ST

SOURCE: DIGITAL BUSINESS DIRECTORY

81 **ALIYA HIRJI**...*RESIDENTIAL*
81 **ARIF GURSEL**...*RESIDENTIAL*
81 **BARRY HYMAN**...*RESIDENTIAL*
81 **DIGITAL HEARTS PHOTO**...*PHOTOGRAPHERS-EVENTS*
81 **DONALD PUGNETTI**...*RESIDENTIAL*
81 **GOKAY TASKIN**...*RESIDENTIAL*
81 **JENNIFER DANZI**...*RESIDENTIAL*
81 **JERILYN FISCH**...*RESIDENTIAL*
81 **TERRENCE VASQUEZ**...*RESIDENTIAL*
240 **EVENTBRAIN INC**...*NONCLASSIFIED ESTABLISHMENTS*

307 total records. Part 1 of 5

2600 ANDERSEN SANDRA...RESIDENTIAL
2600 ANDREW MALM...RESIDENTIAL
2600 ANGELL THOMPSON...RESIDENTIAL
2600 ANJU NUNDY...RESIDENTIAL
2600 ANN WITTKOWSKY...RESIDENTIAL
2600 BEAU CLINE...RESIDENTIAL
2600 BETTY KNUDSON...RESIDENTIAL
2600 CAROL ABODEELY...RESIDENTIAL
2600 CESAR AQUINO...RESIDENTIAL
2600 CHENYANG LI...RESIDENTIAL
2600 CHRIS BOSCH...RESIDENTIAL
2600 CHRIS CRAIG...RESIDENTIAL
2600 CHRISTOPHER RAMSEY...RESIDENTIAL
2600 COLLEEN DINKEL...RESIDENTIAL
2600 COLLEEN K DINKEL INC...NONCLASSIFIED ESTABLISHMENTS
2600 DAN PAZ...RESIDENTIAL
2600 DAVID GABA...RESIDENTIAL
2600 DEBRA THOMAS...RESIDENTIAL
2600 DEREK PESCHEL...RESIDENTIAL
2600 DOUGLAS DAVI ANDERSON...RESIDENTIAL
2600 ELAN RUSKIN...RESIDENTIAL
2600 ELIZABETH LOCATELL...RESIDENTIAL
2600 ELIZABETH SATO...RESIDENTIAL
2600 ELLA SONNENBERG...RESIDENTIAL
2600 EMILY CAHILL...RESIDENTIAL
2600 EMMA LORENZEN...RESIDENTIAL
2600 EUNICE CHAN...RESIDENTIAL
2600 GABA, DAVID...OFFICES OF LAWYERS
2600 GAIL JOHNSTON...RESIDENTIAL
2600 GARY DOUSSON...RESIDENTIAL
2600 HOWARD MEEKS...RESIDENTIAL
2600 J KNUDSON...RESIDENTIAL
2600 JAMES KEMPER...RESIDENTIAL
2600 JAMES LORENZEN...RESIDENTIAL
2600 JEAN BLAKEMORE...RESIDENTIAL
2600 JEH WANG...RESIDENTIAL
2600 JENNIFER ALLEY...RESIDENTIAL
2600 JERRI LAYMAN...RESIDENTIAL
2600 JESSICA TONANI...RESIDENTIAL
2600 JOANNE ORANGE...RESIDENTIAL
2600 JOHN RUDOLF...RESIDENTIAL
2600 JOY AQUINO...RESIDENTIAL
2600 KAREN FELTON...RESIDENTIAL
2600 KAREN TORELLI...RESIDENTIAL
2600 KATHERINE POWELL...RESIDENTIAL
2600 KATHLEEN STILINOVIC...RESIDENTIAL
2600 KATIE URSINO...RESIDENTIAL
2600 KATY BUTLER...RESIDENTIAL
2600 KENDRA MCDERMOTT...RESIDENTIAL
2600 KEREM KARADAYI...RESIDENTIAL
2600 KERSTEN GABA...RESIDENTIAL
2600 KEVIN JONES...RESIDENTIAL
2600 KOHJI KAMIYA...RESIDENTIAL
2600 KRISHNA MENON...RESIDENTIAL
2600 LAURIE GRIFFITH...RESIDENTIAL
2600 LAWRENCE STILINOVIC...RESIDENTIAL
2600 MAN LAU...RESIDENTIAL
2600 MARC ANDERSON...RESIDENTIAL
2600 MARILYN WIDLAN...RESIDENTIAL
2600 MARK LONG...RESIDENTIAL
2600 MERLE SHERMAN...RESIDENTIAL
2600 MICHAEL LOCATELL...RESIDENTIAL
2600 MING CHAN...RESIDENTIAL
2600 NADINE LAPIRA-WOLOS...RESIDENTIAL
2600 NANCY GROTE...RESIDENTIAL
2600 NICHOLAS NOH...RESIDENTIAL
2600 NICK PIZZELLO...RESIDENTIAL
2600 NORA TABLER...RESIDENTIAL

2016 2ND AVE
SOURCE: DIGITAL BUSINESS DIRECTORY

Part 2 of 5

2600 PAUL ABODEELY...RESIDENTIAL
2600 PAUL ONAKOYA...RESIDENTIAL
2600 PAULINE DEHART...RESIDENTIAL
2600 PETER ORANGE...RESIDENTIAL
2600 PETER TORELLI...RESIDENTIAL
2600 PETER WIELAND...RESIDENTIAL
2600 PRADYUMNA AMLEKAR...RESIDENTIAL
2600 RAJIV NUNDY...RESIDENTIAL
2600 RICHANNE OLSON...RESIDENTIAL
2600 ROBERT DOUROUX...RESIDENTIAL
2600 ROBERT FELTON...RESIDENTIAL
2600 ROBERT GROTE...RESIDENTIAL
2600 RUMIO TAKAGI...RESIDENTIAL
2600 SAMANTHA SHERMAN...RESIDENTIAL
2600 SARA TORELLI...RESIDENTIAL
2600 SCOTT BROWN...RESIDENTIAL
2600 SEATTLE HEIGHTS CONDO OWNERS...CONDOMINIUMS
2600 SHELDON WIDLAN...RESIDENTIAL
2600 SOUTHERN EXPLORATIONS...BUSINESS SERVICES NEC
2600 STEVE SCHWEICKERT...RESIDENTIAL
2600 SUSAN PICHT...RESIDENTIAL
2600 SUSAN ROSENTHAL...RESIDENTIAL
2600 THERESA PIZZELLO...RESIDENTIAL
2600 THOMAS RILEY...RESIDENTIAL
2600 TIMOTHY CHAN...RESIDENTIAL
2600 TINGTING LI...RESIDENTIAL
2600 TOM THOMAS...RESIDENTIAL
2600 TORSTEN REINL...RESIDENTIAL
2600 VERA KOCH...RESIDENTIAL
2600 VERONICA LUONGO...RESIDENTIAL
2600 VLADIMIR EREMENKOV...RESIDENTIAL
2600 WILLIAM SHAW...RESIDENTIAL
2600 YAU WANG...RESIDENTIAL
2600 YOLANDE WANG...RESIDENTIAL
2600 ZELLA RAMSEY...RESIDENTIAL
2600 ZHENGMING SONG...RESIDENTIAL
2601 MOTHER NATURE INC...MISCELLANEOUS RETAIL STORES NEC
2602 AXTION CLUB...CLUBS
2602 AXTION CLUB...BOXING INSTRUCTION
2602 INTERNATIONAL KITCHENS...KITCHEN CABINETS & EQUIPMENT-HOUSEHOLD
2606 ARTITRON LLC...WEBSITE DESIGN SERVICE
2606 ESCALATED MARKETING CONSLTNG...MARKETING CONSULTING SERVICES
2606 HOME OFFICE...OFFICE SUPPLIES
2606 RICHANNE, JOY OLSON...FURNITURE-DEALERS-RETAIL
2606 RUSSELL HUSTON...NONCLASSIFIED ESTABLISHMENTS
2606 STORBINS TECHNOLOGY INC...STORAGE-HOUSEHOLD & COMMERCIAL
2606 STUDIO GIOIA...NONCLASSIFIED ESTABLISHMENTS
2606 WORK WELL WITH OTHERS...CONSULTANTS-BUSINESS NEC
2607 BROOK II LLC...REAL ESTATE
2607 THIRD & WALL ART GROUP LLC...ART GALLERIES & DEALERS
2607 YEAR UP...SOCIAL SERVICE & WELFARE ORGANIZATIONS
2608 21ST CENTURY MARTIAL ARTS...MARTIAL ARTS INSTRUCTION
2608 24 HOUR LOCKSMITH...LOCKS & LOCKSMITHS
2608 A FIRST IMPRESSION LIMOUSINE...LIMOUSINE SERVICE
2608 A LIFE STYLE LIMO & TOWN CAR...LIMOUSINE SERVICE
2608 ADVANCED EYE CARE...NONCLASSIFIED ESTABLISHMENTS
2608 AUTOMATED PRACTICE MANAGEMENT...MANAGEMENT SERVICES
2608 BELLTOWN COMMUNITY COUNCIL...NONCLASSIFIED ESTABLISHMENTS
2608 BLACK OPAL VENTURES LLC...EVENTS-SPECIAL
2608 CAR ADVISORY NETWORK INC...DATA PROCESSING, HOSTING & RELATED SERVICES
2608 CHEYANNE'S DETAIL...PATIO & DECK CLEANING & RESTORATION
2608 CHEYANNE'S DETAIL...AUTOMOBILE DETAIL & CLEAN-UP SERVICE
2608 CONCIERGE CARE ADVISORS...SENIOR CITIZENS SERVICE
2608 FOCUS CLEANING SVC...CLEANERS
2608 GLICKMAN, ADAM...NONCLASSIFIED ESTABLISHMENTS
2608 HARRIETTE KANE...RESIDENTIAL

Part 3 of 5

2608 SEATTLE GLEE CLUBS...CLUBS
2608 SEATTLE SEO CONSULTANT...INTERNET SEARCH ENGINES
2608 STARGAZE DEVELOPMENTS INC...INDUSTRIAL DEVELOPMENTS
2608 VIEOSOFT...NONCLASSIFIED ESTABLISHMENTS
2609 PARADISO MECHANICAL LLC...PLUMBING CONTRACTORS
2616 TANDOORI HUT...RESTAURANTS
2617 FASHION SALES...SPORTSWEAR-WHOLESALE
2618 REAL PROPERTY INVESTORS LLC...REAL ESTATE INVESTMENTS
2620 TRF PACIFIC LLC...REAL ESTATE MANAGEMENT
2621 ALBERT BERGER...RESIDENTIAL
2621 ANTOINE SAMPLE...RESIDENTIAL
2621 ARTHUR MARTINELLI...RESIDENTIAL
2621 ATROCIOUS RECORDS...BUSINESS RECORDS & DOCUMENTS-STORAGE
2621 CECILIA SAMPLE...RESIDENTIAL
2621 CHRIS RIGOS...RESIDENTIAL
2621 CHRISTINE JANIKOWSKI...RESIDENTIAL
2621 COREY SCANLON...RESIDENTIAL
2621 DAVID MORRIS...RESIDENTIAL
2621 EAGLE ROCK VENTURES LLC...OFFICES OF REAL ESTATE AGENTS & BROKERS
2621 EILEEN LYNCH...RESIDENTIAL
2621 ERIC HARVEY...RESIDENTIAL
2621 ERIC NEWELL...RESIDENTIAL
2621 FRANCES NEWELL...RESIDENTIAL
2621 FRED DRUMMOND...RESIDENTIAL
2621 GEORGE LEMONNIER...RESIDENTIAL
2621 HARBOUR HEIGHTS HOA...CONDOMINIUMS
2621 JANELLE KINGSLEY...RESIDENTIAL
2621 JEFFREY STOFSKY...RESIDENTIAL
2621 JENNIFER KILDUFF...RESIDENTIAL
2621 KAZUHIRO KAWASAKI...RESIDENTIAL
2621 LAURIE MARTINELLI...RESIDENTIAL
2621 LAWRENCE OBERTO...RESIDENTIAL
2621 LOREN MELL...RESIDENTIAL
2621 MARIANN ROBINSON...RESIDENTIAL
2621 MARIBEL FIGUERA...RESIDENTIAL
2621 MARILYN BERGER...RESIDENTIAL
2621 MARK SMEDLEY...RESIDENTIAL
2621 PAT JANIKOWSKI...RESIDENTIAL
2621 PAULA HOLMES...RESIDENTIAL
2621 REIKO LEMONNIER...RESIDENTIAL
2621 ROBERT BUKOWSKI...RESIDENTIAL
2621 ROBERT KINGSLEY...RESIDENTIAL
2621 ROBERT KOEHLER...RESIDENTIAL
2621 ROBINSON, MARIANNE...PSYCHOANALYSTS
2621 ROLOFF IMPORTS...IMPORTERS (WHLS)
2621 SANDRA MARION...RESIDENTIAL
2621 SCOTT SHAPIRO...RESIDENTIAL
2621 SEATTLE MAYTAG REPAIR...APPLIANCES-HOUSEHOLD-MAJOR-REPAIRING
2621 SHEILA BUKOWSKI...RESIDENTIAL
2621 SHELBY PATIENT...RESIDENTIAL
2621 SQUEEGEE CONSTRUCTION CLEANUP...JANITOR SERVICE
2621 STEPHEN DUNCAN...RESIDENTIAL
2621 SUSAN KADLEC...RESIDENTIAL
2621 VALENTINA ZASLAVSKY...RESIDENTIAL
2621 WILLIAM FARLEY...RESIDENTIAL
2621 YVONNE LEMONNIER...RESIDENTIAL
2623 INTERPACIFIC INVESTORS SVC INC...FEDERAL GOVERNMENT CONTRACTORS
2623 INTERPACIFIC INVESTORS SVC INC...STOCK & BOND BROKERS
2701 EASTERN MERCHANDISE CO...JEWELRY-MANUFACTURERS
2701 EASTERN MERCHANDISE CO...JEWELERS-WHOLESALE
2729 LIGHTING SUPPLY INC...LIGHT BULBS & TUBES (WHLS)
2801 CRESCENT ARMS DRYCLEANING...CLEANERS
2815 ABIERTO Y A MENUDO...NONCLASSIFIED ESTABLISHMENTS
2815 AMALGAMATED TRANSIT UNION...LABOR ORGANIZATIONS
2815 AMALGAMATED TRANSIT UNION...NON-PROFIT ORGANIZATIONS
2815 AMALGAMATED TRANSIT UNION 58...LABOR ORGANIZATIONS

2016 2ND AVE
SOURCE: DIGITAL BUSINESS DIRECTORY

Part 4 of 5

2815 AMERICAN FINANCIAL SOLUTIONS...CREDIT & DEBT COUNSELING SERVICES
2815 ATM...AUTOMATED TELLER MACHINES
2815 BAY VISTA...NONCLASSIFIED ESTABLISHMENTS
2815 BOARD INDUSTRIAL INS APPEALS...INSURANCE
2815 CLEANWORKFORCE.COM...ADVERTISING-COMPUTER
2815 COMMITTEE FOR CHILDREN...ASSOCIATIONS
2815 DEX ONE...ADVERTISING-DIRECTORY & GUIDE
2815 FULL SAIL BREWING CO...BEER & ALE-WHOLESALE
2815 INDUSTRIAL INSURANCE APPEALS...STATE GOVERNMENT-LICENSING & INSPECTION
2815 INTER COOPERATIVE USA...COOPERATIVES
2815 KKMO...RADIO STATIONS & BROADCASTING COMPANIES
2815 KKOL...RADIO STATIONS & BROADCASTING COMPANIES
2815 LEND LEASE...FEDERAL GOVERNMENT CONTRACTORS
2815 LEND LEASE...CONSTRUCTION MANAGEMENT
2815 NORTH SEATTLE CMNTY CLG FNDTN...FOUNDATION-EDUC PHILANTHROPIC RESEARCH
2815 PUCHANT SOUND CREDIT UNION...CREDIT UNIONS
2815 PUGET SOUND CREDIT UNION...CREDIT UNIONS
2815 SALEM COMMUNICATIONS CORP...RADIO STATIONS & BROADCASTING COMPANIES
2815 SATORI SOFTWARE...ELECTRONIC STORES
2815 SEATTLE CUSTOM FRAMING LLC...PICTURE FRAMES-DEALERS
2815 WELFARE PENSION ADMIN...PENSION & PROFIT SHARING PLANS
2819 WORLD CUP COFFEE...RESTAURANTS
2821 BARBARA HOUGHTON...RESIDENTIAL
2821 BARBARA MELSON...RESIDENTIAL
2821 BARBARA SHELDON...RESIDENTIAL
2821 BAY VISTA TOWER CONDOMINIUMS...CONDOMINIUMS
2821 CILLY KAMINOFF...RESIDENTIAL
2821 CRETE CONSULTING INC...BUSINESS MANAGEMENT CONSULTANTS
2821 DALE BLOOMQUIST...RESIDENTIAL
2821 DANIEL SADLER...RESIDENTIAL
2821 DAVID MATTSON...RESIDENTIAL
2821 EDWARD STAHL...RESIDENTIAL
2821 EPIMETRICS GROUP LLC...NONCLASSIFIED ESTABLISHMENTS
2821 GLENDA MALEDY...RESIDENTIAL
2821 GRETCHE MUELLER...RESIDENTIAL
2821 INA JOSEPHSON...RESIDENTIAL
2821 JAN SCHOLTE...RESIDENTIAL
2821 JOHNSTON TRAINING GROUP INC...TRAINING PROGRAMS & SERVICES
2821 KAREN JOHNSTON...RESIDENTIAL
2821 LUCINDA KELLY...RESIDENTIAL
2821 PATRICIA CLARK...RESIDENTIAL
2821 PRISCILLA BATES...RESIDENTIAL
2821 R SCHOLTE...RESIDENTIAL
2821 SABOL, JOHN...ARCHAEOLOGISTS
2821 SAMUEL SELINGER...RESIDENTIAL
2821 SHELL...SERVICE STATIONS-GASOLINE & OIL
2821 SHERRY BERRY...RESIDENTIAL
2821 SIGEKI STAHL...RESIDENTIAL
2821 STEPHEN OLSON...RESIDENTIAL
2821 SUSAN SHELDON...RESIDENTIAL
2821 THOMAS MUELLER...RESIDENTIAL
2821 THORPE KELLY...RESIDENTIAL
2821 TIMOTHY O DONOVAN...RESIDENTIAL
2827 ATM...AUTOMATED TELLER MACHINES
2827 BANNER BANK...BANKS
2827 SEATTLE BANK...BANKS
2901 BANNER BANK...BANKS
2901 FERRIES ADM OFFICE...FERRIES
2911 AMY CONKLIN...RESIDENTIAL
2911 BELLTOWN CAFE MARKET LLC...RESTAURANTS
2911 CHRISTO DEVARAJ...RESIDENTIAL
2911 DANIELLE WALTERS...RESIDENTIAL
2911 DAVID SHIM...RESIDENTIAL
2911 DAVID WOOD...RESIDENTIAL
2911 DESIGNS BY VYSHALI...JEWELERS-RETAIL
2911 DOUGLAS GREENSWAG...RESIDENTIAL

2016 2ND AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

Part 5 of 5

2911 **ERIC LACKSCHEIDE**...*RESIDENTIAL*
2911 **HENRY WALTERS**...*RESIDENTIAL*
2911 **HYANG AN**...*RESIDENTIAL*
2911 **IAN MURRAY**...*RESIDENTIAL*
2911 **IMAN AFROOZ**...*RESIDENTIAL*
2911 **INDEPENDENT APPRAISALS**...*REAL ESTATE APPRAISERS*
2911 **JACOB SIMONS**...*RESIDENTIAL*
2911 **JAMES TISDEL**...*RESIDENTIAL*
2911 **JANA PETERSON**...*RESIDENTIAL*
2911 **JANET LINDNER**...*RESIDENTIAL*
2911 **JEDIDIAH BROWN**...*RESIDENTIAL*
2911 **JEFFREY JOHNSON**...*RESIDENTIAL*
2911 **JENNIFER PETERSON**...*RESIDENTIAL*
2911 **JESSE WALTER**...*RESIDENTIAL*
2911 **JULIE ANDERSON**...*RESIDENTIAL*
2911 **JULIE REPASS**...*RESIDENTIAL*
2911 **KYONG SWOPE**...*RESIDENTIAL*
2911 **LACANFORA, ROBERT J PA**...*PHYSICIANS ASSISTANTS*
2911 **LUCY LUCAS**...*RESIDENTIAL*
2911 **MANU SAREEN**...*RESIDENTIAL*
2911 **MICHAEL SWOPE**...*RESIDENTIAL*
2911 **NATALIE SWOPE**...*RESIDENTIAL*
2911 **OREN TRAUB**...*RESIDENTIAL*
2911 **PATRICIA PEAQUIN**...*RESIDENTIAL*
2911 **PHILIP ROGERS**...*RESIDENTIAL*
2911 **SEATTLE ZEROREZ CARPET CLEAN**...*CARPET & RUG CLEANERS*
2911 **SIMEON SARAIVANOV**...*RESIDENTIAL*
2911 **STEFKA SARAIVANOV**...*RESIDENTIAL*
2911 **STEPHANIE DAVIS**...*RESIDENTIAL*
2911 **SUZANNE POWERS**...*RESIDENTIAL*
2911 **YA WEN**...*RESIDENTIAL*
2933 **ALICE WINSHIP**...*RESIDENTIAL*
2933 **CHRISTINE MC QUAID**...*RESIDENTIAL*
2933 **JACOB JACOB INC**...*NONCLASSIFIED ESTABLISHMENTS*
2933 **MATT STACEY**...*RESIDENTIAL*
2933 **WINDERMERE APARTMENTS**...*APARTMENT FINDING & RENTAL SERVICE*
2933 **WINDERMERE APARTMENTS**...*APARTMENTS*

2016 CLAY ST

SOURCE: DIGITAL BUSINESS DIRECTORY

81 **ALIYA HIRJI**...*RESIDENTIAL*
81 **BARRY HYMAN**...*RESIDENTIAL*
81 **DIGITAL HEARTS PHOTO**...*PHOTOGRAPHERS-EVENTS*
81 **DONALD PUGNETTI**...*RESIDENTIAL*
81 **GOKAY TASKIN**...*RESIDENTIAL*
81 **JERRY PUGNETTI**...*RESIDENTIAL*
81 **TERRENCE VASQUEZ**...*RESIDENTIAL*
81 **TRIPLE EYE DIGITAL STUDIOS**...*DIGITAL MEDIA PRODUCTION*
81 **WENDY PUGNETTI**...*RESIDENTIAL*
81 **YUN KWON**...*RESIDENTIAL*

251 total records. Part 1 of 4

2600 AQUINO AQUINO...RESIDENTIAL
2600 ARMANDO LEIVA...RESIDENTIAL
2600 BARBARA BENINGER...RESIDENTIAL
2600 BARBARA BRANNAN...RESIDENTIAL
2600 CAROLYN FELDSINE...RESIDENTIAL
2600 CATHERINE BOCK...RESIDENTIAL
2600 CESAR AQUNIO...RESIDENTIAL
2600 CHRISTA WEST...RESIDENTIAL
2600 CHRISTOPHER WORLEY...RESIDENTIAL
2600 CLYDE PASCUAL...RESIDENTIAL
2600 CORNICHON COMMUNICATIONS...TELEVISION & RADIO-DEALERS
2600 CRISTIE BAKE...RESIDENTIAL
2600 D ANDERSON...RESIDENTIAL
2600 DANIEL CONKLIN...RESIDENTIAL
2600 DEBRA THOMAS...RESIDENTIAL
2600 DEREK PESCHEL...RESIDENTIAL
2600 DOUGLAS ANDERSON...RESIDENTIAL
2600 ELENA FROLOV...RESIDENTIAL
2600 ELIZABETH RUDOLF...RESIDENTIAL
2600 FRANCES WU...RESIDENTIAL
2600 FRANK BRET...RESIDENTIAL
2600 G JOHNSTON...RESIDENTIAL
2600 GALINA GOLOVINA...RESIDENTIAL
2600 GARY EYRING...RESIDENTIAL
2600 GENNADY KURBAT...RESIDENTIAL
2600 GEORGE KRAUSS...RESIDENTIAL
2600 GRETCHEN MUELLER...RESIDENTIAL
2600 GUILLORY ZARR...RESIDENTIAL
2600 HALI WU...RESIDENTIAL
2600 JANIS HARWELL...RESIDENTIAL
2600 JOAN LEE...RESIDENTIAL
2600 JOHN MANCINI...RESIDENTIAL
2600 JOHN RUDOLF...RESIDENTIAL
2600 JOHN WEST...RESIDENTIAL
2600 JOY AQUINO...RESIDENTIAL
2600 KARAMVIR SINGH...RESIDENTIAL
2600 KAREN TUFF...RESIDENTIAL
2600 L GILBERTSON...RESIDENTIAL
2600 LAPIRAT WOLOS...RESIDENTIAL
2600 LARRY LEE...RESIDENTIAL
2600 LARRY ROBERTS...RESIDENTIAL
2600 LAURA CASTELLANOS...RESIDENTIAL
2600 LESLIE RAINES...RESIDENTIAL
2600 MAN LAU...RESIDENTIAL
2600 MARGARET LEAHEY...RESIDENTIAL
2600 MARGIE BREWER...RESIDENTIAL
2600 MARTHA MITCHELL-MEAGHER...RESIDENTIAL
2600 MERLE SHERMAN...RESIDENTIAL
2600 MICHAEL HIGASHI...RESIDENTIAL
2600 MICHAEL OVESEN...RESIDENTIAL
2600 MICHAEL WHITE...RESIDENTIAL
2600 MOLLY ANDERSON...RESIDENTIAL
2600 NADINE WOLOS...RESIDENTIAL
2600 NICK PASCUAL...RESIDENTIAL
2600 NIROSHINI GUNABALASUBRAMANIAM...RESIDENTIAL
2600 PAUL ABODEELY...RESIDENTIAL
2600 PAUL OKER...RESIDENTIAL
2600 PHILIP FELDSINE...RESIDENTIAL
2600 SARAH BERMAN...RESIDENTIAL
2600 SCOTT NAPIER...RESIDENTIAL
2600 SEATTLE HEIGHTS CONDO OWNERS...BUSINESS ASSOCIATIONS
2600 SERGEY FROLOV...RESIDENTIAL
2600 STEVEN WHITE...RESIDENTIAL
2600 SVEINUNG ODEGARD...RESIDENTIAL
2600 TAKAGI RUMIO...RESIDENTIAL
2600 THERESA PASCUAL...RESIDENTIAL
2600 THEVESA PASCUAL...RESIDENTIAL
2600 THOMAS MUELLER...RESIDENTIAL

2012 2ND AVE
SOURCE: DIGITAL BUSINESS DIRECTORY

Part 2 of 4

2600 TORSTEN REINL...RESIDENTIAL
2600 WALTER TABLER...RESIDENTIAL
2600 WEIYOU CUI...RESIDENTIAL
2601 MOTHER NATURE INC...STORE RETAILERS NOT SPECIFIED ELSEWHERE
2601 MOTHER NATURE INC...MISCELLANEOUS RETAIL STORES NEC
2602 AXTION CLUB...CLUBS
2602 INTERNATIONAL KITCHENS...WOOD KITCHEN CABINET & COUNTERTOP MFG
2606 ARTITRON LLC...WEBSITE DESIGN SERVICE
2606 CATHERINE CHANEY LAW OFFICE...ATTORNEYS
2606 HOME OFFICE...OFFICE SUPPLIES & STATIONERY STORES
2606 HOME OFFICE...OFFICE SUPPLIES
2606 LAVALOBE LLC...COMPUTER GRAPHICS
2606 LAVALOBE LLC...CUSTOM COMPUTER PROGRAMMING SVCS
2606 RICHANNE, JOY OLSON...FURNITURE-DEALERS-RETAIL
2607 CELLO TECHNOLOGIES SEATTLE...SERVICES-ALLIED TO MOTION PICTURE PRODUCTION
2607 FIFTY FIVE YARD LINE INC...RETAIL-EATING PLACES
2607 METAJURE...ATTORNEY REFERRAL SERVICE
2607 RADARWORKS...ADVERTISING AGENCIES
2607 REM MEDICAL...PHYSICIANS & SURGEONS EQUIP & SUPLS-WHLS
2607 THIRD & WALL ART GROUP LLC...ART DEALERS
2607 THIRD & WALL ART GROUP LLC...ART GALLERIES & DEALERS
2607 YEAR UP...SOCIAL SERVICE & WELFARE ORGANIZATIONS
2608 21ST CENTURY MARTIAL ARTS...MARTIAL ARTS INSTRUCTION
2608 A FIRST IMPRESSION LIMOUSINE...LIMOUSINE SERVICE
2608 A LIFE STYLE LIMO & TOWN CAR...LIMOUSINE SERVICE
2608 ADVANTAGE PROCESS & INVSTGTNS...PROCESS SERVERS
2608 ADVANTAGE PROCESS & INVSTGTNS...ALL OTHER LEGAL SVCS
2608 AUTOMATED PRACTICE MANAGEMENT...MANAGEMENT SERVICES
2608 AUTOMATED PRACTICE MANAGEMENT...OFFICE ADMINISTRATIVE SVCS
2608 BAYSIDE INVESTIGATIONS...INVESTIGATORS
2608 BAYSIDE INVESTIGATIONS...SERVICES-DETECTIVE, GUARD & ARMORED CAR SERVICES
2608 BAYSIDE INVESTIGATIONS...INVESTIGATION SVCS
2608 BCI CORP...WHOLESALE TRADE - NONDURABLE GOODS
2608 CHEYANNE'S DETAIL...AUTOMOBILE DETAIL & CLEAN-UP SERVICE
2608 CHEYANNES DETAIL...CAR WASHES
2608 NATHAN WARD...RESIDENTIAL
2608 PACIFIC COAST ATTORNEY SVC LLC...ALL OTHER LEGAL SVCS
2608 PACIFIC COAST ATTORNEY SVC LLC...PROCESS SERVERS
2608 RELIABLE...GENERAL FREIGHT TRUCKING, LOCAL
2608 STARGAZE DEVELOPMENTS INC...LANDSCAPE ARCHITECTURAL SVCS
2608 STARGAZE DEVELOPMENTS INC...INDUSTRIAL DEVELOPMENTS
2608 STELLAR EDGE...SHARPENING SERVICE
2608 STRONG PAINTING CO...PAINT & WALL COVERING CONTRS
2608 THERESA MALPHRUS...RESIDENTIAL
2609 PARADISO MECHANICAL LLC...PLUMBING CONTRACTORS
2616 TANDOORI HUT...RESTAURANTS
2616 TANDOORI HUT...FULL-SERVICE RESTAURANTS
2617 FASHION SALES...SPORTSWEAR-WHOLESALE
2617 FASHION SALES...MEN'S & BOY'S CLOTHING MERCHANT WHOLS
2618 REAL PROPERTY INVESTORS LLC...REAL ESTATE INVESTMENTS
2618 REAL PROPERTY INVESTORS LLC...OFFICES OF REAL ESTATE AGENTS & BROKERS
2620 RAVENHURST DEVELOPMENT INC...OTHER ACTIVITIES RELATED TO REAL ESTATE
2620 STRATFORD GROUP LTD...REAL ESTATE INVESTMENTS
2620 STRATFORD GROUP LTD...OFFICES OF REAL ESTATE AGENTS & BROKERS
2620 TRF PACIFIC LLC...REAL ESTATE INVESTMENTS
2620 TRF PACIFIC LLC...OFFICES OF REAL ESTATE AGENTS & BROKERS
2621 ATROCIOUS RECORDS...BUSINESS RECORDS & DOCUMENTS-STORAGE
2621 BRUCE PATT...RESIDENTIAL
2621 CHERYL JANSON...RESIDENTIAL
2621 DTP LLC...FINANCIAL ADVISORY SERVICES
2621 DTP LLC...INVESTMENT ADVICE
2621 EDWARD DAWSON...RESIDENTIAL
2621 EUGENE YORE...RESIDENTIAL
2621 HARBOUR HEIGHTS HOA...LESSORS OF RESIDENTIAL BUILDINGS

2012 2ND AVE
SOURCE: DIGITAL BUSINESS DIRECTORY

Part 3 of 4

2621 HIRO KAWASKI...RESIDENTIAL
2621 JAMES ROBINSON...RESIDENTIAL
2621 JENNIFER KILDUFF...RESIDENTIAL
2621 JILL BUCY...RESIDENTIAL
2621 JILL DEVINE...RESIDENTIAL
2621 JILL MELL...RESIDENTIAL
2621 JOHN MARSHALL...RESIDENTIAL
2621 KIRSTEN KILDUFF...RESIDENTIAL
2621 LOREN MELL...RESIDENTIAL
2621 MARGARET RICE...RESIDENTIAL
2621 MARI ROBINSON...RESIDENTIAL
2621 MARY BUCY...RESIDENTIAL
2621 MARYANN GOBER...RESIDENTIAL
2621 MELINDA CRARY...RESIDENTIAL
2621 MERLYN BELL...RESIDENTIAL
2621 MICHAEL GELMAN...RESIDENTIAL
2621 MICHAEL PEARCE...RESIDENTIAL
2621 PATRICIA CHIN...RESIDENTIAL
2621 PHILIP RICE...RESIDENTIAL
2621 ROBINSON ANNE...RESIDENTIAL
2621 ROBINSON, MARIANNE...OFFICES OF MENTAL HEALTH PRACTITIONERS
2621 ROBINSON, MARIANNE...PSYCHOANALYSTS
2621 SANDRA MARION...RESIDENTIAL
2621 SYLVIA DUNCAN...RESIDENTIAL
2621 SYLVIA SEMAN...RESIDENTIAL
2621 TIM RICE...RESIDENTIAL
2623 INTER PACIFIC...REAL ESTATE AGENTS & MANAGERS (FOR OTHERS)
2623 INTER PACIFIC...OFFICES OF REAL ESTATE AGENTS & BROKERS
2623 INTERPACIFIC INVESTORS SVC INC...STOCK & BOND BROKERS
2701 EASTERN MERCHANDISE CO...JEWELRY, EXCEPT COSTUME, MFG
2701 EASTERN MERCHANDISE CO...JEWELRY-MANUFACTURERS
2729 LIGHTING SUPPLY INC...LIGHTING FIXTURES-RETAIL
2729 LIGHTING SUPPLY INC...ALL OTHER HOME FURNISHINGS STORES
2801 CRESCENT ARMS DRYCLEANING...CLEANERS
2801 CRESCENT ARMS DRYCLEANING...DRYCLEANING & LAUNDRY SVCS
2815 AMALGAMATED TRANSIT UNION...LABOR ORGANIZATIONS
2815 AMERICAN FINANCIAL SOLUTIONS...CREDIT & DEBT COUNSELING SERVICES
2815 AMERICAN FINANCIAL SOLUTIONS...OTHER PERSONAL CARE SVCS
2815 BANNER BANK...COMMERCIAL BANKING
2815 BAY VISTA...NONCLASSIFIED ESTABLISHMENTS
2815 BAY VISTA
2815 BOVIS LEND LEASE INC...OTHER HEAVY CONSTRUCTION
2815 CLEANWORKFORCE.COM...BUSINESS SERVICES
2815 CLEANWORKFORCE.COM...MEDICAL LABORATORIES
2815 COOL ANIMAL SUFF COM
2815 COOLANIMALSTUFF.COM...GIFT, NOVELTY, & SOUVENIR STORES
2815 EASTSIDE CREDIT UNION...CREDIT UNIONS
2815 FINANCIAL SERVICES CU...CREDIT UNIONS
2815 FULL SAIL BREWING CO...BREWERIES
2815 FULL SAIL BREWING CO...BEER & ALE-WHOLESALE
2815 INTER CO OP USA...OTHER SIMILAR ORGANIZATIONS
2815 INTER CO-OP USA...COOPERATIVES
2815 KKMO...RADIO STATIONS & BROADCASTING COMPANIES
2815 KLFE...RADIO STATIONS & BROADCASTING COMPANIES
2815 KLFE...RADIO STATIONS
2815 LAKELAND PROPERTIES...LAND SUBDIVISION
2815 LEND LEASE...CONSTRUCTION MANAGEMENT
2815 MCI...ALL OTHER TELECOMMUNICATIONS
2815 MCI...TELECOMMUNICATIONS SERVICES
2815 NEONGECKO.COM...DATA PROCESSING & RELATED SVCS
2815 PACIFIC CREDIT UNION...CREDIT UNIONS
2815 PRINCESS CRUISES...TRAVEL AGENCIES
2815 PUCHANT SOUND CREDIT UNION...CREDIT UNIONS
2815 PUGET SOUND CREDIT UNION...CREDIT UNIONS
2815 REPUBLIC PARKING...PARKING STATIONS & GARAGES
2815 REPUBLIC PARKING NORTHWEST...AUTO REPAIR, SERVICES, AND PARKING

Part 4 of 4

2815 SEAMAR COMMUNITY HEALTH CTR...RADIO STATIONS & BROADCASTING COMPANIES
2815 TABLEANDHOME.COM STORE...GIFT, NOVELTY, & SOUVENIR STORES
2815 US EQUAL EMPLOYMENT OPPORTUNTY...OTHER HUMAN RESOURCE PROGRAMS ADMINISTRATION
2815 WESTSIDE CREDIT UNION...CREDIT UNIONS
2815 WPAS INC...PENSION FUNDS
2819 WORLD CUP COFFEE...RESTAURANTS
2819 WORLD CUP COFFEE...FULL-SERVICE RESTAURANTS
2821 ARNIE BERGH...RESIDENTIAL
2821 BAY VISTA TOWER CONDOMINIUMS...LESSORS OF RESIDENTIAL BUILDINGS
2821 BAY VISTA TOWER CONDOMINIUMS...CONDOMINIUMS
2821 BEGINNINGS GUIDES...MISC AMBULATORY HEALTH CARE SVCS
2821 BILL WOOD...RESIDENTIAL
2821 C ROBERT...RESIDENTIAL
2821 EDWARD BIROCHAK...RESIDENTIAL
2821 EUGENE KELLER...RESIDENTIAL
2821 EVELYN HALL...RESIDENTIAL
2821 GAIL PETERSEN...RESIDENTIAL
2821 GEORGE MATSUDA...RESIDENTIAL
2821 IKE ALHADEFF...RESIDENTIAL
2821 JAMES HANRAHAN...RESIDENTIAL
2821 JAYNE MATSUDA...RESIDENTIAL
2821 JOHN WEAVER...RESIDENTIAL
2821 JOHNSTON TRAINING GROUP INC...TRAINING PROGRAMS & SERVICES
2821 JOSE ROBERT...RESIDENTIAL
2821 JOYCE CROSBY...RESIDENTIAL
2821 KAREN RICH...RESIDENTIAL
2821 KIRSTIN RICH...RESIDENTIAL
2821 KRISTINE REED...RESIDENTIAL
2821 LANCE WEINER...RESIDENTIAL
2821 MANI KRISHNAMURTHY...RESIDENTIAL
2821 MICHAEL HASS...RESIDENTIAL
2821 MIKE BERGH...RESIDENTIAL
2821 PER BRAUTASET...RESIDENTIAL
2821 REGINA STEPHENS...RESIDENTIAL
2821 RICHARD HALL...RESIDENTIAL
2821 SHASH WOODS...RESIDENTIAL
2821 TIM RICH...RESIDENTIAL
2827 BANNER BANK...COMMERCIAL BANKING
2901 BANNER BANK...BANKS
2911 BELLTOWN CAFE MARKET LLC...SUPERMARKETS & OTHER GROCERY STORES
2911 BELLTOWN CAFE MARKET LLC...RESTAURANTS
2911 DESIGNS BY VYSHALI...JEWELERS-RETAIL
2911 GALLERY CONDOMINIUMS CTR...CONDOMINIUMS
2911 JOHN FORREST...RESIDENTIAL
2911 PRASHANT GAUR...RESIDENTIAL
2911 SHARAT GAUR...RESIDENTIAL
2911 THERESA WILLIAMS...RESIDENTIAL
2911 WASHINGTON DEPT OF TRANS...WATER TRANSPORTATION
2933 WINDERMERE APARTMENTS...LESSORS OF RESIDENTIAL BUILDINGS
2933 WINDERMERE APARTMENTS...APARTMENTS

2012 CLAY ST

SOURCE: DIGITAL BUSINESS DIRECTORY

81 **BARRY HYMAN**...*RESIDENTIAL*
81 **CELIA HYMAN**...*RESIDENTIAL*
81 **MARIA SANTOS**...*RESIDENTIAL*
81 **MICHAEL GREEN**...*RESIDENTIAL*
81 **SUNG BYON**...*RESIDENTIAL*
81 **WENDY PUGNETTI**...*RESIDENTIAL*

2008 2ND AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

362 total records. Part 1 of 6

2600 **A J GAHWILER**...*RESIDENTIAL*
2600 **ACHAL KAPOOR**...*RESIDENTIAL*
2600 **AKI KIMIHIRA**...*RESIDENTIAL*
2600 **ALAN JOHNSON**...*RESIDENTIAL*
2600 **ALAN UNIS**...*RESIDENTIAL*
2600 **ALFRED & ROSALLA TARANTO**...*RESIDENTIAL*
2600 **ALYSANDRA SCHWARZ**...*RESIDENTIAL*
2600 **ANDREW G CHUNG**...*RESIDENTIAL*
2600 **ANGUS H KONDO**...*RESIDENTIAL*
2600 **ANNA L FLETCHER**...*RESIDENTIAL*
2600 **ANTONIO PENA**...*RESIDENTIAL*
2600 **ARNOLD NESS**...*RESIDENTIAL*
2600 **BARBARA L BRANNAN**...*RESIDENTIAL*
2600 **BETTY L KNUDSON**...*RESIDENTIAL*
2600 **BILL LASH**...*RESIDENTIAL*
2600 **C E HALL**...*RESIDENTIAL*
2600 **CATHY JENSEN**...*RESIDENTIAL*
2600 **CHARLES STEELEY**...*RESIDENTIAL*
2600 **CLYDE PASCUAL**...*RESIDENTIAL*
2600 **CRAIG NELSON**...*RESIDENTIAL*
2600 **CUBA CRAIG**...*RESIDENTIAL*
2600 **CYNTHIA MCLACHLAN**...*RESIDENTIAL*
2600 **DANIEL G CONKLIN**...*RESIDENTIAL*
2600 **DANIEL STEENKAMP**...*RESIDENTIAL*
2600 **DAVE JOHNSON**...*RESIDENTIAL*
2600 **DEREK PESCHEL**...*RESIDENTIAL*
2600 **DESIGN OF INTERIORS EXTERIORS**...*BUSINESS SERVICES*
2600 **DORIS FOSTER**...*RESIDENTIAL*
2600 **EHEALTH INTELLIGENCE LLC**...*MANAGEMENT CONSULTING SERVICES*
2600 **ELLA SONNENBERG**...*RESIDENTIAL*
2600 **ENOCH REMICK**...*RESIDENTIAL*
2600 **EVA L GILBERTSON**...*RESIDENTIAL*
2600 **EYRING & ASSOCIATES**...*BUSINESS MANAGEMENT CONSULTANTS*
2600 **FRANCES WU**...*RESIDENTIAL*
2600 **FRANK BRET**...*RESIDENTIAL*
2600 **FRED CASTELLANO**...*RESIDENTIAL*
2600 **GARY & LAURA ORLICH**...*RESIDENTIAL*
2600 **GARY EYRING**...*RESIDENTIAL*
2600 **GEOFFREY S HELLER**...*RESIDENTIAL*
2600 **GLADWIN BELLAMY**...*RESIDENTIAL*
2600 **GREEN SOURCE**...*NURS & GARDEN STRS*
2600 **GREG TOMAMICHEL**...*RESIDENTIAL*
2600 **HEIDI M MIKKELSEN**...*RESIDENTIAL*
2600 **HENRY E SANDAHL**...*RESIDENTIAL*
2600 **HIROKO KANAI**...*RESIDENTIAL*
2600 **HOWARD MEEKS**...*RESIDENTIAL*
2600 **J DIAMOND**...*RESIDENTIAL*
2600 **J M JENNINGS**...*RESIDENTIAL*
2600 **J MCKELVEY**...*RESIDENTIAL*
2600 **J THORNTON**...*RESIDENTIAL*
2600 **JACK & THELMA COLMAN**...*RESIDENTIAL*
2600 **JAMES & MAN WONG**...*RESIDENTIAL*
2600 **JAMES & MARY E MANNING**...*RESIDENTIAL*
2600 **JAMES B PARKER**...*RESIDENTIAL*
2600 **JAMES J BLAKEMORE**...*RESIDENTIAL*
2600 **JEFF W HUNT**...*RESIDENTIAL*
2600 **JEFFREY A ALSDORF**...*RESIDENTIAL*
2600 **JERRI LAYMAN**...*RESIDENTIAL*
2600 **JOHN & CONNIE BAKER**...*RESIDENTIAL*
2600 **JOHN MORRIS**...*RESIDENTIAL*
2600 **JOHN RUDOLF**...*RESIDENTIAL*
2600 **JUDITH & BRUCE A MURDOCK**...*RESIDENTIAL*
2600 **KAREN TUFF**...*RESIDENTIAL*
2600 **KARRIE BOHI**...*RESIDENTIAL*
2600 **KAZ & ROBIN MIWA**...*RESIDENTIAL*
2600 **KELLE MORRILL**...*RESIDENTIAL*
2600 **KEN CURTIS**...*RESIDENTIAL*
2600 **KOSUKE SAKURAI**...*RESIDENTIAL*

Part 2 of 6

2600 LAWRENCE & KATIE MD STILINOVIC...RESIDENTIAL
2600 LYNN VANLIEROP...RESIDENTIAL
2600 M PROVENZA...RESIDENTIAL
2600 M ROTH...RESIDENTIAL
2600 MADELINE ZECH...RESIDENTIAL
2600 MAN C LAU...RESIDENTIAL
2600 MARI J ANGSIOCO...RESIDENTIAL
2600 MARK GWYTHER...RESIDENTIAL
2600 MARK LILLY...RESIDENTIAL
2600 MARK LONG...RESIDENTIAL
2600 MARK WHEAT...RESIDENTIAL
2600 MEL & BROOKE ASHLAND...RESIDENTIAL
2600 MEL S JACKSON...RESIDENTIAL
2600 MERLE SHERMAN...RESIDENTIAL
2600 MICHAEL & ELIZABETH N WHITE...RESIDENTIAL
2600 MICHEAL & MONICA ALBERT...RESIDENTIAL
2600 MIKE & BETH LOCATELL...RESIDENTIAL
2600 NAMIKO OKUDA...RESIDENTIAL
2600 NORIN EDDINGTON...RESIDENTIAL
2600 OPEN ORGANIZATION...MGMT CONSULTING
2600 OPEN ORGANIZATION INC...MANAGEMENT TRAINING & CONSULTING
2600 P & L R WALKER...RESIDENTIAL
2600 P J HUGHES...RESIDENTIAL
2600 PAUL OKER...RESIDENTIAL
2600 PETER CLAAR...RESIDENTIAL
2600 PETER WIELAND...RESIDENTIAL
2600 PHILIP ELDRIDGE...RESIDENTIAL
2600 PICKERING DEVELOPMENT...CUSTOM COMPUTER PROGRAMING
2600 RANDALL PROSISE...RESIDENTIAL
2600 RICHARD & JUDITH HAHN...RESIDENTIAL
2600 RICHARD COHEN...RESIDENTIAL
2600 RICHARD LEVIN...RESIDENTIAL
2600 RICHARD S HAYES...RESIDENTIAL
2600 ROBERT FELTON...RESIDENTIAL
2600 ROBERT STARIN...RESIDENTIAL
2600 ROD KEEFE...RESIDENTIAL
2600 RONALD G MEDVED...RESIDENTIAL
2600 RUMIO TAKAGI...RESIDENTIAL
2600 S ANDERSEN...RESIDENTIAL
2600 S BAESSLER...RESIDENTIAL
2600 SCOTT & GLORIA ABRAMS...RESIDENTIAL
2600 SCOTT AMERMAN...RESIDENTIAL
2600 SCOTT NAPIER...RESIDENTIAL
2600 SEATTLE HEIGHTS CONDO OWNERS...ASSOCIATIONS
2600 SEATTLE HTS CONDO OWNERS ASSN...CIVIC/SOCIAL ASSOCIATION
2600 SERGEY & LENA FROLOV...RESIDENTIAL
2600 SOJOURNER LITERARY AGENCY...BUSINESS SERVICES
2600 SRI SAGADEVAN...RESIDENTIAL
2600 STEVE DIMARCO...RESIDENTIAL
2600 STEVE KOLB...RESIDENTIAL
2600 STUART C CAMPBELL...RESIDENTIAL
2600 SUE PARTRIDGE...RESIDENTIAL
2600 TAICHI KITAMURA...RESIDENTIAL
2600 TALLULAH MAKI...RESIDENTIAL
2600 TONI M SAWAYA...RESIDENTIAL
2600 TORSTEN REINL...RESIDENTIAL
2600 VLADIMIR EREMENKOV...RESIDENTIAL
2600 VON BINUIA...RESIDENTIAL
2600 W S BOWIE...RESIDENTIAL
2600 WALTER & MARILYN PULLIAM...RESIDENTIAL
2600 WE & SB REINKE...RESIDENTIAL
2600 WILL PICKERING...RESIDENTIAL
2600 WILLIAM & SUSAN LIN...RESIDENTIAL
2600 YU K HUANG...RESIDENTIAL
2601 MOTHER NATURE...RET JEWELRY
2601 MOTHER NATURE INC...MISC RETAIL STORES
2602 INTERNATIONAL KITCHEN...CONTRACTOR SPECIALIZING IN KITCHEN OR BATHROOM REMODELI

2008 2ND AVE
SOURCE: DIGITAL BUSINESS DIRECTORY

Part 3 of 6

2606 BLACK HAT BRIEFINGS THE...COMPUTER SECURITY TRAINING AND CONFERENCES
2606 ELITE COPY & PRINT...LITHO,COML PRINTING
2606 HOME OFFICE...BUSINESS SERVICES & RET STATIONERY
2606 THE HOME OFFICE...OFFICE FORMS,SUPPS
2607 BBFM INC...SALES PROMOTION & ADVERTISING
2607 CELLO...CONTRACTING COMPANY
2607 RADARWORKS...ADVERTISING AGENCY
2608 AARDVARK LEGAL ENTERPRISES...PROCESS SERVERS
2608 ADH...HOLDING COMPANY
2608 ADVANTAGE PRCESS INVSTIGATIONS...DETECTIVE/ARMORED CAR SERVICES
2608 ANAHATAKI...SCHOOL/EDUCATIONAL SERVICES
2608 AUTOMATED PRACTICE MANAGEMENT...MANAGEMENT SERVICES
2608 BAYSIDE INVESTIGATIONS...DET, ARMORED CAR SV
2608 BAYSIDE INVESTIGATIONS...INVESTIGATORS
2608 BRIAN P FAIRCHILD & ASSOC...INVESTIGATORS
2608 DEVELOPMENT STORE...BUSINESS MANAGEMENT CONSULTANTS
2608 DEVELOPMENT STORE...MGMT CONSULTING
2608 DEVELOPMENT STORE THE...MANAGEMENT CONSULTING SERVICES
2608 DOG TOWN PICTURES LLC...MOTION PICTURE/VIDEO PRODUCTION
2608 GI CORPORATION...TEXTILE MFG
2608 HARBOUR HEIGHTS H O A...CONDOMINIUM ASSOCIATION
2608 HELP OF PUGET SOUND...UNCLASSIFIED
2608 KR SUPPLY...ENGINEERING SERVICES
2608 MORGAN FIRST GUARANTY...REAL ESTATE AGENT/MANAGER
2608 MVP SPECIALTY MERCHANDISE...UNCLASSIFIED
2608 NEXT LEVEL CONSULTING...BUSINESS CONSULTING SERVICES
2608 NITAS SHOP...RET MISC MERCHANDISE
2608 OVERCOMERS VICTORIOUS...UNCLASSIFIED
2608 PW BROWN INC...EMPLOYMENT AGENCY
2608 RELIABLE MOVERS...PACKAGING SYS
2608 STRONG PAINTING CO...PTG, PPR HANG CONTR
2608 THOMAS INTERNATIONAL INC...COMMODITIES TRADING AND EXPORT CONSULTING
2608 WISE CONSULTING SERVICES...BUSINESS CONSULTING SERVICES
2616 TANDOORI HUT...EATING PLACES
2617 FASHION SALES...MENS,BOYS SPORTSWEAR
2620 TRF PACIFIC LLC...REAL ESTATE INVT TR
2621 ADY CHU...RESIDENTIAL
2621 ALISHA PEREZ...RESIDENTIAL
2621 B CORNER...RESIDENTIAL
2621 BEN METZLER...RESIDENTIAL
2621 BOB & KATHY WILKES...RESIDENTIAL
2621 BOB CLEVELAND...RESIDENTIAL
2621 BUKOWSKI KORSMO INC...GENERAL CONTRACTOR
2621 BUKOWSKI-KORSMO INC...GENERAL CONTRACTORS
2621 CORRINNE CAIN...RESIDENTIAL
2621 DALE M STERLING...RESIDENTIAL
2621 DAN DOLAN...RESIDENTIAL
2621 DAVID & CLAUDIA WITTMER...RESIDENTIAL
2621 DAVID C MAHLER...SERVICES-MISC
2621 DAVID J MARSHALL...RESIDENTIAL
2621 DEA YU...RESIDENTIAL
2621 DEXING KONG...RESIDENTIAL
2621 DOUG ALKEMA...RESIDENTIAL
2621 E J SULLIVAN...RESIDENTIAL
2621 EDWARD A DAWSON...RESIDENTIAL
2621 ERIC & FRANCES NEWELL...RESIDENTIAL
2621 ERICH KOCH...RESIDENTIAL
2621 FARMERS INSURANCE GROUP...INSURANCE
2621 FRED H DRUMMOND...RESIDENTIAL
2621 G E GOEHRING...RESIDENTIAL
2621 GARY LUNDGREN...RESIDENTIAL
2621 GEORGE & LINDA SUDDOCK...RESIDENTIAL
2621 HARBOUR HEIGHTS HOA...DWELLING OPERATORS
2621 HARBOUR HEIGHTS HOA...CONDOMINIUMS
2621 HOWARD T REYNOLDS...RESIDENTIAL
2621 J A DEVINE...RESIDENTIAL

Part 4 of 6

2621 JAMES & DEBORAH BEVIER...RESIDENTIAL
2621 JAMES J STANTON...RESIDENTIAL
2621 JAMES L WYLIE...RESIDENTIAL
2621 JAY CROSBY...RESIDENTIAL
2621 JOHN C ERICKSON...RESIDENTIAL
2621 JOHN C ZITO...RESIDENTIAL
2621 JOHN D CONNORS...RESIDENTIAL
2621 JOHN T KUGLER...RESIDENTIAL
2621 KENNETH BODMER...RESIDENTIAL
2621 LARRY OBERTO...RESIDENTIAL
2621 LOREN MELL...RESIDENTIAL
2621 MARCIA M MEADE...RESIDENTIAL
2621 MARIANNE ROBINSON...SOCIAL SER ORG
2621 MARIANNE ROBINSON LICSW BCD...MEDICAL DOCTOR'S OFFICE INDIVIDUAL/FAMILY SERVICES
2621 MARY WHITE...RESIDENTIAL
2621 MICHAEL WARE...RESIDENTIAL
2621 MIKE & DIANE HANSEN...RESIDENTIAL
2621 P C BULL...RESIDENTIAL
2621 P HOLMES...RESIDENTIAL
2621 PHYLLIS WOOD...RESIDENTIAL
2621 R & A BALLWEG...RESIDENTIAL
2621 R & J KINGSLEY...RESIDENTIAL
2621 R BENETT...RESIDENTIAL
2621 R TRIPP...RESIDENTIAL
2621 RAY A BALLWEG...MANAGEMENT CONSULTING SERVICES
2621 REIKO MANAKA...RESIDENTIAL
2621 RODGER BENSON...RESIDENTIAL
2621 S N KADLEC...RESIDENTIAL
2621 SALVATORE CAGNINA...RESIDENTIAL
2621 SEAGULF GROUP LLC...SUBDIVIDER/DEVELOPER
2621 SYLVIA I SEMAN TRUSTEE...MANAGEMENT CONSULTING SERVICES
2621 SYLVIA S FISHER...RESIDENTIAL
2621 SYLVIA SEMAN...RESIDENTIAL
2621 THERESA SLECHTA...RESIDENTIAL
2621 TIM RICE...RESIDENTIAL
2621 TOM DIETRICH...RESIDENTIAL
2621 TRACY COOPER...RESIDENTIAL
2621 WILLIAM & B D PARLEY...RESIDENTIAL
2621 WILLIAM F ROUSH...RESIDENTIAL
2623 INTER PACIFIC...REAL ESTATE INVESTMENTS
2623 INTER PACIFIC...REAL ESTATE INVT TR
2623 INTERPACIFIC INVESTORS SERVICE...SECURITY BRK,DEALER
2623 INTERPACIFIC INVESTORS SVC...MERCHANDISE BROKERS
2701 EASTERN MERCHANDISE...JLY,PRECIOUS METALS
2701 EASTERN MERCHANDISE CO...JEWELRY-MANUFACTURERS
2729 LIGHTING SUPPLY CO...LIGHTING,LAMPS,ACCES
2801 CRESCENT ARMS DRYCLEANING...LAUNDRY/GARMENT SERVICES
2801 CRESCENT ARMS DRYCLEANING...GMT PRESSG,CLRS AGT
2815 AMALGAMATED TRANSIT UNION...LABOR ORGANIZATIONS
2815 AMERICAN FINANCIAL SOLUTIONS...MISC PERSONAL SVS
2815 BANNER BANK...NATIONAL COML BANKS
2815 BANNER BANK...BANKS
2815 BOVIS LEND LEASE INC...CONSTRUCTION MANAGEMENT
2815 BOVIS LEND LEASE INC...MANAGEMENT SERVICES
2815 BUYONET US INC...COMPUTER SOFTWARE
2815 C T S...DEV MARKETING AND DIST A DIVERSE MIX OF PRODUCTS FOR TH
2815 CLEANWORKFORCE.COM...BLD MAINTENANCE SVS
2815 COOLANIMALSTUFF.COM...GIFT SHOPS
2815 COOLANIMALSTUFF.COM...GIFT SHOP
2815 COOLANIMALSTUFFCOM...RETAILS GENERAL MERCHANDISE
2815 DENALI PRINCESS LODGE...RESORT HOTELS
2815 FLYING LAB SOFTWARE...COMPUTER SOFTWARE
2815 GEORGIA RICE & SONS...COMMERCIAL PRINTING
2815 INC BOYONET US...WEBSITE DESIGN SERVICE
2815 INTER CO-OP USA...COOPERATIVES
2815 J C DECAUX AIRPORT ADVERTISING...ADVERTISING-INDOOR
2815 J PRICE INC...GENERAL CONTRACTORS

2008 2ND AVE
SOURCE: DIGITAL BUSINESS DIRECTORY

Part 5 of 6

2815 K G N W & K L F E...RADIO BROADCAST STATION
2815 K K O L A M 1300...RELIGIOUS ORGANIZATION
2815 KLFE...RADIO BRDCSTG STNS
2815 LAKELAND PROPERTIES...SUBDIVIDERS & DEVEL
2815 LOCAL 587...LABOR ORGANIZATION
2815 NEONGECKO.COM INC...DATA PROC & PREP
2815 PRINCESS CRUISES...TRAVEL AGENCIES
2815 PRINCESS TOURS...TRAVEL AGENCY TOUR OPERATOR
2815 REPUBLIC PARKING...AUTOMOBILE PARKING
2815 SALEM RADIO REPRESENTATIVES I...ADVERTISING REPRESENTATIVE
2815 SLINGSHOT COMMUNICATIONS...COMMUNICATIONS SVS
2815 US EQUAL EMPLOYMENT OPPORTUNTY...SOCIAL/HUMAN SERVS
2815 WPAS INC...PENSION,HEALTH FUND
2819 WORLD COUP COFFEE...RET COFFEE SHOP
2819 WORLD CUP COFFEE INC...COFFEE SHOP
2821 ARNIE BERGH...COMMERCIAL BUILDING OPERATOR
2821 AYUMI OKAVE...RESIDENTIAL
2821 B R SHELDON...RESIDENTIAL
2821 BAY VISTA TOWER CONDOMINIUMS...CONDOMINIUM ASSOCIATION
2821 BAY VISTA TOWER CONDOMINIUMS...DWELLING OPERATORS
2821 BEGINNING...PERIODICALS-PUBLISHING/PRINTING
2821 BRAD PHILLIPS...RESIDENTIAL
2821 BROWN DEVELOPMENT LLC...DEPOSITORY BANKING SERVICES
2821 BRUCE & JUDY A WALKER...RESIDENTIAL
2821 CHARLES K HOLMES INC...MANAGEMENT CONSULTING SERVICES
2821 CHRISTOPHER L HARRIS...RESIDENTIAL
2821 DAVID & JANNY QUIST...RESIDENTIAL
2821 DEANS CRUISE & TRAVEL...VOCATIONAL SCHOOL
2821 DUANE R DIER...RESIDENTIAL
2821 EDWARD P STAHL...RESIDENTIAL
2821 F & C MERRITT...RESIDENTIAL
2821 G FERRAND...RESIDENTIAL
2821 GEORGE MATSUDA...RESIDENTIAL
2821 GEORGE YAMAMOTO...RESIDENTIAL
2821 H S SUZUKI...RESIDENTIAL
2821 HOWARD WEINER...RESIDENTIAL
2821 IKE ALHADEFF...RESIDENTIAL
2821 J A SCHOLTE...RESIDENTIAL
2821 JAMES & SHIRLEY BARRETT...RESIDENTIAL
2821 JAMES H REED...RESIDENTIAL
2821 JAYNE ROSS...RESIDENTIAL
2821 JERRY & JUDY ALHADEFF...RESIDENTIAL
2821 JIM CONTINI...RESIDENTIAL
2821 JIM DALKE...RESIDENTIAL
2821 JOHN BRAZIER...RESIDENTIAL
2821 JOHN W JR WEAVER...RESIDENTIAL
2821 JOHNSTON TRAINING GROUP INC...TRAINING PROGRAMS & SERVICES
2821 JOSE GOULD...RESIDENTIAL
2821 KRISTIN & TIM RICH...RESIDENTIAL
2821 KRISTINE KUREY...RESIDENTIAL
2821 KUREY CO...ADVERTISING SVS NEC
2821 L & E GOURLIE...RESIDENTIAL
2821 L M GRAY...RESIDENTIAL
2821 LANCE KOSTROBALA...RESIDENTIAL
2821 LARRY & SANDRA J SMITH...RESIDENTIAL
2821 MAX KAMINOFF...RESIDENTIAL
2821 PEGGY & JACK BOYLE...RESIDENTIAL
2821 PIETER VANWINGERDEN...RESIDENTIAL
2821 PRACTICE DEVELOPMENT INC...HEALTH SERVICES NEC
2821 ROBERT & JOYCE HAMILTON...RESIDENTIAL
2821 ROBERT & PATRICIA CLARK...RESIDENTIAL
2821 ROBERT B EDGERS...RESIDENTIAL
2821 ROBERT LEE...RESIDENTIAL
2821 ROBERT WINTNER...RESIDENTIAL
2821 RODNEY A MD BROWN...RESIDENTIAL
2821 ROGER & PATRICIA H TUCKER...RESIDENTIAL
2821 RUSS & KRIS PARK...RESIDENTIAL
2821 SAMUEL L SELINGER...RESIDENTIAL

2008 2ND AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

Part 6 of 6

2821 **TIMOTHY & NADINE O'DONOVAN**...*RESIDENTIAL*
2821 **WAYNE JONES**...*RESIDENTIAL*
2827 **BANNER BANK**...*BANKS*
2827 **BANNER BANK**...*NATIONAL COML BANKS*
2911 **ALLIANCE HEALTHCARE CORP**...*HOME HEALTH CARE SERVICES SKILLED NURSING CARE FACILITY*
2911 **ENGINEERING & DESIGN SVC**...*GOVERNMENT OFFICES-CITY, VILLAGE & TWP*
2911 **FERRIES ADM**...*GOVERNMENT OFFICES-STATE*
2911 **MARINE DIVISION/STATE FERRYS**...*MARINE REGUALTION & TRANSPORT*
2933 **ALICE WINSHIP**...*RESIDENTIAL*
2933 **BRENDON INMAN**...*RESIDENTIAL*
2933 **G GARFIELD**...*RESIDENTIAL*
2933 **J ALBERT**...*RESIDENTIAL*
2933 **LYANNE MA**...*RESIDENTIAL*
2933 **M J AMBROSE**...*RESIDENTIAL*
2933 **MAUREEN TAYLOR**...*RESIDENTIAL*
2933 **MICHELE A GUIHAN**...*RESIDENTIAL*
2933 **NICHOLAS HANSON**...*RESIDENTIAL*
2933 **SHERMAN A ISENSEE**...*RESIDENTIAL*
2933 **T LACEY**...*RESIDENTIAL*
2933 **TROY E STEPHENS**...*RESIDENTIAL*
2933 **WINDERMERE APARTMENTS**...*APARTMENT BLD OPERS*

2008 CLAY ST

SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND

88 total records. Part 1 of 2

2600 OPEN ORGANIZATION...INDUSTRIAL AND LABOR CONSULTING SERVICES
2600 SEATTLE COMMUNICATIONS GROUP...RADIO AND TELEVISION EQUIPMENT AND PARTS
2600 SEATTLE HEIGHTS CONDO OWNERS
2600 SEATTLE HEIGHTS CONDOMINIUMS
2600 SEATTLE PACIFIC INVESTMENTS
2601 MOTHER NATURE INC...MISCELLANEOUS RETAIL STORES, NEC, NEC
2602 INTERNATIONAL KITCHENS
2606 CROWN COMMUNICATION...COMPUTER PERIPHERAL EQUIPMENT
2606 HOME OFFICE
2607 CARA HASKEY DESIGN
2607 CELLO TECHNOLOGIES SEATTLE
2607 MORSE BEST INNOVATION...COMPUTER PERIPHERAL EQUIPMENT
2607 RETAIL GROUP
2608 ADVANTAGE PROCESS & INVSTGTNS
2608 BAYSIDE INVESTIGATIONS
2608 PAUL HENRY ARCHITECTURE
2620 SPA BELLISSIMA
2621 A TAI...RESIDENTIAL
2621 ANDREW T HENGESTEG...RESIDENTIAL
2621 ARTHUR L ATHERTON...RESIDENTIAL
2621 B CORNER...RESIDENTIAL
2621 C GROSS...RESIDENTIAL
2621 CLAUDE CAMPBELL...RESIDENTIAL
2621 DAN DOLAN...RESIDENTIAL
2621 E J SULLIVAN...RESIDENTIAL
2621 FRED H DRUMMOND...RESIDENTIAL
2621 G E GOEHRING...RESIDENTIAL
2621 GEORGE SUDDOCK...RESIDENTIAL
2621 GORDON F VICKERY...RESIDENTIAL
2621 HARBOUR HEIGHTS HOA
2621 M TAKAHASHI...RESIDENTIAL
2621 MART NAPA...RESIDENTIAL
2621 RICHARD BOYCE...RESIDENTIAL
2621 ROBERT K CHAN...RESIDENTIAL
2621 RODGER BENSON...RESIDENTIAL
2623 GLOBAL FINANCE & INVESTMENT CO...REAL ESTATE LEASING AND RENTALS
2623 INTERPACIFIC INVESTORS SVC...SECURITY BROKERS AND DEALERS
2623 WILT DENNIS & ASSOC...SECURITY BROKERS AND DEALERS
2701 EASTERN MERCHANDISE CO...JEWELRY APPAREL
2729 LIGHTING SUPPLY INC
2801 CRESCENT ARMS DRYCLEANING...LAUNDRY AND DRYCLEANER AGENTS
2815 BUYONET US INC...COMPUTER PERIPHERAL EQUIPMENT
2815 CELLULAR TECHNICAL SVC CO INC...COMPUTER PERIPHERAL EQUIPMENT
2815 CLAYTON POOLE & ASSOC
2815 CLEAN WORKFORCE.COM...BUILDING COMPONENT CLEANING SERVICE
2815 INC BOYONET US
2815 INTER CO-OP USA
2815 J C DECAUX AIRPORT ADVERTISING
2815 JOHN J PRICE INC
2815 KGNW...RADIO BROADCASTING STATIONS, MUSIC FORMAT
2815 KKOL...RADIO BROADCASTING STATIONS, MUSIC FORMAT
2815 KLFE...RADIO BROADCASTING STATIONS, MUSIC FORMAT
2815 P & J WHOLESALE INC
2815 PACIFIC NORTHWEST GRANTMAKERS...GROWERS' ASSOCIATIONS
2815 PHILANTHROPY NORTHWEST...GROWERS' ASSOCIATIONS
2815 PRINCESS CRUISES & TOURS
2815 SALEM RADIO REPRESENTATIVES...ELECTRONIC MEDIA ADVERTISING REPRESENTATIVES
2815 SLINGSHOT COMMUNICATIONS
2815 UBARTER.COM
2815 WORLD COM...ONLINE SERVICE PROVIDERS
2815 WPAS INC...UNION FUNDS
2819 WORLD CLASS COFFEE
2821 ALLAN AQUILA...RESIDENTIAL
2821 ANNE L GERBER...RESIDENTIAL
2821 AYUMI OKAVE...RESIDENTIAL

2003 2ND AVE
SOURCE: DIGITAL BUSINESS DIRECTORY

Part 2 of 2

2821 BAY VISTA TOWER CONDOMINIUMS
2821 CHARLES D ALHADEFF...RESIDENTIAL
2821 DENNIS KELLY...RESIDENTIAL
2821 DUANE R DIER...RESIDENTIAL
2821 FLOY J HAGEN...RESIDENTIAL
2821 J A SCHOLTE...RESIDENTIAL
2821 JIM CONTINI...RESIDENTIAL
2821 L GOURLIE...RESIDENTIAL
2821 LANCE KOSTROBALA...RESIDENTIAL
2821 LESLIE AUERBACH...RESIDENTIAL
2821 MAX KAMINOFF...RESIDENTIAL
2821 MEDIUN LIMITED
2821 PIETER VANWINGERDEN...RESIDENTIAL
2821 PRACTICE DEVELOPMENT INC
2821 R L STENSHOEL...RESIDENTIAL
2821 R S DOWNIE...RESIDENTIAL
2821 ROBERT C C U GOULD...RESIDENTIAL
2821 ROBERT J NORRIS...RESIDENTIAL
2911 FERRIES ADM OFFICE...LEGISLATIVE BODIES, STATE AND LOCAL
2933 J A OLINCY...RESIDENTIAL
2933 J M THOMAS...RESIDENTIAL
2933 LADD STEISKAL...RESIDENTIAL

2003 CLAY ST

SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND

2000 2ND AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

116 total records. Part 1 of 2

2600 **A SMILE-GELATI**
2600 **CRAIG CREATIVE RADIO SCRIPTS**
2600 **FASHION SALES**
2600 **MISSING SPOKE PRESS**
2600 **OPEN ORGANIZATION**...*INDUSTRIAL AND LABOR CONSULTING SERVICES*
2600 **SEATTLE HEIGHTS CONDOMINIUMS**
2601 **MOTHER NATURE INC**...*MISCELLANEOUS RETAIL STORES, NEC, NEC*
2602 **INTERNATIONAL KITCHENS**
2606 **HOME OFFICE**...*COMPUTER SOFTWARE AND ACCESSORIES*
2607 **RETAIL GROUP**...*ARCHITECTURAL ENGINEERING*
2607 **WHITEJAY INTERNATIONAL INC**
2608 **ADVANTAGE PROCESS & INVSTGTNS**
2608 **BAYVIEW INVESTIGATIVE AGENCY**
2608 **COST RESEARCH**...*COMPUTER PERIPHERAL EQUIPMENT*
2608 **RELIABLE MOVERS**
2608 **UNION RESOURCE NETWORK/SNAP**
2616 **BELLTOWN INTERNATIONAL CAFE**...*STEAK AND BARBECUE RESTAURANTS*
2620 **SPA BELLISSIMA**
2621 **A TAI**...*RESIDENTIAL*
2621 **ANDREW T HENGESTEG**...*RESIDENTIAL*
2621 **ARTHUR L ATHERTON**...*RESIDENTIAL*
2621 **B CORNER**...*RESIDENTIAL*
2621 **BENETT INVESTIGATIONS INC**
2621 **BOB WILKES**...*RESIDENTIAL*
2621 **C GROSS**...*RESIDENTIAL*
2621 **DAN DOLAN**...*RESIDENTIAL*
2621 **DON WADE**...*RESIDENTIAL*
2621 **E J SULLIVAN**...*RESIDENTIAL*
2621 **FRANK S PANZICA**...*RESIDENTIAL*
2621 **FRED H DRUMMOND**...*RESIDENTIAL*
2621 **G E GOEHRING**...*RESIDENTIAL*
2621 **GEORGE SUDDOCK**...*RESIDENTIAL*
2621 **GORDON F VICKERY**...*RESIDENTIAL*
2621 **HARBOUR HEIGHTS HOA**
2621 **J W D ROBINSON**...*RESIDENTIAL*
2621 **JOHN Y SKELLY**...*RESIDENTIAL*
2621 **LILLY M W GROSS**...*RESIDENTIAL*
2621 **M TAKAHASHI**...*RESIDENTIAL*
2621 **MART NAPA**...*RESIDENTIAL*
2621 **OVERCOMERS VICTORIOUS INC**
2621 **RICHARD BOYCE**...*RESIDENTIAL*
2621 **ROBERT K CHAN**...*RESIDENTIAL*
2621 **RODGER BENSON**...*RESIDENTIAL*
2621 **WILLIAM F ROUSH**...*RESIDENTIAL*
2623 **GLOBAL FINANCE & INVESTMENT CO**...*REAL ESTATE LEASING AND RENTALS*
2623 **INTERPACIFIC INVESTORS SVC**...*SECURITY BROKERS AND DEALERS*
2626 **PENINSULA GALLERY**
2701 **EASTERN MERCHANDISE CO**...*JEWELRY APPAREL*
2729 **LIGHTING SUPPLY INC**
2801 **CRESCENT ARMS DRYCLEAN**...*LAUNDRY AND DRYCLEANER AGENTS*
2815 **BAY VISTA PROPERTY MANAGER**
2815 **BUYONET US INC**...*COMPUTER PERIPHERAL EQUIPMENT*
2815 **C T TAKAHASHI & CO**...*FIREARMS AND AMMUNITION, EXCEPT SPORTING*
2815 **CLAYTON POOLE & ASSOC**
2815 **GRAN CORP INC**...*REAL ESTATE LEASING AND RENTALS*
2815 **INTER CO-OP USA**
2815 **J PRICE INC**
2815 **JOHN J PRICE INC**
2815 **KGNW**...*RADIO BROADCASTING STATIONS, MUSIC FORMAT*
2815 **KKMOAM**...*RADIO BROADCASTING STATIONS, MUSIC FORMAT*
2815 **KKOL**...*RADIO BROADCASTING STATIONS, MUSIC FORMAT*
2815 **KLFE**...*RADIO BROADCASTING STATIONS, MUSIC FORMAT*
2815 **KLFEAM**...*RADIO BROADCASTING STATIONS, MUSIC FORMAT*
2815 **LOCALIZATION & CONSULTING SVC**...*COMPUTER PERIPHERAL EQUIPMENT*
2815 **MCI WORLD COM**...*ONLINE SERVICE PROVIDERS*

2000 2ND AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

Part 2 of 2

2815 **ROSS DE ALESSI LIGHTING DESIGN**...*TESTING SERVICES*
2815 **SALEM RADIO NETWORK**...*THEATRICAL PRODUCERS*
2815 **SALEM RADIO REPRESENTATIVE**...*ELECTRONIC MEDIA ADVERTISING REPRESENTATIVES*
2815 **SATORI SOFTWARE**...*COMPUTER PERIPHERAL EQUIPMENT*
2815 **STREET TALK MINISTRIES**
2815 **UBARTER COM INC**
2815 **US EQUAL EMPLOYMENT OPPORTUNTY**...*INCOME MAINTENANCE PROGRAMS*
2815 **WPAS INC**...*UNION FUNDS*
2819 **WORLD CLASS COFFEE**
2821 **ALLAN AQUILA**...*RESIDENTIAL*
2821 **ANNE L GERBER**...*RESIDENTIAL*
2821 **AYUMI OKAVE**...*RESIDENTIAL*
2821 **BAY VISTA TOWER CONDOMINIUMS**
2821 **BRAD PHILLIPS**...*RESIDENTIAL*
2821 **C A MADISON**...*RESIDENTIAL*
2821 **CHARLES D ALHADEFF**...*RESIDENTIAL*
2821 **DAYTON R CLARK**...*RESIDENTIAL*
2821 **DENNIS KELLY**...*RESIDENTIAL*
2821 **DUANE R DIER**...*RESIDENTIAL*
2821 **FLOY J HAGEN**...*RESIDENTIAL*
2821 **HOWARD WEINER**...*RESIDENTIAL*
2821 **J A SCHOLTE**...*RESIDENTIAL*
2821 **JIM CONTINI**...*RESIDENTIAL*
2821 **KEN WHERRY**...*RESIDENTIAL*
2821 **L GOURLIE**...*RESIDENTIAL*
2821 **L M STILINOVIC**...*RESIDENTIAL*
2821 **LANCE KOSTROBALA**...*RESIDENTIAL*
2821 **LARRY J SMITH**...*RESIDENTIAL*
2821 **LESLIE AUERBACH**...*RESIDENTIAL*
2821 **MAX KAMINOFF**...*RESIDENTIAL*
2821 **N L LEE**...*RESIDENTIAL*
2821 **PIETER VANWINGERDEN**...*RESIDENTIAL*
2821 **PRACTICE DEVELOPMENT INC**
2821 **R L STENSHOEL**...*RESIDENTIAL*
2821 **R S DOWNIE**...*RESIDENTIAL*
2821 **ROBERT B EDGERS**...*RESIDENTIAL*
2821 **ROBERT C C U GOULD**...*RESIDENTIAL*
2821 **ROBERT J NORRIS**...*RESIDENTIAL*
2821 **SHAKLEE DISTRIBUTOR**
2821 **WAYNE R JONES**...*RESIDENTIAL*
2821 **WILLIAM C MCCAMANT**...*RESIDENTIAL*
2827 **COMPUTER RENAISSANCE INC**
2827 **SEATTLE TECHNOLOGY CORP**...*CUSTOM COMPUTER PROGRAMMING SERVICES*
2911 **ENGINEERING & DESIGN SVC**...*LEGISLATIVE BODIES, LEVEL OF GOVERNMENT*
2911 **FERRIES ADM OFFICE**...*LEGISLATIVE BODIES, STATE AND LOCAL*
2933 **J A OLINCY**...*RESIDENTIAL*
2933 **J M THOMAS**...*RESIDENTIAL*
2933 **JOHN L KING**...*RESIDENTIAL*
2933 **LADD STEISKAL**...*RESIDENTIAL*
2933 **LARRY B BOVENKAMP**...*RESIDENTIAL*

2000 CLAY ST

SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND

1994 2ND AVE-A

SOURCE: COLE

2319 ★ Sports Specities .76 441-8412
2320 ★ Kways Rendezvous .89 441-5823
★ Rendezvous .70 ⊙ 441-5823
2321 ★ Morales Studios ¤ 443-1808
2323 Samuel D Redfield ■ 448-5492
2324 ★ Holmans Body&Fendr .76 441-7871
2327 Wm Tell Hotel
Roger Beavers ¤ 448-4035
116 Cameron Cook ■ 448-1874
Frank Czuba .88 728-1654
317 Alvin Henrikson ■ 441-6596
Margaret Hollister ¤ 728-9608
112 Charles Kimble ■ 728-2029
216 Jim Lindsay ■ 441-0263
Lewis M Lindsey ¤ 441-3662
108 Daniel Padar ■ 448-9679
109 Charles Schoening .91 441-3872
106 Caylan Storm ■ 448-1512
John M Willis ¤ 441-7390
114 Thomas J Wozniak .91 443-0738
★ William Tell Hotel .87 443-9196
2331 ★ Blu Canary Statnry .91 443-3328
★ Cafe Septieme .92 448-1506
★ Imago De Lineo .92 441-8522
★ Septieme .87 ⊙ 448-1506
2334 ★ Business Tax Serv .74 728-6560
— 200 BATTERY
2402 Concord Apts
109 Misqu Abdi ■ 448-4293
305 G M Brown ■ 441-5067
208 Renee Crage .90 448-9442
Wayne Dellacqua .91 443-1369
310 J Fletcher .84 728-2236
309 A Kieffer .92 448-0334
103 T M Larue ■ 441-9588
C102 Joseph S Lee ■ 448-3082
303 Renee Martin .92 443-3518
205 David J Meltzer .86 441-1918
104 Maritza Mera .91 443-0989
Yasunari Otsuka ¤ 441-7972
107C Helen E Shelley .92 441-4038
C W Truenski ¤ 441-6046
Linda L Wallin .90 728-1782
307 Billy Williams .88 441-4327
2408 Lexington Apts
203 Stephen Braden ¤ 441-5765
309 Romel R Bustillo ■ 441-0107
205 Arthur Fiske .82 448-7528
109 Betty Flojo ■ 448-8706
308 Kinuyo Hirota .88 728-0524
101 Robin M Kinchen ■ 441-4464
D E Markes ¤ 448-5903
L302 Tia Meacham - 728-5839
104 Robert R Munnell .88 448-5255
201 J Poeschl ■ 443-2110
L302 Tia Rat - 728-5839
210 Tosh Rosford ■ 728-4351
Mohammad Saleh .90 441-3048
102 A Seyler ■ 728-1738
305 T Stefani .92 443-0105
107 Dean Eric Stephen ■ 441-9087
306 S Tate .87 448-9233
Ralph Winters - 448-3316
2412 ★ Pro Tape NW .89 441-8273
★ Protape Northwest .89 ⊙ 441-8273
2415 Apartments
545 Craig Brown ■ 448-4281
542 Doyle Carmody ■ 441-8143
328 Meg Charter ■ 441-7114
737 Thomas R Edwards ■ 728-4036
749 Ron Field ■ 441-4969
642 Marion W Jervay ■ 441-4994
337 Jesse Johnson ■ 448-0570
426 Garrett Marr ■ 443-9863
429 Todd S Miller ■ 443-2331
539 Gary D Pearce ■ 443-9768
347 Ralph Peterson ■ 443-3848
349 T I Shults ■ 441-9263
629 Walter W Tunstall ■ 728-6441
426 Eric D Yaver ■ 443-1986
2416 ★ Sarco Apince Rpr .86 441-5977
2419 Apartments
329 Pete Korfiatis ■ 728-8464
2420 ★ Dione Kennedy .90 448-6400
★ Windemere Rl Est .84 ⊙ 448-6400
2421 NP
— 200 WALL
2502 ★ 2505 2nd Av Mgt - 448-1004
2505 Building
★ Arbor Deli .90 448-8443
★ Arbor Plc Garage .90 441-5470
★ Bosley Med Group .90 728-7500
★ Bowden&Kellet Mrkt .90 448-8855
★ Christiania Bnk .90 448-1225
★ Computer Repair .91 448-3499
★ Computer Serivce .91 ⊙ 448-3499
★ Computer Upgrades .91 ⊙ 448-3499
★ Corp Trvl Mgmnt ¤ 443-5406
620 ★ Design Plus .90 728-1700
★ Envirmntl Solutns .92 441-7888
★ Fmly Dry Cleaning .90 448-3368
★ Fivash Pub Group ¤ 441-8415
★ Griffin College .92 728-6800
★ Hnwh ¤ 441-6930
★ Hapag-Lloyd Agencs .91 448-6789
★ Hapag-Lloyd Europe .91 ⊙ 448-6789
★ The Interep Radio .91 443-1774
★ KCTS Nine Mag ¤ ⊙ 441-8415
★ Macks Pioneer Bg .92 443-1255
★ Major Market Radio .92 728-8016
★ McGavren-Guild Inc .91 441-3401
★ PC Fixx Srvc Cntr ¤ ⊙ 448-3499
★ Pts Tours - 443-5445
★ Penninsula Magzn ¤ ⊙ 441-8415
★ Rainbow Flwr Co .91 728-1880
★ Real Estate Inc .90 441-4660
★ Return To Christ Lv ¤ ⊙ 441-8415
★ G Slaughter&Assoc .91 448-1715
★ Trsprtn Inst .90 443-1738
★ Washington CEO .90 ⊙ 441-8415
★ We St Nurses Assoc .91 443-9762
★ World Travelers .92 443-5632
2512 Carpenters Cntr Bg
See Building Drty
— 200 VINE
2600 Apartments
809 Jack Colman ■ 443-6870
2003 Richard A Davis ■ 728-1323
511 Steven Kolb ■ 443-3215
503 Hsi-Ming Pan ■ 728-0740
2601 ★ Mthr Nature Gemcrf ¤ 728-5952
2607 ★ Antioch University .88 441-5352
2617 2619 NP

1605 A Lee Atherton .83 443-2022
1503 R Benett .90 441-6063
1101 Rodger Benson .90 441-9128
901 Richard Boyce .89 • 443-9372
Dr Rodney A Brown .88 728-2231
P C Bull ¤ 728-9627
501 Robert K Chan .87 • 443-1671
1602 Tracy Cooper ■ 448-2340
1001 B Corner .82 441-5840
Lawrence Davenport ¤ 441-9233
Edward Dawson .92 448-9053
301 Renzo Difuria .92 728-0150
1603 Dan Dolan .84 • 441-1484
803 Fred H Drummond .82 • 441-4166
Robert B Edgers .88 443-0315
John C Erickson .90 • 441-9405
708 William D Farley .92 441-1802
1205 Dr Peter Fisher - 728-9997
1004 Dr Jas Garrison Jr .88 • 441-3623
1404 G E Goehring .88 441-4141
704 Cliff Gross .90 • 441-9665
704 Lilly M Gross .90 441-9665
1504 George R Guppy .90 • 441-5043
604 D Harder .85 441-0170
1403 W Harisberger .82 441-5027
1405 Andrew T Hengesteg .85 • 441-4449
Dexing Kong ¤ 728-7778
1601 Yves J Kron .91 448-7861
1703 John T Kugler ¤ 441-1821
1005 William M Lendman - 448-0100
306 Steven D Lockwood ■ 441-7293
M D Lowman - 448-7542
David Mahler .90 728-2048
707 K Mandell .86 441-9267
Marcia M Meade .92 448-9053
L Mitchell ¤ 441-5967
1204 David Morris .92 • 728-9626
M Napa .86 441-4770
David Oglevie .92 • 728-0878
David Oglevie .90 • 448-5663
1201 David Oglevie .90 • 448-2500
1701 Frank S Panzica .84 • 441-9520
J W Robinson .89 • 441-9643
1105 William F Roush .87 • 443-9019
902 Stephen L Schenzel ¤ 448-1173
Robert Schoeben ¤ 448-0609
804 Bright Sheng ¤ 728-7650
904 John L Silva .91 443-8638
1505 John Y Skelly .82 • 728-2621
1702 George Suddock .83 • 728-0101
406 E J Sullivan .82 • 448-0628
1604 A Tai .83 448-9132
M Takahashi .83 728-9330
1704 D B Thorud .89 • 448-7892
1804 Gordon F Vickery .83 • 448-0448
1803 Don Wade .85 443-9233
304 Bob Wilkes .82 441-2777
1903 Eugene E Yore .90 • 443-9393
505 K Zaugg .89 • 728-4608
★ Atwood-Valentine .84 448-1590
★ Farmers Ins Group - ⊙ 448-1590
★ Harbour Hgts Hos .87 441-7734
— 200 CEDAR
2701 ★ Eastern Merchands .83 448-4466
2713 2715 NP
2729 ★ Lighting Supply Co 441-5075
— 200 CLAY
2801 ★ Crescent Arms Dry .87 441-7107
2805 ★ China Silver&Cryst .87 441-8906
2815 Bay Vista Building
See Building Drty
2819 ★ World Class Coffee .90 441-2967
★ World Cup Coffee .90 ⊙ 441-2967
2821 Bay Vista Tower
Condo
1802 Charles D Alhadeff .89 441-7767
701 James Arasim .91 448-4316
2003 L Auerbach .85 • 441-9029
1004 D Blond .91 443-3412
1001 John Brazier .92 441-9432
1605 Earl K Buchan ■ 448-5380
801 Dayton R Clark .84 • 441-3339
Robert Claus .89 728-7721
210 John E Conner .85 441-5697
Jim Contini ¤ 728-0605
Paul Daigle .90 • 441-4722
805 Duane R Dier .87 443-9030
1104 R S Downie .86 • 441-0362
1004 I K Ezra .90 • 443-3412
1803 Charles E Finney .92 441-5758
Anne L Gember .86 441-1625
1701 Capt Robt C Gould .89 • 728-1368
L Gourlie .84 441-5634
Ethel L Graham .87 728-4848
2203 Garth W Green .90 728-1715
2203 Richard J Green .90 • 728-1715
1201 Leonard A Haba ■ 448-4971
1801 Floy J Hagen .83 728-9300
1002 Bernard Haldane ■ 448-0881
904 Robert Hamilton .90 • 441-6443
Harry L Harden - • 728-7643
Roberta Jensen ■ 443-6836
905 Wayne Jones .90 • 448-8667
1804 Max Kaminoff .85 • 441-2821
1202 Dennis Kelly .89 • 448-7822
1204 Kosei Kenmotsu ¤ 728-0133
Kosei Kenmotsu .86 728-0135
Lance Kostrobala .89 • 441-8127
1103 Kristine Kurey - 441-2202
M L Lee .89 448-8822
705 Robert Lee .90 • 443-0144
705 C A Madison .87 • 443-1345
1005 William C McCamant .90 441-1498
1302 Robert J Norris .91 • 728-4325
1501 Timothy O'Donovan ■ 441-9874
902 Ayumi Okave .90 441-0480
Mrs M Ostrander - 448-0943
1403 Brad Phillips .91 443-1101
1101 M E Preble .91 448-4316
701 Timothy Rich .92 443-0534
Jerry E Rosenthal .90 • 728-8602
Yuri Sasaki ■ 448-7685
2001 J A Scholte .91 448-9154
Larry J Smith Atty .91 • 728-4402
1601 Larry J Smith .89 • 728-4402
1601 R L Stenshoel .88 • 728-5162
1504 L M Stilinovic .89 • 728-1047
H S Suzuki - 448-6876
P Vanwingerden .91 448-5857
2102 Bruce A Walker .90 • 441-5541
1902 Howard Weiner .89 441-8127
1103 Ken Wherry .91 448-0321
1003 Oscar K Will .90 441-0948
★ Bay Vista Twr Cndmn .83 448-9547


1994 2ND AVE-B

SOURCE: COLE

2827 ★ All In 1 Deli .92 441-9393
— 200 BROAD
2911 ★ Found Intl Coop&Dv .92 728-1902
★ Cty Preservtn Prog .91 684-0777
★ Cty Pk Prsrvtn Prg .91 684-9777
★ Cty Prk Open Space .91 ⊙ 684-0777
2933 Windemere Apts
Clark I Abe .92 441-8976
Jeff Benoliel .90 728-1524
Jeff Benoliel .90 728-6867
110 Larry B Bovenkamp .91 443-4487
109 Marcus A Brown ■ 448-2652
204 Wm H Dehuff Jr .91 441-9123
Rafael E Flores .92 443-4677
104 Michele A Guihan ■ 448-5360
202 John L King .89 448-4308
310 Stephanie Kluger ■ 448-0326
101 Todd J Kluger ■ 728-1524
John Moser ¤ 448-0309
301 James V Santoro .65 728-6025
Ken Sato .92 441-3352
308 Todd Spence ■ 448-9214
Ladd Steiskal Jr .88 441-3512
Ed J Strumpfer ¤ 441-4926
103 J M Thomas ¤ 441-1357
305 Andrea Vitalich ■ 441-9445
207 Raymond Williams ¤ 728-2021
A Winship .90 448-0707
2934 NP
— PARALLEL STS
— 1ST
— 3RD
570 RESIDENCE 293 BUSINESS

1994 CLAY ST

SOURCE: COLE



CLAY ST 98121

New Street-1991.

1- 299 CT 80 $A..G13

300- 499 CT 72 $B..G13

THOMAS BROS MAP LOC K 564-H5

63★Natl Video Tape Co . .91 441-1182

1 BUSINESS

1990 2ND AVE-A

SOURCE: COLE

305 Jeannie M Falls 88 448-8551
2405★ Bard Sales 78 728-9200
★ Incentive Sales Co . . 78 ⊙ 728-9200
2408★ Lexington Apts
Laurel Allen 89 448-7433
Lionel Arsenault 89 441-1416
Arthur Fiske 82 448-7528
Kinuyo Hirota 88 728-0524
Charles McAteer 89 441-5356
Mohammad Saleh . . . . H 441-3048
Dennis Sullivan . . . . – 443-7903
104 Robert R Munnell 88 448-5255
306 Stephanie Tate 87 448-9233
2412★ Pro Tape NW 89 441-8273
★ Protape Northwest . . 89 ⊙ 441-8273
2415★ Jerry Chinn . . . . H 443-0982
★ Prop&Costume 88 433-2025
2416★ Sarco Apince Rpr . . 86 441-5977
2417★ Simpson Photogrphy . . 86 441-7789
2420★ Dione Kennedy . . . . H 448-6400
★ Windemere RI Est . . 84 ⊙ 448-6400
★ Windemere RI Est . . 88 283-8080
2421 . . . . . NP
— 200 WALL
2505★ Arbor Deli . . . . H 448-8443
★ Arbor Plc Garage . . . H 441-5470
★ Bailie Communctns . . H 443-5606
★ Bailie Sh Broadcst . . – 448-1231
★ Bosley Med Group . . – 728-7500
★ Bowden&Kellet Mrkt . . H 448-8855
★ Christiania Bnk . . . – 448-1225
★ Fmly Tlrng&Altrtn . . H 448-3368
★ Kathy J Rall Aty . . . 89 441-8840
★ Sterne&Rall Aty . . . 89 ⊙ 441-8840
★ Richie Sterne Aty . . 89 ⊙ 441-8840
★ G M Stieber CPA . . . – 441-1641
★ Christopher Sutton . . 89 ⊙ 441-8840
★ Trsprtn Inst . . . . H 443-1738
★ Washington Ceo . . . H 441-8415
620 ★ Design Plus . . . . H 728-1700
700 ★ Magic Fngrs Grphc . . – 443-2707
2512★ Carpenters Cntr Bg
★ See Building Drty
— 200 VINE
2600★ 2nd Av Oasis . . . . H 728-9090
2601★ Shear Grphcs Athnt . . 88 441-3836
2607★ Antioch University . . 88 441-5352
2612★ Island Imprints . . . H 441-7147
2617★ Glbl Finance&Invst . . 89 448-2405
★ Gary Lundgren . . . . H 728-1438
S Gary Lundgren . . . . ■ 441-4500
2619 . . . . . NP
2621 A Lee Atherton 83 443-2022
R Benett . . . . – 441-6063
Rodger Benson . . . . H 441-9128
Richard Boyce . . . . 89 ● 443-9372
Dr Rodney A Brown . . 88 728-2231
Wesley A Bull . . . . 82 ● 624-9827
William Calderhead . . . H 728-8578
B Corner 82 441-5840
Penelope Cummer . . . – 441-5043
Robert B Edgers 88 443-0315
Gloria Elliott 88 728-7240
Richard E Emerson . . . H 728-8107
John C Erickson . . . . H ● 441-9405
Alfred J Ferrara 83 448-7732
Dr Jas Garrison Jr . . . 88 ● 441-3623
Cliff Gross . . . . – ● 441-9665
Lilly M Gross . . . . – 441-9665
George R Guppy . . . . – ● 441-5043
D Harder 85 441-0170
W Harisberger 82 441-5027
Gary Harkey . . . . H 441-8143
V E Hild 82 441-9686
E Hofmann 89 441-8143
Erle Johnson . . . . H 448-4317
David Mahler . . . . – 728-2048
K Mandell 86 441-9267
Ken McEwan 89 441-9803
M Napa 86 441-4770
David Oglevie . . . . H ● 448-2500
David Oglevie . . . . H ● 448-5663
Kenneth M Ritchey . . . 84 ● 441-4411
J W Robinson . . . . 89 ● 441-9643
Peggy Ann Shepherd . . 84 441-4411
George Suddock . . . . 83 ● 728-0101
John G Sullivan 88 728-5150
A Tai 83 448-9132
M Takahashi 83 728-9330
Don Wade 85 443-9233
Dr Larry Wagner 89 448-7522
Wallace Wright 84 441-6410
Eugene E Yore . . . . H ● 443-9393
★ Atwood Valentine . . . 84 448-1590
★ Farmers Ins . . . . 84 ⊙ 448-1590
★ Harbour Hgts Hoa . . 87 441-7734
304 Bob Wilkes 82 441-2777
305 J Sample . . . . ■ 443-6940
404 Frances M Jones . . . 89 441-8231
406 E J Sullivan 82 448-0628
501 Robert K Chan . . . . 87 ● 443-1671
505 K Zaugg . . . . 89 ● 728-4608
706 John E Roberts . . . 85 728-1304
803 Fred H Drummond . . 82 ● 441-4166
902 Doug Kirstein . . . . ■ 448-8644
903 Scott Whitbeck . . . . ■ 448-2222
904 John L Silva . . . . ■ 443-8638
1102 Wanda Key . . . . ■ 443-8240
1105 William F Roush . . . 87 ● 443-9019
1204 W J Loacker 82 728-9799
1404 G E Goehring 88 441-4141
1405 Andrew T Hengesteg . . 85 ● 441-4449
1505 John Y Skelly . . . . 82 ● 728-2621
1601 Otto Ma 82 728-6012
1601 Yves J Kron . . . . ■ 448-7861
1602 T Komotsubara . . . . ■ 728-1439
1603 Dan Dolan . . . . 84 ● 441-1484
1701 Frank S Panzica . . . 84 ● 441-9520
1704 D B Thorud . . . . 89 ● 448-7892
1804 Gordon F Vickery . . 83 ● 448-0448
— 200 CEDAR
2701★ Eastern Merchands . . 83 448-4466
2713 2715 . . . . NP
2729★ Lighting Supply Co . . 441-5075
— 200 CLAY
2801★ Crescent Arms Dry . . 87 441-7107
2805★ China Silver&Cryst . . 87 441-8906
2815★ Bay Vista Bldg
★ See Building Drty
2821★ Bay Vista Tower
★ Condo
Charles D Alhadeff . . . 89 441-7767
Allan Aquila . . . . 89 ● 441-6908

1990 2ND AVE-B

SOURCE: COLE

2821	John Brazier	¤	441-9432
	Robert Claus	89	728-7721
	B D Coe	¤	728-5928
	John E Conner	85	441-5697
	Thomas J Conrad	84	441-7776
	Jim Contini	88	728-0605
	Paul Daigle	– ●	441-4722
	Milton Doumit	89	728-8125
	R S Downie	86 ●	441-0362
	I K Ezra	– ●	443-3412
	Anne L Gember	86	441-1625
	Mary Geyer	89	448-6279
	Capt Robt C Gould	89 ●	728-1368
	L Gourlie	84	441-5634
	Garth W Green	–	728-1715
	Richard J Green	– ●	728-1715
	Richard F Hahn	88 ●	443-9898
	Robert Hamilton	¤ ●	441-6443
	Kryoshi Ito	89	441-0714
	William R Jennings	89	441-7716
	Wayne Jones	¤ ●	448-8667
	Masao Kenmotsu	86 ●	728-0133
	Masao Kenmotsu	87 ●	728-0135
	Yasuhiro Koga	89	441-0712
	M L Lee	89	448-8822
	Robert Lee	– ●	443-0144
	William C McCamant	¤	441-1498
	Ross McDonald	89 ●	441-5627
	Ayumi Okave	¤	441-0480
	Jill Peck	89	441-8730
	Jerry E Rosenthal	¤ ●	728-8602
	L M Stilinovic	89 ●	728-1047
	Toru Takagi	89	441-0712
	Bruce A Walker	– ●	441-5541
	M White	¤	441-1568
	Oscar K Will	¤	441-0948
	★ **Bay Vista Condos**	85	441-9533
500	Harvey D Leap	84	448-9547
500	★ **Bay Vsta Twr Cndmn**	83	448-9547
801	Dayton R Clark	84 ●	441-3339
805	Duane R Dier	87	443-9030
903	Clark Andresen	■	441-5860
1003	Ken & Jan Wherry	■	448-0321
1005	C A Madison	87 ●	443-1345
1101	Brad Phillips	■	443-1101
1103	Lance Kostrobala	89 ●	441-8127
1103	Howard Weiner	89	441-8127
1202	Max Kaminoff	85 ●	441-2821
1204	Dennis Kelly	89 ●	448-7822
1304	E H Murphy	87	441-1920
1304	Patti Newman	87	441-1920
1402	J A Scholte	■	448-9154
1405	Joseph M Gifford	89	441-9464
1501	Robert J Norris	■	728-4325
1502	Ethel L Graham	87	728-4848
1504	R L Stenshoel	88 ●	728-5162
1601	Larry J Smith	89 ●	728-4402
1605	Ralph M Vandyke	87	443-0431
1801	Fred J Hagen	83	728-9300
1803	Karl Geyer	89 ●	728-8144
2102	P Vanwingerden	■	448-5857
2301	Hiroshi Tanaka	■	441-6048
2827	★ **Village Mart**	85	441-9393

— 200 BROAD

2933	★ **Windemere Apts**		
	Jimmy Archuleta	¤	441-0694
	David Austin	–	728-1758
	E Bamber	89	448-7889
	Phoebe Benedict	¤	441-4926
	Jeff Benoliel	¤	728-1524
	Jeff Benoliel	¤	728-6867
	Michael Carrington	¤	441-8114
	James Erickson	¤	441-9857
	E Green	82	441-8543
	J A Olincy	88	441-6970
	Ric Smith	86	448-1703
	Ladd Steiskal Jr	88	441-3512
	Andrea Vitalich	¤	443-3206
	A Winship	–	448-0707
110	Larry B Bovenkamp	■	443-4487
202	John L King	89	448-4308
301	James V Santoro	65	624-6025
307	Jon Pryor	■	448-2563
2934		NP	

— PARALLEL STS

— 1ST

— 3RD

1990 CLAY ST

SOURCE: COLE

STREET NOT LISTED

1984-85 2ND AVE-A

SOURCE: COLE

2408	★ Lexington Apts		
	J C Chapin	83	343 - 0406
	A S Esayi	¤	623 - 4846
	Arthur Fiske	82	622 - 7528
	J Fletcher	¤	382 - 1510
	Stephen Paul Flinn	¤	682 - 1774
	D James	¤	623 - 8009
	T D Larson	¤	682 - 6786
	Scott C McKee	¤	621 - 7242
	S L Nunn	83	292 - 9548
	Randy Pepprock	¤	682 - 3768
	Leonard M Piha	–	467 - 9647
	F R Posel	¤	621 - 7468
	N L Sale	–	623 - 5630
	Norris Tripp	78	624 - 6457
2413	★ Advertising Indust		624 - 2882
	★ Natl Screen Serv		624 - 2882
2414	★ 1 Reel Vaudvl Show		622 - 7656
2415	★ Gamma Vision Inc		223 - 0000
2417	★ Chromatechnic Lab		623 - 0910
2418	★ Sarco Applnc Srvc		682 - 5977
2420	★ Windermere Rl Est	¤	628 - 6400
2421	★ Avaunt Prdctns Inc		624 - 1173
	200 WALL		
2512	★ Carpenters Cntr Bg		
	★ See Building Drty		
2521	★ Orion Multi-Svc	¤	223 - 1303
	★ Youthworks	¤	343 - 0303
	★ Youth Works	–	343 - 0303
	200 VINE		
2600	★ Sidneys Restaurant	¤	624 - 8880
2607	★ Robert M Capeloto		622 - 0272
	★ James W Clarke		622 - 0272
	★ Dale Carnegie Crs		623 - 6222
	★ G V Fred&Assoc		623 - 6222
	★ Ken Gollings		622 - 0272
	★ John A King		622 - 0272
	★ John L Oleson		622 - 0272
	★ Monte Solkover		622 - 0272
	★ Stimpson Associate		622 - 0272
	★ I R Stimpson		622 - 0272
	★ Fred G Vest&Assoc		623 - 6222
2612	★ Sonitrol Northwest		223 - 9620
	★ Archie Taft Assoc	–	623 - 8090
2620	★ Grand Cntrl Sauna		447 - 9444
	★ Hot Tubs&Saunas	¤	447 - 9444
	★ Saunas&Hot Tubs	¤	447 - 9444
2621	A Lee Atherton	83	621 - 7941
	★ Atwood Valentine	¤	622 - 1590
	B Y Auger	¤	682 - 6436
	Ken Baker	¤	292 - 8222
	Earl W Becker	¤	623 - 7732
	Wesley A Bull	82	624 - 9627
	Wm F Calderhead	82	623 - 5548
	George D Clark Jr	82	624 - 8265
	B Corner	82	623 - 1247
	Wm S Cunningham Jr	83	624 - 7622
	Paul N Daigle	83	343 - 9636
	Dan Dolan	–	682 - 6268
	Fred H Drummond	82	623 - 4166
	★ Farmers Ins Group	¤	622 - 1590
	Alfred J Ferrara	83	343 - 7732
	S A Filion	–	682 - 4622
	J L Gaylord	–	382 - 1506
	Philip H Gayton	–	682 - 3362
	Thomas Girvan	¤	623 - 8140
	★ Harbor Heights		625 - 0774
	W Harisberger	82	623 - 5027
	Brian Hegre	–	682 - 0940
	V E Hild	82	682 - 8234
	Loren D Hostek	82	623 - 3939
	G J Jacobson	83	343 - 0829
	A R Johnson	82	623 - 1001
	Jeanette Kennedy	¤	682 - 0438
	Robert Kornfeld	¤	682 - 3638
	D Krause	82	624 - 6511
	Mary R Lester	–	382 - 1432
	Patrice Lewand	¤	622 - 0403
	Ella Linker	83	682 - 9463
	W J Loacker	82	624 - 9899
	G Lundgren	83	587 - 2500
	Otto Ma	82	624 - 6006
	James E Mason	82	623 - 1700
	James F McGarry	¤	623 - 5363
	Joe McKeown	¤	682 - 8562
	Dee McKern	82	621 - 9191
	Dean J Michelson	82	622 - 9531
	E Mohseni	83	382 - 9466
	Michael Mohseni	83	622 - 1089
	Phillip B Mowrey	82	447 - 9042
	Albert Musalo	¤	682 - 0537
	Tom Napa	82	623 - 8439
	Robin Norman	83	343 - 0461
	Paul ONeil	–	624 - 8732
	Frank S Panzica	–	682 - 0397
	Alice Phillips	81	621 - 8960
	Michael Poe	¤	623 - 5702
	Kenneth M Ritchey	¤	623 - 6665
	B L Ruppert	¤	682 - 0859

1984-85 2ND AVE-B

SOURCE: COLE

2621	Michael Shenk	82	622 - 1878
	Peggy Ann Shepherd	¤	623 - 6665
	John Y Skelly	82	587 - 0035
	Sam M Storey	82	624 - 1495
	George Suddock	83	624 - 0079
	E J Sullivan	82	343 - 7412
	A Tai	83	622 - 9132
	M Takahashi	83	382 - 9330
	Gordon F Vickery	83	343 - 9140
	Jaime O Viloria	82	447 - 9042
	Bob Wilkes	82	623 - 6693
	Wallace Wright	¤	623 - 6410
2623	★ Marshall&Meyer		622 - 2405
	★ D A Meyer		622 - 2405
	200 CEDAR		
2701	★ Eastern Merchands		622 - 2611
2713	2715	NP	
2729	★ Lighting Supply Co		682 - 5074
	200 CLAY		
2801	★ Fletchers Cleaners	¤	682 - 7107
2809	★ Ellingsons Gifts		622 - 4406
2815	★ Bay Vista Bldg		
	★ See Building Drty		
2821	John W Baetz	82	382 - 9499
	★ Bay Vsta Twr Cndmn		343 - 9545
	Dayton R Clark	¤	623 - 8482
	Thomas J Conrad	–	682 - 2132
	Jay Gerlings	–	622 - 9889
	Robert Giersdorf	–	623 - 2111
	E F Gourlie	¤	623 - 5634
	Fred Hagen	83	382 - 9300
	Harvey D Leap	–	343 - 9545
	Scott A Mickeleit	¤	624 - 9287
	Edgar W Scdoris	83	382 - 9499
2827	★ Bay Vsta Twr Deli		622 - 3130
	200 BROAD		
2911	★ Coast Mortg Co Bg		
	★ See Building Drty		
2933	★ Windemere Apts		
	Chet Anderson	81	622 - 9315
	Frank Arao	75	624 - 9254
	E N Bartee	83	622 - 9360
	John Brenesk	78	622 - 2665
	H H Bruce	83	343 - 9864
	A Byrne	80	623 - 0269
	Joe Fujii	77	622 - 7559
	E Green	82	682 - 1850
	S E Kelly	77	624 - 5968
	Robert G Marrs	73	624 - 4879
	E T Robertson	82	623 - 9436
	James V Santoro		624 - 6025
	Steph J Westerdale	78	622 - 2651
	L T Zingmeister	¤	682 - 9139
2934		NP	
	PARALLEL STS		
	1ST		
	3RD		
NO #	★ J A Phelan Atty		343 - 9815
	215 RESIDENCE	211	BUSINESS

1980-81 2ND AVE-A

SOURCE: COLE

2403 ★Antiqu Wrld Nwsppr 624-3643
★Western Typogrphrs 624-3642
2405 ★Commission Sales 624-6116
★Incentive Sales Co 624-6116
2408 ★Lexington Apts .....
Edward H Florence 77 622-9335
M Kent 623-0556
Jerome R Newman 79 623-9455
E Winton Pearson 74 624-9845
James D Petersen .....¤ 622-0788
Janine Richards .....¤ 622-4504
Donna J Scherer .....¤ 623-4720
Gary Stanchfield 77 623-5158
Leonard Thomas .....¤ 682-2789
Norris Tripp 78 624-6457
2412 ★Byte Shop Computer ...¤ 625-0072
2413 ★Advertising Indust 624-2882
★Natl Screen Serv 624-2882
★Natl Theatre Sup 624-7710
2414 ★Holly Management .....- 623-0113
2417 ★Chromatechnic Lab 623-0910
★Imagic Color Inc .....¤ 623-0237
2420 ★Sarco Inc 682-5977
★Sarco Seattle Appl 682-5977
★Seattle Appliance 682-5977
2421 ★Consldtd Travl Ser .....¤ 623-4620
★Mike Sedam Phtgphy 622-6883
★Tst Agency 682-7722

200 WALL

2512 ★Carpenters Cntr Bg .....
★See Building Drty .....
2517 ★Building .....
★Action Distributng 624-3545
★Peter Print 623-6928
★Super City 624-0110
2519 ★R L Polk&Co 622-6126
★R L Polk&Company 624-3879
★R L Polk&Comp 622-8610
★Lynn E Sawyer 622-6126
2521 Safari Shah .....- 682-6447
★Shahlimar .....¤ 623-9494

200 VINE

2600 ★Studio 26 .....¤ 622-9494
2605 ★Byte Shop 622-7196

1980-81 2ND AVE-B

SOURCE: COLE

2607 ★Dawson&Hall Limitd ....¤ 622-9524
★G V Fred&Assoc .....¤ 623-6222
★Lykes Bros Stmshp ....¤ 447-9100
★Lykes Lines .....¤ 447-9100
★Phillip B Mowrey .....- 447-9760
★Recruiters Nrthwst .....- 682-6726
★Rockwell Institute 622-6833
★TMA Architects .....- 447-9760
★Fred G Vest&Assoc ....¤ 623-6222
2612 ★Coast Indstrl Supl 622-5770
2620 ★Grand Cntrl Sauna .....¤ 447-9444

200 CEDAR

2700 ★Grange Ins Assn 682-6971
★Rocky Mtn Fire&Csl 682-6971
2701 ★K&E Co Engr Suplys ... 623-5535
★Keuffel&Esser Co 623-5535
2702 ★Charles M Garrett 682-1866
★Insurance Brkr Inc 624-0677
★N McHugh Ins Brokr ... 624-0677
★Peterson&Garrett 682-1866
★Haller E Peterson 682-1866
2712 ★Embossing McKay 623-0650
★McKay Printg Corp 623-0650
2713 .....NP
2714 ★Camera Craft Inc 682-0996
★Royal C Crooks 682-0996
★William H Houlton 682-0996
2715 .....NP
2729 ★Lighting Supply Co 682-5074

200 CLAY
200 BROAD

2911 ★Coast Mortg Co Bg ....
★See Building Drty .....
2933 ★Windemere Apts .....
Frank Arao 75 624-9254
John Brenesk 78 622-2665
A Byrne .....¤ 623-0269
A Enquist 79 682-8048
K A Flotre 71 624-3128
Harold Formoe 73 682-5180
Joe Fujii 77 622-7559
Clara V Hutton .....¤ 623-4250
Stephen James 79 622-9540
S E Kelly 77 624-5968
Robert G Marrs 73 624-4879
Jack R Mattox .....¤ 623-4250
Bruce McLauchlan 78 622-0296
A P Nissen 624-6109
James V Santoro 624-6025
Steph J Westerdale 78 622-2651
2934 .....NP
2938 ★Blue Line Inn 624-5783
★Seattle Taxicab 622-6500
★Yellow Cabs .....- 622-6500

PARALLEL STS
1ST
3RD

1980-81 CLAY ST

SOURCE: COLE

STREET NOT LISTED


1975 2ND AVE-A

SOURCE: COLE

```
2403*AMER INTRNL PICTUR   6220660
2405*SERAC-AMERICA        6222921
     *SUPER-VISOR CORP    6222921
2408*LEXINGTON APTS
     HENRY DALTON        ¤6826035
     M KENT               6230556
     LOLA LEWIS          ¤6249457
     ROBERT MAULDIN      ¤6225755
     E WINTON PEARSON   4 6249845
     ROBERT A PETERSON   ¤6225124
     G H RHODA           ¤6234831
     CLARA SANDERS        6223254
2413*ADVERTISING INDUST   6242882
     *NATL SCREEN SERV    6242882
2414*HOLIDAY SALES INC    6222660
2415*NATNL THEATRE SUPL   6247710
2416*WESTERN TYPOGRPHRS   6243642
2417*CHROMATECHNIC LAB    6230910
     *GENE HARMON        -6230910
2418*CHIDGEYS MUSICL RP   6237107
     *CHIDGEYS PLATING    6237107
     *DEC ELECTRONICS     6237107
2419*BUENA VISTA DISTR    6240186
2420*SARCO INC             6825977
     *SARCO SEATTLE APPL   6825977
     *SEATTLE APPLIANCE    6825977
2421*S&S AMUSEMENTS INC   6237454
     *SAFFLS THTR&TV SER   6235177
     *20 CENTURY-FOX FLM   6237815
  ..   200 WALL             ..
2512*CARPENTERS CNTR BG
     *SEE BUILDING CRTY
2515*ADVERTISING SERVCS    6236963
2517*BUILDING
     *ACTION DISTRIBUTNG   6243545
     *SUPER CITY           6240110
2519*R L POLK&CO           6226126
     *LYNN E SAWYER       -6226126
2521*KJAER EQPT CO PAC    ¤6224216
  ..   200 VINE             ..
2600*APPL SERV STA          6828011
     *FRENCHS ELEC SERV     6241811
2612*COAST INDSTRL SUPL   -6228770
2620*NORTHWEST DATA SYS     6238330
  ..   200 CEDAR            ..
2701*K&E CO ENGR SUPLYS     6235535
     *KEUFFEL&ESSER CO      6235535
2702*CLAUSING AGENCY        6228728
     *CHARLES M GARRETT     6821866
     *HALLER&ASSOCS         6821866
     *INSURANCE BRKR INC   ¤6240677
     *N MCHUGH INS BRKRS   -6240677
     *PETERSON&GARRETT      6821866
     *HALLER E PETERSON     6821866
     *YOUTH TENNIS FNDTN    6821866
2706*SOUND BUS SYS INC     6827844
2708*AFFILIATED ADJSTRS    6828025
     *MILOT&LENKE          ¤6828025
     *PASA                  6828025
     *PROFESSNL ADJUSTRS    6828025
2712*EMBOSSING MCKAY      -6230650
     *MCKAY PRINTG CORP    -6230650
2713                  NP
2714*CAMERA CRAFT INC       6820996
     *ROYAL C CROCKS        6820996
     *WILLIAM H HOULTON     6820996
     *WALTER H QUADE III    6820996
2715                  NP
2725*ALEXANDER FIRE EQP     6822660
     *A GOW FIRE EQPT CO    6822660
2729*LIGHTING SUPPLY CO     6825074
  ..   200 CLAY             ..
  ..   200 BROAD            ..
2911*COAST MORTG CO BG
     *SEE BUILDING CRTY
2933*WINDEMERE APTS
     FRANK ARAO          ¤6249254
     L J BRUSEAU       1 6230736
```

1975 2ND AVE-B


SOURCE: COLE



```
2933 K A FLOTRE                    1 6243128
     HAROLD FORMOE                 3 6825180
     JOE FUJII                       6227559
     E GERMAIN                     0 6243646
     STANLEY T HAMLIN              ¤6825299
     M HOGG                        1 6248248
     MRS L M KELLY                 8 6245968
     ROBERT G MARRS                3 6244879
     A P NISSEN                      6246109
     J L NUTTALL                   3 6236749
     IVAN N RIVARD                 4 6246352
     JAMES V SANTORO                 6246025
     WALTER O SMITH                ¤6240604
2934                        NP
2938*BLUE LINE INN                   6245783
  ..  PARELLEL STS                     ..
  ..  1ST                              ..
  ..  3RD                              ..
    132 RESIDENCE    375 BUSINESS
```

1975 CLAY ST


SOURCE: COLE



```
 A A  CLAY                          98121
AT 2700 1ST AVE
...        1- 299 T    80 SE..K 3
 67*LINES INC                     6224084
 ..  2700 2ND AVE                   ..
211*MILK FUND                     6237632
   *SEATTLE MILK FUND             6237632
                          3 BUSINESS
```

1970-71 2ND AVE-A


SOURCE: COLE



```
2403*JACK C PARTIN          MA23788
    *UNITED ARTISTS COR     MA23788
    *H HARDEN               MA23788
2405*METRO GOLDWYN MAYR     MA34056
2408*LEXINGTON APTS
     L S LOVERIDGE         □MA27129
     CLARA SANDERS      5  MA23254
     A E SIMPIER        6  MA33854
     M KENT                MA30556
     WAYNE D WENZEL     8  MU22413
     JEANETTE VANTHUYNE
                        5  MU25049
     THOMAS E BERRY     8  MA33307
2413*ADVERTISING INDUST     MA42882
    *NATL SCREEN SERV       MA42882
    *NATL THEATRE SUP      □MA47710
2415*COLUMBIA PCTR CORP     MA35349
2416*WESTERN TYPOGRPHRS-    MA43642
2418*CHIDGEYS               MA37107
    *CHIDGEYS PLATING       MA37107
2419*BUENA VISTA DISTR      MA40186
2420*SARCO SEATTLE APPL      MU25977
2421*SAFFLS THTR&TV SER     MA35177
    *20 CENTURY-FOX FLM     MA37815
 ..  200 WALL                ..
2503*FREDS UNION SERV       MA49080
2512*CARPENTERS CNTR BG
    *SEE BUILDING DRTY
2515*MAC TYPESETTING        MA36049
    *PACIFIC NW PUBLSHG    □MA36046
    *PAC NW UNDERWRITER     MA36046
    *MRS G D CONNOR         MA36046
2517*BUILDING
    *OLYMPIC SALES CO      -MA34874
    *PAYMSTR SL&SERV CO-    MA28845
    *INTERCOM INC          -MA34866
    *A-A-A PAYMSTR SALS-    MA28845
    *BUSINS EQPT WHLSLR-    MA35213
     H H HINTON            -MA28845
2521*WESTALL SALES CO       MA43635
 ..  200 VINE                ..
2600*FRENCHS ELEC SERV       MA41811
    *APPLIANCE SERV STA      MU28011
2601*SEA LUGGAGE CORP       MA33571
2607*IKON INC              -MA43410
    *SYNERGISTICS INC      □MA43410
    *PHYSIO CONTRL CORP     MA44824
2612*DANDO SAFE CO         -MA46910
    *LOOMIS CORP           □MA46910
    *LOOMIS PROTCTN INC    □MA46910
2619*IKON INC              □MA43415
2620*UNT DATA PROCESSNG     MA38330
 ..  200 CEDAR               ..
2700*GRAY DICTATN SYSTM      MA44534
2701*K&E CO ENGR SUPLYS     MA35535
    *KEUFFEL&ESSER CO       MA35535
2703*HARRY REIXON           MA44520
```

1970-71 2ND AVE-B

SOURCE: COLE



```
    *PETERSON&ASSOCTS       MU21866
    *MONARCH INS AGENCY     MA44520
    *HALLER&ASSOCS          MU21866
    *BOSTICK-MONARCH AG     MA44520
    *C M GARRETT INS AG     MU21866
2704*WARNER BROS DSTBTG     MA20046
2706*C B GUSTAFSON ACCT     MA26434
2708*DATA FORMS INC        □MA42873
2710*JOHN OSTER SERV CO     MA24301
    *BOJO APPLINC SERVC-    MA24301
2712*EUTECTIC WELDING       MA35120
    *EUTECTIC WELDING       MA37132
2713 H HESS              9  MA33490
2714*WILLIAM H HOULTON      MU20996
    *ROYAL C CROOKS         MU20996
    *CAMERA CRAFT INC       MU20996
2725*A GOW FIRE EQPT CO     MU22660
    *ALEXANDER GOW FIRE     MU22660
2729*LIGHTING SUPPLY CO     MU25074
 ..  200 CLAY                ..
2811*EL MATADOR             MA35415
 ..  200 BROAD               ..
2911*COAST MORTGAGE         MA48700
    *WILLIAM A SMITH        MA48700
    *COAST DEVELOPMT CO     MA48700
    *COAST INS AGENCY       MA48700
    *R E CADY APPRSR        MA48700
    *EVERGREEN PRINTING     MA21794
2933*WINDEMERE APTS
     N LAHD                □MA26175
     E GERMAIN             □MA43646
     SIGURD HENRIKSEN   8   MA23923
     IVAN N RIVARD         □MA27786
     JOE FUJII              MA27559
     RUTH FINNEY        7   MA26999
     DOUGLAS M BURCH       □MA41076
     MRS T G SPELLMAN   6   MA20516
     M I TEMPLETON          MU21154
     RUTH E CARTER          MA33548
     ANN BYRNE              MA30269
     D V BEAVER            □MA46875
     JAMES V SANTORO        MA46025
     MRS MERCY DELONG   8   MU24625
     CARL C CRAIG           MA40857
     A P NISSEN             MA46109
     MRS L M KELLY      8   MA45968
     FRANCES B VIDLER   7   MA40598
     RAYMOND H FINNEY      □MA34449
     J M GOWER          6   MA35381
     ROGER A MOON          □MU21873
2934                    NP
2938*BLUE LINE INN          MA45783
 ..  PARELLEL STS            ..
 ..  1ST                     ..
 ..  3RD                     ..
```

1970-71 CLAY ST

SOURCE: COLE



CLAY 98121

1- 299 T 80 $E..K 3


211*SEATTLE MILK FUND MA37632

*MILK FUND MA37632

2 BUSINESS

1965 2ND AVE-A

SOURCE: PACIFIC NORTHWEST BELL



2ND AVE CONTINUED

2401	UNIVERSAL FILM EXCH	MA2-3245
2402	CONCORD APTS	
	HOFF LAWRENCE	MA3-0067
	CONLEY R E	MA2-4497
	MASON DAISY V	MA4-4254
	MCGINNIS EVELYN	MA3-4825
	LAWSON STEVE	MA3-8579
	COTTONGYM ZACK	MA3-2534
	GROSS DAVID M	MU2-8938
	HENRY C E	MA3-1037
	DONOHO HARRIETT H	MU2-4599
	MCGEE MARY A	MA3-1755
	MIETTUNEN ALFRED T	MA3-7362
	ROBERTS H W	MU2-2261
	ROBINSON MERA	MA2-6122
	ESTRADA JOE	MA3-5530
	GOFF WILLIAM L	MA3-6399
	BARNES CHESTER F	MA4-1417
	AUSTIN M	MA4-2685
	BEALL C R	MA3-6379
2403	UNITED ARTISTS CORP	MA2-3788
2405	METRO GOLDWYN MAYER	MA3-4056
2408	LEXINGTON APTS	
	PRICE MARIE	MA3-5429
	DROUGARD VAL J	MA4-8624
	VANTHUYNE JEANETTE	MA4-3999
	MORTENSEN ODIN	MA3-7109
	MOSDAHL BENJAMIN D	MA3-8695
	COTHERN DIANE	MA2-2330
	DILLARD WESLEY O	MA2-8675
	SANDERS CLARA	MA2-3254
	KENT MARJORIE	MA3-0556
	HINTON CLIFF	MA3-6078
	REYNOLDS A	MU2-6976
	SRAEVO A	MU2-6976
	GOSSELIN ESTHER A	MU2-2639
	SIMPIER ALICE E	MA3-3854
2412	CANDY DISTRIBUTORS INC	MA2-2617
2413	NATL SCREEN SERV CORP	MA4-2882
2415	COLUMBIA PICTURES CORP	MA3-5349
2418	ALASKA FILM EXCHANGE	MA2-3236
2419	UNIVERSAL PREMIUM CORP	MA3-5124
2420	J M APPLNCE SVC CNTER	MU2-5977
2421	SAFFLES THEATRE & TV SERV	MA3-5177
2421	TWENTIETH CENTURY FOX FILM	MA3-7815
2503	FREDS UNION SERVICE	MA4-9080
2512	BUILDING	
	FRANKFURTER & ASSOC	MA3-8295
	ISAAC WALTER M & ASSOC	MA3-7422
	CARPENTERS UNION LOCAL 1289	MA4-8111
	KING CO TRADE RLTNS BOARD	MA4-2430
	PILE DRIVERS LOC 2396	MA4-6019
	MILLMENS UNION LOCAL 338	MA4-8236
	CARPNTRS TRSTS WSTRN WASH	MA3-6514
	CARPENTERS UNION 131	MA3-5828
	LBR & SAWMILL WKRS UNION LOC 2519	MA3-4980
	CARPENTERS DIST CNCL	MU2-0360
	HARSTAD ASSOCIATES INC	MA4-2525
2600	C & G ELECTRONICS CO	MA3-4536
2600	C & G ELECTRONICS CO	MA4-4354
2601	SEATTLE LUGGAGE CORP	MA3-3571
2616	GARDNER TOM C	MA4-1565
2619	EASTMAN KODAK STORES	MA2-9072
2620	PETERSON INS AGENCY	MU2-1866
2624	RICONOSCIUTO ADV AGNCY	MA3-0532
2626	AUTO TYPIST CO	MA2-1588
2700	AMERICAN SEATING CO	MA4-2560
2701	KEUFFEL & ESSER OF WASH INC	MA3-5535
2704	WARNER BROS PICTURES DISTR CORP	MA2-0046
2706	GUSTAFSON C B	MA2-6434
2708	GENERAL BINDING SALES CORP	MU2-3086
2710	CLARY BUSINESS EQUIP	MA3-5085
2712	EUTECTIC WELDING ALLOYS	MA3-5120
2712	EUTECTIC WELDNG ALLOYS	MA3-7132
2713½	PERSSON SWAN	MA2-4389
2714	ALLIED PRINTERS THE	MA3-2243
2718	LOCKLAND DISTRBTNG CO	MA3-4717
2722	OSTER JOHN SVC CO INC	MA2-4301
2722	OSTER JOHN MFG CO	MA2-4302
2725	GOW ALEXANDER FIRE EQ	MU2-2660
2729	LIGHTING SUPPLY CO	MU2-5074
2811	COUNTRY SQUIRE REST	MA3-5415
2911	COAST MGE & INV CO	MA4-8700
2911	EVERGREEN PRINTING CO	MA2-1794
2933	WINDEMERE APTS	
	AOKI MIN	MA2-2148
	FUJII JOE	MA2-7559
	MILES IRENE M	MA2-2714
	CARTER RUTH E	MA3-3548
	CHESLEY BURDETT D	MA4-8697
	BYRNE A	MA3-0269
	NISSEN ALPHONSINE P	MA4-6109
	ABREGO MARGARET	MA3-7659
	CORMACK E	MA4-2019

1965 2ND AVE-B

SOURCE: PACIFIC NORTHWEST BELL

2ND AVE CONTINUED

	LANGE ALLEN J	MA4-8039
	SANTORO J V	MA4-6025
	HEATER MARIE L	MA2-4589
	CRAIG C C	MA4-0857
	TEMPLETON MARIE INGA	MU2-1154
2938	BLUE LINE INN	MA4-5783

1965 CLAY ST

SOURCE: PACIFIC NORTHWEST BELL

CLAY ST

211	SEATTLE MILK FUND	MA3-7632

2ND AVE CONTINUED

2421	TWENTIETH CENTURY FOX FILM	MA3-7815
	WALL ST	
2503	BUDS UNION SERVICE	MA2-9495
2503	HEALEYS UNION SERVICE	MA2-9495
2512	BUILDING	
	CARPENTERS DISTRICT	MU2-0360
	CARPENTERS UNION LOCAL 1289	MA4-8111
	KING CNTY PNTRS DCRTRS DRYWL JNT COMM	MA4-2430
	PAINTERS JOINT COMM OF KING COUNTY	MA4-2430
	PILE DRVRS BRDGE DOCK WHARF CARPNTRS	MA4-6019
	MILLMENS UNION LOCAL 338	MA4-8236
	WSTRN WASH CRPNTRS TRUST FUND	MA3-4711
	HOME BLDRS & CRPNTRS HEALTH FUND	MA3-4711
	CARPENTERS UNION 131	MA3-5828
	LBR & SAWMILL WKRS UNI ON LOC 2519	MA3-4980
	UNION REGISTER	MA3-4980
	HARSTAD HOWARD T & ASSOCIATES	MA4-2525
	ECKERT ROBERT A	MA4-2525
	FRANKFURTER HARSTAD &ASSOC	MA4-2525
	THOMAS & HARSTAD ASSOC	MA4-2525
2515	AUDOGRAPH OF WASH	MA3-7322
2515	GRAY AUDOGRAPH CO DISTRIBUTOR	MA3-7322
2515	SWANBERG & JOHNSON	MA4-5575
2515	BAKERY MACHINERY EXCH	MA4-5575
2515	SWANBERG JACK H	MA4-5575
2517	LEE DAVE M CO INC	MA2-5512
	VINE ST	
2601	ECKSTROM EARL E & ASSOC	MA3-3816
2601	SPEED QUEEN COML SALES & SERV CO	MA3-3816
2609	NORTHWEST FACTORS	MA4-8116
2609	KOLD HOLD DIV TRANTER MFG INC	MA4-8116
2609	TECUMSEH PRODUCTS CO	MA4-8116
2609	YATES O C CHUCK	MA4-8116
2609	JOHNSTON OVERHEAD DOOR CO	MA2-6861
2609	BARCOL OVERDOORS OF SEATTLE	MA2-6861
2609	JOHNSON OVERHEAD DOORS	MA2-6861
2609	JOHNSTON FOLDING DOOR CO	MA2-6861
2609½	FINNELL SYSTEM INC IF NO ANSWER CALL	MA3-7229 AD2-0728
2612	METROPOLITAN PRESS & WESTERN	MA2-8609
2616	GARDNER HAL A & SON	MA4-1565
2616	COLUMBIA ELECTRIC & MFG CO	MA4-1565
2619	EASTMAN KODAK STORES INC	MA2-9072
2620	PETERSON INS AGENCY	MU2-1866
2620	BOSTICK WALLY INS	MU2-1866
2620	GARRETT CHARLES M	MU2-1866
2620	GARDNER HAL A & SON	MA4-1565
2624	ATSCO WHSLE DRUG	MA3-5021
2626	JONES R F	MA4-7255
	CEDAR ST	
2700	PACIFIC COPY CORP	MA4-5823
2700	PHOTORAPID CORPORATION	MA4-5823
2701	KEUFFEL & ESSER OF WASH INC	MA3-5535
2701	K & E OF WASH INC	MA3-5535
2701	KEUFFEL & ESSER OF WASHINGTON	MA4-8254
2702		
	AMERICAN PHOTOCOPY EQUIPMENT CO	MA2-1544
	APECO	MA2-1544
2704	WARNER BROS PICTURES DSTRBTNG CORP	MA2-0046
2706	ROSEN H M OFFICE MACHINES CO	MA2-2466
2708	GENERAL BINDING SALES CORP	MU2-3086
2708	REXOGRAPH INC	MU2-3086
2710	CLARY PROD RMNGTN RND DV SPY RND CRP	MA3-5085
2712	EUTECTIC WELDING ALLOYS	MA3-5120
2713		

2ND AVE CONTINUED

	ARVIK J E	MA2-5931
2713½		
	PERSSON S	MA2-4389
2714	ALLIED PRINTERS THE	MA3-2243
2715½	APARTMENT	
	SMAKER JOHN	MA3-2826
2718	LOCKLAND DISTRIBUTING CO	MA3-4717
2722	NATL HOME OWNERS CLUB OF SEATTLE INC	MA2-3500
2722	HOME OWNERS CLUB OF SEATTLE	MA2-3500
2722	SEATTLE HOME OWNERS CLUB	MA2-3500
2722	KRAMER BORIS B	MA3-3919
2725	GOW ALEXANDER INC	MU2-1995
2725	GOW A INC	MU2-2660
2727	ELECTROLUX CORPORATION	MA4-0057
2729	MARCHANT DIV OF SMITH CORONA MARCHNT	MA3-2727
2729	KELLEY JOHN E	MA3-2727
	CLAY ST	
2811	COUNTRY SQUIRE RESTAURANT	MA3-5415
2811	CARRIAGE ROOM THE	MA3-5415
	BROAD ST	
2933	WINDEMERE APTS	
	AOKI MIN	MA2-2148
	AOKI J S	MA3-2156
	MILES IRENE M	MA2-2714
	DAVIS LETTIE E	MA4-3389
	BISHOP ORA F MRS	MU2-3684
	PHILLIPS L	MA4-0612
	WOLFE MARGARET J	MA3-6738
	BRAY ALMA S MRS	MU2-7963
	BAUMAN L	MA4-4162
	BYRNE A	MA3-0269
	NISSEN ALPHONSINE P	MA4-2313
	KOSER P V	MA4-4079
	CHESLEY BURDETT D	MA4-8697
	SOMES BARBARA	MA3-4730
	LANGE ALLEN J	MA4-8039
	SANTORO J V	MA4-6025
	THOMAS KATHERINE G	MA2-0355
	ODY THERESE M	MU2-9129
	HEATER MARIE L	MA2-4589
	CRAIG C C	MA4-0857
	HAZEL V M	MA3-5389
	TEMPLETON MARIE INGA	MA3-1776

1960 CLAY ST

SOURCE: PACIFIC TELEPHONE

CLAY ST

111 KEYSTONE PRINTING CO MA2-7830

2ND AV

211 M C INSURANCE AGENCY MA3-1881
211 MACKENZIE FRANK P MA3-1881
211 TEMPERANCE INSURANCE AGENCY MA3-1881

3RD AV

1956 2ND AVE-A

SOURCE: PACIFIC TELEPHONE

2323 2d Penning J R MA-1190
2323 2d Slater W A Company candies ... MU-0155
2324 2d Master Auto Service EL-8065

2327 2d **WILLIAM TELL HOTEL**
2327 2d Hokanson Arnold R r SE-2659
2327 2d William Tell Hotel SE-9921
2330 2d Acme Visible Records Inc MA-1141
2330 2d Shea Wm B MA-1141
2331 2d Loew's Incorporated EL-4056
2331 2d Metro-Goldwyn-Mayer Pictures Exchange EL-4056
2332 2d Balyeat Forrest S calcultng machs. EL-3012
2332 2d Blix Ed calcultng machs EL-3012

BATTERY ST
2401 2d Nelson Earl H MA-3245
2401 2d Universal Film Exchanges Inc ... MA-3245

2402 2d **CONCORD APTS**
2402 2d Aure Louis P SE-6468
2402 2d Austin Mary r SE-2685
2402 2d Barnes Chester F r SE-1417
2402 2d Brasfield George D SE-5438
2402 2d Cyr Victor J MU-5399
2402 2d Dillon Anne EL-5552
2402 2d Head Beverly EL-4913
2402 2d Head Ilene F EL-4913
2402 2d Kirsch Ernest EL-5377
2402 2d Miettunen Alfred T EL-7362
2402 2d Henry Claude E r EL-1037
2402 2d Johnson Mary R r EL-4857
2402 2d Jones Mildred A r EL-8359
2402 2d Laurine Howard J MU-5195
2402 2d Martin Inga MA-8358
2402 2d Moyle Hazel Mrs EL-3857
2402 2d Newbert K M r MA-8574
2402 2d Peha Katherine r EL-0312
2402 2d Raasok Karl F r SE-5409
2402 2d Roberts Helena W r MU-2261
2402 2d Robinson Mera EL-6021
2402 2d Rohrer Anna G r EL-5070
2402 2d Rossie George r MA-3674
2402 2d Russette Alfred EL-8359
2402 2d Sills J W r SE-2095
2402 2d Starheim Ragnhild EL-6107
2402 2d Torrey Marianna P MA-7223
2402 2d .....(2)..... Non-Pub
2403 2d Harden H ofc MA-3788
2403 2d Sullivan A J ofc MA-3788
2403 2d United Artists Corp MA-3788
2405 2d Warner Bros Pictures Distrng Corp MA-0046

2408 2d **LEXINGTON APTS**
2408 2d Beall Addie O r MA-0894
2408 2d Beasley Sue EL-3073
2408 2d Brackett Lucy Mrs r EL-8563
2408 2d Christensen David A r SE-6422
2408 2d Cottongym Z T r EL-2534
2408 2d Curtis Alma SE-0648
2408 2d Dokken Alfred D EL-7253
2408 2d Dunand Therese EL-8986
2408 2d Fletcher Joan SE-0287
2408 2d Flower Edward SE-1835
2408 2d Gottschalk Ann MA-6104
2408 2d Grizzell Cecile E SE-3015
2408 2d Hagen Donald H MA-7208
2408 2d Jensen Orin J MA-0238
2408 2d Larson J Bernard EL-5026
2408 2d Newman Beverley EL-3413
2408 2d Pomaville Bruce V SE-7243
2408 2d .....(3)..... Non-Pub
2412 2d Candy Distrs Inc MA-2617
2413 2d National Screen Service Corp ... SE-2882
2414 2d Northwest Releasing Corp SE-4787
2415 2d Columbia Pictures Corp EL-5349
2415 2d ..... Non-Pub
2416 2d Garretson Radio Supply Inc MU-4380
2416 2d Wash Electronic Supply Co MU-4380
2417 2d West Coast Industries MU-2663
2418 2d Allied Artists Pictures of the Northwest Inc MU-2460
2418 2d Cruea Edmond D ofc MU-2460
2419 2d C I O Council SE-0725
2419 2d Favorite Films of California Inc SE-6234
2419 2d Wash State C I O Council SE-0725
2419 2d .....(3)..... Non-Pub
2420 2d Hollywood Television Service Inc. EL-8678
2420 2d Northwest Bakers Exchange SE-5575
2420 2d Republic Pictures Corp EL-8678
2420 2d Swanberg Jack H ins SE-5575
2420 2d Swanberg & Johnson ins SE-5575
2421 2d Saffle's Theatre & TV Service ... EL-5177
2421 2d Twentieth Century-Fox

WALL ST
2503 2d Nick's Union Service SE-3342
2515 2d Audograph of Washington EL-7322
2515 2d Dixon Don F MU-4161
2515 2d Gray Audograph Co Distributor . EL-7322
2515 2d Milprint Inc Sales Rep MU-4161
2517 2d Lee Dave M Co mfg agts MA-5512
2519 2d Fire-Fighter Co MU-1995
2519 2d Fyr-Fyter Co The MU-1995
2521 2d Wash Distributors EL-0305

VINE ST
2600 2d Jones R F Co SE-7255
2601 2d Eckstrom Earl E & Associates mfrs rep. EL-3818
2603 2d Corl Chemical Co MA-4077
2603 2d Falkenhagen Merrill mfrs rep ... EL-4330
2603 2d Givaudan-Delawanna Inc MA-4077
2603 2d Givaudan Flavors Inc MA-4077
2603 2d Patterson Foundry & Machine Co. MA-4077
2603 2d Sindar Corp MA-4077
2605 2d Brooks And Company machy SE-1570
2607 2d Coder Ellis L ofc SE-0740
2607 2d Coder Lloyd X SE-0740
2607 2d Finnell System Inc EL-7229
If no answer call AD-0728
2607 2d Savogran Pacific Corp SE-0740
2607 2d System Transfer & Storage Co . SE-0740
2607 2d Vitalastic Corp SE-0740
2607 2d Western Freight Assn SE-0740
2607 2d Western Zone Sales Co SE-0740
2609 2d Barcol Overdoors of Seattle MA-6861
2609 2d Johnston Overhead Door Co MA-6861
2609 2d Kold-Hold Division-Tranter Manufacturing Inc SE-8116
2609 2d Northwest Factors SE-8116
2609 2d Ralph M Johnston's Overhead Door Co. MA-6861
2609 2d Tecumseh Products Co SE-8116
2609 2d Yates O C Chuck mfrs agent ... SE-8116
2609 2d ..... Non-Pub
2611 2d A & P Display & Merchandising Service. EL-3215
2611 2d Northwest Display Service EL-3215
2611 2d Northwest Lot Services Inc EL-3215
2616 2d Jensen Verner O Co MU-2929
2618 2d Campbell Chain Co MU-4814
2618 2d Falkenhagen Merrill mfrs rep ... MU-4814
2619 2d Eastman Kodak Stores Inc MA-9072
2620 2d Bostick Wally ins MU-1866
2620 2d Peterson Insurance Agency MU-1866
2622 2d Cosman R J EL-8455
2622 2d Pump & Equip Co EL-8455
2624 2d Atsco Whsle Drug Co EL-5021

CEDAR ST
2700 2d Food of the Month Club of Seattle SE-7088
2700 2d .....(4)..... Non-Pub
2701 2d Ernst E E EL-5535
2701 2d K & E of Wash Inc EL-5535
2701 2d Keuffel & Esser of Washington Inc EL-5535
2702 2d World Ins Co SE-2821
Or SE-5188
2704 2d State Farm Mutual Auto Insurance Co Personal Injury Claims Dept SE-6580
2706 2d Kohler Eugene A EL-1135
2706 2d Seattle Injector & Electric Co .. EL-1135
After 6 PM call MI-6581
2708 2d General Binding Sales Corp MU-6399
2710 2d Clary Corporation ofc equip EL-5085
2712 2d Loheet Stainless Steel Co SE-8371
2712 2d .....(2)..... Non-Pub
2713 2d Arvik J E r MA-5931
2713 2d ..... Non-Pub
2713½ 2d Persson Swan r MA-4389
2714 2d Allied Printers The EL-2243
2715 2d Hammock Eve D MA-3845
2715½ 2d ..... Non-Pub
2718 2d Blumenthal Sidney & Co Inc SE-0348
2718 2d Shelton Looms Distributing Corp The. SE-0348
2722 2d Calvert Fire Insurance Co SE-5280
2722 2d Commercial Credit Corp MA-6740
2722 2d Commercial Credit Plan Industrial Loan Co. MA-6740
2725 2d Gow Alexndr Inc mar survyrs Fire Equipment Branch. MU-2660
2727 2d Phillips Distributing Co MU-4655
2727 2d Phillips J W Distributing Co MU-4655
2727 2d ..... Non-Pub
2729 2d Leigh Frank C EL-3737
2729 2d Universal Index Tab Co EL-3737

CLAY ST

2811 2d Seafair Restaurant EL-5415

BROAD ST

2d & Broad .....Non-Pub

2933 2d **WINDEMERE APTS**
2933 2d Aoki J S r.....EL-2156
2933 2d Aoki Min MA-2148
2933 2d Bauman Lyel Mrs r.....SE-4162
2933 2d Brenesk John MA-9125
2933 2d Craig Carl C r.....SE-0857
2933 2d DeSalliers Lee r.....EL-0909
2933 2d Finkel Richard MA-3087
2933 2d Gainus Irene E.....MA-9064
2933 2d Herdman Mason r.....SE-7871
2933 2d Hiett Ellen MA-2192
2933 2d Hill Patricia L.....EL-4382
2933 2d Hoffman Margarita MU-3896
2933 2d Howley N B r.....EL-2984
2933 2d Koser H L r.....SE-4079
2933 2d Lange Patricia L.....SE-8039
2933 2d LeFebvre W J r.....EL-7404
2933 2d Moore Lillian M.....EL-2831
2933 2d Peel Chas r.....MA-2879
2933 2d Peterson Hannah O r.....SE-1983
2933 2d Peterson Mildred A.....MA-2813
2933 2d Phillips Lenora SE-0612
2933 2d Santoro Jas V r.....SE-6025
2933 2d Santoro Vito r.....EL-8768
2933 2d Sullivan Toy Lee.....MA-8941
2933 2d Templeton Marie Inga.....EL-1776
2933 2d Weis Jessie M.....SE-5268
2938 2d Blue Line Inn.....SE-5783
2938 2d .....(3).....Non-Pub

CLAY ST

85 Clay Cochran Hershel r.....EL-3476
111 Clay Keystone Printing Co.....MA-7830

2nd AV

211 Clay Hayes Gordon ins.....EL-1881
211 Clay Mr Insurance Inc.....EL-1881

3rd AV

1950 2ND AVE

SOURCE: PACIFIC TELEPHONE

2321 2d Industrial Sales Co.....MA-8811
2321 2d Ken-Rad Lamp Div Westinghouse Elec Corp MA-8811
2321 2d Speedway Mfg Co.....MA-8811
2323 2d Allith Prouty Inc ofc.....EL-4356
2323 2d Favorite Films of California Inc.SE-6566
2323 2d King C A Co mfg agts.....EL-4356
2323 2d Slater W A Company confctnrs.MU-0155
2323 2d Western Equip & Supl Co.....MA-1190
2324 2d Master Auto Service.....EL-8065

2327 2d **WILLIAM TELL HOTEL**
2327 2d William Tell Hotel.....SE-9921
2331 2d Loew's Incorporated.....EL-4056
2331 2d Metro-Goldwyn-Mayer Pictures..EL-4056

BATTERY ST
2401 2d Universal Film Exchanges Inc...MA-3245

2402 2d **CONCORD APTS**
2402 2d Baker Fredrck D Jr r.....EL-6896
2402 2d Barnes Chester F r.....SE-1417
2402 2d Davis E L r.....MA-6682
2402 2d Estey H W r.....MA-4136
2402 2d Gustafson Magnus A r.....EL-4172
2402 2d Hansen H C Mrs r.....MA-7804
2402 2d Haugen E O r.....SE-7584
2402 2d Heltness G F r.....SE-5407
2402 2d Henry Claude E r.....EL-1037
2402 2d Holcomb T F r.....EL-5958
2402 2d Johnson Lillian B G Rev r.....MA-2422
2402 2d Johnson Mary R r.....EL-4857
2402 2d Jones Mildred A r.....EL-8359
2402 2d Kingdon Mildred r.....EL-5662
2402 2d Lyon Harold S r.....MA-2464
2402 2d Newbert K M r.....MA-8574
2402 2d Peha Katherine r.....EL-0312
2402 2d Platt Ick r.....EL-1649
2402 2d Sills J W r.....SE-2095
2402 2d Sowers Jeane R r.....EL-2103
2402 2d Walker Root R r.....MA-1615
2402 2d Warner Howard E r.....MA-6788
2402 2d Wileen J Leonard r.....EL-2587
2402 2d Wuslich Jos M r.....MA-5795
2402 2d .....(2).....Non-Pub
2403 2d Harden H ofc.....MA-3788
2403 2d Sullivan A J.....MA-3788
2403 2d United Artists Corp.....MA-3788
2405 2d Warner Bros Pictures Distrng Corp MA-0046

2408 2d **LEXINGTON APTS**
2408 2d Beattie Phyllis r.....SE-6865
2408 2d Betker Chris J r.....MA-3926
2408 2d Bormann Gloria N r.....MA-0061
2408 2d Brackett Lucy Mrs r.....EL-8563
2408 2d Cameron Kay r.....SE-1875
2408 2d Cottongym Z T r.....EL-2534
2408 2d Dunning Geo F r.....MA-5179
2408 2d Edwards Fredrck L r.....MA-6697
2408 2d Foster Irene r.....SE-0873
2408 2d Gregerson M H r.....EL-6166
2408 2d Griebie Grace r.....EL-0847
2408 2d Hardy Joey W r.....MA-9061
2408 2d Herron E B r.....EL-4278
2408 2d Jennings David M r.....MA-1866
2408 2d Longo Jos P r.....EL-0167
2408 2d Lukins Dorothy r.....SE-2635
2408 2d Munson Alda r.....MA-8891
2408 2d Murray Geo S r.....SE-5912
2408 2d Stacer Richard Kent r.....MA-5629
2408 2d Sullivan Myrtle M r.....SE-2639
2408 2d Tucker Sylvia r.....MA-7018
2408 2d Willard Patricia r.....MA-8294
2408 2d Wilson Grant r.....SE-7795
2408 2d .....Non-Pub
2412 2d Candy Distrs Inc.....MA-2617
2413 2d National Screen Service Corp...SE-2882
2414 2d Lippert Pictures.....SE-4787
2415 2d Columbia Pictures Corp.....EL-5349
2416 2d Photo-Electric Pilot Corp.....SE-4503
2417 2d Linden Record Corp.....SE-5949
2417 2d Western Recording Studio.....SE-5949
2418 2d Abbett Ralph W.....SE-2460
2418 2d Monogram Pictures of the Northwest Inc SE-2460
2419 2d Arnberg Ernie flameproofing...SE-1770
2419 2d Film Classics Inc.....EL-7330
2419 2d Film Classics Inc Seattle Exch EL-1789
2420 2d Commercial Realty Co.....SE-5575
2420 2d Denton Co.....SE-5575
2420 2d Motor-In Theatres.....SE-5575
2420 2d Northwest Bakers Exchange.....SE-5575
2420 2d Republic Pictures Corp.....EL-8678
2420 2d Spracher Dwight L.....SE-5575
2420 2d Swanberg Jack H Ins.....SE-5575
2420 2d Swanberg & Johnson Ins.....SE-5575
2421 2d Twentieth Century-Fox Film Corp.EL-7815

WALL ST
2d & Wall Union Oil Service No 3284....MA-9795
2516 2d Johanson Marie r.....EL-6021
2517 2d Western Herb Products Co.....EL-0625
2517 2d Western Natural Foods Co Inc....EL-0625
2518 2d Carlson Ernest r.....EL-6413
2521 2d Haroldson Vern Sales.....MA-8866
2521 2d Sanford D E Co mfrs rep.....SE-2958

VINE ST
2600 2d Sun Electric Corp motr testng equip.SE-5410
2601 2d Eckstrom Earl E & Associates mfrs rep.EL-3818
2603 2d Corl Chemical Co.....MA-4077
2603 2d Falkenhagen Merrill mfrs rep...EL-4330
2603 2d Kelite Products Co.....MA-6757
2603 2d Palmtag E R Co.....EL-4330
2603 2d Tague Jay.....MA-6757
2603½ 2d Patterson Foundry & Mach Co MA-4077
2605 2d Brooks Richard C Co machy.....SE-1570
2607 2d Coder Ellis L ofc.....SE-0740
2607 2d Coder Lloyd X.....SE-0740
2607 2d Finnell System Inc.....SE-0740
2607 2d Scott Paper Co.....SE-0740
2607 2d System Transfer & Storage Co SE-0740
2609 2d Overhead Door Co.....MA-6861
2609 2d .....Non-Pub
2611 2d A & P Display & Merchandising Service.EL-3215
2611 2d Caswell Coffee Co.....MA-8251
2611 2d Northwest Display Service.....EL-3215
2614 2d Kemble Chas r.....EL-3971
2614½ 2d Bitle D E r.....EL-5423
2616 2d Commodity Sales Co.....EL-6871
2616 2d Jensen Verner O Co.....EL-6871
2618 2d Nelson Harry N Co.....EL-1910
2622 2d Cosman R J.....EL-8455
2622 2d Pump & Equip Co.....EL-8455
2624 2d Atsco Whsle Drug Co.....EL-5021

CEDAR ST
2700 2d Baker Co Inc.....EL-2417
2700 2d Cash Register Exch.....EL-2417
2702 2d Dickey Thomas P Agency.....SE-2821
2702 2d World Ins Co.....SE-2821
2702 2d .....Non-Pub
2704 2d Universal Bee Jay Co punch brds.MU-1128
2706 2d Seattle Injector Co.....SE-2966
2708 2d Air-Way Branches Inc vacum clnrs.EL-8625
2708 2d Tilley W A.....EL-8625
2708 2d .....Non-Pub
2710 2d Clary Multiplier Corp.....EL-5085
2712 2d Lo-Heet Stainless Steel Co.....SE-8371
2712 2d .....Non-Pub
2713 2d Arvik J E r.....SE-5602
2713 2d .....Non-Pub
2713½ 2d Berg Maynard r.....MA-3595
2714 2d Allied Printers The.....EL-2243
2714 2d Amer Paper Products Co.....EL-2243
2715½ 2d Persson Swan r.....MA-4389
2716 2d Bludworth Marine.....SE-8424
2716 2d Gilmore J J Office.....SE-8424
2718 2d Blumenthal Sidney & Co Inc....SE-0348
2718 2d Shelton Looms Distributing Corp The.SE-0348
2722 2d Commercial Credit Corp.....MA-6740
2722 2d .....Non-Pub
2727 2d R C A Service Co Inc.....SE-5535
2729 2d Heine W F Supply Co mtl moldngs.SE-2876

CLAY ST
2808 2d MacBride Jewell r.....MA-1994
2811 2d White Spot The rest.....MA-9192

BROAD ST
2917 2d Christensen A L r.....MA-2353
2919 2d Douglass Wm C r.....EL-2897
2921 2d Maxwell Alfred r.....MA-4808
2921½ 2d Stephens Wm E r.....MA-6842
2923 2d Hoffman H L r.....EL-3408

2933 2d **WINDEMERE APTS**
2933 2d Bauman Lyel Mrs r.....SE-4162
2933 2d Broyles Jas N r.....MA-1822
2933 2d Carter Ruth E r.....MA-2175
2933 2d Chasey Genevieve r.....MA-7940
2933 2d Cote Florence I Mrs r.....SE-5560
2933 2d Craig Carl C r.....SE-0857
2933 2d Crawford Neal S r.....SE-5899
2933 2d Fisher Nora A Mrs r.....SE-7871
2933 2d Gibbs Paul C r.....MA-5780
2933 2d Haynes Leon W r.....SE-0830
2933 2d Howley N B r.....EL-2984
2933 2d Koser H L r.....SE-4079
2933 2d Lindskog Earl V r.....EL-7479
2933 2d Madden Jas Martin r.....MA-7921
2933 2d Madden V G Comndr r.....EL-2042
2933 2d Morgan Forrest E r.....SE-8176
2933 2d Neylon Ethel r.....MA-4453
2933 2d Noonan Mildred G r.....SE-1694
2933 2d Peel Chas r.....MA-2879
2933 2d Peterson Hannah O r.....SE-1983
2933 2d Phillips Lenora r.....SE-7167
2933 2d Rieker Oscar E r.....MA-8549
2933 2d Runck Jo r.....MU-0336
2933 2d Santoro Jas V r.....SE-6025
2933 2d Santoro Vito r.....EL-8768
2933 2d Shearer W A r.....MA-6909
2933 2d Tipton Edwin H r.....MA-0736
2933 2d Weller J R r.....SE-5728
2938 2d Blue Line Inn.....MA-9793
2938 2d .....(2).....Non-Pub

1950 CLAY ST

SOURCE: PACIFIC TELEPHONE

CLAY ST

WESTERN AV
85 Clay Hawkins Helga M r.....EL-7086

CLAY ST
111 Clay Keystone Printing Co.....MA-7830

2nd AV
211 Clay Morrison Music Co.....MU-1466
If no answer call.....GA-9384
215 Clay Allen Grace r.....MA-7116

3rd AV
309 Clay LaRue L W r.....EL-1707
319 Clay Rodgers Chas A.....SE-9010

2413 2d National Screen Service Corp...SE-2882
2415 2d Columbia Pictures Corp.....EL-5349
2417 2d ..... Non-Pub
2418 2d Abbett Ralph W.....SE-2460
2418 2d Monogram Pictures of the Northwest Inc SE-2460
2419 2d Altec Service Corp thtr eqpt....EL-8221
2419 2d Arnberg Ernie flameproofing...SE-1770
2419 2d Film Classics EL-1789
2419 2d ..... Non-Pub
2420 2d Saffle's Theatre Serv.....MA-4901
2421 2d Fox Movietone News.....EL-7815
2421 2d If no answer call EV-0990
2421 2d Twentieth Century Fox Film Corp EL-7815
2422 2d Republic Pictures Corp.....EL-8678

WALL ST

2505 2d Birkinshaw Faye r.....SE-0407
2509 2d Smith Marie T r EL-1374
2518 2d Revenig Elmer J Intr decrtr....EL-1668

VINE ST

2601 2d Norris Geo D Co mfrs agts.....EL-1344
2603 2d Brooks Richard C boilers.....SE-1570
2603½ 2d Corl Chemical Co.....MA-4077
2605 2d Simmons Co beds MA-4750
2607 2d Coder Ellis L ofc.....SE-0740
2607 2d Coder Lloyd X.....SE-0740
2607 2d Finnell System Inc.....SE-0740
2607 2d Pielow Transfer Co.....SE-0740
2607 2d Scott Paper Co.....SE-0740
2607 2d Superior Fast Freight SE-0740
2607 2d System Transfer & Storage Co..SE-0740
2607 2d Waller Geo D Sales Co.....EL-7936

2609 2d Overhead Door Co.....MA-6861
2609 2d Sound Sales elec appls.....MA-5502
2611 2d Caswell Coffee Co.....MA-8251
2611 2d Northwest Display Service Inc...EL-3215
2611 2d Thompson M A ofc.....EL-3215
2614½ 2d Karkanen Henry Mrs r.....MA-8970
2616 2d Jensen Verner O Co.....EL-6871
2618 2d Cronk Inc appls MA-6123
2618 2d Cronk Richard H acct.....MA-6123
2618 2d Nelson Harry N Co.....EL-1910
2622 2d Pump & Equip Co.....EL-8455
2624 2d Atsco Whsle Drug Co EL-5021
2626 2d Lee Dave M Co mfg agts.....MA-5512

CEDAR ST

2713 2d Atkinson C W r.....SE-0795
2713½ 2d Dahlberg Elaine r.....EL-6912
2715½ 2d Persson Swan r.....MA-4389

CLAY ST

2808 2d Gibson S r MA-4833
2811 2d White Spot The rest.....MA-9192

BROAD ST

2917 2d Christensen A L r.....MA-2353
2919 2d Douglass Wm C r.....EL-2897
2921 2d Clark Marjorie r.....EL-0906
2921½ 2d Stephens Wm E r.....MA-6842

2933 2d **WINDEMERE APTS**
2933 2d Arbogast Ray C r.....MA-8498
2933 2d Ayers Harold r.....MA-7040
2933 2d Benchley J E r MA-8549
2933 2d Bjorklund Verne r.....MA-4776
2933 2d Carr Georgia Mrs r.....EL-6885
2933 2d Cleaver P J r.....SE-1694
2933 2d Craig Carl C r.....SE-0857
2933 2d Elbrader Ruth r.....EL-1169
2933 2d Howley N B r.....EL-2984
2933 2d Madden Robt H r.....MA-6339
2933 2d Madden V G r.....EL-2310
2933 2d Peel Chas r.....MA-2879
2933 2d Peterson Hannah O r.....SE-1983
2933 2d Philp C E r.....EL-0349
2933 2d Shearer W A r.....MA-6909
2933 2d Smith Ralph M MA-3160
2933 2d Ungari Dorothy M r.....EL-2914
2933 2d Wells Robt C r.....EL-5412
2933 2d White Edith M Mrs r.....MA-8749
2933 2d Workman John r.....EL-6642
2933 2d ..... Non-Pub

1946 CLAY ST

SOURCE: PACIFIC TELEPHONE

CLAY ST

WESTERN AV

1st AV

115 Clay Arvik J E r.....SE-2832
115 Clay Johnson Andrew r.....EL-4745
117 Clay Cashdollar Harold J r.....MA-1860

2nd AV

215 Clay APARTMENTS
215 Clay Allen Grace r.....MA-7116

3rd AV

309 Clay LaRue L W r.....EL-1707

319 Clay APARTMENTS
319 Clay Schwab Helen A MA-9309

1942 2ND AVE

SOURCE: PACIFIC TELEPHONE

2418 2d Abbett Ralph W.....SE-2460
2418 2d Monogram Pictures of the Northwest Inc SE-2460
2419 2d Altec Service Corp thtr eqpt....EL-8221
2419 2d Cinema Screen Service.....EL-6163
2419 2d Zell Harold A.....EL-6163
2421 2d Twentieth Century Fox Film Corp EL-7815
2422 2d Gustafson C B acct.....MA-6434
2422 2d Republic Pictures of the Northwest EL-8678
2422 2d Sheffield Exchange System.....EL-8678

WALL ST

2505 2d Birkinshaw Faye r.....SE-0407
2505 2d Tillery Virgil U r.....MA-6763
2509 2d Smith Marie T r.....EL-1374
2516 2d Kirtley Molly Mrs r.....MA-0729
2518 2d Baker I E r.....EL-1668

VINE ST

2601 2d Sunlite Corp of Seattle.....MA-6090
2601 2d White Horace A.....MA-6090
2603 2d Brooks Richard C boilers.....SE-1570
2603½ 2d General Fire Truck Corp.....MA-8082
2603½ 2d Overhead Door Co.....MA-6861
2603½ 2d Supply Sales Co.....MA-6861
2605 2d Corl Chemical Co.....MA-4077
2605 2d Dingley H M mfr agt.....MA-3388
2605 2d Maplewood Co.....MA-3388
2605 2d Michigan Seamless Tube Co....MA-3388
2605 2d U S Air Compressor Co.....MA-3388
2607 2d Coder Lloyd X.....SE-0740
2607 2d Coder Ellis L ofc.....SE-0740
2607 2d Finnell System Inc.....SE-0740
2607 2d General Sales Co.....EL-6871
2607 2d Nelson Harry N Co.....EL-1910
2607 2d Pielow Transfer Co.....SE-0740
2607 2d System Transfer & Storage Co. SE-0740
2611 2d Caswell Coffee Co.....MA-8251
2611 2d Great Western Coffee Co Inc...MA-8251
2611 2d Northwest Display Service Inc...EL-3215
2611 2d Thompson M A ofc.....EL-3215

CEDAR ST

2712 2d APARTMENTS
2715½ 2d Persson Swan r.....MA-4389

CLAY ST

2808 2d APARTMENTS
2808 2d Smith Addie r.....MA-5882
2811 2d White Spot The rest.....MA-9192

BROAD ST

2917 2d Christensen A L r.....MA-2353
2921 2d Pallette Grace r.....EL-0257

2933 2d WINDEMERE APTS
2933 2d Allyn Fred E r.....EL-4238
2933 2d Billingsley Lena r.....SE-2893
2933 2d Cieutat John D r.....MA-0667
2933 2d Clark Caroline W r.....MA-8087
2933 2d Cleaver P J r.....SE-1694
2933 2d Craig Carl C r.....SE-0857
2933 2d Hewitt Harley W r.....EL-0793
2933 2d Howley N B r.....EL-2984
2933 2d Judge George M r.....MA-6092
2933 2d McMahon Evelyn r.....EL-8230
2933 2d Meisenheimer Shiral r.....EL-1059
2933 2d Peterson Hannah O r.....SE-1983
2933 2d Russo Joe D r.....EL-3577
2933 2d Scott Melvin W r.....MA-1020
2933 2d Shearer W A r.....MA-6909
2933 2d Smith Arthur M r.....MA-4899
2933 2d Watt Arthur M r.....MA-2956
2933 2d Wilson Dorothea r.....EL-1169

1942 CLAY ST

SOURCE: PACIFIC TELEPHONE

CLAY ST

WESTERN AV

85 Clay ..... Non-Pub

1st AV

115 Clay Johnson Andrew r.....EL-4745

2nd AV

215 Clay APARTMENTS
215 Clay Allen Grace r.....MA-7116

3rd AV

309 Clay LaRue L W r EL-1707
319 Clay APARTMENTS
319 Clay Durham Margaret r.....EL-2269

1939 2ND AVE-A

SOURCE: POLKS

2501-11 △Ohio Apartments
Birkenshaw Faye Mrs mgr
Adolphson T
Alfredson Walfred
Anderson Myrtle
Bland M Mrs
Bruce Robt L
Clifford Ed
Coates Lloyd O
Elliason Carrie Mrs
Falk Hazel L
Maxfield Eva
Nichols Mary
Olson Victor N jr
Salmond Walter S
Scherm Walter
Skinner Walter
Smith Marie
Spencer Frank
Vester Eug
Wangemann W J
Wilson E K Mrs
Winzenried Jack
Wyatt Homer S
2514 Bilderback Ruth Mrs
2516 △Kirtley Mollie Mrs
2518 Baker Ira E
2522 Vacant

Vine intersects

2601 △Rushlight A G & Co of Washington plmbg contrs
△Corl Chemical Co
2603 Brooks Richd C mfrs agt
2603½ Anderson Norman B radio repr
2605 Dingley H M Co mfrs agt
2607 △System Transfer & Storage Co
△Finnell System Inc machy
△Tilley Robt D refrigeration eng
2611 △Caswell Coffee Co
Northwest Display Service Inc
2612 Dahlbeck Chas
2612½ Hixson Howard H
2613 Vacant
2614 Suprenant Andrew A
2614½ Thorsen Knud
2620 Hyneman John W gas sta
Hender Ollie auto repr

Cedar intersects

2712-16 Apartments
△Humes Mabel E Mrs mgr
Berger Lawrence
Brown Wm
Burklund Peter
Gribben Leo
Kruger John
Lindsay Jas T
Marvin Walter
Parrish John F
2713 Bard Herbert M
Dolphin Elsie Mrs
2713½ △Keffler Elmer
O'Dell Dorothy Mrs
2715 △Prescott Geo W
2715½ Vacant

Clay intersects

2808 Apartments
△Smith A Alzora Mrs mgr
Brown Chas H
Foster Danl
Galvin John
Gibson Stewart
Hoffman Barney
Larson A E
2810 Jones Ira D
2811 △White Spot The restr

Broad intersects

2914 Vacant
2917 △Christensen Andrew L ◎
2919 Vacant
2920 McClary Chas M
Bates Blanche M Mrs
Hall Edgar H
2920½ Goodman Anna Mrs

2921½ Vacant
2923 Weisman Harriet Mrs
Fabulae Nickolas
2933 **Windemere Apartments**
Smith Frank E ◎
Attwell Percy B
Bray Jas A
Burrell Theo E
Cheney Eliz Mrs
Crow Carrie Mrs
Dwyer Maude E
Erskine A G
Godsall Elwood
Green John J
Harrison Audry
Henderson Kay
Howley Nell B
Jones David E
Lyle Ronald J
Mason Theo A
Saunders Thelma
Scott Melvin W
Shearer Walter A
Shelberg Irwin L
Simonson Orville
Teague Peter F
Truher Louis B
Wright Thos
se cor Westcott's restr
Denny way intersects

CLAY—Fr 2800 Elliott av ne
Western av intersects
85 Mathews F C
1st av intersects
115 Vacant
117 Cashdollar Walter I
2d av intersects
213 Baker Geo
215 **Apartments**
Allen Grace Mrs
Gilmore J Arth
Langton Albert W
Keeble Chas
3d av intersects
309 Bagger Jean N
311 Park Thos M veterinarian
319 **Apartments**
Hanson Augusta A ◎
Blythe Walter A
Briley E
Connick Edw
Eakin Wm J
Edgard Virginia Mrs
Foley Rex

1939 CLAY ST-B

SOURCE: POLKS

Gordon Jack
Henderson Sidney
Kragh Larry
McFadden Lester
Newton Delbert
Nolan Edw
Ramey Ernest
Snyder Roy
Vezina Antone
Wilson Bert O

4th av intersects

1934 2ND AVE-A

SOURCE: STREET ADDRESS DIRECTORY

2413	Paramount Pictures Distr Co Inc	Ma 4287
2415	American Seating Co	El 5982
2415	Columbia Pictures	El 5349
2415	Northern School Supply	El 5982
2417	Monogram Pictures	El 8678
2417	Sheffield Exch System	El 8678
2418	National Screen Service of Wash Inc	Se 2882
2419	Dyrness Marvin	Se 2143
2419	National Film Exch	Se 2511
2419	Stiles D F	Se 2143
2419	Thomason C E	Se 2143
2421	Universal Fil Exch	Ma 3245
2422	Bloom Sound Projection	Se 0241
2422	Higgins Pale	Se 0241
2422	Majestic Film Co	Se 0241
2422	Northwest Film Ser	Se 0241
2505	Johnson Carrie	Se 0407
2509	Russell L. S.	Ma 6615
2522	Hoo Sang Groc Co	El 8215
2607	Continental Car-Na-Var Corp	El 2288
2607	Dolliver & Bro	Se 0740
2607	Finnell System Inc	Se 0740
2607	Pielow Transfer Co	El 2288
2607	Scovill Mfg Corp	Se 0740
2607	Standard Conveyor Co	El 2288
2607	System Transfer & Storage Co	Se 0740
2611	Caswell Geo W Co	Ma 8251
2611	Chocolate Sales Corp	El 4546
2620	Standard Station	El 8951
2708	Lynch Geo Patrick	El 6839
2713½	Hansen Chas	Ma 4139
2808	Smith Addie Mrs	Ma 5882
2811	White Spot The	Ma 9192
2917	Christenson A L	Ma 2353
2933	Aagaard Annette M	Ma 5769

1934 2ND AVE-B

SOURCE: STREET ADDRESS DIRECTORY

2933	Chilton J O	El 1085
2933	Federici Thos	Ma 5795
2933	Hamilton Stanley G	Ma 0581
2933	Howley N B	El 2984
2933	Jamieson W L	El 1799
2933	Lawler J H	El 1085
2933	Lawson E L	Ma 5769
2933	McMahan A V	Se 0431
2933	Pew Clarence	El 4505
2933	Riegert R L	Ma 9299
2933	Shultz K B	Ma 8298
2933	Taylor Edward	Ma 7647

1934 CLAY ST

SOURCE: STREET ADDRESS DIRECTORY

Clay Street

115	Johnson Andrew	El 4745
117	Kendall Kyle W	Ma 0725
117	Kendall Laura Mrs	Ma 0725
319	Anderson R A	El 7357

1928 2ND AVE

SOURCE: STREET ADDRESS DIRECTORY

2415 Educational Film Exchange of Seattle El 4823
2417 Co-operative Film Exch El 7405
2417 Davis J W El 7405
2419 Cosmopolitan Film Exch El 6797
2419 Maritime Film Service El 5038
2419 Millward D C El 6797
2419 Olympic Film Studios El 5038
2419 Shaw Harry El 5038
2419 Shaw Slide Service El 5038
2419 Skreen Adz Co El 5038
2419 Tiffany Stahl Productions Inc El 6684
2419 Western Film Corp El 6797
2421 Universal Film Exchange Inc Ma 3245
2501 George Emma S Ma 1247
2505 Kirtley Mary Mrs Ma 5479
2507 Reith Wm S Ma 0760
2511 Bushman Josephine Mrs Ma 5943
2520 Wolff May El 6089
2524 Spickard Paul W Dr Ca 1069
2611 Caswell Geo W Co Ma 8251
2611 Chocolate Sales Corp El 4546
2611 Finch L S Chemical Corp El 2067
2611 Hershey Chocolate Co El 4546
2611 System Delivery Co El 2067
2612 Dial Olive E El 0416
2708 Lynch Geo P El 6839
2712 Hopkins Anna Ma 0930
2713½ Hansen Chas Ma 4139
2715½ Cumbo Chas Mrs Ma 7563
2808 Smith A Mrs Ma 5882
2917 Christensen A L Ma 2353

1928 CLAY ST

SOURCE: STREET ADDRESS DIRECTORY

CLAY

Ft of Clay
American Can Co El 2132
115 Burke Tom El 4823
117 Pearson Harry El 4745
215 Smith D F El 0844
309 Morris Chas El 2459
319 Peterson Fred Ma 3994

APPENDIX C
ARCHIVED TAXES

```
RVI150-18  (DATA ENTRY: RVI100-J)
C/I DATA COLLECTION AND DISPLAY FORM      (100)            ACCOUNT NO: 065400-0065-0
LOG/DATE:   PM3   02/05/96                                      FOLIO: 02178- -
LEVY CODE:  0010          LAST UPDATE: 02/05/96 BY: DWI
TAX STATUS: TAXABLE        APPR ID:____ MO__DA__YR__            AREA: 900
Q/SC/TW/RG: NW/31/25/04    __/__/__/__/                         DOWNTOWN SEATTLE

LAND USE:   502                          PROP NAME: LIGHTING SUPPLY
             INDUSTRIAL-WAR              (105)
PROPERTY ADDRESS:     2729        2ND                    AV
         (110)
                RB   NUM  FR  PR   STREET NAME          TY  SU

(112)++++++++++++++++++ COMMERCIAL/INDUSTRIAL LAND RECORD ++++++++++++++++++++++++

ZONING JURIS/__              SEATTLE          % USABLE/__                      100
ZONE ACTUAL/__                DMRC/*          TOPOGRAPHY/_                   LEVEL
ZONE CODE/__                LD MULTI          SHAPE/_                      REGULAR
LOT SIZE/_____.__          12,960.00          ACCESS/_                    STANDARD
    UNIT/S_A_                    SQFT         VISUAL EXPOSURE/_           STANDARD
CORNER LOT/Y_N_                   YES         OPEN SPACE CLASS.               NO
WATERFRONT ON/_                   NONE        RESTRICTIVE CONDITIONS/Y_N_     NO
                                              CONTAMINATED PROP  NO_ HW_ HC_ UT_ AS_  NO
(335)++++++++++++++++++++++++++++ PERMIT ACTIVITY ++++++++++++++++++++++++++++++++

ACT    BLDG:    TYPE    PERMIT DATE     VALUE        %  COMPLETE
---                                                 %    ___%
---                                                 %    ___%
___                                                 %    ___%
ADD  ___        ____     __/__/__    _________             ___%

(510)++DEL ALL BLDGS /__/+++++++ PROPERTY WIDE IMPROVEMENTS SUMMARY ++++++++++++++++

DESC: RETAIL                                  TOTAL BLDGS ON PROPERTY/__          1
                                              GROSS AREA (ALL BLDGS)/______   6,096
YEAR BLT/__ 48  CLASS/__       MASONRY        NET AREA (ALL BLDGS)/______     6,096
EFF YEAR/__ 57  QUAL/__        AVERAGE        MULTI-USE/Y_N_                     NO
LOT COVERAGE/_____               6,096        MULTI-PARCEL PROP/Y_N_             NO
NUMBER OF UNITS/___                  0

(500)++++++++++++++++++++++ INDIVIDUAL BUILDING DETAILS ++++++++++++++++++++++++++++

BLD CL QU   DESCRIPTION                    NU   GROSS    NET          %   %   HE  SP
NUM AS AL                                  ST   AREA     AREA    YB/EY  CMP AT  SH  KL
 #1 C  C  RETAIL                           1    6,096    6,096   48 65  100 SH  N
 #2 __ _ ___________________________ __  ______  ______  __/__   __  __      N
 #3 __ _ ___________________________ __  ______  ______  __/__   __  __      N
 #4 __ _ ___________________________ __  ______  ______  __/__   __  __      N
__ __ ___________________________ __  ______  ______  __/__   __  __      _
(520)++++++++++++++++++++ INTERIOR SECTION DETAILS ++++++++++++++++++++++++++++++++
------ SECT 1 ------------ SECT 2 ------------ SECT 3 ------------ SECT 4 -------
BLD#   AREA  STR-HT         AREA  STR-HT         AREA  STR-HT         AREA  STR-HT
1     2,400    14          3,696    14
 C02-STORE,RETAIL     D12-WAREHOUSE
     ______  __ _/__      ______  __ _/__      ______  __ _/__      ______  __ _/__
2

     ______  __ _/__      ______  __ _/__      ______  __ _/__      ______  __ _/__
3

     ______  __ _/__      ______  __ _/__      ______  __ _/__      ______  __ _/__
4

     ______  __ _/__      ______  __ _/__      ______  __ _/__      ______  __ _/__

(589)++++++++++++++++++++ACCESSORY IMPROVEMENT SUMMARY ++++++++++++++++++++++++++++
 ACT  ENT   DESCRIPTION                    ACT  ENT   DESCRIPTION

/__/  (1)   ____________________           /__/  (2)  ____________________

(160)++++++++++++++++++++++++++++++++ COMMENTS ++++++++++++++++++++++++++++++++++++

          ---------------------------------------

00054
```

**JOB RV1100 C/I PARCEL VALUE ANALYSIS WORKSHEET PARCEL NO: 065400-0065-0
RPT RV1150-20 PRINTED ON: 09/11/93 FOLIO: 02178- -
PROP NAME: LIGHTING SUPPLY Q-S-T-R: NW-31-25-04
PROP ADDR: 2729 2ND AV AREA: 900 LUC: 502
CLASS: MASONRY QUAL: AVERAGE TAX STATUS: TAXABLE
YR-BLT/EFF-YR: 48/57 #STY: 01 #UNITS: LOG/DATE: 900 09/11/93
GBA/NRA: 6,096 / 6,096 AVG-UNIT-SIZE: SEG-MERGE DATE:

* * * * * * * ECONOMIC INCOME * * * * * * * * * * * * * * * * COST APPROACH * * * *

USE	AREA	RATE	GROSS	VCL	EXP	NET INC
RETAIL	6100	$ 12.00	73200	5%	20%	55600
		$				
		$				
		$				
		$				
		$				

OCC# CL RANK
#STY STY HT EFF AGE
HEAT ELEV SPR
AREA PERIM
MISC CODE SF
CODE SF
CODE SF

* * * * ECONOMIC INCOME APPROACH * * * * * * * * * *

NET INCOME
LESS PER. PROP. INCOME
LESS LAND INCOME
X(+) =
LAND VALUE INT + TAX
NET IMPROVEMENT INCOME
CAPITALIZATION RATE
+ + =
INT + TAX + RECAP
CAPITALIZED IMP. VALUE
LAND VALUE
EXCESS LAND/ADD LAND
TOTAL BY INCOME APPROACH $
= $/SF

* * * * OTHER VALUE INDICATORS * * * * *

NET INC (55600)/(9)OAR= 617800
GR INC ( )X( )GRM=
UNITS( )X( )$/UNIT=
GBA (6,096)X( )$/SF=
RA (6,096)X(100)$/SF= 609600

* * * * * * * * * LAND * * * * * * * * *

ZONE/TYPE	AREA	$/SF	VALUE
			=$
			=$
			=$
TOTAL	12960.00SF	65	=$

RATIOS: (SF LAND)/(SF GBA) = 2.1
(SF LAND)/(SF RA) = 2.1

* * * * * SELECTED VALUE * * * * * * * *

APPRAISER KHC LAND $ 84 2400
DATE 5-11-94 IMPS $ 1000
TOTAL $ 843400
=$ /UNIT OR =$ /SF

ACCY IMPS	AREA	COST	DEP	RCNLD

M&S BASE
HEAT
SPRINKLER
ELEVATOR
TOT BASE
STY FACT
HGT FACT
AREA FACT
REF COST
COST MULT
LCL MULT
FINAL COST

STY/BLDG	AREA	FIN COST	RCN-BLDG#1

SUB TOTAL
PHYSICAL DEPRECIATION
ECON-FUNCT OBSOLESCENCE
DEPRECIATED IMP VALUE
ACCESSORY IMPS (SEE ABOVE)
TOTAL IMPROVEMENTS
LAND
TOTAL BY COST APPROACH =$ /SF

* * * * * * * * * * * * * * * * * * SALES & COMPARABLES * * * * * * * * * * * * * * *

PARCEL #	E-NUMBER	SALES PRICE	VC	DATE	$/RA	REMARKS

* * * * * * * * * * * * * * * * * * APPEAL ACTIVITY * * * * * * * * * * * * * * * * * *

PETITION	CHG ORDER	DATE	FROM-LAND	TO-LAND	FROM-IMPS	TO-IMPS

OTHER APPEALS:

* *COMMENTS *

LIGHTING SUPPLY
VALUED @ 600K FOR IMPS @ MINIMUM

05086

33 00

**JOB RVI100 C/I PARCEL VALUE ANALYSIS WORKSHEET PARCEL NO: 065400-0065-0
RPT RVI150-20 PRINTED ON: 11/27/91 FOLIO: 02178- -
PROP NAME: LIGHTING SUPPLY Q-S-T-R: NW-31-25-04
PROP ADDR: 2725 2ND AV AREA: 900 LUC: 502
CLASS: MASONRY QUAL: AVERAGE TAX STATUS: TAXABLE
YR-BLT/EFF-YR: 48/57 #STY: 99 #UNITS: LOG/DATE: 900 11/27/91
GBA/NRA: 6,000 / 6,000 AVG-UNIT-SIZE: SEG-MERGE DATE:

* * * * * * ECONOMIC INCOME * * * * *

**JOB RVI100 C/I PARCEL VALUE ANALYSIS WORKSHEET PARCEL NO: 065400-0065-0
RPT RVI150-20 PRINTED ON: 12/09/89 FOLIO: 02178- -
PROP NAME: LIGHTING SUPPLY Q-S-T-R: NW-31-25-04
PROP ADDR: 2725 2 2ND AV AREA: 900 LUC: 502
CLASS/QUAL: MASONRY/ AVERAGE CONDITION:_____ TAX STATUS: TAXABLE
YR-BLT/EFF-YR: 48/57 #STY: 99 #UNITS: LOG/DATE: 900 12/09/89
GBA/NRA: 6,000 / 6,000 AVG-UNIT-SIZE: SEG-MERGE DATE:

* * * * * * * ECONOMIC INCOME * * * * * * * * * * * * * * * COST APPROACH * * * *

USE	AREA	RATE	GROSS	VCL	EXP	NET INC
		$_____				
		$_____				
	6000	$ 10	60000	6	15	48450
		$_____				
		$_____				
		$_____				

OCC#_____ CL__ RANK__
#STY __ STY HT __ EFF AGE__
HEAT __ ELEV __ SPR_____
AREA _____ PERIM____
MISC ___CODE _____SF
___CODE _____SF
___CODE _____SF

* * * * ECONOMIC INCOME APPROACH* *

NET INCOME _____
LESS PER. PROP. INCOME _____
LESS LAND INCOME _____
_____X(____+____) = _____
LAND VALUE INT + TAX
NET IMPROVEMENT INCOME _____
CAPITALIZATION RATE _____
_____ + _____ + _____ = _____
INT + TAX + RECAP
CAPITALIZED IMP. VALUE _____
LAND VALUE _____
EXCESS LAND/ADD LAND _____
TOTAL BY INCOME APPROACH $_____
= $_____/SF

ACCY IMPS	AREA	COST	DEP	RCNLD

M&S BASE				
HEAT				
SPRINKLER				
ELEVATOR				
TOT BASE				
STY FACT				
HGT FACT				
AREA FACT				
REF COST				
COST MULT				
LCL MULT				
FINAL COST				

* * * * OTHER VALUE INDICATORS* * * * *

NET INC(48450)/(.095)OAR= 510,000
GR INC ( )X( )GRM=_____
UNITS( )X( )$/UNIT=_____
GBA (6,000)X(85)$/SF= 510,000
RA (6,000)X( )$/SF=_____

STY/BLDG	AREA	FIN COST	RCN-BLDG#1

* * * * * * * * * LAND* * * * * * * * *

ZONE/TYPE	AREA	$/SF	VALUE
			=$_____
			=$_____
			=$_____
TOTAL	12960.00SF	45	=$_____

RATIOS: (SF LAND)/(SF GBA)= 2.2
(SF LAND)/(SF RA) = 2.2

SUB TOTAL _____
PHYSICAL DEPRECIATION _____
ECON-FUNCT OBSOLESCENCE _____
DEPRECIATED IMP VALUE _____
ACCESSORY IMPS(SEE ABOVE)_____
TOTAL IMPROVEMENTS _____
LAND _____
TOTAL BY COST APPROACH _____
=$_____/SF

* * * * * SELECTED VALUE* *

APPRAISER RWL LAND $ 583,200
DATE 3/20 IMPS $ 1000
TOTAL $ 584,200
=$_____/UNIT OR =$_____/SF

* SALES & COMPARABLES *

PARCEL #	E-NUMBER	SALES PRICE	VC	DATE	$/RA	REMARKS
	907365		--		$85/¢	

* APPEAL ACTIVITY *

PETITION	CHG ORDER	DATE	FROM-LAND	TO-LAND	FROM-IMPS	TO-IMPS

OTHER APPEALS:

* *COMMENTS *

ZONED DMP/C 12/5/65
INCOME & SALES ANALYSIS INDICATE
VALUE of $85/¢ - DOES NOT SUPPORT
LAND - ∴ EV IMPS @ $1000

02084

ASSESSOR'S FORM NO. 250-2 FOLIO NO 2178 ASSESSOR'S ACCT NO 065400 - 0065

GRADE C	L/C	USE CODE		STORY STATISTICS	STORIES	1 -						
YEAR BUILT	1948	CONDITION			PERIMETER							
EFFECTIVE AGE		NO. OF UNITS			SQUARE FEET							

STORY HGT.	ADDITIONS		FLAT ITEMS		BUILDING CALCULATIONS						
BSMT.	SF @		PLUMBING		STORIES	1 -					
1 ST	SF @				BASE						
2 ND	SF @				HGT. FAC.						
3 RD	SF @				AREA FAC.						
4 TH	SF @				STY. FAC.						
5 TH	SF @				ADJ. FAC.						
6 TH	SF @				ADJ. BASE						
7 TH	SF @				BSMT.						
8 TH	SF @				FLOOR						
9 TH	SF @				ROOF						
10 TH	SF @				CEIL						
11 TH	SF @				PART						
					HEAT						
					AIR COND.						
					LIGHTS						
					SPRINK.						
					TOTAL						
					STORIES						
						SF @					
						SF @					
						SF @					
						SF @					
	TOTAL		TOTAL			SF @					

	AREA OR QUANTITY	UNIT COST	REPLACE COST	FFF. AGE	DEPR. NET	TOTAL VALUE
TOTAL ACCESSORY BUILDINGS & OTHER IMPROVEMENTS						$

FLAT ITEMS	
SUB - TOTAL	
ADDITIONS	
TOTAL	
COST FACTOR	
TOTAL REPLACEMENT COST	$
PHYSICAL DEPRECIATION (NET)	X
TOTAL PHYSICAL VALUE	$
ECON. OR FUNCT OBSOL. (NET)	X
FINAL APPRAISED VALUE	$
PERCENT COMPLETE (NET)	X
PARTIAL VALUE	$

INCOME APPROACH	ACTUAL	ECONOMIC
ANNUAL POTENTIAL GROSS		30480
LESS VAC. & CREDIT LOSS		.90
ANNUAL EFFECTIVE GROSS		
LESS EXPENSES		.75
ANNUAL NET INCOME		20574
6 + 1 + 7 (INT. RATE + TAX RATE + LAND RATE)		
LESS LAND INCOME: 220300 x .07 = (LAND VALUE x LAND RATE)		-15421
NET INCOME TO BUILDING		5153
6 + 1 + 4 = (INT. RATE + TAX RATE + RECAPTURE RATE = BLDG RATE)		11%
BUILDING VALUE		46845
PERSONAL PROP VALUE		
LAND VALUE		220300
INDIC TOTAL PROPERTY VALUE		267145
INCOME APPROACH	# 1	# 2 43.82¢
3. COST APPROACH OR RCN		
4. MKT # 1: ___ GRM x ___ GROSS =		
5. MKT # 2: ___ NO. UNITS x ___ $ PER UNIT =		
6. MKT # 3: ___ AREA x ___ $ PER SQ. FT. =		
SELECTED VALUE:	LAND	220300
APPRAISER GFA	BLD'S	46800
DATE 2-86	TOTAL	267100

'88 Value - 0065 + bldg on 0070 merged total AV is 474500 or 77.83 per SF. NC for 1989

COMMENTS

Lighting & Supply Co - Retail + whse

0070 is parking for this parcel - Storage type Bldg used as retail

6096 @ GBA @ 5.00 = 30480

Subject has off Street Parking

Sales: E 629499 6480@ = $34.72

E 730877 12224@ = $40.98

E 736643 14770@ = $47.39

E 670419 6480@ = $57.87

Office Sales Same Size as subj $60.00 $105.00 @

" " " " " " 75.88 @

with off Street Parking

6480@ @ 34.00 = $220320

SALES

	PARCEL	E #	AMOUNT	DATE	LOCATION	NOTES
SUBJECT						
SUBJECT						
COMP						
COMP						

ASSESSOR'S FORM NO. FOLIO NO. 2178 ASSESSOR'S ACCT NO. 065400-0065

GRADE		USE CODE		STORY STATISTICS	STORIES	1 -					
YEAR BUILT		CONDITION			PERIMETER						
EFFECTIVE AGE		NO. OF UNITS			SQUARE FEET						

STORY HGT.	ADDITIONS		FLAT ITEMS		BUILDING CALCULATIONS						
BSMT.	SF @		PLUMBING		STORIES	1 -					
1 ST	SF @				BASE						
2 ND	SF @				HGT. FAC.						
3 RD	SF @				AREA FAC.						
4 TH	SF @				STY. FAC.						
5 TH	SF @				ADJ. FAC.						
6 TH	SF @				ADJ. BASE						
7 TH	SF @				BSMT.						
8 TH	SF @				FLOOR						
9 TH	SF @				ROOF						
10 TH	SF @				CEIL						
11 TH	SF @				PART						
					HEAT						
					AIR COND.						
					LIGHTS						
					SPRINK.						
					TOTAL						
					STORIES						
						SF @					
						SF @					
						SF @					
						SF @					
	TOTAL		TOTAL			SF @					

	AREA OR QUANTITY	UNIT COST	REPLACE COST	FFF. AGE	DEPR. NET.	TOTAL VALUE
TOTAL ACCESSORY BUILDINGS & OTHER IMPROVEMENTS						$

FLAT ITEMS	
SUB - TOTAL	
ADDITIONS	
TOTAL	
COST FACTOR	
TOTAL REPLACEMENT COST	$
PHYSICAL DEPRECIATION (NET)	X
TOTAL PHYSICAL VALUE	$
ECON. OR FUNCT OBSOL. (NET)	X
FINAL APPRAISED VALUE	$
PERCENT COMPLETE (NET)	X
PARTIAL VALUE	$

INCOME APPROACH

	ACTUAL	ECONOMIC
ANNUAL POTENTIAL GROSS		45,720
LESS VAC. & CREDIT LOSS		-5%
ANNUAL EFFECTIVE GROSS		
LESS EXPENSES		-20%
ANNUAL NET INCOME		34,747

6 + 1 = 7
INT RATE TAX RATE LAND RATE

LESS LAND INCOME:
291,600 x .07 = 20,412
LAND VALUE LAND RATE

NET INCOME TO BUILDING 14,335

÷ BLDG RATE: 15 YR
6 + 1 + 6.5 = 13½%
INT. RATE TAX RATE RECAPTURE RATE BUILDING RATE

BUILDING VALUE 106,185
PERSONAL PROP. VALUE
LAND VALUE
INDIC TOTAL PROPERTY VALUE

	INCOME APPROACH	# 1	# 2
3.	COST APPROACH OR RCN		
4.	MKT # 1: ____ (GRM) x ____ (GROSS) =		
5.	MKT # 2: ____ (NO. UNITS) x ____ ($ PER UNIT) =		
6.	MKT # 3: ____ (AREA) x ____ ($ PER SQ. FT.) =		

SELECTED VALUE: LAND 291,600
APPRAISER DSL BLD'S 106,000 → 17.40/sf (BLDG)
DATE 2/82 TOTAL 397,600 → 61.25/sf (LAND)

COMMENTS

1 STORY RETAIL
6096 sf @ 7.50 (ECON) OWNER OCCUPIED(?)

LAND: 6480 sf @ 45/sf = 291,600

SALES

	PARCEL	E #	AMOUNT	DATE	LOCATION	NOTES
SUBJECT						
SUBJECT						
COMP	0075 -	this folio				
COMP						

retail / whse.

REFERENCE ONLY

ASSESSOR'S FORM NO. 250-2 FOLIO NO. 2178 ASSESSOR'S ACCT NO. 065400-0065

GRADE	C	USE CODE		STORY STATISTICS	STORIES	1-						
YEAR BUILT	1917	CONDITION	AVG		PERIMETER	336						
EFFECTIVE AGE	10 ~~40~~	NO. OF UNITS			SQUARE FEET	6096						

STORY HGT.	ADDITIONS		FLAT ITEMS		BUILDING CALCULATIONS						
BSMT.	SF @		PLUMBING		STORIES	1-					
1 ST	SF @				BASE						
2 ND	SF @				HGT. FAC.						
3 RD	SF @				AREA FAC.						
4 TH	SF @				STY. FAC.						
5 TH	SF @				ADJ. FAC.						
6 TH	SF @				ADJ. BASE						
7 TH	SF @				BSMT.						
8 TH	SF @				FLOOR						
9 TH	SF @				ROOF						
10 TH	SF @				CEIL						
11 TH	SF @				PART						
					HEAT						
					AIR COND.						
					LIGHTS						
					SPRINK.						
					TOTAL						
					STORIES						
						SF @					
						SF @					
						SF @					
						SF @					
						SF @					
TOTAL			TOTAL								

	AREA OR QUANTITY	UNIT COST	REPLACE COST	FFF. AGE	DEPR NET	TOTAL VALUE
TOTAL ACCESSORY BUILDINGS & OTHER IMPROVEMENTS						$

FLAT ITEMS	
SUB-TOTAL	
ADDITIONS	
TOTAL	
COST FACTOR	
TOTAL REPLACEMENT COST	$
PHYSICAL DEPRECIATION (NET)	x
TOTAL PHYSICAL VALUE	$
ECON. OR FUNCT OBSOL. (NET)	x
FINAL APPRAISED VALUE	$
PERCENT COMPLETE (NET)	x
PARTIAL VALUE	$

6480 @ 20 129 600

INCOME APPROACH

	ACTUAL	ECONOMIC
ANNUAL POTENTIAL GROSS		22860
LESS VAC. & CREDIT LOSS		95
ANNUAL EFFECTIVE GROSS		21 717
LESS EXPENSES		95
ANNUAL NET INCOME		18459

6 + 1 = 07
INT. RATE TAX RATE LAND RATE

LESS LAND INCOME:
129 600 x 07 = 9072
LAND VALUE LAND RATE
NET INCOME TO BUILDING 9387

÷ BLDG RATE:
6 + 1 + 6.6 = .17
INT. RATE TAX RATE RECAPTURE RATE BUILDING RATE

BUILDING VALUE 55217 = 9004
PERSONAL PROP. VALUE
LAND VALUE
INDIC TOTAL PROPERTY VALUE

	INCOME APPROACH # 1	# 2
3. COST APPROACH OR RCN		
4. MKT # 1: ___ (GRM) x ___ (GROSS) =		
5. MKT # 2: ___ (NO. UNITS) x ___ ($ PER UNIT) =		
6. MKT # 3: ___ (AREA) x ___ ($ PER SQ. FT.) =		

SELECTED VALUE: LAND 129600
APPRAISER JJ BLD'S 55200
DATE 6/11/80 TOTAL 184800

COMMENTS

set unit @ 3.75 Lighting supply
6096 @ 3.75

SALES

	PARCEL	E #	AMOUNT	DATE	LOCATION	NOTES
SUBJECT						
SUBJECT						
COMP						
COMP						

KING COUNTY ASSESSOR'S COMMERCIAL - INDUSTRIAL CHARACTERISTICS COLLECTION RECORD
LAND AND PRINCIPAL IMPROVEMENTS

RVI 818-2

ACCOUNT 065400-0065 (3) (9) (13) BATCH V,A (1) REV A (18)

A,1 FOLIO 2178 (21) L N 1/4 2 (30) SEC 31 TWP 25 RGE 4 AREA (64) LAND USE 637 (57) OWNER (61) BLDG (28) SHEETS (30) C (68)

A,2 PROPERTY NAME (21)

A,3 RT/BOX (21) NUMBER 2725 1/ (23) (26) PREF (30) 12 N.D. STREET NAME (33) ST. TYPE AV (53) SUF (56)

LAND DATA

A,4 APPRAISER 96 (21) DATE 10-21-76 (25)

NEIGHBORHOOD (32) PARK ID (33) LOCATION 2 (36) TOPOGRAPHY (37) USABLE (38) % GRADE (61) SHAPE (62)

UNIT S (41) SIZE 64.80 (42) WIDTH (50) DEPTH (55)

MAJOR ACC (63) PAVING (64) RAIL ACC (65) WFT (66) VIEW (67) REC WTR (68) PUB TRANS (69) VISUAL (70) PARKING (71)

A,5 RESTRICTIONS:

PHYSICAL: DRAINAGE (21) FILL (22) PILING (23) PERCOLATION (24) GRADE (25) SLIDE (26) POWER (27) WATER (28)

GAS (29) SEWER (30) STORM SEWER (31) ECONOMIC: NUISANCE (32) INHARMONIOUS (33)

LEGAL: ZONE ACTUAL RM/MD (34) JURISDICTION SE (41) CODE 3 (43) CONFORM (44) H. B. U. (45) SHORELINES (46)

FLD-PLN (47) HISTORICAL (48) O'ZONE 4 (49) O'ZONE 5 (50) RIGHTS (52) DEED (53) HEALTH (54) R. O. W. (55) EASEMENTS (56)

BUILDING DATA

BUILDING NO. 1 (14)

C,3 DESCRIP STORES (21)

YR BUILT 48 (53) LOT COVERAGE 6096 (56) STORIES 1 (61) EFF YR 57 (63) GRADE A,V (65) LEASE (67) LESSEE OWNED (68)

C,5 BUILDING SECTIONS: 70/45 TOTAL BUILDING AREA 6096

SEC	TYPE	CL	QUAL	STRS	HT	PERIM	AREA	WALL	FLR	ROOF	NO. ELEV	NO. ESCL	HEAT	A/C
1	D.1.2	C.	C	1	14	336	6096	6	4	1			1	

(16) (21) (24) (26) (27) (29) (31) (35) (41) (43) (45) (47) (49) (51) (53)

C,6 INTERIOR AREAS:

SEC	AREA	FLOOR	USE	QUAL	MEAS TYPE	AREA SIZE	ELEV IND	HEAT TYPE	A/C TYPE	SPRK TYPE	PLB QUAL	ELEC QUAL	NO. UNITS
1	1	1	D.1.2	C		6096					C	C	

(16) (17) (21) (23) (26) (27) (28) (34) (35) (37) (39) (41) (43) (45)

D,2 APARTMENT DATA:

STUDIO APTS (21) 1 BDRM (24) 2 BDRM (27) 3+ BDRM (30) NO. FUR. APTS (33)

SECURITY (36) NO. LANAIS (37) FIN AREA _____ AVG SIZE _____

ASSESSOR'S FORM NO. 250

ASSESSOR'S FORM NO. 250-2

GRADE		USE CODE		STORY STATISTICS	STORIES	1-						
YEAR BUILT		CONDITION			PERIMETER							
EFFECTIVE AGE		NO. OF UNITS			SQUARE FEET							

STORY HGT.	ADDITIONS		FLAT ITEMS		BUILDING CALCULATIONS							
BSMT.	SF @		PLUMBING		STORIES	1-						
1 ST	SF @				BASE							
2 ND	SF @				HGT. FAC.							
3 RD	SF @				AREA FAC.							
4 TH	SF @				STY. FAC.							
5 TH	SF @				ADJ. FAC.							
6 TH	SF @				ADJ. BASE							
7 TH	SF @				BSMT.							
8 TH	SF @				FLOOR							
9 TH	SF @				ROOF							
10 TH	SF @				CEIL.							
11 TH	SF @				PART.							
					HEAT							
					AIR COND.							
					LIGHTS							
					SPRINK.							
					TOTAL							
					STORIES							
						SF @						
						SF @						
						SF @						
						SF @						
	TOTAL		TOTAL			SF @						

	AREA OR QUANTITY	UNIT COST	REPLACE COST	FFF. AGE	DEPR. NET	TOTAL VALUE
TOTAL ACCESSORY BUILDINGS & OTHER IMPROVEMENTS						$

FLAT ITEMS	
SUB-TOTAL	
ADDITIONS	
TOTAL	
COST, FACTOR	
TOTAL REPLACEMENT COST	$
PHYSICAL DEPRECIATION (NET)	X
TOTAL PHYSICAL VALUE	$
ECON. OR FUNCT OBSOL. (NET)	X
FINAL APPRAISED VALUE	$
PERCENT COMPLETE (NET)	X
PARTIAL VALUE	$

INCOME APPROACH

	ACTUAL	ECONOMIC
ANNUAL POTENTIAL GROSS		13167
LESS VAC. & CREDIT LOSS - 5%		-658
ANNUAL EFFECTIVE GROSS		
LESS EXPENSES - 15%		-1975
ANNUAL NET INCOME		
7 + 2 • 9 (INT. RATE + TAX RATE • LAND RATE)		
LESS LAND INCOME: 68000 x 9 = (LAND VALUE x LAND RATE)		-6120
NET INCOME TO BUILDING		4414
÷ BLDG RATE: 7 + 2 + 4 = (INT. RATE + TAX RATE + RECAPTURE RATE)		13 (BUILDING RATE)
BUILDING VALUE		33900
PERSONAL PROP. VALUE		
LAND VALUE		68000
INDIC TOTAL PROPERTY VALUE		101900

INCOME APPROACH	#1	#2
3. COST APPROACH OR RCN		
4. MKT #1: ___ (GRM) x ___ (GROSS) =		
5. MKT #2: ___ (NO. UNITS) x ___ ($ PER UNIT) =		
6. MKT #3: ___ (AREA) x ___ ($ PER SQ. FT.) =		

SELECTED VALUE: LAND 68000; BLD'G 33900; TOTAL 101900

APPRAISER 10

DATE 11/22/76

COMMENTS

RENT =

4256 @ LIGHTING SUPPLY OWN OCC

1840 @ ALEXANDER FIRE EQUIP $412.50/MO

MO TO MO TENANT PAYS OWN UTL

EST. ECON. RENT - .184

SALES

	PARCEL	E #	AMOUNT	DATE	LOCATION	NOTES
SUBJECT			80000	1970		
SUBJECT			157000	12-72		INC MI 0070
COMP						
COMP						

FOLIO 2178

PERMIT No. 387843

DATE 5-18-48

ADDITION Bell + Dennys 1st Add. Section Twp. Range Ewm Block 19 Tract or Lot 5

OK 0065

tegs pool for 51.

FOR REFERENCE ONLY STORE C REM STORAGE SEALED

2725-29 - 2nd Ave. 10-21-10 S2-A FM6 E-143 C-515

WJ Hudson + Billy J. Eichu P

SALE 1970 $80,000.

Fee Owner Gibbs + Hudson Address of Property No. Architect

Condition of Exterior A Interior A Foundation A Floor Plan: Good Accept Poor

USE Stores

- 1 No. Stories
- 4 No. Stores
- No. Rooms
- Basement
- No. Offices
- No. Apartments
- 1 rm. 2 rm. 3 rm.
- 4 rm. 5 rm.

TYPE OF CONSTRUCTI

- Frame
- Single Dou
- X Ordinary Masonry
- Mill Construction
- Class A Rein. Con.
- Stru. Steel and Con.
- Tile Brick
- X Con. Blk Rein.

Good X Med. Cheap.

FOUNDATION

- Mud Sills
- Post and Pier
- Brick
- X Concrete
- Pile

BASEMENT

- Full %
- Sub-Basement
- 41 Size x
- Garage No. Cars
- D- Floors
- Plastered
- Living Rooms
- Service Rooms

ROOF CONSTRUCTION

- X Frame Lam
- Mill Construction
- Rein. Concrete
- No. Trusses
- Wood Steel

ROOFING MATERIAL

- X Tar

Date Built

Effective A

Dep. for C

FLOOR FINISHES

- Fir Maple
- Oak 2" x 6" T&G
- Lino. 3" x 6" T&G
- X Cement 13ob REM
- Terrazzo
- Racolith

X Tile Lino.

Tile: X Baths Fl. Walls; Sq. Ft. 2200 Floors; Sq. Ft. Walls; Lin. Ft. Dr. Bds.; Total Sq. Ft. Floors; Sq. Ft. Walls

Lino. Total

PLUMBING

- 15 No. Fixtures
- 7 Toilets
- Tubs, Leg or Pem.
- Basins, ~~Bed~~
- 4 Sinks
- Urinals
- Showers (Tub) (Stall)
- Laundry Trays
- H.W.Tank Fl. Drains
- Sprink. Sys. No. Hds.

HEATING

- Stove H45 GAS
- Pipeless Furnace 100%
- Gravity H. A.
- Air Cond., Fan 9RS
- Arcola Suspended
- 1-Pipe Steam
- 2-Pipe St. or Vapor
- Hot Water
- Oil Burner
- Coal Stoker

WIRING

- Knobe & Tube
- Flex Cable 10100 4065
- Conduit
- Power Wiring
- Range Wiring
- No. Outlets

ELEVATORS

- Pass. Freight
- Auto. Elec.
- Man. Hyd.
- Man.

8800 X 49



F-3178

Other Buildings $

Total $

Assessed Value 50% $

Sup. Building A. V. $

Total $

EXTERIOR WALL CONSTR.

- Single Double
- 2" x 4" Stud Walls
- 2" x 6" Stud Walls
- Brick Walls
- Brick With Pilasters
- X Concrete Walls 10 4/12 8" BLK
- X Con. With Pilasters
- Tile Walls
- Rein. Con. Skel.
- Filler Walls
- Laminated Walls

EXTERIOR FACING

- Siding Shingles
- Shakes X Stucco 2 REM
- Brick Veneer 168 x 1
- X Conc. Blk. 2 Kind ROCK
- Stone Cast S.
- Terra Cotta
- X Struct. Glass 72 LF x 4
- Trim

FLOOR CONSTRUCTION

Joist Con. Size x

O. C. In Bridg

- Mill Construction
- X Rein. Con.

INTERIOR WALLS

- X Stud and Plaster
- Lam. Plastered
- X Ply Wood Partitions
- Ceiled
- X Plaster Board Boo acoustical city
- Painted
- X Stain Rubbed Varnish
- Kalsomine
- Whitewashed
- Unfinished

INTERIOR TRIM

- X Fir
- Mah. Oak
- Metal
- wood Doors
- X Metal Windows
- Stained
- Varnished
- X Painted
- Unfinished

GAS STATIONS

- Frame
- Metal
- Masonry
- Plastered or Ceiled
- Floors

SERVICE BUILDING

- Frame
- Metal
- Masonry
- Plastered or Ceiled
- Floors

TANKS, ETC., LIST

1200 gal Stm + Ret glass over

Hoists: Elect. Hyd.

DOCKS AND PIERS


- Treated Piles and Timbers
- Untreated
- Treated Piles only
- Average Length
- Paved

C. H.

S. B.	
B	
1	14
2	
3	
4	
5	
6	
7	
8	
9	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	

GROUND FLOOR AREA 6096

TOTAL FLOOR AREA



	Other Buildings	Construction	Floor	Roof	Stories	Dimensions	S.F. Area	Factor	Value	% Dep.	Deprec.	Net Value
	Garage					x			$		$	$
						x			$		$	$
						x			$		$	$
						x			$		$	$

2M 4-46 53

FOLIO 2178 | ADDITION | Section | Twp | 0045

PERMIT No. 387843

DATE 5-18-48 | 2725-

Fee Owner Gibbs + Hu | Look for ...

Condition of Exterior A Interior | ...C | ...E SEALED | ...+ Billy's Kitchen

... No. Architect | Poor

POLAROID © L508161X

06540 / 0065 / F-2178 / 2/86

USE Stores

- 1 No. Stories
- 4 No. Stores
- No. Rooms
- Basement
- No. Offices
- No. Apartments
- 1 rm. ☐ 2 rm. ☐ 3 rm.
- 4 rm. ☐ 5 rm. ☐

ROOF CO...

- X Fra...
- Mill...
- Rei...
- No...
- Wo...

ROOFING MATERIAL

- X Tar...

TYPE OF CONSTRUCTI...

- Frame
- Single ☐ Dou...
- X Ordinary Masonry
- Mill Construction
- Class A Rein. Con.
- Stru. Steel and Con.
- 1X Tile ☐ Brick
- Con. BLK ☐ Rein.

Good X Med. Cheap.

FOUNDATION

- Mud Sills
- Post and Pier
- Brick
- X Concrete
- Pile

BASEMENT

- Full ☐ %
- Sub-Basement
- M Size x
- D Garage ☐ No. Cars
- Floors
- Plastered
- Living Rooms
- Service Rooms

Date Built 1948 ☐ Finished ☐ Unfinished ☐ Remodeled

Effective Age Years | Future Life Years

Dep. for Cond. | Dep. for Ob. | Dep. for Es. | Total 20



Other Buildings $

Total $

Assessed Value 50% $

Sup. Building A. V. $

Total $

PLUMBING

- 15 No. Fixtures
- 7 Toilets
- Tubs, Leg or Pem.
- 4 Basins, ~~Ped.~~
- Sinks
- Urinals
- Showers (Tub) (Stall)
- Laundry Trays
- H.W. Tank Fl. Drains ☐
- Sprink. Sys. No. Hds.

...ING

- Stove H545 GAS
- Pipeless Furnace 100%
- Gravity H. A.
- Air Cond., Fan 3RS
- Arcola Suspended
- 1-Pipe Steam
- 2-Pipe St. or Vapor
- Hot Water
- Oil Burner
- Coal Stoker

...NG

- Knobe & Tube
- Flex Cable 10100
- Conduit 4065
- Power Wiring
- Range Wiring
- No. Outlets

ELEVATORS

- Pass. ☐ Freight
- Auto. ☐ Elec.
- Man. ☐ Hyd.
- ☐ Man.

8800 X 49

EXTERIOR WALL CONSTR.

- Single ☐ Double
- 2" x 4" Stud Walls
- 2" x 6" Stud Walls
- Brick Walls
- Brick With Pilasters
- X Concrete Walls 100% 8" BLK
- X Con. With Pilasters
- Tile Walls
- Rein. Con. Skel.
- Filler Walls
- Laminated Walls

EXTERIOR FACING

- Siding ☐ Shingles REM
- Shakes ☒ Stucco 2
- Brick Veneer 168 x 1
- X ~~Conc. Tilt~~ 2 Kind BLOCK
- Stone ☐ Cast S.
- Terra Cotta
- X Struct. Glass 72 LF x 4
- Trim

FLOOR CONSTRUCTION

Joist Con. Size x

O. C. In Bridg. ☐

- Mill Construction
- X Rein. Con.

INTERIOR WALLS

- X Stud and Plaster
- Lam. ☐ Plastered
- Ply Wood Partitions
- Ceiled
- X Plaster Board 80% ONLY
- Painted
- X Stain Paint ☒ Varnish
- Kalsomine
- Whitewashed
- Unfinished

INTERIOR TRIM

- X Fir
- Mah. ☐ Oak
- Metal
- X Wood Doors
- X Metal Windows
- Stained
- Varnished
- X Painted
- Unfinished

GAS STATIONS

- Frame
- Metal
- Masonry
- Plastered or Ceiled
- Floors

SERVICE BUILDING

- Frame
- Metal
- Masonry
- Plastered or Ceiled
- Floors

TANKS, ETC., LIST

1200 gal ~~Stl~~ Steel

glass OVER

Hoists: Elect. Hyd.

DOCKS AND PIERS


- Treated Piles and Timbers
- Untreated
- Treated Piles only
- Average Length
- Paved

C. H.

S. B.	
B	
1	14
2	
3	
4	
5	
6	
7	
8	
9	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	

GROUND FLOOR AREA 6096

TOTAL FLOOR AREA



Other Buildings	Construction	Floor	Roof	Stories	Dimensions	S.F. Area	Factor	Value	% Dep.	Deprec.	Net Value
Garage					x			$		$	$
					x			$		$	$
					x			$		$	$
					x			$		$	$

2M 4-46 53

FOLIO 2178 | ADDITION | Section | Twp | 0065

PERMIT No. 387843

DATE 5-18-48 | 2725-

Fee Owner Gibbs + Hu

Condition of Exterior A Interior | No. Architect | Poor

USE Stores

1	No. Stories
4	No. Stores
	No. Rooms
	Basement
	No. Offices
	No. Apartments
	1 rm. 2 rm. 3 rm.
	4 rm. 5 rm.

TYPE OF CONSTRUCTI

	Frame
	Single Dou
X	Ordinary Masonry
	Mill Construction
	Class A Rein. Con.
	Stru. Steel and Con.
	Tile Brick
X	Con. Blk Rein.

Good X Med. Cheap

FOUNDATION

	Mud Sills
	Post and Pier
	Brick
X	Concrete
	Pile

BASEMENT

	Full %
	Sub-Basement
M	Size x
D	Garage No. Cars
	Floors
	Plastered
	Living Rooms
	Service Rooms

EXTERIOR WALL CONSTR.

	Single Double
	2" x 4" Stud Walls
	2" x 6" Stud Walls
	Brick Walls
	Brick With Pilasters
X	Concrete Walls 8" Blk
X	Con. With Pilasters
	Tile Walls
	Rein. Con. Skel.
	Filler Walls
	Laminated Walls

EXTERIOR FACING

	Siding Shingles
	Shakes Stucco 2
	Brick Veneer
X	Cone. Tile 2 Kind
	Stone Cast S.
	Terra Cotta
X	Struct. Glass 72 LF x 4
	Trim

FLOOR CONSTRUCTION

Joist Con. Size x

O. C. In Bridg

	Mill Construction
X	Rein. Con.

ROOF CO

X	Fra
	Mill
	Rei
	No.
	Wo

ROOFING MATERIAL

X	Tar

Date Built 1948 | Finished | Unfinished | Remodeled

Effective Age Years | Future Life Years

Dep. for Cond. | Dep. for Ob. | Dep. for Es. | Total 20

REPRODUCTION COST Factor Make-Up Type III Stone + Blk

Factor	Plus or Minus	Dimensions	S. F. Area	Factor	Cost
5.63		60 x 108	6096	.425	25908
-.34	Conc Bl				
.529		Cone	384	.25	96
.05	Tile				
.36	Eq				
.55	Plbg				
.26	Heat				
50 Lbs	Dust				
.09	T+G Roof				
760 x	60% = 455	Pch. x			
710 x	61% = .425	Pch. x			

Total	26004
Less Depreciation	5721
Total	20283
Other Buildings	
Total Value (Full)	
Assessed Valuation 50%	10100

10M 5-59

PLUMBING

15	No. Fixtures
7	Toilets
	Tubs, Leg or Pem.
	Basins, ~~Ped.~~
4	Sinks
	Urinals
	Showers (Tub) (Stall)
	Laundry Trays
	H.W. Tank Fl. Drains
	Sprink. Sys. No. Hds.

HEATING

	Stove HS45 GAS
	Pipeless Furnace 100%
	Gravity H. A.
	Air Cond., Fan GAS
	Arcola Suspended
	I-Pipe Steam
	2-Pipe St. or Vapor
	Hot Water
	Oil Burner
	Coal Stoker

WIRING

	Knobe & Tube
	Flex Cable 10100
	Conduit 40'65
	Power Wiring
	Range Wiring
	No. Outlets

ELEVATORS

	Pass.		Freight
	Auto.		Elec.
	Man.		Hyd.
			Man.

8800 lbs x 9

6096

INTERIOR TRIM

X	Fir
	Mah. Oak
	Metal
	Wood Doors
X	Metal Windows
	Stained
	Varnished
X	Painted
	Unfinished

	Plastered or Ceiled
	Floors

TANKS, ETC., LIST

1200 sq ft Alum + Plast glass over


Hoists: Elect. Hyd.

DOCKS AND PIERS

	Treated Piles and Timbers
	Untreated
	Treated Piles only
	Average Length
	Paved

	Other Buildings	Construction	Floor	Roof	Stories	Dimensions	S.F. Area	Factor	Value	% Dep.	Deprec.	Net Value
	Garage					x			$		$	$
						x			$		$	$
						x			$		$	$
						x			$		$	$

3M 1-46



FOLIO 2178

PERMIT No. 38743

DATE 5-18-48

Fee Owner Gibb

Condition of Exterior

USE Stores

1 No. Stories
4 No. Stores
No. Rooms
Basement
No. Offices
No. Apartments
1 rm. 2 rm. 3 rm.
4 rm. 5 rm. 6 rm.

TYPE OF CONSTRUCTION
Frame
Single Double
X Ordinary Masonry
Mill Construction
Class A Rein. Con.
Stru. Steel and Con.
Tile Brick
X Con. Blk Rein. Con.
Good X Med. Cheap

FOUNDATION
Mud Sills
Post and Pier
Brick
X Concrete
Pile

BASEMENT
Full %
Sub-Basement
M Size x
Garage No. Cars
D Floors
Plastered
Living Rooms
Service Rooms

EXTERIOR WALL CONSTR.
Single Double
2" x 4" Stud Walls
2" x 6" Stud Walls
Brick Walls
Brick With Pilasters
X Concrete Walls 8" Blk
X Con. With Pilasters
Tile Walls
Rein. Con. Skel.
Filler Walls
Laminated Walls

EXTERIOR FACING
Siding Shingles REM
Shakes X Stucco 2
Brick Veneer 168 x 1
X Conc. Tile 2 Kind Block
Stone Cast S.
Terra Cotta
X Struct. Glass 72 LF x 4
Trim

FLOOR CONSTRUCTION
Joist Con. Size x
O. C. In Bridg.
Mill Construction
X Rein. Con.

ROOFING MATERIAL
X Tar and Gravel Or.
X Tile Asphalt 3405 ft Or.
Lin. Ft. Dr. Bds.
Kit's. Fl. Walls

Date Built 1948 X Finished Unfinished Remodeled
Effective Age 22 Years Future Life Years
Dep. for Cond. Dep. for Ob. Dep. for Es. Total 20

REPRODUCTION COST Factor Make Up Opened Sept. 1948.

Factor	Plus or Minus	Dimensions	S. F. Area	Factor	Cost
		60 x 108	6480		
	—	16 x 24	384		
			6096	290	17678
6" Conc. on gd.		Pch. 16 x 24	384	20	77
		Pch. x			
		P. 25 000.	Total		17755
			Less Depreciation		
			Total		
			Other Buildings		
			Total Value (Full)		
			Assessed Valuation 50%		

Main Building

INTERIOR TRIM
X Fir
Mah. Oak
Metal
X Wood Doors
X Metal Windows
Stained
Varnished
X Painted
Unfinished

Plastered or Ceiled
Floors

TANKS, ETC., LIST
1200 sq ft Steam Plant Glass over
Hoists: Elect. Hyd.

DOCKS AND PIERS
Treated Piles and Timbers
Untreated
Treated Piles only
Average Length
Paved

HEATING
Stove
Pipeless Furnace
Gravity H. A.
X Air Cond., Fan
Arcola Suspended
1-Pipe Steam
2-Pipe St. or Vapor
Hot Water
Oil Burner
Coal Stoker


WIRING
Knobe & Tube
Flex Cable
X Conduit
Power Wiring
Range Wiring
No. Outlets

ELEVATORS
Pass. Freight
Auto. Elec.
Man. Hyd.
Man.

6096

PLUMBING
No. Fixtures
Toilets
Tubs, Leg or Pem.
Basins, ~~Ped.~~
Sinks
Urinals
Showers (Tub) (Stall)
Laundry Trays
4 H.W. Tank Fl. Drains
Sprink. Sys. No. Hds.

	Other Buildings	Construction	Floor	Roof	Stories	Dimensions	S.F. Area	Factor	Value	% Dep.	Deprec.	Net Value
	Garage					x						
						x						
						x						
						x						



Rent 42604 @ 9375 PM

CONSTRUCTION	SIZE	GRADE	AGE
5056 MTL STORE FRONT	1000 ft Ave Flr	Avg	

Center Stor ... ...ator, celotex.
1 Partition Pa ... ...or.
Left portion ... ...tion Lath & Pl.
Right "
Rear por m
Very good f ...
Rear Por ... has 12x20 ft ... glass
Partitions are Lath & Pl. on 2x6 - 5" steel col. 20'0"c.
with 18" I Beam over. Roof 2x14-16"oc.

E Gotland 5/49

1966 land - 9070
1965 " - 8570

1 vacancy. Rentals comparable for the area as there are a number of this type of bldg. Rents range from 200-250 This bldg should gross approx $800

Cindy Apparel
1/65
3

Rent 426



Center Store is Television set up. 1/2 # clg is accoustic, celotex.
1 Partition Plaster Bd. Hol. Veneer. Thin Por. are Tile floor.
Left portion 2 - 8' Veneer partitions -
Right " 1 - 8' " " " all Law Partitions Laid & Pl.
Rear per no Parts. except Law.
Very good Jamb Recessed Store & Plate glass.
Rear Por. printing has 12x20 # store & Plate glass
Partitions are Laid & Pl. on 2x6 - 5" steel col. 20' O.C.
with 18" I Beam over. Roof 2x14-16" OC.

Gertrude 5/49

1966 land - 9070
1965 " - 8570

1 vacancy. Rentals comparable for the area as there are a number of this type of bldg. Rents range from 200 - 250
This bldg should gross approx $800
Cindy Apanel
1/65
3

APPENDIX D
CURRENT TAXES

Department of Assessments

201 South Jackson Street, Room 708
Seattle, WA 98104

Office Hours: Mon - Fri 8:30 a.m. to 4:30 p.m.

TEL: 206-296-7300
FAX: 206-296-5107
TTY: 206-296-7888

Send us mail

ADVERTISEMENT

- New Search
- Property Tax Bill
- Map This Property
- Glossary of Terms
- Area Report
- Property Detail

PARCEL


Parcel Number	065400-0065
Name	MGM PROPERTIES LLC
Site Address	2729 2ND AVE 98121
Legal	BELL AND DENNYS 1ST ADD LESS POR FOR ST

BUILDING 1

Year Built	1948
Building Net Square Footage	6096
Construction Class	MASONRY
Building Quality	AVERAGE
Lot Size	12960
Present Use	Retail Store
Views	No
Waterfront	

TOTAL LEVY RATE DISTRIBUTION

Tax Year: 2022 **Levy Code:** 0011 **Total Levy Rate:** $8.82940 **Total Senior Rate:** $5.08826



59.50% Voter Approved

Click here to see levy distribution comparison by year.

TAX ROLL HISTORY

Valued Year	Tax Year	Appraised Land Value ($)	Appraised Imps Value ($)	Appraised Total ($)	Appraised Imps Increase ($)	Taxable Land Value ($)	Taxable Imps Value ($)	Taxable Total ($)
2022	2023	7,452,000	1,000	7,453,000	0	7,452,000	1,000	7,453,000
2021	2022	7,452,000	1,000	7,453,000	0	7,452,000	1,000	7,453,000
2020	2021	7,452,000	1,000	7,453,000	0	7,452,000	1,000	7,453,000
2019	2020	7,257,600	1,000	7,258,600	0	7,257,600	1,000	7,258,600
2018	2019	7,257,600	1,000	7,258,600	0	7,257,600	1,000	7,258,600
2017	2018	6,350,400	1,000	6,351,400	0	6,350,400	1,000	6,351,400
2016	2017	5,184,000	1,000	5,185,000	0	5,184,000	1,000	5,185,000
2015	2016	4,536,000	1,000	4,537,000	0	4,536,000	1,000	4,537,000
2014	2015	3,758,400	1,000	3,759,400	0	3,758,400	1,000	3,759,400
2013	2014	3,564,000	1,000	3,565,000	0	3,564,000	1,000	3,565,000
2012	2013	3,369,600	1,000	3,370,600	0	3,369,600	1,000	3,370,600
2011	2012	3,369,600	1,000	3,370,600	0	3,369,600	1,000	3,370,600
2010	2011	3,369,600	1,000	3,370,600	0	3,369,600	1,000	3,370,600
2009	2010	3,369,600	1,000	3,370,600	0	3,369,600	1,000	3,370,600
2008	2009	3,304,800	1,000	3,305,800	0	3,304,800	1,000	3,305,800
2007	2008	3,175,200	1,000	3,176,200	0	3,175,200	1,000	3,176,200
2006	2007	2,203,200	1,000	2,204,200	0	2,203,200	1,000	2,204,200
2005	2006	2,008,800	1,000	2,009,800	0	2,008,800	1,000	2,009,800
2004	2005	1,944,000	1,000	1,945,000	0	1,944,000	1,000	1,945,000
2003	2004	1,944,000	1,000	1,945,000	0	1,944,000	1,000	1,945,000

Reference Links:

- King County Taxing Districts Codes and Levies (.PDF)
- King County Tax Links
- Property Tax Advisor
- Washington State Department of Revenue (External link)
- Washington State Board of Tax Appeals (External link)
- Board of Appeals/Equalization
- Districts Report
- iMap
- Recorder's Office
- Scanned images of surveys and other map documents
- Scanned images of plats

ADVERTISEMENT

Notice mailing date: 06/02/2022

2002	2003	1,944,000	1,000	1,945,000	0	1,944,000	1,000	1,945,000
2001	2002	1,814,400	1,000	1,815,400	0	1,814,400	1,000	1,815,400
2000	2001	1,296,000	1,000	1,297,000	0	1,296,000	1,000	1,297,000
1999	2000	972,000	1,000	973,000	0	972,000	1,000	973,000
1998	1999	972,000	1,000	973,000	0	972,000	1,000	973,000
1997	1998	0	0	0	0	842,400	1,000	843,400
1996	1997	0	0	0	0	842,400	1,000	843,400
1994	1995	0	0	0	0	842,400	1,000	843,400
1992	1993	0	0	0	0	648,000	1,000	649,000
1990	1991	0	0	0	0	583,200	1,000	584,200
1988	1989	0	0	0	0	427,700	46,800	474,500
1987	1988	0	0	0	0	427,700	46,800	474,500
1986	1987	0	0	0	0	427,700	46,800	474,500
1984	1985	0	0	0	0	291,600	106,000	397,600
1982	1983	0	0	0	0	291,600	106,000	397,600

ADVERTISEMENT

Updated: July 25, 2022

Share Tweet Email

© King County, WA 2022 Privacy Accessibility Terms of use

Information for... **Do more online**
Get help

Department of Assessments

201 South Jackson Street, Room 708
Seattle, WA 98104

Office Hours: Mon - Fri 8:30 a.m. to 4:30 p.m.

TEL: 206-296-7300
FAX: 206-296-5107
TTY: 206-296-7888

Send us mail

ADVERTISEMENT

- New Search
- Property Tax Bill
- Map This Property
- Glossary of Terms
- Area Report
- Print Property Detail

PARCEL DATA

Parcel	065400-0065	**Jurisdiction**	SEATTLE
Name	MGM PROPERTIES LLC	**Levy Code**	0011
Site Address	2729 2ND AVE 98121	**Property Type**	C
Geo Area	30-90	**Plat Block / Building Number**	19
Spec Area		**Plat Lot / Unit Number**	5-6
Property Name	LIGHTING SUPPLY	**Quarter-Section-Township-Range**	NW-31-25-4

Legal Description
BELL AND DENNYS 1ST ADD LESS POR FOR ST
PLat Block: 19
Plat Lot: 5-6

LAND DATA

Highest & Best Use As If Vacant	COMMERCIAL SERVICE	**Percentage Unusable**	
Highest & Best Use As Improved	PRESENT USE	**Restrictive Size Shape**	NO
Present Use	Retail Store	**Zoning**	DMR/C 145/75
Land SqFt	12,960	**Water**	WATER DISTRICT
Acres	0.30	**Sewer/Septic**	PUBLIC
		Road Access	PUBLIC
		Parking	ADEQUATE
		Street Surface	PAVED

Views

Rainier	
Territorial	
Olympics	
Cascades	
Seattle Skyline	
Puget Sound	
Lake Washington	
Lake Sammamish	
Lake/River/Creek	
Other View	

Waterfront

Waterfront Location	
Waterfront Footage	0
Lot Depth Factor	0
Waterfront Bank	
Tide/Shore	
Waterfront Restricted Access	
Waterfront Access Rights	NO
Poor Quality	NO
Proximity Influence	NO

Designations

Historic Site	
Current Use	(none)
Nbr Bldg Sites	
Adjacent to Golf Fairway	NO
Adjacent to Greenbelt	NO
Other Designation	NO
Deed Restrictions	NO
Development Rights Purchased	NO
Easements	NO
Native Growth Protection Easement	NO
DNR Lease	NO

Nuisances

Topography	
Traffic Noise	
Airport Noise	
Power Lines	NO
Other Nuisances	NO

Problems

Water Problems	NO
Transportation Concurrency	NO
Other Problems	NO

Environmental

Environmental	NO

BUILDING

Building Number	1
Building Description	RETAIL
Number Of Buildings Aggregated	1
Predominant Use	RETAIL STORE (353)
Shape	Rect or Slight Irreg
Construction Class	MASONRY
Building Quality	AVERAGE
Stories	1
Building Gross Sq Ft	6,096
Building Net Sq Ft	6,096
Year Built	1948
Eff. Year	1985

Picture of Building 1

Reference Links:

- King County Tax Links
- Property Tax Advisor
- Washington State Department of Revenue (External link)
- Washington State Board of Tax Appeals (External link)
- Board of Appeals/Equalization
- Districts Report
- iMap
- Recorder's Office

Scanned images of surveys and other map documents

Scanned images of plats

Notice mailing date: 06/02/2022

ADVERTISEMENT

Percentage Complete	100
Heating System	SPACE HEATERS
Sprinklers	No
Elevators	

Section(s) Of Building Number: 1

Section Number	Section Use	Description	Stories	Height	Floor Number	Gross Sq Ft	Net Sq Ft
1	RETAIL STORE (353)		1	14		6,096	6,096

TAX ROLL HISTORY

Account	Valued Year	Tax Year	Omit Year	Levy Code	Appraised Land Value ($)	Appraised Imps Value ($)	Appraised Total Value ($)	New Dollars ($)	Taxable Land Value ($)	Taxable Imps Value ($)	Taxable Total Value ($)	Tax Value Reason
065400006501	2022	2023		0011	7,452,000	1,000	7,453,000	0	7,452,000	1,000	7,453,000	
065400006501	2021	2022		0011	7,452,000	1,000	7,453,000	0	7,452,000	1,000	7,453,000	
065400006501	2020	2021		0011	7,452,000	1,000	7,453,000	0	7,452,000	1,000	7,453,000	
065400006501	2019	2020		0011	7,257,600	1,000	7,258,600	0	7,257,600	1,000	7,258,600	
065400006501	2018	2019		0011	7,257,600	1,000	7,258,600	0	7,257,600	1,000	7,258,600	
065400006501	2017	2018		0011	6,350,400	1,000	6,351,400	0	6,350,400	1,000	6,351,400	
065400006501	2016	2017		0012	5,184,000	1,000	5,185,000	0	5,184,000	1,000	5,185,000	
065400006501	2015	2016		0012	4,536,000	1,000	4,537,000	0	4,536,000	1,000	4,537,000	
065400006501	2014	2015		0010	3,758,400	1,000	3,759,400	0	3,758,400	1,000	3,759,400	
065400006501	2013	2014		0010	3,564,000	1,000	3,565,000	0	3,564,000	1,000	3,565,000	
065400006501	2012	2013		0010	3,369,600	1,000	3,370,600	0	3,369,600	1,000	3,370,600	
065400006501	2011	2012		0010	3,369,600	1,000	3,370,600	0	3,369,600	1,000	3,370,600	
065400006501	2010	2011		0010	3,369,600	1,000	3,370,600	0	3,369,600	1,000	3,370,600	
065400006501	2009	2010		0010	3,369,600	1,000	3,370,600	0	3,369,600	1,000	3,370,600	
065400006501	2008	2009		0010	3,304,800	1,000	3,305,800	0	3,304,800	1,000	3,305,800	
065400006501	2007	2008		0010	3,175,200	1,000	3,176,200	0	3,175,200	1,000	3,176,200	
065400006501	2006	2007		0010	2,203,200	1,000	2,204,200	0	2,203,200	1,000	2,204,200	
065400006501	2005	2006		0010	2,008,800	1,000	2,009,800	0	2,008,800	1,000	2,009,800	
065400006501	2004	2005		0010	1,944,000	1,000	1,945,000	0	1,944,000	1,000	1,945,000	
065400006501	2003	2004		0010	1,944,000	1,000	1,945,000	0	1,944,000	1,000	1,945,000	
065400006501	2002	2003		0010	1,944,000	1,000	1,945,000	0	1,944,000	1,000	1,945,000	
065400006501	2001	2002		0010	1,814,400	1,000	1,815,400	0	1,814,400	1,000	1,815,400	
065400006501	2000	2001		0010	1,296,000	1,000	1,297,000	0	1,296,000	1,000	1,297,000	
065400006501	1999	2000		0010	972,000	1,000	973,000	0	972,000	1,000	973,000	
065400006501	1998	1999		0010	972,000	1,000	973,000	0	972,000	1,000	973,000	
065400006501	1997	1998		0010	0	0	0	0	842,400	1,000	843,400	
065400006501	1996	1997		0010	0	0	0	0	842,400	1,000	843,400	
065400006501	1994	1995		0010	0	0	0	0	842,400	1,000	843,400	
065400006501	1992	1993		0010	0	0	0	0	648,000	1,000	649,000	
065400006501	1990	1991		0010	0	0	0	0	583,200	1,000	584,200	
065400006501	1988	1989		0010	0	0	0	0	427,700	46,800	474,500	
065400006501	1987	1988		0010	0	0	0	0	427,700	46,800	474,500	
065400006501	1986	1987		0010	0	0	0	0	427,700	46,800	474,500	
065400006501	1984	1985		0010	0	0	0	0	291,600	106,000	397,600	
065400006501	1982	1983		0010	0	0	0	0	291,600	106,000	397,600	

SALES HISTORY

Excise Number	Recording Number	Document Date	Sale Price	Seller Name	Buyer Name	Instrument	Sale Reason
1557618	199707290773	7/23/1997	$0.00	MUNDAY MARK ET AL	MGM PROPERTIES LLC	Quit Claim Deed	Other
1477421	199604010637	3/24/1996	$486,000.00	CLINE DONALD G+DONA J	MUNDAY MARK	Statutory Warranty Deed	None

REVIEW HISTORY

PERMIT HISTORY

HOME IMPROVEMENT EXEMPTION

- New Search
- Property Tax Bill
- Map This Property
- Glossary of Terms
- Area Report
- Print Property Detail

ADVERTISEMENT

Updated: July 25, 2022

Share Tweet Email

Information for...

Residents
Businesses
Job seekers
Volunteers
King County employees

Do more online

Trip Planner
Property tax information & payment
Jail inmate look up
Parcel viewer or iMap
Public records
More online tools...

Get help

Contact us
Customer service
Phone list
Employee directory
Subscribe to alerts

King County

© King County, WA 2022 Privacy Accessibility Terms of use

Information for... **Do more online**
Get help

APPENDIX E
TITLE DOCUMENTS

ALTA COMMITMENT FOR TITLE INSURANCE (07-01-2021)

ISSUED BY
STEWART TITLE GUARANTY COMPANY

NOTICE

IMPORTANT - READ CAREFULLY: THIS COMMITMENT IS AN OFFER TO ISSUE ONE OR MORE TITLE INSURANCE POLICIES. ALL CLAIMS OR REMEDIES SOUGHT AGAINST THE COMPANY INVOLVING THE CONTENT OF THIS COMMITMENT OR THE POLICY MUST BE BASED SOLELY IN CONTRACT.

THIS COMMITMENT IS NOT AN ABSTRACT OF TITLE, REPORT OF THE CONDITION OF TITLE, LEGAL OPINION, OPINION OF TITLE, OR OTHER REPRESENTATION OF THE STATUS OF TITLE. THE PROCEDURES USED BY THE COMPANY TO DETERMINE INSURABILITY OF THE TITLE, INCLUDING ANY SEARCH AND EXAMINATION, ARE PROPRIETARY TO THE COMPANY, WERE PERFORMED SOLELY FOR THE BENEFIT OF THE COMPANY, AND CREATE NO EXTRACONTRACTUAL LIABILITY TO ANY PERSON, INCLUDING A PROPOSED INSURED.

THE COMPANY'S OBLIGATION UNDER THIS COMMITMENT IS TO ISSUE A POLICY TO A PROPOSED INSURED IDENTIFIED IN SCHEDULE A IN ACCORDANCE WITH THE TERMS AND PROVISIONS OF THIS COMMITMENT. THE COMPANY HAS NO LIABILITY OR OBLIGATION INVOLVING THE CONTENT OF THIS COMMITMENT TO ANY OTHER PERSON.

COMMITMENT TO ISSUE POLICY

Subject to the Notice; Schedule B, Part I - Requirements; Schedule B, Part II - Exceptions; and the Commitment Conditions, STEWART TITLE GUARANTY COMPANY, a Texas corporation (the "Company"), commits to issue the Policy according to the terms and provisions of this Commitment. This Commitment is effective as of the Commitment Date shown in Schedule A for each Policy described in Schedule A, only when the Company has entered in Schedule A both the specified dollar amount as the Proposed Amount of Insurance and the name of the Proposed Insured.

If all of the Schedule B, Part I - Requirements have not been met within six months after the Commitment Date, this Commitment terminates and the Company's liability and obligation end.

Countersigned by:

Authorized Countersignature

Stewart Title Guaranty Company
1420 Fifth Avenue, Suite 440
Seattle, WA 98101
(888) 896-1443

STEWART TITLE GUARANTY COMPANY INCORPORATED 1908 TEXAS

Frederick H. Eppinger
President and CEO

David Hisey
Secretary

This page is only a part of a 2021 ALTA® Commitment for Title Insurance. This Commitment is not valid without the Notice; the Commitment to Issue Policy; the Commitment Conditions; Schedule A; Schedule B, Part I - Requirements; and Schedule B, Part II - Exceptions; and a countersignature by the Company or its issuing agent that may be in electronic form.

Copyright 2021 American Land Title Association. All rights reserved.
The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use.
All other uses are prohibited. Reprinted under license from the American Land Title Association.

COMMITMENT CONDITIONS

1. DEFINITIONS

a. "Discriminatory Covenant": Any covenant, condition, restriction, or limitation that is unenforceable under applicable law because it illegally discriminates against a class of individuals based on personal characteristics such as race, color, religion, sex, sexual orientation, gender identity, familial status, disability, national origin, or other legally protected class.

b. "Knowledge" or "Known": Actual knowledge or actual notice, but not constructive notice imparted by the Public Records.

c. "Land": The land described in Item 5 of Schedule A and improvements located on that land that by State law constitute real property. The term "Land" does not include any property beyond that described in Schedule A, nor any right, title, interest, estate, or easement in any abutting street, road, avenue, alley, lane, right-of-way, body of water, or waterway, but does not modify or limit the extent that a right of access to and from the Land is to be insured by the Policy.

d. "Mortgage": A mortgage, deed of trust, trust deed, security deed, or other real property security instrument, including one evidenced by electronic means authorized by law.

e. "Policy": Each contract of title insurance, in a form adopted by the American Land Title Association, issued or to be issued by the Company pursuant to this Commitment.

f. "Proposed Amount of Insurance": Each dollar amount specified in Schedule A as the Proposed Amount of Insurance of each Policy to be issued pursuant to this Commitment.

g. "Proposed Insured": Each person identified in Schedule A as the Proposed Insured of each Policy to be issued pursuant to this Commitment.

h. "Public Records": The recording or filing system established under State statutes in effect at the Commitment Date under which a document must be recorded or filed to impart constructive notice of matters relating to the Title to a purchaser for value without Knowledge. The term "Public Records" does not include any other recording or filing system, including any pertaining to environmental remediation or protection, planning, permitting, zoning, licensing, building, health, public safety, or national security matters.

i. "State": The state or commonwealth of the United States within whose exterior boundaries the Land is located. The term "State" also includes the District of Columbia, the Commonwealth of Puerto Rico, the U.S. Virgin Islands, and Guam.

j. "Title": The estate or interest in the Land identified in Item 3 of Schedule A.

2. If all of the Schedule B, Part I - Requirements have not been met within the time period specified in the Commitment to Issue Policy, this Commitment terminates and the Company's liability and obligation end.

3. The Company's liability and obligation is limited by and this Commitment is not valid without:

a. the Notice;
b. the Commitment to Issue Policy;
c. the Commitment Conditions;
d. Schedule A;
e. Schedule B, Part I - Requirements;
f. Schedule B, Part II - Exceptions; and
g. a countersignature by the Company or its issuing agent that may be in electronic form.

4. COMPANY'S RIGHT TO AMEND

The Company may amend this Commitment at any time. If the Company amends this Commitment to add a defect, lien, encumbrance, adverse claim, or other matter recorded in the Public Records prior to the Commitment Date, any liability of the Company is limited by Commitment Condition 5. The Company is not liable for any other amendment to this Commitment.

Copyright 2021 American Land Title Association. All rights reserved.
The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use.
All other uses are prohibited. Reprinted under license from the American Land Title Association.

5. LIMITATIONS OF LIABILITY

a. The Company's liability under Commitment Condition 4 is limited to the Proposed Insured's actual expense incurred in the interval between the Company's delivery to the Proposed Insured of the Commitment and the delivery of the amended Commitment, resulting from the Proposed Insured's good faith reliance to:
   i. comply with the Schedule B, Part I - Requirements;
   ii. eliminate, with the Company's written consent, any Schedule B, Part II - Exceptions; or
   iii. acquire the Title or create the Mortgage covered by this Commitment.

b. The Company is not liable under Commitment Condition 5.a. if the Proposed Insured requested the amendment or had Knowledge of the matter and did not notify the Company about it in writing.

c. The Company is only liable under Commitment Condition 4 if the Proposed Insured would not have incurred the expense had the Commitment included the added matter when the Commitment was first delivered to the Proposed Insured.

d. The Company's liability does not exceed the lesser of the Proposed Insured's actual expense incurred in good faith and described in Commitment Condition 5.a. or the Proposed Amount of Insurance.

e. The Company is not liable for the content of the Transaction Identification Data, if any.

f. The Company is not obligated to issue the Policy referred to in this Commitment unless all of the Schedule B, Part I—Requirements have been met to the satisfaction of the Company.

g. The Company's liability is further limited by the terms and provisions of the Policy to be issued to the Proposed Insured.

6. LIABILITY OF THE COMPANY MUST BE BASED ON THIS COMMITMENT; CHOICE OF LAW AND CHOICE OF FORUM

a. Only a Proposed Insured identified in Schedule A, and no other person, may make a claim under this Commitment.

b. Any claim must be based in contract under the State law of the State where the Land is located and is restricted to the terms and provisions of this Commitment. Any litigation or other proceeding brought by the Proposed Insured against the Company must be filed only in a State or federal court having jurisdiction.

c. This Commitment, as last revised, is the exclusive and entire agreement between the parties with respect to the subject matter of this Commitment and supersedes all prior commitment negotiations, representations, and proposals of any kind, whether written or oral, express or implied, relating to the subject matter of this Commitment.

d. The deletion or modification of any Schedule B, Part II—Exception does not constitute an agreement or obligation to provide coverage beyond the terms and provisions of this Commitment or the Policy.

e. Any amendment or endorsement to this Commitment must be in writing and authenticated by a person authorized by the Company.

f. When the Policy is issued, all liability and obligation under this Commitment will end and the Company's only liability will be under the Policy.

7. IF THIS COMMITMENT IS ISSUED BY AN ISSUING AGENT

The issuing agent is the Company's agent only for the limited purpose of issuing title insurance commitments and policies. The issuing agent is not the Company's agent for closing, settlement, escrow, or any other purpose.

8. PRO-FORMA POLICY

The Company may provide, at the request of a Proposed Insured, a pro-forma policy illustrating the coverage that the Company may provide. A pro-forma policy neither reflects the status of Title at the time that the pro-forma policy is delivered to a Proposed Insured, nor is it a commitment to insure.

9. CLAIMS PROCEDURES

This Commitment incorporates by reference all Conditions for making a claim in the Policy to be issued to the Proposed Insured. Commitment Condition 9 does not modify the limitations of liability in Commitment Conditions 5 and 6.

Copyright 2021 American Land Title Association. All rights reserved.
The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use.
All other uses are prohibited. Reprinted under license from the American Land Title Association.

10. CLASS ACTION

ALL CLAIMS AND DISPUTES ARISING OUT OF OR RELATING TO THIS COMMITMENT, INCLUDING ANY SERVICE OR OTHER MATTER IN CONNECTION WITH ISSUING THIS COMMITMENT, ANY BREACH OF A COMMITMENT PROVISION, OR ANY OTHER CLAIM OR DISPUTE ARISING OUT OF OR RELATING TO THE TRANSACTION GIVING RISE TO THIS COMMITMENT, MUST BE BROUGHT IN AN INDIVIDUAL CAPACITY. NO PARTY MAY SERVE AS PLAINTIFF, CLASS MEMBER, OR PARTICIPANT IN ANY CLASS OR REPRESENTATIVE PROCEEDING. ANY POLICY ISSUED PURSUANT TO THIS COMMITMENT WILL CONTAIN A CLASS ACTION CONDITION.

11. ARBITRATION (INTENTIONALLY DELETED)

STEWART TITLE GUARANTY COMPANY

All notices required to be given the Company and any statement in writing required to be furnished the Company shall be addressed to it at Stewart Title Guaranty Company, P.O. Box 2029, Houston, Texas 77252-2029.

Copyright 2021 American Land Title Association. All rights reserved.
The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use.
All other uses are prohibited. Reprinted under license from the American Land Title Association.

ALTA COMMITMENT FOR TITLE INSURANCE (07-01-2021)
SCHEDULE A

ISSUED BY
STEWART TITLE GUARANTY COMPANY

Transaction Identification Data, for which the Company assumes no liability as set forth in Commitment Condition 5.e.:

Issuing Agent: Stewart Title Guaranty Company
Issuing Office: 1420 Fifth Avenue, Suite 440, Seattle, WA 98101
Issuing Office's ALTA® Registry ID: N/A
Loan ID Number:
Commitment Number: 22000200779
Issuing Office File Number: 22000200779
Property Address: 2729 2nd Ave., Seattle, WA 98121
Revision Number:

Title Officer: Paul Ostrom
Phone: (206) 770-8876
seattlecstitleofficers@stewart.com

Escrow Officer: Chelsey Parra
Phone: (206) 770-8880
Email: chelsey.parra@stewart.com

Title Officer: Debbi Hodgson
Phone: (360) 713-9260
seattlecstitleofficers@stewart.com

1. **Commitment Date:** August 31, 2022 at 8:00 A.M.

2. **Policy to be issued:** **Proposed Amount of Insurance**

(a) 2021 ALTA® Owner's Policy - Extended Short Term Rate $10,000,000.00
Premium: $12,700.00
Tax: $1,301.75
Total: $14,001.75

Proposed Insured: Cavatina Group SA

Extended Portion of Premium **Charge:** $3,810.00 **Tax:** $390.53 **Total:** $4,200.53

(b) 2021 ALTA® Loan Policy

Proposed Insured:

3. **The estate or interest in the Land at the Commitment Date is:**

Fee Simple

4. **The Title is, at the Commitment Date, vested in:**

MGM Properties, L.L.C., a Washington limited liability company

5. **The Land is described as follows:**

FOR LEGAL DESCRIPTION SEE EXHIBIT "A" ATTACHED HERETO

This page is only a part of a 2021 ALTA® Commitment for Title Insurance. This Commitment is not valid without the Notice; the Commitment to Issue Policy; the Commitment Conditions; Schedule A; Schedule B, Part I - Requirements; and Schedule B, Part II - Exceptions; and a countersignature by the Company or its issuing agent that may be in electronic form.

Copyright 2021 American Land Title Association. All rights reserved.
The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association.

ALTA COMMITMENT FOR TITLE INSURANCE (07-01-2021)
SCHEDULE A

ISSUED BY
STEWART TITLE GUARANTY COMPANY

STEWART TITLE GUARANTY COMPANY


Authorized Countersignature

This page is only a part of a 2021 ALTA® Commitment for Title Insurance. This Commitment is not valid without the Notice; the Commitment to Issue Policy; the Commitment Conditions; Schedule A; Schedule B, Part I - Requirements; and Schedule B, Part II - Exceptions; and a countersignature by the Company or its issuing agent that may be in electronic form.

Copyright 2021 American Land Title Association. All rights reserved.
The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use.
All other uses are prohibited. Reprinted under license from the American Land Title Association.

ALTA COMMITMENT FOR TITLE INSURANCE (07-01-2021)
SCHEDULE A

ISSUED BY
STEWART TITLE GUARANTY COMPANY

EXHIBIT "A"

Legal Description:

Lots 5 and 6, Block 19, First Addition to that part of Seattle laid off by WM. N. Bell and A. A. Denny (commonly known as Bell and Denny's First Addition to the City of Seattle), according to the plat thereof recorded in Volume 1 of Plats, page 61, in King County Washington;

Except the Northeast 12 feet as condemned by the City of Seattle for widening of 2nd Avenue as provided for by Ordinance No. 1107.

Situate in the City of Seattle, County of King, State of Washington.

MAP

Abbreviated Legal: Ptn Lts 5 & 6, Blk 19, Bell and Denny's 1st Add. to Seattle

Parcel No(s): 065400-0065-01

Purported Address: 2729 2nd Ave., Seattle, WA 98121

Copyright 2021 American Land Title Association. All rights reserved.
The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use.
All other uses are prohibited. Reprinted under license from the American Land Title Association.

ALTA COMMITMENT FOR TITLE INSURANCE (07-01-2021)
SCHEDULE B PART I

ISSUED BY
STEWART TITLE GUARANTY COMPANY

Requirements

File No.: 22000200779

All of the following Requirements must be met:

1. The Proposed Insured must notify the Company in writing of the name of any party not referred to in this Commitment who will obtain an interest in the Land or who will make a loan on the Land. The Company may then make additional Requirements or Exceptions.

2. Pay the agreed amount for the estate or interest to be insured.

3. Pay the premiums, fees, and charges for the Policy to the Company.

4. Documents satisfactory to the Company that convey the Title or create the Mortgage to be insured, or both, must be properly authorized, executed, delivered, and recorded in the Public Records.

Note: Effective January 1, 1997, and pursuant to amendment of Washington state statutes relating to standardization of recorded documents, the following format and content requirements must be met. Failure to comply may result in rejection of the document by the recorder.

Format:
Margins to be 3" on top of first page, 1" on sides and bottom, 1" on top, sides and bottom of each succeeding page.
Font size of 8 points or larger and paper size of no more than 8 ½" by 14".

No attachments on pages such as stapled or taped notary seals, pressure seals must be smudged.

Information which must appear on the first page:
Title or titles of document. If assignment or reconveyance reference to auditor's file number of subject deed of trust.

Names of grantor(s) and grantee(s) with reference to additional names on following page(s), if any.
Abbreviated legal description (lot, block, plat name or section, township, range and quarter section for unplatted).

Assessor's tax parcel number(s)

Return address which may appear in the upper left hand 3" top margin

Copyright 2021 American Land Title Association. All rights reserved.
The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use.
All other uses are prohibited. Reprinted under license from the American Land Title Association.

ALTA COMMITMENT FOR TITLE INSURANCE (07-01-2021)
SCHEDULE B PART II

ISSUED BY
STEWART TITLE GUARANTY COMPANY

Exceptions

File No.: 22000200779

Some historical land records contain Discriminatory Covenants that are illegal and unenforceable by law. This Commitment and the Policy treat any Discriminatory Covenant in a document referenced in Schedule B as if each Discriminatory Covenant is redacted, repudiated, removed, and not republished or recirculated. Only the remaining provisions of the document will be excepted from coverage.

The Policy will not insure against loss or damage resulting from the terms and conditions of any lease or easement identified in Schedule A, and will include the following Exceptions unless cleared to the satisfaction of the Company:

1. Any defect, lien, encumbrance, adverse claim, or other matter that appears for the first time in the Public Records or is created, attaches, or is disclosed between the Commitment Date and the date on which all of the Schedule B, Part I - Requirements are met.

2. Rights or claims of parties in possession, or claiming possession, not shown by the Public Records.

3. Any encroachment, encumbrance, violation, variation, adverse circumstance, discrepancies, conflicts in boundary lines or shortages in area affecting the Title that would be disclosed by an accurate and complete and current survey of the Land.

4. Easements, prescriptive rights, rights-of-way, liens or encumbrances, or claims thereof, not shown by the Public Records.

5. Any lien, or right to a lien, for contributions to employee benefit funds, or for state workers' compensation, or for services, labor, or material heretofore or hereafter furnished, all as imposed by law, and not shown by the Public Records.

6. Taxes or special assessments which are not yet payable or which are not shown as existing liens by the Public Records.

7. Any lien for service, installation, connection, maintenance, tap, capacity, or construction or similar charges for sewer, water electricity, natural gas or other utilities, or for garbage collection and disposal not shown by the Public Records.

8. Unpatented mining claims, and all rights relating thereto.

9. Reservations and exceptions in United States Patents or in Acts authorizing the issuance thereof.

10. Indian tribal codes or regulations, Indian treaty or aboriginal rights, including easements or equitable servitudes.

11. Water rights, claims or title to water.

Copyright 2021 American Land Title Association. All rights reserved.
The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use.
All other uses are prohibited. Reprinted under license from the American Land Title Association.

Exceptions

12. Payment of Real Estate Excise tax, if required:

    The property described herein is situated within the boundaries of local taxing authority of the City of Seattle

    Present levy code is 0011. See Notes section below for formula for amount(s) due, and/or contact your Escrow Officer, or Title Officer.

13. General taxes: First half delinquent May 1; Second half delinquent November 1:

Year:	2022
Amount Billed:	$68,127.64
Amount Paid:	$34,063.82
Amount Due:	$34,063.82, plus interest and penalty if delinquent
Tax Account No.:	065400-0065-01
Levy Code:	0011
Land:	$7,452,000.00
Improvements:	$1,000.00

    Note: King County Treasurer, 500 4th Avenue, 6th Floor Admin. Bldg., Seattle, WA 98104 (206) 263-2890
    Web Address: https://kingcounty.gov/depts/finance-business-operations/treasury.aspx

14. Current and/or advance personal property taxes that may become due upon transfer or sale of the premises herein described. Please contact the King County Treasurer's office for further information.

15. Liability for sewer treatment capacity charges that may be assessed but not disclosed in the public records. Please contact the King County Capacity Charge Department for further information at 206-296-1450.

16. Deed of Trust and the terms and conditions thereof:

Grantor:	MGM Properties, L.L.C., a Washington limited liability company
Trustee:	UPF Washington, Incorporated
Beneficiary:	Banner Bank
Amount:	$1,725,000.00, plus future advances, if any
Dated:	June 28, 2019
Recorded:	July 9, 2019
Recording No.:	20190709001245

    The amount now secured by said Deed of Trust and the terms upon which the same can be discharged or assumed should be ascertained from the holder of the indebtedness secured.

Copyright 2021 American Land Title Association. All rights reserved.
The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use.
All other uses are prohibited. Reprinted under license from the American Land Title Association.

Exceptions

17. Deed of Trust and the terms and conditions thereof:

Grantor:	MGM Properties, L.L.C., a Washington limited liability company
Trustee:	UPF Washington, Incorporated
Beneficiary:	Banner Bank
Amount:	$600,000.00, plus future advances, if any
Dated:	March 8, 2022
Recorded:	March 15, 2022
Recording No.:	20220315001222

The amount now secured by said Deed of Trust and the terms upon which the same can be discharged or assumed should be ascertained from the holder of the indebtedness secured.

18. Any unrecorded leaseholds, right of vendors and holders of security interest on personal property installed upon said property, and right of tenants to remove trade fixtures at the expiration of the term.

    Copies of all unrecorded commercial leases and amendments should be submitted prior to closing.

19. Matters of extended owner's coverage which are dependent upon an inspection and an ALTA/NSPS SURVEY of the property for determination of insurability.

    Please submit a copy of the ALTA/NSPS survey at your earliest convenience for review. Your inspection will be held pending our review of the ALTA/NSPS survey and the results of said inspection will be furnished by supplemental report.

20. We find no corporation, limited liability company, limited partnership or other entity under the name Cavatina Group SA on the list of active corporations/entities in the office of the Secretary of State for the State of Washington. It may not be a legal entity capable of acquiring an interest in real property. We must be furnished with the classification/type of said entity and state of origin/incorporation.

    Evidence of the identity and authority of the officers of Cavatina Group SA to execute any forthcoming instrument must be submitted prior to closing.

21. Evidence of the authority of the individual(s) to execute the forthcoming document(s) for MGM Properties, L.L.C., a Washington limited liability company, and copies of the current operating agreement and any amendments thereto, should be submitted prior to closing.

22. The attached Commercial Title Affidavit must be completed in full, notarized, and submitted to the Company for review prior to closing.

Copyright 2021 American Land Title Association. All rights reserved.
The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use.
All other uses are prohibited. Reprinted under license from the American Land Title Association.

ALTA COMMITMENT FOR TITLE INSURANCE (07-01-2021)
SCHEDULE B PART II

ISSUED BY
STEWART TITLE GUARANTY COMPANY

Exceptions

NOTES

A. The legal description contained herein has been derived from information submitted with the application and as available from the record title. Said description should be carefully reviewed to assure it meets the intentions of the parties to this transaction.

B. Any maps, plats or surveys attached to this commitment are provided solely for informational purposes and to assist in locating the property with reference to streets and other parcels. While it is believed to be correct, Stewart Title Guaranty Company assumes no liability for any loss occurring by reason of reliance thereon.

C. This office conforms to the Federal Privacy Laws. Please see attached Privacy Policy Notice.

D. Recording fees charged by the county will be billed as follows: Deeds of Trust $204.50 for the first page and $1.00 for each additional page. Deeds $203.50 for the first page and $1.00 for each additional page. For electronic recorded documents, please add $2.75 plus tax for King, Pierce, Snohomish and Thurston Counties and $5.00 plus tax for all remaining counties in Washington.

E. In the event of cancellation, a cancellation charge may be made.

F. There are no deeds affecting said land recorded within 24 months of the date of this report.

G. **Beginning January 1, 2023, the state will switch to a graduated tax scale based on the selling price of the property (RCW 82.45.060<https://app.leg.wa.gov/RCW/default.aspx?cite=82.45.060>):**

1.1% (plus local .25 or .50) on that portion of the sale price of $525,000 and less;
1.28% (plus local .25 or .50) on that portion of the sale price Greater than $525,000 and less than or equal to $1,525,000;
2.75% (plus local .25 or .50) on that portion of the sale price Greater than $1,525,000 and less than or equal to $3,025,000; and
3.0% (plus local .25 or .50) on that portion of the sale price Greater than $3,025,000.

H. We find no pertinent matters filed or recorded against Cavatina Group SA, proposed insured purchasers.

tc

Copyright 2021 American Land Title Association. All rights reserved.
The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use.
All other uses are prohibited. Reprinted under license from the American Land Title Association.

STG Privacy Notice
Stewart Title Companies

WHAT DO THE STEWART TITLE COMPANIES DO WITH YOUR PERSONAL INFORMATION?

Federal and applicable state law and regulations give consumers the right to limit some but not all sharing. Federal and applicable state law regulations also require us to tell you how we collect, share, and protect your personal information. Please read this notice carefully to understand how we use your personal information. This privacy notice is distributed on behalf of the Stewart Title Guaranty Company and its title affiliates (the Stewart Title Companies), pursuant to Title V of the Gramm-Leach-Bliley Act (GLBA).

The types of personal information we collect and share depend on the product or service that you have sought through us. This information can include social security numbers and driver's license number.

All financial companies, such as the Stewart Title Companies, need to share customers' personal information to run their everyday business—to process transactions and maintain customer accounts. In the section below, we list the reasons that we can share customers' personal information; the reasons that we choose to share; and whether you can limit this sharing.

Reasons we can share your personal information.	Do we share	Can you limit this sharing?
For our everyday business purposes— to process your transactions and maintain your account. This may include running the business and managing customer accounts, such as processing transactions, mailing, and auditing services, and responding to court orders and legal investigations.	Yes	No
For our marketing purposes— to offer our products and services to you.	Yes	No
For joint marketing with other financial companies	No	We don't share
For our affiliates' everyday business purposes— information about your transactions and experiences. Affiliates are companies related by common ownership or control. They can be financial and non-financial companies. *Our affiliates may include companies with a Stewart name; financial companies, such as Stewart Title Company*	Yes	No
For our affiliates' everyday business purposes— information about your creditworthiness.	No	We don't share
For our affiliates to market to you — For your convenience, Stewart has developed a means for you to opt out from its affiliates marketing even though such mechanism is not legally required.	Yes	Yes, send your first and last name, the email address used in your transaction, your Stewart file number and the Stewart office location that is handling your transaction by email to optout@stewart.com or fax to 1-800-335-9591.
For non-affiliates to market to you. Non-affiliates are companies not related by common ownership or control. They can be financial and non-financial companies.	No	We don't share

We may disclose your personal information to our affiliates or to non-affiliates as permitted by law. If you request a transaction with a non-affiliate, such as a third party insurance company, we will disclose your personal information to that non-affiliate. [We do not control their subsequent use of information, and suggest you refer to their privacy notices.]

SHARING PRACTICES

How often do the Stewart Title Companies notify me about their practices?	We must notify you about our sharing practices when you request a transaction.
How do the Stewart Title Companies protect my personal information?	To protect your personal information from unauthorized access and use, we use security measures that comply with federal law. These measures include computer, file, and building safeguards.
How do the Stewart Title Companies collect my personal information?	We collect your personal information, for example, when you ▪ request insurance-related services ▪ provide such information to us We also collect your personal information from others, such as the real estate agent or lender involved in your transaction, credit reporting agencies, affiliates or other companies.
What sharing can I limit?	Although federal and state law give you the right to limit sharing (e.g., opt out) in certain instances, we do not share your personal information in those instances.

Contact us: If you have any questions about this privacy notice, please contact us at: **Stewart Title Guaranty Company, 1360 Post Oak Blvd., Ste. 100, Privacy Officer, Houston, Texas 77056**

Privacy Notice for California Residents

Pursuant to the California Consumer Privacy Act of 2018 ("CCPA"), Stewart Information Services Corporation and its subsidiary companies (collectively, "Stewart") are providing this **Privacy Notice for California Residents** ("CCPA Notice"). This CCPA Notice supplements the information contained in Stewart's existing privacy notice and applies solely to all visitors, users and others who reside in the State of California or are considered California Residents ("consumers" or "you"). Terms used but not defined shall have the meaning ascribed to them in the CCPA.

Information Stewart Collects

Stewart collects information that identifies, relates to, describes, references, is capable of being associated with, or could reasonably be linked, directly or indirectly, with a particular consumer, household, or device. Most of the information that Stewart collects in the course of its regular business is already protected pursuant to the Gramm-Leach-Bliley Act (GLBA). Additionally, much of this information comes from government records or other information already in the public domain. Personal information under the CCPA does not include:

- Publicly available information from government records.
- Deidentified or aggregated consumer information.
- Certain personal information protected by other sector-specific federal or California laws, including but not limited to the Fair Credit Reporting Act (FCRA), GLBA and California Financial Information Privacy Act (FIPA).

Specifically, Stewart has collected the following categories of personal information from consumers within the last twelve (12) months:

Category	**Examples**	**Collected?**
A. Identifiers.	A real name, alias, postal address, unique personal identifier, online identifier, Internet Protocol address, email address, account name, Social Security number, driver's license number, passport number, or other similar identifiers.	YES
B. Personal information categories listed in the California Customer Records statute (Cal. Civ. Code § 1798.80(e)).	A name, signature, Social Security number, physical characteristics or description, address, telephone number, passport number, driver's license or state identification card number, insurance policy number, education, employment, employment history, bank account number, credit card number, debit card number, or any other financial information, medical information, or health insurance information. Some personal information included in this category may overlap with other categories.	YES
C. Protected classification characteristics under California or federal law.	Age (40 years or older), race, color, ancestry, national origin, citizenship, religion or creed, marital status, medical condition, physical or mental disability, sex (including gender, gender identity, gender expression, pregnancy or childbirth and related medical conditions), sexual orientation, veteran or military status, genetic information (including familial genetic information).	YES
D. Commercial information.	Records of personal property, products or services purchased, obtained, or considered, or other purchasing or consuming histories or tendencies.	YES
E. Biometric information.	Genetic, physiological, behavioral, and biological characteristics, or activity patterns used to extract a template or other identifier or identifying information, such as, fingerprints, faceprints, and voiceprints, iris or retina scans, keystroke, gait, or other physical patterns, and sleep, health, or exercise data.	YES
F. Internet or other similar network activity.	Browsing history, search history, information on a consumer's interaction with a website, application, or advertisement.	YES
G. Geolocation data.	Physical location or movements.	YES
H. Sensory data.	Audio, electronic, visual, thermal, olfactory, or similar information.	YES
I. Professional or employment-related information.	Current or past job history or performance evaluations.	YES
J. Non-public education information (per the Family Educational Rights and Privacy Act (20 U.S.C. Section 1232g, 34 C.F.R. Part 99)).	Education records directly related to a student maintained by an educational institution or party acting on its behalf, such as grades, transcripts, class lists, student schedules, student identification codes, student financial information, or student disciplinary records.	YES
K. Inferences drawn from other personal information.	Profile reflecting a person's preferences, characteristics, psychological trends, predispositions, behavior, attitudes, intelligence, abilities, and aptitudes.	YES

Stewart obtains the categories of personal information listed above from the following categories of sources:

- Directly and indirectly from customers, their designees or their agents (For example, realtors, lenders, attorneys, etc.)
- Directly and indirectly from activity on Stewart's website or other applications.
- From third-parties that interact with Stewart in connection with the services we provide.

Use of Personal Information

Stewart may use or disclose the personal information we collect for one or more of the following purposes:

- To fulfill or meet the reason for which the information is provided.
- To provide, support, personalize, and develop our website, products, and services.
- To create, maintain, customize, and secure your account with Stewart.
- To process your requests, purchases, transactions, and payments and prevent transactional fraud.
- To prevent and/or process claims.
- To assist third party vendors/service providers who complete transactions or perform services on Stewart's behalf.
- As necessary or appropriate to protect the rights, property or safety of Stewart, our customers or others.
- To provide you with support and to respond to your inquiries, including to investigate and address your concerns and monitor and improve our responses.
- To personalize your website experience and to deliver content and product and service offerings relevant to your interests, including targeted offers and ads through our website, third-party sites, and via email or text message (with your consent, where required by law).
- To help maintain the safety, security, and integrity of our website, products and services, databases and other technology assets, and business.
- To respond to law enforcement or regulator requests as required by applicable law, court order, or governmental regulations.
- Auditing for compliance with federal and state laws, rules and regulations.
- Performing services including maintaining or servicing accounts, providing customer service, processing or fulfilling orders and transactions, verifying customer information, processing payments, providing advertising or marketing services or other similar services.
- To evaluate or conduct a merger, divestiture, restructuring, reorganization, dissolution, or other sale or transfer of some or all of our assets, whether as a going concern or as part of bankruptcy, liquidation, or similar proceeding, in which personal information held by us is among the assets transferred.

Stewart will not collect additional categories of personal information or use the personal information we collected for materially different, unrelated, or incompatible purposes without providing you notice.

Disclosure of Personal Information to Affiliated Companies and Nonaffiliated Third Parties

Stewart does not sell your personal information to nonaffiliated third parties. Stewart may share your information with those you have designated as your agent in the course of your transaction (for example, a realtor or a lender). Stewart may disclose your personal information to a third party for a business purpose. Typically, when we disclose personal information for a business purpose, we enter a contract that describes the purpose and requires the recipient to both keep that personal information confidential and not use it for any purpose except performing the contract.

We share your personal information with the following categories of third parties:

- Service providers and vendors (For example, search companies, mobile notaries, and companies providing credit/debit card processing, billing, shipping, repair, customer service, auditing, marketing, etc.)
- Affiliated Companies
- Litigation parties and attorneys, as required by law.
- Financial rating organizations, rating bureaus and trade associations.
- Federal and State Regulators, law enforcement and other government entities

In the preceding twelve (12) months, Stewart has disclosed the following categories of personal information for a business purpose:

Category A: Identifiers
Category B: California Customer Records personal information categories
Category C: Protected classification characteristics under California or federal law
Category D: Commercial Information
Category E: Biometric Information
Category F: Internet or other similar network activity
Category G: Geolocation data
Category H: Sensory data
Category I: Professional or employment-related information
Category J: Non-public education information
Category K: Inferences

Consumer Rights and Choices

The CCPA provides consumers (California residents) with specific rights regarding their personal information. This section describes your CCPA rights and explains how to exercise those rights.

Access to Specific Information and Data Portability Rights

You have the right to request that Stewart disclose certain information to you about our collection and use of your personal information over the past 12 months. Once we receive and confirm your verifiable consumer request, Stewart will disclose to you:

- The categories of personal information Stewart collected about you.
- The categories of sources for the personal information Stewart collected about you.
- Stewart's business or commercial purpose for collecting that personal information.
- The categories of third parties with whom Stewart shares that personal information.
- The specific pieces of personal information Stewart collected about you (also called a data portability request).
- If Stewart disclosed your personal data for a business purpose, a listing identifying the personal information categories that each category of recipient obtained.

Deletion Request Rights

You have the right to request that Stewart delete any of your personal information we collected from you and retained, subject to certain exceptions. Once we receive and confirm your verifiable consumer request, Stewart will delete (and direct our service providers to delete) your personal information from our records, unless an exception applies.

Stewart may deny your deletion request if retaining the information is necessary for us or our service providers to:

1. Complete the transaction for which we collected the personal information, provide a good or service that you requested, take actions reasonably anticipated within the context of our ongoing business relationship with you, or otherwise perform our contract with you
2. Detect security incidents, protect against malicious, deceptive, fraudulent, or illegal activity, or prosecute those responsible for such activities.
3. Debug products to identify and repair errors that impair existing intended functionality.
4. Exercise free speech, ensure the right of another consumer to exercise their free speech rights, or exercise another right provided for by law.
5. Comply with the California Electronic Communications Privacy Act (Cal. Penal Code § 1546 *seq.*).
6. Engage in public or peer-reviewed scientific, historical, or statistical research in the public interest that adheres to all other applicable ethics and privacy laws, when the information's deletion may likely render impossible or seriously impair the research's achievement, if you previously provided informed consent.
7. Enable solely internal uses that are reasonably aligned with consumer expectations based on your relationship with us.
8. Comply with a legal obligation.
9. Make other internal and lawful uses of that information that are compatible with the context in which you provided it.

Exercising Access, Data Portability, and Deletion Rights

To exercise the access, data portability, and deletion rights described above, please submit a verifiable consumer request to us either:

- Calling us Toll Free at 1-866-571-9270
- Emailing us at Privacyrequest@stewart.com
- Visiting http://stewart.com/ccpa

Only you, or someone legally authorized to act on your behalf, may make a verifiable consumer request related to your personal information. You may also make a verifiable consumer request on behalf of your minor child.

To designate an authorized agent, please contact Stewart through one of the methods mentioned above.

You may only make a verifiable consumer request for access or data portability twice within a 12-month period. The verifiable consumer request must:

- Provide sufficient information that allows us to reasonably verify you are the person about whom we collected personal information or an authorized representative.
- Describe your request with sufficient detail that allows us to properly understand, evaluate, and respond to it.

Stewart cannot respond to your request or provide you with personal information if we cannot verify your identity or authority to make the request and confirm the personal information relates to you.

Making a verifiable consumer request does not require you to create an account with Stewart.

Response Timing and Format

We endeavor to respond to a verifiable consumer request within forty-five (45) days of its receipt. If we require more time (up to an additional 45 days), we will inform you of the reason and extension period in writing.

A written response will be delivered by mail or electronically, at your option.

Any disclosures we provide will only cover the 12-month period preceding the verifiable consumer request's receipt. The response we provide will also explain the reasons we cannot comply with a request, if applicable. For data portability requests, we will select a format to provide your personal information that is readily useable and should allow you to transmit the information from one entity to another entity without hindrance.

Stewart does not charge a fee to process or respond to your verifiable consumer request unless it is excessive, repetitive, or manifestly unfounded. If we determine that the request warrants a fee, we will tell you why we made that decision and provide you with a cost estimate before completing your request.

Non-Discrimination

Stewart will not discriminate against you for exercising any of your CCPA rights. Unless permitted by the CCPA, we will not:

- Deny you goods or services.
- Charge you a different prices or rates for goods or services, including through granting discounts or other benefits, or imposing penalties.
- Provide you a different level or quality of goods or services.
- Suggest that you may receive a different price or rate for goods or services or a different level or quality of goods or services.

Changes to Our Privacy Notice

Stewart reserves the right to amend this privacy notice at our discretion and at any time. When we make changes to this privacy notice, we will post the updated notice on Stewart's website and update the notice's effective date. **Your continued use of Stewart's website following the posting of changes constitutes your acceptance of such changes.**

Contact Information

If you have questions or comments about this notice, the ways in which Stewart collects and uses your information described here, your choices and rights regarding such use, or wish to exercise your rights under California law, please do not hesitate to contact us at:

Phone: Toll Free at 1-866-571-9270

Website: http://stewart.com/ccpa

Email: Privacyrequest@stewart.com

Postal Address: Stewart Information Services Corporation
Attn: Mary Thomas, Deputy Chief Compliance Officer
1360 Post Oak Blvd., Ste. 100, MC #14-1
Houston, TX 77056

APPENDIX F

USER QUESTIONNAIRE

USER QUESTIONNAIRE for PHASE 1 ESA

(ASTM Standard E 1527-21)

Site Name: Belltown Tower

Location: 2729- 2nd Avenue
Seattle, Washington
TPN 0654000065

The person who will use the Phase 1 ESA should provide the following information. This is not a questionnaire for the seller of the property. Please fill in this form to the best of your ability, explaining any Yes answers on a separate sheet of paper. Without these answers, our report would have to note that the Phase 1 ESA is incomplete, and your Landowner Liability Protections could be at risk.

(1.) Did a search of *land title records* (or judicial records where appropriate) identify any *environmental liens* filed or recorded against the *subject property* under federal, tribal, state, or local law?

No No.

Yes_____ if yes, what liens or judicial records have been filed against the Property, please attach a summary.

(2.) Did a search of *land title records* (or judicial records where appropriate) identify any *AULs*, such as *engineering controls*, land use restrictions or *institutional controls* that are in place at the *subject property* and/or have been filed or recorded against the *subject property* under federal, tribal, state or local law?

No No

Yes_____ if yes, what AULs are in place for the Property, please attach a summary.

(3.) Do you have any specialized knowledge or experience related to the *subject property* or nearby *properties*? For example, are you involved in the same line of business as the current or former *occupants* of the *subject property* or an *adjoining property* so that you would have specialized knowledge of the chemicals and processes used by this type of business?

No No

Yes_____ if yes, please summarize your knowledge below. Attach more sheets if needed.

_____

_____

(4.) Does the purchase price being paid for this *subject property* reasonably reflect the fair market value of the *property*?

Yes Yes

No_____ if No, please summarize your knowledge of discounted price below. Attach more sheets if needed.

If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the *subject property*?

(5.) Are you aware of commonly known or *reasonably ascertainable* information about the *subject property* that would help the *environmental professional* to identify conditions indicative of *releases* or threatened *releases*?

(a.) Do you know the past uses of the *subject property*?

No _____

Yes_____ if yes, please summarize your knowledge below. Attach more sheets if needed.

Small shop

(b.) Do you know of specific chemicals that are present or once were present at the *subject property*?

No No

Yes_____ if yes, please summarize your knowledge below. Attach more sheets if needed.

Rafał Malarz

Name (printed)



30 09 2022

Signature **Date**

Vice President of the Management Board

Title

Explain Yes answers on a separate sheet.
# of separate sheets attached: _____

APPENDIX G
KING COUNTY HEALTH DEPARTMENT

Nick Hoffman

From: Nick Hoffman
Sent: Thursday, September 29, 2022 2:00 PM
To: public.disclosure@kingcounty.gov
Subject: new records request

Hello,

I am currently conducting a Phase I Environmental Site Assessment for one parcel in king county. The parcel number is 0654000065 with a listed address of 2729 Second Avenue in Bellevue, Washington.

I would like copies of any available documents for the parcel regarding underground storage tanks, storage/spills/releases of hazardous materials, and meth lab responses/complaints.

Let me know if you need any more information or if there is some type of form I need to fill out to complete the request.

Thanks

Nicolas R. Hoffman L.G.
Senior Project Geologist
Cell (206) 396-3707
NHoffman@terra-associates.com

TERRA ASSOCIATES, INC.
12220 – 113th Avenue NE, Suite 130
Kirkland, Washington 98034
Office - 425-821-7777
Fax - 425-821-4334

Nick Hoffman

From: King County Public Records <kingcountyexec@govqa.us>
Sent: Monday, October 3, 2022 11:41 AM
To: Nick Hoffman
Subject: [Records Center] Environmental Records Request :: E002398-093022

--- Please respond above this line ---

Dear Nicolas Hoffman,

We are in receipt of your public records request, received on 9/30/2022, and are responding to it on behalf of the King County Executive Branch only per King County Code 2.12.005 and 2.12.230(B). Your request has been assigned tracking number E002398-093022.

We are currently gathering and reviewing any records that may be responsive to your request. We anticipate providing you an installment, should responsive records exist, in approximately six to eight weeks. If the records are available sooner, we will provide them to you. Please reply to this correspondence or contact me if you have any questions.

Sincerely,
Chris Zanassi
Administrator II
Department of Natural Resources and Parks
206-477-4541

To monitor the progress or update this request please log into the Public Records Request System

APPENDIX H

CITY OF SEATTLE

Nick Hoffman

From: City of Seattle Public Records Request Center <seattle@mycusthelp.net>
Sent: Thursday, September 29, 2022 1:17 PM
To: Nick Hoffman
Subject: Construction & Inspections :: C106631-092922

Dear Nicolas Hoffman,

Welcome to the City of Seattle Public Records Request Center (PRRC). Your request was received on September 29, 2022 and is appended below.

The reference number for this request is C106631-092922. You will see this number in the title of any communications about this request.

You will hear from a Public Disclosure Officer within five business days regarding the status of your request.

Please visit the City of Seattle Public Records Request Center where you can manage your profile and access your request. Your login ID is: NHoffman@terra-associates.com

If a Public Disclosure Officer submitted your public disclosure request into the PRRC on your behalf, please login and complete your new user account by following these steps:

- Access the Public Records Request Center
- Select 'Forgot my Password'
- Enter your 'Login ID' (email address)
- A temporary password will be sent to you via email
- Login with the temporary password

You may now visit the PRRC 'My Records Request Center' anytime!

Request C106631-092922:

> "*Building permits and plans for the existing building located at 2729 2nd Avenue in the Belltown neighborhood of Seattle. King county tax parcel 0654000065.*"

Nick Hoffman

From: City of Seattle Public Records Request Center <seattle@mycusthelp.net>
Sent: Thursday, September 29, 2022 1:16 PM
To: Nick Hoffman
Subject: Fire Marshal's Office - Underground Tanks; NOVs; :: C106630-092922

Dear Nicolas Hoffman,

Welcome to the City of Seattle Public Records Request Center (PRRC). Your request related to *Fire Marshal's Office - Underground Tanks; NOVs;* information was received on September 29, 2022.

The reference number for this request is **C106630-092922**. You will see this number in the title of any communications about this request.

You will hear from a Public Disclosure Officer within five business days regarding the status of your request.

Please visit the City of Seattle Public Records Request Center where you can manage your profile and access your request. Your login ID is: NHoffman@terra-associates.com.

If a Public Disclosure Officer submitted your public disclosure request into the PRRC on your behalf, please login and complete your new user account by following these steps:

- Access the Public Records Request Center
- Select 'Forgot my Password'
- Enter your 'Login ID' (email address)
- A temporary password will be sent to you via email
- Login with the temporary password
- You will be asked to create a new password

You may now visit the PRRC 'My Records Request Center' anytime!

Nick Hoffman

From: City of Seattle Public Records Request Center <seattle@mycusthelp.net>
Sent: Tuesday, October 4, 2022 12:23 PM
To: Nick Hoffman
Subject: Fire Marshal's Office - Underground Tanks; NOVs; :: C106630-092922

--- Please respond above this line ---

Dear Nicolas Hoffman,

This acknowledges receipt of your public disclosure request C106630-092922 received on September 29, 2022 regarding:

Type of Record(s):
Decommissioned Underground Storage Tanks|Hazmat Permit Face - Cancelled|Hazmat Permit Face - Open|Notices of Violation - Closed|Notices of Violation - Open|Spills/Releases (land only)|

Address Associated With Requested Document:
2729 2nd Avenue, king county tax parcel 0654000065

Building Name:

Business Name:
Lighting Supply

There is no record of open fire code violations. A comprehensive search of my department resulted in no responsive documents. The Seattle Fire Department considers your request closed.

Sincerely,
Necia Marte
Public Records Officer
Seattle Fire Department

To monitor the progress, update this request, make payments and download your responsive records please log into the Public Records Request Center.

Nick Hoffman

From: City of Seattle Public Records Request Center <seattle@mycusthelp.net>
Sent: Tuesday, October 4, 2022 12:23 PM
To: Nick Hoffman
Subject: Fire Marshal's Office - Underground Tanks; NOVs; :: C106630-092922

--- Please respond above this line ---

Dear Nicolas Hoffman,

This acknowledges receipt of your public disclosure request C106630-092922 received on September 29, 2022 regarding:

Type of Record(s):
Decommissioned Underground Storage Tanks|Hazmat Permit Face - Cancelled|Hazmat Permit Face - Open|Notices of Violation - Closed|Notices of Violation - Open|Spills/Releases (land only)|

Address Associated With Requested Document:
2729 2nd Avenue, king county tax parcel 0654000065


Building Name:

Business Name:
Lighting Supply


There is no record of open fire code violations. A comprehensive search of my department resulted in no responsive documents. The Seattle Fire Department considers your request closed.

Sincerely,
Necia Marte
Public Records Officer
Seattle Fire Department

To monitor the progress, update this request, make payments and download your responsive records please log into the Public Records Request Center.




WEST ELEVATION




SW ELEVATION.


ALL WELDING BY WABO CERTIFIED WELDERS

991222-024




SITE PLAN (NO SCALE)





TOP VIEW

3 DIMENSIONAL NEON "LIGHT BULB"



CITY OF SEATTLE
DEPT. OF DESIGN CONSTRUCTION AND LAND USE

DEC 2 2 1999


ELECTRICAL
APPROVED Subject to Errors and Omissions
By

RECEIVED
JAN 1 1 2002

WESTERN NEON
2700 · 1st AVE S. (206) 682-7738

PROJECT NAME: NEON LIGHT BULB
ADDRESS. 2729 2ND AVE
DATE: 12/10/99

Approv. BY:	DATE: 12/10
Approv. BY:	DATE:
Approv BY:	DATE:



Western Neon

2700 1st Avenue South
Seattle, WA 98134
PHONE 206-682-7738 FAX 206-682-8159


To: CHIP CHAMLIN


FAX # 6084-8113

From: MARC. 99/222-024


Message: HERE IS THE REQUESTED MOUNTING DETAIL FOR. NEON LIGHT BULB PROJECT 2729 2ND AVE

CALL WITH ANY QUESTIONS.







EAST ELEVATION




ELEV A



SOUTH ELEVATION




SECTION A




REMODELED OFFICES
LIGHTING SUPPLY CO

JAN 31 1974


[redacted]


FIRST FLOOR PLAN
SCALE
CITY OF SEATTLE
DEPT. OF BUILDING
JAN 3 1974
Examined for Code Compliance




DUCT LAY OUT FOR LIGHTING SUPPLY COMPANY
1519 SECOND AVENUE SEATTLE WASH
PLENUM DOOR CLIMATE CONTROL 6910 SW SPOKANE ST SEATTLE
GENERAL ELECTRIC 100 SQ FT UNIT ON ROOF SECTION
4X6 STACK 280 LBS
NO BLDG MEMBERS CUT
CONTRACTOR


ALL ROUND DUCTS ABOVE FIRST T BAR CEILING













SOUTH WEST COR.
BALDWIN AVE. - CLAY ST.
GIBBS & HUDSON
ARTISTS IN MUNICIPAL ARCHITECTURE
HARRY S. HUDSON
ARCHITECT


Re. Con. Beam
6"x14'-30# Steel I Beam
4-18"# Steel Pipe Columns
8" Con. Blk. Wall
2nd Ave. Floor Grade
Alley Grade
Section at C.C.
GIBBS & HUDSON
HARRY C. HUDSON
ARCHITECT



SHOWING UNDER PINNING OF OLD BUILDING AT

SCALE 1/4" = 1'-0"

38184

APPENDIX I

ERIS DATABASE REPORT

DATABASE REPORT

Project Property:	*Belltown Tower* *Belltown Tower* *Seattle WA 98121*
Project No:	*8819*
Report Type:	*Database Report*
Order No:	*22092804724*
Requested by:	*Terra-Associates, Inc.*
Date Completed:	*September 29, 2022*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....8
Executive Summary: Site Report Summary - Surrounding Properties.....9
Executive Summary: Summary by Data Source.....70
Map.....136
Aerial.....139
Topographic Map.....140
Detail Report.....141
Unplottable Summary.....1023
Unplottable Report.....1025
Appendix: Database Descriptions.....1045
Definitions.....1058

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc. ("ERIS") using various sources of information, including information provided by Federal and State government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Inc. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:		*Belltown Tower* *Belltown Tower Seattle WA 98121*
Project No:		*8819*
Coordinates:		
	Latitude:	*47.61665149*
	Longitude:	*-122.35067771*
	UTM Northing:	*5,273,898.29*
	UTM Easting:	*548,794.17*
	UTM Zone:	*UTM Zone 10T*
Elevation:		*106 FT*

Order Information:

Order No:	*22092804724*
Date Requested:	*September 28, 2022*
Requested by:	*Terra-Associates, Inc.*
Report Type:	*Database Report*

Historicals/Products:

City Directory Search	*CD - 1 Street Search*
ERIS Xplorer	*ERIS Xplorer*
Excel Add-On	*Excel Add-On*
Fire Insurance Maps	*US Fire Insurance Maps*
Physical Setting Report (PSR)	*Physical Setting Report (PSR)*

Executive Summary: Report Summary

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
Standard Environmental Records								
Federal								
DOE FUSRAP	Y	1	0	0	0	0	0	0
NPL	Y	1	0	0	0	0	0	0
PROPOSED NPL	Y	1	0	0	0	0	0	0
DELETED NPL	Y	0.5	0	0	0	0	-	0
SEMS	Y	0.5	0	0	0	0	-	0
ODI	Y	0.5	0	0	0	0	-	0
SEMS ARCHIVE	Y	0.5	0	0	0	**1**	-	**1**
CERCLIS	Y	0.5	0	0	0	**1**	-	**1**
IODI	Y	0.5	0	0	0	0	-	0
CERCLIS NFRAP	Y	0.5	0	0	0	**1**	-	**1**
CERCLIS LIENS	Y	PO	0	-	-	-	-	0
RCRA CORRACTS	Y	1	0	0	0	0	0	0
RCRA TSD	Y	0.5	0	0	0	**1**	-	**1**
RCRA LQG	Y	0.25	0	0	**2**	-	-	**2**
RCRA SQG	Y	0.25	0	0	0	-	-	0
RCRA VSQG	Y	0.25	0	0	**4**	-	-	**4**
RCRA NON GEN	Y	0.25	0	**6**	**30**	-	-	**36**
RCRA CONTROLS	Y	0.5	0	0	0	0	-	0
FED ENG	Y	0.5	0	0	0	0	-	0
FED INST	Y	0.5	0	0	0	0	-	0
LUCIS	Y	0.5	0	0	0	0	-	0
NPL IC	Y	0.5	0	0	0	0	-	0
ERNS 1982 TO 1986	Y	PO	0	-	-	-	-	0
ERNS 1987 TO 1989	Y	PO	0	-	-	-	-	0
ERNS	Y	PO	0	-	-	-	-	0
FED BROWNFIELDS	Y	0.5	0	0	0	0	-	0
FEMA UST	Y	0.25	0	0	0	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
FRP	Y	0.25	0	0	0	-	-	0
DELISTED FRP	Y	0.25	0	0	0	-	-	0
HIST GAS STATIONS	Y	0.25	0	0	0	-	-	0
REFN	Y	0.25	0	0	0	-	-	0
BULK TERMINAL	Y	0.25	0	0	0	-	-	0
SEMS LIEN	Y	PO	0	-	-	-	-	0
SUPERFUND ROD	Y	1	0	0	0	0	0	0
State								
HSL	Y	1	0	**1**	**4**	**3**	**26**	**34**
CSCSL	Y	1	0	**1**	**15**	**23**	**109**	**148**
DELISTED SHWS	Y	1	0	0	**3**	**6**	**16**	**25**
CSCSL NFA	Y	0.5	0	**3**	**12**	**23**	-	**38**
SWF/LF	Y	0.5	0	0	0	**2**	-	**2**
RECYCLERS	Y	0.5	0	0	0	**2**	-	**2**
WASTE TIRE	Y	0.5	0	0	0	0	-	0
LUST	Y	0.5	0	**1**	**11**	**21**	-	**33**
LUST PTAP	Y	0.5	0	0	**2**	**2**	-	**4**
UST LOAN	Y	0.5	0	0	0	0	-	0
LST HOT	Y	0.5	0	0	0	**1**	-	**1**
UST	Y	0.25	0	**5**	**16**	-	-	**21**
DELISTED LST	Y	0.5	0	0	**1**	**2**	-	**3**
AST	Y	0.25	0	0	0	-	-	0
AST SPL PREV	Y	0.25	0	0	0	-	-	0
DELISTED TNK	Y	0.25	0	0	0	-	-	0
INST	Y	0.5	0	0	**4**	**4**	-	**8**
VCP	Y	0.5	0	**2**	**16**	**23**	-	**41**
BROWNFIELDS	Y	0.5	0	0	0	0	-	0
Tribal								
INDIAN LUST	Y	0.5	0	0	0	0	-	0
INDIAN UST	Y	0.25	0	0	0	-	-	0
DELISTED ILST	Y	0.5	0	0	0	0	-	0
DELISTED IUST	Y	0.25	0	0	0	-	-	0
County								

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
KING HIST LF	Y	0.5	0	0	0	0	-	0
SEA HIST LF	Y	0.5	0	0	0	0	-	0
KING SKLF	Y	0.5	0	0	0	0	-	0
UST SEATTLE	Y	0.25	0	**7**	**15**	-	-	**22**

Additional Environmental Records

Federal

FINDS/FRS	Y	PO	0	-	-	-	-	0
TRIS	Y	PO	0	-	-	-	-	0
PFAS TRI	Y	0.5	0	0	0	0	-	0
PFAS NPL	Y	0.5	0	0	0	0	-	0
PFAS WATER	Y	0.5	0	0	0	0	-	0
PFAS SSEHRI	Y	0.5	0	0	0	0	-	0
ERNS PFAS	Y	0.5	0	0	0	0	-	0
HMIRS	Y	0.125	**2**	0	-	-	-	**2**
NCDL	Y	0.125	0	0	-	-	-	0
TSCA	Y	0.125	0	0	-	-	-	0
HIST TSCA	Y	0.125	0	0	-	-	-	0
FTTS ADMIN	Y	PO	0	-	-	-	-	0
FTTS INSP	Y	PO	0	-	-	-	-	0
PRP	Y	PO	0	-	-	-	-	0
SCRD DRYCLEANER	Y	0.5	0	0	0	0	-	0
ICIS	Y	PO	0	-	-	-	-	0
FED DRYCLEANERS	Y	0.25	0	0	**2**	-	-	**2**
DELISTED FED DRY	Y	0.25	0	0	0	-	-	0
FUDS	Y	1	0	0	0	**1**	**41**	**42**
FORMER NIKE	Y	1	0	0	0	0	0	0
PIPELINE INCIDENT	Y	PO	0	-	-	-	-	0
MLTS	Y	PO	0	-	-	-	-	0
HIST MLTS	Y	PO	0	-	-	-	-	0
MINES	Y	0.25	0	0	0	-	-	0
SMCRA	Y	1	0	0	0	0	0	0
MRDS	Y	1	0	0	0	0	0	0
URANIUM	Y	1	0	0	0	0	0	0
ALT FUELS	Y	0.25	0	**1**	**5**	-	-	**6**
CONSENT DECREES	Y	0.25	0	0	0	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
AFS	Y	PO	0	-	-	-	-	0
SSTS	Y	0.25	0	0	**1**	-	-	**1**
PCBT	Y	0.5	0	0	0	0	-	0
PCB	Y	0.5	0	**1**	**3**	**1**	-	**5**
State								
SPILLS	Y	0.125	0	**19**	-	-	-	**19**
SPILLS WATER	Y	0.125	0	**1**	-	-	-	**1**
ALL SITES	Y	0.5	0	**14**	**64**	**116**	**1**	**195**
ERTS	Y	0.125	0	**16**	-	-	-	**16**
ICR	Y	0.5	0	**3**	**26**	**40**	-	**69**
DRYCLEANERS	Y	0.25	0	0	**2**	-	-	**2**
DELISTED DRYCLEANERS	Y	0.25	0	0	0	-	-	0
TIER 2	Y	0.125	0	0	-	-	-	0
CDL	Y	PO	0	-	-	-	-	0
HIST CDL	Y	PO	0	-	-	-	-	0
AIR PERMITS	Y	0.25	0	0	0	-	-	0
UIC	Y	PO	0	-	-	-	-	0
Tribal	***No Tribal additional environmental record sources available for this State.***							
County								
CDL KING COUNTY	Y	0.125	0	0	-	-	-	0
Total:			***2***	***81***	***238***	***274***	***193***	***788***

**** PO – Property Only***
**** 'Property and adjoining properties' database search radii are set at 0.25 miles.***

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
1	HMIRS		2729 SECOND AVE SEATTLE WA	W	0.00 / 0.00	-2	141
1	HMIRS		2729 SECOND AVE SEATTLE WA	W	0.00 / 0.00	-2	142

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
2	ERTS		2800 BLOCK OF 2ND ST SEATTLE WA	N	0.01 / 55.17	3	144
2	SPILLS		2800 BLOCK OF 2ND ST SEATTLE WA ***Incident ID*	*Incident Date:*** 511738 |	N	0.01 / 55.17	3	145
3	RCRA NON GEN	SEA COAST TOWING INC HOME OFFI	2701 1ST AVE SEATTLE WA 98121 ***EPA Handler ID:*** WAD988477253	SSW	0.04 / 184.96	-13	145
3	ALL SITES	Sea Coast Towing Inc Home Offi	2701 1ST AVE SEATTLE WA 98121	SSW	0.04 / 184.96	-13	147
3	ERTS	PIER 70	2701 1ST AVE SEATTLE WA	SSW	0.04 / 184.96	-13	148
3	SPILLS	PUGET SOUND	2701 1ST AVE SEATTLE WA ***Incident ID*	*Incident Date:*** 555687 | 6/8/2006	SSW	0.04 / 184.96	-13	151
3	SPILLS		2701 1ST AVE SEATTLE WA ***Incident ID*	*Incident Date:*** 555687 |	SSW	0.04 / 184.96	-13	151
4	UST SEATTLE		2702 1ST AVE Seattle WA 98119 ***Permit No*	*Date Issued:*** 3-43475 | 07/23/2002	S	0.04 / 200.06	-12	152
5	RCRA NON GEN	GRANGE INSURANCE GROUP	200 CEDAR ST SEATTLE WA 98121 ***EPA Handler ID:*** WAH000019778	E	0.04 / 205.62	8	152
5	ALL SITES	Grange Insurance Group	200 CEDAR ST SEATTLE WA 98121	E	0.04 / 205.62	8	155
6	ERTS		2821 2ND AVE SEATTLE WA	NW	0.05 / 250.19	2	155
6	ERTS		2821 2ND AVE SEATTLE WA 98121	NW	0.05 / 250.19	2	156

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
6	SPILLS		2821 2ND AVE SEATTLE WA	NW	0.05 / 250.19	2	157
			Incident ID* | *Incident Date: 90778 | 10/5/2016				
6	SPILLS	NULL	2821 2ND AVE SEATTLE WA	NW	0.05 / 250.19	2	158
			Incident ID* | *Incident Date: 501975 | 1/11/1999				
6	SPILLS		2821 2ND AVE SEATTLE WA	NW	0.05 / 250.19	2	158
			Incident ID* | *Incident Date: 501975 |			
7	RCRA NON GEN	SEATTLE LABOR TEMPLE ASSOC PARKING LOT	2801 1ST AVE SEATTLE WA 98121	W	0.06 / 295.13	-14	158
			EPA Handler ID: WAD982658270				
7	ALL SITES	Seattle Labor Temple Assoc Parking Lot	2801 1ST AVE SEATTLE WA 98121	W	0.06 / 295.13	-14	160
8	ERTS	`JOB SITE`	2600 2ND AVE SEATTLE WA	ESE	0.06 / 306.72	3	161
9	ALT FUELS	Dimension Seattle	225 Cedar Street Seattle WA 98121	E	0.06 / 311.19	11	161
			ID: 147755				
9	UST SEATTLE		225 CEDAR ST Seattle WA 98121	E	0.06 / 311.19	11	162
			Permit No* | *Date Issued: 3-89824 | 08/29/2012				
10	UST	THIRD AVENUE PRODUCTIONS	2720 3RD AVE Seattle WA 98121	NE	0.07 / 371.39	16	162
			UST ID* | *Site Active: 11732 | No ***Tank Name* | *Tank Status:*** 1 | Removed				
10	ALL SITES	THIRD AVENUE PRODUCTIONS	2720 3RD AVE SEATTLE WA 98121-1260	NE	0.07 / 371.39	16	163
11	UST SEATTLE		2703 3RD AVE Seattle WA 98109	ENE	0.07 / 372.20	13	163
			Permit No* | *Date Issued: 3-45657 | 01/21/2003				
12	ERTS	Parking Lot of Wells Fargo	2800 3rd Ave Seattle WA 98121	NNE	0.07 / 384.66	17	163
13	ERTS		2607 2nd Ave (Alley) SEATTLE WA	ESE	0.08 / 418.39	2	165

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
14	UST	COX MEDIA GROUP SEATTLE	2807 3RD AVE Seattle WA 98121	N	0.08 / 419.66	16	167
			***UST ID	Site Active:*** 12511 | Yes ***Tank Name	Tank Status:*** 2 | Removed, 7867 | Operational			
14	ALL SITES	KIRO INC	2807 3RD AVE SEATTLE WA 98121	N	0.08 / 419.66	16	168
15	UST	FRANK JAMES AUTO & PEOPLES VOLKSWAGEN	2900-2922 1ST AVENUE Seattle WA 98121	W	0.08 / 421.07	-15	168
			***UST ID	Site Active:*** 10214 | No ***Tank Name	Tank Status:*** 3 | Removed, 11 | Removed, 5 | Removed, 8 | Removed, 1 | Removed, 4 | Removed, 7 | Removed, 10 | Removed, 2 | Removed, 6 | Removed, 9 | Removed			
16	ERTS	WA STATE FERRY SYSTEM	2911 2ND AVE SEATTLE WA	NW	0.08 / 443.04	2	174
16	ERTS	GALLERY BELL TOWN	2911 - 2ND AVENUE SEATTLE WA	NW	0.08 / 443.04	2	179
16	SPILLS	PUGET SOUND	2911 2ND AVE SEATTLE WA	NW	0.08 / 443.04	2	183
			***Incident ID	Incident Date:*** 553152 | 1/26/2006			
16	SPILLS	GALLERY BELL TOWN	2911 - 2ND AVENUE SEATTLE WA	NW	0.08 / 443.04	2	183
			***Incident ID	Incident Date:*** 65499 | 2/21/2011			
16	SPILLS		2911 - 2ND AVENUE SEATTLE WA	NW	0.08 / 443.04	2	183
			***Incident ID	Incident Date:*** 625156 |			
16	SPILLS		2911 2ND AVE SEATTLE WA	NW	0.08 / 443.04	2	184
			***Incident ID	Incident Date:*** 553152 |			
17	ERTS	ARBOR PLACE TOWER	121 VINE ST SEATTLE WA 98121-	ESE	0.09 / 471.81	0	184
17	SPILLS		121 VINE ST SEATTLE WA	ESE	0.09 / 471.81	0	185
			***Incident ID	Incident Date:*** 549811 |			
18	ALL SITES	Rite Aid 5218	2603 3RD AVE SEATTLE WA 98121	E	0.10 / 509.10	11	185
18	RCRA NON GEN	RITE AID 5218	2603 3RD AVE SEATTLE WA 98121	E	0.10 / 509.10	11	186
			EPA Handler ID: WAR000002709				

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
19	UST SEATTLE		2915 1ST AVE Seattle WA 98109 ***Permit No* | *Date Issued:*** 3-40995 | 01/28/2002	WNW	0.10 / 538.54	-16	210
20	SPILLS WATER		SEATTLE WA	WNW	0.10 / 552.90	-18	210
21	CSCSL NFA	The Olympus	2801 WESTERN AVE SEATTLE WA 98121	WSW	0.11 / 577.56	-56	210
21	UST	THE OLYMPUS	2801 WESTERN AVE Seattle WA 98121 ***UST ID* | *Site Active:*** 579191 | No ***Tank Name* | *Tank Status:*** 1 | Closed in Place	WSW	0.11 / 577.56	-56	211
21	ALL SITES	THE OLYMPUS	2801 WESTERN AVE SEATTLE WA 98121	WSW	0.11 / 577.56	-56	211
21	ICR	THE OLYMPUS	2801 WESTERN AVE SEATTLE WA 98121	WSW	0.11 / 577.56	-56	212
21	VCP	The Olympus	2801 WESTERN AVE SEATTLE WA 98121	WSW	0.11 / 577.56	-56	213
21	LUST	The Olympus	2801 WESTERN AVE SEATTLE WA 98121 ***Facility Site ID:*** 35216721	WSW	0.11 / 577.56	-56	214
22	SPILLS		SEATTLE WA ***Incident ID* | *Incident Date:*** 120341 | 01/03/2022	SW	0.11 / 591.76	-52	214
23	PCB	3RD AND BROAD	2901 3RD AVE SEATTLE WA 98121 ***Site ID:*** WAW000200592	NNW	0.11 / 592.50	20	215
23	ERTS	WA STATE FERRY OPERATIONS CENTER	2901 3RD AVE SEATTLE WA 98121	NNW	0.11 / 592.50	20	216
23	ERTS		2901 3RD AVE SEATTLE WA	NNW	0.11 / 592.50	20	219
23	SPILLS	PS- ELLIOTT BAY	2901 3RD AVE SEATTLE WA ***Incident ID* | *Incident Date:*** 617011 | 12/13/2009	NNW	0.11 / 592.50	20	220
23	SPILLS		2901 3RD AVE SEATTLE WA	NNW	0.11 / 592.50	20	220

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			Incident ID **|** ***Incident Date:*** 547548 **|**			
23	SPILLS		2901 3RD AVE SEATTLE WA ***Incident ID*** **|** ***Incident Date:*** 617011 **|**	NNW	0.11 / 592.50	20	221
24	ERTS		320 CEDAR STREET AT 4TH AND CEDAR IN THE SEATTLE WA	ENE	0.11 / 592.78	19	221
25	UST SEATTLE		2517 1ST AVE Seattle WA 98119 ***Permit No*** **|** ***Date Issued:*** 3-49166 **|** 09/22/2003	SE	0.11 / 595.00	-9	222
26	SPILLS		2717 WESTERN AVE SEATTLE WA ***Incident ID*** **|** ***Incident Date:*** 611562 **|**	SW	0.11 / 601.93	-54	222
27	ERTS	OLYMPIC SCULPTURE PARK	WESTERN AVE. & BROAD ST. SEATTLE WA	W	0.12 / 607.50	-51	223
27	SPILLS	NULL	WESTERN AVE. & BROAD ST. SEATTLE WA ***Incident ID*** **|** ***Incident Date:*** 553847 **|** 3/7/2006	W	0.12 / 607.50	-51	226
28	UST SEATTLE		2556 1ST AVE Seattle WA 98109 ***Permit No*** **|** ***Date Issued:*** 3-36566 **|** 02/07/2001	SE	0.12 / 610.99	-7	226
29	SPILLS	NULL	320 CEDAR STREET AT 4TH AND CEDAR IN THE SEATTLE WA ***Incident ID*** **|** ***Incident Date:*** 425987 **|** 1/22/1997	ENE	0.12 / 611.69	18	226
29	SPILLS		320 CEDAR STREET AT 4TH AND CEDAR IN THE SEATTLE WA ***Incident ID*** **|** ***Incident Date:*** 425987 **|**	ENE	0.12 / 611.69	18	226
30	UST SEATTLE		2551 2ND AVE Seattle WA N/A ***Permit No*** **|** ***Date Issued:*** 3-36899 **|** 03/09/2001	ESE	0.12 / 613.18	3	227
31	RCRA NON GEN	WASHINGTON TRANSIT ADVERTISING	2600 WESTERN AVE SEATTLE WA 98121 ***EPA Handler ID:*** WAD027482959	S	0.12 / 619.56	-41	227
31	ALL SITES	Washington Transit Advertising	2600 WESTERN AVE SEATTLE WA 98121	S	0.12 / 619.56	-41	229
32	CSCSL NFA	Vine Building	2607 WESTERN AVE SEATTLE WA 98121	S	0.12 / 621.29	-44	229

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
32	ALL SITES	VINE BUILDING	2607 WESTERN AVE SEATTLE WA 98121	S	0.12 / 621.29	-44	230
32	ICR	VINE BUILDING	2607 WESTERN AVE SEATTLE WA 98121	S	0.12 / 621.29	-44	230
32	VCP	Vine Building	2607 WESTERN AVE SEATTLE WA 98121	S	0.12 / 621.29	-44	231
33	ERTS	Parking Garage	75 Vine St Seattle WA 98121	S	0.12 / 627.43	-34	232
34	CSCSL	Martin Selig Property	2601 4TH AVE SEATTLE WA 98121	ENE	0.12 / 629.45	16	234
34	HSL	Martin Selig Property	2601 4TH AVE SEATTLE WA 98121	ENE	0.12 / 629.45	16	235
34	ALL SITES	MARTIN SELIG PROPERTY	2601 4TH AVE SEATTLE WA 98121	ENE	0.12 / 629.45	16	236
34	ALL SITES	Grizzly Retail Rentals	2601 4TH AVE STE 350 SEATTLE WA 98121	ENE	0.12 / 629.45	16	237
34	ICR	Martin Selig Property	2601 4TH AVE SEATTLE WA 98121	ENE	0.12 / 629.45	16	237
34	ALL SITES	Cascadian Therapeutics Seattle	2601 4th Ave Ste 500 Seattle WA 98121	ENE	0.12 / 629.45	16	239
34	RCRA NON GEN	CASCADIAN THERAPEUTICS SEATTLE	2601 4TH AVE STE 500 SEATTLE WA 98121 ***EPA Handler ID:*** WAH000053608	ENE	0.12 / 629.45	16	239
34	ERTS		2601 FOURTH AVE SEATTLE WA	ENE	0.12 / 629.45	16	248
35	CSCSL NFA	Cottage Properties	VINE ST SEATTLE WA 98121	SSE	0.12 / 637.31	-22	250

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
35	ALL SITES	COTTAGE PROPERTIES	VINE ST SEATTLE WA 98121	SSE	0.12 / 637.31	-22	250
36	UST	CEDAR DEVELOPMENT LLC	2627 WESTERN AVE Seattle WA 98121 ***UST ID	Site Active:*** 542217 | No ***Tank Name	Tank Status:*** 1 | Removed	SSW	0.12 / 651.76	-58	251
36	ALL SITES	CEDAR DEVELOPMENT LLC	2627 WESTERN AVE SEATTLE WA 98121	SSW	0.12 / 651.76	-58	251
37	UST SEATTLE		2530 2ND AVE Seattle WA 98119 ***Permit No	Date Issued:*** 3-34303 | 09/21/2000	ESE	0.13 / 661.01	4	252
38	RCRA NON GEN	WITS AIR FREIGHT	333 VINE ST SEATTLE WA 98121 ***EPA Handler ID:*** WAD041331935	E	0.13 / 661.67	12	252
38	ALL SITES	Wits Air Freight	333 VINE ST SEATTLE WA 98121	E	0.13 / 661.67	12	253
39	RCRA VSQG	RITE AID 6977 DBA BARTELL DRUGS 077	2506 2ND AVE SEATTLE WA 98121 ***EPA Handler ID:*** WAH000058410	ESE	0.13 / 674.54	4	254
39	ALL SITES	Rite Aid 6977 DBA Bartell Drugs 077	2506 2nd Ave Seattle WA 98121	ESE	0.13 / 674.54	4	258
40	ALL SITES	FRANK JAMES AUTO & PEOPLES VOLKSWAGEN	2900 2922 1ST AVE SEATTLE WA 98121	WNW	0.13 / 679.50	-13	258
41	CSCSL NFA	Sailors Union of the Pacific Building	2505 1ST AVE SEATTLE WA 98121	SSE	0.13 / 689.65	-19	259
41	UST	SAILORS UNION OF THE PACIFIC BLDG	2505 1ST AVE Seattle WA 98121 ***UST ID	Site Active:*** 319027 | No ***Tank Name	Tank Status:*** 1 | Closed in Place	SSE	0.13 / 689.65	-19	259
41	ALL SITES	SAILORS UNION OF THE PACIFIC BLDG	2505 1ST AVE SEATTLE WA 98121	SSE	0.13 / 689.65	-19	260
41	ICR	SAILOR'S UNION OF THE PACIFIC BLDG	2505 1ST AVE SEATTLE WA 98121	SSE	0.13 / 689.65	-19	261

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
41	LUST	Sailors Union of the Pacific Building	2505 1ST AVE SEATTLE WA 98121 ***Facility Site ID:*** 42839734	SSE	0.13 / 689.65	-19	262
42	UST	DEAN STRALEY'S BP	351 BROAD ST Seattle WA 98109 ***UST ID | Site Active:*** 8217 | Yes ***Tank Name | Tank Status:*** 1 | Operational, 3 | Operational, 4 | Operational, 2 | Operational	NNE	0.14 / 721.11	26	262
42	ALL SITES	DEAN STRALEYS BP	351 BROAD ST SEATTLE WA 98109	NNE	0.14 / 721.11	26	264
43	CSCSL NFA	NORTHWEST PROTECTIVE SERVICE	2700 ELLIOTT AVE SEATTLE WA 98121	SW	0.14 / 723.90	-67	265
43	UST	NORTHWEST PROTECTIVE SERVICE INC	2700 ELLIOTT AVE Seattle WA 98121 ***UST ID | Site Active:*** 1163 | No ***Tank Name | Tank Status:*** 1 | Removed, 2 | Removed	SW	0.14 / 723.90	-67	266
43	ALL SITES	Northwest Protective Service Inc	2700 ELLIOTT AVE SEATTLE WA 98121	SW	0.14 / 723.90	-67	267
43	ICR	NORTHWEST PROTECTIVE SERVICE	2700 ELLIOTT AVE SEATTLE WA 98121	SW	0.14 / 723.90	-67	269
43	RCRA NON GEN	BELLTOWN DEVELOPMENT PARTNERS II LLC	2700 ELLIOTT AVE SEATTLE WA 98121 ***EPA Handler ID:*** WAR000009753	SW	0.14 / 723.90	-67	270
43	LUST	NORTHWEST PROTECTIVE SERVICE	2700 ELLIOTT AVE SEATTLE WA 98121 ***Facility Site ID:*** 77333528	SW	0.14 / 723.90	-67	275
44	RCRA NON GEN	LA SCALA APARTMENTS	2922 WESTERN AVE SEATTLE WA 98121 ***EPA Handler ID:*** WAD988474540	W	0.14 / 748.41	-57	275
44	ALL SITES	La Scala Apartments	2922 WESTERN AVE SEATTLE WA 98121	W	0.14 / 748.41	-57	277
45	UST SEATTLE		2618 4TH AVE Seattle WA 98119 ***Permit No | Date Issued:*** 3-42668 | 05/31/2002	ENE	0.14 / 749.07	17	278

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
46	ALL SITES	K & N MEATS SEATTLE	2900 4TH AVE SEATTLE WA 98108	NE	0.14 / 758.42	24	278
47	RCRA NON GEN	OENING CO 81 VINE	2518 WESTERN AVE SEATTLE WA 98121 ***EPA Handler ID:*** WA0000188722	SSE	0.14 / 765.49	-41	278
47	ALL SITES	Oening Co 81 Vine	2518 WESTERN AVE SEATTLE WA 98121	SSE	0.14 / 765.49	-41	280
48	CSCSL NFA	Pacific Science Center Frol Building	204 DENNY WAY SEATTLE WA 98109	NW	0.15 / 771.91	7	280
48	ALL SITES	PACIFIC SCIENCE CTR FROL BLDG	204 DENNY WAY SEATTLE WA 98109	NW	0.15 / 771.91	7	281
48	ICR	Pacific Science Center Frol Building	204 DENNY WAY SEATTLE WA 98109	NW	0.15 / 771.91	7	282
48	VCP	Pacific Science Center Frol Building	204 DENNY WAY SEATTLE WA 98109	NW	0.15 / 771.91	7	283
49	RCRA NON GEN	PUGET SOUND INSTITUTE OF PATHO	2600 4TH AVE SEATTLE WA 98111 ***EPA Handler ID:*** WAD063338339	E	0.15 / 812.05	15	284
49	ALL SITES	Puget Sound Institute of Patho	2600 4TH AVE SEATTLE WA 98121	E	0.15 / 812.05	15	286
50	UST	THE FAMOUS PACIFIC DESSERT COMPANY	420 DENNY WAY Seattle WA 98109 ***UST ID | Site Active:*** 2732 | No ***Tank Name | Tank Status:*** 1. | Closed in Place	NE	0.16 / 820.79	23	287
50	ALL SITES	FAMOUS PACIFIC DESSERT COMPANY	420 DENNY WAY SEATTLE WA 98109	NE	0.16 / 820.79	23	287
51	INST	UNOCAL Seattle Marketing Terminal	BROAD ST & WESTERN AVE & BAY ST SEATTLE WA 98121	W	0.16 / 844.14	-76	288
51	CSCSL	Unocal Seattle Market Lower	BN ELLIOTT RR BAY & BROAD SEATTLE WA 98121	W	0.16 / 844.14	-76	289

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
51	CSCSL	UNOCAL Seattle Marketing Terminal	BROAD ST & WESTERN AVE & BAY ST SEATTLE WA 98121	W	0.16 / 844.14	-76	290
51	HSL	UNOCAL Seattle Marketing Terminal	BROAD ST & WESTERN AVE & BAY ST SEATTLE WA 98121	W	0.16 / 844.14	-76	294
51	HSL	Unocal Seattle Market Lower	BN ELLIOTT RR BAY & BROAD SEATTLE WA 98121	W	0.16 / 844.14	-76	296
51	ALL SITES	UNOCAL SEATTLE MARKET LOWER	BN ELLIOTT RR BAY & BROAD SEATTLE WA 98121	W	0.16 / 844.14	-76	297
51	ALL SITES	UNOCAL SEATTLE MARKETING TERM	BROAD ST & WESTERN AVE & BAY ST SEATTLE WA 98121	W	0.16 / 844.14	-76	298
51	ICR	UNOCAL SEATTLE MARKET LOWER	BN ELLIOTT RR BAY & BROAD SEATTLE WA 98121	W	0.16 / 844.14	-76	298
51	ICR	UNOCAL Seattle Marketing Terminal	BROAD ST & WESTERN AVE & BAY ST SEATTLE WA 98121	W	0.16 / 844.14	-76	300
52	RCRA NON GEN	ROSSMAN INDUSTRIAL SUPPLY CO	2500 WESTERN AVE SEATTLE WA 98121 ***EPA Handler ID:*** WAD988517991	SSE	0.16 / 856.05	-34	304
52	ALL SITES	Rossman Industrial Supply Co	2500 WESTERN AVE SEATTLE WA 98121-1308	SSE	0.16 / 856.05	-34	306
53	UST SEATTLE		2439 2ND AVE Seattle WA 98119 ***Permit No*** **|** ***Date Issued:*** 3-47025 | 05/08/2003	ESE	0.17 / 878.57	7	307
54	UST SEATTLE		2434 2ND AVE Seattle WA 98109 ***Permit No*** **|** ***Date Issued:*** 3-46042 | 02/27/2003	ESE	0.17 / 878.94	7	307
55	RCRA NON GEN	BRISTOL MYERS SQUIBB PHARM RES INST SEA	3005 1ST AVE STE 200 SEATTLE WA 98121 ***EPA Handler ID:*** WAD067194340	WNW	0.17 / 912.96	-26	307
55	CSCSL NFA	Bristol Myers Squibb	3005 1ST AVE SEATTLE WA 98121	WNW	0.17 / 912.96	-26	312

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
55	INST	Bristol Myers Squibb	3005 1ST AVE SEATTLE WA 98121	WNW	0.17 / 912.96	-26	313
55	DELISTED SHWS	ONCOGEN	3005 1ST AVE SEATTLE WA 98121	WNW	0.17 / 912.96	-26	314
55	UST	3005 FIRST AVENUE	3005 1ST AVE Seattle WA 98121 ***UST ID | Site Active:*** 102205 | Yes ***Tank Name | Tank Status:*** 1 | Removed, 2 | Operational	WNW	0.17 / 912.96	-26	314
55	ALL SITES	Bristol Myers Squibb Pharm Res Inst Sea	3005 1ST AVE STE 200 SEATTLE WA 98121	WNW	0.17 / 912.96	-26	315
55	ALL SITES	Dendreon Corp	3005 1ST AVE SEATTLE WA 98121	WNW	0.17 / 912.96	-26	316
55	DELISTED LST	ONCOGEN	3005 1ST AVE SEATTLE WA 98121	WNW	0.17 / 912.96	-26	318
55	ICR	Bristol Myers Squibb Pharm Res Inst Sea	3005 1ST AVE STE 200 SEATTLE WA 98121	WNW	0.17 / 912.96	-26	318
55	ICR	BRISTOL-MEYERS SQUIBB RESEARCH LAB	3005 1ST AVE SEATTLE WA 98121	WNW	0.17 / 912.96	-26	319
55	ICR	ONCOGEN	3005 1ST AVE SEATTLE WA 98121	WNW	0.17 / 912.96	-26	320
55	ICR	Dendreon Corp	3005 1ST AVE SEATTLE WA 98121	WNW	0.17 / 912.96	-26	321
55	SSTS	PLANT HEALTH CARE, INC	3005 1ST AVE SUITE 301 SEATTLE WA 98121 ***Establishment No:*** 71771-WA-1	WNW	0.17 / 912.96	-26	322
55	VCP	Bristol Myers Squibb	3005 1ST AVE SEATTLE WA 98121	WNW	0.17 / 912.96	-26	323
55	LUST	Bristol Myers Squibb	3005 1ST AVE SEATTLE WA 98121 ***Facility Site ID:*** 21448945	WNW	0.17 / 912.96	-26	324

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
55	ALL SITES	Cyrus Biotechnology Inc Seattle	3005 1st Ave Ste 203 Seattle WA 98121	WNW	0.17 / 912.96	-26	324
55	ALL SITES	Affini-T Therapeutics Seattle	3005 1st Ave Ste 102 Seattle WA 98121	WNW	0.17 / 912.96	-26	325
55	RCRA VSQG	CYRUS BIOTECHNOLOGY INC SEATTLE	3005 1ST AVE STE 203 SEATTLE WA 98121 ***EPA Handler ID:*** WAH000059595	WNW	0.17 / 912.96	-26	325
55	RCRA VSQG	AFFINI-T THERAPEUTICS SEATTLE	3005 1ST AVE STE 102 SEATTLE WA 98121 ***EPA Handler ID:*** WAH000059535	WNW	0.17 / 912.96	-26	327
55	RCRA NON GEN	ASTELLAS PHARMA US INC	3005 1ST AVE SEATTLE WA 98121 ***EPA Handler ID:*** WAD003095932	WNW	0.17 / 912.96	-26	328
56	UST SEATTLE		2446 1ST AVE Seattle WA 98119 ***Permit No | Date Issued:*** 3-39696 | 09/24/2001	SE	0.18 / 931.34	-2	347
57	CSCSL NFA	Belltown Pea Patch	ELLIOTT AVE & VINE ST SEATTLE WA 98121	SSW	0.18 / 931.76	-75	347
57	ALL SITES	BELLTOWN PEA PATCH	ELLIOTT AVE & VINE ST SEATTLE WA 98121	SSW	0.18 / 931.76	-75	348
57	ICR	BELLTOWN PEA PATCH	ELLIOTT AVE & VINE ST SEATTLE WA 98121	SSW	0.18 / 931.76	-75	349
58	CSCSL NFA	Fisher Plaza KOMO TV	100 4TH AVE N SEATTLE WA 98109	NE	0.18 / 940.23	26	350
58	UST	KOMO RADIO & TV	100 4TH AVE N Seattle WA 98109 ***UST ID | Site Active:*** 7404 | No ***Tank Name | Tank Status:*** 2 | Removed, 1 | Removed, 4 | Removed, 5 | Removed, 3 | Removed	NE	0.18 / 940.23	26	351
58	ALL SITES	FISHER PLAZA KOMO TV	100 4TH AVE N SEATTLE WA 98109	NE	0.18 / 940.23	26	353
58	ALL SITES	VADATA INC 4TH AVE	100 4TH AVE N STE 420 SEATTLE WA 98109	NE	0.18 / 940.23	26	354

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
58	ICR	Fisher Plaza KOMO TV	100 4TH AVE N SEATTLE WA 98109	NE	0.18 / 940.23	26	355
58	VCP	Fisher Plaza KOMO TV	100 4TH AVE N SEATTLE WA 98109	NE	0.18 / 940.23	26	356
58	LUST	Fisher Plaza KOMO TV	100 4TH AVE N SEATTLE WA 98109 ***Facility Site ID:*** 15636867	NE	0.18 / 940.23	26	357
58	ALL SITES	FRONTIER COMMUNICATIONS WA79899	100 4TH AVE N STE 250 SEATTLE WA 98109	NE	0.18 / 940.23	26	357
59	DELISTED SHWS	Bristol Myers Squibb	WA	WNW	0.18 / 943.25	-33	358
60	RCRA NON GEN	UNOCAL SS NO 0355	159 DENNY WAY SEATTLE WA 98119 ***EPA Handler ID:*** WAD988493441	WNW	0.18 / 945.58	-10	358
60	CSCSL	Unocal 0355	159 DENNY WAY SEATTLE WA 98109	WNW	0.18 / 945.58	-10	362
60	UST	UNION OIL 0355	159 DENNY WAY Seattle WA 98109 ***UST ID | Site Active:*** 8421 | No ***Tank Name | Tank Status:*** TK 2 | Removed, TK 3 | Removed, TK 6 | Removed, 4 | Removed, 2 | Removed, 1 | Removed, TK 7 | Removed, TK 1 | Removed, 3 | Removed, TK 5 | Removed, TK 4 | Removed, TK 8 | Removed	WNW	0.18 / 945.58	-10	364
60	ALL SITES	Unocal SS No 0355	159 DENNY WAY SEATTLE WA 98109	WNW	0.18 / 945.58	-10	370
60	LUST	Unocal 0355	159 DENNY WAY SEATTLE WA 98109 ***Facility Site ID:*** 32873776	WNW	0.18 / 945.58	-10	372
60	ICR	Unocal 0355	159 DENNY WAY SEATTLE WA 98109	WNW	0.18 / 945.58	-10	373
60	LUST PTAP	Unocal 0355	159 Denny Way, Seattle, WA 98109 WA	WNW	0.18 / 945.58	-10	382
60	VCP	Unocal 0355	159 DENNY WAY SEATTLE WA 98109	WNW	0.18 / 945.58	-10	382

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
61	RCRA NON GEN	SPACE NEEDLE CORP	219 4TH AVE N SEATTLE WA 98109 ***EPA Handler ID:*** WAD988514014	NNE	0.18 / 955.86	27	383
61	ALL SITES	Space Needle Corp	219 4TH AVE N SEATTLE WA 98109	NNE	0.18 / 955.86	27	387
62	UST SEATTLE		2517 4TH AVE Seattle WA 98109 ***Permit No	Date Issued:*** 3-42651 | 05/30/2002	E	0.18 / 963.63	16	387
63	UST SEATTLE		2432 1ST AVE Seattle WA 98109 ***Permit No	Date Issued:*** 3-36741 | 02/23/2001	SE	0.18 / 964.88	-1	387
64	CSCSL NFA	Chevron 97032	5TH AVE & DENNY WAY NW CORNER SEATTLE WA 98109	ENE	0.18 / 968.73	22	388
64	UST	CHEVRON 97032	5TH AVE & DENNY WAY Seattle WA 98109 ***UST ID	Site Active:*** 453155 | No ***Tank Name	Tank Status:*** 1 | Removed	ENE	0.18 / 968.73	22	388
64	ALL SITES	CHEVRON SERV STA 97032	5TH AVE & DENNY WAY NW CORNER SEATTLE WA 98109	ENE	0.18 / 968.73	22	389
64	ICR	Chevron 97032	5TH AVE & DENNY WAY NW CORNER SEATTLE WA 98109	ENE	0.18 / 968.73	22	390
64	VCP	Chevron 97032	5TH AVE & DENNY WAY NW CORNER SEATTLE WA 98109	ENE	0.18 / 968.73	22	391
64	LUST	Chevron 97032	5TH AVE & DENNY WAY NW CORNER SEATTLE WA 98109 ***Facility Site ID:*** 18935188	ENE	0.18 / 968.73	22	392
65	UST SEATTLE		2500 4TH AVE Seattle WA 98121 ***Permit No	Date Issued:*** P990119-34187 | 01/19/1999	E	0.19 / 976.90	16	392
66	UST SEATTLE		2426 1ST AVE Seattle WA 98109 ***Permit No	Date Issued:*** 3-45360 | 12/12/2002	SE	0.19 / 979.09	-1	392
67	RCRA NON GEN	S EPA H INC	150 DENNY WAY SEATTLE WA 98109 ***EPA Handler ID:*** WAD982821191	WNW	0.19 / 997.79	-10	392

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
67	ALL SITES	S EPA H Inc	150 DENNY WAY SEATTLE WA 98109	WNW	0.19 / 997.79	-10	394
68	RCRA NON GEN	SEATTLE CITY PARKS & REC BELLTOWN PP	2512 ELLIOT AVE SEATTLE WA 98102 ***EPA Handler ID:*** WAH000016816	S	0.19 / 1,001.11	-75	395
68	ALL SITES	Seattle City Parks & Rec Belltown PP	2512 ELLIOT AVE SEATTLE WA 98102	S	0.19 / 1,001.11	-75	399
69	CSCSL	Edwards on Fifth	2619 5TH AVE SEATTLE WA 98121	ENE	0.19 / 1,002.02	20	400
69	HSL	Edwards on Fifth	2619 5TH AVE SEATTLE WA 98121	ENE	0.19 / 1,002.02	20	400
69	ALL SITES	EDWARDS ON 5TH BLDG	2619 5TH AVE SEATTLE WA 98121	ENE	0.19 / 1,002.02	20	401
69	ICR	Edwards on Fifth	2619 5TH AVE SEATTLE WA 98121	ENE	0.19 / 1,002.02	20	402
69	VCP	Edwards on Fifth	2619 5TH AVE SEATTLE WA 98121	ENE	0.19 / 1,002.02	20	403
69	RCRA LQG	EDWARDS ON 5TH BLDG	2619 5TH AVE SEATTLE WA 98121 ***EPA Handler ID:*** WAH000059830	ENE	0.19 / 1,002.02	20	404
70	UST SEATTLE		2437 3RD AVE Seattle WA 98119 ***Permit No | Date Issued:*** 3-36933 | 03/12/2001	ESE	0.19 / 1,003.12	12	405
71	CSCSL NFA	Belltown Court Condos	2400 1ST AVE SEATTLE WA 98121	SE	0.19 / 1,005.13	-1	405
71	ALL SITES	BELLTOWN COURT CONDOS	2400 1ST AVE SEATTLE WA 98121	SE	0.19 / 1,005.13	-1	406
71	ICR	BELLTOWN COURT CONDOS	2400 1ST AVE SEATTLE WA 98121	SE	0.19 / 1,005.13	-1	406
71	VCP	Belltown Court Condos	2400 1ST AVE SEATTLE WA 98121	SE	0.19 / 1,005.13	-1	407

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
72	UST SEATTLE		2417 1ST AVE Seattle WA 98119 ***Permit No* | *Date Issued:*** 3-32958 | 06/19/2000	SE	0.19 / 1,006.48	-1	408
73	ALL SITES	WA UW Western Ave	3000 WESTERN AVE SEATTLE WA 98121	W	0.19 / 1,010.03	-59	408
73	RCRA NON GEN	GENETIC SYSTEMS CORPORATION WESTERN	3000 WESTERN AVENUE SEATTLE WA 98121-0000 ***EPA Handler ID:*** WAD988469193	W	0.19 / 1,010.03	-59	409
73	RCRA NON GEN	WA UW WESTERN AVE	3000 WESTERN AVE SEATTLE WA 98121 ***EPA Handler ID:*** WAH000005462	W	0.19 / 1,010.03	-59	410
74	CSCSL	Elliott & Broad	10 BROAD ST SEATTLE WA 98121	WSW	0.19 / 1,017.60	-90	425
74	ALL SITES	ELLIOTT & BROAD	10 BROAD ST SEATTLE WA 98121	WSW	0.19 / 1,017.60	-90	426
74	ICR	ELLIOTT & BROAD	10 BROAD ST SEATTLE WA 98121	WSW	0.19 / 1,017.60	-90	426
74	VCP	Elliott & Broad	10 BROAD ST SEATTLE WA 98121	WSW	0.19 / 1,017.60	-90	427
75	RCRA NON GEN	2ND AVE BELL DRUMS	2408 2ND AVE SEATTLE WA 98121 ***EPA Handler ID:*** WAD981770233	ESE	0.19 / 1,017.98	9	428
75	ALL SITES	2nd Ave Bell Drums	2408 2ND AVE SEATTLE WA 98121	ESE	0.19 / 1,017.98	9	430
76	DRYCLEANERS	A 1 Laundry Inc	2401 1st Ave Seattle WA 98121	SE	0.19 / 1,026.78	-2	430
76	ALL SITES	A 1 Laundry Inc	2401 1st Ave Seattle WA 98121	SE	0.19 / 1,026.78	-2	431
76	RCRA NON GEN	A 1 LAUNDRY INC	2401 1ST AVE SEATTLE WA 98121 ***EPA Handler ID:*** WAH000049635	SE	0.19 / 1,026.78	-2	431

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
76	FED DRYCLEANERS	A 1 LAUNDRY INC	2401 1ST AVE SEATTLE WA 98121 ***FRS Facility ID:*** 110064832061	SE	0.19 / 1,026.78	-2	434
77	RCRA NON GEN	FAT CITY INC	508 DENNY WAY SEATTLE WA 98109 ***EPA Handler ID:*** WAD988513578	ENE	0.20 / 1,062.07	22	434
77	ALL SITES	Fat City Inc	508 DENNY WAY SEATTLE WA 98109-5009	ENE	0.20 / 1,062.07	22	440
78	RCRA NON GEN	TRIAD VINE & ELLIOT LLC	10 WALL ST SEATTLE WA 98121 ***EPA Handler ID:*** WAH000013706	S	0.20 / 1,063.52	-70	440
78	ALL SITES	Triad Vine & Elliot LLC	10 WALL ST SEATTLE WA 98121	S	0.20 / 1,063.52	-70	444
79	ALL SITES	FISHER PLAZA	140 4TH AVE N SEATTLE WA 98109	NE	0.21 / 1,095.97	25	445
80	RCRA NON GEN	PARSON SEATRUST PARTNERSHIP	400 WALL ST SEATTLE WA 98121 ***EPA Handler ID:*** WA0000100503	E	0.21 / 1,099.70	18	446
80	CSCSL NFA	Parson Seatrust Partnership	400 WALL ST SEATTLE WA 98121	E	0.21 / 1,099.70	18	450
80	UST	KEY LOCK PARKING LOT	400 WALL ST Seattle WA 98109 ***UST ID | Site Active:*** 102119 | No ***Tank Name | Tank Status:*** 2 | Removed, 1 | Removed, 3 | Removed, 4 | Removed	E	0.21 / 1,099.70	18	451
80	ALL SITES	Parson Seatrust Partnership	400 WALL ST SEATTLE WA 98121	E	0.21 / 1,099.70	18	453
80	ICR	Parson Seatrust Partnership	400 WALL ST SEATTLE WA 98121	E	0.21 / 1,099.70	18	454
80	LUST	Parson Seatrust Partnership	400 WALL ST SEATTLE WA 98121 ***Facility Site ID:*** 2543	E	0.21 / 1,099.70	18	456
81	UST SEATTLE		2466 4TH AVE Seattle WA 98103 ***Permit No | Date Issued:*** 3-43047 | 06/25/2002	E	0.21 / 1,111.03	17	457

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
82	RCRA NON GEN	GRAPHICOLOR INC	3018 WESTERN AVE SEATTLE WA 98121-1023 ***EPA Handler ID:*** WAD094627460	W	0.21 / 1,117.79	-60	457
82	INST	Graphicolor Inc	3018 WESTERN AVE SEATTLE WA 98121	W	0.21 / 1,117.79	-60	459
82	CSCSL	Graphicolor Inc	3018 WESTERN AVE SEATTLE WA 98121	W	0.21 / 1,117.79	-60	460
82	UST	GRAPHICOLOR INC	3018 WESTERN AVE Seattle WA 98121 ***UST ID | Site Active:*** 6604 | No ***Tank Name | Tank Status:*** 1 | Closed in Place	W	0.21 / 1,117.79	-60	460
82	ALL SITES	Graphicolor Inc	3018 WESTERN AVE SEATTLE WA 98121-1023	W	0.21 / 1,117.79	-60	461
82	LUST	Graphicolor Inc	3018 WESTERN AVE SEATTLE WA 98121 ***Facility Site ID:*** 23682319	W	0.21 / 1,117.79	-60	462
82	ICR	Graphicolor Inc	3018 WESTERN AVE SEATTLE WA 98121-1023	W	0.21 / 1,117.79	-60	463
82	VCP	Graphicolor Inc	3018 WESTERN AVE SEATTLE WA 98121	W	0.21 / 1,117.79	-60	464
83	ALL SITES	Faulkenbury Wright	501 DENNY WAY SEATTLE WA 98109	ENE	0.21 / 1,118.54	20	465
83	DRYCLEANERS	Faulkenbury Wright	501 DENNY WAY SEATTLE WA 98109	ENE	0.21 / 1,118.54	20	466
83	FED DRYCLEANERS	FAULKENBURY AND WRIGHT DRYCLEANERS	501 DENNY WAY SEATTLE WA 98109 ***FRS Facility ID:*** 110005327976	ENE	0.21 / 1,118.54	20	467
83	CSCSL	Faulkenbury & Wright	501 DENNY WAY SEATTLE WA 98109	ENE	0.21 / 1,118.54	20	467
83	RCRA LQG	FAULKENBURY AND WRIGHT DRYCLEANERS	501 DENNY WAY SEATTLE WA 98109 ***EPA Handler ID:*** WAD085811768	ENE	0.21 / 1,118.54	20	467
84	RCRA NON GEN	HAWAIIAN MARINE LINES INC	2401 4TH AVE SEATTLE WA 98121	E	0.21 / 1,118.74	15	478

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			EPA Handler ID: WAD991281916				
84	RCRA VSQG	LIFESPAN BIOSCIENCES	2401 4TH AVE 12TH FLOOR SEATTLE WA 98121 ***EPA Handler ID:*** WAH000017913	E	0.21 / 1,118.74	15	480
84	ALL SITES	Lifespan Biosciences	2401 4TH AVE 12TH FLOOR SEATTLE WA 98121	E	0.21 / 1,118.74	15	492
84	ALL SITES	Hawaiian Marine Lines Inc	2401 4TH AVE SEATTLE WA 98121	E	0.21 / 1,118.74	15	493
84	PCB	PACIFIC ALASKA LINES WEST	2401 4 AVE SEATTLE WA 98121 ***Site ID:*** WAD044592384	E	0.21 / 1,118.74	15	493
84	PCB	HAWAIIAN MARINE LINES	2401 4TH AVE SEATTLE WA 98121 ***Site ID:*** WAD991281916	E	0.21 / 1,118.74	15	493
84	PCB	CROWLEY MARINE SERVICES	2401 4TH AVE SEATTLE WA 98121 ***Site ID:*** WAD008958027	E	0.21 / 1,118.74	15	494
85	RCRA NON GEN	UNOCAL MARKETING TERMINAL NO TM0724	3001 ELLIOTT AVE SEATTLE WA 98121 ***EPA Handler ID:*** WAD988497624	W	0.21 / 1,121.65	-83	494
85	ALL SITES	Unocal Marketing Terminal No TM0724	3001 ELLIOTT AVE SEATTLE WA 98121	W	0.21 / 1,121.65	-83	497
86	ICR	Champion-Teutsch Property	124 DENNY WAY SEATTLE WA 98109	WNW	0.22 / 1,143.70	-21	498
86	ALL SITES	Champion Teutsch Property	124 DENNY WAY SEATTLE WA 98109	WNW	0.22 / 1,143.70	-21	499
86	CSCSL	Champion-Teutsch	124 DENNY WAY SEATTLE WA 98109	WNW	0.22 / 1,143.70	-21	500
86	VCP	Champion-Teutsch	124 DENNY WAY SEATTLE WA 98109	WNW	0.22 / 1,143.70	-21	501
87	UST	303 Battery	303 Battery St Seattle WA 98121	ESE	0.22 / 1,151.76	16	502

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			***UST ID	Site Active:*** 620513 | No ***Tank Name	Tank Status:*** 1 | Removed			
87	ALL SITES	303 Battery	303 BATTERY ST SEATTLE WA 98121	ESE	0.22 / 1,151.76	16	503
87	CSCSL NFA	303 Battery	303 BATTERY ST SEATTLE WA 98121	ESE	0.22 / 1,151.76	16	504
88	ALL SITES	Denny & Warren Petrol Plume	101 DENNY WAY SEATTLE WA 98109	WNW	0.22 / 1,162.18	-23	505
88	CSCSL	Denny & Warren Petrol Plume	101 DENNY WAY SEATTLE WA 98109	WNW	0.22 / 1,162.18	-23	505
89	UST SEATTLE		2434 4TH AVE Seattle WA 98119 ***Permit No	Date Issued:*** 3-43775 | 08/12/2002	E	0.22 / 1,169.61	17	506
90	RCRA NON GEN	PACIFIC SCIENCE CENTER	200 2ND AVE N SEATTLE WA 98109 ***EPA Handler ID:*** WAH000019513	NW	0.22 / 1,184.23	33	506
90	UST	Pacific Science Center	200 2ND AVE N Seattle WA 98109 ***UST ID	Site Active:*** 619795 | No ***Tank Name	Tank Status:*** 1 | Removed	NW	0.22 / 1,184.23	33	513
90	ALL SITES	Pacific Science Center	200 2ND AVE N SEATTLE WA 98109	NW	0.22 / 1,184.23	33	514
90	LUST	Pacific Science Center UST Denny & Broad	200 2ND AVE N SEATTLE WA 98109 ***Facility Site ID:*** 2868852	NW	0.22 / 1,184.23	33	515
90	CSCSL	Pacific Science Center UST Denny & Broad	200 2ND AVE N SEATTLE WA 98109	NW	0.22 / 1,184.23	33	515
90	ICR	Pacific Science Center UST Denny & Broad	200 2ND AVE N SEATTLE WA 98109	NW	0.22 / 1,184.23	33	516
90	ALT FUELS	DC CORRIDOR PAC SCI L2	200 2nd Ave N Seattle WA 98109 ***ID:*** 104286	NW	0.22 / 1,184.23	33	517
90	ALT FUELS	DC CORRIDOR PAC SCI CENTER	200 2nd Ave N Seattle WA 98109	NW	0.22 / 1,184.23	33	517

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			ID: 173491				
90	ALT FUELS	DC CORRIDOR PAC SCI DC2	200 2nd Ave N Seattle WA 98109 ***ID:*** 173492	NW	0.22 / 1,184.23	33	518
91	UST SEATTLE		2552 5TH AVE Seattle WA 98109 ***Permit No	Date Issued:*** 3-46039	02/27/2003	ENE	0.23 / 1,188.92	19	518
92	DELISTED SHWS	303 Battery	2330 3RD AVE SEATTLE WA	ESE	0.23 / 1,200.38	16	519
92	LUST PTAP	303 Battery	2330 3rd Avenue, Seattle, WA WA	ESE	0.23 / 1,200.38	16	519
93	RCRA NON GEN	HOLMAN BODY & FENDER	2324 2ND AVE SEATTLE WA 98121 ***EPA Handler ID:*** WAD062788161	ESE	0.23 / 1,201.53	14	519
93	CSCSL	Holman Body & Fender	2324 2ND AVE SEATTLE WA 98121	ESE	0.23 / 1,201.53	14	523
93	HSL	Holman Body & Fender	2324 2ND AVE SEATTLE WA 98121	ESE	0.23 / 1,201.53	14	524
93	UST	HOLMAN BODY AND FENDER	2324 2ND AVE Seattle WA 98121 ***UST ID	Site Active:*** 323980	No ***Tank Name	Tank Status:*** 1	Removed	ESE	0.23 / 1,201.53	14	525
93	ALL SITES	Holman Body & Fender	2324 2ND AVE SEATTLE WA 98121	ESE	0.23 / 1,201.53	14	526
93	LUST	Holman Body & Fender	2324 2ND AVE SEATTLE WA 98121 ***Facility Site ID:*** 33457373	ESE	0.23 / 1,201.53	14	527
93	ICR	HOLMAN BODY & FENDER	2324 2ND AVE SEATTLE WA 98121	ESE	0.23 / 1,201.53	14	528
94	CSCSL NFA	Fountain Court Apartments	2400 4TH AVE SEATTLE WA 98121	E	0.23 / 1,216.71	18	529
94	ALL SITES	FOUNTAIN COURT APARTMENTS	2400 4TH AVE SEATTLE WA 98121	E	0.23 / 1,216.71	18	530

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
94	ICR	FOUNTAIN COURT APARTMENTS	2400 4TH AVE SEATTLE WA 98121	E	0.23 / 1,216.71	18	530
94	VCP	Fountain Court Apartments	2400 4TH AVE SEATTLE WA 98121	E	0.23 / 1,216.71	18	531
95	CSCSL	Da Li 5th Avenue Development	124 - 130 5TH AVE N SEATTLE WA 98109	NE	0.23 / 1,217.55	23	532
95	VCP	Da Li 5th Avenue Development	124 - 130 5TH AVE N SEATTLE WA 98109	NE	0.23 / 1,217.55	23	533
95	ALL SITES	Da Li 5th Avenue Development	124 - 130 5TH AVE N SEATTLE WA 98109	NE	0.23 / 1,217.55	23	535
96	UST	WRIGHT GROUP	65 BAY ST Seattle WA 98121 ***UST ID | Site Active:*** 9847 | No ***Tank Name | Tank Status:*** 1 | Removed	WNW	0.23 / 1,228.08	-35	535
96	ALL SITES	CONSTRUCTION SITE	65 BAY ST SEATTLE WA 98121-1015	WNW	0.23 / 1,228.08	-35	536
97	ALL SITES	AT&T WIRELESS PIER 70	2815 ALASKAN WAY SEATTLE WA 98121	WSW	0.23 / 1,240.49	-97	536
98	UST	GROSVENOR HOUSE	505 VINE ST Seattle WA 98121 ***UST ID | Site Active:*** 97226 | No ***Tank Name | Tank Status:*** TANK #2 | Removed, WASTEOIL | Removed, TANK #1 | Removed	ENE	0.24 / 1,250.63	19	537
98	ALL SITES	GROSVENOR HOUSE VINE ST	505 VINE ST SEATTLE WA 98121-1508	ENE	0.24 / 1,250.63	19	539
99	ALL SITES	CLIPPER NAVIGATION ELLIOTT BAY	WA	SW	0.24 / 1,254.28	-97	539
100	RCRA NON GEN	ARCTIC MARINE FREIGHTERS	4TH & BATTERY SEATTLE WA 98111 ***EPA Handler ID:*** WAD980738009	E	0.24 / 1,255.55	18	540
100	ALL SITES	Arctic Marine Freighters	4TH & BATTERY SEATTLE WA 98111	E	0.24 / 1,255.55	18	542

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
101	ALL SITES	PORT OF SEATTLE PIER 69	PIER 69 SEATTLE WA 98111	SW	0.24 / 1,268.67	-96	542
101	ALL SITES	Seattle Port Pier 69	2711 ALASKAN WAY SEATTLE WA 98121	SW	0.24 / 1,268.67	-96	543
101	RCRA NON GEN	SEATTLE PORT PIER 69	2711 ALASKAN WAY SEATTLE WA 98121 ***EPA Handler ID:*** WAD988519229	SW	0.24 / 1,268.67	-96	544
102	CSCSL NFA	Ivars Seafood Bar	3101 1ST AVE SEATTLE WA 98121	WNW	0.24 / 1,268.70	-30	556
102	ALL SITES	IVARS SEAFOOD BAR	3101 1ST AVE SEATTLE WA 98121-1051	WNW	0.24 / 1,268.70	-30	557
102	ICR	IVARS SEAFOOD BAR	3101 1ST AVE SEATTLE WA 98121-1051	WNW	0.24 / 1,268.70	-30	558
102	VCP	Ivars Seafood Bar	3101 1ST AVE SEATTLE WA 98121	WNW	0.24 / 1,268.70	-30	559
103	RCRA NON GEN	PRIME CYTE INC	130 5TH AVE N SEATTLE WA 98109 ***EPA Handler ID:*** WAH000003616	NE	0.24 / 1,273.55	21	560
103	ALL SITES	Prime Cyte Inc	130 5TH AVE N SEATTLE WA 98109	NE	0.24 / 1,273.55	21	566
104	CSCSL	Taylor & Denny Building	101 TAYLOR AVE N SEATTLE WA 98109	ENE	0.24 / 1,275.61	20	566
104	ALL SITES	Taylor and Denny New Building	101 TAYLOR AVE N SEATTLE WA 98109	ENE	0.24 / 1,275.61	20	568
104	ICR	Taylor & Denny Building	101 TAYLOR AVE N SEATTLE WA 98109	ENE	0.24 / 1,275.61	20	569
104	VCP	Taylor & Denny Building	101 TAYLOR AVE N SEATTLE WA 98109	ENE	0.24 / 1,275.61	20	570

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
104	ALT FUELS	The Century Apartments - Residential Parking	101 Taylor Ave N Seattle WA 98109 ***ID:*** 193830	ENE	0.24 / 1,275.61	20	572
104	ALT FUELS	The Century Apartments - Retail Parking	101 Taylor Ave N Seattle WA 98109 ***ID:*** 193780	ENE	0.24 / 1,275.61	20	572
105	RCRA NON GEN	GROSVENOR HOUSE	500 WALL ST STE 100 SEATTLE WA 98121 ***EPA Handler ID:*** WAD135034577	ENE	0.24 / 1,284.97	18	573
105	CSCSL	Archstone Belltown	500 WALL ST SEATTLE WA 98121	ENE	0.24 / 1,284.97	18	575
105	ALL SITES	Grosvenor House	500 WALL ST STE 100 SEATTLE WA 98121	ENE	0.24 / 1,284.97	18	575
105	ALL SITES	Archstone Belltown	500 WALL ST SEATTLE WA 98121	ENE	0.24 / 1,284.97	18	576
105	ICR	Archstone Belltown	500 WALL ST SEATTLE WA 98121	ENE	0.24 / 1,284.97	18	577
105	VCP	Archstone Belltown	500 WALL ST SEATTLE WA 98121	ENE	0.24 / 1,284.97	18	578
106	CSCSL	Fifth & Broad	417 BROAD ST SEATTLE WA 98109	NE	0.25 / 1,304.95	26	579
106	UST	Fifth and Broad Property	417 BROAD ST Seattle WA 98109 ***UST ID | Site Active:*** 620081 | No ***Tank Name | Tank Status:*** 1 | Unknown, 3 | Unknown, 5 | Unknown, 6 | Unknown, 2 | Unknown, 4 | Unknown	NE	0.25 / 1,304.95	26	580
106	ALL SITES	Fifth & Broad Property	417 BROAD ST SEATTLE WA 98109	NE	0.25 / 1,304.95	26	584
106	LUST	Fifth & Broad	417 BROAD ST SEATTLE WA 98109 ***Facility Site ID:*** 21907	NE	0.25 / 1,304.95	26	585
106	ICR	Fifth and Broad Property	417 BROAD ST SEATTLE WA 98109	NE	0.25 / 1,304.95	26	586

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
106	RCRA NON GEN	1221 DENNY LLC	417 BROAD ST SEATTLE WA 98109 ***EPA Handler ID:*** WAH000044432	NE	0.25 / 1,304.95	26	588
106	INST	Fifth & Broad	417 BROAD ST SEATTLE WA 98109	NE	0.25 / 1,304.95	26	590
106	VCP	Fifth & Broad	417 BROAD ST SEATTLE WA 98109	NE	0.25 / 1,304.95	26	591
107	RCRA NON GEN	EDGEWATER HOTEL	2411 ALASKAN WAY PIER 67 SEATTLE WA 98121 ***EPA Handler ID:*** WAH000037063	SSW	0.25 / 1,306.08	-96	593
107	ALL SITES	Edgewater Hotel	2411 Alaskan Way Pier 67 Seattle WA 98121	SSW	0.25 / 1,306.08	-96	596
108	UST SEATTLE		2459 5TH AVE Seattle WA 98199 ***Permit No | Date Issued:*** 3-34092 | 09/07/2000	E	0.25 / 1,309.94	18	596
109	ICR	Interbay Redevelopment Property	15TH AVE W SEATTLE WA 98119	SE	0.26 / 1,350.86	5	597
110	CSCSL	Seattle Fire Station 2	2334 4TH AVE SEATTLE WA 98121	E	0.26 / 1,354.65	20	598
110	ALL SITES	SEATTLE FIRE STATION 2	2334 4TH AVE SEATTLE WA 98121	E	0.26 / 1,354.65	20	599
110	LUST	Seattle Fire Station 2	2334 4TH AVE SEATTLE WA 98121 ***Facility Site ID:*** 29958424	E	0.26 / 1,354.65	20	600
110	ICR	SEATTLE FIRE STATION 2	2334 4TH AVE SEATTLE WA 98121-1718	E	0.26 / 1,354.65	20	600
110	ALL SITES	Seattle Fire Station 2 4th Ave	2334 4TH AVE SEATTLE WA 98121	E	0.26 / 1,354.65	20	601
111	CSCSL NFA	Valco Graphics Inc Western Ave	3104 WESTERN AVE SEATTLE WA 98121	WNW	0.26 / 1,367.35	-52	602

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
111	ALL SITES	Valco Graphics Inc Western Ave	3104 WESTERN AVE SEATTLE WA 98121	WNW	0.26 / 1,367.35	-52	602
111	ICR	Valco Graphics Inc Western Ave	3104 WESTERN AVE SEATTLE WA 98121	WNW	0.26 / 1,367.35	-52	603
111	VCP	Valco Graphics Inc Western Ave	3104 WESTERN AVE SEATTLE WA 98121	WNW	0.26 / 1,367.35	-52	605
111	LUST	Valco Graphics Inc Western Ave	3104 WESTERN AVE SEATTLE WA 98121 ***Facility Site ID:*** 19521513	WNW	0.26 / 1,367.35	-52	606
112	CSCSL	Second & Bell Building LLC	2306 2ND AVE SEATTLE WA 98121	ESE	0.26 / 1,379.92	18	606
112	ALL SITES	Second & Bell Building LLC	2306 2ND AVE SEATTLE WA 98121	ESE	0.26 / 1,379.92	18	608
112	ICR	Second & Bell Building LLC	2306 2ND AVE SEATTLE WA 98121	ESE	0.26 / 1,379.92	18	609
112	VCP	Second & Bell Building LLC	2306 2ND AVE SEATTLE WA 98121	ESE	0.26 / 1,379.92	18	611
113	ALL SITES	Seattle Fire Dept Sta	2318 4TH AVE SEATTLE WA 98121	E	0.26 / 1,391.92	20	612
114	CERCLIS	SEATTLE POST INTELLIGENCER	521 WALL ST SEATTLE WA 98121 ***Site EPA ID:*** WAD001533538	E	0.27 / 1,408.52	18	612
114	CERCLIS NFRAP	SEATTLE POST INTELLIGENCER	521 WALL ST SEATTLE WA 98121 ***Site EPA ID:*** WAD001533538	E	0.27 / 1,408.52	18	614
114	CSCSL NFA	Seattle Post Intelligencer	521 WALL ST SEATTLE WA 98121	E	0.27 / 1,408.52	18	615
114	ALL SITES	SEATTLE POST INTELLIGENCER	521 WALL ST SEATTLE WA 98121	E	0.27 / 1,408.52	18	615

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
114	ICR	SEATTLE POST INTELLIGENCER	521 WALL ST SEATTLE WA 98121	E	0.27 / 1,408.52	18	616
114	SEMS ARCHIVE	SEATTLE POST INTELLIGENCER	521 WALL ST SEATTLE WA 98121 ***EPA ID:*** WAD001533538	E	0.27 / 1,408.52	18	617
115	ALL SITES	AIRBORNE EXPRESS	3101 WESTERN AVE SEATTLE WA 98121	WNW	0.27 / 1,410.34	-50	617
115	PCB	3101 WESTERN	3101 WESTERN AVE SEATTLE WA 98121 ***Site ID:*** WAW000200600	WNW	0.27 / 1,410.34	-50	618
115	ALL SITES	Invitae Seattle	3101 Western Ave Ste 100 Seattle WA 98121	WNW	0.27 / 1,410.34	-50	618
116	CSCSL NFA	55 Battery LLC	2334 ELLIOTT AVE / 55 BATTERY ST SEATTLE WA 98121	SSE	0.27 / 1,411.12	-60	618
116	ALL SITES	Pinnacle Productions International Inc	2334 ELLIOTT AVE / 55 BATTERY ST SEATTLE WA 98121	SSE	0.27 / 1,411.12	-60	619
116	ICR	55 Battery LLC	2334 ELLIOTT AVE / 55 BATTERY ST SEATTLE WA 98121	SSE	0.27 / 1,411.12	-60	621
116	VCP	55 Battery LLC	2334 ELLIOTT AVE / 55 BATTERY ST SEATTLE WA 98121	SSE	0.27 / 1,411.12	-60	623
116	LUST	55 Battery LLC	2334 ELLIOTT AVE / 55 BATTERY ST SEATTLE WA 98121 ***Facility Site ID:*** 16772747	SSE	0.27 / 1,411.12	-60	624
117	CSCSL NFA	BRE Properties Inc	552 DENNY WAY & 553 JOHN ST SEATTLE WA 98109	ENE	0.27 / 1,415.34	18	625
117	ALL SITES	BRE Properties Inc	552 DENNY WAY & 553 JOHN ST SEATTLE WA 98109	ENE	0.27 / 1,415.34	18	625
117	ICR	BRE Properties Inc	552 DENNY WAY & 553 JOHN ST SEATTLE WA 98109	ENE	0.27 / 1,415.34	18	626

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
117	VCP	BRE Properties Inc	552 DENNY WAY & 553 JOHN ST SEATTLE WA 98109	ENE	0.27 / 1,415.34	18	627
117	RCRA TSD	BRE PROPERTIES INC	552 DENNY WAY & 553 JOHN ST SEATTLE WA 98109 ***EPA Handler ID:*** WAH000029059	ENE	0.27 / 1,415.34	18	628
118	ALL SITES	VERIZON WIRELESS BATTERY STREET TUNNEL	2315 WESTERN AVE SEATTLE WA 98121	SE	0.27 / 1,417.61	-26	633
119	CSCSL	Unocal Elliott Ave N of Bay St GW Plume	ELLIOTT AVE & BAY ST NEC SEATTLE WA 98121	W	0.27 / 1,449.04	-79	633
119	ALL SITES	UNOCAL ELLIOTT AVE N OF BAY ST	ELLIOTT AVE & BAY ST NEC SEATTLE WA 98121	W	0.27 / 1,449.04	-79	635
119	ICR	UNOCAL ELLIOTT AVE N OF BAY ST GW PLUME	ELLIOTT AVE & BAY ST NEC SEATTLE WA 98121	W	0.27 / 1,449.04	-79	635
120	ALL SITES	Ride the Ducks	516 BROAD ST SEATTLE WA 98109	NE	0.28 / 1,479.78	15	637
120	CSCSL	Ride the Ducks	516 BROAD ST SEATTLE WA 98109	NE	0.28 / 1,479.78	15	637
121	ALL SITES	WA DOT Alaskan Way Viaduct Project	ALASKAN WAY VIADUCT MP 28.61 TO 33.8 SEATTLE WA 98104	S	0.28 / 1,491.62	-96	638
122	SWF/LF	Konankada Inc., dba: Seattle Micro	2310 4th Ave Seattle WA 98121-1718	E	0.28 / 1,503.26	22	640
123	ALL SITES	Bell Street Park	WA	SE	0.29 / 1,505.52	8	640
124	ALL SITES	Import Doctors	211 BELL ST SEATTLE WA 98121-1715	ESE	0.29 / 1,511.98	23	641
125	ALL SITES	Symetrix Inc Seattle	109 BELL ST SEATTLE WA 98121	SE	0.29 / 1,513.98	11	641

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
126	ALL SITES	4th and Bell Seattle	2306 4th Ave Seattle WA 98121	E	0.29 / 1,517.85	22	642
127	CSCSL NFA	Shell Station 121702	10 DENNY WAY SEATTLE WA 98109	WNW	0.29 / 1,552.46	-37	642
127	ALL SITES	Shell Station 121702	10 DENNY WAY SEATTLE WA 98109	WNW	0.29 / 1,552.46	-37	644
127	ICR	Shell Station 121702	10 DENNY WAY SEATTLE WA 98109	WNW	0.29 / 1,552.46	-37	646
127	VCP	Shell Station 121702	10 DENNY WAY SEATTLE WA 98109	WNW	0.29 / 1,552.46	-37	653
127	LUST	Shell Station 121702	10 DENNY WAY SEATTLE WA 98109 ***Facility Site ID:*** 49674295	WNW	0.29 / 1,552.46	-37	654
128	CSCSL NFA	First & Bell	2233 1ST AVE SEATTLE WA 98121	SE	0.30 / 1,573.67	8	655
128	ALL SITES	First & Bell	2233 1ST AVE SEATTLE WA 98121	SE	0.30 / 1,573.67	8	655
128	ICR	First & Bell	2233 1ST AVE SEATTLE WA 98121	SE	0.30 / 1,573.67	8	656
128	VCP	First & Bell	2233 1ST AVE SEATTLE WA 98121	SE	0.30 / 1,573.67	8	657
129	CSCSL NFA	Japanese Auto Clinic	600 DENNY WAY SEATTLE WA 98109	ENE	0.30 / 1,583.60	14	658
129	ALL SITES	Japanese Auto Clinic	600 DENNY WAY SEATTLE WA 98109	ENE	0.30 / 1,583.60	14	659
129	ICR	Japanese Auto Clinic	600 DENNY WAY SEATTLE WA 98109	ENE	0.30 / 1,583.60	14	660

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
129	VCP	Japanese Auto Clinic	600 DENNY WAY SEATTLE WA 98109	ENE	0.30 / 1,583.60	14	662
129	LUST	Japanese Auto Clinic	600 DENNY WAY SEATTLE WA 98109 ***Facility Site ID:*** 84772579	ENE	0.30 / 1,583.60	14	664
129	CSCSL	Japanese Auto Clinic	600 DENNY WAY SEATTLE WA 98109	ENE	0.30 / 1,583.60	14	665
130	ALL SITES	Wilson Engraving Co Inc	314 BELL ST SEATTLE WA 98121	ESE	0.30 / 1,586.57	24	666
131	ALL SITES	Belltown Lofts	66 BELL ST SEATTLE WA 98101	SE	0.30 / 1,601.47	-32	666
132	CSCSL	600 Wall Street	600 WALL ST SEATTLE WA 98121	ENE	0.30 / 1,607.90	13	667
132	ALL SITES	600 wall street	600 WALL ST SEATTLE WA 98121	ENE	0.30 / 1,607.90	13	668
132	ICR	600 wall street	600 WALL ST SEATTLE WA 98121	ENE	0.30 / 1,607.90	13	668
132	VCP	600 Wall Street	600 WALL ST SEATTLE WA 98121	ENE	0.30 / 1,607.90	13	669
132	LUST PTAP	600 Wall Street	600 Wall Street,Seattle, WA 98121 WA	ENE	0.30 / 1,607.90	13	670
133	ALL SITES	Consolidated Press Printing Co	2228 1ST AVE SEATTLE WA 98121	SE	0.31 / 1,612.73	11	670
134	ALL SITES	Edelstein Assoc Advertising BE	50 BELL ST SEATTLE WA 98121	SE	0.31 / 1,619.72	-35	671
135	CSCSL	Phom Property	2301 4th Ave / 314 Bell St SEATTLE WA 98121	E	0.31 / 1,620.12	23	671
135	HSL	Phom Property	2301 4th Ave / 314 Bell St SEATTLE WA 98121	E	0.31 / 1,620.12	23	673

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
135	ALL SITES	PHOM PROPERTY	2301 4th Ave / 314 Bell St SEATTLE WA 98121	E	0.31 / 1,620.12	23	673
135	LUST	Phom Property	2301 4th Ave / 314 Bell St SEATTLE WA 98121 ***Facility Site ID:*** 47763267	E	0.31 / 1,620.12	23	674
135	ICR	PHOM PROPERTY	2301 4th Ave / 314 Bell St SEATTLE WA 98121	E	0.31 / 1,620.12	23	675
136	ALL SITES	The Belltown Collective LLC	2231 1st Ave Seattle WA 98121	SE	0.31 / 1,637.74	12	677
137	ALL SITES	LEVEL 3 COMMUNICATIONS SEATTLE STTLWATTA	223 TAYLOR AVE N SEATTLE WA 98109	NE	0.32 / 1,665.56	12	677
138	CSCSL NFA	Stadium Shell	620 DENNY WAY SEATTLE WA 98109	ENE	0.32 / 1,701.58	12	678
138	ALL SITES	DENNY WAY SHELL	620 DENNY WAY SEATTLE WA 98109	ENE	0.32 / 1,701.58	12	678
138	ICR	WRIGHTS RESTAURANT	620 DENNY WAY SEATTLE WA 98109	ENE	0.32 / 1,701.58	12	679
138	LUST	Stadium Shell	620 DENNY WAY SEATTLE WA 98109 ***Facility Site ID:*** 41751629	ENE	0.32 / 1,701.58	12	680
139	ALL SITES	UNOCAL STATEWIDE LISTING	3131 ELLIOTT AVE SEATTLE WA 98121	W	0.33 / 1,758.53	-78	680
140	ALL SITES	3rd Ave Redevelopment	2211 2217 3RD AVE SEATTLE WA 98121	ESE	0.33 / 1,762.15	29	681
140	VCP	3rd Ave Redevelopment	2211 2217 3RD AVE SEATTLE WA 98121	ESE	0.33 / 1,762.15	29	682
140	CSCSL NFA	3rd Ave Redevelopment	2211 2217 3RD AVE SEATTLE WA 98121	ESE	0.33 / 1,762.15	29	683

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
141	DELISTED SHWS	3rd Ave Redevelopment	2211 2217 3RD AVE SEATTLE WA 98121	ESE	0.34 / 1,779.72	27	684
141	ICR	3rd Ave Redevelopment	2211 2217 3RD AVE SEATTLE WA 98121	ESE	0.34 / 1,779.72	27	684
142	CSCSL NFA	133 Queen Anne Property	133 QUEEN ANNE AVE N SEATTLE WA 98109	WNW	0.34 / 1,790.09	-26	685
142	ALL SITES	133 Queen Anne Ave N Property	133 QUEEN ANNE AVE N SEATTLE WA 98109	WNW	0.34 / 1,790.09	-26	686
142	ICR	133 Queen Anne Property	133 QUEEN ANNE AVE N SEATTLE WA 98109	WNW	0.34 / 1,790.09	-26	687
142	VCP	133 Queen Anne Property	133 QUEEN ANNE AVE N SEATTLE WA 98109	WNW	0.34 / 1,790.09	-26	688
142	LUST	133 Queen Anne Property	133 QUEEN ANNE AVE N SEATTLE WA 98109 ***Facility Site ID:*** 95244754	WNW	0.34 / 1,790.09	-26	688
143	ALL SITES	Hauge & Hassain Inc	207 6TH AVE N SEATTLE WA 98109	ENE	0.34 / 1,790.74	9	689
144	CSCSL NFA	Barrat Transfer & Storage	123 QUEEN ANNE AVE N SEATTLE WA 98109	WNW	0.34 / 1,817.77	-32	689
144	ALL SITES	BARRAT TRANSFER & STORAGE CO	123 QUEEN ANNE AVE N SEATTLE WA 98109	WNW	0.34 / 1,817.77	-32	691
144	ICR	Barrat Transfer & Storage	123 QUEEN ANNE AVE N SEATTLE WA 98109	WNW	0.34 / 1,817.77	-32	691
144	LUST	Barrat Transfer & Storage	123 QUEEN ANNE AVE N SEATTLE WA 98109 ***Facility Site ID:*** 83727198	WNW	0.34 / 1,817.77	-32	693
145	ALL SITES	WA UW 2211 Elliott Ave	2211 ELLIOTT AVE SEATTLE WA 98101	SSE	0.35 / 1,837.12	-44	694

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
145	ALL SITES	Stratos Genomics	2211 Elliott Ave Ste 210 Seattle WA 98121	SSE	0.35 / 1,837.12	-44	695
146	ALL SITES	Graphics West Typeline	217 6TH AVE N SEATTLE WA 98109	ENE	0.35 / 1,846.67	7	695
147	ALL SITES	Frederick Cadillac	2301 6TH AVE SEATTLE WA 98121	E	0.35 / 1,848.07	12	696
148	CSCSL	Port of Seattle Pier 66	2201 ALASKAN WAY TERM 66 PIERCE MARINE SEATTLE WA 98121	SSE	0.35 / 1,851.81	-93	697
149	ALL SITES	Seattle Port Term 66	2201 ALASKAN WAY TERM 66 PIERCE MARINE SEATTLE WA 98121	SSE	0.35 / 1,853.03	-93	700
149	LUST	Port of Seattle Pier 66	2201 ALASKAN WAY TERM 66 PIERCE MARINE SEATTLE WA 98121 ***Facility Site ID:*** 94766722	SSE	0.35 / 1,853.03	-93	701
149	ICR	SEATTLE PORT OF BELL ST PIER 66	2201 ALASKAN WAY TERM 66 PIERCE MARINE SEATTLE WA 98121	SSE	0.35 / 1,853.03	-93	703
150	ALL SITES	ELEPHANT CAR WASH UST 4919	616 BATTERY ST SEATTLE WA 98121-1538	E	0.35 / 1,867.33	11	706
150	DELISTED LST	ELEPHANT CAR WASH	616 BATTERY ST SEATTLE WA 98121-1538	E	0.35 / 1,867.33	11	707
150	CSCSL NFA	Elephant Car Wash	616 Battery St Seattle WA 98121	E	0.35 / 1,867.33	11	707
150	ICR	ELEPHANT CAR WASH	616 BATTERY ST SEATTLE WA 98121-1538	E	0.35 / 1,867.33	11	708
150	VCP	Elephant Car Wash	616 Battery St Seattle WA 98121	E	0.35 / 1,867.33	11	711
150	LUST	Elephant Car Wash	616 Battery St Seattle WA 98121 ***Facility Site ID:*** 66184117	E	0.35 / 1,867.33	11	712

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
151	ALL SITES	2200 Western Avenue LLC	2200 Western Ave Seattle WA 98121	SE	0.36 / 1,875.55	-5	713
151	VCP	2200 Western Avenue LLC	2200 Western Ave Seattle WA 98121	SE	0.36 / 1,875.55	-5	714
151	DELISTED SHWS	2200 Western Avenue LLC	2200 Western Ave Seattle WA 98121	SE	0.36 / 1,875.55	-5	715
151	ICR	2200 Western Avenue LLC	2200 Western Ave Seattle WA 98121	SE	0.36 / 1,875.55	-5	715
151	CSCSL NFA	2200 Western Avenue LLC	2200 Western Ave Seattle WA 98121	SE	0.36 / 1,875.55	-5	718
151	INST	2200 Western Avenue LLC	2200 Western Ave Seattle WA 98121	SE	0.36 / 1,875.55	-5	719
151	CSCSL	2200 Western Avenue LLC	2200 Western Ave Seattle WA 98121	SE	0.36 / 1,875.55	-5	719
152	ALL SITES	Robbins Brothers	2200 1st Ave Seattle WA 98121	SE	0.36 / 1,877.46	19	721
153	ALL SITES	AT&T WIRELESS DEXTER	618 JOHN ST SEATTLE WA 98109	ENE	0.36 / 1,879.54	7	722
154	CSCSL	Lewiston Hotel	2201 1ST AVE SEATTLE WA 98121	SE	0.36 / 1,891.41	18	722
154	HSL	Lewiston Hotel	2201 1ST AVE SEATTLE WA 98121	SE	0.36 / 1,891.41	18	723
154	ALL SITES	LEWISTON HOTEL	2201 1ST AVE SEATTLE WA 98121	SE	0.36 / 1,891.41	18	724
154	ICR	LEWISTON HOTEL	2201 1ST AVE SEATTLE WA 98121	SE	0.36 / 1,891.41	18	725
154	VCP	Lewiston Hotel	2201 1ST AVE SEATTLE WA 98121	SE	0.36 / 1,891.41	18	726

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
155	ALL SITES	VARTEC SEATTLE SWITCH	2308 N 6TH AVE SEATTLE WA 98121	E	0.37 / 1,937.83	10	727
156	ALL SITES	DIAMOND PARKING INC ELLIOTT AVE	3161 ELLIOTT AVE SEATTLE WA 98121-1054	WNW	0.37 / 1,940.90	-80	728
157	ALL SITES	PRECISION TUNE 7TH AVE SEATTLE	2331 7TH AVE SEATTLE WA 98121-1903	E	0.38 / 1,982.00	8	728
158	ALL SITES	United Technologies Otis Elevator Settle	3150 ELLIOT AVE SEATTLE WA 98121	WNW	0.38 / 1,986.02	-78	729
159	ALL SITES	Sterling Engraving Co	2218 5TH AVE E SEATTLE WA 98121-1808	E	0.38 / 1,994.77	14	729
160	ALL SITES	ATT MOBILITY DEXTER	225 AURORA AVE N SEATTLE WA 98109	ENE	0.38 / 2,003.50	3	730
161	ALL SITES	Hebei Ocean Shipping Co Elliott Bay	WA	S	0.38 / 2,022.77	-98	730
161	ALL SITES	TSANGARIS BROS LTD ELLIOTT BAY	WA	S	0.38 / 2,022.77	-98	731
162	ALL SITES	Gem East Corp	2124 2ND AVE SEATTLE WA 98121	ESE	0.39 / 2,047.44	40	731
162	ALL SITES	ATT MOBILITY LENORA & 3RD	2124 2ND AVE SEATTLE WA 98121	ESE	0.39 / 2,047.44	40	732
163	SWF/LF	Action Small Appliance	2125 2nd Ave Seattle WA 98121	ESE	0.39 / 2,049.37	40	732
164	CSCSL	Rexland Co	2126 3RD AVE SEATTLE WA 98121	ESE	0.39 / 2,060.44	33	733
164	ALL SITES	REXLAND CO INC	2126 3RD AVE SEATTLE WA 98121-2306	ESE	0.39 / 2,060.44	33	734

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
164	LUST	Rexland Co	2126 3RD AVE SEATTLE WA 98121 ***Facility Site ID:*** 54147485	ESE	0.39 / 2,060.44	33	734
164	ICR	REXLAND CO	2126 3RD AVE SEATTLE WA 98121-2306	ESE	0.39 / 2,060.44	33	735
165	DELISTED SHWS	Western and Blanchard Property	WA	SE	0.39 / 2,073.47	-8	736
166	FUDS	BELL HARBOR MARINE CRUISE TERMINAL (PIER 66)	SEATTLE WA ***FUDS Property No:*** F10WA0664	SSE	0.39 / 2,073.50	-98	736
167	CSCSL	Basil Lee	505 HARRISON ST SEATTLE WA 98109	NNE	0.39 / 2,077.96	-2	737
167	ALL SITES	BASIL LEE PROPERTY	505 HARRISON ST SEATTLE WA 98109	NNE	0.39 / 2,077.96	-2	737
167	LUST	Basil Lee	505 HARRISON ST SEATTLE WA 98109 ***Facility Site ID:*** 79418734	NNE	0.39 / 2,077.96	-2	738
167	ICR	Basil Lee Property	505 HARRISON ST SEATTLE WA 98109	NNE	0.39 / 2,077.96	-2	739
168	ALL SITES	Anacomp Inc 1st	200 1ST AVE W STE 105 SEATTLE WA 98119-4219	WNW	0.39 / 2,079.33	-34	739
168	ALL SITES	First West Investment Property LLC	200 1ST AVE W ENTIRE BLDG SEATTLE WA 98119	WNW	0.39 / 2,079.33	-34	740
169	ALL SITES	DAVES AUTO ELECTRIC	701 JOHN ST SEATTLE WA 98109	ENE	0.40 / 2,090.19	1	741
170	ICR	Astro Apartments	315 1ST AVE N SEATTLE WA 98109	NW	0.40 / 2,094.96	15	741
170	ALL SITES	Astro Apartments	315 1ST AVE N SEATTLE WA 98109	NW	0.40 / 2,094.96	15	742

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
170	CSCSL	Astro Apartments	315 1ST AVE N SEATTLE WA 98109	NW	0.40 / 2,094.96	15	743
171	VCP	Western and Blanchard Property	2134 Western Ave Seattle WA 98121	SE	0.40 / 2,101.90	-15	743
171	DELISTED SHWS	Western and Blanchard Property	2134 Western Avenue Seattle WA 98121	SE	0.40 / 2,101.90	-15	744
171	ALL SITES	Western and Blanchard Property	2134 Western Ave Seattle WA 98121	SE	0.40 / 2,101.90	-15	744
171	CSCSL NFA	Western and Blanchard Property	2134 Western Ave Seattle WA 98121	SE	0.40 / 2,101.90	-15	745
172	ALL SITES	Seattle Center Arena	334 1st Ave N Seattle WA 98109	NW	0.40 / 2,103.79	20	745
173	ALL SITES	PARKING LOT UST 510091	2120 1ST AVE SEATTLE WA 98121-2103	SE	0.40 / 2,111.73	21	746
174	ALL SITES	SEATTLE CENTER N PARKING GARAGE	516 HARRISON ST SEATTLE WA 98109	NNE	0.40 / 2,112.79	-2	747
175	CSCSL NFA	Bay View Building	129 1ST AVE W SEATTLE WA 98119	WNW	0.40 / 2,119.04	-61	747
175	ALL SITES	BAY VIEW BLDG	129 1ST AVE W SEATTLE WA 98119	WNW	0.40 / 2,119.04	-61	748
175	ICR	BAY VIEW BLDG	129 1ST AVE W SEATTLE WA 98119	WNW	0.40 / 2,119.04	-61	748
175	VCP	Bay View Building	129 1ST AVE W SEATTLE WA 98119	WNW	0.40 / 2,119.04	-61	749
175	INST	Bay View Building	129 1ST AVE W SEATTLE WA 98119	WNW	0.40 / 2,119.04	-61	750

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
176	RECYCLERS	DOWNTOWN PUBLIC HEALTH CENTER	2124 4TH AVE SEATTLE WA 98121	ESE	0.40 / 2,119.38	26	751
177	ALL SITES	Blanchard Plaza	2201 6TH AVE STE 100 SEATTLE WA 98121	E	0.41 / 2,154.31	9	751
177	ALL SITES	WORLDCOM STFAWA	2201 6TH AVE SEATTLE WA 98121	E	0.41 / 2,154.31	9	752
178	ALL SITES	Qualex at Seattle Center	305 HARRISON ST SEATTLE CTR CENTER HOUSE SEATTLE WA 98109	NW	0.41 / 2,157.12	21	752
178	ALL SITES	Seattle Center	305 HARRISON ST SEATTLE WA 98109	NW	0.41 / 2,157.12	21	753
178	ALL SITES	Fun Forest Ride Shop	305 HARRISON ST RIDE SHOP SEATTLE WA 98109	NW	0.41 / 2,157.12	21	755
178	LUST	Seattle Center	305 HARRISON ST SEATTLE WA 98109 ***Facility Site ID:*** 42937592	NW	0.41 / 2,157.12	21	755
178	ICR	SEATTLE CENTER	305 HARRISON ST SEATTLE WA 98109	NW	0.41 / 2,157.12	21	756
178	CSCSL	Seattle Center	305 HARRISON ST SEATTLE WA 98109	NW	0.41 / 2,157.12	21	757
179	ALL SITES	Martin Selig Real Estate Seattle	2118 3RD AVE SEATTLE WA 98121	ESE	0.41 / 2,161.65	37	757
180	CSCSL NFA	Neuffer Construction	5TH & BLANCHARD SEATTLE WA 98121	E	0.41 / 2,176.44	16	758
180	ALL SITES	NEUFFER CONSTRUCTION COMPANY	5TH & BLANCHARD SEATTLE WA 98121	E	0.41 / 2,176.44	16	759
180	ICR	NEUFFER CONSTRUCTION COMPANY	5TH & BLANCHARD SEATTLE WA 98121	E	0.41 / 2,176.44	16	760

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
180	LUST	Neuffer Construction	5TH & BLANCHARD SEATTLE WA 98121 ***Facility Site ID:*** 77948398	E	0.41 / 2,176.44	16	761
181	ALL SITES	Frederick Pontiac Buick	2300 7TH AVE SEATTLE WA 98121	E	0.41 / 2,180.91	2	761
182	ALL SITES	Seattle School Dist 1 Memorial Stad	401 5TH AVE N SEATTLE WA 98109	NNE	0.42 / 2,201.27	-5	762
183	ALL SITES	Verizon Wireless WARE WEST DENNY WAY	101 ELLIOTT AVE W SEATTLE WA 98119	WNW	0.42 / 2,204.43	-82	762
183	ALL SITES	Sabey Corp Seattle	101 ELLIOTT AVE W STE 330 SEATTLE WA 98119	WNW	0.42 / 2,204.43	-82	763
184	ALL SITES	LEE COURT	2133 5TH AVE SEATTLE WA 98121	E	0.42 / 2,217.95	16	763
185	CSCSL	Elliott Bay Bicycles	2114 WESTERN AVE SEATTLE WA 98121	SE	0.42 / 2,219.31	-10	764
185	HSL	Elliott Bay Bicycles	2114 WESTERN AVE SEATTLE WA 98121	SE	0.42 / 2,219.31	-10	765
185	ALL SITES	Elliott Bay Bicycles	2114 WESTERN AVE SEATTLE WA 98121	SE	0.42 / 2,219.31	-10	765
185	ICR	Elliott Bay Bicycles	2114 WESTERN AVE SEATTLE WA 98121	SE	0.42 / 2,219.31	-10	766
186	ALL SITES	Norwegian Cruise Line Elliott Bay	WA	S	0.42 / 2,221.76	-106	767
187	CSCSL	King County Denny Way CSO	3165 ALASKAN WAY SEATTLE WA 98121	WNW	0.42 / 2,236.09	-92	767
187	ALL SITES	King Cnty DOT Metro Waterfront Streetcar	3001 ALASKAN WAY SEATTLE WA 98121	WNW	0.42 / 2,236.09	-92	769

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
187	ALL SITES	King County Denny Way CSO	3165 ALASKAN WAY SEATTLE WA 98121	WNW	0.42 / 2,236.09	-92	769
187	ICR	King County Denny Way CSO	3165 ALASKAN WAY SEATTLE WA 98121	WNW	0.42 / 2,236.09	-92	770
188	CSCSL NFA	OLD BRITISH MOTORCAR	7TH & BELL SEATTLE WA 98121	E	0.42 / 2,236.45	1	771
188	ALL SITES	OLD BRITISH MOTORCAR	7TH & BELL SEATTLE WA 98121	E	0.42 / 2,236.45	1	772
188	ICR	OLD BRITISH MOTORCAR	7TH & BELL SEATTLE WA 98121	E	0.42 / 2,236.45	1	773
188	LUST	OLD BRITISH MOTORCAR	7TH & BELL SEATTLE WA 98121 ***Facility Site ID:*** 47192364	E	0.42 / 2,236.45	1	774
189	ALL SITES	Seattle City Used Oil Collect 7th Ave	2229 7TH AVE SEATTLE WA 98121	E	0.43 / 2,262.08	1	775
190	ALL SITES	Seattle City Broad St Substation	319 6TH AVE N SEATTLE WA 98109-4606	NE	0.43 / 2,275.57	-8	775
191	DELISTED SHWS	IRIS Holding LLC	WA	NNE	0.44 / 2,306.67	-9	776
192	ALL SITES	Potala Tower Seattle	2116 4TH AVE SEATTLE WA 98121	ESE	0.44 / 2,308.82	24	776
192	CSCSL NFA	Potala Tower Seattle	2116 4TH AVE SEATTLE WA 98121	ESE	0.44 / 2,308.82	24	777
192	ICR	Potala Tower Seattle	2116 4TH AVE SEATTLE WA 98121	ESE	0.44 / 2,308.82	24	779

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
193	ALL SITES	WORLDCOM INTERMIEDIA FACILITY	2200 6TH AVE SEATTLE WA 98121	E	0.44 / 2,318.58	2	780
194	ALL SITES	Uptown Flats Queen Anne	300 1ST AVE W SEATTLE WA 98119	WNW	0.44 / 2,338.32	-17	781
194	CSCSL	Uptown Flats Queen Anne	300 1ST AVE W SEATTLE WA 98119	WNW	0.44 / 2,338.32	-17	781
194	VCP	Uptown Flats Queen Anne	300 1ST AVE W SEATTLE WA 98119	WNW	0.44 / 2,338.32	-17	782
195	ALL SITES	PPG Industries Inc Loc 180	234 DEXTER AVE SEATTLE WA 98109	ENE	0.45 / 2,350.25	-9	783
196	ALL SITES	Qwest Corporation W00A80	120 LENORA ST SEATTLE WA 98121	SE	0.45 / 2,351.72	38	783
197	CSCSL NFA	Seattle Waterfront Marriott Hotel	2100 ALASKAN WAY SEATTLE WA 98121	SSE	0.45 / 2,352.02	-97	785
197	ALL SITES	Seattle Waterfront Marriott Hotel	2100 ALASKAN WAY SEATTLE WA 98121	SSE	0.45 / 2,352.02	-97	786
197	ICR	Seattle Waterfront Marriott Hotel	2100 ALASKAN WAY SEATTLE WA 98121	SSE	0.45 / 2,352.02	-97	787
197	VCP	Seattle Waterfront Marriott Hotel	2100 ALASKAN WAY SEATTLE WA 98121	SSE	0.45 / 2,352.02	-97	788
197	LUST	Seattle Waterfront Marriott Hotel	2100 ALASKAN WAY SEATTLE WA 98121 ***Facility Site ID:*** 1938238	SSE	0.45 / 2,352.02	-97	789
198	ALL SITES	Cinerama	2100 4TH AVE SEATTLE WA 98121	ESE	0.45 / 2,355.41	27	790
199	RECYCLERS	THE MAIL BOX	300 LENORA ST. SEATTLE WA 98121	ESE	0.45 / 2,382.08	36	791

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
200	ALL SITES	SEA43 Nitro North	2250 7TH AVE SEATTLE WA 98121	E	0.45 / 2,387.75	-4	791
201	ALL SITES	AMAZON SEA44 FRONTIER	2205 7TH AVE SEATTLE WA 98121	E	0.46 / 2,444.32	-6	792
201	CSCSL	Block 18 Amazon Frontier	2205 7TH Avenue SEATTLE WA 98121	E	0.46 / 2,444.32	-6	792
201	VCP	Block 18 Amazon Frontier	2205 7TH Avenue SEATTLE WA 98121	E	0.46 / 2,444.32	-6	793
202	ALL SITES	Lenora Holdings Company LLC	2031 3RD AVE SEATTLE WA 98121	ESE	0.47 / 2,456.05	43	794
202	CSCSL	Lenora Holdings	2031 3RD AVE SEATTLE WA 98121	ESE	0.47 / 2,456.05	43	794
202	LUST PTAP	Lenora Holdings	2031 3rd Avenue, Seattle, WA 98121 WA	ESE	0.47 / 2,456.05	43	795
203	CSCSL	Seattle Vagabond Inn	325 AURORA AVE N SEATTLE WA 98109	NE	0.47 / 2,459.32	-17	795
203	ALL SITES	Seattle Vagabond Inn	325 AURORA AVE N 325 7th Ave N SEATTLE WA 98109	NE	0.47 / 2,459.32	-17	796
203	ICR	Seattle Vagabond Inn	325 AURORA AVE N SEATTLE WA 98109	NE	0.47 / 2,459.32	-17	798
203	VCP	Seattle Vagabond Inn	325 AURORA AVE N SEATTLE WA 98109	NE	0.47 / 2,459.32	-17	799
204	ALL SITES	United Resource System	2025 1ST AVE STE 500 SEATTLE WA 98121	SE	0.47 / 2,462.70	33	799
205	CSCSL	Martin Apartments	2101 2105 & 2111 5TH AVE SEATTLE WA 98121	ESE	0.47 / 2,481.50	16	800

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
205	ALL SITES	Tax Parcel 069600-0025	2101 2105 & 2111 5TH AVE SEATTLE WA 98121	ESE	0.47 / 2,481.50	16	801
205	ICR	Martin Apartments	2101 2105 & 2111 5TH AVE SEATTLE WA 98121	ESE	0.47 / 2,481.50	16	802
205	VCP	Martin Apartments	2101 2105 & 2111 5TH AVE SEATTLE WA 98121	ESE	0.47 / 2,481.50	16	804
206	ALL SITES	Adsco Printing	315 1ST AVE W SEATTLE WA 98119-4196	WNW	0.47 / 2,506.34	-23	806
207	ALL SITES	CVS Pharmacy 10982	2035 4th Ave Seattle WA 98121	ESE	0.48 / 2,510.52	29	806
208	CSCSL	Sterling Realty Organization Co	2101-2111 5TH AVE SEATTLE WA 98121	ESE	0.48 / 2,521.17	16	807
208	ALL SITES	STERLING REALTY ORGANIZATION CO	2101-2111 5TH AVE SEATTLE WA 98121-2510	ESE	0.48 / 2,521.17	16	808
208	LUST	Sterling Realty Organization Co	2101-2111 5TH AVE SEATTLE WA 98121 ***Facility Site ID:*** 92546394	ESE	0.48 / 2,521.17	16	809
208	ICR	STERLING REALTY ORGANIZATION CO	2101-2111 5TH AVE SEATTLE WA 98121-2510	ESE	0.48 / 2,521.17	16	809
209	ALL SITES	ELLIOTT BAY SEAWALL	Seattle WA 98101	SE	0.48 / 2,542.72	-96	811
210	ALL SITES	Barg KH Cleaners	2018 3RD AVE SEATTLE WA 98121	ESE	0.48 / 2,550.13	43	811
211	ALL SITES	Vulcan Construction	5th & Lenora Seattle WA 98121	ESE	0.48 / 2,555.35	15	812
212	CSCSL NFA	USPS Queen Anne	415 1ST AVE N SEATTLE WA 98109	NW	0.48 / 2,556.68	29	812
212	ALL SITES	USPS QUEEN ANNE	415 1ST AVE N SEATTLE WA 98109	NW	0.48 / 2,556.68	29	813

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
212	ICR	USPS Queen Anne	415 1ST AVE N SEATTLE WA 98109	NW	0.48 / 2,556.68	29	814
212	VCP	USPS Queen Anne	415 1ST AVE N SEATTLE WA 98109	NW	0.48 / 2,556.68	29	815
212	LUST	USPS Queen Anne	415 1ST AVE N SEATTLE WA 98109 ***Facility Site ID:*** 31537996	NW	0.48 / 2,556.68	29	816
213	ALL SITES	WA UW Queen Anne	401 QUEEN ANNE AVE N SEATTLE WA 98119	NW	0.48 / 2,557.39	14	816
214	ALL SITES	Jiffy Lube Store 2077	2025 4TH AVE SEATTLE WA 98121	ESE	0.49 / 2,564.21	30	818
214	DELISTED LST	Jiffy Lube Store 2077	2025 4TH AVE SEATTLE WA 98121	ESE	0.49 / 2,564.21	30	819
214	INST	Jiffy Lube Store 2077	2025 4TH AVE SEATTLE WA 98121	ESE	0.49 / 2,564.21	30	819
214	CSCSL NFA	Jiffy Lube Store 2077	2025 4TH AVE SEATTLE WA 98121	ESE	0.49 / 2,564.21	30	820
214	ICR	Jiffy Lube Store 2077	2025 4TH AVE SEATTLE WA 98121	ESE	0.49 / 2,564.21	30	822
214	VCP	Jiffy Lube Store 2077	2025 4TH AVE SEATTLE WA 98121	ESE	0.49 / 2,564.21	30	825
214	LUST	Jiffy Lube Store 2077	2025 4TH AVE SEATTLE WA 98121 ***Facility Site ID:*** 31325769	ESE	0.49 / 2,564.21	30	826
215	CSCSL	Seattle Mercer Ops Base	520 5TH AVE N SEATTLE WA 98109	NNE	0.49 / 2,565.68	-16	827
215	ALL SITES	Mercer Operating Base	520 5TH AVE N SEATTLE WA 98109	NNE	0.49 / 2,565.68	-16	828

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
215	LUST	Seattle Mercer Ops Base	520 5TH AVE N SEATTLE WA 98109 ***Facility Site ID:*** 8984	NNE	0.49 / 2,565.68	-16	829
215	ICR	Seattle Mercer Ops Base	520 5TH AVE N SEATTLE WA 98109	NNE	0.49 / 2,565.68	-16	830
216	ALL SITES	Queen Anne Auto Body	420 QUEEN ANNE N SEATTLE WA 98109	NW	0.49 / 2,597.17	24	832
217	ALL SITES	Amazon Go ISE1	2131 7th Ave Seattle WA 98121	E	0.49 / 2,610.89	-6	832
218	LST HOT	THE RILEY GROUP	215 8TH AVE N SEATTLE WA	ENE	0.50 / 2,615.46	-22	833
219	ALL SITES	Life Span Bio Sciences	700 BLANCHARD ST SEATTLE WA 98121	E	0.50 / 2,616.97	-13	833
220	VCP	IRIS Holding LLC	500 5TH AVE N SEATTLE WA 98109	NNE	0.50 / 2,618.41	-17	834
220	DELISTED SHWS	IRIS Holding LLC	500 5TH AVE N SEATTLE WA 98109	NNE	0.50 / 2,618.41	-17	835
220	ALL SITES	IRIS Holding LLC	500 5TH AVE N SEATTLE WA 98109	NNE	0.50 / 2,618.41	-17	835
220	ICR	IRIS Holding LLC	500 5TH AVE N SEATTLE WA 98109	NNE	0.50 / 2,618.41	-17	837
220	CSCSL NFA	IRIS Holding LLC	500 5TH AVE N SEATTLE WA 98109	NNE	0.50 / 2,618.41	-17	839
220	INST	IRIS Holding LLC	500 5TH AVE N SEATTLE WA 98109	NNE	0.50 / 2,618.41	-17	840
221	ALL SITES	SEA98	720 BLANCHARD ST SEATTLE WA 98121	E	0.50 / 2,619.59	-13	841
222	CSCSL NFA	Sixth & Lenora Apartments	2121 6TH AVE SEATTLE WA 98121	E	0.50 / 2,622.04	2	842

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
222	ALL SITES	Sixth & Lenora Apartments	2121 6TH AVE SEATTLE WA 98121	E	0.50 / 2,622.04	2	842
222	ICR	Sixth & Lenora Apartments	2121 6TH AVE SEATTLE WA 98121	E	0.50 / 2,622.04	2	843
223	ALL SITES	MCI INTERNATIONAL	2001 WESTERN AVE STE 425 SEATTLE WA 98121-2114	SE	0.50 / 2,630.66	-7	844
224	ALL SITES	Wilderman Refrigeration Co	300 DEXTER AVE N SEATTLE WA 98109-5106	ENE	0.50 / 2,637.06	-20	844
225	ALL SITES	SEA47 The Summit	2122 7TH AVE SEATTLE WA 98121	E	0.50 / 2,643.15	-7	845
226	CSCSL	Unocal Myrtle Edwards Park	3130 ALASKAN WAY W SEATTLE WA 98121	WNW	0.51 / 2,676.99	-97	845
227	DELISTED SHWS	8th & Thomas JV LLC	777 THOMAS ST SEATTLE WA 98109	ENE	0.51 / 2,699.58	-25	847
228	CSCSL	Block 21 Amazon 8th & Bell	2205 8TH AVE SEATTLE WA 98121	E	0.51 / 2,700.42	-19	847
229	CSCSL	Block 20 8th & Blanchard	2101 2121 8th Ave & 2130 2100 7th Ave Seattle WA 98121	E	0.53 / 2,798.69	-15	848
230	DELISTED SHWS	Block 19 7th & Lenora	2101 7TH AVE SEATTLE WA 98119	E	0.53 / 2,806.15	-10	849
231	CSCSL	Dexter Office Building	400 DEXTER AVE N SEATTLE WA 98109	ENE	0.54 / 2,832.36	-28	849
232	CSCSL	Standish Property	420 MERCER ST SEATTLE WA 98109	NNE	0.55 / 2,877.70	-12	850
233	CSCSL	Barg French Cleaners	1929 3RD AVE SEATTLE WA 98101	ESE	0.55 / 2,924.95	44	851

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
234	CSCSL	Texaco Pro Investments	150 Mercer St / 600 Warren Ave N SEATTLE WA 98109	NNW	0.55 / 2,926.82	30	852
234	HSL	Texaco Pro Investments	150 Mercer St / 600 Warren Ave N SEATTLE WA 98109	NNW	0.55 / 2,926.82	30	853
235	CSCSL	4th & Virginia	1920 4TH AVE SEATTLE WA 98101	ESE	0.56 / 2,980.94	24	853
235	HSL	4th & Virginia	1920 4TH AVE SEATTLE WA 98101	ESE	0.56 / 2,980.94	24	854
236	CSCSL	Uptown Bakery	513-525 QUEEN ANNE AVE N SEATTLE WA 98119	NW	0.57 / 2,992.49	35	855
236	HSL	Uptown Bakery	513-525 QUEEN ANNE AVE N SEATTLE WA 98119	NW	0.57 / 2,992.49	35	856
237	CSCSL	First & Stewart Hotel Owner LLC	1916 1ST AVE SEATTLE WA 98101	SE	0.57 / 3,025.25	40	857
238	CSCSL	Queen Anne Properties Mercer St	541 QUEEN ANNE AVE N SEATTLE WA 98109	NW	0.57 / 3,033.03	36	858
238	HSL	Queen Anne Properties Mercer St	541 QUEEN ANNE AVE N SEATTLE WA 98109	NW	0.57 / 3,033.03	36	860
239	CSCSL	Pier 63 Sediments	1915 ALASKAN WAY SEATTLE WA 98101	SE	0.57 / 3,034.40	-97	862
240	CSCSL	Kenney Property	100 WESTLAKE AVE N SEATTLE WA 98109	E	0.58 / 3,036.05	-38	863
241	CSCSL	Second Avenue Garage	1915 2ND AVE SEATTLE WA 98101	ESE	0.58 / 3,054.66	52	864
241	CSCSL	Viktoria Apartments	1915 2ND AVE SEATTLE WA 98101	ESE	0.58 / 3,054.66	52	865

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
241	HSL	Viktoria Apartments	1915 2ND AVE SEATTLE WA 98101	ESE	0.58 / 3,054.66	52	868
242	CSCSL	Seattle Opera Parking	620 2ND AVE N SEATTLE WA 98109	NNW	0.59 / 3,103.10	20	869
243	CSCSL	Nash Holland Denny Investors	964 970 DENNY WAY SEATTLE WA 98109	E	0.59 / 3,107.75	-38	870
243	HSL	Nash Holland Denny Investors	964 970 DENNY WAY SEATTLE WA 98109	E	0.59 / 3,107.75	-38	871
244	CSCSL	Seattle Center Property	601-615 MERCER ST SEATTLE WA 98109	NE	0.59 / 3,113.84	-33	872
245	CSCSL	9th Space	308 9TH AVE N SEATTLE WA 98109	ENE	0.59 / 3,131.47	-42	873
246	DELISTED SHWS	Westlake Chevrolet	2030 8TH AVE SEATTLE WA 98121	E	0.60 / 3,146.31	-20	874
247	DELISTED SHWS	Budget Rent A Car Westlake	2001 WESTLAKE AVE SEATTLE WA 98121-2605	E	0.60 / 3,147.70	-9	874
248	CSCSL	Coleman Creosoting Works	333 ELLIOTT AVE W SEATTLE WA 98119	WNW	0.60 / 3,161.27	-84	874
248	HSL	Coleman Creosoting Works	333 ELLIOTT AVE W SEATTLE WA 98119	WNW	0.60 / 3,161.27	-84	875
249	CSCSL	St Regis Hotel	116 STEWART ST SEATTLE WA 98101	ESE	0.60 / 3,186.59	46	876
249	HSL	St Regis Hotel	116 STEWART ST SEATTLE WA 98101	ESE	0.60 / 3,186.59	46	877
250	CSCSL	Block 52 East	333 9TH AVE N SEATTLE WA 98109	ENE	0.61 / 3,200.91	-44	878

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
251	CSCSL	PCY Corp	601 6TH AVE N SEATTLE WA 98109	NE	0.61 / 3,216.47	-33	879
252	CSCSL	Lenora Building	2101 9TH AVE SEATTLE WA 98121	E	0.61 / 3,224.00	-18	880
253	CSCSL	Greiling Property	222 WESTLAKE AVE N SEATTLE WA 98109	ENE	0.62 / 3,259.01	-42	881
253	CSCSL	202 Westlake Office Building	202 WESTLAKE AVE N SEATTLE WA 98109	ENE	0.62 / 3,259.01	-42	882
254	DELISTED SHWS	West 8th Building	718 VIRGINIA ST & 2001 8TH AVE SEATTLE WA 98121	E	0.62 / 3,272.53	-13	883
254	CSCSL	West 8th Building	718 VIRGINIA ST & 2001 8TH AVE SEATTLE WA 98121	E	0.62 / 3,272.53	-13	883
255	CSCSL	Chevron Vacant Site	707 TAYLOR AVE N 700 5TH AVE N SEATTLE WA 98109	NNE	0.63 / 3,323.84	-22	884
255	HSL	Chevron Vacant Site	707 TAYLOR AVE N 700 5TH AVE N SEATTLE WA 98109	NNE	0.63 / 3,323.84	-22	885
256	CSCSL	Seattle City ROW behind 222 Westlake N	ALLEY 222 WESTLAKE & 219 TERRY AVES N SEATTLE WA 98109	ENE	0.63 / 3,328.29	-41	886
257	FUDS	SEATTLE ARMY TERMINAL	SEATTLE WA ***FUDS Property No:*** F10WA0417	ESE	0.64 / 3,374.27	20	887
257	FUDS	JEFFERSON PK VEHICLE STOR	SEATTLE WA ***FUDS Property No:*** F10WA0340	ESE	0.64 / 3,374.27	20	888
257	FUDS	N/WEST RELAY (AUX) STA	SEATTLE WA ***FUDS Property No:*** F10WA0387	ESE	0.64 / 3,374.27	20	888
257	FUDS	MASSACHUSETTS STREET OPEN STORAGE SITE	SEATTLE WA	ESE	0.64 / 3,374.27	20	889

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			FUDS Property No: F10WA0141				
257	FUDS	N SEATTLE NIKE 03	SEATTLE WA ***FUDS Property No:*** F10WA0093	ESE	0.64 / 3,374.27	20	889
257	FUDS	OLYMPIC GOLF COURSE AAA	SEATTLE WA ***FUDS Property No:*** F10WA0114	ESE	0.64 / 3,374.27	20	890
257	FUDS	CAMP GEORGE JORDAN	SEATTLE WA ***FUDS Property No:*** F10WA0259	ESE	0.64 / 3,374.27	20	890
257	FUDS	COLLEGE ST OPEN STOR SITE	SEATTLE WA ***FUDS Property No:*** F10WA0268	ESE	0.64 / 3,374.27	20	891
257	FUDS	SEATTLE DRUM STORAGE	SEATTLE WA ***FUDS Property No:*** F10WA0433	ESE	0.64 / 3,374.27	20	891
257	FUDS	SEATTLE NAVAL INDUSTRIAL RESERVE SHIPYARD PLANT A	SEATTLE WA ***FUDS Property No:*** F10WA0435	ESE	0.64 / 3,374.27	20	892
257	FUDS	LAKE WA SHIP CAN STORAGE	SEATTLE WA ***FUDS Property No:*** F10WA0346	ESE	0.64 / 3,374.27	20	893
257	FUDS	HQS SEATTLE REGION	SEATTLE WA ***FUDS Property No:*** F10WA0339	ESE	0.64 / 3,374.27	20	893
257	FUDS	GUN BATTERY SITE GW9-41	SEATTLE WA ***FUDS Property No:*** F10WA0116	ESE	0.64 / 3,374.27	20	894
257	FUDS	SEATTLE TROOP TRA SIDING	SEATTLE WA ***FUDS Property No:*** F10WA0443	ESE	0.64 / 3,374.27	20	894
257	FUDS	SEATTLE PORT EMBARKATION	SEATTLE WA ***FUDS Property No:*** F10WA0437	ESE	0.64 / 3,374.27	20	895
257	FUDS	SEATTLE WAC HOUSING SITE	SEATTLE WA ***FUDS Property No:*** F10WA0445	ESE	0.64 / 3,374.27	20	895

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
257	FUDS	U.S. ENGINEER WAREHOUSE (FREMONT)	SEATTLE WA ***FUDS Property No:*** F10WA0129	ESE	0.64 / 3,374.27	20	896
257	FUDS	GREAT NORTHERN PIER 88	SEATTLE WA ***FUDS Property No:*** F10WA0576	ESE	0.64 / 3,374.27	20	896
257	FUDS	AIR FORCE PLANT NO. 17	SEATTLE WA ***FUDS Property No:*** F10WA0236	ESE	0.64 / 3,374.27	20	897
257	FUDS	SEATTLE NAVAL INDUSTRIAL RESERVE SHIPYARD PLANT B	SEATTLE WA ***FUDS Property No:*** F10WA0436	ESE	0.64 / 3,374.27	20	898
257	FUDS	SEATTLE SAL SEG SITE	SEATTLE WA ***FUDS Property No:*** F10WA0438	ESE	0.64 / 3,374.27	20	898
257	FUDS	ACS CABLE STORAGE AREA	SEATTLE WA ***FUDS Property No:*** F10WA0573	ESE	0.64 / 3,374.27	20	899
257	FUDS	ARGO REDISTRIBUTION SITE	SEATTLE WA ***FUDS Property No:*** F10WA0242	ESE	0.64 / 3,374.27	20	899
257	FUDS	ALASKA COMMUNICATION SYS	SEATTLE WA ***FUDS Property No:*** F10WA0241	ESE	0.64 / 3,374.27	20	900
257	FUDS	HOLGATE ST SALVAGE SITE	SEATTLE WA ***FUDS Property No:*** F10WA0338	ESE	0.64 / 3,374.27	20	900
257	FUDS	BOEING FIELD	SEATTLE WA ***FUDS Property No:*** F10WA0254	ESE	0.64 / 3,374.27	20	901
257	FUDS	SEATTLE BEACON TRAN SITE	SEATTLE WA ***FUDS Property No:*** F10WA0419	ESE	0.64 / 3,374.27	20	901
257	FUDS	SEATTLE TUG&BARGE MOORING	SEATTLE WA ***FUDS Property No:*** F10WA0444	ESE	0.64 / 3,374.27	20	902
257	FUDS	US DIST ENG INT STOR SITE	SEATTLE WA	ESE	0.64 / 3,374.27	20	902

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			FUDS Property No: F10WA0467				
257	FUDS	AUTOMATIC WEAPONS BATTERY HEADQUARTERS SW9-29	SEATTLE WA ***FUDS Property No:*** F10WA0587	ESE	0.64 / 3,374.27	20	903
257	FUDS	US DIST ENG WAREHOUSE	SEATTLE WA ***FUDS Property No:*** F10WA0468	ESE	0.64 / 3,374.27	20	904
257	FUDS	BOEING SEATTLE PLANT #12	SEATTLE WA ***FUDS Property No:*** F10WA0255	ESE	0.64 / 3,374.27	20	904
257	FUDS	NG GD FAC PIER 91 SEATTLE	SEATTLE WA ***FUDS Property No:*** F10WA0398	ESE	0.64 / 3,374.27	20	905
257	FUDS	ISAACSON IRON WORKS	SEATTLE WA ***FUDS Property No:*** F10WA0536	ESE	0.64 / 3,374.27	20	905
257	FUDS	LAKE WA SHIP CAN MIL RES	SEATTLE WA ***FUDS Property No:*** F10WA0345	ESE	0.64 / 3,374.27	20	906
257	FUDS	SEATTLE STOCKPILE STORAGE	SEATTLE WA ***FUDS Property No:*** F10WA0440	ESE	0.64 / 3,374.27	20	906
257	FUDS	SEATTLE TRAN LAB CAM SITE	SEATTLE WA ***FUDS Property No:*** F10WA0441	ESE	0.64 / 3,374.27	20	907
257	FUDS	Western Processing	KENT WA ***FUDS Property No:*** F10WA0095	ESE	0.64 / 3,374.27	20	907
257	FUDS	SEATTLE AREA DISPOSAL CEN	SEATTLE WA ***FUDS Property No:*** F10WA0415	ESE	0.64 / 3,374.27	20	908
257	FUDS	TODD-SEATTLE DRYDOCK INC	SEATTLE WA ***FUDS Property No:*** F10WA0550	ESE	0.64 / 3,374.27	20	909
257	FUDS	SEATTLE AUT MAINT SHOP	SEATTLE WA ***FUDS Property No:*** F10WA0418	ESE	0.64 / 3,374.27	20	909

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
258	CSCSL	Seattle DOT Promenade & Overlook Walk	1500 1524 1528 ALASKAN WAY SEATTLE WA 98101	SE	0.65 / 3,414.65	-93	910
259	CSCSL	United Furniture Refinishers	219 TERRY AVE N SEATTLE WA 98109	ENE	0.65 / 3,433.49	-39	911
260	CSCSL	Bayless Book Bindery	427 9TH AVE N SEATTLE WA 98109	ENE	0.65 / 3,446.36	-52	912
261	CSCSL	Block 40 East & West Westlake & Terry	320 WESTLAKE AVE N SEATTLE WA 98109	ENE	0.65 / 3,446.84	-49	913
262	CSCSL	Broad Street Alignment Contaminated Fill	DEXTER AVE N & MERCER ST SEATTLE WA 98102	NE	0.65 / 3,449.87	-50	913
263	CSCSL	Unocal 306568	700 QUEEN ANNE AVE N SEATTLE WA 98109	NW	0.66 / 3,494.40	45	914
263	HSL	Unocal 306568	700 QUEEN ANNE AVE N SEATTLE WA 98109	NW	0.66 / 3,494.40	45	915
264	CSCSL	Gilead Sciences Inc	410 W HARRISON ST 2ND FLOOR SEATTLE WA 98119	WNW	0.66 / 3,496.38	-71	916
265	CSCSL	Texaco 211577 Monterey	631 QUEEN ANNE AVE N SEATTLE WA 98109	NW	0.66 / 3,504.36	38	917
265	HSL	Texaco 211577 Monterey	631 QUEEN ANNE AVE N SEATTLE WA 98109	NW	0.66 / 3,504.36	38	919
266	DELISTED SHWS	MONTEREY APARTMENTS	622 1ST AVE W & QUEEN AVE N SEATTLE WA 98119	NW	0.67 / 3,523.61	33	921
266	DELISTED SHWS	MONTEREY APARTMENTS	622 1ST AVE W & QUEEN AVE N SEATTLE WA 98119	NW	0.67 / 3,523.61	33	921
266	CSCSL	MONTEREY APARTMENTS	622 1ST AVE W & QUEEN AVE N SEATTLE WA 98119	NW	0.67 / 3,523.61	33	922

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
266	HSL	MONTEREY APARTMENTS	622 1ST AVE W & QUEEN AVE N SEATTLE WA 98119	NW	0.67 / 3,523.61	33	923
267	CSCSL	601 Dexter	601 DEXTER AVE N SEATTLE WA 98109	NE	0.67 / 3,542.80	-51	923
268	CSCSL	1918 Eighth Office Tower	1918 8TH AVE SEATTLE WA 98101	E	0.67 / 3,544.11	-4	926
269	CSCSL	Dollar Rent a Car	7TH & STEWART SEATTLE WA 98101	E	0.68 / 3,603.76	0	927
270	CSCSL	Firestone Tire & Rubber Co	400 WESTLAKE AVE N SEATTLE WA 98109	ENE	0.68 / 3,604.52	-56	927
271	CSCSL	Seattle DOT Dexter Parcel	615 DEXTER AVE N SEATTLE WA 98109	NE	0.69 / 3,619.17	-49	928
271	HSL	Seattle DOT Dexter Parcel	615 DEXTER AVE N SEATTLE WA 98109	NE	0.69 / 3,619.17	-49	929
272	CSCSL	Federal Courthouse	700 STEWART ST SEATTLE WA 98101	E	0.69 / 3,664.88	3	929
273	CSCSL	Seattle DOT Mercer Parcels	800 MERCER ST SEATTLE WA 98109	NE	0.72 / 3,779.34	-57	930
273	HSL	Seattle DOT Mercer Parcels	800 MERCER ST SEATTLE WA 98109	NE	0.72 / 3,779.34	-57	931
274	CSCSL	701 Dexter	701 DEXTER AVE N SEATTLE WA 98109	NE	0.72 / 3,811.48	-45	932
275	CSCSL	City Mini Storage	2000 TERRY AVE & 1000 VIRGINIA ST SEATTLE WA 98121	E	0.72 / 3,815.25	14	933
276	CSCSL	American Linen Supply Co Dexter Ave	700 DEXTER AVE N SEATTLE WA 98109	NE	0.73 / 3,831.49	-47	933

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
276	HSL	American Linen Supply Co Dexter Ave	700 DEXTER AVE N SEATTLE WA 98109	NE	0.73 / 3,831.49	-47	935
277	CSCSL	Stewart Court Apartments	1835 8TH AVE SEATTLE WA 98101	E	0.73 / 3,841.51	10	936
278	CSCSL	818 Stewart St	818 STEWART ST SEATTLE WA 98101	E	0.74 / 3,889.33	16	937
279	DELISTED SHWS	Boren and Lenora	2019 - 2031 BOREN AVE SEATTLE WA 98121	E	0.74 / 3,896.87	16	938
280	CSCSL	Seattle Roy Aloha Shops	802 ROY ST SEATTLE WA 98109	NE	0.75 / 3,947.06	-60	938
281	CSCSL	Block 38 West	520 Westlake Ave N Seattle WA 98109	ENE	0.75 / 3,979.68	-70	939
281	HSL	Block 38 West	520 Westlake Ave N Seattle WA 98109	ENE	0.75 / 3,979.68	-70	940
282	CSCSL	Lake Union III	410 TERRY N 415 BOREN N SEATTLE WA 98109	ENE	0.75 / 3,982.54	-51	941
283	CSCSL	Seattle Times	1120 JOHN ST SEATTLE WA 98109	E	0.76 / 3,998.58	15	942
284	CSCSL	Rosen Property	960 REPUBLICAN ST SEATTLE WA 98109	ENE	0.76 / 4,035.61	-66	943
285	CSCSL	Maryatt Industries	771 VALLEY ST SEATTLE WA 98109	NE	0.77 / 4,042.16	-51	943
286	CSCSL	Seattle Times Parcel 1B	100 FAIRVIEW AVE SEATTLE WA 98109	E	0.77 / 4,045.51	19	944
287	CSCSL	Block 79 East	701 9TH AVE N SEATTLE WA 98109	NE	0.78 / 4,112.63	-66	946
287	HSL	Block 79 East	701 9TH AVE N SEATTLE WA 98109	NE	0.78 / 4,112.63	-66	948

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
288	CSCSL	Seattle SD 1 Facilities Bldg	810 DEXTER AVE N SEATTLE WA 98109	NE	0.78 / 4,142.85	-46	949
289	CSCSL	Pier 58 Sediments	1401 ALASKAN WAY SEATTLE WA 98101	SE	0.78 / 4,143.65	-93	951
290	CSCSL	Ivars Commissary	500 TERRY AVE N SEATTLE WA 98109	ENE	0.79 / 4,176.53	-63	952
290	HSL	Ivars Commissary	500 TERRY AVE N SEATTLE WA 98109	ENE	0.79 / 4,176.53	-63	953
291	CSCSL	8th & Howell	808 HOWELL ST SEATTLE WA 98101	E	0.79 / 4,185.63	28	954
292	CSCSL	AIBS Building Block 43	601 WESTLAKE AVE N SEATTLE WA 98109	NE	0.80 / 4,198.75	-72	955
293	CSCSL	Seattle City DOT ROW 710 9th Ave N	710 9TH AVE N SEATTLE WA 98109	NE	0.80 / 4,238.40	-70	957
294	CSCSL	Moxy Hotel	1016 REPUBLICAN ST SEATTLE WA 98109	ENE	0.80 / 4,245.61	-59	958
295	CSCSL	Red Carpet Car Wash	1164 DENNY WAY SEATTLE WA 98109	E	0.80 / 4,249.17	20	959
295	HSL	Red Carpet Car Wash	1164 DENNY WAY SEATTLE WA 98109	E	0.80 / 4,249.17	20	960
296	DELISTED SHWS	Creases Dry Cleaner	1820 TERRY AVE SEATTLE WA 98101	E	0.81 / 4,252.57	29	961
297	CSCSL	South Lake Union 293 Parcel A	424 BOREN AVE N SEATTLE WA 98109	ENE	0.81 / 4,262.76	-54	961
298	CSCSL	Block 37	600 WESTLAKE AVE N SEATTLE WA 98109	ENE	0.81 / 4,299.01	-74	962

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
298	HSL	Block 37	600 WESTLAKE AVE N SEATTLE WA 98109	ENE	0.81 / 4,299.01	-74	965
299	CSCSL	Cascade 1 & 2 Apartments	Minor & Fairview Ave N Thomas & John Seattle WA 98109	ENE	0.82 / 4,323.01	10	966
300	CSCSL	525 Boren Building	525 BOREN AVE N SEATTLE WA 98109	ENE	0.82 / 4,333.90	-62	968
301	CSCSL	Maaco Auto Painting Bodywork 9th Ave	739 9TH AVE N SEATTLE WA 98109	NE	0.82 / 4,337.49	-72	969
302	CSCSL	Troy Laundry Seattle	399 FAIRVIEW AVE N SEATTLE WA 98109	ENE	0.83 / 4,358.45	-14	970
303	CSCSL	Seattle Steam Co Western Ave	1319 WESTERN AVE SEATTLE WA 98101	SE	0.83 / 4,368.01	-80	972
303	HSL	Seattle Steam Co Western Ave	1319 WESTERN AVE SEATTLE WA 98101	SE	0.83 / 4,368.01	-80	973
304	CSCSL	Oden Investment Condos	619 5TH AVE W SEATTLE WA 98119	NW	0.83 / 4,407.43	16	975
304	HSL	Oden Investment Condos	619 5TH AVE W SEATTLE WA 98119	NW	0.83 / 4,407.43	16	975
305	CSCSL	Auto Service Company	630 WESTLAKE AVE N SEATTLE WA 98109	NE	0.84 / 4,415.51	-76	976
305	HSL	Auto Service Company	630 WESTLAKE AVE N SEATTLE WA 98109	NE	0.84 / 4,415.51	-76	977
306	CSCSL	Crescent Heights	1901 - 1933 Minor Ave SEATTLE WA 98101	E	0.84 / 4,436.57	25	978
307	CSCSL	WA State Convention & Trade Center	8TH & PINE SEATTLE WA 98101	ESE	0.84 / 4,441.52	41	980

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
308	CSCSL	Goodyear Stewart St	1105 STEWART ST SEATTLE WA 98101	E	0.84 / 4,441.61	28	981
309	CSCSL	Jarvie Paint	760 ALOHA ST SEATTLE WA 98109	NE	0.84 / 4,443.47	-52	983
310	CSCSL	400 Fairview LLC Seattle	412 Fairview Ave N Seattle WA 98109	ENE	0.85 / 4,491.52	-24	984
311	CSCSL	Neptune Apartments proposed	900 912 DEXTER AVE N SEATTLE WA 98121	NE	0.85 / 4,495.30	-46	985
312	DELISTED SHWS	Western & University Property	WA	SE	0.85 / 4,503.78	-87	986
313	CSCSL	Block 32 North Bldg City Place III LLC	1001 & 1021 Mercer St 500 Terry Ave N Seattle WA 98109	ENE	0.85 / 4,511.05	-69	986
314	CSCSL	Blackstock Lumber	601 Elliott Ave W Seattle WA 98119	WNW	0.86 / 4,524.17	-78	988
315	DELISTED SHWS	Western & University Property	50 UNIVERSITY ST SEATTLE WA 98101	SE	0.86 / 4,556.50	-87	989
316	CSCSL	Shell 23714	601 BOREN AVE N SEATTLE WA 98109	ENE	0.87 / 4,600.01	-71	989
317	CSCSL	Immunex Corporation 51 U	51 UNIVERSITY ST SEATTLE WA 98101	SE	0.87 / 4,614.53	-89	990
318	CSCSL	Mastercraft Metal Finishing	1175 HARRISON ST SEATTLE WA 98109	ENE	0.88 / 4,639.38	-8	991
318	HSL	Mastercraft Metal Finishing	1175 HARRISON ST SEATTLE WA 98109	ENE	0.88 / 4,639.38	-8	992
319	CSCSL	Seattle Cancer Care Alliance House	1216 JOHN ST SEATTLE WA 98109	E	0.88 / 4,646.91	15	992

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
320	CSCSL	Staybridge Suite Even Hotel	527 FAIRVIEW AVE N SEATTLE WA 98109	ENE	0.88 / 4,667.83	-55	994
321	CSCSL	Washington Athletic Club Garage	1405 6TH AVE SEATTLE WA 98101	ESE	0.89 / 4,673.80	42	994
321	HSL	Washington Athletic Club Garage	1405 6TH AVE SEATTLE WA 98101	ESE	0.89 / 4,673.80	42	995
322	CSCSL	Greyhound Denny Way	1250 DENNY WAY SEATTLE WA 98109	E	0.89 / 4,680.61	24	996
323	CSCSL	Paramount Theatre	911 PINE ST SEATTLE WA 98101	E	0.90 / 4,730.26	55	997
324	DELISTED SHWS	Seattle S Lake Union Park	1000 VALLEY ST 815 BOREN AVE N SEATTLE WA 98109	ENE	0.90 / 4,738.21	-75	997
324	CSCSL	Seattle S Lake Union Park	1000 VALLEY ST 815 BOREN AVE N SEATTLE WA 98109	ENE	0.90 / 4,738.21	-75	998
325	CSCSL	Tritell Parking Lot	1821-1823 MINOR AVE SEATTLE WA 98101	E	0.90 / 4,757.37	34	999
326	CSCSL	Central Seattle Waterfront	PIERS 53-58 ALASKAN WAY SEATTLE WA 98101	SE	0.91 / 4,791.06	-97	1001
327	CSCSL	New Richmond Laundry	224 PONTIUS ST N SEATTLE WA 98109	E	0.91 / 4,826.28	19	1003
327	CSCSL	Alley 24 West LLC	224 PONTIUS AVE N SEATTLE WA 98109	E	0.91 / 4,826.28	19	1003
328	DELISTED SHWS	Freymuller Enterprises	1108 AURORA AVE N SEATTLE WA 98109	NNE	0.91 / 4,828.71	21	1005
329	CSCSL	Cascade Supportive Housing	424 MINOR AVE N SEATTLE WA 98109	ENE	0.93 / 4,894.82	-11	1005

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
330	CSCSL	Seattle City Parks NW Seaport	1002 VALLEY ST SEATTLE WA 98109	NE	0.93 / 4,895.52	-81	1006
331	CSCSL	Kerner Scott Building	510 MINOR AVE N SEATTLE WA 98109	ENE	0.95 / 5,025.27	-22	1007
332	CSCSL	Qwest W00294	1200 3RD AVE SEATTLE WA 98104	ESE	0.95 / 5,030.76	35	1008
332	HSL	Qwest W00294	1200 3RD AVE SEATTLE WA 98104	ESE	0.95 / 5,030.76	35	1009
333	CSCSL	Seattle Hilton Hotel Parking Garage	1301 6TH AVE SEATTLE WA 98101	ESE	0.96 / 5,045.15	68	1009
334	DELISTED SHWS	PEMCO Property	221 YALE AVE SEATTLE WA 98109	E	0.96 / 5,063.88	24	1011
334	CSCSL	Pemco Property	221 YALE AVE N SEATTLE WA 98109	E	0.96 / 5,063.88	24	1011
335	CSCSL	Overall Laundry	200 222 YALE AVE N SEATTLE WA 98109	E	0.96 / 5,068.94	27	1012
336	CSCSL	Seattle SD Warehouse	1255 Harrison St Seattle WA 98109	ENE	0.97 / 5,099.54	7	1013
337	CSCSL	Tomlinson UST 101457 Block 10	414 420 Pontius Ave N & 1260 Harrison Seattle WA 98109	ENE	0.98 / 5,162.16	2	1014
338	CSCSL	Seattle City South Lake Union Naval Reserve Ctr	860 TERRY AVE N SEATTLE WA 98109	NE	0.98 / 5,166.64	-79	1015
339	CSCSL	Elliott Holding Company LLC	635 Elliott Ave W Seattle WA 98119	WNW	0.98 / 5,195.13	-78	1016
340	CSCSL	First Choice Business Machines	1333 STEWART ST SEATTLE WA 98109	E	0.99 / 5,247.01	41	1019

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
341	DELISTED SHWS	PEMCO Parking Concrete Cutter	300-320 Yale Ave N & 325 Eastlake Ave E SEATTLE WA 98109	ENE	1.00 / 5,263.38	27	1020
341	DELISTED SHWS	PEMCO Parking Concrete Cutter	300-320 Yale Ave N & 325 Eastlake Ave E SEATTLE WA 98109	ENE	1.00 / 5,263.38	27	1020
341	CSCSL	Yale & Harrison Development	300-320 Yale Ave N & 325 Eastlake Ave E SEATTLE WA 98109	ENE	1.00 / 5,263.38	27	1021

Executive Summary: Summary by Data Source

Standard

Federal

SEMS ARCHIVE - SEMS List 8R Archive Sites

A search of the SEMS ARCHIVE database, dated Jun 30, 2022 has found that there are 1 SEMS ARCHIVE site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
SEATTLE POST INTELLIGENCER	521 WALL ST SEATTLE WA 98121 ***EPA ID**: WAD001533538*	E	0.27 / 1,408.52	114

CERCLIS - Comprehensive Environmental Response, Compensation and Liability Information System - CERCLIS

A search of the CERCLIS database, dated Oct 25, 2013 has found that there are 1 CERCLIS site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
SEATTLE POST INTELLIGENCER	521 WALL ST SEATTLE WA 98121 ***Site EPA ID**: WAD001533538*	E	0.27 / 1,408.52	114

CERCLIS NFRAP - CERCLIS - No Further Remedial Action Planned

A search of the CERCLIS NFRAP database, dated Oct 25, 2013 has found that there are 1 CERCLIS NFRAP site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
SEATTLE POST INTELLIGENCER	521 WALL ST SEATTLE WA 98121 ***Site EPA ID**: WAD001533538*	E	0.27 / 1,408.52	114

RCRA TSD - RCRA non-CORRACTS TSD Facilities

A search of the RCRA TSD database, dated Jun 27, 2022 has found that there are 1 RCRA TSD site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
BRE PROPERTIES INC	552 DENNY WAY & 553 JOHN ST SEATTLE WA 98109 ***EPA Handler ID**: WAH000029059*	ENE	0.27 / 1,415.34	117

RCRA LQG - RCRA Generator List

A search of the RCRA LQG database, dated Jun 27, 2022 has found that there are 2 RCRA LQG site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
EDWARDS ON 5TH BLDG	2619 5TH AVE SEATTLE WA 98121 ***EPA Handler ID**: WAH000059830*	ENE	0.19 / 1,002.02	69
FAULKENBURY AND WRIGHT DRYCLEANERS	501 DENNY WAY SEATTLE WA 98109 ***EPA Handler ID**: WAD085811768*	ENE	0.21 / 1,118.54	83

RCRA VSQG - RCRA Very Small Quantity Generators List

A search of the RCRA VSQG database, dated Jun 27, 2022 has found that there are 4 RCRA VSQG site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
RITE AID 6977 DBA BARTELL DRUGS 077	2506 2ND AVE SEATTLE WA 98121 ***EPA Handler ID**: WAH000058410*	ESE	0.13 / 674.54	39
LIFESPAN BIOSCIENCES	2401 4TH AVE 12TH FLOOR SEATTLE WA 98121 ***EPA Handler ID**: WAH000017913*	E	0.21 / 1,118.74	84

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
AFFINI-T THERAPEUTICS SEATTLE	3005 1ST AVE STE 102 SEATTLE WA 98121 ***EPA Handler ID**: WAH000059535*	WNW	0.17 / 912.96	55
CYRUS BIOTECHNOLOGY INC SEATTLE	3005 1ST AVE STE 203 SEATTLE WA 98121 ***EPA Handler ID**: WAH000059595*	WNW	0.17 / 912.96	55

RCRA NON GEN - RCRA Non-Generators

A search of the RCRA NON GEN database, dated Jun 27, 2022 has found that there are 36 RCRA NON GEN site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
GRANGE INSURANCE GROUP	200 CEDAR ST SEATTLE WA 98121 ***EPA Handler ID**: WAH000019778*	E	0.04 / 205.62	5
RITE AID 5218	2603 3RD AVE SEATTLE WA 98121 ***EPA Handler ID**: WAR000002709*	E	0.10 / 509.10	18
CASCADIAN THERAPEUTICS SEATTLE	2601 4TH AVE STE 500 SEATTLE WA 98121 ***EPA Handler ID**: WAH000053608*	ENE	0.12 / 629.45	34

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
WITS AIR FREIGHT	333 VINE ST SEATTLE WA 98121 ***EPA Handler ID**: WAD041331935*	E	0.13 / 661.67	38
PUGET SOUND INSTITUTE OF PATHO	2600 4TH AVE SEATTLE WA 98111 ***EPA Handler ID**: WAD063338339*	E	0.15 / 812.05	49
SPACE NEEDLE CORP	219 4TH AVE N SEATTLE WA 98109 ***EPA Handler ID**: WAD988514014*	NNE	0.18 / 955.86	61
2ND AVE BELL DRUMS	2408 2ND AVE SEATTLE WA 98121 ***EPA Handler ID**: WAD981770233*	ESE	0.19 / 1,017.98	75
FAT CITY INC	508 DENNY WAY SEATTLE WA 98109 ***EPA Handler ID**: WAD988513578*	ENE	0.20 / 1,062.07	77
PARSON SEATRUST PARTNERSHIP	400 WALL ST SEATTLE WA 98121 ***EPA Handler ID**: WA0000100503*	E	0.21 / 1,099.70	80
HAWAIIAN MARINE LINES INC	2401 4TH AVE SEATTLE WA 98121 ***EPA Handler ID**: WAD991281916*	E	0.21 / 1,118.74	84
PACIFIC SCIENCE CENTER	200 2ND AVE N SEATTLE WA 98109 ***EPA Handler ID**: WAH000019513*	NW	0.22 / 1,184.23	90
HOLMAN BODY & FENDER	2324 2ND AVE SEATTLE WA 98121 ***EPA Handler ID**: WAD062788161*	ESE	0.23 / 1,201.53	93
ARCTIC MARINE FREIGHTERS	4TH & BATTERY SEATTLE WA 98111 ***EPA Handler ID**: WAD980738009*	E	0.24 / 1,255.55	100
PRIME CYTE INC	130 5TH AVE N SEATTLE WA 98109 ***EPA Handler ID**: WAH000003616*	NE	0.24 / 1,273.55	103
GROSVENOR HOUSE	500 WALL ST STE 100 SEATTLE WA 98121 ***EPA Handler ID**: WAD135034577*	ENE	0.24 / 1,284.97	105
1221 DENNY LLC	417 BROAD ST SEATTLE WA 98109 ***EPA Handler ID**: WAH000044432*	NE	0.25 / 1,304.95	106

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
SEA COAST TOWING INC HOME OFFI	2701 1ST AVE SEATTLE WA 98121 ***EPA Handler ID**: WAD988477253*	SSW	0.04 / 184.96	3
SEATTLE LABOR TEMPLE ASSOC PARKING LOT	2801 1ST AVE SEATTLE WA 98121 ***EPA Handler ID**: WAD982658270*	W	0.06 / 295.13	7
WASHINGTON TRANSIT ADVERTISING	2600 WESTERN AVE SEATTLE WA 98121 ***EPA Handler ID**: WAD027482959*	S	0.12 / 619.56	31
BELLTOWN DEVELOPMENT PARTNERS II LLC	2700 ELLIOTT AVE SEATTLE WA 98121 ***EPA Handler ID**: WAR000009753*	SW	0.14 / 723.90	43
LA SCALA APARTMENTS	2922 WESTERN AVE SEATTLE WA 98121 ***EPA Handler ID**: WAD988474540*	W	0.14 / 748.41	44
OENING CO 81 VINE	2518 WESTERN AVE SEATTLE WA 98121 ***EPA Handler ID**: WA0000188722*	SSE	0.14 / 765.49	47
ROSSMAN INDUSTRIAL SUPPLY CO	2500 WESTERN AVE SEATTLE WA 98121 ***EPA Handler ID**: WAD988517991*	SSE	0.16 / 856.05	52
BRISTOL MYERS SQUIBB PHARM RES INST SEA	3005 1ST AVE STE 200 SEATTLE WA 98121 ***EPA Handler ID**: WAD067194340*	WNW	0.17 / 912.96	55
ASTELLAS PHARMA US INC	3005 1ST AVE SEATTLE WA 98121 ***EPA Handler ID**: WAD003095932*	WNW	0.17 / 912.96	55
UNOCAL SS NO 0355	159 DENNY WAY SEATTLE WA 98119 ***EPA Handler ID**: WAD988493441*	WNW	0.18 / 945.58	60
S EPA H INC	150 DENNY WAY SEATTLE WA 98109 ***EPA Handler ID**: WAD982821191*	WNW	0.19 / 997.79	67
SEATTLE CITY PARKS & REC BELLTOWN PP	2512 ELLIOT AVE SEATTLE WA 98102 ***EPA Handler ID**: WAH000016816*	S	0.19 / 1,001.11	68
GENETIC SYSTEMS CORPORATION WESTERN	3000 WESTERN AVENUE SEATTLE WA 98121-0000 ***EPA Handler ID**: WAD988469193*	W	0.19 / 1,010.03	73

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
WA UW WESTERN AVE	3000 WESTERN AVE SEATTLE WA 98121 ***EPA Handler ID**: WAH000005462*	W	0.19 / 1,010.03	73
A 1 LAUNDRY INC	2401 1ST AVE SEATTLE WA 98121 ***EPA Handler ID**: WAH000049635*	SE	0.19 / 1,026.78	76
TRIAD VINE & ELLIOT LLC	10 WALL ST SEATTLE WA 98121 ***EPA Handler ID**: WAH000013706*	S	0.20 / 1,063.52	78
GRAPHICOLOR INC	3018 WESTERN AVE SEATTLE WA 98121-1023 ***EPA Handler ID**: WAD094627460*	W	0.21 / 1,117.79	82
UNOCAL MARKETING TERMINAL NO TM0724	3001 ELLIOTT AVE SEATTLE WA 98121 ***EPA Handler ID**: WAD988497624*	W	0.21 / 1,121.65	85
SEATTLE PORT PIER 69	2711 ALASKAN WAY SEATTLE WA 98121 ***EPA Handler ID**: WAD988519229*	SW	0.24 / 1,268.67	101
EDGEWATER HOTEL	2411 ALASKAN WAY PIER 67 SEATTLE WA 98121 ***EPA Handler ID**: WAH000037063*	SSW	0.25 / 1,306.08	107

State

HSL - Hazardous Sites List

A search of the HSL database, dated Aug 22, 2022 has found that there are 34 HSL site(s) within approximately 1.00 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Martin Selig Property	2601 4TH AVE SEATTLE WA 98121	ENE	0.12 / 629.45	34
Edwards on Fifth	2619 5TH AVE SEATTLE WA 98121	ENE	0.19 / 1,002.02	69
Holman Body & Fender	2324 2ND AVE SEATTLE WA 98121	ESE	0.23 / 1,201.53	93
Phom Property	2301 4th Ave / 314 Bell St SEATTLE WA 98121	E	0.31 / 1,620.12	135

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Lewiston Hotel	2201 1ST AVE SEATTLE WA 98121	SE	0.36 / 1,891.41	154
Texaco Pro Investments	150 Mercer St / 600 Warren Ave N SEATTLE WA 98109	NNW	0.55 / 2,926.82	234
4th & Virginia	1920 4TH AVE SEATTLE WA 98101	ESE	0.56 / 2,980.94	235
Uptown Bakery	513-525 QUEEN ANNE AVE N SEATTLE WA 98119	NW	0.57 / 2,992.49	236
Queen Anne Properties Mercer St	541 QUEEN ANNE AVE N SEATTLE WA 98109	NW	0.57 / 3,033.03	238
Viktoria Apartments	1915 2ND AVE SEATTLE WA 98101	ESE	0.58 / 3,054.66	241
St Regis Hotel	116 STEWART ST SEATTLE WA 98101	ESE	0.60 / 3,186.59	249
Unocal 306568	700 QUEEN ANNE AVE N SEATTLE WA 98109	NW	0.66 / 3,494.40	263
Texaco 211577 Monterey	631 QUEEN ANNE AVE N SEATTLE WA 98109	NW	0.66 / 3,504.36	265
MONTEREY APARTMENTS	622 1ST AVE W & QUEEN AVE N SEATTLE WA 98119	NW	0.67 / 3,523.61	266
Red Carpet Car Wash	1164 DENNY WAY SEATTLE WA 98109	E	0.80 / 4,249.17	295
Oden Investment Condos	619 5TH AVE W SEATTLE WA 98119	NW	0.83 / 4,407.43	304
Washington Athletic Club Garage	1405 6TH AVE SEATTLE WA 98101	ESE	0.89 / 4,673.80	321

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Qwest W00294	1200 3RD AVE SEATTLE WA 98104	ESE	0.95 / 5,030.76	332

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
UNOCAL Seattle Marketing Terminal	BROAD ST & WESTERN AVE & BAY ST SEATTLE WA 98121	W	0.16 / 844.14	51
Unocal Seattle Market Lower	BN ELLIOTT RR BAY & BROAD SEATTLE WA 98121	W	0.16 / 844.14	51
Elliott Bay Bicycles	2114 WESTERN AVE SEATTLE WA 98121	SE	0.42 / 2,219.31	185
Nash Holland Denny Investors	964 970 DENNY WAY SEATTLE WA 98109	E	0.59 / 3,107.75	243
Coleman Creosoting Works	333 ELLIOTT AVE W SEATTLE WA 98119	WNW	0.60 / 3,161.27	248
Chevron Vacant Site	707 TAYLOR AVE N 700 5TH AVE N SEATTLE WA 98109	NNE	0.63 / 3,323.84	255
Seattle DOT Dexter Parcel	615 DEXTER AVE N SEATTLE WA 98109	NE	0.69 / 3,619.17	271
Seattle DOT Mercer Parcels	800 MERCER ST SEATTLE WA 98109	NE	0.72 / 3,779.34	273
American Linen Supply Co Dexter Ave	700 DEXTER AVE N SEATTLE WA 98109	NE	0.73 / 3,831.49	276
Block 38 West	520 Westlake Ave N Seattle WA 98109	ENE	0.75 / 3,979.68	281
Block 79 East	701 9TH AVE N SEATTLE WA 98109	NE	0.78 / 4,112.63	287

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Ivars Commissary	500 TERRY AVE N SEATTLE WA 98109	ENE	0.79 / 4,176.53	290
Block 37	600 WESTLAKE AVE N SEATTLE WA 98109	ENE	0.81 / 4,299.01	298
Seattle Steam Co Western Ave	1319 WESTERN AVE SEATTLE WA 98101	SE	0.83 / 4,368.01	303
Auto Service Company	630 WESTLAKE AVE N SEATTLE WA 98109	NE	0.84 / 4,415.51	305
Mastercraft Metal Finishing	1175 HARRISON ST SEATTLE WA 98109	ENE	0.88 / 4,639.38	318

CSCSL - Confirmed and Suspected Contaminated Sites List

A search of the CSCSL database, dated Aug 22, 2022 has found that there are 148 CSCSL site(s) within approximately 1.00 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Martin Selig Property	2601 4TH AVE SEATTLE WA 98121	ENE	0.12 / 629.45	34
Edwards on Fifth	2619 5TH AVE SEATTLE WA 98121	ENE	0.19 / 1,002.02	69
Faulkenbury & Wright	501 DENNY WAY SEATTLE WA 98109	ENE	0.21 / 1,118.54	83
Pacific Science Center UST Denny & Broad	200 2ND AVE N SEATTLE WA 98109	NW	0.22 / 1,184.23	90
Holman Body & Fender	2324 2ND AVE SEATTLE WA 98121	ESE	0.23 / 1,201.53	93
Da Li 5th Avenue Development	124 - 130 5TH AVE N SEATTLE WA 98109	NE	0.23 / 1,217.55	95
Taylor & Denny Building	101 TAYLOR AVE N SEATTLE WA 98109	ENE	0.24 / 1,275.61	104

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Archstone Belltown	500 WALL ST SEATTLE WA 98121	ENE	0.24 / 1,284.97	105
Fifth & Broad	417 BROAD ST SEATTLE WA 98109	NE	0.25 / 1,304.95	106
Seattle Fire Station 2	2334 4TH AVE SEATTLE WA 98121	E	0.26 / 1,354.65	110
Second & Bell Building LLC	2306 2ND AVE SEATTLE WA 98121	ESE	0.26 / 1,379.92	112
Ride the Ducks	516 BROAD ST SEATTLE WA 98109	NE	0.28 / 1,479.78	120
Japanese Auto Clinic	600 DENNY WAY SEATTLE WA 98109	ENE	0.30 / 1,583.60	129
600 Wall Street	600 WALL ST SEATTLE WA 98121	ENE	0.30 / 1,607.90	132
Phom Property	2301 4th Ave / 314 Bell St SEATTLE WA 98121	E	0.31 / 1,620.12	135
Lewiston Hotel	2201 1ST AVE SEATTLE WA 98121	SE	0.36 / 1,891.41	154
Rexland Co	2126 3RD AVE SEATTLE WA 98121	ESE	0.39 / 2,060.44	164
Astro Apartments	315 1ST AVE N SEATTLE WA 98109	NW	0.40 / 2,094.96	170
Seattle Center	305 HARRISON ST SEATTLE WA 98109	NW	0.41 / 2,157.12	178
Lenora Holdings	2031 3RD AVE SEATTLE WA 98121	ESE	0.47 / 2,456.05	202

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Martin Apartments	2101 2105 & 2111 5TH AVE SEATTLE WA 98121	ESE	0.47 / 2,481.50	205
Sterling Realty Organization Co	2101-2111 5TH AVE SEATTLE WA 98121	ESE	0.48 / 2,521.17	208
Barg French Cleaners	1929 3RD AVE SEATTLE WA 98101	ESE	0.55 / 2,924.95	233
Texaco Pro Investments	150 Mercer St / 600 Warren Ave N SEATTLE WA 98109	NNW	0.55 / 2,926.82	234
4th & Virginia	1920 4TH AVE SEATTLE WA 98101	ESE	0.56 / 2,980.94	235
Uptown Bakery	513-525 QUEEN ANNE AVE N SEATTLE WA 98119	NW	0.57 / 2,992.49	236
First & Stewart Hotel Owner LLC	1916 1ST AVE SEATTLE WA 98101	SE	0.57 / 3,025.25	237
Queen Anne Properties Mercer St	541 QUEEN ANNE AVE N SEATTLE WA 98109	NW	0.57 / 3,033.03	238
Second Avenue Garage	1915 2ND AVE SEATTLE WA 98101	ESE	0.58 / 3,054.66	241
Viktoria Apartments	1915 2ND AVE SEATTLE WA 98101	ESE	0.58 / 3,054.66	241
Seattle Opera Parking	620 2ND AVE N SEATTLE WA 98109	NNW	0.59 / 3,103.10	242
St Regis Hotel	116 STEWART ST SEATTLE WA 98101	ESE	0.60 / 3,186.59	249
Unocal 306568	700 QUEEN ANNE AVE N SEATTLE WA 98109	NW	0.66 / 3,494.40	263

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Texaco 211577 Monterey	631 QUEEN ANNE AVE N SEATTLE WA 98109	NW	0.66 / 3,504.36	265
MONTEREY APARTMENTS	622 1ST AVE W & QUEEN AVE N SEATTLE WA 98119	NW	0.67 / 3,523.61	266
Federal Courthouse	700 STEWART ST SEATTLE WA 98101	E	0.69 / 3,664.88	272
City Mini Storage	2000 TERRY AVE & 1000 VIRGINIA ST SEATTLE WA 98121	E	0.72 / 3,815.25	275
Stewart Court Apartments	1835 8TH AVE SEATTLE WA 98101	E	0.73 / 3,841.51	277
818 Stewart St	818 STEWART ST SEATTLE WA 98101	E	0.74 / 3,889.33	278
Seattle Times	1120 JOHN ST SEATTLE WA 98109	E	0.76 / 3,998.58	283
Seattle Times Parcel 1B	100 FAIRVIEW AVE SEATTLE WA 98109	E	0.77 / 4,045.51	286
8th & Howell	808 HOWELL ST SEATTLE WA 98101	E	0.79 / 4,185.63	291
Red Carpet Car Wash	1164 DENNY WAY SEATTLE WA 98109	E	0.80 / 4,249.17	295
Cascade 1 & 2 Apartments	Minor & Fairview Ave N Thomas & John Seattle WA 98109	ENE	0.82 / 4,323.01	299
Oden Investment Condos	619 5TH AVE W SEATTLE WA 98119	NW	0.83 / 4,407.43	304
Crescent Heights	1901 - 1933 Minor Ave SEATTLE WA 98101	E	0.84 / 4,436.57	306

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
WA State Convention & Trade Center	8TH & PINE SEATTLE WA 98101	ESE	0.84 / 4,441.52	307
Goodyear Stewart St	1105 STEWART ST SEATTLE WA 98101	E	0.84 / 4,441.61	308
Seattle Cancer Care Alliance House	1216 JOHN ST SEATTLE WA 98109	E	0.88 / 4,646.91	319
Washington Athletic Club Garage	1405 6TH AVE SEATTLE WA 98101	ESE	0.89 / 4,673.80	321
Greyhound Denny Way	1250 DENNY WAY SEATTLE WA 98109	E	0.89 / 4,680.61	322
Paramount Theatre	911 PINE ST SEATTLE WA 98101	E	0.90 / 4,730.26	323
Tritell Parking Lot	1821-1823 MINOR AVE SEATTLE WA 98101	E	0.90 / 4,757.37	325
New Richmond Laundry	224 PONTIUS ST N SEATTLE WA 98109	E	0.91 / 4,826.28	327
Alley 24 West LLC	224 PONTIUS AVE N SEATTLE WA 98109	E	0.91 / 4,826.28	327
Qwest W00294	1200 3RD AVE SEATTLE WA 98104	ESE	0.95 / 5,030.76	332
Seattle Hilton Hotel Parking Garage	1301 6TH AVE SEATTLE WA 98101	ESE	0.96 / 5,045.15	333
Pemco Property	221 YALE AVE N SEATTLE WA 98109	E	0.96 / 5,063.88	334
Overall Laundry	200 222 YALE AVE N SEATTLE WA 98109	E	0.96 / 5,068.94	335

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Seattle SD Warehouse	1255 Harrison St Seattle WA 98109	ENE	0.97 / 5,099.54	336
Tomlinson UST 101457 Block 10	414 420 Pontius Ave N & 1260 Harrison Seattle WA 98109	ENE	0.98 / 5,162.16	337
First Choice Business Machines	1333 STEWART ST SEATTLE WA 98109	E	0.99 / 5,247.01	340
Yale & Harrison Development	300-320 Yale Ave N & 325 Eastlake Ave E SEATTLE WA 98109	ENE	1.00 / 5,263.38	341

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Unocal Seattle Market Lower	BN ELLIOTT RR BAY & BROAD SEATTLE WA 98121	W	0.16 / 844.14	51
UNOCAL Seattle Marketing Terminal	BROAD ST & WESTERN AVE & BAY ST SEATTLE WA 98121	W	0.16 / 844.14	51
Unocal 0355	159 DENNY WAY SEATTLE WA 98109	WNW	0.18 / 945.58	60
Elliott & Broad	10 BROAD ST SEATTLE WA 98121	WSW	0.19 / 1,017.60	74
Graphicolor Inc	3018 WESTERN AVE SEATTLE WA 98121	W	0.21 / 1,117.79	82
Champion-Teutsch	124 DENNY WAY SEATTLE WA 98109	WNW	0.22 / 1,143.70	86
Denny & Warren Petrol Plume	101 DENNY WAY SEATTLE WA 98109	WNW	0.22 / 1,162.18	88
Unocal Elliott Ave N of Bay St GW Plume	ELLIOTT AVE & BAY ST NEC SEATTLE WA 98121	W	0.27 / 1,449.04	119

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Port of Seattle Pier 66	2201 ALASKAN WAY TERM 66 PIERCE MARINE SEATTLE WA 98121	SSE	0.35 / 1,851.81	148
2200 Western Avenue LLC	2200 Western Ave Seattle WA 98121	SE	0.36 / 1,875.55	151
Basil Lee	505 HARRISON ST SEATTLE WA 98109	NNE	0.39 / 2,077.96	167
Elliott Bay Bicycles	2114 WESTERN AVE SEATTLE WA 98121	SE	0.42 / 2,219.31	185
King County Denny Way CSO	3165 ALASKAN WAY SEATTLE WA 98121	WNW	0.42 / 2,236.09	187
Uptown Flats Queen Anne	300 1ST AVE W SEATTLE WA 98119	WNW	0.44 / 2,338.32	194
Block 18 Amazon Frontier	2205 7TH Avenue SEATTLE WA 98121	E	0.46 / 2,444.32	201
Seattle Vagabond Inn	325 AURORA AVE N SEATTLE WA 98109	NE	0.47 / 2,459.32	203
Seattle Mercer Ops Base	520 5TH AVE N SEATTLE WA 98109	NNE	0.49 / 2,565.68	215
Unocal Myrtle Edwards Park	3130 ALASKAN WAY W SEATTLE WA 98121	WNW	0.51 / 2,676.99	226
Block 21 Amazon 8th & Bell	2205 8TH AVE SEATTLE WA 98121	E	0.51 / 2,700.42	228
Block 20 8th & Blanchard	2101 2121 8th Ave & 2130 2100 7th Ave Seattle WA 98121	E	0.53 / 2,798.69	229
Dexter Office Building	400 DEXTER AVE N SEATTLE WA 98109	ENE	0.54 / 2,832.36	231

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Standish Property	420 MERCER ST SEATTLE WA 98109	NNE	0.55 / 2,877.70	232
Pier 63 Sediments	1915 ALASKAN WAY SEATTLE WA 98101	SE	0.57 / 3,034.40	239
Kenney Property	100 WESTLAKE AVE N SEATTLE WA 98109	E	0.58 / 3,036.05	240
Nash Holland Denny Investors	964 970 DENNY WAY SEATTLE WA 98109	E	0.59 / 3,107.75	243
Seattle Center Property	601-615 MERCER ST SEATTLE WA 98109	NE	0.59 / 3,113.84	244
9th Space	308 9TH AVE N SEATTLE WA 98109	ENE	0.59 / 3,131.47	245
Coleman Creosoting Works	333 ELLIOTT AVE W SEATTLE WA 98119	WNW	0.60 / 3,161.27	248
Block 52 East	333 9TH AVE N SEATTLE WA 98109	ENE	0.61 / 3,200.91	250
PCY Corp	601 6TH AVE N SEATTLE WA 98109	NE	0.61 / 3,216.47	251
Lenora Building	2101 9TH AVE SEATTLE WA 98121	E	0.61 / 3,224.00	252
Greiling Property	222 WESTLAKE AVE N SEATTLE WA 98109	ENE	0.62 / 3,259.01	253
202 Westlake Office Building	202 WESTLAKE AVE N SEATTLE WA 98109	ENE	0.62 / 3,259.01	253
West 8th Building	718 VIRGINIA ST & 2001 8TH AVE SEATTLE WA 98121	E	0.62 / 3,272.53	254

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Chevron Vacant Site	707 TAYLOR AVE N 700 5TH AVE N SEATTLE WA 98109	NNE	0.63 / 3,323.84	255
Seattle City ROW behind 222 Westlake N	ALLEY 222 WESTLAKE & 219 TERRY AVES N SEATTLE WA 98109	ENE	0.63 / 3,328.29	256
Seattle DOT Promenade & Overlook Walk	1500 1524 1528 ALASKAN WAY SEATTLE WA 98101	SE	0.65 / 3,414.65	258
United Furniture Refinishers	219 TERRY AVE N SEATTLE WA 98109	ENE	0.65 / 3,433.49	259
Bayless Book Bindery	427 9TH AVE N SEATTLE WA 98109	ENE	0.65 / 3,446.36	260
Block 40 East & West Westlake & Terry	320 WESTLAKE AVE N SEATTLE WA 98109	ENE	0.65 / 3,446.84	261
Broad Street Alignment Contaminated Fill	DEXTER AVE N & MERCER ST SEATTLE WA 98102	NE	0.65 / 3,449.87	262
Gilead Sciences Inc	410 W HARRISON ST 2ND FLOOR SEATTLE WA 98119	WNW	0.66 / 3,496.38	264
601 Dexter	601 DEXTER AVE N SEATTLE WA 98109	NE	0.67 / 3,542.80	267
1918 Eighth Office Tower	1918 8TH AVE SEATTLE WA 98101	E	0.67 / 3,544.11	268
Dollar Rent a Car	7TH & STEWART SEATTLE WA 98101	E	0.68 / 3,603.76	269
Firestone Tire & Rubber Co	400 WESTLAKE AVE N SEATTLE WA 98109	ENE	0.68 / 3,604.52	270
Seattle DOT Dexter Parcel	615 DEXTER AVE N SEATTLE WA 98109	NE	0.69 / 3,619.17	271

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Seattle DOT Mercer Parcels	800 MERCER ST SEATTLE WA 98109	NE	0.72 / 3,779.34	273
701 Dexter	701 DEXTER AVE N SEATTLE WA 98109	NE	0.72 / 3,811.48	274
American Linen Supply Co Dexter Ave	700 DEXTER AVE N SEATTLE WA 98109	NE	0.73 / 3,831.49	276
Seattle Roy Aloha Shops	802 ROY ST SEATTLE WA 98109	NE	0.75 / 3,947.06	280
Block 38 West	520 Westlake Ave N Seattle WA 98109	ENE	0.75 / 3,979.68	281
Lake Union III	410 TERRY N 415 BOREN N SEATTLE WA 98109	ENE	0.75 / 3,982.54	282
Rosen Property	960 REPUBLICAN ST SEATTLE WA 98109	ENE	0.76 / 4,035.61	284
Maryatt Industries	771 VALLEY ST SEATTLE WA 98109	NE	0.77 / 4,042.16	285
Block 79 East	701 9TH AVE N SEATTLE WA 98109	NE	0.78 / 4,112.63	287
Seattle SD 1 Facilities Bldg	810 DEXTER AVE N SEATTLE WA 98109	NE	0.78 / 4,142.85	288
Pier 58 Sediments	1401 ALASKAN WAY SEATTLE WA 98101	SE	0.78 / 4,143.65	289
Ivars Commissary	500 TERRY AVE N SEATTLE WA 98109	ENE	0.79 / 4,176.53	290
AIBS Building Block 43	601 WESTLAKE AVE N SEATTLE WA 98109	NE	0.80 / 4,198.75	292

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Seattle City DOT ROW 710 9th Ave N	710 9TH AVE N SEATTLE WA 98109	NE	0.80 / 4,238.40	293
Moxy Hotel	1016 REPUBLICAN ST SEATTLE WA 98109	ENE	0.80 / 4,245.61	294
South Lake Union 293 Parcel A	424 BOREN AVE N SEATTLE WA 98109	ENE	0.81 / 4,262.76	297
Block 37	600 WESTLAKE AVE N SEATTLE WA 98109	ENE	0.81 / 4,299.01	298
525 Boren Building	525 BOREN AVE N SEATTLE WA 98109	ENE	0.82 / 4,333.90	300
Maaco Auto Painting Bodywork 9th Ave	739 9TH AVE N SEATTLE WA 98109	NE	0.82 / 4,337.49	301
Troy Laundry Seattle	399 FAIRVIEW AVE N SEATTLE WA 98109	ENE	0.83 / 4,358.45	302
Seattle Steam Co Western Ave	1319 WESTERN AVE SEATTLE WA 98101	SE	0.83 / 4,368.01	303
Auto Service Company	630 WESTLAKE AVE N SEATTLE WA 98109	NE	0.84 / 4,415.51	305
Jarvie Paint	760 ALOHA ST SEATTLE WA 98109	NE	0.84 / 4,443.47	309
400 Fairview LLC Seattle	412 Fairview Ave N Seattle WA 98109	ENE	0.85 / 4,491.52	310
Neptune Apartments proposed	900 912 DEXTER AVE N SEATTLE WA 98121	NE	0.85 / 4,495.30	311
Block 32 North Bldg City Place III LLC	1001 & 1021 Mercer St 500 Terry Ave N Seattle WA 98109	ENE	0.85 / 4,511.05	313

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Blackstock Lumber	601 Elliott Ave W Seattle WA 98119	WNW	0.86 / 4,524.17	314
Shell 23714	601 BOREN AVE N SEATTLE WA 98109	ENE	0.87 / 4,600.01	316
Immunex Corporation 51 U	51 UNIVERSITY ST SEATTLE WA 98101	SE	0.87 / 4,614.53	317
Mastercraft Metal Finishing	1175 HARRISON ST SEATTLE WA 98109	ENE	0.88 / 4,639.38	318
Staybridge Suite Even Hotel	527 FAIRVIEW AVE N SEATTLE WA 98109	ENE	0.88 / 4,667.83	320
Seattle S Lake Union Park	1000 VALLEY ST 815 BOREN AVE N SEATTLE WA 98109	ENE	0.90 / 4,738.21	324
Central Seattle Waterfront	PIERS 53-58 ALASKAN WAY SEATTLE WA 98101	SE	0.91 / 4,791.06	326
Cascade Supportive Housing	424 MINOR AVE N SEATTLE WA 98109	ENE	0.93 / 4,894.82	329
Seattle City Parks NW Seaport	1002 VALLEY ST SEATTLE WA 98109	NE	0.93 / 4,895.52	330
Kerner Scott Building	510 MINOR AVE N SEATTLE WA 98109	ENE	0.95 / 5,025.27	331
Seattle City South Lake Union Naval Reserve Ctr	860 TERRY AVE N SEATTLE WA 98109	NE	0.98 / 5,166.64	338
Elliott Holding Company LLC	635 Elliott Ave W Seattle WA 98119	WNW	0.98 / 5,195.13	339

DELISTED SHWS - Delisted Confirmed and Suspected Contaminated Sites

A search of the DELISTED SHWS database, dated Aug 22, 2022 has found that there are 25 DELISTED SHWS site(s) within approximately 1.00 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
303 Battery	2330 3RD AVE SEATTLE WA	ESE	0.23 / 1,200.38	92
3rd Ave Redevelopment	2211 2217 3RD AVE SEATTLE WA 98121	ESE	0.34 / 1,779.72	141
MONTEREY APARTMENTS	622 1ST AVE W & QUEEN AVE N SEATTLE WA 98119	NW	0.67 / 3,523.61	266
MONTEREY APARTMENTS	622 1ST AVE W & QUEEN AVE N SEATTLE WA 98119	NW	0.67 / 3,523.61	266
Boren and Lenora	2019 - 2031 BOREN AVE SEATTLE WA 98121	E	0.74 / 3,896.87	279
Creases Dry Cleaner	1820 TERRY AVE SEATTLE WA 98101	E	0.81 / 4,252.57	296
Freymuller Enterprises	1108 AURORA AVE N SEATTLE WA 98109	NNE	0.91 / 4,828.71	328
PEMCO Property	221 YALE AVE SEATTLE WA 98109	E	0.96 / 5,063.88	334
PEMCO Parking Concrete Cutter	300-320 Yale Ave N & 325 Eastlake Ave E SEATTLE WA 98109	ENE	1.00 / 5,263.38	341
PEMCO Parking Concrete Cutter	300-320 Yale Ave N & 325 Eastlake Ave E SEATTLE WA 98109	ENE	1.00 / 5,263.38	341

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
ONCOGEN	3005 1ST AVE SEATTLE WA 98121	WNW	0.17 / 912.96	55
Bristol Myers Squibb	WA	WNW	0.18 / 943.25	59
2200 Western Avenue LLC	2200 Western Ave Seattle WA 98121	SE	0.36 / 1,875.55	151

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Western and Blanchard Property	WA	SE	0.39 / 2,073.47	165
Western and Blanchard Property	2134 Western Avenue Seattle WA 98121	SE	0.40 / 2,101.90	171
IRIS Holding LLC	WA	NNE	0.44 / 2,306.67	191
IRIS Holding LLC	500 5TH AVE N SEATTLE WA 98109	NNE	0.50 / 2,618.41	220
8th & Thomas JV LLC	777 THOMAS ST SEATTLE WA 98109	ENE	0.51 / 2,699.58	227
Block 19 7th & Lenora	2101 7TH AVE SEATTLE WA 98119	E	0.53 / 2,806.15	230
Westlake Chevrolet	2030 8TH AVE SEATTLE WA 98121	E	0.60 / 3,146.31	246
Budget Rent A Car Westlake	2001 WESTLAKE AVE SEATTLE WA 98121-2605	E	0.60 / 3,147.70	247
West 8th Building	718 VIRGINIA ST & 2001 8TH AVE SEATTLE WA 98121	E	0.62 / 3,272.53	254
Western & University Property	WA	SE	0.85 / 4,503.78	312
Western & University Property	50 UNIVERSITY ST SEATTLE WA 98101	SE	0.86 / 4,556.50	315
Seattle S Lake Union Park	1000 VALLEY ST 815 BOREN AVE N SEATTLE WA 98109	ENE	0.90 / 4,738.21	324

CSCSL NFA - No Further Action Sites List

A search of the CSCSL NFA database, dated Aug 22, 2022 has found that there are 38 CSCSL NFA site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Pacific Science Center Frol Building	204 DENNY WAY SEATTLE WA 98109	NW	0.15 / 771.91	48
Fisher Plaza KOMO TV	100 4TH AVE N SEATTLE WA 98109	NE	0.18 / 940.23	58
Chevron 97032	5TH AVE & DENNY WAY NW CORNER SEATTLE WA 98109	ENE	0.18 / 968.73	64
Parson Seatrust Partnership	400 WALL ST SEATTLE WA 98121	E	0.21 / 1,099.70	80
303 Battery	303 BATTERY ST SEATTLE WA 98121	ESE	0.22 / 1,151.76	87
Fountain Court Apartments	2400 4TH AVE SEATTLE WA 98121	E	0.23 / 1,216.71	94
Seattle Post Intelligencer	521 WALL ST SEATTLE WA 98121	E	0.27 / 1,408.52	114
BRE Properties Inc	552 DENNY WAY & 553 JOHN ST SEATTLE WA 98109	ENE	0.27 / 1,415.34	117
First & Bell	2233 1ST AVE SEATTLE WA 98121	SE	0.30 / 1,573.67	128
Japanese Auto Clinic	600 DENNY WAY SEATTLE WA 98109	ENE	0.30 / 1,583.60	129
Stadium Shell	620 DENNY WAY SEATTLE WA 98109	ENE	0.32 / 1,701.58	138
3rd Ave Redevelopment	2211 2217 3RD AVE SEATTLE WA 98121	ESE	0.33 / 1,762.15	140

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Elephant Car Wash	616 Battery St Seattle WA 98121	E	0.35 / 1,867.33	150
Neuffer Construction	5TH & BLANCHARD SEATTLE WA 98121	E	0.41 / 2,176.44	180
OLD BRITISH MOTORCAR	7TH & BELL SEATTLE WA 98121	E	0.42 / 2,236.45	188
Potala Tower Seattle	2116 4TH AVE SEATTLE WA 98121	ESE	0.44 / 2,308.82	192
USPS Queen Anne	415 1ST AVE N SEATTLE WA 98109	NW	0.48 / 2,556.68	212
Jiffy Lube Store 2077	2025 4TH AVE SEATTLE WA 98121	ESE	0.49 / 2,564.21	214
Sixth & Lenora Apartments	2121 6TH AVE SEATTLE WA 98121	E	0.50 / 2,622.04	222

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
The Olympus	2801 WESTERN AVE SEATTLE WA 98121	WSW	0.11 / 577.56	21
Vine Building	2607 WESTERN AVE SEATTLE WA 98121	S	0.12 / 621.29	32
Cottage Properties	VINE ST SEATTLE WA 98121	SSE	0.12 / 637.31	35
Sailors Union of the Pacific Building	2505 1ST AVE SEATTLE WA 98121	SSE	0.13 / 689.65	41
NORTHWEST PROTECTIVE SERVICE	2700 ELLIOTT AVE SEATTLE WA 98121	SW	0.14 / 723.90	43
Bristol Myers Squibb	3005 1ST AVE SEATTLE WA 98121	WNW	0.17 / 912.96	55

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Belltown Pea Patch	ELLIOTT AVE & VINE ST SEATTLE WA 98121	SSW	0.18 / 931.76	57
Belltown Court Condos	2400 1ST AVE SEATTLE WA 98121	SE	0.19 / 1,005.13	71
Ivars Seafood Bar	3101 1ST AVE SEATTLE WA 98121	WNW	0.24 / 1,268.70	102
Valco Graphics Inc Western Ave	3104 WESTERN AVE SEATTLE WA 98121	WNW	0.26 / 1,367.35	111
55 Battery LLC	2334 ELLIOTT AVE / 55 BATTERY ST SEATTLE WA 98121	SSE	0.27 / 1,411.12	116
Shell Station 121702	10 DENNY WAY SEATTLE WA 98109	WNW	0.29 / 1,552.46	127
133 Queen Anne Property	133 QUEEN ANNE AVE N SEATTLE WA 98109	WNW	0.34 / 1,790.09	142
Barrat Transfer & Storage	123 QUEEN ANNE AVE N SEATTLE WA 98109	WNW	0.34 / 1,817.77	144
2200 Western Avenue LLC	2200 Western Ave Seattle WA 98121	SE	0.36 / 1,875.55	151
Western and Blanchard Property	2134 Western Ave Seattle WA 98121	SE	0.40 / 2,101.90	171
Bay View Building	129 1ST AVE W SEATTLE WA 98119	WNW	0.40 / 2,119.04	175
Seattle Waterfront Marriott Hotel	2100 ALASKAN WAY SEATTLE WA 98121	SSE	0.45 / 2,352.02	197
IRIS Holding LLC	500 5TH AVE N SEATTLE WA 98109	NNE	0.50 / 2,618.41	220

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key

SWF/LF - Solid Waste Facility Database

A search of the SWF/LF database, dated Sep 8, 2022 has found that there are 2 SWF/LF site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Konankada Inc., dba: Seattle Micro	2310 4th Ave Seattle WA 98121-1718	E	0.28 / 1,503.26	122
Action Small Appliance	2125 2nd Ave Seattle WA 98121	ESE	0.39 / 2,049.37	163

RECYCLERS - Recycling Facilities

A search of the RECYCLERS database, dated Sep 16, 2020 has found that there are 2 RECYCLERS site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
DOWNTOWN PUBLIC HEALTH CENTER	2124 4TH AVE SEATTLE WA 98121	ESE	0.40 / 2,119.38	176
THE MAIL BOX	300 LENORA ST. SEATTLE WA 98121	ESE	0.45 / 2,382.08	199

LUST - Leaking Underground Storage Tank (LUST) List

A search of the LUST database, dated Aug 22, 2022 has found that there are 33 LUST site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Fisher Plaza KOMO TV	100 4TH AVE N SEATTLE WA 98109 ***Facility Site ID**: 15636867*	NE	0.18 / 940.23	58
Chevron 97032	5TH AVE & DENNY WAY NW CORNER SEATTLE WA 98109 ***Facility Site ID**: 18935188*	ENE	0.18 / 968.73	64
Parson Seatrust Partnership	400 WALL ST SEATTLE WA 98121 ***Facility Site ID**: 2543*	E	0.21 / 1,099.70	80
Pacific Science Center UST Denny & Broad	200 2ND AVE N SEATTLE WA 98109 ***Facility Site ID**: 2868852*	NW	0.22 / 1,184.23	90

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Holman Body & Fender	2324 2ND AVE SEATTLE WA 98121 ***Facility Site ID**: 33457373*	ESE	0.23 / 1,201.53	**93**
Fifth & Broad	417 BROAD ST SEATTLE WA 98109 ***Facility Site ID**: 21907*	NE	0.25 / 1,304.95	**106**
Seattle Fire Station 2	2334 4TH AVE SEATTLE WA 98121 ***Facility Site ID**: 29958424*	E	0.26 / 1,354.65	**110**
Japanese Auto Clinic	600 DENNY WAY SEATTLE WA 98109 ***Facility Site ID**: 84772579*	ENE	0.30 / 1,583.60	**129**
Phom Property	2301 4th Ave / 314 Bell St SEATTLE WA 98121 ***Facility Site ID**: 47763267*	E	0.31 / 1,620.12	**135**
Stadium Shell	620 DENNY WAY SEATTLE WA 98109 ***Facility Site ID**: 41751629*	ENE	0.32 / 1,701.58	**138**
Elephant Car Wash	616 Battery St Seattle WA 98121 ***Facility Site ID**: 66184117*	E	0.35 / 1,867.33	**150**
Rexland Co	2126 3RD AVE SEATTLE WA 98121 ***Facility Site ID**: 54147485*	ESE	0.39 / 2,060.44	**164**
Seattle Center	305 HARRISON ST SEATTLE WA 98109 ***Facility Site ID**: 42937592*	NW	0.41 / 2,157.12	**178**
Neuffer Construction	5TH & BLANCHARD SEATTLE WA 98121 ***Facility Site ID**: 77948398*	E	0.41 / 2,176.44	**180**
OLD BRITISH MOTORCAR	7TH & BELL SEATTLE WA 98121 ***Facility Site ID**: 47192364*	E	0.42 / 2,236.45	**188**
Sterling Realty Organization Co	2101-2111 5TH AVE SEATTLE WA 98121 ***Facility Site ID**: 92546394*	ESE	0.48 / 2,521.17	**208**
USPS Queen Anne	415 1ST AVE N SEATTLE WA 98109 ***Facility Site ID**: 31537996*	NW	0.48 / 2,556.68	**212**

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Jiffy Lube Store 2077	2025 4TH AVE SEATTLE WA 98121 ***Facility Site ID**: 31325769*	ESE	0.49 / 2,564.21	**214**

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
The Olympus	2801 WESTERN AVE SEATTLE WA 98121 ***Facility Site ID**: 35216721*	WSW	0.11 / 577.56	**21**
Sailors Union of the Pacific Building	2505 1ST AVE SEATTLE WA 98121 ***Facility Site ID**: 42839734*	SSE	0.13 / 689.65	**41**
NORTHWEST PROTECTIVE SERVICE	2700 ELLIOTT AVE SEATTLE WA 98121 ***Facility Site ID**: 77333528*	SW	0.14 / 723.90	**43**
Bristol Myers Squibb	3005 1ST AVE SEATTLE WA 98121 ***Facility Site ID**: 21448945*	WNW	0.17 / 912.96	**55**
Unocal 0355	159 DENNY WAY SEATTLE WA 98109 ***Facility Site ID**: 32873776*	WNW	0.18 / 945.58	**60**
Graphicolor Inc	3018 WESTERN AVE SEATTLE WA 98121 ***Facility Site ID**: 23682319*	W	0.21 / 1,117.79	**82**
Valco Graphics Inc Western Ave	3104 WESTERN AVE SEATTLE WA 98121 ***Facility Site ID**: 19521513*	WNW	0.26 / 1,367.35	**111**
55 Battery LLC	2334 ELLIOTT AVE / 55 BATTERY ST SEATTLE WA 98121 ***Facility Site ID**: 16772747*	SSE	0.27 / 1,411.12	**116**
Shell Station 121702	10 DENNY WAY SEATTLE WA 98109 ***Facility Site ID**: 49674295*	WNW	0.29 / 1,552.46	**127**
133 Queen Anne Property	133 QUEEN ANNE AVE N SEATTLE WA 98109 ***Facility Site ID**: 95244754*	WNW	0.34 / 1,790.09	**142**
Barrat Transfer & Storage	123 QUEEN ANNE AVE N SEATTLE WA 98109 ***Facility Site ID**: 83727198*	WNW	0.34 / 1,817.77	**144**

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Port of Seattle Pier 66	2201 ALASKAN WAY TERM 66 PIERCE MARINE SEATTLE WA 98121 ***Facility Site ID**: 94766722*	SSE	0.35 / 1,853.03	149
Basil Lee	505 HARRISON ST SEATTLE WA 98109 ***Facility Site ID**: 79418734*	NNE	0.39 / 2,077.96	167
Seattle Waterfront Marriott Hotel	2100 ALASKAN WAY SEATTLE WA 98121 ***Facility Site ID**: 1938238*	SSE	0.45 / 2,352.02	197
Seattle Mercer Ops Base	520 5TH AVE N SEATTLE WA 98109 ***Facility Site ID**: 8984*	NNE	0.49 / 2,565.68	215

LUST PTAP - Petroleum Technical Assistance Program

A search of the LUST PTAP database, dated Jun 21, 2022 has found that there are 4 LUST PTAP site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
303 Battery	2330 3rd Avenue, Seattle, WA WA	ESE	0.23 / 1,200.38	92
600 Wall Street	600 Wall Street,Seattle, WA 98121 WA	ENE	0.30 / 1,607.90	132
Lenora Holdings	2031 3rd Avenue, Seattle, WA 98121 WA	ESE	0.47 / 2,456.05	202

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Unocal 0355	159 Denny Way, Seattle, WA 98109 WA	WNW	0.18 / 945.58	60

LST HOT - Heating Oil Technical Assistance Program

A search of the LST HOT database, dated Jun 22, 2022 has found that there are 1 LST HOT site(s) within approximately 0.50 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
THE RILEY GROUP	215 8TH AVE N SEATTLE WA	ENE	0.50 / 2,615.46	218

UST - Underground Storage Tanks

A search of the UST database, dated Aug 22, 2022 has found that there are 21 UST site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
THIRD AVENUE PRODUCTIONS	2720 3RD AVE Seattle WA 98121	NE	0.07 / 371.39	10
	***UST ID | Site Active**: 11732 | No* ***Tank Name | Tank Status**: 1 | Removed*			
COX MEDIA GROUP SEATTLE	2807 3RD AVE Seattle WA 98121	N	0.08 / 419.66	14
	***UST ID | Site Active**: 12511 | Yes* ***Tank Name | Tank Status**: 2 | Removed, 7867 | Operational*			
DEAN STRALEY'S BP	351 BROAD ST Seattle WA 98109	NNE	0.14 / 721.11	42
	***UST ID | Site Active**: 8217 | Yes* ***Tank Name | Tank Status**: 1 | Operational, 3 | Operational, 4 | Operational, 2 | Operational*			
THE FAMOUS PACIFIC DESSERT COMPANY	420 DENNY WAY Seattle WA 98109	NE	0.16 / 820.79	50
	***UST ID | Site Active**: 2732 | No* ***Tank Name | Tank Status**: 1. | Closed in Place*			
KOMO RADIO & TV	100 4TH AVE N Seattle WA 98109	NE	0.18 / 940.23	58
	***UST ID | Site Active**: 7404 | No* ***Tank Name | Tank Status**: 2 | Removed, 1 | Removed, 4 | Removed, 5 | Removed, 3 | Removed*			
CHEVRON 97032	5TH AVE & DENNY WAY Seattle WA 98109	ENE	0.18 / 968.73	64
	***UST ID | Site Active**: 453155 | No* ***Tank Name | Tank Status**: 1 | Removed*			
KEY LOCK PARKING LOT	400 WALL ST Seattle WA 98109	E	0.21 / 1,099.70	80
	***UST ID | Site Active**: 102119 | No* ***Tank Name | Tank Status**: 2 | Removed, 1 | Removed, 3 | Removed, 4 | Removed*			
303 Battery	303 Battery St Seattle WA 98121	ESE	0.22 / 1,151.76	87
	***UST ID | Site Active**: 620513 | No* ***Tank Name | Tank Status**: 1 | Removed*			
Pacific Science Center	200 2ND AVE N Seattle WA 98109	NW	0.22 / 1,184.23	90
	***UST ID | Site Active**: 619795 | No* ***Tank Name | Tank Status**: 1 | Removed*			
HOLMAN BODY AND FENDER	2324 2ND AVE Seattle WA 98121	ESE	0.23 / 1,201.53	93
	***UST ID | Site Active**: 323980 | No* ***Tank Name | Tank Status**: 1 | Removed*			
GROSVENOR HOUSE	505 VINE ST Seattle WA 98121	ENE	0.24 / 1,250.63	98
	***UST ID | Site Active**: 97226 | No* ***Tank Name | Tank Status**: TANK #2 | Removed, WASTEOIL | Removed, TANK #1 | Removed*			

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Fifth and Broad Property	417 BROAD ST Seattle WA 98109	NE	0.25 / 1,304.95	106

***UST ID | Site Active**: 620081 | No*
***Tank Name | Tank Status**: 1 | Unknown, 3 | Unknown, 5 | Unknown, 6 | Unknown, 2 | Unknown, 4 | Unknown*

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
FRANK JAMES AUTO & PEOPLES VOLKSWAGEN	2900-2922 1ST AVENUE Seattle WA 98121	W	0.08 / 421.07	15

***UST ID | Site Active**: 10214 | No*
***Tank Name | Tank Status**: 3 | Removed, 11 | Removed, 5 | Removed, 8 | Removed, 1 | Removed, 4 | Removed, 7 | Removed, 10 | Removed, 2 | Removed, 6 | Removed, 9 | Removed*

THE OLYMPUS	2801 WESTERN AVE Seattle WA 98121	WSW	0.11 / 577.56	21

***UST ID | Site Active**: 579191 | No*
***Tank Name | Tank Status**: 1 | Closed in Place*

CEDAR DEVELOPMENT LLC	2627 WESTERN AVE Seattle WA 98121	SSW	0.12 / 651.76	36

***UST ID | Site Active**: 542217 | No*
***Tank Name | Tank Status**: 1 | Removed*

SAILORS UNION OF THE PACIFIC BLDG	2505 1ST AVE Seattle WA 98121	SSE	0.13 / 689.65	41

***UST ID | Site Active**: 319027 | No*
***Tank Name | Tank Status**: 1 | Closed in Place*

NORTHWEST PROTECTIVE SERVICE INC	2700 ELLIOTT AVE Seattle WA 98121	SW	0.14 / 723.90	43

***UST ID | Site Active**: 1163 | No*
***Tank Name | Tank Status**: 1 | Removed, 2 | Removed*

3005 FIRST AVENUE	3005 1ST AVE Seattle WA 98121	WNW	0.17 / 912.96	55

***UST ID | Site Active**: 102205 | Yes*
***Tank Name | Tank Status**: 1 | Removed, 2 | Operational*

UNION OIL 0355	159 DENNY WAY Seattle WA 98109	WNW	0.18 / 945.58	60

***UST ID | Site Active**: 8421 | No*
***Tank Name | Tank Status**: TK 2 | Removed, TK 3 | Removed, TK 6 | Removed, 4 | Removed, 2 | Removed, 1 | Removed, TK 7 | Removed, TK 1 | Removed, 3 | Removed, TK 5 | Removed, TK 4 | Removed, TK 8 | Removed*

GRAPHICOLOR INC	3018 WESTERN AVE Seattle WA 98121	W	0.21 / 1,117.79	82

***UST ID | Site Active**: 6604 | No*
***Tank Name | Tank Status**: 1 | Closed in Place*

WRIGHT GROUP	65 BAY ST Seattle WA 98121	WNW	0.23 / 1,228.08	96

***UST ID | Site Active**: 9847 | No*
***Tank Name | Tank Status**: 1 | Removed*

DELISTED LST - Delisted Leaking Storage Tanks

A search of the DELISTED LST database, dated Aug 22, 2022 has found that there are 3 DELISTED LST site(s) within approximately

0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
ELEPHANT CAR WASH	616 BATTERY ST SEATTLE WA 98121-1538	E	0.35 / 1,867.33	150
Jiffy Lube Store 2077	2025 4TH AVE SEATTLE WA 98121	ESE	0.49 / 2,564.21	214

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
ONCOGEN	3005 1ST AVE SEATTLE WA 98121	WNW	0.17 / 912.96	55

INST - Environmental Covenants Institutional Controls

A search of the INST database, dated Aug 22, 2022 has found that there are 8 INST site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Fifth & Broad	417 BROAD ST SEATTLE WA 98109	NE	0.25 / 1,304.95	106
Jiffy Lube Store 2077	2025 4TH AVE SEATTLE WA 98121	ESE	0.49 / 2,564.21	214

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
UNOCAL Seattle Marketing Terminal	BROAD ST & WESTERN AVE & BAY ST SEATTLE WA 98121	W	0.16 / 844.14	51
Bristol Myers Squibb	3005 1ST AVE SEATTLE WA 98121	WNW	0.17 / 912.96	55
Graphicolor Inc	3018 WESTERN AVE SEATTLE WA 98121	W	0.21 / 1,117.79	82
2200 Western Avenue LLC	2200 Western Ave Seattle WA 98121	SE	0.36 / 1,875.55	151
Bay View Building	129 1ST AVE W SEATTLE WA 98119	WNW	0.40 / 2,119.04	175

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
IRIS Holding LLC	500 5TH AVE N SEATTLE WA 98109	NNE	0.50 / 2,618.41	220

VCP - Voluntary Cleanup Program

A search of the VCP database, dated Aug 22, 2022 has found that there are 41 VCP site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Pacific Science Center Frol Building	204 DENNY WAY SEATTLE WA 98109	NW	0.15 / 771.91	48
Fisher Plaza KOMO TV	100 4TH AVE N SEATTLE WA 98109	NE	0.18 / 940.23	58
Chevron 97032	5TH AVE & DENNY WAY NW CORNER SEATTLE WA 98109	ENE	0.18 / 968.73	64
Edwards on Fifth	2619 5TH AVE SEATTLE WA 98121	ENE	0.19 / 1,002.02	69
Fountain Court Apartments	2400 4TH AVE SEATTLE WA 98121	E	0.23 / 1,216.71	94
Da Li 5th Avenue Development	124 - 130 5TH AVE N SEATTLE WA 98109	NE	0.23 / 1,217.55	95
Taylor & Denny Building	101 TAYLOR AVE N SEATTLE WA 98109	ENE	0.24 / 1,275.61	104
Archstone Belltown	500 WALL ST SEATTLE WA 98121	ENE	0.24 / 1,284.97	105
Fifth & Broad	417 BROAD ST SEATTLE WA 98109	NE	0.25 / 1,304.95	106
Second & Bell Building LLC	2306 2ND AVE SEATTLE WA 98121	ESE	0.26 / 1,379.92	112

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
BRE Properties Inc	552 DENNY WAY & 553 JOHN ST SEATTLE WA 98109	ENE	0.27 / 1,415.34	117
First & Bell	2233 1ST AVE SEATTLE WA 98121	SE	0.30 / 1,573.67	128
Japanese Auto Clinic	600 DENNY WAY SEATTLE WA 98109	ENE	0.30 / 1,583.60	129
600 Wall Street	600 WALL ST SEATTLE WA 98121	ENE	0.30 / 1,607.90	132
3rd Ave Redevelopment	2211 2217 3RD AVE SEATTLE WA 98121	ESE	0.33 / 1,762.15	140
Elephant Car Wash	616 Battery St Seattle WA 98121	E	0.35 / 1,867.33	150
Lewiston Hotel	2201 1ST AVE SEATTLE WA 98121	SE	0.36 / 1,891.41	154
Martin Apartments	2101 2105 & 2111 5TH AVE SEATTLE WA 98121	ESE	0.47 / 2,481.50	205
USPS Queen Anne	415 1ST AVE N SEATTLE WA 98109	NW	0.48 / 2,556.68	212
Jiffy Lube Store 2077	2025 4TH AVE SEATTLE WA 98121	ESE	0.49 / 2,564.21	214

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
The Olympus	2801 WESTERN AVE SEATTLE WA 98121	WSW	0.11 / 577.56	21
Vine Building	2607 WESTERN AVE SEATTLE WA 98121	S	0.12 / 621.29	32
Bristol Myers Squibb	3005 1ST AVE SEATTLE WA 98121	WNW	0.17 / 912.96	55

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Unocal 0355	159 DENNY WAY SEATTLE WA 98109	WNW	0.18 / 945.58	60
Belltown Court Condos	2400 1ST AVE SEATTLE WA 98121	SE	0.19 / 1,005.13	71
Elliott & Broad	10 BROAD ST SEATTLE WA 98121	WSW	0.19 / 1,017.60	74
Graphicolor Inc	3018 WESTERN AVE SEATTLE WA 98121	W	0.21 / 1,117.79	82
Champion-Teutsch	124 DENNY WAY SEATTLE WA 98109	WNW	0.22 / 1,143.70	86
Ivars Seafood Bar	3101 1ST AVE SEATTLE WA 98121	WNW	0.24 / 1,268.70	102
Valco Graphics Inc Western Ave	3104 WESTERN AVE SEATTLE WA 98121	WNW	0.26 / 1,367.35	111
55 Battery LLC	2334 ELLIOTT AVE / 55 BATTERY ST SEATTLE WA 98121	SSE	0.27 / 1,411.12	116
Shell Station 121702	10 DENNY WAY SEATTLE WA 98109	WNW	0.29 / 1,552.46	127
133 Queen Anne Property	133 QUEEN ANNE AVE N SEATTLE WA 98109	WNW	0.34 / 1,790.09	142
2200 Western Avenue LLC	2200 Western Ave Seattle WA 98121	SE	0.36 / 1,875.55	151
Western and Blanchard Property	2134 Western Ave Seattle WA 98121	SE	0.40 / 2,101.90	171
Bay View Building	129 1ST AVE W SEATTLE WA 98119	WNW	0.40 / 2,119.04	175

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Uptown Flats Queen Anne	300 1ST AVE W SEATTLE WA 98119	WNW	0.44 / 2,338.32	194
Seattle Waterfront Marriott Hotel	2100 ALASKAN WAY SEATTLE WA 98121	SSE	0.45 / 2,352.02	197
Block 18 Amazon Frontier	2205 7TH Avenue SEATTLE WA 98121	E	0.46 / 2,444.32	201
Seattle Vagabond Inn	325 AURORA AVE N SEATTLE WA 98109	NE	0.47 / 2,459.32	203
IRIS Holding LLC	500 5TH AVE N SEATTLE WA 98109	NNE	0.50 / 2,618.41	220

County

UST SEATTLE - Seattle Underground Storage Tank (UST) - Residential

A search of the UST SEATTLE database, dated Jul 15, 2022 has found that there are 22 UST SEATTLE site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	225 CEDAR ST Seattle WA 98121	E	0.06 / 311.19	9
	***Permit No | Date Issued**: 3-89824 | 08/29/2012*			
	2703 3RD AVE Seattle WA 98109	ENE	0.07 / 372.20	11
	***Permit No | Date Issued**: 3-45657 | 01/21/2003*			
	2551 2ND AVE Seattle WA N/A	ESE	0.12 / 613.18	30
	***Permit No | Date Issued**: 3-36899 | 03/09/2001*			
	2530 2ND AVE Seattle WA 98119	ESE	0.13 / 661.01	37
	***Permit No | Date Issued**: 3-34303 | 09/21/2000*			
	2618 4TH AVE Seattle WA 98119	ENE	0.14 / 749.07	45
	***Permit No | Date Issued**: 3-42668 | 05/31/2002*			
	2439 2ND AVE Seattle WA 98119	ESE	0.17 / 878.57	53

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	Permit No* | *Date Issued: *3-47025* | *05/08/2003*			
	2434 2ND AVE Seattle WA 98109	ESE	0.17 / 878.94	54
	Permit No* | *Date Issued: *3-46042* | *02/27/2003*			
	2517 4TH AVE Seattle WA 98109	E	0.18 / 963.63	62
	Permit No* | *Date Issued: *3-42651* | *05/30/2002*			
	2500 4TH AVE Seattle WA 98121	E	0.19 / 976.90	65
	Permit No* | *Date Issued: *P990119-34187* | *01/19/1999*			
	2437 3RD AVE Seattle WA 98119	ESE	0.19 / 1,003.12	70
	Permit No* | *Date Issued: *3-36933* | *03/12/2001*			
	2466 4TH AVE Seattle WA 98103	E	0.21 / 1,111.03	81
	Permit No* | *Date Issued: *3-43047* | *06/25/2002*			
	2434 4TH AVE Seattle WA 98119	E	0.22 / 1,169.61	89
	Permit No* | *Date Issued: *3-43775* | *08/12/2002*			
	2552 5TH AVE Seattle WA 98109	ENE	0.23 / 1,188.92	91
	Permit No* | *Date Issued: *3-46039* | *02/27/2003*			
	2459 5TH AVE Seattle WA 98199	E	0.25 / 1,309.94	108
	Permit No* | *Date Issued: *3-34092* | *09/07/2000*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	2702 1ST AVE Seattle WA 98119	S	0.04 / 200.06	4
	Permit No* | *Date Issued: *3-43475* | *07/23/2002*			
	2915 1ST AVE Seattle WA 98109	WNW	0.10 / 538.54	19
	Permit No* | *Date Issued: *3-40995* | *01/28/2002*			
	2517 1ST AVE Seattle WA 98119	SE	0.11 / 595.00	25
	Permit No* | *Date Issued: *3-49166* | *09/22/2003*			
	2556 1ST AVE Seattle WA 98109	SE	0.12 / 610.99	28
	Permit No* | *Date Issued: *3-36566* | *02/07/2001*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	2446 1ST AVE Seattle WA 98119	SE	0.18 / 931.34	56
	***Permit No | Date Issued**: 3-39696 | 09/24/2001*			
	2432 1ST AVE Seattle WA 98109	SE	0.18 / 964.88	63
	***Permit No | Date Issued**: 3-36741 | 02/23/2001*			
	2426 1ST AVE Seattle WA 98109	SE	0.19 / 979.09	66
	***Permit No | Date Issued**: 3-45360 | 12/12/2002*			
	2417 1ST AVE Seattle WA 98119	SE	0.19 / 1,006.48	72
	***Permit No | Date Issued**: 3-32958 | 06/19/2000*			

Non Standard

Federal

HMIRS - Hazardous Materials Information Reporting System

A search of the HMIRS database, dated Sep 1, 2020 has found that there are 2 HMIRS site(s) within approximately 0.12 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	2729 SECOND AVE SEATTLE WA	W	0.00 / 0.00	1
	2729 SECOND AVE SEATTLE WA	W	0.00 / 0.00	1

FED DRYCLEANERS - Drycleaner Facilities

A search of the FED DRYCLEANERS database, dated Jun 25, 2022 has found that there are 2 FED DRYCLEANERS site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
FAULKENBURY AND WRIGHT DRYCLEANERS	501 DENNY WAY SEATTLE WA 98109	ENE	0.21 / 1,118.54	83
	***FRS Facility ID**: 110005327976*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
A 1 LAUNDRY INC	2401 1ST AVE SEATTLE WA 98121	SE	0.19 / 1,026.78	76
	***FRS Facility ID**: 110064832061*			

FUDS - Formerly Used Defense Sites

A search of the FUDS database, dated May 26, 2021 has found that there are 42 FUDS site(s) within approximately 1.00 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
OLYMPIC GOLF COURSE AAA	SEATTLE WA ***FUDS Property No**: F10WA0114*	ESE	0.64 / 3,374.27	257
CAMP GEORGE JORDAN	SEATTLE WA ***FUDS Property No**: F10WA0259*	ESE	0.64 / 3,374.27	257
COLLEGE ST OPEN STOR SITE	SEATTLE WA ***FUDS Property No**: F10WA0268*	ESE	0.64 / 3,374.27	257
SEATTLE DRUM STORAGE	SEATTLE WA ***FUDS Property No**: F10WA0433*	ESE	0.64 / 3,374.27	257
SEATTLE NAVAL INDUSTRIAL RESERVE SHIPYARD PLANT A	SEATTLE WA ***FUDS Property No**: F10WA0435*	ESE	0.64 / 3,374.27	257
LAKE WA SHIP CAN STORAGE	SEATTLE WA ***FUDS Property No**: F10WA0346*	ESE	0.64 / 3,374.27	257
HQS SEATTLE REGION	SEATTLE WA ***FUDS Property No**: F10WA0339*	ESE	0.64 / 3,374.27	257
GUN BATTERY SITE GW9-41	SEATTLE WA ***FUDS Property No**: F10WA0116*	ESE	0.64 / 3,374.27	257
SEATTLE TROOP TRA SIDING	SEATTLE WA ***FUDS Property No**: F10WA0443*	ESE	0.64 / 3,374.27	257
SEATTLE PORT EMBARKATION	SEATTLE WA ***FUDS Property No**: F10WA0437*	ESE	0.64 / 3,374.27	257
SEATTLE WAC HOUSING SITE	SEATTLE WA ***FUDS Property No**: F10WA0445*	ESE	0.64 / 3,374.27	257
U.S. ENGINEER WAREHOUSE (FREMONT)	SEATTLE WA ***FUDS Property No**: F10WA0129*	ESE	0.64 / 3,374.27	257

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
GREAT NORTHERN PIER 88	SEATTLE WA ***FUDS Property No**: F10WA0576*	ESE	0.64 / 3,374.27	257
AIR FORCE PLANT NO. 17	SEATTLE WA ***FUDS Property No**: F10WA0236*	ESE	0.64 / 3,374.27	257
SEATTLE NAVAL INDUSTRIAL RESERVE SHIPYARD PLANT B	SEATTLE WA ***FUDS Property No**: F10WA0436*	ESE	0.64 / 3,374.27	257
SEATTLE SAL SEG SITE	SEATTLE WA ***FUDS Property No**: F10WA0438*	ESE	0.64 / 3,374.27	257
ACS CABLE STORAGE AREA	SEATTLE WA ***FUDS Property No**: F10WA0573*	ESE	0.64 / 3,374.27	257
ARGO REDISTRIBUTION SITE	SEATTLE WA ***FUDS Property No**: F10WA0242*	ESE	0.64 / 3,374.27	257
ALASKA COMMUNICATION SYS	SEATTLE WA ***FUDS Property No**: F10WA0241*	ESE	0.64 / 3,374.27	257
HOLGATE ST SALVAGE SITE	SEATTLE WA ***FUDS Property No**: F10WA0338*	ESE	0.64 / 3,374.27	257
BOEING FIELD	SEATTLE WA ***FUDS Property No**: F10WA0254*	ESE	0.64 / 3,374.27	257
SEATTLE BEACON TRAN SITE	SEATTLE WA ***FUDS Property No**: F10WA0419*	ESE	0.64 / 3,374.27	257
SEATTLE TUG&BARGE MOORING	SEATTLE WA ***FUDS Property No**: F10WA0444*	ESE	0.64 / 3,374.27	257
US DIST ENG INT STOR SITE	SEATTLE WA ***FUDS Property No**: F10WA0467*	ESE	0.64 / 3,374.27	257
AUTOMATIC WEAPONS BATTERY HEADQUARTERS SW9-29	SEATTLE WA ***FUDS Property No**: F10WA0587*	ESE	0.64 / 3,374.27	257

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
US DIST ENG WAREHOUSE	SEATTLE WA ***FUDS Property No**: F10WA0468*	ESE	0.64 / 3,374.27	257
BOEING SEATTLE PLANT #12	SEATTLE WA ***FUDS Property No**: F10WA0255*	ESE	0.64 / 3,374.27	257
NG GD FAC PIER 91 SEATTLE	SEATTLE WA ***FUDS Property No**: F10WA0398*	ESE	0.64 / 3,374.27	257
ISAACSON IRON WORKS	SEATTLE WA ***FUDS Property No**: F10WA0536*	ESE	0.64 / 3,374.27	257
LAKE WA SHIP CAN MIL RES	SEATTLE WA ***FUDS Property No**: F10WA0345*	ESE	0.64 / 3,374.27	257
SEATTLE STOCKPILE STORAGE	SEATTLE WA ***FUDS Property No**: F10WA0440*	ESE	0.64 / 3,374.27	257
SEATTLE TRAN LAB CAM SITE	SEATTLE WA ***FUDS Property No**: F10WA0441*	ESE	0.64 / 3,374.27	257
Western Processing	KENT WA ***FUDS Property No**: F10WA0095*	ESE	0.64 / 3,374.27	257
SEATTLE AREA DISPOSAL CEN	SEATTLE WA ***FUDS Property No**: F10WA0415*	ESE	0.64 / 3,374.27	257
TODD-SEATTLE DRYDOCK INC	SEATTLE WA ***FUDS Property No**: F10WA0550*	ESE	0.64 / 3,374.27	257
SEATTLE AUT MAINT SHOP	SEATTLE WA ***FUDS Property No**: F10WA0418*	ESE	0.64 / 3,374.27	257
N SEATTLE NIKE 03	SEATTLE WA ***FUDS Property No**: F10WA0093*	ESE	0.64 / 3,374.27	257
SEATTLE ARMY TERMINAL	SEATTLE WA ***FUDS Property No**: F10WA0417*	ESE	0.64 / 3,374.27	257

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
JEFFERSON PK VEHICLE STOR	SEATTLE WA ***FUDS Property No**: F10WA0340*	ESE	0.64 / 3,374.27	257
MASSACHUSETTS STREET OPEN STORAGE SITE	SEATTLE WA ***FUDS Property No**: F10WA0141*	ESE	0.64 / 3,374.27	257
N/WEST RELAY (AUX) STA	SEATTLE WA ***FUDS Property No**: F10WA0387*	ESE	0.64 / 3,374.27	257

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
BELL HARBOR MARINE CRUISE TERMINAL (PIER 66)	SEATTLE WA ***FUDS Property No**: F10WA0664*	SSE	0.39 / 2,073.50	166

ALT FUELS - Alternative Fueling Stations

A search of the ALT FUELS database, dated Aug 1, 2022 has found that there are 6 ALT FUELS site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Dimension Seattle	225 Cedar Street Seattle WA 98121 ***ID**: 147755*	E	0.06 / 311.19	9
DC CORRIDOR PAC SCI DC2	200 2nd Ave N Seattle WA 98109 ***ID**: 173492*	NW	0.22 / 1,184.23	90
DC CORRIDOR PAC SCI CENTER	200 2nd Ave N Seattle WA 98109 ***ID**: 173491*	NW	0.22 / 1,184.23	90
DC CORRIDOR PAC SCI L2	200 2nd Ave N Seattle WA 98109 ***ID**: 104286*	NW	0.22 / 1,184.23	90
The Century Apartments - Retail Parking	101 Taylor Ave N Seattle WA 98109 ***ID**: 193780*	ENE	0.24 / 1,275.61	104
The Century Apartments - Residential Parking	101 Taylor Ave N Seattle WA 98109 ***ID**: 193830*	ENE	0.24 / 1,275.61	104

SSTS - Registered Pesticide Establishments

A search of the SSTS database, dated Mar 30, 2022 has found that there are 1 SSTS site(s) within approximately 0.25 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
PLANT HEALTH CARE, INC	3005 1ST AVE SUITE 301 SEATTLE WA 98121	WNW	0.17 / 912.96	55
	***Establishment No**: 71771-WA-1*			

PCB - Polychlorinated Biphenyl (PCB) Notifiers

A search of the PCB database, dated Jul 28, 2022 has found that there are 5 PCB site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
3RD AND BROAD	2901 3RD AVE SEATTLE WA 98121	NNW	0.11 / 592.50	23
	***Site ID**: WAW000200592*			
CROWLEY MARINE SERVICES	2401 4TH AVE SEATTLE WA 98121	E	0.21 / 1,118.74	84
	***Site ID**: WAD008958027*			
HAWAIIAN MARINE LINES	2401 4TH AVE SEATTLE WA 98121	E	0.21 / 1,118.74	84
	***Site ID**: WAD991281916*			
PACIFIC ALASKA LINES WEST	2401 4 AVE SEATTLE WA 98121	E	0.21 / 1,118.74	84
	***Site ID**: WAD044592384*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
3101 WESTERN	3101 WESTERN AVE SEATTLE WA 98121	WNW	0.27 / 1,410.34	115
	***Site ID**: WAW000200600*			

State

SPILLS - Spills Incidents Sites

A search of the SPILLS database, dated Mar 10, 2022 has found that there are 19 SPILLS site(s) within approximately 0.12 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	2800 BLOCK OF 2ND ST SEATTLE WA	N	0.01 / 55.17	2
	***Incident ID**	**Incident Date**: 511738 |*		
	2821 2ND AVE SEATTLE WA	NW	0.05 / 250.19	6
	***Incident ID**	**Incident Date**: 90778 | 10/5/2016*		
NULL	2821 2ND AVE SEATTLE WA	NW	0.05 / 250.19	6

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	Incident ID **|** ***Incident Date***: *501975* | *1/11/1999*			
	2821 2ND AVE SEATTLE WA	NW	0.05 / 250.19	6
	Incident ID **|** ***Incident Date***: *501975* |			
GALLERY BELL TOWN	2911 - 2ND AVENUE SEATTLE WA	NW	0.08 / 443.04	16
	Incident ID **|** ***Incident Date***: *65499* | *2/21/2011*			
PUGET SOUND	2911 2ND AVE SEATTLE WA	NW	0.08 / 443.04	16
	Incident ID **|** ***Incident Date***: *553152* | *1/26/2006*			
	2911 2ND AVE SEATTLE WA	NW	0.08 / 443.04	16
	Incident ID **|** ***Incident Date***: *553152* |			
	2911 - 2ND AVENUE SEATTLE WA	NW	0.08 / 443.04	16
	Incident ID **|** ***Incident Date***: *625156* |			
PS- ELLIOTT BAY	2901 3RD AVE SEATTLE WA	NNW	0.11 / 592.50	23
	Incident ID **|** ***Incident Date***: *617011* | *12/13/2009*			
	2901 3RD AVE SEATTLE WA	NNW	0.11 / 592.50	23
	Incident ID **|** ***Incident Date***: *547548* |			
	2901 3RD AVE SEATTLE WA	NNW	0.11 / 592.50	23
	Incident ID **|** ***Incident Date***: *617011* |			
NULL	320 CEDAR STREET AT 4TH AND CEDAR IN THE SEATTLE WA ***Incident ID*** **|** ***Incident Date***: *425987* | *1/22/1997*	ENE	0.12 / 611.69	29
	320 CEDAR STREET AT 4TH AND CEDAR IN THE SEATTLE WA ***Incident ID*** **|** ***Incident Date***: *425987* |	ENE	0.12 / 611.69	29

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
PUGET SOUND	2701 1ST AVE SEATTLE WA	SSW	0.04 / 184.96	3
	Incident ID **|** ***Incident Date***: *555687* | *6/8/2006*			
	2701 1ST AVE SEATTLE WA	SSW	0.04 / 184.96	3
	Incident ID **|** ***Incident Date***: *555687* |			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	121 VINE ST SEATTLE WA	ESE	0.09 / 471.81	17
	Incident ID* | *Incident Date: *549811* |			
	SEATTLE WA	SW	0.11 / 591.76	22
	Incident ID* | *Incident Date: *120341* | *01/03/2022*			
	2717 WESTERN AVE SEATTLE WA	SW	0.11 / 601.93	26
	Incident ID* | *Incident Date: *611562* |			
NULL	WESTERN AVE. & BROAD ST. SEATTLE WA	W	0.12 / 607.50	27
	Incident ID* | *Incident Date: *553847* | *3/7/2006*			

SPILLS WATER - Reported Spills to Water

A search of the SPILLS WATER database, dated Apr 14, 2022 has found that there are 1 SPILLS WATER site(s) within approximately 0.12 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	SEATTLE WA	WNW	0.10 / 552.90	20

ALL SITES - Facility/Site Identification System

A search of the ALL SITES database, dated Jun 2, 2022 has found that there are 195 ALL SITES site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Grange Insurance Group	200 CEDAR ST SEATTLE WA 98121	E	0.04 / 205.62	5
THIRD AVENUE PRODUCTIONS	2720 3RD AVE SEATTLE WA 98121-1260	NE	0.07 / 371.39	10
KIRO INC	2807 3RD AVE SEATTLE WA 98121	N	0.08 / 419.66	14
Rite Aid 5218	2603 3RD AVE SEATTLE WA 98121	E	0.10 / 509.10	18
Cascadian Therapeutics Seattle	2601 4th Ave Ste 500 Seattle WA 98121	ENE	0.12 / 629.45	34

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
MARTIN SELIG PROPERTY	2601 4TH AVE SEATTLE WA 98121	ENE	0.12 / 629.45	34
Grizzly Retail Rentals	2601 4TH AVE STE 350 SEATTLE WA 98121	ENE	0.12 / 629.45	34
Wits Air Freight	333 VINE ST SEATTLE WA 98121	E	0.13 / 661.67	38
Rite Aid 6977 DBA Bartell Drugs 077	2506 2nd Ave Seattle WA 98121	ESE	0.13 / 674.54	39
DEAN STRALEYS BP	351 BROAD ST SEATTLE WA 98109	NNE	0.14 / 721.11	42
K & N MEATS SEATTLE	2900 4TH AVE SEATTLE WA 98108	NE	0.14 / 758.42	46
PACIFIC SCIENCE CTR FROL BLDG	204 DENNY WAY SEATTLE WA 98109	NW	0.15 / 771.91	48
Puget Sound Institute of Patho	2600 4TH AVE SEATTLE WA 98121	E	0.15 / 812.05	49
FAMOUS PACIFIC DESSERT COMPANY	420 DENNY WAY SEATTLE WA 98109	NE	0.16 / 820.79	50
VADATA INC 4TH AVE	100 4TH AVE N STE 420 SEATTLE WA 98109	NE	0.18 / 940.23	58
FRONTIER COMMUNICATIONS WA79899	100 4TH AVE N STE 250 SEATTLE WA 98109	NE	0.18 / 940.23	58
FISHER PLAZA KOMO TV	100 4TH AVE N SEATTLE WA 98109	NE	0.18 / 940.23	58
Space Needle Corp	219 4TH AVE N SEATTLE WA 98109	NNE	0.18 / 955.86	61

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
CHEVRON SERV STA 97032	5TH AVE & DENNY WAY NW CORNER SEATTLE WA 98109	ENE	0.18 / 968.73	64
EDWARDS ON 5TH BLDG	2619 5TH AVE SEATTLE WA 98121	ENE	0.19 / 1,002.02	69
2nd Ave Bell Drums	2408 2ND AVE SEATTLE WA 98121	ESE	0.19 / 1,017.98	75
Fat City Inc	508 DENNY WAY SEATTLE WA 98109-5009	ENE	0.20 / 1,062.07	77
FISHER PLAZA	140 4TH AVE N SEATTLE WA 98109	NE	0.21 / 1,095.97	79
Parson Seatrust Partnership	400 WALL ST SEATTLE WA 98121	E	0.21 / 1,099.70	80
Faulkenbury Wright	501 DENNY WAY SEATTLE WA 98109	ENE	0.21 / 1,118.54	83
Lifespan Biosciences	2401 4TH AVE 12TH FLOOR SEATTLE WA 98121	E	0.21 / 1,118.74	84
Hawaiian Marine Lines Inc	2401 4TH AVE SEATTLE WA 98121	E	0.21 / 1,118.74	84
303 Battery	303 BATTERY ST SEATTLE WA 98121	ESE	0.22 / 1,151.76	87
Pacific Science Center	200 2ND AVE N SEATTLE WA 98109	NW	0.22 / 1,184.23	90
Holman Body & Fender	2324 2ND AVE SEATTLE WA 98121	ESE	0.23 / 1,201.53	93
FOUNTAIN COURT APARTMENTS	2400 4TH AVE SEATTLE WA 98121	E	0.23 / 1,216.71	94

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Da Li 5th Avenue Development	124 - 130 5TH AVE N SEATTLE WA 98109	NE	0.23 / 1,217.55	95
GROSVENOR HOUSE VINE ST	505 VINE ST SEATTLE WA 98121-1508	ENE	0.24 / 1,250.63	98
Arctic Marine Freighters	4TH & BATTERY SEATTLE WA 98111	E	0.24 / 1,255.55	100
Prime Cyte Inc	130 5TH AVE N SEATTLE WA 98109	NE	0.24 / 1,273.55	103
Taylor and Denny New Building	101 TAYLOR AVE N SEATTLE WA 98109	ENE	0.24 / 1,275.61	104
Grosvenor House	500 WALL ST STE 100 SEATTLE WA 98121	ENE	0.24 / 1,284.97	105
Archstone Belltown	500 WALL ST SEATTLE WA 98121	ENE	0.24 / 1,284.97	105
Fifth & Broad Property	417 BROAD ST SEATTLE WA 98109	NE	0.25 / 1,304.95	106
SEATTLE FIRE STATION 2	2334 4TH AVE SEATTLE WA 98121	E	0.26 / 1,354.65	110
Seattle Fire Station 2 4th Ave	2334 4TH AVE SEATTLE WA 98121	E	0.26 / 1,354.65	110
Second & Bell Building LLC	2306 2ND AVE SEATTLE WA 98121	ESE	0.26 / 1,379.92	112
Seattle Fire Dept Sta	2318 4TH AVE SEATTLE WA 98121	E	0.26 / 1,391.92	113
SEATTLE POST INTELLIGENCER	521 WALL ST SEATTLE WA 98121	E	0.27 / 1,408.52	114

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
BRE Properties Inc	552 DENNY WAY & 553 JOHN ST SEATTLE WA 98109	ENE	0.27 / 1,415.34	117
Ride the Ducks	516 BROAD ST SEATTLE WA 98109	NE	0.28 / 1,479.78	120
Bell Street Park	WA	SE	0.29 / 1,505.52	123
Import Doctors	211 BELL ST SEATTLE WA 98121-1715	ESE	0.29 / 1,511.98	124
Symetrix Inc Seattle	109 BELL ST SEATTLE WA 98121	SE	0.29 / 1,513.98	125
4th and Bell Seattle	2306 4th Ave Seattle WA 98121	E	0.29 / 1,517.85	126
First & Bell	2233 1ST AVE SEATTLE WA 98121	SE	0.30 / 1,573.67	128
Japanese Auto Clinic	600 DENNY WAY SEATTLE WA 98109	ENE	0.30 / 1,583.60	129
Wilson Engraving Co Inc	314 BELL ST SEATTLE WA 98121	ESE	0.30 / 1,586.57	130
600 wall street	600 WALL ST SEATTLE WA 98121	ENE	0.30 / 1,607.90	132
Consolidated Press Printing Co	2228 1ST AVE SEATTLE WA 98121	SE	0.31 / 1,612.73	133
PHOM PROPERTY	2301 4th Ave / 314 Bell St SEATTLE WA 98121	E	0.31 / 1,620.12	135
The Belltown Collective LLC	2231 1st Ave Seattle WA 98121	SE	0.31 / 1,637.74	136

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
LEVEL 3 COMMUNICATIONS SEATTLE STTLWATTA	223 TAYLOR AVE N SEATTLE WA 98109	NE	0.32 / 1,665.56	137
DENNY WAY SHELL	620 DENNY WAY SEATTLE WA 98109	ENE	0.32 / 1,701.58	138
3rd Ave Redevelopment	2211 2217 3RD AVE SEATTLE WA 98121	ESE	0.33 / 1,762.15	140
Hauge & Hassain Inc	207 6TH AVE N SEATTLE WA 98109	ENE	0.34 / 1,790.74	143
Graphics West Typeline	217 6TH AVE N SEATTLE WA 98109	ENE	0.35 / 1,846.67	146
Frederick Cadillac	2301 6TH AVE SEATTLE WA 98121	E	0.35 / 1,848.07	147
ELEPHANT CAR WASH UST 4919	616 BATTERY ST SEATTLE WA 98121-1538	E	0.35 / 1,867.33	150
Robbins Brothers	2200 1st Ave Seattle WA 98121	SE	0.36 / 1,877.46	152
AT&T WIRELESS DEXTER	618 JOHN ST SEATTLE WA 98109	ENE	0.36 / 1,879.54	153
LEWISTON HOTEL	2201 1ST AVE SEATTLE WA 98121	SE	0.36 / 1,891.41	154
VARTEC SEATTLE SWITCH	2308 N 6TH AVE SEATTLE WA 98121	E	0.37 / 1,937.83	155
PRECISION TUNE 7TH AVE SEATTLE	2331 7TH AVE SEATTLE WA 98121-1903	E	0.38 / 1,982.00	157
Sterling Engraving Co	2218 5TH AVE E SEATTLE WA 98121-1808	E	0.38 / 1,994.77	159

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
ATT MOBILITY DEXTER	225 AURORA AVE N SEATTLE WA 98109	ENE	0.38 / 2,003.50	160
Gem East Corp	2124 2ND AVE SEATTLE WA 98121	ESE	0.39 / 2,047.44	162
ATT MOBILITY LENORA & 3RD	2124 2ND AVE SEATTLE WA 98121	ESE	0.39 / 2,047.44	162
REXLAND CO INC	2126 3RD AVE SEATTLE WA 98121-2306	ESE	0.39 / 2,060.44	164
DAVES AUTO ELECTRIC	701 JOHN ST SEATTLE WA 98109	ENE	0.40 / 2,090.19	169
Astro Apartments	315 1ST AVE N SEATTLE WA 98109	NW	0.40 / 2,094.96	170
Seattle Center Arena	334 1st Ave N Seattle WA 98109	NW	0.40 / 2,103.79	172
PARKING LOT UST 510091	2120 1ST AVE SEATTLE WA 98121-2103	SE	0.40 / 2,111.73	173
Blanchard Plaza	2201 6TH AVE STE 100 SEATTLE WA 98121	E	0.41 / 2,154.31	177
WORLDCOM STFAWA	2201 6TH AVE SEATTLE WA 98121	E	0.41 / 2,154.31	177
Qualex at Seattle Center	305 HARRISON ST SEATTLE CTR CENTER HOUSE SEATTLE WA 98109	NW	0.41 / 2,157.12	178
Seattle Center	305 HARRISON ST SEATTLE WA 98109	NW	0.41 / 2,157.12	178
Fun Forest Ride Shop	305 HARRISON ST RIDE SHOP SEATTLE WA 98109	NW	0.41 / 2,157.12	178

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Martin Selig Real Estate Seattle	2118 3RD AVE SEATTLE WA 98121	ESE	0.41 / 2,161.65	179
NEUFFER CONSTRUCTION COMPANY	5TH & BLANCHARD SEATTLE WA 98121	E	0.41 / 2,176.44	180
Frederick Pontiac Buick	2300 7TH AVE SEATTLE WA 98121	E	0.41 / 2,180.91	181
LEE COURT	2133 5TH AVE SEATTLE WA 98121	E	0.42 / 2,217.95	184
OLD BRITISH MOTORCAR	7TH & BELL SEATTLE WA 98121	E	0.42 / 2,236.45	188
Seattle City Used Oil Collect 7th Ave	2229 7TH AVE SEATTLE WA 98121	E	0.43 / 2,262.08	189
Potala Tower Seattle	2116 4TH AVE SEATTLE WA 98121	ESE	0.44 / 2,308.82	192
WORLDCOM INTERMIEDIA FACILITY	2200 6TH AVE SEATTLE WA 98121	E	0.44 / 2,318.58	193
Qwest Corporation W00A80	120 LENORA ST SEATTLE WA 98121	SE	0.45 / 2,351.72	196
Cinerama	2100 4TH AVE SEATTLE WA 98121	ESE	0.45 / 2,355.41	198
Lenora Holdings Company LLC	2031 3RD AVE SEATTLE WA 98121	ESE	0.47 / 2,456.05	202
United Resource System	2025 1ST AVE STE 500 SEATTLE WA 98121	SE	0.47 / 2,462.70	204
Tax Parcel 069600-0025	2101 2105 & 2111 5TH AVE SEATTLE WA 98121	ESE	0.47 / 2,481.50	205

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
CVS Pharmacy 10982	2035 4th Ave Seattle WA 98121	ESE	0.48 / 2,510.52	207
STERLING REALTY ORGANIZATION CO	2101-2111 5TH AVE SEATTLE WA 98121-2510	ESE	0.48 / 2,521.17	208
Barg KH Cleaners	2018 3RD AVE SEATTLE WA 98121	ESE	0.48 / 2,550.13	210
Vulcan Construction	5th & Lenora Seattle WA 98121	ESE	0.48 / 2,555.35	211
USPS QUEEN ANNE	415 1ST AVE N SEATTLE WA 98109	NW	0.48 / 2,556.68	212
WA UW Queen Anne	401 QUEEN ANNE AVE N SEATTLE WA 98119	NW	0.48 / 2,557.39	213
Jiffy Lube Store 2077	2025 4TH AVE SEATTLE WA 98121	ESE	0.49 / 2,564.21	214
Queen Anne Auto Body	420 QUEEN ANNE N SEATTLE WA 98109	NW	0.49 / 2,597.17	216
Sixth & Lenora Apartments	2121 6TH AVE SEATTLE WA 98121	E	0.50 / 2,622.04	222

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Sea Coast Towing Inc Home Offi	2701 1ST AVE SEATTLE WA 98121	SSW	0.04 / 184.96	3
Seattle Labor Temple Assoc Parking Lot	2801 1ST AVE SEATTLE WA 98121	W	0.06 / 295.13	7
THE OLYMPUS	2801 WESTERN AVE SEATTLE WA 98121	WSW	0.11 / 577.56	21
Washington Transit Advertising	2600 WESTERN AVE SEATTLE WA 98121	S	0.12 / 619.56	31

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
VINE BUILDING	2607 WESTERN AVE SEATTLE WA 98121	S	0.12 / 621.29	32
COTTAGE PROPERTIES	VINE ST SEATTLE WA 98121	SSE	0.12 / 637.31	35
CEDAR DEVELOPMENT LLC	2627 WESTERN AVE SEATTLE WA 98121	SSW	0.12 / 651.76	36
FRANK JAMES AUTO & PEOPLES VOLKSWAGEN	2900 2922 1ST AVE SEATTLE WA 98121	WNW	0.13 / 679.50	40
SAILORS UNION OF THE PACIFIC BLDG	2505 1ST AVE SEATTLE WA 98121	SSE	0.13 / 689.65	41
Northwest Protective Service Inc	2700 ELLIOTT AVE SEATTLE WA 98121	SW	0.14 / 723.90	43
La Scala Apartments	2922 WESTERN AVE SEATTLE WA 98121	W	0.14 / 748.41	44
Oening Co 81 Vine	2518 WESTERN AVE SEATTLE WA 98121	SSE	0.14 / 765.49	47
UNOCAL SEATTLE MARKET LOWER	BN ELLIOTT RR BAY & BROAD SEATTLE WA 98121	W	0.16 / 844.14	51
UNOCAL SEATTLE MARKETING TERM	BROAD ST & WESTERN AVE & BAY ST SEATTLE WA 98121	W	0.16 / 844.14	51
Rossman Industrial Supply Co	2500 WESTERN AVE SEATTLE WA 98121-1308	SSE	0.16 / 856.05	52
Bristol Myers Squibb Pharm Res Inst Sea	3005 1ST AVE STE 200 SEATTLE WA 98121	WNW	0.17 / 912.96	55
Dendreon Corp	3005 1ST AVE SEATTLE WA 98121	WNW	0.17 / 912.96	55

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Cyrus Biotechnology Inc Seattle	3005 1st Ave Ste 203 Seattle WA 98121	WNW	0.17 / 912.96	55
Affini-T Therapeutics Seattle	3005 1st Ave Ste 102 Seattle WA 98121	WNW	0.17 / 912.96	55
BELLTOWN PEA PATCH	ELLIOTT AVE & VINE ST SEATTLE WA 98121	SSW	0.18 / 931.76	57
Unocal SS No 0355	159 DENNY WAY SEATTLE WA 98109	WNW	0.18 / 945.58	60
S EPA H Inc	150 DENNY WAY SEATTLE WA 98109	WNW	0.19 / 997.79	67
Seattle City Parks & Rec Belltown PP	2512 ELLIOT AVE SEATTLE WA 98102	S	0.19 / 1,001.11	68
BELLTOWN COURT CONDOS	2400 1ST AVE SEATTLE WA 98121	SE	0.19 / 1,005.13	71
WA UW Western Ave	3000 WESTERN AVE SEATTLE WA 98121	W	0.19 / 1,010.03	73
ELLIOTT & BROAD	10 BROAD ST SEATTLE WA 98121	WSW	0.19 / 1,017.60	74
A 1 Laundry Inc	2401 1st Ave Seattle WA 98121	SE	0.19 / 1,026.78	76
Triad Vine & Elliot LLC	10 WALL ST SEATTLE WA 98121	S	0.20 / 1,063.52	78
Graphicolor Inc	3018 WESTERN AVE SEATTLE WA 98121-1023	W	0.21 / 1,117.79	82
Unocal Marketing Terminal No TM0724	3001 ELLIOTT AVE SEATTLE WA 98121	W	0.21 / 1,121.65	85

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Champion Teutsch Property	124 DENNY WAY SEATTLE WA 98109	WNW	0.22 / 1,143.70	86
Denny & Warren Petrol Plume	101 DENNY WAY SEATTLE WA 98109	WNW	0.22 / 1,162.18	88
CONSTRUCTION SITE	65 BAY ST SEATTLE WA 98121-1015	WNW	0.23 / 1,228.08	96
AT&T WIRELESS PIER 70	2815 ALASKAN WAY SEATTLE WA 98121	WSW	0.23 / 1,240.49	97
CLIPPER NAVIGATION ELLIOTT BAY	WA	SW	0.24 / 1,254.28	99
PORT OF SEATTLE PIER 69	PIER 69 SEATTLE WA 98111	SW	0.24 / 1,268.67	101
Seattle Port Pier 69	2711 ALASKAN WAY SEATTLE WA 98121	SW	0.24 / 1,268.67	101
IVARS SEAFOOD BAR	3101 1ST AVE SEATTLE WA 98121-1051	WNW	0.24 / 1,268.70	102
Edgewater Hotel	2411 Alaskan Way Pier 67 Seattle WA 98121	SSW	0.25 / 1,306.08	107
Valco Graphics Inc Western Ave	3104 WESTERN AVE SEATTLE WA 98121	WNW	0.26 / 1,367.35	111
AIRBORNE EXPRESS	3101 WESTERN AVE SEATTLE WA 98121	WNW	0.27 / 1,410.34	115
Invitae Seattle	3101 Western Ave Ste 100 Seattle WA 98121	WNW	0.27 / 1,410.34	115
Pinnacle Productions International Inc	2334 ELLIOTT AVE / 55 BATTERY ST SEATTLE WA 98121	SSE	0.27 / 1,411.12	116

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
VERIZON WIRELESS BATTERY STREET TUNNEL	2315 WESTERN AVE SEATTLE WA 98121	SE	0.27 / 1,417.61	118
UNOCAL ELLIOTT AVE N OF BAY ST	ELLIOTT AVE & BAY ST NEC SEATTLE WA 98121	W	0.27 / 1,449.04	119
WA DOT Alaskan Way Viaduct Project	ALASKAN WAY VIADUCT MP 28.61 TO 33.8 SEATTLE WA 98104	S	0.28 / 1,491.62	121
Shell Station 121702	10 DENNY WAY SEATTLE WA 98109	WNW	0.29 / 1,552.46	127
Belltown Lofts	66 BELL ST SEATTLE WA 98101	SE	0.30 / 1,601.47	131
Edelstein Assoc Advertising BE	50 BELL ST SEATTLE WA 98121	SE	0.31 / 1,619.72	134
UNOCAL STATEWIDE LISTING	3131 ELLIOTT AVE SEATTLE WA 98121	W	0.33 / 1,758.53	139
133 Queen Anne Ave N Property	133 QUEEN ANNE AVE N SEATTLE WA 98109	WNW	0.34 / 1,790.09	142
BARRAT TRANSFER & STORAGE CO	123 QUEEN ANNE AVE N SEATTLE WA 98109	WNW	0.34 / 1,817.77	144
WA UW 2211 Elliott Ave	2211 ELLIOTT AVE SEATTLE WA 98101	SSE	0.35 / 1,837.12	145
Stratos Genomics	2211 Elliott Ave Ste 210 Seattle WA 98121	SSE	0.35 / 1,837.12	145
Seattle Port Term 66	2201 ALASKAN WAY TERM 66 PIERCE MARINE SEATTLE WA 98121	SSE	0.35 / 1,853.03	149
2200 Western Avenue LLC	2200 Western Ave Seattle WA 98121	SE	0.36 / 1,875.55	151

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
DIAMOND PARKING INC ELLIOTT AVE	3161 ELLIOTT AVE SEATTLE WA 98121-1054	WNW	0.37 / 1,940.90	156
United Technologies Otis Elevator Settle	3150 ELLIOT AVE SEATTLE WA 98121	WNW	0.38 / 1,986.02	158
Hebei Ocean Shipping Co Elliott Bay	WA	S	0.38 / 2,022.77	161
TSANGARIS BROS LTD ELLIOTT BAY	WA	S	0.38 / 2,022.77	161
BASIL LEE PROPERTY	505 HARRISON ST SEATTLE WA 98109	NNE	0.39 / 2,077.96	167
Anacomp Inc 1st	200 1ST AVE W STE 105 SEATTLE WA 98119-4219	WNW	0.39 / 2,079.33	168
First West Investment Property LLC	200 1ST AVE W ENTIRE BLDG SEATTLE WA 98119	WNW	0.39 / 2,079.33	168
Western and Blanchard Property	2134 Western Ave Seattle WA 98121	SE	0.40 / 2,101.90	171
SEATTLE CENTER N PARKING GARAGE	516 HARRISON ST SEATTLE WA 98109	NNE	0.40 / 2,112.79	174
BAY VIEW BLDG	129 1ST AVE W SEATTLE WA 98119	WNW	0.40 / 2,119.04	175
Seattle School Dist 1 Memorial Stad	401 5TH AVE N SEATTLE WA 98109	NNE	0.42 / 2,201.27	182
Verizon Wireless WARE WEST DENNY WAY	101 ELLIOTT AVE W SEATTLE WA 98119	WNW	0.42 / 2,204.43	183
Sabey Corp Seattle	101 ELLIOTT AVE W STE 330 SEATTLE WA 98119	WNW	0.42 / 2,204.43	183

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Elliott Bay Bicycles	2114 WESTERN AVE SEATTLE WA 98121	SE	0.42 / 2,219.31	185
Norwegian Cruise Line Elliott Bay	WA	S	0.42 / 2,221.76	186
King Cnty DOT Metro Waterfront Streetcar	3001 ALASKAN WAY SEATTLE WA 98121	WNW	0.42 / 2,236.09	187
King County Denny Way CSO	3165 ALASKAN WAY SEATTLE WA 98121	WNW	0.42 / 2,236.09	187
Seattle City Broad St Substation	319 6TH AVE N SEATTLE WA 98109-4606	NE	0.43 / 2,275.57	190
Uptown Flats Queen Anne	300 1ST AVE W SEATTLE WA 98119	WNW	0.44 / 2,338.32	194
PPG Industries Inc Loc 180	234 DEXTER AVE SEATTLE WA 98109	ENE	0.45 / 2,350.25	195
Seattle Waterfront Marriott Hotel	2100 ALASKAN WAY SEATTLE WA 98121	SSE	0.45 / 2,352.02	197
SEA43 Nitro North	2250 7TH AVE SEATTLE WA 98121	E	0.45 / 2,387.75	200
AMAZON SEA44 FRONTIER	2205 7TH AVE SEATTLE WA 98121	E	0.46 / 2,444.32	201
Seattle Vagabond Inn	325 AURORA AVE N 325 7th Ave N SEATTLE WA 98109	NE	0.47 / 2,459.32	203
Adsco Printing	315 1ST AVE W SEATTLE WA 98119-4196	WNW	0.47 / 2,506.34	206
ELLIOTT BAY SEAWALL	Seattle WA 98101	SE	0.48 / 2,542.72	209

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Mercer Operating Base	520 5TH AVE N SEATTLE WA 98109	NNE	0.49 / 2,565.68	215
Amazon Go ISE1	2131 7th Ave Seattle WA 98121	E	0.49 / 2,610.89	217
Life Span Bio Sciences	700 BLANCHARD ST SEATTLE WA 98121	E	0.50 / 2,616.97	219
IRIS Holding LLC	500 5TH AVE N SEATTLE WA 98109	NNE	0.50 / 2,618.41	220
SEA98	720 BLANCHARD ST SEATTLE WA 98121	E	0.50 / 2,619.59	221
MCI INTERNATIONAL	2001 WESTERN AVE STE 425 SEATTLE WA 98121-2114	SE	0.50 / 2,630.66	223
Wilderman Refrigeration Co	300 DEXTER AVE N SEATTLE WA 98109-5106	ENE	0.50 / 2,637.06	224
SEA47 The Summit	2122 7TH AVE SEATTLE WA 98121	E	0.50 / 2,643.15	225

ERTS - Environmental Report Tracking System (ERTS)

A search of the ERTS database, dated Nov 22, 2021 has found that there are 16 ERTS site(s) within approximately 0.12 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	2800 BLOCK OF 2ND ST SEATTLE WA	N	0.01 / 55.17	2
	2821 2ND AVE SEATTLE WA	NW	0.05 / 250.19	6
	2821 2ND AVE SEATTLE WA 98121	NW	0.05 / 250.19	6

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
`JOB SITE`	2600 2ND AVE SEATTLE WA	ESE	0.06 / 306.72	8
Parking Lot of Wells Fargo	2800 3rd Ave Seattle WA 98121	NNE	0.07 / 384.66	12
	2607 2nd Ave (Alley) SEATTLE WA	ESE	0.08 / 418.39	13
WA STATE FERRY SYSTEM	2911 2ND AVE SEATTLE WA	NW	0.08 / 443.04	16
GALLERY BELL TOWN	2911 - 2ND AVENUE SEATTLE WA	NW	0.08 / 443.04	16
WA STATE FERRY OPERATIONS CENTER	2901 3RD AVE SEATTLE WA 98121	NNW	0.11 / 592.50	23
	2901 3RD AVE SEATTLE WA	NNW	0.11 / 592.50	23
	320 CEDAR STREET AT 4TH AND CEDAR IN THE SEATTLE WA	ENE	0.11 / 592.78	24
	2601 FOURTH AVE SEATTLE WA	ENE	0.12 / 629.45	34

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
PIER 70	2701 1ST AVE SEATTLE WA	SSW	0.04 / 184.96	3
ARBOR PLACE TOWER	121 VINE ST SEATTLE WA 98121-	ESE	0.09 / 471.81	17
OLYMPIC SCULPTURE PARK	WESTERN AVE. & BROAD ST. SEATTLE WA	W	0.12 / 607.50	27
Parking Garage	75 Vine St Seattle WA 98121	S	0.12 / 627.43	33

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key

ICR - Independent Cleanup Reports

A search of the ICR database, dated Nov 6, 2015 has found that there are 69 ICR site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Martin Selig Property	2601 4TH AVE SEATTLE WA 98121	ENE	0.12 / 629.45	34
Pacific Science Center Frol Building	204 DENNY WAY SEATTLE WA 98109	NW	0.15 / 771.91	48
Fisher Plaza KOMO TV	100 4TH AVE N SEATTLE WA 98109	NE	0.18 / 940.23	58
Chevron 97032	5TH AVE & DENNY WAY NW CORNER SEATTLE WA 98109	ENE	0.18 / 968.73	64
Edwards on Fifth	2619 5TH AVE SEATTLE WA 98121	ENE	0.19 / 1,002.02	69
Parson Seatrust Partnership	400 WALL ST SEATTLE WA 98121	E	0.21 / 1,099.70	80
Pacific Science Center UST Denny & Broad	200 2ND AVE N SEATTLE WA 98109	NW	0.22 / 1,184.23	90
HOLMAN BODY & FENDER	2324 2ND AVE SEATTLE WA 98121	ESE	0.23 / 1,201.53	93
FOUNTAIN COURT APARTMENTS	2400 4TH AVE SEATTLE WA 98121	E	0.23 / 1,216.71	94
Taylor & Denny Building	101 TAYLOR AVE N SEATTLE WA 98109	ENE	0.24 / 1,275.61	104
Archstone Belltown	500 WALL ST SEATTLE WA 98121	ENE	0.24 / 1,284.97	105

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Fifth and Broad Property	417 BROAD ST SEATTLE WA 98109	NE	0.25 / 1,304.95	106
Interbay Redevelopment Property	15TH AVE W SEATTLE WA 98119	SE	0.26 / 1,350.86	109
SEATTLE FIRE STATION 2	2334 4TH AVE SEATTLE WA 98121-1718	E	0.26 / 1,354.65	110
Second & Bell Building LLC	2306 2ND AVE SEATTLE WA 98121	ESE	0.26 / 1,379.92	112
SEATTLE POST INTELLIGENCER	521 WALL ST SEATTLE WA 98121	E	0.27 / 1,408.52	114
BRE Properties Inc	552 DENNY WAY & 553 JOHN ST SEATTLE WA 98109	ENE	0.27 / 1,415.34	117
First & Bell	2233 1ST AVE SEATTLE WA 98121	SE	0.30 / 1,573.67	128
Japanese Auto Clinic	600 DENNY WAY SEATTLE WA 98109	ENE	0.30 / 1,583.60	129
600 wall street	600 WALL ST SEATTLE WA 98121	ENE	0.30 / 1,607.90	132
PHOM PROPERTY	2301 4th Ave / 314 Bell St SEATTLE WA 98121	E	0.31 / 1,620.12	135
WRIGHTS RESTAURANT	620 DENNY WAY SEATTLE WA 98109	ENE	0.32 / 1,701.58	138
3rd Ave Redevelopment	2211 2217 3RD AVE SEATTLE WA 98121	ESE	0.34 / 1,779.72	141
ELEPHANT CAR WASH	616 BATTERY ST SEATTLE WA 98121-1538	E	0.35 / 1,867.33	150

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
LEWISTON HOTEL	2201 1ST AVE SEATTLE WA 98121	SE	0.36 / 1,891.41	154
REXLAND CO	2126 3RD AVE SEATTLE WA 98121-2306	ESE	0.39 / 2,060.44	164
Astro Apartments	315 1ST AVE N SEATTLE WA 98109	NW	0.40 / 2,094.96	170
SEATTLE CENTER	305 HARRISON ST SEATTLE WA 98109	NW	0.41 / 2,157.12	178
NEUFFER CONSTRUCTION COMPANY	5TH & BLANCHARD SEATTLE WA 98121	E	0.41 / 2,176.44	180
OLD BRITISH MOTORCAR	7TH & BELL SEATTLE WA 98121	E	0.42 / 2,236.45	188
Potala Tower Seattle	2116 4TH AVE SEATTLE WA 98121	ESE	0.44 / 2,308.82	192
Martin Apartments	2101 2105 & 2111 5TH AVE SEATTLE WA 98121	ESE	0.47 / 2,481.50	205
STERLING REALTY ORGANIZATION CO	2101-2111 5TH AVE SEATTLE WA 98121-2510	ESE	0.48 / 2,521.17	208
USPS Queen Anne	415 1ST AVE N SEATTLE WA 98109	NW	0.48 / 2,556.68	212
Jiffy Lube Store 2077	2025 4TH AVE SEATTLE WA 98121	ESE	0.49 / 2,564.21	214
Sixth & Lenora Apartments	2121 6TH AVE SEATTLE WA 98121	E	0.50 / 2,622.04	222

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
THE OLYMPUS	2801 WESTERN AVE SEATTLE WA 98121	WSW	0.11 / 577.56	21

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
VINE BUILDING	2607 WESTERN AVE SEATTLE WA 98121	S	0.12 / 621.29	32
SAILOR'S UNION OF THE PACIFIC BLDG	2505 1ST AVE SEATTLE WA 98121	SSE	0.13 / 689.65	41
NORTHWEST PROTECTIVE SERVICE	2700 ELLIOTT AVE SEATTLE WA 98121	SW	0.14 / 723.90	43
UNOCAL SEATTLE MARKET LOWER	BN ELLIOTT RR BAY & BROAD SEATTLE WA 98121	W	0.16 / 844.14	51
UNOCAL Seattle Marketing Terminal	BROAD ST & WESTERN AVE & BAY ST SEATTLE WA 98121	W	0.16 / 844.14	51
Bristol Myers Squibb Pharm Res Inst Sea	3005 1ST AVE STE 200 SEATTLE WA 98121	WNW	0.17 / 912.96	55
BRISTOL-MEYERS SQUIBB RESEARCH LAB	3005 1ST AVE SEATTLE WA 98121	WNW	0.17 / 912.96	55
ONCOGEN	3005 1ST AVE SEATTLE WA 98121	WNW	0.17 / 912.96	55
Dendreon Corp	3005 1ST AVE SEATTLE WA 98121	WNW	0.17 / 912.96	55
BELLTOWN PEA PATCH	ELLIOTT AVE & VINE ST SEATTLE WA 98121	SSW	0.18 / 931.76	57
Unocal 0355	159 DENNY WAY SEATTLE WA 98109	WNW	0.18 / 945.58	60
BELLTOWN COURT CONDOS	2400 1ST AVE SEATTLE WA 98121	SE	0.19 / 1,005.13	71
ELLIOTT & BROAD	10 BROAD ST SEATTLE WA 98121	WSW	0.19 / 1,017.60	74

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Graphicolor Inc	3018 WESTERN AVE SEATTLE WA 98121-1023	W	0.21 / 1,117.79	82
Champion-Teutsch Property	124 DENNY WAY SEATTLE WA 98109	WNW	0.22 / 1,143.70	86
IVARS SEAFOOD BAR	3101 1ST AVE SEATTLE WA 98121-1051	WNW	0.24 / 1,268.70	102
Valco Graphics Inc Western Ave	3104 WESTERN AVE SEATTLE WA 98121	WNW	0.26 / 1,367.35	111
55 Battery LLC	2334 ELLIOTT AVE / 55 BATTERY ST SEATTLE WA 98121	SSE	0.27 / 1,411.12	116
UNOCAL ELLIOTT AVE N OF BAY ST GW PLUME	ELLIOTT AVE & BAY ST NEC SEATTLE WA 98121	W	0.27 / 1,449.04	119
Shell Station 121702	10 DENNY WAY SEATTLE WA 98109	WNW	0.29 / 1,552.46	127
133 Queen Anne Property	133 QUEEN ANNE AVE N SEATTLE WA 98109	WNW	0.34 / 1,790.09	142
Barrat Transfer & Storage	123 QUEEN ANNE AVE N SEATTLE WA 98109	WNW	0.34 / 1,817.77	144
SEATTLE PORT OF BELL ST PIER 66	2201 ALASKAN WAY TERM 66 PIERCE MARINE SEATTLE WA 98121	SSE	0.35 / 1,853.03	149
2200 Western Avenue LLC	2200 Western Ave Seattle WA 98121	SE	0.36 / 1,875.55	151
Basil Lee Property	505 HARRISON ST SEATTLE WA 98109	NNE	0.39 / 2,077.96	167
BAY VIEW BLDG	129 1ST AVE W SEATTLE WA 98119	WNW	0.40 / 2,119.04	175


Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Elliott Bay Bicycles	2114 WESTERN AVE SEATTLE WA 98121	SE	0.42 / 2,219.31	185
King County Denny Way CSO	3165 ALASKAN WAY SEATTLE WA 98121	WNW	0.42 / 2,236.09	187
Seattle Waterfront Marriott Hotel	2100 ALASKAN WAY SEATTLE WA 98121	SSE	0.45 / 2,352.02	197
Seattle Vagabond Inn	325 AURORA AVE N SEATTLE WA 98109	NE	0.47 / 2,459.32	203
Seattle Mercer Ops Base	520 5TH AVE N SEATTLE WA 98109	NNE	0.49 / 2,565.68	215
IRIS Holding LLC	500 5TH AVE N SEATTLE WA 98109	NNE	0.50 / 2,618.41	220

DRYCLEANERS - Registered Drycleaners List

A search of the DRYCLEANERS database, dated Jul 12, 2022 has found that there are 2 DRYCLEANERS site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Faulkenbury Wright	501 DENNY WAY SEATTLE WA 98109	ENE	0.21 / 1,118.54	83

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
A 1 Laundry Inc	2401 1st Ave Seattle WA 98121	SE	0.19 / 1,026.78	76



Map: 1.0 Mile Radius


Order Number: 22092804724

Address: Belltown Tower, Seattle, WA

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- Plume
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Map: 0.5 Mile Radius


Order Number: 22092804724

Address: Belltown Tower, Seattle, WA

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- Plume
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Map: 0.25 Mile Radius

Order Number: 22092804724

Address: Belltown Tower, Seattle, WA

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- Plume
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Aerial **Year: 2021**

Address: Belltown Tower, Seattle, WA

Source: ESRI World Imagery

Order Number: 22092804724

© ERIS Information Inc.



Topographic Map

Year: 2017

Order Number: 22092804724

Address: Belltown Tower, WA

Quadrangle(s): Seattle South, WA; Seattle North, WA; Duwamish Head, WA; Shilshole Bay, WA

© ERIS Information Inc.

Source: USGS Topographic Map

Detail Report

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	1 of 2	W	0.00 / 0.00	103.67 / -2	2729 SECOND AVE SEATTLE WA	HMIRS

Incident County: KING

HMIR Historical Reports

Report No:	I-2009110137	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	10/08/2009	**Report Submit Src:**	Paper
Time of Incident:	1230	**Inc Multiple Rows:**	No
Haz Class Code:	5.2	**Inc Non US State:**	
Hazardous Class:	ORGANIC PEROXIDE	**Mode Transport:**	Highway
Commodity Short Nm:	ORGANIC PEROXIDE TYPE F	**Transport Phase:**	IN TRANSIT
Commodity Long Nm:	ORGANIC PEROXIDE TYPE F LIQUID	**Incident Occrrnce:**	
Trade Name:	ORGANIC PEROXIDE TYPE F	**Mat Ship Approval?:**	No
ID No:	UN3109	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	USF REDDAWAY INC.
Qty Released:	0.1250	**CR Street Name:**	7720 SW MOHAWK ST BLDG H
Unit of Measure:	Liquid - Gallon	**CR City:**	TUALATIN
What Failed:	104	**CR State:**	OR
What Failed Desc:	Body	**CR Postal Code:**	97062-8120
How Failed Code:	309	**CR Non US State:**	
How Failed Desc:	Punctured	**CR Fed DOT ID:**	62227
Failure Cause Code:	516	**CR Hazmat Reg ID:**	052909550094RT
Failure Cause Desc:	Impact with Sharp or Protruding Object (e.g. nails)	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	ECOLAB INC.
Cont1 Pkging Type:	Jerrican	**Shipper Street Name:**	18383 RAILROAD ST
Cont1 Const Mat:	Plastic	**Shipper City:**	CITY OF INDUSTRY
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:	5	**Shipper Postal:**	91748-1218
C1 Capacity UOM:	LGA	**Shipper Non US St:**	
Cont1 Pkg Amt:	5	**Shipper Country:**	US
C1 Pkg Amt UOM:	LGA	**Shipper Waybill:**	3900234211
Cont1 Pkg No:	2	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	1	**Origin City:**	SAN JOSE
Cont1 Pkg Mnfctr:		**Origin State:**	CALIFORNIA
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	95133
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Plastic	**Destination City:**	SEATTLE
C1 Pkg Dsign Pres.:		**Destination State:**	WASHINGTON
C1 Dsign Press UOM:		**Destination Postal:**	98101
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	No	**Ship Phase Transfer:**	No
Other Cleanup:	Yes	**Contact Name:**	STEVE SHINNERS
Damage > 500:	Yes	**Contact Title:**	SR MGR - INDUSTRIAL SAFETY AND ENV
Material Loss:	20	**Contact Business:**	YRC INC.
Carrier Damage:	0	**Contact Street:**	10990 ROE AVE.
Property Damage:	0	**Contact City:**	OVERLAND PARK
Response Cost:	0	**Contact State:**	KS
Remediation Cost:	1100	**Contact Postal:**	66211
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	1120	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	PAIL PLS
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Plastic pail open head capacity 10 gallons or less
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: DRUMS SHIFTED ON PALLET NAIL ON PALLET STUCK OUT CAUSING PUNCTURE TO ONE DRUM. A HAZMAT TEAM WAS CALLED OUT TO HANDLE THE DECONTAMINATION AND OVERPACK THE DAMAGED PAIL INTO A SALVAGE RECOVERY DRUM.

Recommend Actions Taken: PROPERLY SECURE HAZMAT PRIOR TO TRANSPORTING.

1	2 of 2	W	0.00 / 0.00	103.67 / -2	2729 SECOND AVE SEATTLE WA	HMIRS

Incident County: KING

HMIR Incident Reports

Report No:	I-2009110137	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2009-10-08	**Report Submit Src:**	Paper
Time of Incident:	1230	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	5.2	**Mode Transport:**	Highway

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Commodity Short Nm:	ORGANIC PEROXIDE TYPE F,	**Transport Phase:**	In Transit
Commodity Long Nm:	ORGANIC PEROXIDE TYPE F, LIQUID	**Incident Occrrnce:**	
Trade Name:	ORGANIC PEROXIDE TYPE F	**Mat Ship Approval?:**	No
ID No:	UN3109	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	REDDAWAY
Qty Released:	0.125	**CR Street Name:**	16277 S.E. 130TH AVENUE
Unit of Measure:	Liquid - Gallon	**CR City:**	CLACKAMAS
What Failed:	104	**CR State:**	OR
What Failed Desc:	Body	**CR Postal Code:**	97015
How Failed Code:	309	**CR Non US State:**	
How Failed Desc:	Punctured	**CR Fed DOT ID:**	62227
Failure Cause Code:	516	**CR Hazmat Reg ID:**	052909550094RT
Failure Cause Desc:	Impact with Sharp or Protruding Object (e.g., nails)	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	ECOLAB
Cont1 Pkging Type:	Jerrican	**Shipper Street Name:**	640 LENFEST RD
Cont1 Const Mat:	Plastic	**Shipper City:**	SAN JOSE
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:	5	**Shipper Postal:**	95133
C1 Capacity UOM:	LGA	**Shipper Non US St:**	
Cont1 Pkg Amt:	5	**Shipper Country:**	US
C1 Pkg Amt UOM:	LGA	**Shipper Waybill:**	3900234211
Cont1 Pkg No:	2	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	1	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	US
C1 Test Const Mat:	Plastic	**Destination City:**	SEATTLE
C1 Pkg Dsign Pres.:	0	**Destination State:**	WASHINGTON
C1 Dsign Press UOM:		**Destination Postal:**	98101
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	No	**Ship Phase Transfer:**	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Other Cleanup:	Yes	**Contact Name:**	STEVE SHINNERS
Damage > 500:	Yes	**Contact Title:**	SR MGR - INDUSTRIAL SAFETY AND ENV
Material Loss:	20	**Contact Business:**	YRC INC.
Carrier Damage:	0	**Contact Street:**	10990 ROE AVE.
Property Damage:	0	**Contact City:**	OVERLAND PARK
Response Cost:	0	**Contact State:**	KS
Remediation Cost:	1100	**Contact Postal:**	66211
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	1120	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	DRUM NON-METAL
Haz Hosp Old Form:	0	**HMIS Container Code:**	PAIL PLS
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Plastic pail, open head, capacity 10 gallons or less
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: DRUMS SHIFTED ON PALLET NAIL ON PALLET STUCK OUT CAUSING PUNCTURE TO ONE DRUM. A HAZMAT TEAM WAS CALLED OUT TO HANDLE THE DECONTAMINATION AND OVERPACK THE DAMAGED PAIL INTO A SALVAGE RECOVERY DRUM.

Recommend Actions Taken: PROPERLY SECURE HAZMAT PRIOR TO TRANSPORTING.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
2	1 of 2	N	0.01 / 55.17	108.60 / 3	2800 BLOCK OF 2ND ST SEATTLE WA	ERTS

Incident ID:	511738	**Latitude:**	
Incident Date:	2000-06-20	**Longitude:**	
County:	KING		
Location:			

Initial Report Details

Initial Report Substance Name:	Any
Initial Report Subst Catego:	Smoke
Initial Report Subst Quanti:	
Initial Report Substance Unit:	
Initial Report Medium Name:	N/A
Initial Report Medium Category:	Air
Initial Report Cause Category:	Human error
Initial Report Cause Name:	Unknown
Initial Report Source Name:	Undetermined
Initial Report Source Category:	Historical
Initial Report Activity Name:	Unknown
Initial Report Comment Desc:	A PIPE IS STICKING OUT OF WINDOW OF BUILDING AT 28

Follow up Details

ERTS Follow up No:	
Follow up Substance Name:	
Follow up Substance Quantity:	
Follow up Subst Unit of Meas:	
Follow up Cause Name:	
Follow up Medium Name:	
Follow up Source Nname:	
Follow up Activity Name:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Potential Details

Pot Resp Party First Name:
Pot Resp Prty Last Name:
Potentially Resp Party Org: UNKNOWN

Initial Comments

Initial Report Comment:

ERTS Number 511738 - A PIPE IS STICKING OUT OF WINDOW OF BUILDING AT 2800 BLOCK OF SECOND ST, SEATTLE. THIS MORNING, FUMES COMING OUT WERE BLACKISH COLOR. AT 9:50 AM TODAY THERE IS NOTHING COMING OUT. EARLY LAST SUMMER (1999) THE PAINTER'S DISTRICT CALLED ERTS WITH THE SAME CONCERN, AND THE PROBLEM SEEMED TO BE HANDLED.

Historic Referral Contact Information - ReferralDate: 2000-06-20 FirstName: MiddleName: LastName: STEVE FRY Email: PhoneNumber: OrganizationName: AIR POLLUTION CONTROL AUTHORITY WorkLocation: UNKNOWN

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
2	2 of 2	N	0.01 / 55.17	108.60 / 3	2800 BLOCK OF 2ND ST SEATTLE WA	SPILLS

Incident ID: 511738
Incident Date:
Latitude:
Longitude:

Location:
Address: 2800 BLOCK OF 2ND ST
City: SEATTLE
County: KING

Spill Information

Incident Date: 6/20/2000
Latitude: NULL
Longitude: NULL

Spill Details Historical

Material: SMOKE
Qty: NULL
Medium: AIR
Impact: AIR POLLUTION
Cause: UNKNOWN
Activity: UNKNOWN

Source: UNKNOWN
Sheen Only: 0
Waterway: NULL
Prp Business Name: UNKNOWN
Prp First Name: NULL
Prp Last Name:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
3	1 of 5	SSW	0.04 / 184.96	92.46 / -13	SEA COAST TOWING INC HOME OFFI 2701 1ST AVE SEATTLE WA 98121	RCRA NON GEN

EPA Handler ID: WAD988477253
Gen Status Universe: No Report
Contact Name:
Contact Address:
Contact Phone No and Ext:
Contact Email:
Contact Country:
County Name: KING
EPA Region: 10
Land Type: Other
Receive Date: 19910524
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19910523
Handler Name:	SEA COAST TOWING INC HOME OFFI
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19910523
Handler Name:	SEA COAST TOWING INC HOME OFFI
Source Type:	Notification
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	19910524
Handler Name:	SEA COAST TOWING INC HOME OFFI
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	2701 1ST AVE
Name:	SEA COAST TOWING INC HOME OFFI	***Street 2:***	
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	000-000-0000	***Country:***	US
Source Type:	Implementer	***Zip Code:***	98121

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	2701 1ST AVE
Name:	SEA COAST TOWING INC HOME OFFI	***Street 2:***	
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA

Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2701 1ST AVE
Name:	SEA COAST TOWING INC HOME OFFI	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2701 1ST AVE
Name:	SEA COAST TOWING INC	**Street 2:**	
Date Became Current:	19960502	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2701 1ST AVE
Name:	SEA COAST TOWING INC	**Street 2:**	
Date Became Current:	19960502	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2701 1ST AVE
Name:	SEA COAST TOWING INC HOME OFFI	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2701 1ST AVE
Name:	SEE PAPER COPY	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2701 1ST AVE
Name:	SEA COAST TOWING INC	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121-1123

Historical Handler Details

Receive Dt:	19910523
Generator Code Description:	Not a Generator, Verified
Handler Name:	SEA COAST TOWING INC HOME OFFI

3	2 of 5	SSW	0.04 / 184.96	92.46 / -13	**Sea Coast Towing Inc Home Offi** **2701 1ST AVE** **SEATTLE WA 98121**	ALL SITES

Facility/Site ID:	42967265
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Program ID: WAD988477253
Facility Alternate:
Interaction ID: 44188
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 07-Sep-1990
Interact End Dt: 30-Sep-1990
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.61596
GIS longitude: -122.3507

3	3 of 5	SSW	0.04 / 184.96	92.46 / -13	PIER 70 2701 1ST AVE SEATTLE WA	ERTS

Incident ID: 555687
Incident Date: 2006-06-08
County: KING
Location: PIER 70
Latitude: 47.613249000000003
Longitude: 122.355081

Initial Report Details

Initial Report Substance Name: Unknown
Initial Report Subst Catego: Oil
Initial Report Subst Quanti: 1
Initial Report Substance Unit: Sheen
Initial Report Medium Name: Surface Water-Marine
Initial Report Medium Category: Water
Initial Report Cause Category: Human error
Initial Report Cause Name: Unknown
Initial Report Source Name: Tank
Initial Report Source Category: Vessel
Initial Report Activity Name: Transferring
Initial Report Comment Desc: RECEVIED INFO VIA EMAIL FROM WA STATE EOC:

DESC

Follow up Details

ERTS Follow up No: 73231
Follow up Substance Name: Unknown
Follow up Substance Quantity: 1
Follow up Subst Unit of Meas: Sheen
Follow up Cause Name: Unknown
Follow up Medium Name: Surface Water-Marine
Follow up Source Nname: Tank
Follow up Activity Name: Transferring

Potential Details

Pot Resp Party First Name:
Pot Resp Prty Last Name: UNK
Potentially Resp Party Org:

Follow up Comments

Follow up Comment:

ERTS Number 555687 - CONTACTED JANICE PAGE WITH ENTRIX - VERIFIED INFORMATION.

CONTACTED USCG AND THEY HAVE PI`S GOING TO THE VESSEL - THEY ARE LEAVING NOW (1145 HOURS) WILL REPORT BACK TO US THEIR FINDINGS.

HAVE PAGED PSFO FOR A HEADS UP AND REPORTED TO MIKE CAHILL.

WAS CONTACED BY USCG AND REPORT NO SHEEN PRESENT, WAS A MILITARY VSL - CIV. RUN VSL - HAS MOVED TO MANCHESTER - THEY WERE BUNKERING BUT NO SPILL OCCURRED. CALLER HAD REPORTED A DIFFERENCE IN TEXTURE TO WATER. - USCG DID NOT FIND A SHEEN OR SIGN OF A SHEEN. NFA BY SPILLS. CONTACTED MR. CAHILL AND WAS TAKEN OFF STANDBY FOR THIS EVENT.

Follow up Comment:

ERTS Number 555687 - Historic Investigator Contact Information - FirstName: HOWARD MiddleName: LastName: ZORZI OrganizationName: SPILLS, PREVENTION, PREPAREDNESS AND RESPONSE WorkLocation: NWRO

Follow up Comment:

ERTS Number 555687 - Historic Referral Contact Information - ReferralDate: 2006-06-08 FirstName: HOWARD MiddleName: LastName: ZORZI Email: hzor461@ecy.wa.gov PhoneNumber: (425) 649-7262 OrganizationName: SPILLS, PREVENTION, PREPAREDNESS AND RESPONSE WorkLocation: NWRO

Initial Comments

Initial Report Comment:

ERTS Number 555687 - RECEVIED INFO VIA EMAIL FROM WA STATE EOC:

DESCRIPTION OF INCIDENT
THE CALLER STATED THAT A VESSEL WAS PERFORMING AN OIL TRANSFER OPERATION, WHEN A SHEEN WAS NOTICED RUNNING OFF THE SIDE OF THE VESSEL.

NATIONAL RESPONSE CENTER - FLASH FAX
GOVERNMENT USE ONLYGOVERNMENT USE ONLY***
DO NOT RELEASE this information to the public without
permission from the NATIONAL RESPONSE CENTER 1-800-424-8802

Incident Report # 799993

INCIDENT DESCRIPTION

*Report taken by: CIV JONES at 12:44 on 08-JUN-06
Incident Type: VESSEL
Incident Cause: UNKNOWN
Affected Area: PUGET SOUND
The incident was discovered on 08-JUN-06 at 09:40 local time.
Affected Medium: WATER PUGET SOUND

REPORTING PARTY
Name: JANICE PAGE
Organization: ENTRIX
Address: 2701 FIRST AVE
SEATTLE, WA 98121

PRIMARY Phone: (206)2397387
Type of Organization: PRIVATE ENTERPRISE

SUSPECTED RESPONSIBLE PARTY
Name: UNKNOWN

XX

Type of Organization: UNKNOWN

INCIDENT LOCATION
2701 FIRST AVE County: KING
City: SEATTLE State: WA Zip: 98121
PIER 70 / PUGET SOUND

RELEASED MATERIAL(S)
CHRIS Code: OUN Official Material Name: UNKNOWN OIL
Also Known As:
Qty Released: 0 UNKNOWN AMOUNT Qty in Water: 0 UNKNOWN AMOUNT

DESCRIPTION OF INCIDENT
THE CALLER STATED THAT A VESSEL WAS PERFORMING AN OIL TRANSFER OPERATION, WHEN A SHEEN WAS NOTICED RUNNING OFF THE SIDE OF THE VESSEL.

INCIDENT DETAILS

Platform Rig Name:
Platform Letter:
Location Area ID:
Location Block ID:
OCSG Number:
OCSP Number:
State Lease Number:
Pier Dock Number: 70
Berth Slip Number:
---SHEEN INFORMATION---
Sheen Color: UNKNOWN
Sheen Odor Description:
Sheen Travel Direction:
Sheen Size Length:
Sheen Size Width:
---WATER INFORMATION---
Body of Water: PUGET SOUND
Tributary of:
Nearest River Mile Marker:
Water Supply Contaminated: NO

---VESSEL INFORMATION---
Name: UNKNOWN Number: Aground: NO
Flag:
Length: Breadth: Draught:
Type: TANKER
Hull Construction:
Fuel Capacity:
Fuel on Board:
Cargo Capacity:
Cargo on Board:

DAMAGES
Fire Involved: NO Fire Extinguished: UNKNOWN
INJURIES: Hospitalized: Empl/Crew: Passenger:

FATALITIES: Empl/Crew: Passenger: Occupant:
EVACUATIONS: Who Evacuated: Radius/Area:
Damages:

Hours Direction of
Closure Type Description of Closure Closed Closure
Air: N

Road: N Major N
Artery:
Waterway: N

Track: N

Passengers Transferred: UNKNOWN
Media Interest: NONE Community Impact due to Material: NO

REMEDIAL ACTIONS
NONE
Release Secured: UNKNOWN
Release Rate:
Estimated Release Duration:

WEATHER
Weather: OVERCAST, 60ºF

ADDITIONAL AGENCIES NOTIFIED
Federal:
State/Local:
State/Local On Scene:
State Agency Number:

NOTIFICATIONS BY NRC
ATSDR WA ATTN: HOPE HOUGH (PRIMARY)
08-JUN-06 12:47 (360)2363327
USCG HSOC AT DHS (USCG HSOC DESK)
08-JUN-06 12:47 (202)2828114
CG INVESTIGATIVE SERVICE HQ (PRIMARY)
08-JUN-06 12:47 (202)4936607
DOT CRISIS MANAGEMENT CENTER (PRIMARY)
08-JUN-06 12:47 (202)3661863
FEMA REGION 10 (PRIMARY)
08-JUN-06 12:47 (425)4874704
NATIONAL INFRASTRUCTURE COORD CTR (PRIMARY)
08-JUN-06 12:47 (202)2829201
NOAA RPTS FOR WA (PRIMARY)
08-JUN-06 12:47 (206)5266344
MSO PUGET SOUND (PRIMARY)
(206)2176002
WA STATE EMERGENCY MANAGEMENT (PRIMARY)
08-JUN-06 12:47 (800)2585990
TSA MARITIME AND LAND (PRIMARY)
08-JUN-06 12:47 (703)5633236

ADDITIONAL INFORMATION
THE CALLER HAD NO ADDITIONAL INFORMATION

*** END INCIDENT REPORT 799993 ***
Report any problems or Fax number changes by calling 1-800-424-8802
PLEASE VISIT OUR WEB SITE AT http://www.nrc.uscg.mil

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
3	4 of 5	SSW	0.04 / 184.96	92.46 / -13	PUGET SOUND 2701 1ST AVE SEATTLE WA	SPILLS

Incident ID:	555687	**Location:**	PUGET SOUND
Incident Date:	6/8/2006	**Address:**	2701 1ST AVE
Latitude:	47.613249	**City:**	SEATTLE
Longitude:	122.355081	**County:**	KING

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
3	5 of 5	SSW	0.04 / 184.96	92.46 / -13	2701 1ST AVE SEATTLE WA	SPILLS

Incident ID:	555687	**Location:**	
Incident Date:		**Address:**	2701 1ST AVE
Latitude:		**City:**	SEATTLE
Longitude:		**County:**	KING

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spill Information

Incident Date: 6/8/2006
Latitude: NULL
Longitude: NULL

Spill Details Historical

Material: PETROLEUM - UNKNOWN
Qty: 1
Medium: SURFACE WATER-MARINE
Impact: WATER POLLUTION
Cause: UNKNOWN
Activity: TRANSFERRING
Source: VESSEL - TANK
Sheen Only: 0
Waterway: PUGET SOUND
Prp Business Name: NULL
Prp First Name: NULL
Prp Last Name: UNK

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
4	1 of 1	S	0.04 / 200.06	93.83 / -12	2702 1ST AVE Seattle WA 98119	UST SEATTLE

Permit No: 3-43475
Date Issued: 07/23/2002
Fill Material: No Fill
Date Decommissioned: 07/23/2002
Type Decommissioned: Abandonment in Place
Tank Size: 300
Tank Age: 20+
Tank Content: HEATING OIL

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
5	1 of 2	E	0.04 / 205.62	114.10 / 8	GRANGE INSURANCE GROUP 200 CEDAR ST SEATTLE WA 98121	RCRA NON GEN

EPA Handler ID: WAH000019778
Gen Status Universe: No Report
Contact Name: MELODY OXLEY
Contact Address: 200 CEDAR ST , , SEATTLE , WA, 98121 , US
Contact Phone No and Ext: 206-448-4911
Contact Email:
Contact Country: US
County Name: KING
EPA Region: 10
Land Type: Other
Receive Date: 20030304
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No

Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20030303
Handler Name: GRANGE INSURANCE GROUP
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20021217
Handler Name: GRANGE INSURANCE GROUP
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20030303
Handler Name: GRANGE INSURANCE GROUP
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20030303
Handler Name: GRANGE INSURANCE GROUP
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20030304
Handler Name: GRANGE INSURANCE GROUP
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: GRANGE INSURANCE GROUP
Date Became Current:
Date Ended Current:
Phone: 206-448-4911
Source Type: Implementer
Street No:
Street 1: 200 CEDAR ST
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Owner
Type: Private
Name: GRANGE INSURANCE GROUP
Street No:
Street 1: 200 CEDAR ST
Street 2:

Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-448-4911	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	200 CEDAR ST
Name:	GRANGE INSURANCE GROUP	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-448-4911	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	200 CEDAR ST
Name:	GRANGE INSURANCE GROUP	**Street 2:**	
Date Became Current:	20021217	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-448-4911	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	200 CEDAR ST
Name:	GRANGE INSURANCE GROUP	**Street 2:**	
Date Became Current:	20021217	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-448-4911	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	200 CEDAR ST
Name:	GRANGE INSURANC G	**Street 2:**	
Date Became Current:	20021217	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-448-4911	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	200 CEDAR ST
Name:	GRANGE INSURANCE GROUP	**Street 2:**	
Date Became Current:	20021217	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-448-4911	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	200 CEDAR ST
Name:	GRANGE INSURANCE GROUP	**Street 2:**	
Date Became Current:	20021217	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-448-4911	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	200 CEDAR ST
Name:	MELODY O	**Street 2:**	
Date Became Current:	20021217	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-448-4911	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	200 CEDAR ST
Name:	GRANGE INSURANCE GROUP	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-448-4911	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Historical Handler Details

Receive Dt: 20030303
Generator Code Description: Not a Generator, Verified
Handler Name: GRANGE INSURANCE GROUP

Receive Dt: 20021217
Generator Code Description: Not a Generator, Verified
Handler Name: GRANGE INSURANCE GROUP

Receive Dt: 20030303
Generator Code Description: Not a Generator, Verified
Handler Name: GRANGE INSURANCE GROUP

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
5	2 of 2	E	0.04 / 205.62	114.10 / 8	Grange Insurance Group 200 CEDAR ST SEATTLE WA 98121	ALL SITES

Facility/Site ID: 5955968
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000019778
Facility Alternate:
Interaction ID: 17908
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 17-Dec-2002
Interact End Dt: 31-Dec-2002
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: Unknown
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.6164052233
GIS longitude: -122.350958573

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
6	1 of 5	NW	0.05 / 250.19	107.87 / 2	2821 2ND AVE SEATTLE WA	ERTS

Incident ID: 501975
Incident Date: 1999-01-11
County: KING
Location:
Latitude:
Longitude:

Initial Report Details

Initial Report Substance Name: Diesel oil/Marine gas
Initial Report Subst Catego: Oil
Initial Report Subst Quanti: 405
Initial Report Substance Unit: U.S. gallons
Initial Report Medium Name: Roadway-paved
Initial Report Medium Category: Impermeable surface
Initial Report Cause Category: Human error
Initial Report Cause Name: Unknown

Initial Report Source Name: Commercial/Industrial facility
Initial Report Source Category: Facility
Initial Report Activity Name: Refueling (vessel)
Initial Report Comment Desc: NUMBER 2 DIESEL WENT AROUND TANK BERM AND DOWN TWO

Follow up Details

ERTS Follow up No: 22640
Follow up Substance Name: Diesel oil/Marine gas
Follow up Substance Quantity: 405
Follow up Subst Unit of Meas: U.S. gallons
Follow up Cause Name: Unknown
Follow up Medium Name: Roadway-paved
Follow up Source Nname: Commercial/Industrial facility
Follow up Activity Name: Refueling (vessel)

Potential Details

Pot Resp Party First Name:
Pot Resp Prty Last Name:
Potentially Resp Party Org: SOUND OIL

Follow up Comments

Follow up Comment:

ERTS Number 501975 - NO RELEASE TO SOIL OR WATER, NFA. FINAL REPORT COMING, CLEANUP WAS RESTRICTED TO THE CONCRETE PARKING GARAGE.

COMPLETED AND CLOSED OUT IITS. 5/4/99

Follow up Comment:

ERTS Number 501975 - Historic Investigator Contact Information - FirstName: GAIL MiddleName: LastName: COLBURN OrganizationName: TOXICS CLEANUP WorkLocation: NWRO

Follow up Comment:

ERTS Number 501975 - Historic Referral Contact Information - ReferralDate: 1999-01-12 FirstName: MiddleName: LastName: SECTION HEAD Email: PhoneNumber: OrganizationName: TOXICS CLEANUP WorkLocation: NWRO

Initial Comments

Initial Report Comment:

ERTS Number 501975 - NUMBER 2 DIESEL WENT AROUND TANK BERM AND DOWN TWO FLOORS OF CONDOS. TANK WAS IN PARKING GARAGE. FOSS ENV RESPONDED IMMEDIATELY AND IS CLEANING UP. NO RELEASE TO SOIL OR WATER.

6	2 of 5	NW	0.05 / 250.19	107.87 / 2	2821 2ND AVE SEATTLE WA 98121	ERTS

Incident ID: 668052
Incident Date: 2016-10-05
County: KING
Location:
Latitude:
Longitude:

Initial Report Details

Initial Report Substance Name: Hydraulic oil
Initial Report Subst Catego: Oil
Initial Report Subst Quanti:
Initial Report Substance Unit: U.S. gallons
Initial Report Medium Name: Impermeable containment
Initial Report Medium Category: Impermeable surface
Initial Report Cause Category:
Initial Report Cause Name:
Initial Report Source Name: Truck
Initial Report Source Category: Vehicle
Initial Report Activity Name: Underway or in motion
Initial Report Comment Desc: CALLER REPORTS 0.5 CUPS OF HYDRAULIC FLUID SPILLIN

Follow up Details

ERTS Follow up No:
Follow up Substance Name:
Follow up Substance Quantity:
Follow up Subst Unit of Meas:
Follow up Cause Name:
Follow up Medium Name:
Follow up Source Nname:
Follow up Activity Name:

Potential Details

Pot Resp Party First Name:
Pot Resp Prty Last Name:
Potentially Resp Party Org: RECOLOGY CLEANSCAPES

Initial Comments

Initial Report Comment:

ERTS Number 668052 - CALLER REPORTS 0.5 CUPS OF HYDRAULIC FLUID SPILLING TO THE STREET DUE TO A LEAKING HYDRAULIC FITTING. CLEAN UP IS COMPLETE WITH ABSORBENT PADS.

Historic Referral Contact Information - ReferralDate: 2016-10-05 FirstName: Corey MiddleName: LastName: King Email: CKIN461@ecy.wa.gov ; 4254954390@onpage.com PhoneNumber: (425) 649-7092 OrganizationName: SPILLS, PREVENTION, PREPAREDNESS AND RESPONSE WorkLocation: NWRO

6	3 of 5	NW	0.05 / 250.19	107.87 / 2	2821 2ND AVE SEATTLE WA	SPILLS

Incident ID: 90778
Incident Date: 10/5/2016
Latitude: 47.62
Longitude: -122.35

Location:
Address: 2821 2ND AVE
City: SEATTLE
County: KING

Spill Details May 2016 - April 2019

Incident Category:
Incident Cat Desc:
Product: HYDRAULIC OIL
Spill Quantity: 0.03
Unit: Gals
Medium: Roadway - Paved
Medium Type Desc:
Activity: UNDERWAY OR IN MOTION
Impact: CONTAMINATED ROADWAY/PARKING LOT
Prp Bus Name: RECOLOGY CLEANSCAPES
Prp Contact Name:

Cause: MECHANICAL FAILURE
Cause Type Desc:
Source: Commercial Truck
Source Type Desc:
Regulated 1:
Primary Prp:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Narrative Description:						
6	4 of 5	NW	0.05 / 250.19	107.87 / 2	NULL 2821 2ND AVE SEATTLE WA	SPILLS

Incident ID:	501975	**Location:**	NULL
Incident Date:	1/11/1999	**Address:**	2821 2ND AVE
Latitude:	NULL	**City:**	SEATTLE
Longitude:	NULL	**County:**	KING

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
6	5 of 5	NW	0.05 / 250.19	107.87 / 2	2821 2ND AVE SEATTLE WA	SPILLS

Incident ID:	501975	**Location:**	
Incident Date:		**Address:**	2821 2ND AVE
Latitude:		**City:**	SEATTLE
Longitude:		**County:**	KING

Spill Information

Incident Date:	1/11/1999
Latitude:	NULL
Longitude:	NULL

Spill Details Historical

Material:	PETROLEUM - DIESEL FUEL	**Source:**	COMMERCIAL
Qty:	405	**Sheen Only:**	0
Medium:	ROADWAY-PAVED	**Waterway:**	NULL
Impact:	NONE	**Prp Business Name:**	SOUND OIL
Cause:	UNKNOWN	**Prp First Name:**	NULL
Activity:	REFUELING	**Prp Last Name:**	NULL

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
7	1 of 2	W	0.06 / 295.13	91.57 / -14	SEATTLE LABOR TEMPLE ASSOC PARKING LOT 2801 1ST AVE SEATTLE WA 98121	RCRA NON GEN

EPA Handler ID:	WAD982658270
Gen Status Universe:	No Report
Contact Name:	SEATTLE LABOR T SEATTLE LABOR T
Contact Address:	2800 1ST AVE RM 140 , , SEATTLE , WA, 98121-1114 , US
Contact Phone No and Ext:	000-000-0000
Contact Email:	
Contact Country:	US
County Name:	KING
EPA Region:	10
Land Type:	Private
Receive Date:	19960304
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19960304
Handler Name:	SEATTLE LABOR TEMPLE ASSOC PARKING LOT
Source Type:	Notification
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	19960304
Handler Name:	SEATTLE LABOR TEMPLE ASSOC PARKING LOT
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19960304
Handler Name:	SEATTLE LABOR TEMPLE ASSOC PARKING LOT
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	2800 1ST AVE STE 140
Name:	SEATTLE LABOR TEMPLE ASSOC	***Street 2:***	
Date Became Current:	19961206	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-441-7582	***Country:***	US
Source Type:	Notification	***Zip Code:***	98121

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	2800 1ST AVE STE 140
Name:	SEATTLE LABOR T S	***Street 2:***	
Date Became Current:	19960502	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-441-7582	***Country:***	US
Source Type:	Implementer	***Zip Code:***	98121-1114

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	2800 1ST AVE STE 140
Name:	SEATTLE LABOR TEMPLE ASSOC	***Street 2:***	

Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-441-7582	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121-1114
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2800 1ST AVE STE 140
Name:	HORD, CHARLES	**Street 2:**	
Date Became Current:	19961206	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-441-7582	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2800 1ST AVE STE 140
Name:	SEATTLE LABOR TEMPLE ASSOC	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-441-7582	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121-1114
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2800 1ST AVE STE 140
Name:	CHARLES H	**Street 2:**	
Date Became Current:	19961206	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-441-7582	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121-1114
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2800 1ST AVE STE 140
Name:	SEATTLE LABOR TEMPLE ASSOC	**Street 2:**	
Date Became Current:	19960502	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-441-7582	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121

Historical Handler Details

Receive Dt:	19960304
Generator Code Description:	Very Small Quantity Generator
Handler Name:	SEATTLE LABOR TEMPLE ASSOC PARKING LOT
Receive Dt:	19960304
Generator Code Description:	Not a Generator, Verified
Handler Name:	SEATTLE LABOR TEMPLE ASSOC PARKING LOT

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
7	2 of 2	W	0.06 / 295.13	91.57 / -14	**Seattle Labor Temple Assoc** **Parking Lot** **2801 1ST AVE** **SEATTLE WA 98121**	ALL SITES

Facility/Site ID:	81872766
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAD982658270
Facility Alternate:	
Interaction ID:	66203
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	30-Jun-1989

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Interact End Dt: 31-Dec-1994
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.61649
GIS longitude: -122.35162

---

8 | ***1 of 1*** | ***ESE*** | ***0.06 / 306.72*** | ***108.33 / 3*** | ***`JOB SITE`
2600 2ND AVE
SEATTLE WA*** | ***ERTS***

Incident ID: 533449
Incident Date:
County: KING
Location: `JOB SITE`
Latitude:
Longitude:

Initial Report Details

Initial Report Substance Name: Other
Initial Report Subst Catego: Oil
Initial Report Subst Quanti:
Initial Report Substance Unit:
Initial Report Medium Name: Storm drain pipe
Initial Report Medium Category: Water
Initial Report Cause Category: Human error
Initial Report Cause Name: Policy/Procedure; Incorrect
Initial Report Source Name: Construction site
Initial Report Source Category: Facility
Initial Report Activity Name: Storing
Initial Report Comment Desc: JOB SITE IN SEATTLE THAT STORES KEROSENE AND DIESE

Follow up Details

ERTS Follow up No:
Follow up Substance Name:
Follow up Substance Quantity:
Follow up Subst Unit of Meas:
Follow up Cause Name:
Follow up Medium Name:
Follow up Source Nname:
Follow up Activity Name:

Potential Details

Pot Resp Party First Name:
Pot Resp Prty Last Name:
Potentially Resp Party Org: UNKNOWN

---

9 | ***1 of 2*** | ***E*** | ***0.06 / 311.19*** | ***116.39 / 11*** | ***Dimension Seattle
225 Cedar Street
Seattle WA 98121*** | ***ALT FUELS***

Fuel Type Code: ELEC: Electric
Station Phone: 800-663-5633
Expected Date:
BD Blends:
NG Fill Type Code:
NG PSI:
ID: 147755
Updated at: 2022-08-01 00:31:23 UTC
CNG Dispenser No:
CNG Site Renew Src:
CNG Tot Compr Cap:
CNG Storage Cap:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Federal Agency ID:
Open Date: 2019-07-09
NG Vehicle Class:
LPG Primary:
E85 Blender Pump:
NG Fill Type Desc:
Hydrogen is Retail:
Federal Agency:
Facility Type:
Dt Last Confirmed: 2022-08-01
Restricted Access: false
Fed Agency Name:
Hydrogen Status Link:
Status: Open: The station is open.
Owner Type Desc:
E85 Blender Pump Desc:
NG Vehicle Class Desc:
Geocode Status Desc: The location is from a real GPS readout at the station.
LPG Primary Desc:
E85 Other Ethanol Blends:
EV Pricing: FREE
EV Pricing French:
EV on Site Renewable Source:
Intersection Directions:
CNG Fill Type Code:
CNG PSI:
CNG Vehicle Class:
LNG Site Renew Src:
LNG Vehicle Class:
LPG Nozzle Types:
Hydrogen Pressures:
Hydrogen Standards:
Latitude: 47.6166344
Longitude: -122.3495259

9	2 of 2	E	0.06 / 311.19	116.39 / 11	225 CEDAR ST Seattle WA 98121	UST SEATTLE

Permit No: 3-89824
Date Issued: 08/29/2012
Fill Material: X
Date Decommissioned: 08/29/2012
Type Decommissioned: Removal
Tank Size: 675 GALLON
Tank Age: 20 + YRS
Tank Content: FUEL OIL/DIESEL

10	1 of 2	NE	0.07 / 371.39	121.62 / 16	THIRD AVENUE PRODUCTIONS 2720 3RD AVE Seattle WA 98121	UST

UST ID: 11732
Facility Site ID: 11339432
Site Active: No
Responsible Unit: Northwest
Active Tag:
Alternate Site Names:
Region: Northwest
County: King
Latitude: 47.61723
Longitude: -122.350368

Tank Detail(s)

Tank Name: 1
Status Date: 08/06/1996
Install Date: 01/01/1980
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Steel
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material: Steel
Pipe Construction:
Pipe Corrosion Protection:
Tank Construction:
Tank Capacity:
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance:
Used Substance:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
10	2 of 2	NE	0.07 / 371.39	121.62 / 16	THIRD AVENUE PRODUCTIONS 2720 3RD AVE SEATTLE WA 98121-1260	ALL SITES

Facility/Site ID: 11339432
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 11732
Facility Alternate:
Interaction ID: 26091
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 01-Jan-1980
Interact End Dt: 03-May-2000
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83
Horizont 2: Address
Location Verified: N
GIS latitude: 47.61723
GIS longitude: -122.350368

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
11	1 of 1	ENE	0.07 / 372.20	119.08 / 13	2703 3RD AVE Seattle WA 98109	UST SEATTLE

Permit No: 3-45657
Date Issued: 01/21/2003
Fill Material: No Fill
Date Decommissioned: 01/21/2003
Type Decommissioned: Abandonment in Place
Tank Size: 300
Tank Age: 20+
Tank Content: HEATING OIL

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
12	1 of 1	NNE	0.07 / 384.66	122.44 / 17	Parking Lot of Wells Fargo 2800 3rd Ave Seattle WA 98121	ERTS

Incident ID: 701330
Incident Date: 2020-10-16
County: King
Latitude: 47.64622
Longitude: -122.36127

Location: Parking Lot of Wells Fargo

Initial Report Details

Initial Report Substance Name: Other
Initial Report Subst Catego: Chemical
Initial Report Subst Quanti:
Initial Report Substance Unit:
Initial Report Medium Name: Impermeable surface
Initial Report Medium Category: Impermeable surface
Initial Report Cause Category: Human error
Initial Report Cause Name: Unknown
Initial Report Source Name: Commercial truck
Initial Report Source Category: Vehicle
Initial Report Activity Name:
Initial Report Comment Desc: caller reported a fire in the back of the Recycle

Follow up Details

ERTS Follow up No: 182273
Follow up Substance Name:
Follow up Substance Quantity:
Follow up Subst Unit of Meas:
Follow up Cause Name: Unknown
Follow up Medium Name:
Follow up Source Nname:
Follow up Activity Name:

Follow up Details

ERTS Follow up No: 182271
Follow up Substance Name:
Follow up Substance Quantity:
Follow up Subst Unit of Meas:
Follow up Cause Name: Unknown
Follow up Medium Name:
Follow up Source Nname:
Follow up Activity Name:

Follow up Details

ERTS Follow up No: 182272
Follow up Substance Name:
Follow up Substance Quantity:
Follow up Subst Unit of Meas:
Follow up Cause Name: Unknown
Follow up Medium Name: Impermeable surface
Follow up Source Nname:
Follow up Activity Name:

Potential Details

Pot Resp Party First Name:
Pot Resp Prty Last Name:
Potentially Resp Party Org:

Follow up Comments

Follow up Comment:

ERTS Number 701330 - Based on follow-up narrative in SPIIS report by Agustina Cartegena, it appears the site fully cleaned the debris and the FD arrived and investigated. No impacts to drains entering the Seattle MS4 is reported, and all debris was retained and collected in the private Wells Fargo

parking lot, so at this time there is NFA from the MS4 permit.

Initial Comments

Initial Report Comment:

ERTS Number 701330 - caller reported a fire in the back of the Recycle Truck possibly caused by lithium batteries. Driver dumped the Truck contents into the parking lot. Fire Department came and put the fire out. Caller did not know if Fire Dept used water only but thought that batteries may be involved in causing fire.

one drain in parking lot.

Debris has been cleaned up with 20 and 30 yard roll off boxes. Bob Cat used to scoop up debris and placed into boxes to haul away. pavement was swept up and cleaned of any remaining debris.

13	1 of 1	ESE	0.08 / 418.39	107.49 / 2	2607 2nd Ave (Alley) SEATTLE WA	ERTS

Incident ID: 681899
Incident Date: 2018-06-11
County: KING
Location:
Latitude:
Longitude:

Initial Report Details

Initial Report Substance Name:	Sewage/Sludge
Initial Report Subst Catego:	Waste
Initial Report Subst Quanti:	200
Initial Report Substance Unit:	U.S. gallons
Initial Report Medium Name:	Roadway-paved
Initial Report Medium Category:	Impermeable surface
Initial Report Cause Category:	Human error
Initial Report Cause Name:	Unknown
Initial Report Source Name:	Domestic
Initial Report Source Category:	Private property
Initial Report Activity Name:	Routine/Normal operations
Initial Report Comment Desc:	Called out to work order # 9056330 by Seattle City

Follow up Details

ERTS Follow up No:
Follow up Substance Name:
Follow up Substance Quantity:
Follow up Subst Unit of Meas:
Follow up Cause Name:
Follow up Medium Name:
Follow up Source Nname:
Follow up Activity Name:

Potential Details

Pot Resp Party First Name:	Tony
Pot Resp Prty Last Name:	
Potentially Resp Party Org:	Year Up Puget Sound

Initial Comments

Initial Report Comment:

ERTS Number 681899 - Called out to work order # 9056330 by Seattle City Light for sewer entering their electrical vault in sidewalk east of 1st ave on

Cedar St. The Vault had automated pumps within them to protect the electric components. So sewer was being pumped up to the Right of Way and flowing west to the NEC of 1st and Cedar. The inlet to combined catch basin asset # 563430 had a construction sock blocking the flow so I removed it so the flow wouldn't go any further down the street. We later found two other vaults that had sewer in them and the sewer was moving thru the conduit pipes from vault to vault. Other vault had been pumping out into alley but was covered by garbage cans. Flow went to NEC of 1st and vine, cb asset # 563562. I've created work orders to have the flows paths to both cb's cleaned and the asset cleaned and pumped. After pumping them down, we dyed the nearest building and the dye showed from side sewer 2607 2nd Ave in to the vault we were pumping. Notified business at address of possible issue. (btw... this is the 3rd time doing this ERTS but kept getting error messages when I submitted. 1st one did not have all the info this one does as we were still investigating.

From: noreply@ecy.wa.gov [mailto:noreply@ecy.wa.gov]
Sent: Monday, June 11, 2018 4:43 PM
To: ECY RE NWRO ERTS <nwroerts@ECY.WA.GOV>
Subject: Report of an environmental issue in King county

Environmental issue report in King
Form updated 6/11/2018 4:41:46 PM
Information about you
Your first name TINA
Your last name RAMOS
Your business name (if any) SEATTLE PUBLIC UTILITIES
Your street address 714 S CHARLES ST
Apartment number (if any)
Your city SEATTLE
Your zip code 98134
Your primary phone number (206) 218-6332
Your secondary phone number (206) 522-6234
Your Email tina.ramos@seattle.gov

Confidential? (If you indicate `Yes,` your name, etc. will be kept confidential.) No
What happened? Description of incident
Date of incident 6/11/2018 12:00:00 AM
Medium Roadway - paved
If Other, please specify
Material Sewage or sludge
If Other, please specify
Quantity 200
Unit of measure Gallon
Source Residential
Cause Unknown
Activity Routine or normal operations
Impacts Unknown
Vessel name
Vessel type Unknown
Additional description of incident (Maximum 1,500 characters, approx. 250 words) Called out to work order # 9056330 by Seattle City Light for sewer entering their electrical vault in sidewalk east of 1st ave on Cedar St. The Vault had automated pumps within them to protect the electric components. So sewer was being pumped up to the Right of Way and flowing west to the NEC of 1st and Cedar. The inlet to combined catch basin asset # 563430 had a construction sock blocking the flow so I removed it so the flow wouldn't go any further down the street. We later found two other vaults that had sewer in them and the sewer was moving thru the conduit pipes from vault to vault. Other vault had been pumping out into alley but was covered by garbage cans. Flow went to NEC of 1st and vine, cb asset # 563562. I've created work orders to have the flows paths to both cb's cleaned and the asset cleaned and pumped. After pumping them down, we dyed the nearest building and the dye showed from side sewer 2607 2nd Ave in to the vault we were pumping. Notified business at address of possible issue. (btw... this is the 3rd time doing this ERTS but kept getting error messages when I submitted. 1st one did not have all the info this one does as we were still investigating.
Where did it happen? Location of incident
County King
Nearest city SEATTLE
Street address 2607 2ND AVE (ALLEY)
Waterway
Waterway type Unknown
Directions
Who is responsible? Potentially responsible party information
First name TONY (FACILITIES MAINTENANCE)
Last name
Business (if any) YEAR UP PUGET SOUND
Street address 2607 2ND AVE
Apartment or suite (if any)
City (206) 441-4465
State WA
U.S. ZIP code 98121
Phone number (206) 441-4465
Other information about the potentially responsible party SEATTLE CITY LIGHT

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Historic Referral Contact Information - ReferralDate: 2018-06-12 FirstName: Shawn MiddleName: LastName: McKone Email: shmc461@ecy.wa.gov PhoneNumber: (425) 649-7037 OrganizationName: WATER QUALITY WorkLocation: NWRO

Historic Referral Contact Information - ReferralDate: 2018-06-12 FirstName: MiddleName: LastName: NWRO WQ Email: nwrowqerts@ecy.wa.gov PhoneNumber: (425) 649-7105 OrganizationName: WATER QUALITY WorkLocation: NWRO

Historic Referral Contact Information - ReferralDate: 2018-06-12 FirstName: ERIC AUTRY MiddleName: LastName: SEATTLE PUBLIC UTIL WQ Email: ERTS@seattle.gov PhoneNumber: (206) 684-7988 OrganizationName: SEATTLE WorkLocation: PUBLIC UTILITIES

14	1 of 2	N	0.08 / 419.66	121.85 / 16	COX MEDIA GROUP SEATTLE 2807 3RD AVE Seattle WA 98121	UST

UST ID: 12511
Facility Site ID: 6767258
Site Active: Yes
Responsible Unit: Northwest
Active Tag: A5376
Alternate Site Names: KIRO INC

Region: Northwest
County: King
Latitude: 47.617
Longitude: -122.351361

Tank Detail(s)

Tank Name: 2
Status Date: 04/15/1994
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date: 07/20/2021
Tank Status: Removed
Tank Material: Steel
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material: Steel
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction: Single Wall Tank
Tank Capacity: 111 TO 1,100 Gallons
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Heating Fuel
Used Substance:

Tank Detail(s)

Tank Name: 7867
Status Date: 08/06/1996
Install Date: 04/20/1994
Upgrade Date: 04/20/1994
Perm Closure Date:
Tank Status: Operational
Tank Material: Steel Clad with Corrosion Resistant Composite
Tank Corrosion Protection: Corrosion Resistant
Tank Manifold: Non-Manifolded Tank

Tank Construction: Double Wall Tank
Tank Capacity: 2,001 to 4,999 Gallons
Actual Capacity: 4000
Pipe Install Date:
Endorsement Expire: 01/31/2023

Tank Release Detection:	Automatic Tank Gauging
Tank Tightness Test:	
Tank Spill Prevention:	Single Wall Spill Bucket
Tank Overfill Prevention:	Automatic Shutoff (fill pipe)
Pipe Material:	Flexible Piping
Pipe Construction:	Double Wall Pipe
Pipe Corrosion Protection:	Corrosion Resistant
Tank SFC:	Not Applicable
Dispenser SFC:	Not Applicable
Primary Pipe Release Detection:	Every 3 years Line TT (Non-Safe Suction)
Secondary Pipe Rel Detect:	
Pipe Pumping System:	Non-Safe Suction
Turbine Sump Construction:	

Compartments

Compartment No:	1
Compart Capacity:	4000
Stored Substance:	Diesel
Used Substance:	Emergency Power Generation

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
14	*2 of 2*	*N*	*0.08 / 419.66*	*121.85 / 16*	***KIRO INC*** ***2807 3RD AVE*** ***SEATTLE WA 98121***	***ALL SITES***

Facility/Site ID:	6767258
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	12511
Facility Alternate:	Cox Media Group Seattle
Interaction ID:	19557
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	UST
Interaction Desc:	Underground Storage Tank
Interact Start Dt:	20-Mar-2000
Interact End Dt:	
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	UST
Database Name Desc:	Underground Storage Tanks

Facility Location Detail

Horizontal:	20ft	***Location Verified:***	N
Horizont 1:	NAD83	***GIS latitude:***	47.617
Horizont 2:	Address	***GIS longitude:***	-122.351361

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
15	*1 of 1*	*W*	*0.08 / 421.07*	*90.75 / -15*	***FRANK JAMES AUTO & PEOPLES VOLKSWAGEN*** ***2900-2922 1ST AVENUE*** ***Seattle WA 98121***	***UST***

UST ID:	10214	***Region:***	Northwest
Facility Site ID:	9468585	***County:***	King
Site Active:	No	***Latitude:***	47.61686
Responsible Unit:	Northwest	***Longitude:***	-122.353768
Active Tag:			
Alternate Site Names:			

Tank Detail(s)

Tank Name: 3
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Steel
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material: Steel
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction: Single Wall Tank
Tank Capacity:
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Leaded Gasoline
Used Substance:

Tank Detail(s)

Tank Name: 11
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Steel
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material: Steel
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction: Single Wall Tank
Tank Capacity: 111 TO 1,100 Gallons
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance:

Used Substance:

Tank Detail(s)

Tank Name: 5
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Steel
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material: Steel
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction: Single Wall Tank
Tank Capacity: 111 TO 1,100 Gallons
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Used Oil/Waste Oil
Used Substance:

Tank Detail(s)

Tank Name: 8
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Steel
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material: Steel
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction: Single Wall Tank
Tank Capacity: 111 TO 1,100 Gallons
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1

Compart Capacity:
Stored Substance:
Used Substance:

Tank Detail(s)

Tank Name: 1
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Steel
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material: Steel
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction: Single Wall Tank
Tank Capacity:
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Leaded Gasoline
Used Substance:

Tank Detail(s)

Tank Name: 4
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Steel
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material: Steel
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction: Single Wall Tank
Tank Capacity: 111 TO 1,100 Gallons
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Used Oil/Waste Oil
Used Substance:

Tank Detail(s)

Tank Name: 7
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Steel
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material: Steel
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction: Single Wall Tank
Tank Capacity: 111 TO 1,100 Gallons
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance:
Used Substance:

Tank Detail(s)

Tank Name: 10
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Steel
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material: Steel
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction: Single Wall Tank
Tank Capacity: 111 TO 1,100 Gallons
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance:
Used Substance:

Tank Detail(s)

Tank Name: 2
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Steel
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material: Steel
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction: Single Wall Tank
Tank Capacity:
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Unleaded Gasoline
Used Substance:

Tank Detail(s)

Tank Name: 6
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Steel
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material: Steel
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction: Single Wall Tank
Tank Capacity: 111 TO 1,100 Gallons
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance:
Used Substance:

Tank Detail(s)

Tank Name: 9
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Steel
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material: Steel
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction: Single Wall Tank
Tank Capacity: 111 TO 1,100 Gallons
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance:
Used Substance:

16	1 of 6	NW	0.08 / 443.04	107.39 / 2	WA STATE FERRY SYSTEM 2911 2ND AVE SEATTLE WA	ERTS

Incident ID: 553152
Incident Date: 2006-01-26
County: KING
Location: WA STATE FERRY SYSTEM

Latitude:
Longitude:

Initial Report Details

Initial Report Substance Name: Gasoline
Initial Report Subst Catego: Oil
Initial Report Subst Quanti: 2
Initial Report Substance Unit: Quart
Initial Report Medium Name: Vessel
Initial Report Medium Category: Impermeable surface
Initial Report Cause Category: Equipment failure
Initial Report Cause Name: Unknown
Initial Report Source Name: Car
Initial Report Source Category: Vehicle
Initial Report Activity Name: Routine/Normal operations

Initial Report Comment Desc: VASHON --> FAUNTLERY RUN
CAPTAIN PETER JEFFERSON

Follow up Details

ERTS Follow up No: 70529
Follow up Substance Name: Gasoline
Follow up Substance Quantity: 2
Follow up Subst Unit of Meas: Quart
Follow up Cause Name: Unknown
Follow up Medium Name: Vessel
Follow up Source Nname: Car
Follow up Activity Name: Routine/Normal operations

Potential Details

Pot Resp Party First Name:
Pot Resp Prty Last Name: UNK CAR
Potentially Resp Party Org:

Follow up Comments

Follow up Comment:

ERTS Number 553152 - CALLED ARTHUR. CAR SPILLED SOME GAS ON FERRY DECK. NOTHING TO SURFACE WATER.

CLEAN UP BY CREW.

Follow up Comment:

ERTS Number 553152 - Historic Investigator Contact Information - FirstName: LORI MiddleName: LastName: LeVANDER AHR OrganizationName: SPILLS, PREVENTION, PREPAREDNESS AND RESPONSE WorkLocation: NWRO

Follow up Comment:

ERTS Number 553152 - Historic Referral Contact Information - ReferralDate: 2006-02-02 FirstName: CARL MiddleName: LastName: ANDERSEN Email: CARA461@ECY.WA.GOV PhoneNumber: (425) 649-7250 OrganizationName: SPILLS, PREVENTION, PREPAREDNESS AND RESPONSE WorkLocation: NWRO

Initial Comments

Initial Report Comment:

ERTS Number 553152 - VASHON --> FAUNTLERY RUN
CAPTAIN PETER JEFFERSON
206.999.6856
0 IMPACT TO SURFACE WATER

NATIONAL RESPONSE CENTER - FLASH FAX
GOVERNMENT USE ONLYGOVERNMENT USE ONLY***
DO NOT RELEASE this information to the public without
permission from the NATIONAL RESPONSE CENTER 1-800-424-8802

Incident Report # 786435

INCIDENT DESCRIPTION

*Report taken by: MST2 LAYMAN at 23:57 on 26-JAN-06
Incident Type: VESSEL
Incident Cause: OTHER
Affected Area:
The incident was discovered on 26-JAN-06 at 20:30 local time.
Affected Medium: OTHER DECK OF VSL

REPORTING PARTY
Name: ARTHUE LUSIS
Organization: MARINE EXCHANGE PUGET SOUND(WA MARITIME)Address: 100 WEST HARRISON

SEATTLE, WA 98119
MARINE EXCHANGE PUGET SOUND(WA MARITIME) called for the responsible party
PRIMARY Phone: (206)4433830
Type of Organization: PRIVATE ENTERPRISE

SUSPECTED RESPONSIBLE PARTY
Name: PETER JEFFERSON
Organization: WASH. STATE MARITME CO-OP
WA
PRIMARY Phone: (206)9996856
Type of Organization: STATE GOVERNMENT

INCIDENT LOCATION
PUGET SOUND County: KING
State: WA
BETWEEN VASHON AND FAUNTLEROY FERRY DOCK

RELEASED MATERIAL(S)
CHRIS Code: GAS Official Material Name: GASOLINE: AUTOMOTIVE (UNLEADED)
Also Known As:
Qty Released: .5 GALLON(S)

DESCRIPTION OF INCIDENT
OIL LEAKED FROM A VEHICLE ON THE CAR DECK. NO SHEENING WS SEEN IN THE WATER.

INCIDENT DETAILS

Platform Rig Name:
Platform Letter:
Location Area ID:
Location Block ID:
OCSG Number:
OCSP Number:
State Lease Number:
Pier Dock Number:
Berth Slip Number:

---VESSEL INFORMATION---
Name: ISSAQUAH Number: Aground: NO
Flag: UNITED STATES OF AMERICA
Length: Breadth: Draught:
Type: FERRY
Hull Construction:
Fuel Capacity:
Fuel on Board:
Cargo Capacity:
Cargo on Board:

DAMAGES
Fire Involved: NO Fire Extinguished: UNKNOWN
INJURIES: Hospitalized: Empl/Crew: Passenger:

FATALITIES: Empl/Crew: Passenger: Occupant:
EVACUATIONS: Who Evacuated: Radius/Area:
Damages:

Hours Direction of
Closure Type Description of Closure Closed Closure
Air: N

Road: N Major N
Artery:
Waterway: N

Track: N

Passengers Transferred: UNKNOWN
Media Interest: NONE Community Impact due to Material: NO

REMEDIAL ACTIONS
CLEAN UP COMPLETED
Release Secured: UNKNOWN
Release Rate:
Estimated Release Duration:

WEATHER
Weather: OTHER, ºF

ADDITIONAL AGENCIES NOTIFIED
Federal:
State/Local: DEM
State/Local On Scene:
State Agency Number: NONE

NOTIFICATIONS BY NRC
ATSDR WA ATTN: HOPE HOUGH (PRIMARY)
27-JAN-06 00:03 (360)2363327
USCG HSOC AT DHS (USCG HSOC DESK)
27-JAN-06 00:03 (202)2828114
CG INVESTIGATIVE SERVICE HQ (PRIMARY)
27-JAN-06 00:03 (202)4936607
DOT CRISIS MANAGEMENT CENTER (PRIMARY)
27-JAN-06 00:03 (202)3661863
FEMA REGION 10 (PRIMARY)
27-JAN-06 00:03 (425)4874704
NATIONAL INFRASTRUCTURE COORD CTR (PRIMARY)
27-JAN-06 00:03 (202)2829201
NOAA RPTS FOR WA (PRIMARY)
27-JAN-06 00:03 (206)5266344
MSO PUGET SOUND (PRIMARY)
(206)2176002
WA STATE EMERGENCY MANAGEMENT (PRIMARY)
27-JAN-06 00:03 (800)2585990

ADDITIONAL INFORMATION
MSO WILL BE NOTIFIED.

*** END INCIDENT REPORT 786435 ***
Report any problems or Fax number changes by calling 1-800-424-8802
PLEASE VISIT OUR WEB SITE AT http://www.nrc.uscg.mil

Initial Report Comment:

ERTS Number 553152 - VASHON --> FAUNTLERY RUN
CAPTAIN PETER JEFFERSON
206.999.6856
0 IMPACT TO SURFACE WATER

NATIONAL RESPONSE CENTER - FLASH FAX
GOVERNMENT USE ONLYGOVERNMENT USE ONLY***
DO NOT RELEASE this information to the public without
permission from the NATIONAL RESPONSE CENTER 1-800-424-8802

Incident Report # 786435

INCIDENT DESCRIPTION

*Report taken by: MST2 LAYMAN at 23:57 on 26-JAN-06
Incident Type: VESSEL
Incident Cause: OTHER
Affected Area:
The incident was discovered on 26-JAN-06 at 20:30 local time.

Affected Medium: OTHER DECK OF VSL

REPORTING PARTY
Name: ARTHUE LUSIS
Organization: MARINE EXCHANGE PUGET SOUND(WA MARITIME)Address: 100 WEST HARRISON

SEATTLE, WA 98119
MARINE EXCHANGE PUGET SOUND(WA MARITIME) called for the responsible party
PRIMARY Phone: (206)4433830
Type of Organization: PRIVATE ENTERPRISE

SUSPECTED RESPONSIBLE PARTY
Name: PETER JEFFERSON
Organization: WASH. STATE MARITME CO-OP
WA
PRIMARY Phone: (206)9996856
Type of Organization: STATE GOVERNMENT

INCIDENT LOCATION
PUGET SOUND County: KING
State: WA
BETWEEN VASHON AND FAUNTLEROY FERRY DOCK

RELEASED MATERIAL(S)
CHRIS Code: GAS Official Material Name: GASOLINE: AUTOMOTIVE (UNLEADED)
Also Known As:
Qty Released: .5 GALLON(S)

DESCRIPTION OF INCIDENT
OIL LEAKED FROM A VEHICLE ON THE CAR DECK. NO SHEENING WS SEEN IN THE WATER.

INCIDENT DETAILS

Platform Rig Name:
Platform Letter:
Location Area ID:
Location Block ID:
OCSG Number:
OCSP Number:
State Lease Number:
Pier Dock Number:
Berth Slip Number:

---VESSEL INFORMATION---
Name: ISSAQUAH Number: Aground: NO
Flag: UNITED STATES OF AMERICA
Length: Breadth: Draught:
Type: FERRY
Hull Construction:
Fuel Capacity:
Fuel on Board:
Cargo Capacity:
Cargo on Board:

DAMAGES
Fire Involved: NO Fire Extinguished: UNKNOWN
INJURIES: Hospitalized: Empl/Crew: Passenger:

FATALITIES: Empl/Crew: Passenger: Occupant:
EVACUATIONS: Who Evacuated: Radius/Area:
Damages:

Hours Direction of
Closure Type Description of Closure Closed Closure
Air: N

Road: N Major N
Artery:

Waterway: N

Track: N

Passengers Transferred: UNKNOWN
Media Interest: NONE Community Impact due to Material: NO

REMEDIAL ACTIONS
CLEAN UP COMPLETED
Release Secured: UNKNOWN
Release Rate:
Estimated Release Duration:

WEATHER
Weather: OTHER, ºF

ADDITIONAL AGENCIES NOTIFIED
Federal:
State/Local: DEM
State/Local On Scene:
State Agency Number: NONE

NOTIFICATIONS BY NRC
ATSDR WA ATTN: HOPE HOUGH (PRIMARY)
27-JAN-06 00:03 (360)2363327
USCG HSOC AT DHS (USCG HSOC DESK)
27-JAN-06 00:03 (202)2828114
CG INVESTIGATIVE SERVICE HQ (PRIMARY)
27-JAN-06 00:03 (202)4936607
DOT CRISIS MANAGEMENT CENTER (PRIMARY)
27-JAN-06 00:03 (202)3661863
FEMA REGION 10 (PRIMARY)
27-JAN-06 00:03 (425)4874704
NATIONAL INFRASTRUCTURE COORD CTR (PRIMARY)
27-JAN-06 00:03 (202)2829201
NOAA RPTS FOR WA (PRIMARY)
27-JAN-06 00:03 (206)5266344
MSO PUGET SOUND (PRIMARY)
(206)2176002
WA STATE EMERGENCY MANAGEMENT (PRIMARY)
27-JAN-06 00:03 (800)2585990

ADDITIONAL INFORMATION
MSO WILL BE NOTIFIED.

*** END INCIDENT REPORT 786435 ***
Report any problems or Fax number changes by calling 1-800-424-8802
PLEASE VISIT OUR WEB SITE AT http://www.nrc.uscg.mil

16	2 of 6	NW	0.08 / 443.04	107.39 / 2	GALLERY BELL TOWN 2911 - 2ND AVENUE SEATTLE WA	ERTS

Incident ID: 625156
Incident Date: 2011-02-21
County: KING
Location: GALLERY BELL TOWN
Latitude: 47.617800000000003
Longitude: 122.33159999999999

Initial Report Details

Initial Report Substance Name: Diesel oil/Marine gas
Initial Report Subst Catego: Oil
Initial Report Subst Quanti: 20
Initial Report Substance Unit: U.S. gallons
Initial Report Medium Name: Impermeable containment
Initial Report Medium Category: Impermeable surface

Initial Report Cause Category:
Initial Report Cause Name:
Initial Report Source Name: Truck
Initial Report Source Category: Vehicle
Initial Report Activity Name: Refueling (vessel)
Initial Report Comment Desc: FUELING COMPANY DELIVERING DIESEL TO TANK. TRUCK D

Follow up Details

ERTS Follow up No: 109755
Follow up Substance Name: Diesel oil/Marine gas
Follow up Substance Quantity: 20
Follow up Subst Unit of Meas: U.S. gallons
Follow up Cause Name: Unknown
Follow up Medium Name: Building/Structure
Follow up Source Nname: Truck
Follow up Activity Name: Refueling (vessel)

Potential Details

Pot Resp Party First Name:
Pot Resp Prty Last Name: UNKNOWN
Potentially Resp Party Org:

Follow up Comments

Follow up Comment:

ERTS Number 625156 - Historic Referral Contact Information - ReferralDate: 2011-02-25 FirstName: LORI MiddleName: LastName: LeVANDER AHR Email: LLEV461@ECY.WA.GOV PhoneNumber: (425) 649-7039 OrganizationName: SPILLS, PREVENTION, PREPAREDNESS AND RESPONSE WorkLocation: NWRO

Follow up Comment:

ERTS Number 625156 - LEVANDER CALL BACK.

STAYED IN MAINTROOM, LEAKED OUT AND DRIPPED.

ALL CONTAINED INSIDE BUILDING.

CLEAN-UP DONE.

NO GO - TOTALLY INSIDE BLDG.

Follow up Comment:

ERTS Number 625156 - Historic Investigator Contact Information - FirstName: LORI MiddleName: LastName: LeVANDER AHR OrganizationName: SPILLS, PREVENTION, PREPAREDNESS AND RESPONSE WorkLocation: NWRO

Initial Comments

Initial Report Comment:

ERTS Number 625156 - FUELING COMPANY DELIVERING DIESEL TO TANK. TRUCK DELIVERED FUEL TO TANK ON INSIDE BUILDING, TANK ALARM FAILED, SO TANK OVERFLOWED, SPILLED TO FLOOR AND DRIPPED TO CONCRETE. PUT OUT SORBENTS. LOCAL FIRE DEPARTMENT RESPONDED. NO DRAINS IN AREA.

-----Original Message-----
From: Duty Officer (EMD)
Sent: Monday, February 21, 2011 12:14 PM
To: LeVander, Lori (ECY); Sacayanan, Tamara L. (ECY); lis.rudolph@seattle.gov
Subject: FW: NRC#968137

The R/P also called.

State Emergency Operations Officer
Washington State Emergency Operations Center
Camp Murray, WA 98430
24-hr: 800-258-5990 Fax: 253-512-7203
www.emd.wa.gov

-----Original Message-----
From: HQS-PF-fldr-NRC@uscg.mil [mailto:HQS-PF-fldr-NRC@uscg.mil]
Sent: Monday, February 21, 2011 12:14 PM
To: Duty Officer (EMD)
Subject: NRC#968137

NATIONAL RESPONSE CENTER 1-800-424-8802
GOVERNMENT USE ONLYGOVERNMENT USE ONLY***
Information released to a third party shall comply with any
applicable federal and/or state Freedom of Information and Privacy Laws

Incident Report # 968137

INCIDENT DESCRIPTION

*Report taken by: CIV NICHAULUS THREATT at 15:08 on 21-FEB-11
Incident Type: STORAGE TANK
Incident Cause: EQUIPMENT FAILURE
Affected Area:
Incident occurred on 21-FEB-11 at 10:00 local incident time.
Affected Medium: LAND CONCRETE FLOOR, TWO CARS

REPORTING PARTY
Name: DAVID SCHOEPF
Organization: CHS
Address: 1919 AUBURN WAY NORTH
AUBURN, WA 98002

PRIMARY Phone: (253)8337220 ALTERNATE Phone: (253)3501174
Type of Organization: PRIVATE ENTERPRISE

SUSPECTED RESPONSIBLE PARTY
Name: UNKNOWN

XX

INCIDENT LOCATION
2911 2ND AVE. County: KING
City: SEATTLE State: WA

RELEASED MATERIAL(S)
CHRIS Code: ODS Official Material Name: OIL: DIESEL
Also Known As:
Qty Released: 20 GALLON(S)

DESCRIPTION OF INCIDENT
CALLER IS REPORTING A DISCHARGE OF DIESEL FUEL FROM A STORAGE TANK INSIDE THE BUILDING DUE TO AN ALARM SYSTEM FAILURE.

SENSITIVE INFORMATION

INCIDENT DETAILS
Description of Tank: STORAGE TANK
Tank Above/Below Ground: ABOVE
Transportable Container: UNKNOWN
Tank Regulated: UNKNOWN
Tank Regulated By:
Tank ID: N/A
Capacity of Tank: 265 GALLON(S)

Actual Amount: 0 UNKNOWN AMOUNT

IMPACT
Fire Involved: NO Fire Extinguished: UNKNOWN

INJURIES: NO Hospitalized: Empl/Crew: Passenger:
FATALITIES: NO Empl/Crew: Passenger: Occupant:
EVACUATIONS:NO Who Evacuated: Radius/Area:

Damages: NO
Hours Direction of
Closure Type Description of Closure Closed Closure
N
Air:
N Major
Road: Artery:N
N
Waterway:
N
Track:

Environmental Impact: UNKNOWN
Media Interest: NONE Community Impact due to Material:

REMEDIAL ACTIONS
CALLER STATES ABSORBENTS WERE APPLIED, CLEANUP IS UNDERWAY AND THE FIRE DEPT. RESPONDED.
Release Secured: YES
Release Rate:
Estimated Release Duration:

WEATHER
Weather: CLEAR, 35ºF

ADDITIONAL AGENCIES NOTIFIED
Federal: NONE
State/Local: STATE OF WA., FIRE DEPT.
State/Local On Scene: FIRE DEPT.
State Agency Number: 11-0548

NOTIFICATIONS BY NRC
DHS CUSTOMS AND BORDER PATROL (INTEL BRANCH/BLAINE SECTOR)
21-FEB-11 15:13 (360)4107222
DOT CRISIS MANAGEMENT CENTER (MAIN OFFICE)
21-FEB-11 15:13 (202)3661863
EPA CRIMINAL INVESTIGATION DIVISION (EPA CRIMINAL INVESTIGATION DIV REG
21-FEB-11 15:13 (206)5538306
U.S. EPA X SEATTLE (MAIN OFFICE)
(206)5531263
FEMA REGION 10 (MAIN OFFICE)
21-FEB-11 15:13 (425)4874704
NATIONAL INFRASTRUCTURE COORD CTR (MAIN OFFICE)
21-FEB-11 15:13 (202)2829201
NOAA RPTS FOR WA (MAIN OFFICE)
21-FEB-11 15:13 (206)5264911
SECTOR PUGET SOUND (COMMAND CENTER)
(206)2176002
WA STATE EMERGENCY MANAGEMENT (MAIN OFFICE)
21-FEB-11 15:13 (800)2585990
STATE OF WA DEPT OF HEALTH (WA DOH)
21-FEB-11 15:13 (360)2363327
WASHINGTON STATE FUSION CENTER (MAIN OFFICE)
21-FEB-11 15:13 (877)

ADDITIONAL INFORMATION
CALLER HAD NO ADDITIONAL COMMENTS.

*** END INCIDENT REPORT #968137 ***
Report any problems by calling 1-800-424-8802

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

PLEASE VISIT OUR WEB SITE AT http://www.nrc.uscg.mil

---

16 | **3 of 6** | **NW** | **0.08 / 443.04** | **107.39 / 2** | **PUGET SOUND**
2911 2ND AVE
SEATTLE WA | **SPILLS**

Incident ID:	553152	**Location:**	PUGET SOUND
Incident Date:	1/26/2006	**Address:**	2911 2ND AVE
Latitude:	NULL	**City:**	SEATTLE
Longitude:	NULL	**County:**	KING

---

16 | **4 of 6** | **NW** | **0.08 / 443.04** | **107.39 / 2** | **GALLERY BELL TOWN**
2911 - 2ND AVENUE
SEATTLE WA | **SPILLS**

Incident ID:	65499	**Location:**	GALLERY BELL TOWN
Incident Date:	2/21/2011	**Address:**	2911 - 2ND AVENUE
Latitude:	47.6178	**City:**	SEATTLE
Longitude:	-122.3316	**County:**	KING

---

16 | **5 of 6** | **NW** | **0.08 / 443.04** | **107.39 / 2** | **2911 - 2ND AVENUE**
SEATTLE WA | **SPILLS**

Incident ID:	625156	**Location:**	
Incident Date:		**Address:**	2911 - 2ND AVENUE
Latitude:		**City:**	SEATTLE
Longitude:		**County:**	KING

Spill Information

Incident Date:	2/21/2011
Latitude:	NULL
Longitude:	NULL

Spill Information

Incident Date:	2/21/2011
Latitude:	NULL
Longitude:	NULL

Spill Details Historical

Material:	PETROLEUM - DIESEL FUEL	**Source:**	TRANSPORTATION-VEHICLE TRUCK
Qty:	20	**Sheen Only:**	0
Medium:	IMPERMEABLE CONTAINMENT	**Waterway:**	NULL
Impact:	OTHER	**Prp Business Name:**	NULL
Cause:	NULL	**Prp First Name:**	NULL
Activity:	REFUELING	**Prp Last Name:**	UNKNOWN

Spill Details Historical

Material:	PETROLEUM - DIESEL FUEL	**Source:**	TRANSPORTATION-VEHICLE TRUCK
Qty:	20	**Sheen Only:**	0
Medium:	IMPERMEABLE CONTAINMENT	**Waterway:**	NULL
Impact:	OTHER	**Prp Business Name:**	NULL
Cause:	NULL	**Prp First Name:**	NULL
Activity:	REFUELING	**Prp Last Name:**	UNKNOWN

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
16	6 of 6	NW	0.08 / 443.04	107.39 / 2	2911 2ND AVE SEATTLE WA	SPILLS

Incident ID: 553152
Incident Date:
Latitude:
Longitude:

Location:
Address: 2911 2ND AVE
City: SEATTLE
County: KING

Spill Information

Incident Date: 1/26/2006
Latitude: NULL
Longitude: NULL

Spill Details Historical

Material: PETROLEUM - GASOLINE
Qty: 2
Medium: VESSEL
Impact: POTENTIAL POLLUTION/RELEASE
Cause: EQUIPMENT FAILURE
Activity: ROUTINE/NORMAL OPERATIONS

Source: MOTOR VEHICLE - CAR
Sheen Only: 0
Waterway: PUGET SOUND
Prp Business Name: NULL
Prp First Name: NULL
Prp Last Name: UNK CAR

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
17	1 of 2	ESE	0.09 / 471.81	105.51 / 0	ARBOR PLACE TOWER 121 VINE ST SEATTLE WA 98121-	ERTS

Incident ID: 549811
Incident Date: 2005-08-04
County: KING
Location: ARBOR PLACE TOWER

Latitude:
Longitude:

Initial Report Details

Initial Report Substance Name: Dust
Initial Report Subst Catego: Debris
Initial Report Subst Quanti:
Initial Report Substance Unit:
Initial Report Medium Name: N/A
Initial Report Medium Category: Air
Initial Report Cause Category: Human error
Initial Report Cause Name: Policy/Procedure; Incorrect
Initial Report Source Name: Commercial/Industrial facility
Initial Report Source Category: Facility
Initial Report Activity Name: Cleaning
Initial Report Comment Desc: CONDO GARAGE WAS CLEANED BY THE USE OF BLOWERS. TH

Follow up Details

ERTS Follow up No:
Follow up Substance Name:
Follow up Substance Quantity:
Follow up Subst Unit of Meas:
Follow up Cause Name:
Follow up Medium Name:
Follow up Source Nname:
Follow up Activity Name:

Potential Details

Pot Resp Party First Name:

Pot Resp Prty Last Name:
Potentially Resp Party Org: ARBOR PLACE TOWER CONDO ASSOC.

Initial Comments

Initial Report Comment:

ERTS Number 549811 - CONDO GARAGE WAS CLEANED BY THE USE OF BLOWERS. THE AIR WAS SO THICK WITH DUST THAT PEOPLE COULDN`T SEE THROUGH IT.

THE CONDO ASSOCIATION PLANS ON DOING THIS AGAIN EVERY MONTH UNTIL THE GARAGE IS CLEAN.

Historic Referral Contact Information - ReferralDate: FirstName: RADIO ROOM MiddleName: LastName: PUGET SOUND CLEAN AIR AGENCY Email: inspection@pscleanair.org PhoneNumber: (206) 343-8800 OrganizationName: INSPECTIONS WorkLocation: PSCAA

17	2 of 2	ESE	0.09 / 471.81	105.51 / 0	121 VINE ST SEATTLE WA	SPILLS

Incident ID: 549811
Incident Date:
Latitude:
Longitude:

Location:
Address: 121 VINE ST
City: SEATTLE
County: KING

Spill Information

Incident Date: 8/4/2005
Latitude: NULL
Longitude: NULL

Spill Details Historical

Material: DUST
Qty: NULL
Medium: AIR
Impact: AIR POLLUTION
Cause: IMPROPER PROCEDURE
Activity: CLEANING

Source: COMMERCIAL
Sheen Only: 0
Waterway: NULL
Prp Business Name: ARBOR PLACE TOWER CONDO ASSOC.
Prp First Name: NULL
Prp Last Name: NULL

18	1 of 2	E	0.10 / 509.10	116.27 / 11	Rite Aid 5218 2603 3RD AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID: 52583565
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAR000002709
Facility Alternate: Rite Aid 5218
Interaction ID: 104721
Interaction Status: A
Interac Status Desc: Active
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 31-Dec-2012
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID:	WAR000002709
Facility Alternate:	Rite Aid 5218
Interaction ID:	101316
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWOTHER
Interaction Desc:	Haz Waste Management Activity
Interact Start Dt:	31-Dec-2011
Interact End Dt:	31-Dec-2012
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Program ID:	WAR000002709
Facility Alternate:	Rite Aid 5218
Interaction ID:	98746
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	09-Dec-2011
Interact End Dt:	31-Dec-2011
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Program ID:	WAR000002709
Facility Alternate:	RITE AID 5218
Interaction ID:	49464
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	16-May-1995
Interact End Dt:	31-Dec-2009
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Program ID:	WAR000002709
Facility Alternate:	Rite Aid 5218
Interaction ID:	91816
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWOTHER
Interaction Desc:	Haz Waste Management Activity
Interact Start Dt:	31-Dec-2009
Interact End Dt:	09-Dec-2011
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	40ft	***Location Verified:***	
Horizont 1:	NAD83HARN	***GIS latitude:***	47.6165102395
Horizont 2:	Digital map or GIS	***GIS longitude:***	-122.348541341

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
18	*2 of 2*	*E*	*0.10 / 509.10*	*116.27 / 11*	*RITE AID 5218* *2603 3RD AVE* *SEATTLE WA 98121*	*RCRA NON GEN*

EPA Handler ID:	WAR000002709
Gen Status Universe:	No Report
Contact Name:	JOSEPH CHEST
Contact Address:	30 HUNTER LANE , , CAMP HILL , PA, 17011 , US
Contact Phone No and Ext:	717-975-8643
Contact Email:	EHS@RITEAID.COM
Contact Country:	US
County Name:	KING
EPA Region:	10
Land Type:	Private
Receive Date:	20210909
Location Latitude:	47.61678
Location Longitude:	-122.34808

Violation/Evaluation Summary

Note:	NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Jun, 2022.

Evaluation Details

Evaluation Start Date:	19991108
Evaluation Type Description:	COMPLIANCE ASSISTANCE VISIT
Violation Short Description:	
Return to Compliance Date:	
Evaluation Agency:	State

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	19
Receive Date:	20120406
Handler Name:	RITE AID 5218
Source Type:	Notification
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	30
Receive Date:	20200108
Handler Name:	RITE AID 5218
Source Type:	Notification
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D026
Waste Code Description: CRESOL

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: U154
Waste Code Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Hazardous Waste Code: U279
Waste Code Description: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: U240
Waste Code Description: 2,4-D, SALTS & ESTERS (OR) ACETIC ACID, (2,4-DICHLOROPHENOXY)-, SALTS & ESTERS (OR) DICHLOROPHENOXYACETIC ACID 2,4-D

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: WP01
Waste Code Description: Washington State Extremely Hazardous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of Greater than 1.0%.

Hazardous Waste Code: WP02
Waste Code Description: Washington State Dangerous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of 0.01% to 1.0%.

Hazardous Waste Code: U002
Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: P042
Waste Code Description: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: U117
Waste Code Description: ETHANE, 1,1'-OXYBIS-(I) (OR) ETHYL ETHER (I)

Hazardous Waste Code: U058
Waste Code Description: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

Hazardous Waste Code: U122
Waste Code Description: FORMALDEHYDE

Hazardous Waste Code: U035
Waste Code Description: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

Hazardous Waste Code: U044
Waste Code Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D016
Waste Code Description: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

Hazardous Waste Handler Details

Sequence No: 33
Receive Date: 20210909
Handler Name: RITE AID 5218
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 11
Receive Date: 20050228
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Handler Details

Sequence No: 17
Receive Date: 20110526
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 15
Receive Date: 20090128
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 18
Receive Date: 20111209
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Handler Details

Sequence No: 23
Receive Date: 20150119
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D026
Waste Code Description: CRESOL

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT

CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: WP01
Waste Code Description: Washington State Extremely Hazardous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of Greater than 1.0%.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Handler Details

Sequence No: 27
Receive Date: 20180129
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D026
Waste Code Description: CRESOL

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: WP01
Waste Code Description: Washington State Extremely Hazardous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of Greater than 1.0%.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: U165
Waste Code Description: NAPHTHALENE

Hazardous Waste Handler Details

Sequence No: 28
Receive Date: 20190107
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D026
Waste Code Description: CRESOL

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: WP01
Waste Code Description: Washington State Extremely Hazardous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of Greater than 1.0%.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: U165
Waste Code Description: NAPHTHALENE

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20051231
Handler Name: RITE AID 5218

Source Type: Annual/Biennial Report
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19931231
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: WT01
Waste Code Description: Washington State Extremely Hazardous Toxic Waste with a toxic constituents concentration greater than or equal to 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 19991210
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 19990301
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 7
Receive Date: 20010228
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D002

Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: WP01
Waste Code Description: Washington State Extremely Hazardous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of Greater than 1.0%.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D026
Waste Code Description: CRESOL

Hazardous Waste Handler Details

Sequence No: 10
Receive Date: 20040331
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Handler Details

Sequence No: 12
Receive Date: 20060217
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 19980903
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Waste Code Details

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Handler Details

Sequence No: 32
Receive Date: 20210908
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 8
Receive Date: 20020228
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: WP01
Waste Code Description: Washington State Extremely Hazardous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of Greater than 1.0%.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001%

and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: U044
Waste Code Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Hazardous Waste Code: D026
Waste Code Description: CRESOL

Hazardous Waste Handler Details

Sequence No: 9
Receive Date: 20030303
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: WP01
Waste Code Description: Washington State Extremely Hazardous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of Greater than 1.0%.

Hazardous Waste Code: WSC2
Waste Code Description: Washington State solid or semisolid corrosive Dangerous Waste with a pH less than or equal to 2, or greater than or equal to 12.5, based upon a specific testing method.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D026
Waste Code Description: CRESOL

Hazardous Waste Handler Details

Sequence No: 22
Receive Date: 20140220
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: WP01
Waste Code Description: Washington State Extremely Hazardous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of Greater than 1.0%.

Hazardous Waste Handler Details

Sequence No: 24
Receive Date: 20150914
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: WP01
Waste Code Description: Washington State Extremely Hazardous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of Greater than 1.0%.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: U044
Waste Code Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: D026
Waste Code Description: CRESOL

Hazardous Waste Handler Details

Sequence No: 26
Receive Date: 20170110
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: WP01
Waste Code Description: Washington State Extremely Hazardous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of Greater than 1.0%.

Hazardous Waste Code: WSC2
Waste Code Description: Washington State solid or semisolid corrosive Dangerous Waste with a pH less than or equal to 2, or greater than or equal to 12.5, based upon a specific testing method.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D026
Waste Code Description: CRESOL

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20071231
Handler Name: RITE AID 5218
Source Type: Annual/Biennial Report
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20100319
Handler Name: RITE AID 5218
Source Type: Annual/Biennial Report update with Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 13
Receive Date: 20070228
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Handler Details

Sequence No: 29
Receive Date: 20190401
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D010

Waste Code Description: SELENIUM

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: WP01
Waste Code Description: Washington State Extremely Hazardous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of Greater than 1.0%.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: U165
Waste Code Description: NAPHTHALENE

Hazardous Waste Code: D026
Waste Code Description: CRESOL

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19970221
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Handler Details

Sequence No: 16
Receive Date: 20100319
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 20
Receive Date: 20130507
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Handler Details

Sequence No: 21
Receive Date: 20131031
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: WP01
Waste Code Description: Washington State Extremely Hazardous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of Greater than 1.0%.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D026
Waste Code Description: CRESOL

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20031231
Handler Name: RITE AID 5218
Source Type: Annual/Biennial Report
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20120406
Handler Name: RITE AID 5218
Source Type: Annual/Biennial Report update with Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 6
Receive Date: 20000229
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: P075

Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Handler Details

Sequence No: 14
Receive Date: 20080602
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 25
Receive Date: 20160216
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: WP01
Waste Code Description: Washington State Extremely Hazardous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of Greater than 1.0%.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D026
Waste Code Description: CRESOL

Hazardous Waste Handler Details

Sequence No: 31
Receive Date: 20210107
Handler Name: RITE AID 5218
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: U154
Waste Code Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Hazardous Waste Code: U279
Waste Code Description: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: U240
Waste Code Description: 2,4-D, SALTS & ESTERS (OR) ACETIC ACID, (2,4-DICHLOROPHENOXY)-, SALTS & ESTERS (OR) DICHLOROPHENOXYACETIC ACID 2,4-D

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: WP01
Waste Code Description: Washington State Extremely Hazardous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of Greater than 1.0%.

Hazardous Waste Code: WP02
Waste Code Description: Washington State Dangerous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of 0.01% to 1.0%.

Hazardous Waste Code: U002
Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: P042
Waste Code Description: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: U117
Waste Code Description: ETHANE, 1,1'-OXYBIS-(I) (OR) ETHYL ETHER (I)

Hazardous Waste Code: U058
Waste Code Description: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

Hazardous Waste Code: U122
Waste Code Description: FORMALDEHYDE

Hazardous Waste Code: U035
Waste Code Description: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

Hazardous Waste Code: U044
Waste Code Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Hazardous Waste Code: D016
Waste Code Description: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

Hazardous Waste Code: D026
Waste Code Description: CRESOL

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	PO BOX 3165
Name:	RITE AID CORP	***Street 2:***	
Date Became Current:	19970101	***City:***	HARRISBURG
Date Ended Current:		***State:***	PA
Phone:		***Country:***	US
Source Type:	Annual/Biennial Report	***Zip Code:***	17105

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	PO BOX 3165
Name:	RITE AID CORP	***Street 2:***	
Date Became Current:	19970101	***City:***	HARRISBURG
Date Ended Current:		***State:***	PA
Phone:	717-761-2633	***Country:***	US
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	17105

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	PO BOX 3165
Name:	RITE AID CORP	***Street 2:***	
Date Became Current:	19970101	***City:***	HARRISBURG
Date Ended Current:		***State:***	PA
Phone:	717-761-2633	***Country:***	US
Source Type:	Notification	***Zip Code:***	17105

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	2650 LOU MENK DR
Name:	WEC 98D 33 LLC	***Street 2:***	
Date Became Current:		***City:***	FORT WORTH
Date Ended Current:		***State:***	TX
Phone:	717-761-2633	***Country:***	US
Source Type:	Notification	***Zip Code:***	76131

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	2603 3RD AVE
Name:	RITE AID 5218	***Street 2:***	
Date Became Current:	19000101	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:		***Country:***	US

Source Type:	Annual/Biennial Report	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2603 3RD AVE
Name:	RITE AID 5218	**Street 2:**	
Date Became Current:	19000101	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-441-8790	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	30 HUNTER LANE
Name:	THRIFTY PAYLESS INC	**Street 2:**	
Date Became Current:	19970530	**City:**	CAMP HILL
Date Ended Current:		**State:**	PA
Phone:	717-761-2633	**Country:**	US
Source Type:	Implementer	**Zip Code:**	17011
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 218
Name:	GREAT LAKE INVESTMENT CO	**Street 2:**	
Date Became Current:		**City:**	BELLEVUE
Date Ended Current:		**State:**	WA
Phone:	425-505-1778	**Country:**	US
Source Type:	Notification	**Zip Code:**	98009
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	30 HUNTER LANE
Name:	RITE AID CORP	**Street 2:**	
Date Became Current:	19970530	**City:**	CAMP HILL
Date Ended Current:		**State:**	PA
Phone:	717-761-2633	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	17011
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	30 HUNTER LANE
Name:	THRIFTY PAYLESS INC	**Street 2:**	
Date Became Current:	19970530	**City:**	CAMP HILL
Date Ended Current:		**State:**	PA
Phone:	717-761-2633	**Country:**	US
Source Type:	Implementer	**Zip Code:**	17011
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	30 HUNTER LANE
Name:	RITE AID 5218	**Street 2:**	
Date Became Current:	19970530	**City:**	CAMP HILL
Date Ended Current:		**State:**	PA
Phone:	717-761-2633	**Country:**	US
Source Type:	Notification	**Zip Code:**	17011
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	30 HUNTER LANE
Name:	THRIFTY PAYLESS INC	**Street 2:**	
Date Became Current:	19970530	**City:**	CAMP HILL
Date Ended Current:		**State:**	PA
Phone:	717-761-2633	**Country:**	US
Source Type:	Notification	**Zip Code:**	17011
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	30 HUNTER LANE
Name:	THRIFTY PAYLESS INC	**Street 2:**	
Date Became Current:	19970530	**City:**	CAMP HILL
Date Ended Current:		**State:**	PA
Phone:	717-761-2633	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	17011
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 218
Name:	GREAT LAKE INVESTMENT CO	**Street 2:**	

Date Became Current:	20171231	**City:**	BELLEVUE
Date Ended Current:		**State:**	WA
Phone:	425-505-1778	**Country:**	US
Source Type:	Notification	**Zip Code:**	98009
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2603 3RD AVE
Name:	RITE AID 5218	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 3165
Name:	RITE AID 5218	**Street 2:**	
Date Became Current:	19970101	**City:**	HARRISBURG
Date Ended Current:		**State:**	PA
Phone:	717-761-2633	**Country:**	US
Source Type:	Notification	**Zip Code:**	17105
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	30 HUNTER LANE
Name:	THRIFTY PAYLESS INC	**Street 2:**	
Date Became Current:	19970530	**City:**	CAMP HILL
Date Ended Current:		**State:**	PA
Phone:	717-761-2633	**Country:**	US
Source Type:	Notification	**Zip Code:**	17011
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2650 LOU MENK DR
Name:	WEC 98D 33 LLC	**Street 2:**	
Date Became Current:		**City:**	FORT WORTH
Date Ended Current:		**State:**	TX
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	76131
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2603 3RD AVE
Name:	RITE AID 5218	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 218
Name:	GREAT LAKE INVESTMENT CO	**Street 2:**	
Date Became Current:	20171231	**City:**	BELLEVUE
Date Ended Current:		**State:**	WA
Phone:	425-505-1778	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98009
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	600 UNIVERSITY ST
Name:	THIRD VINE RETAIL LLC	**Street 2:**	STE 2018
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-812-9135	**Country:**	US
Source Type:	Notification	**Zip Code:**	98101

Historical Handler Details

Receive Dt:	20080602
Generator Code Description:	Very Small Quantity Generator
Handler Name:	RITE AID 5218

Receive Dt:	20200108

Generator Code Description: Very Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 20120406
Generator Code Description: Not a Generator, Verified
Handler Name: RITE AID 5218

Receive Dt: 20020228
Generator Code Description: Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 19991210
Generator Code Description: Very Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 20040331
Generator Code Description: Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 20140220
Generator Code Description: Very Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 20090128
Generator Code Description: Very Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 20180129
Generator Code Description: Very Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 20071231
Generator Code Description: Not a Generator, Verified
Handler Name: RITE AID 5218

Receive Dt: 20000229
Generator Code Description: Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 20050228
Generator Code Description: Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 20150914
Generator Code Description: Very Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 20051231
Generator Code Description: Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 20060217
Generator Code Description: Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 20111209
Generator Code Description: Very Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 20120406
Generator Code Description: Not a Generator, Verified
Handler Name: RITE AID 5218

Receive Dt: 20150119
Generator Code Description: Very Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 19970221
Generator Code Description: Small Quantity Generator

Handler Name: RITE AID 5218

Receive Dt: 20130507
Generator Code Description: Very Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 20210107
Generator Code Description: Very Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 20031231
Generator Code Description: Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 19931231
Generator Code Description: Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 19980903
Generator Code Description: Not a Generator, Verified
Handler Name: RITE AID 5218

Receive Dt: 20100319
Generator Code Description: Not a Generator, Verified
Handler Name: RITE AID 5218

Receive Dt: 20210908
Generator Code Description: Not a Generator, Verified
Handler Name: RITE AID 5218

Receive Dt: 20070228
Generator Code Description: Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 20131031
Generator Code Description: Very Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 20030303
Generator Code Description: Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 20010228
Generator Code Description: Not a Generator, Verified
Handler Name: RITE AID 5218

Receive Dt: 20110526
Generator Code Description: Not a Generator, Verified
Handler Name: RITE AID 5218

Receive Dt: 20100319
Generator Code Description: Not a Generator, Verified
Handler Name: RITE AID 5218

Receive Dt: 20160216
Generator Code Description: Very Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 20190401
Generator Code Description: Very Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 20190107
Generator Code Description: Very Small Quantity Generator
Handler Name: RITE AID 5218

Receive Dt: 19990301
Generator Code Description: Small Quantity Generator
Handler Name: RITE AID 5218

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Receive Dt: 20170110
Generator Code Description: Very Small Quantity Generator
Handler Name: RITE AID 5218

---

19 | **1 of 1** | **WNW** | **0.10 / 538.54** | **89.25 / -16** | **2915 1ST AVE, Seattle WA 98109** | **UST SEATTLE**

Permit No: 3-40995
Date Issued: 01/28/2002
Fill Material: Sand
Date Decommissioned: 01/28/2002
Type Decommissioned: Abandonment in Place
Tank Size: 300
Tank Age: UNKNOWN
Tank Content: FUEL OIL

---

20 | **1 of 1** | **WNW** | **0.10 / 552.90** | **87.96 / -18** | **SEATTLE WA** | **SPILLS WATER**

Report ID:
Incident No: 56467
ERTS No: 641635
Incident Date: 6/1/2013
Is Regulated?:
Location Description:
Latitude: 47.6172
Longitude: -122.3531
City: SEATTLE
County: KING
Source: Washington Department of Ecology Spill Summary
Date Incident (Map):
Regulated (Map):
Address1 (Map):
Address2 (Map):
Location (Map):
Latitude (Map):
Longitude (Map):
City (Map):
County (Map):

---

21 | **1 of 6** | **WSW** | **0.11 / 577.56** | **49.42 / -56** | **The Olympus, 2801 WESTERN AVE, SEATTLE WA 98121** | **CSCSL NFA**

Fac Site ID: 35216721
Cleanup Site ID: 5927
Site Status: NFA
NFA Date: 08/24/2001
Responsible Unit: Northwest
Has Insti Control:
Region: Northwest
County: King
Latitude: 47.6156351382033
Longitude: -122.353325395295
NFA Reason: Voluntary Cleanup Program Review
Alternate Site Names: ELLIOTT & BROAD STREET,THE OLYMPUS ELLIOTT & BROAD ST
Location (OD): "" (47.615635, -122.353325)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants
Fac Site ID (OD): 35216721
Cleanup SiteID(OD): 5927
Site Status (OD): No Further Action
Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
Region (OD): Northwest
County (OD): King
Latitude (OD): 47.615635
Longitude (OD): -122.353325

NFA Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
21	2 of 6	WSW	0.11 / 577.56	49.42 / -56	THE OLYMPUS 2801 WESTERN AVE Seattle WA 98121	UST

UST ID: 579191
Facility Site ID: 35216721
Site Active: No
Responsible Unit: Northwest
Active Tag:
Alternate Site Names: ELLIOTT & BROAD STREET,THE OLYMPUS ELLIOTT & BROAD ST

Region: Northwest
County: King
Latitude: 47.6156351382033
Longitude: -122.353325395295

Tank Detail(s)

Tank Name: 1
Status Date: 08/03/2001
Install Date: 01/01/1900
Upgrade Date:
Perm Closure Date:
Tank Status: Closed in Place
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction:
Tank Capacity:
Actual Capacity: 500
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity: 500
Stored Substance: Unleaded Gasoline
Used Substance:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
21	3 of 6	WSW	0.11 / 577.56	49.42 / -56	THE OLYMPUS 2801 WESTERN AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID: 35216721
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 579191
Facility Alternate:
Interaction ID: 39775
Interaction Status: I
Interac Status Desc: Inactive

Interaction Type:	LUST
Interaction Desc:	LUST Facility
Interact Start Dt:	17-May-2001
Interact End Dt:	17-May-2001
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Program ID:	579191
Facility Alternate:	THE OLYMPUS ELLIOTT & BROAD ST
Interaction ID:	39776
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	UST
Interaction Desc:	Underground Storage Tank
Interact Start Dt:	18-May-2001
Interact End Dt:	18-May-2001
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	UST
Database Name Desc:	Underground Storage Tanks

Program ID:	
Facility Alternate:	THE OLYMPUS
Interaction ID:	39777
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	VOLCLNST
Interaction Desc:	Voluntary Cleanup Sites
Interact Start Dt:	18-May-2001
Interact End Dt:	24-Aug-2001
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Facility Location Detail

Horizontal:	40ft	***Location Verified:***	
Horizont 1:	NAD83HARN	***GIS latitude:***	47.6156351382
Horizont 2:	Digital map or GIS	***GIS longitude:***	-122.353325395

21	4 of 6	WSW	0.11 / 577.56	49.42 / -56	THE OLYMPUS 2801 WESTERN AVE SEATTLE WA 98121	ICR

Cleanup Site ID:	5927	***WRIA ID:***	8
Facility Site ID:	35216721	***Is NFA Site:***	Yes
Site Status:	No Further Action Required	***Responsible Unit:***	Northwest
Statute:	MTCA	***Latitude:***	47.615635138203309
Rank:		***Longitude:***	-122.35332539529546
Rank Description:		***Legislative District:***	36
Has Env Covenant:		***Congr District:***	7
Is Brownfiled Site:		***County Name:***	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		***Start Date:***	2001-05-18
VCP Prj No:	NW0649	***End Date:***	
Activity Name:	VCP Application	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Related ID: **Start Date:**
VCP Prj No: NW0649 **End Date:** 2001-08-24
Activity Name: VCP Termination **Legal Mechanism:**
Activity Status: Completed **Performed by:**
County Name: King **Project Manager:**
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Related ID: **Start Date:**
VCP Prj No: **End Date:** 2001-08-24
Activity Name: Site Status Changed to NFA **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: CleanupSite
Applies to Description:

Related ID: 5680 **Start Date:** 2001-05-14
VCP Prj No: **End Date:** 2001-05-17
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 5680 **Start Date:** 2001-05-17
VCP Prj No: **End Date:** 2001-05-17
Activity Name: LUST - Notification **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 5680 **Start Date:** 1999-12-22
VCP Prj No: **End Date:** 2001-05-17
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: **Start Date:**
VCP Prj No: NW0649 **End Date:**
Activity Name: VCP Opinion on Cleanup Action **Legal Mechanism:**
Activity Status: Canceled **Performed by:**
County Name: King **Project Manager:** Sato, Brian
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Media Contaminants

Contaminant Type: Petroleum-Other **Sediment:**
Groundwater: **Sediment Desc.:**
Groundwater Desc.: **Air:**
Surface Water: **Air Desc.:**
Surfacewater Desc.: **Bedrock:**
Soil: C **Bedrock Desc.:**
Soil Desc.: Confirmed Above Cleanup Level **County Name:** King

---

21 **5 of 6** **WSW** **0.11 / 577.56** **49.42 / -56** **The Olympus**
2801 WESTERN AVE
SEATTLE WA 98121 **VCP**

Facility Site ID: 35216721 **County:** King
Cleanup Site ID: 5927 **Latitude:** 47.6156351382033
Region: Northwest **Longitude:** -122.353325395295
Alternate Site Names: ELLIOTT & BROAD STREET,THE OLYMPUS ELLIOTT & BROAD ST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Data Source(s): No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status: NFA
NFA Date: 08/24/2001
Responsible Unit: Northwest
Has Inst Control:
NFA Reason: Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: No Further Action
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

21	6 of 6	WSW	0.11 / 577.56	49.42 / -56	The Olympus 2801 WESTERN AVE SEATTLE WA 98121	LUST

Facility Site ID: 35216721
Cleanup Site ID: 5927
Responsible Unit: Northwest
Region: Northwest
Alternate Site Names: ELLIOTT & BROAD STREET,THE OLYMPUS ELLIOTT & BROAD ST
County: King
Latitude: 47.6156351382033
Longitude: -122.353325395295

Tank Detail(s)

UST ID: 579191
LUST ID: 5680
LUST Status: LUST - NFA
Status Date: 08/24/2001
Release Date: 05/17/2001

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

22	1 of 1	SW	0.11 / 591.76	54.05 / -52	SEATTLE WA	SPILLS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Incident ID:	120341	**Location:**	
Incident Date:	01/03/2022	**Address:**	
Latitude:	47.6152	**City:**	SEATTLE
Longitude:	-122.3522	**County:**	KING

Spill Details June 2020 - Present

ERTS ID:	711677	**To Water Qty:**	
Incident Type No.:	6	**Tosoil Qty:**	7
Spill Quantity:	84273.77	**Imperm Qty:**	
Total Spill Qty:	7.5	**To Water Rec Qty:**	
Recovered Quantity1:	33986.3	**To Soil Rec Qty:**	7
Total Recovered Qty:	7.5	**Imperm Rec Qty:**	
Inc Primary Ca Type:	Oil Spill	**Is Regulated Flag:**	
Incident Categories:	Oil Spill	**Resp Party Name:**	Recology CleanScapes
Source Type Desc:	Vehicle	**Response Person:**	Buck Smith
Source Description:	Construction/utility vehicle	**Response Act Desc:**	TELEPHONE
Material Desc:	HYDRAULIC OIL	**Vessel Facility Name:**	
Medium Desc:	Public Road Right-of-Way		
Activity Description:	UNDERWAY OR IN MOTION		
Cause Type Desc:	EQUIPMENT/MATERIAL FAILURE		
Cause Description:	MECHANICAL FAILURE		
Impacts:	CONTAMINATED ROADWAY/PARKING LOT		
Case Name:	Recology hydraulic fluid spill Seattle 1/3/22		
Narrative Description:			

AHR Smith spoke with Jason (Recology CleanScapes) at 19:42. A broken hose on a Recology CleanScapes collection truck sprayed 5-7 gallons of hydraulic fluid to pavement and a building. Two quarts reached a catch basin. The fluid did not exit the catch basin. US Ecology cleaned the pavement, building, and catch basin. No impacts to waters of the state. SPU was notified.

Spill Details June 2020 - Present

ERTS ID:	711677	**To Water Qty:**	0.5
Incident Type No.:	6	**Tosoil Qty:**	
Spill Quantity:	84273.77	**Imperm Qty:**	
Total Spill Qty:	7.5	**To Water Rec Qty:**	0.5
Recovered Quantity1:	33986.3	**To Soil Rec Qty:**	
Total Recovered Qty:	7.5	**Imperm Rec Qty:**	
Inc Primary Ca Type:	Oil Spill	**Is Regulated Flag:**	
Incident Categories:	Oil Spill	**Resp Party Name:**	Recology CleanScapes
Source Type Desc:	Vehicle	**Response Person:**	Buck Smith
Source Description:	Construction/utility vehicle	**Response Act Desc:**	TELEPHONE
Material Desc:	HYDRAULIC OIL	**Vessel Facility Name:**	
Medium Desc:	Catch Basin - Wet		
Activity Description:	UNDERWAY OR IN MOTION		
Cause Type Desc:	EQUIPMENT/MATERIAL FAILURE		
Cause Description:	MECHANICAL FAILURE		
Impacts:	CONTAMINATED ROADWAY/PARKING LOT		
Case Name:	Recology hydraulic fluid spill Seattle 1/3/22		
Narrative Description:			

AHR Smith spoke with Jason (Recology CleanScapes) at 19:42. A broken hose on a Recology CleanScapes collection truck sprayed 5-7 gallons of hydraulic fluid to pavement and a building. Two quarts reached a catch basin. The fluid did not exit the catch basin. US Ecology cleaned the pavement, building, and catch basin. No impacts to waters of the state. SPU was notified.

23	***1 of 6***	***NNW***	***0.11 / 592.50***	***125.36 / 20***	***3RD AND BROAD 2901 3RD AVE SEATTLE WA 98121***	***PCB***

Site ID:	WAW000200592	**Mail Address 1:**	1000-2ND AVE
Receive Date:		**Mail Address 2:**	SUITE 1800
Generator:	Yes	**Mail Street No:**	
Storer:	No	**Mail City:**	SEATTLE
Transporter:	No	**Mail State:**	WA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Disposer:	No	**Mail Zip:**	98104
Research:	No	**Mail Country:**	US
Smelter:	No	**Contact Name:**	PAUL SCHMIDT
Cert Title:		**Contact Title:**	BUILDING MANAGER
Cert Date:	1/28/2016 12:00:00 AM	**Contact Phone:**	206-386-5100
Cert Name:		**Contact Phone Ext:**	
Location Country:	US	**Contact Email:**	
State Name:	WASHINGTON	**Owner Name:**	SELIG HOLDINGS, LLC
Region:	10		

23	2 of 6	NNW	0.11 / 592.50	125.36 / 20	**WA STATE FERRY OPERATIONS CENTER** **2901 3RD AVE** **SEATTLE WA 98121**	ERTS

Incident ID:	617011	**Latitude:**	
Incident Date:	2009-12-13	**Longitude:**	
County:	KING		
Location:	WA STATE FERRY OPERATIONS CENTER		

Initial Report Details

Initial Report Substance Name:	Sewage/Sludge
Initial Report Subst Catego:	Waste
Initial Report Subst Quanti:	10
Initial Report Substance Unit:	U.S. gallons
Initial Report Medium Name:	Surface Water-Marine
Initial Report Medium Category:	Water
Initial Report Cause Category:	Equipment failure
Initial Report Cause Name:	Unknown
Initial Report Source Name:	Public vessel
Initial Report Source Category:	Vessel
Initial Report Activity Name:	Routine/Normal operations
Initial Report Comment Desc:	-----Original Message----- From: Duty Officer (EM

Follow up Details

ERTS Follow up No:	100955
Follow up Substance Name:	Sewage/Sludge
Follow up Substance Quantity:	10
Follow up Subst Unit of Meas:	U.S. gallons
Follow up Cause Name:	Unknown
Follow up Medium Name:	Surface Water-Marine
Follow up Source Nname:	Public vessel
Follow up Activity Name:	Routine/Normal operations

Potential Details

Pot Resp Party First Name:	CHRISTOPHER
Pot Resp Prty Last Name:	KENNEDY
Potentially Resp Party Org:	WA STATE FERRY OPERATIONS CENTER

Follow up Comments

Follow up Comment:

ERTS Number 617011 - 12/13/2009
Called Reporting/Responsible Party, WSF. The pipe failed while transferring sewage off of the ferry to the receiving facility. Refer to water quality.

Follow up Comment:

ERTS Number 617011 - Historic Investigator Contact Information - FirstName: KELLI (ECY) MiddleName: LastName: GUSTAF AHR OrganizationName: SPILLS, PREVENTION, PREPAREDNESS AND RESPONSE WorkLocation: NWRO

Follow up Comment:

ERTS Number 617011 - Historic Referral Contact Information - ReferralDate: 2009-12-14 FirstName: KELLI (ECY) MiddleName: LastName: GUSTAF AHR Email: kgus461@ECY.WA.GOV PhoneNumber: (425) 649-7194 OrganizationName: SPILLS, PREVENTION, PREPAREDNESS AND RESPONSE WorkLocation: NWRO

Follow up Comment:

ERTS Number 617011 - Historic Referral Contact Information - ReferralDate: 2009-12-14 FirstName: AMY MiddleName: LastName: JANKOWIAK Email: AJAN461@ECY.WA.GOV PhoneNumber: (425) 649-7195 OrganizationName: WATER QUALITY WorkLocation: NWRO

Initial Comments

Initial Report Comment:

ERTS Number 617011 - -----Original Message-----
From: Duty Officer (EMD)
Sent: Sunday, December 13, 2009 9:27 AM
To: Sacayanan, Tamara L. (ECY)
Subject: FW: NRC#926039

Tamara:

We received this just before 0930 today (12/12/09).

Ted Henkle
State Emergency Operations Officer
Washington State Emergency Operations Center
24-hr: 800-258-5990 Fax: 253-512-7203
www.emd.wa.gov

-----Original Message-----
From: HQS-PF-fldr-NRC@uscg.mil [mailto:HQS-PF-fldr-NRC@uscg.mil]
Sent: Sunday, December 13, 2009 9:22 AM
To: Duty Officer (EMD)
Subject: NRC#926039

NATIONAL RESPONSE CENTER 1-800-424-8802
GOVERNMENT USE ONLYGOVERNMENT USE ONLY***
Information released to a third party shall comply with any
applicable federal and/or state Freedom of Information and Privacy Laws

Incident Report # 926039

INCIDENT DESCRIPTION

*Report taken by: PO2 BRIAN DOVE at 12:14 on 13-DEC-09
Incident Type: FIXED
Incident Cause: EQUIPMENT FAILURE
Affected Area: ELLIOT BAY
Incident occurred on 13-DEC-09 at 08:51 local incident time.
Affected Medium: WATER ELLIOT BAY

REPORTING PARTY
Name: CHRISTOPHER KENNEDY
Organization: WA. STATE FERRY OPERATIONS CENTER
Address: 2901 3RD AVENUE
SEATTLE, WA 98121
WA. STATE FERRY OPERATIONS CENTER reported for the responsible party.
PRIMARY Phone: (206)5153456
Type of Organization: STATE GOVERNMENT

SUSPECTED RESPONSIBLE PARTY
Name: CHRISTOPHER KENNEDY

Organization: WA. STATE FERRY OPERATIONS CENTER
Address: 2901 3RD AVENUE
SEATTLE, WA 98121
PRIMARY Phone: (206)5153456

INCIDENT LOCATION
2901 3RD AVENUE County: KING
City: SEATTLE State: WA Zip: 98121
PIER 52

RELEASED MATERIAL(S)
CHRIS Code: NCC Official Material Name: NO CHRIS CODE
Also Known As: RAW SEWAGE
Qty Released: 10 GALLON(S) Qty in Water: 10 GALLON(S)

DESCRIPTION OF INCIDENT
CALLER STATED SEWAGE WAS BEING PUMPED FROM A VESSEL TO THE FACILITY AND THE PIPELINE LEADING TO THE FACILITY DEVELOPED A LEAK AND RELEASED SEWAGE ONTO LAND AND INTO THE WATER.

SENSITIVE INFORMATION

INCIDENT DETAILS
Package: NO
Building ID:
Type of Fixed Object: PORT FACILITY
Power Generating Facility: NO
Generating Capacity:
Type of Fuel:
NPDES:
NPDES Compliance: UNKNOWN
---WATER INFORMATION---
Body of Water: ELLIOT BAY
Tributary of: PUGET SOUND
Nearest River Mile Marker:
Water Supply Contaminated: NO

IMPACT
Fire Involved: NO Fire Extinguished: UNKNOWN

INJURIES: NO Hospitalized: Empl/Crew: Passenger:
FATALITIES: NO Empl/Crew: Passenger: Occupant:
EVACUATIONS:NO Who Evacuated: Radius/Area:

Damages: NO
Hours Direction of
Closure Type Description of Closure Closed Closure
N
Air:
N Major
Road: Artery:N
N
Waterway:
N
Track:

Environmental Impact: NO
Media Interest: NONE Community Impact due to Material:

REMEDIAL ACTIONS
NONE
Release Secured: YES
Release Rate:
Estimated Release Duration:

WEATHER

Weather: OVERCAST, 31ºF
Wave Condition: 0 CALM

ADDITIONAL AGENCIES NOTIFIED
Federal: NONE
State/Local: NONE
State/Local On Scene: NONE
State Agency Number: NONE

NOTIFICATIONS BY NRC
DHS NOC (NOC)
13-DEC-09 12:21 (202)2828114
DOT CRISIS MANAGEMENT CENTER (MAIN OFFICE)
13-DEC-09 12:21 (202)3661863
EPA CRIMINAL INVESTIGATION DIVISION (EPA CRIMINAL INVESTIGATION DIV REG
13-DEC-09 12:21 (206)5538306
U.S. EPA X SEATTLE (MAIN OFFICE)
(206)5531263
FEMA REGION 10 (MAIN OFFICE)
13-DEC-09 12:21 (425)4874704
NATIONAL INFRASTRUCTURE COORD CTR (MAIN OFFICE)
13-DEC-09 12:21 (202)2829201
NOAA RPTS FOR WA (MAIN OFFICE)
13-DEC-09 12:21 (206)5264911
PIPELINE & HAZMAT SAFETY ADMIN (OFFICE OF PIPELINE SAFETY (AUTO))
13-DEC-09 12:21 (202)3660568
SECTOR SEATTLE (COMMAND CENTER)
(206)2176002
WA STATE EMERGENCY MANAGEMENT (MAIN OFFICE)
13-DEC-09 12:21 (800)2585990
STATE OF WA DEPT OF HEALTH (WA DOH)
13-DEC-09 12:21 (360)2363327
WASHINGTON STATE FUSION CENTER (MAIN OFFICE)
13-DEC-09 12:21 (877)

ADDITIONAL INFORMATION
CALLER STATED THE MATERIAL THAT SPILLED IS LESS THAN 10 GALLONS.

*** END INCIDENT REPORT #926039 ***
Report any problems by calling 1-800-424-8802
PLEASE VISIT OUR WEB SITE AT http://www.nrc.uscg.mil

23	3 of 6	NNW	0.11 / 592.50	125.36 / 20	2901 3RD AVE SEATTLE WA	ERTS

Incident ID: 547548
Incident Date: 2005-04-19
County: KING
Location:
Latitude:
Longitude:

Initial Report Details

Initial Report Substance Name: Debris/Garbage
Initial Report Subst Catego: Debris
Initial Report Subst Quanti:
Initial Report Substance Unit:
Initial Report Medium Name: Roadway-paved
Initial Report Medium Category: Impermeable surface
Initial Report Cause Category: Human error
Initial Report Cause Name: Policy/Procedure; Incorrect
Initial Report Source Name: Construction site
Initial Report Source Category: Facility
Initial Report Activity Name: Construction, other
Initial Report Comment Desc: REMODELING IS OCCURING IN THE 6 STORY BUILDING. E

Follow up Details

ERTS Follow up No:
Follow up Substance Name:
Follow up Substance Quantity:
Follow up Subst Unit of Meas:
Follow up Cause Name:
Follow up Medium Name:
Follow up Source Nname:
Follow up Activity Name:

Potential Details

Pot Resp Party First Name:
Pot Resp Prty Last Name: UNK
Potentially Resp Party Org:

Initial Comments

Initial Report Comment:

ERTS Number 547548 - REMODELING IS OCCURING IN THE 6 STORY BUILDING. EVERYTHING IS BEING THROWN OUT THE WINDOWS ON TO THE GROUND BELOW. THERE IS A CHUTE INSTALLED ON THE 5TH FLOOR, BUT IT IS NOT BEING USED. THERE IS AN EXTREME AMOUNT OF DUST AND PARTICLES THROUGH OUT THE BUILDING FROM THE DRYWALL AND INSULATION BEING REMOVED. THERE ARE ALSO METAL PIECES BEING THROWN OUT THE WINDOW TO THE GROUND BELOW. THERE ARE WORKERS ON THE GROUND PLACING THE ITEMS IN THE DUMPSTER.

COMPLAINTS TO THE BUILDING MANAGER HAVE NOT RESULTED IN A SOLUTION. HE SAYS HE IS ON A TIGHT TIME SCHEDULE.

Historic Referral Contact Information - ReferralDate: 2005-04-19 FirstName: COMPLAINT HOTLINE MiddleName: LastName: SEATTLE DCLU Email: karen.white@seattle.gov PhoneNumber: (206) 684-7899 OrganizationName: seattle WorkLocation: CODE ENFORCEMENT

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	4 of 6	NNW	0.11 / 592.50	125.36 / 20	PS- ELLIOTT BAY 2901 3RD AVE SEATTLE WA	SPILLS

Incident ID: 617011
Incident Date: 12/13/2009
Latitude: NULL
Longitude: NULL
Location: PS- ELLIOTT BAY
Address: 2901 3RD AVE
City: SEATTLE
County: KING

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	5 of 6	NNW	0.11 / 592.50	125.36 / 20	2901 3RD AVE SEATTLE WA	SPILLS

Incident ID: 547548
Incident Date:
Latitude:
Longitude:
Location:
Address: 2901 3RD AVE
City: SEATTLE
County: KING

Spill Information

Incident Date: 4/19/2005
Latitude: NULL
Longitude: NULL

Spill Details Historical

Material: DEBRIS/GARBAGE
Qty: NULL
Medium: ROADWAY-PAVED
Source: CONSTRUCTION SITE
Sheen Only: 0
Waterway: NULL

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Impact:	AIR POLLUTION	**Prp Business Name:**	NULL
Cause:	IMPROPER PROCEDURE	**Prp First Name:**	NULL
Activity:	OTHER CONSTRUCTION	**Prp Last Name:**	UNK

---

23 | **6 of 6** | **NNW** | **0.11 / 592.50** | **125.36 / 20** | **2901 3RD AVE SEATTLE WA** | **SPILLS**

Incident ID:	617011	**Location:**	
Incident Date:		**Address:**	2901 3RD AVE
Latitude:		**City:**	SEATTLE
Longitude:		**County:**	KING

Spill Information

Incident Date:	12/13/2009
Latitude:	NULL
Longitude:	NULL

Spill Details Historical

Material:	SEWAGE/SLUDGE	**Source:**	VESSEL - PUBLIC
Qty:	10	**Sheen Only:**	0
Medium:	SURFACE WATER-MARINE	**Waterway:**	PS- ELLIOTT BAY
Impact:	WATER POLLUTION	**Prp Business Name:**	WA STATE FERRY OPERATIONS CENTER
Cause:	EQUIPMENT FAILURE	**Prp First Name:**	CHRISTOPHER
Activity:	ROUTINE/NORMAL OPERATIONS	**Prp Last Name:**	KENNEDY

---

24 | **1 of 1** | **ENE** | **0.11 / 592.78** | **124.47 / 19** | **320 CEDAR STREET AT 4TH AND CEDAR IN THE SEATTLE WA** | **ERTS**

Incident ID:	425987	**Latitude:**	
Incident Date:	1997-01-22	**Longitude:**	
County:	KING		
Location:			

Initial Report Details

Initial Report Substance Name:	Undetermined
Initial Report Subst Catego:	Historical
Initial Report Subst Quanti:	55
Initial Report Substance Unit:	U.S. gallons
Initial Report Medium Name:	Undetermined
Initial Report Medium Category:	Historical
Initial Report Cause Category:	Human error
Initial Report Cause Name:	Dumping
Initial Report Source Name:	Underground storage tank (UST)
Initial Report Source Category:	Tank
Initial Report Activity Name:	Disposing
Initial Report Comment Desc:	CALLER REPORTS A DRUM WAS LEFT IN HIS ALLEY. THER

Follow up Details

ERTS Follow up No:	13413
Follow up Substance Name:	Undetermined
Follow up Substance Quantity:	55
Follow up Subst Unit of Meas:	U.S. gallons
Follow up Cause Name:	Dumping
Follow up Medium Name:	Undetermined
Follow up Source Nname:	Underground storage tank (UST)
Follow up Activity Name:	Disposing

Potential Details

Pot Resp Party First Name:
Pot Resp Prty Last Name:
Potentially Resp Party Org: UNKNOWN

Follow up Comments

Follow up Comment:

ERTS Number 425987 - 1-22-97 TALKED W/CITIZEN WHO REPORTED DRUM 1-24-97 HAZCATTED W/SUSANNE WINTER 1-30-97 MET PHILLIPS ENVIRONMENTAL ON SITE FOR DISPOSAL.

Follow up Comment:

ERTS Number 425987 - Historic Investigator Contact Information - FirstName: SHEILA MiddleName: LastName: HOSNER OrganizationName: SPILLS, PREVENTION, PREPAREDNESS AND RESPONSE WorkLocation: NWRO

Follow up Comment:

ERTS Number 425987 - Historic Referral Contact Information - ReferralDate: 1997-01-22 FirstName: MiddleName: LastName: O'BRIEN Email: PhoneNumber: OrganizationName: SPILLS, PREVENTION, PREPAREDNESS AND RESPONSE WorkLocation: NWRO

Initial Comments

Initial Report Comment:

ERTS Number 425987 - CALLER REPORTS A DRUM WAS LEFT IN HIS ALLEY. THERE IS AN UNKNOWN SUBSTANCE IN IT. THE DRUM IS SEALED. CALLER REPORTS HE HAS MADE SEVERAL CALLS TO THE CITY AND NONE HAVE BEEN RETURNED. HE CALLED AGAIN TODAY AND WAS TOLD THAT EVERY TIME HE CALLED, HIS REPORT WAS REFERRED TO ECOLOGY. I HAVE DONE A QUERY AND NO SUCH REPORT CAME INTO ME ON THIS LOCATION.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
25	1 of 1	SE	0.11 / 595.00	96.69 / -9	2517 1ST AVE Seattle WA 98119	UST SEATTLE

Permit No: 3-49166
Date Issued: 09/22/2003
Fill Material: N/A
Date Decommissioned: 09/22/2003
Type Decommissioned: Removal
Tank Size: 300
Tank Age: 30+
Tank Content: HEATING OIL

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
26	1 of 1	SW	0.11 / 601.93	52.07 / -54	2717 WESTERN AVE SEATTLE WA	SPILLS

Incident ID: 611562
Incident Date:
Latitude:
Longitude:
Location:
Address: 2717 WESTERN AVE
City: SEATTLE
County: KING

Spill Information

Incident Date: 3/15/2009
Latitude: NULL
Longitude: NULL

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spill Details Historical

Material:	PETROLEUM - OIL OTHER	***Source:***	VESSEL - CARGO
Qty:	1000	***Sheen Only:***	0
Medium:	SURFACE WATER-MARINE	***Waterway:***	PS- ELLIOTT BAY
Impact:	WATER POLLUTION	***Prp Business Name:***	HANJIN CARGO SHIP
Cause:	NULL	***Prp First Name:***	NULL
Activity:	BILGE PUMPING	***Prp Last Name:***	NULL

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
27	1 of 2	W	0.12 / 607.50	55.10 / -51	OLYMPIC SCULPTURE PARK WESTERN AVE. & BROAD ST. SEATTLE WA	ERTS

Incident ID:	553847	***Latitude:***	47.615608000000002
Incident Date:	2006-03-07	***Longitude:***	122.355546
County:	KING		
Location:	OLYMPIC SCULPTURE PARK		

Initial Report Details

Initial Report Substance Name:	Undetermined
Initial Report Subst Catego:	Historical
Initial Report Subst Quanti:	
Initial Report Substance Unit:	
Initial Report Medium Name:	Undetermined
Initial Report Medium Category:	Historical
Initial Report Cause Category:	Accident
Initial Report Cause Name:	Undetermined
Initial Report Source Name:	Rail
Initial Report Source Category:	Vehicle
Initial Report Activity Name:	Unknown
Initial Report Comment Desc:	RECEIVED INFO VIA EMAIL ONLY FROM WA STATE EOC -

Follow up Details

ERTS Follow up No:	71400
Follow up Substance Name:	Undetermined
Follow up Substance Quantity:	1
Follow up Subst Unit of Meas:	Each
Follow up Cause Name:	Other
Follow up Medium Name:	Building/Structure
Follow up Source Nname:	Construction site
Follow up Activity Name:	Construction, other

Potential Details

Pot Resp Party First Name:	
Pot Resp Prty Last Name:	
Potentially Resp Party Org:	BNSF

Follow up Comments

Follow up Comment:

ERTS Number 553847 - 3/13/06 9:00am Called Paula Hodge w/BNSF. She reported last week a crane fell across the railroad tracks casuing an interruption of passenger service. She said the crane operator was experienced with 40 years experience but the crane fell when earth underneath it gave way. She did not know if there was a release of any oil from the equipment. I educated her that WA state law requires immediate notification if oil or hazardous substances threaten water. She referred me to a local contact for more information: Kathleen Sage, 206.625.6294.

3/14/06 8:30am Called Kathleen. She verified nothing was discharged. There was minimal damage done to the tracks but the interruption of service did impact business. NFA

Follow up Comment:

ERTS Number 553847 - Historic Investigator Contact Information - FirstName: CHARMAINE MiddleName: LastName: BERNARD OrganizationName: SPILLS, PREVENTION, PREPAREDNESS AND RESPONSE WorkLocation: NWRO

Follow up Comment:

ERTS Number 553847 - Historic Referral Contact Information - ReferralDate: 2006-03-13 FirstName: CHARMAINE MiddleName: LastName: BERNARD Email: chas461@ecy.wa.gov PhoneNumber: (425) 649-7194 OrganizationName: SPILLS, PREVENTION, PREPAREDNESS AND RESPONSE WorkLocation: NWRO

Initial Comments

Initial Report Comment:

ERTS Number 553847 - RECEIVED INFO VIA EMAIL ONLY FROM WA STATE EOC - NO PHONE CALL RECEIVED. IT IS UNKNOWN IF THERE WAS A RELEASE OF ANYTHING INVOLVED:

A CONTRACTOR`S CRANE WORKING AT A PARK
ADJACENT TO THE ART INSTITUTE, TOPPLED OVER. THE BOOM LAID ACROSS
THE MAIN TRACKS WHICH CAUSED TRAINS TO BE DELAYED.

NATIONAL RESPONSE CENTER - FLASH FAX
GOVERNMENT USE ONLYGOVERNMENT USE ONLY***
DO NOT RELEASE this information to the public without
permission from the NATIONAL RESPONSE CENTER 1-800-424-8802

Incident Report # 790707

INCIDENT DESCRIPTION

*Report taken by: CIV JONES at 11:42 on 13-MAR-06
Incident Type: RAILROAD
Incident Cause: OPERATOR ERROR
Affected Area:
The incident occurred on 07-MAR-06 at 15:25 local time.
Affected Medium: RAIL REPORT (N/A) NONE

REPORTING PARTY
Name: PAULA HODGE
Organization: BNSF
Address: 2600 LOUMINK DRIVE
FORT WORTH, TX 76131

PRIMARY Phone: (817)3523991
Type of Organization: PRIVATE ENTERPRISE

SUSPECTED RESPONSIBLE PARTY
Name: UNKNOWN

XX

Type of Organization: UNKNOWN

INCIDENT LOCATION
County: KING
City: SEATTLE State: WA
MILE POST 1.8-1.9

RELEASED MATERIAL(S)

DESCRIPTION OF INCIDENT
THE CALLER STATED THAT A CONTRACTOR`S CRANE WORKING AT A PARK
ADJACENT TO THE ART INSTITUTE, TOPPLED OVER. THE BOOM LAID ACROSS
THE MAIN TRACKS WHICH CAUSED TRAINS TO BE DELAYED.

INCIDENT DETAILS

Grade Crossing: NO
Location Subdivision: SCENIC
Railroad Milepost: 1.8-1.9
Type of Vehicle Involved:
Crossing Device Type:
Device Operational: YES
DOTCrossing Number:
Date and Time Service was/will be Restored:
Brake Failure: NO
Federal Post-Accident 219.201 Sub Part C Testing Required: NO

---RAILROAD INFORMATION---
Railroad Involved:
Train Number: OTHER
Train Type: OTHER Train Direction:
Train Speed: Track Speed:
Locomotives: Cars: Derailed:
Suspected DOT Regulation Non Compliance: NO
DERAILED CARS:
Pos. Carnumber Type Cargo

DAMAGES
Fire Involved: NO Fire Extinguished: UNKNOWN
INJURIES: Hospitalized: Empl/Crew: Passenger:

FATALITIES: Empl/Crew: Passenger: Occupant:
EVACUATIONS: Who Evacuated: Radius/Area:
Damages:

Hours Direction of
Closure Type Description of Closure Closed Closure
Air: N

Road: N Major N
Artery:
Waterway: N

Track: N

Passengers Transferred: UNKNOWN
Media Interest: NONE Community Impact due to Material: NO

REMEDIAL ACTIONS

Release Secured: UNKNOWN
Release Rate:
Estimated Release Duration:

WEATHER
Weather: UNKNOWN, ºF

ADDITIONAL AGENCIES NOTIFIED
Federal:
State/Local:
State/Local On Scene:
State Agency Number:

NOTIFICATIONS BY NRC
ATSDR WA ATTN: HOPE HOUGH (PRIMARY)
13-MAR-06 11:47 (360)2363327
DOT CRISIS MANAGEMENT CENTER (PRIMARY)
13-MAR-06 11:47 (202)3661863
FEDERAL RAILROAD ADMIN. (PRIMARY)
(202)4936214
EPA CRIMINAL INVESTIGATION DIV R10 (SPECIAL AGENT IN CHARGE)
13-MAR-06 11:47 (503)3262032
FEMA REGION 10 (PRIMARY)
13-MAR-06 11:47 (425)4874704
NATIONAL INFRASTRUCTURE COORD CTR (PRIMARY)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

13-MAR-06 11:47 (202)2829201
NOAA RPTS FOR WA (PRIMARY)
13-MAR-06 11:47 (206)5266344
WA STATE EMERGENCY MANAGEMENT (PRIMARY)
13-MAR-06 11:47 (800)2585990

ADDITIONAL INFORMATION
THE CALLER HAD NO ADDITIONAL INFORMATION

*** END INCIDENT REPORT 790707 ***
Report any problems or Fax number changes by calling 1-800-424-8802
PLEASE VISIT OUR WEB SITE AT http://www.nrc.uscg.mil

---

27 | **2 of 2** | **W** | **0.12 / 607.50** | **55.10 / -51** | **NULL**
WESTERN AVE. & BROAD ST.
SEATTLE WA | **SPILLS**

Incident ID:	553847	**Location:**	NULL
Incident Date:	3/7/2006	**Address:**	WESTERN AVE. & BROAD ST.
Latitude:	47.615608	**City:**	SEATTLE
Longitude:	122.355546	**County:**	KING

---

28 | **1 of 1** | **SE** | **0.12 / 610.99** | **98.38 / -7**
2556 1ST AVE
Seattle WA 98109 | **UST SEATTLE**

Permit No:	3-36566	**Tank Size:**	300
Date Issued:	02/07/2001	**Tank Age:**	40
Fill Material:	No Fill	**Tank Content:**	HEATING OIL
Date Decommissioned:	02/09/2001		
Type Decommissioned:	Abandonment in Place		

---

29 | **1 of 2** | **ENE** | **0.12 / 611.69** | **123.42 / 18** | **NULL**
320 CEDAR STREET AT 4TH AND CEDAR IN THE
SEATTLE WA | **SPILLS**

Incident ID:	425987	**Location:**	NULL
Incident Date:	1/22/1997	**Address:**	320 CEDAR STREET AT 4TH AND CEDAR IN THE
Latitude:	NULL	**City:**	SEATTLE
Longitude:	NULL	**County:**	KING

---

29 | **2 of 2** | **ENE** | **0.12 / 611.69** | **123.42 / 18**
320 CEDAR STREET AT 4TH AND CEDAR IN THE
SEATTLE WA | **SPILLS**

Incident ID:	425987	**Location:**	
Incident Date:		**Address:**	320 CEDAR STREET AT 4TH AND CEDAR IN THE
Latitude:		**City:**	SEATTLE
Longitude:		**County:**	KING

Spill Information

Incident Date:	1/22/1997
Latitude:	NULL
Longitude:	NULL

Spill Details Historical

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Material: UNKNOWN
Qty: 55
Medium: UNKNOWN
Impact: UNKNOWN
Cause: DUMPING
Activity: DISPOSING
Source: UNDERGROUND STORAGE TANK
Sheen Only: 0
Waterway: NULL
Prp Business Name: UNKNOWN
Prp First Name: NULL
Prp Last Name:

---

30 | 1 of 1 | ESE | 0.12 / 613.18 | 108.63 / 3 | 2551 2ND AVE Seattle WA N/A | UST SEATTLE

Permit No: 3-36899
Date Issued: 03/09/2001
Fill Material: No Fill
Date Decommissioned: 03/09/2001
Type Decommissioned: Abandonment in Place
Tank Size: 500 to 675 GALLON
Tank Age: 60+
Tank Content: H20

---

31 | 1 of 2 | S | 0.12 / 619.56 | 64.91 / -41 | WASHINGTON TRANSIT ADVERTISING 2600 WESTERN AVE SEATTLE WA 98121 | RCRA NON GEN

EPA Handler ID: WAD027482959
Gen Status Universe: No Report
Contact Name: WASHINGTON TRAN WASHINGTON TRAN
Contact Address: 1601 5TH AVE STE 110 , , SEATTLE , WA, 98101-1625 , US
Contact Phone No and Ext: 000-000-0000
Contact Email:
Contact Country: US
County Name: KING
EPA Region: 10
Land Type: Private
Receive Date: 19900121
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 2

Receive Date: 19900121
Handler Name: WASHINGTON TRANSIT ADVERTISING
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19900121
Handler Name: WASHINGTON TRANSIT ADVERTISING
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19900121
Handler Name: WASHINGTON TRANSIT ADVERTISING
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: SEE PAPER COPY
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Implementer
Street No:
Street 1: 2600 WESTERN AVE
Street 2:
City: SEATTLE
State: WA
Country:
Zip Code: 98121

Owner/Operator Ind: Current Owner
Type: Private
Name: WASHINGTON TRAN W
Date Became Current: 19960502
Date Ended Current:
Phone: 000-000-0000
Source Type: Implementer
Street No:
Street 1: 2600 WESTERN AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121-1376

Owner/Operator Ind: Current Owner
Type: Private
Name: WASHINGTON TRANSIT ADVERTISING
Date Became Current: 19960502
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 2600 WESTERN AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Operator
Type: Private
Name: WASHINGTON TRANSIT ADVERTISING
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 2600 WESTERN AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Operator
Type: Private
Name: WASHINGTON TRANSIT ADVERTISING
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Implementer
Street No:
Street 1: 2600 WESTERN AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121-1376

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2600 WESTERN AVE
Name:	WASHINGTON TRANSIT ADVERTISING	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121

Historical Handler Details

Receive Dt:	19900121
Generator Code Description:	Not a Generator, Verified
Handler Name:	WASHINGTON TRANSIT ADVERTISING

---

31 | ***2 of 2*** | ***S*** | ***0.12 / 619.56*** | ***64.91 / -41*** | ***Washington Transit Advertising 2600 WESTERN AVE SEATTLE WA 98121*** | ***ALL SITES***

Facility/Site ID:	86324942
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAD027482959
Facility Alternate:	
Interaction ID:	69018
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	21-Jan-1990
Interact End Dt:	01-Apr-1991
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	N
Horizont 1:	NAD83	**GIS latitude:**	47.61481
Horizont 2:	Unknown	**GIS longitude:**	-122.35051

---

32 | ***1 of 4*** | ***S*** | ***0.12 / 621.29*** | ***61.61 / -44*** | ***Vine Building 2607 WESTERN AVE SEATTLE WA 98121*** | ***CSCSL NFA***

Fac Site ID:	35169248	**Fac Site ID (OD):**	35169248
Cleanup Site ID:	2330	**Cleanup SiteID(OD):**	2330
Site Status:	NFA	**Site Status (OD):**	No Further Action
NFA Date:	07/13/2001	**Rank (OD):**	
Responsible Unit:	Northwest	**Has Env Coven (OD):**	
Has Insti Control:		**Respon Unit (OD):**	Northwest
Region:	Northwest	**Region (OD):**	Northwest
County:	King	**County (OD):**	King
Latitude:	47.614805	**Latitude (OD):**	47.614805
Longitude:	-122.350611	**Longitude (OD):**	-122.350611
NFA Reason:	Voluntary Cleanup Program Review		
Alternate Site Names:			
Location (OD):	"" (47.614805, -122.350611)		
Data Source(s):	Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminants

NFA Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
32	2 of 4	S	0.12 / 621.29	61.61 / -44	VINE BUILDING 2607 WESTERN AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID: 35169248
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: VINE BUILDING
Interaction ID: 39753
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 14-May-2001
Interact End Dt: 13-Jul-2001
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Address
Location Verified: N
GIS latitude: 47.614805
GIS longitude: -122.350611

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
32	3 of 4	S	0.12 / 621.29	61.61 / -44	VINE BUILDING 2607 WESTERN AVE SEATTLE WA 98121	ICR

Cleanup Site ID: 2330
Facility Site ID: 35169248
Site Status: No Further Action Required
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site: Yes
WRIA ID: 8
Is NFA Site: Yes
Responsible Unit: Northwest
Latitude: 47.614804999999997
Longitude: -122.350611
Legislative District: 36
Congr District: 7
County Name: King

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Cleanup Activities

Related ID:		***Start Date:***	2001-05-14
VCP Prj No:	NW0648	***End Date:***	
Activity Name:	VCP Application	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Northwest Region
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	
VCP Prj No:	NW0648	***End Date:***	
Activity Name:	VCP Opinion on Cleanup Action	***Legal Mechanism:***	
Activity Status:	Canceled	***Performed by:***	
County Name:	King	***Project Manager:***	Yang, Grant
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	2001-07-13
Activity Name:	Site Status Changed to NFA	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		***Start Date:***	
VCP Prj No:	NW0648	***End Date:***	2001-07-13
Activity Name:	VCP Termination	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Media Contaminants

Contaminant Type:	Petroleum Products-Unspecified	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

---

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
32	*4 of 4*	*S*	*0.12 / 621.29*	*61.61 / -44*	***Vine Building*** ***2607 WESTERN AVE*** ***SEATTLE WA 98121***	***VCP***

Facility Site ID:	35169248	***County:***	King
Cleanup Site ID:	2330	***Latitude:***	47.614805
Region:	Northwest	***Longitude:***	-122.350611
Alternate Site Names:			
Data Source(s):	No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State		

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status:	NFA
NFA Date:	07/13/2001
Responsible Unit:	Northwest
Has Inst Control:	
NFA Reason:	Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: No Further Action
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

---

33 | ***1 of 1*** | ***S*** | ***0.12 / 627.43*** | ***71.70 / -34*** | ***Parking Garage***
75 Vine St
Seattle WA 98121 | ***ERTS***

Incident ID: 703567
Incident Date: 2021-01-29
County: King
Location: Parking Garage
Latitude: 47.614269999999998
Longitude: -122.35055

Initial Report Details

Initial Report Substance Name: Water
Initial Report Subst Catego: Water
Initial Report Subst Quanti:
Initial Report Substance Unit:
Initial Report Medium Name: Impermeable surface
Initial Report Medium Category: Impermeable surface
Initial Report Cause Category: Equipment failure
Initial Report Cause Name: Unknown
Initial Report Source Name: Other-Private property
Initial Report Source Category: Private property
Initial Report Activity Name: Underway or in motion
Initial Report Comment Desc: USCG was advised by Seattle Fire that a parking ga

Initial Report Details

Initial Report Substance Name: Gasoline
Initial Report Subst Catego: Oil
Initial Report Subst Quanti:
Initial Report Substance Unit:
Initial Report Medium Name: Drain - Unknown
Initial Report Medium Category: Water
Initial Report Cause Category: Equipment failure
Initial Report Cause Name: Unknown
Initial Report Source Name: Other-Vehicle
Initial Report Source Category: Vehicle
Initial Report Activity Name: Underway or in motion
Initial Report Comment Desc: USCG was advised by Seattle Fire that a parking ga

Follow up Details

ERTS Follow up No: 187357
Follow up Substance Name:
Follow up Substance Quantity:
Follow up Subst Unit of Meas:
Follow up Cause Name: Unknown
Follow up Medium Name:
Follow up Source Nname:
Follow up Activity Name: Underway or in motion

Follow up Details

ERTS Follow up No: 187345
Follow up Substance Name:
Follow up Substance Quantity:
Follow up Subst Unit of Meas:
Follow up Cause Name: Unknown
Follow up Medium Name:
Follow up Source Nname:
Follow up Activity Name: Underway or in motion

Follow up Details

ERTS Follow up No: 187344
Follow up Substance Name:
Follow up Substance Quantity:
Follow up Subst Unit of Meas:
Follow up Cause Name: Unknown
Follow up Medium Name:
Follow up Source Nname:
Follow up Activity Name: Underway or in motion

Potential Details

Pot Resp Party First Name:
Pot Resp Prty Last Name:
Potentially Resp Party Org:

Initial Comments

Initial Report Comment:

ERTS Number 703567 - THE CALLER STATED THAT PARKING GARAGE FLOODED ON LEVELS 04 AND 03 SUBMERGING 16 VEHICLES. A STRONG GASOLINE ORDER WAS NOTICED AS WELL AS AN OIL SHEEN ON THE FLOOD WATERS. THE CAUSE OF THE RELEASE IS UNKNOWN, HOWEVER THE CALLER BELIEVES IT MAY HAVE BEEN CAUSED BY THE FIRE SUPPRESSION SYSTEM IN THE GARAGE. THE EXACT AMOUNT OF WATER THAT WAS RELEASE IS CURRENTLY UNKNOWN BUT IS BELIEVED TO BE IN THE THOUSANDS OF GALLONS.

INCIDENT LOCATION
75 VINE STREET County: KING
City: SEATTLE State: WA Zip: 98121

RELEASED MATERIAL(S)
CHRIS Code: GAS Official Material Name: GASOLINE: AUTOMOTIVE (UNLEADED)
Also Known As:
Qty Released: 0 UNKNOWN AMOUNT Qty in Water: 0 UNKNOWN AMOUNT
CHRIS Code: NCC Official Material Name: NO CHRIS CODE
Also Known As: WATER
Qty Released: 0 UNKNOWN AMOUNT Qty in Water: 0 UNKNOWN AMOUNT
CHRIS Code: OMT Official Material Name: OIL, MISC: MOTOR
Also Known As:
Qty Released: 0 UNKNOWN AMOUNT Qty in Water: 0 UNKNOWN AMOUNT

INCIDENT DETAILS
Package: N/A
Building ID:

Type of Fixed Object: OTHER
Power Generating Facility: UNKNOWN
Generating Capacity:
Type of Fuel:
NPDES:
NPDES Compliance: UNKNOWN
---SHEEN INFORMATION---
Sheen Color: DARK BLACK
Sheen Odor Description:
Sheen Travel Direction:
Sheen Size Length:
Sheen Size Width:
---WATER INFORMATION---
Body of Water: FLOOD WATERS
Tributary of:
Nearest River Mile Marker:
Water Supply Contaminated: UNKNOWN

REMEDIAL ACTIONS
THE USCG IS ON SCENE ADDRESSING THE RELEASE
Release Secured: YES
Release Rate:
Estimated Release Duration:

ADDITIONAL AGENCIES NOTIFIED
Federal: USCG
State/Local: PUBLIC UTILITIES, ECOLOGY, FIRE
State/Local On Scene: PUBLIC UTILITIES, ECOLOGY, FIRE
State Agency Number: 9430

Initial Report Comment:

ERTS Number 703567 - USCG was advised by Seattle Fire that a parking garage has flooded. We anticipate an NRC report shortly. USCG is planning to respond - requested to be connect with ECY's ROTD.

The lowest floor of the garage and 4.5 feet of the next floor up are flooded. An estimated 20 cars were impacted. Oil is visible and the odor is present.

SPU has been notified and is en route as well. Unknown drainage impacts.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
34	1 of 8	ENE	0.12 / 629.45	121.78 / 16	Martin Selig Property 2601 4TH AVE SEATTLE WA 98121	CSCSL

Fac Site ID:	18421913	***Responsible Unit:***	Northwest
Cleanup Site ID:	1102	***Fac Site ID (OD):***	18421913
Site Status:	Cleanup Started	***Cleanup SiteID(OD):***	1102
Site Rank:	3 - Moderate Risk	***Site Rank (OD):***	3 - Moderate Risk
Current VCP:		***Has Env Coven (OD):***	
Past VCP:		***Respon Unit (OD):***	Northwest
Has Inst Control:		***County (OD):***	King
County:	King	***Region (OD):***	Northwest
Region:	Northwest	***Longitude (OD):***	-122.347847
Latitude:	47.6172651888499	***Latitude (OD):***	47.617265
Longitude:	-122.347846714683		
Site Name:	Martin Selig Property		
Address:	2601 4TH AVE		
City:	SEATTLE		
Zip Code:	98121		
Site Status (OD):	Cleanup Started		
Site Name (OD):	Martin Selig Property		
Address (OD):	2601 4TH AVE		
City (OD):	SEATTLE		
Zipcode (OD):	98121		
Location (OD):	"" (47.617265, -122.347847)		
Alternate Site Names:			
Data Source(s):	Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminants Detail(s)

Contaminant Name: Metals Priority Pollutants
Groundwater: Suspected
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Non-Halogenated Solvents
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals Priority Pollutants
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Non-Halogenated Solvents
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals Priority Pollutants
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Non-Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

34	2 of 8	ENE	0.12 / 629.45	121.78 / 16	**Martin Selig Property** **2601 4TH AVE** **SEATTLE WA 98121**	HSL

Fac Site ID: 18421913
Cleanup Site ID: 1102
Site Status: Cleanup Started
Site Rank: 3 - Moderate Risk
Has Inst Control:
Responsible Unit: Northwest
County: King
Region: Northwest
Latitude: 47.6172651888499
Longitude: -122.347846714683

Fac Site ID (OD): 18421913
Cleanup Site ID (OD): 1102
Site Status (OD): Cleanup Started
Site Rank (OD): 3 - Moderate Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Site Name (OD): Martin Selig Property
Address (OD): 2601 4TH AVE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Latitude (OD): 47.617265
Longitude (OD): -122.347847
Current VCP:
Location (OD): "" (47.617265, -122.347847)
City (OD): SEATTLE
ZIP code (OD): 98121
Past VCP:
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Metals Priority Pollutants
Groundwater: Suspected
Surfacewater:
Air:
Sediment:
Soil: Suspected
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Air:
Sediment:
Soil: Confirmed Above Cleanup Levels
Bedrock:

Contaminant Name: Non-Halogenated Solvents
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Air:
Sediment:
Soil: Confirmed Above Cleanup Levels
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Non-Halogenated Solvents
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Groundwater

Contaminant: Metals Priority Pollutants
Contaminant Status: Suspected
Contaminant Media: Soil

Contaminant: Petroleum Products-Unspecified
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Soil

Contaminant: Metals Priority Pollutants
Contaminant Status: Suspected
Contaminant Media: Groundwater

Contaminant: Non-Halogenated Solvents
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Soil

Contaminant: Petroleum Products-Unspecified
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Groundwater

34	3 of 8	ENE	0.12 / 629.45	121.78 / 16	MARTIN SELIG PROPERTY 2601 4TH AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID: 18421913
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: MARTIN SELIG PROPERTY
Interaction ID: 104695
Interaction Status: A
Interac Status Desc: Active
Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 19-Jun-1996
Interact End Dt:
Ecology Program: TOXICS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID:
Facility Alternate: MARTIN SELIG PROPERTY
Interaction ID: 104696
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: IRAP
Interaction Desc: Independent Remedial Actn Prg
Interact Start Dt: 05-Jun-1996
Interact End Dt: 19-Jun-1996
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6172651888
GIS longitude: -122.347846715

34	4 of 8	ENE	0.12 / 629.45	121.78 / 16	Grizzly Retail Rentals 2601 4TH AVE STE 350 SEATTLE WA 98121	ALL SITES

Facility/Site ID: 24926
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: Grizzly Retail Rentals
Interaction ID: 97869
Interaction Status: A
Interac Status Desc: Active
Interaction Type: RSVP
Interaction Desc: Revised Site Visit Program
Interact Start Dt: 27-Jul-2011
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: RSVP
Database Name Desc: Revised Site Visit Program

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6173633664
GIS longitude: -122.347733798

34	5 of 8	ENE	0.12 / 629.45	121.78 / 16	Martin Selig Property 2601 4TH AVE SEATTLE WA 98121	ICR

Cleanup Site ID: 1102
Facility Site ID: 18421913
Site Status: Cleanup Started
Statute: MTCA
Rank: 3
Rank Description:
WRIA ID: 8
Is NFA Site:
Responsible Unit: Northwest
Latitude: 47.617265188849885
Longitude: -122.347846714683
Legislative District: 36

Has Env Covenant:		***Congr District:***	7
Is Brownfiled Site:		***County Name:***	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:	3457	***Start Date:***	1996-06-05
VCP Prj No:		***End Date:***	1996-06-28
Activity Name:	Independent Report Review - Paid	***Legal Mechanism:***	
Activity Status:	Canceled	***Performed by:***	Ecology
County Name:	King	***Project Manager:***	Trejo, Barbara
Applies to:	CleanupUnit		
Applies to Description:			

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	1996-06-05
Activity Name:	Site Discovery/Release Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	Trejo, Barbara
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		***Start Date:***	2013-05-07
VCP Prj No:		***End Date:***	2013-06-28
Activity Name:	Site Hazard Assessment/Federal Site Inspection	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	Ecology w/ Contractor
County Name:	King	***Project Manager:***	Musa, Donna
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	2013-08-08
Activity Name:	Hazardous Sites Listing/NPL	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	Musa, Donna
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		***Start Date:***	1996-06-19
VCP Prj No:		***End Date:***	1996-06-19
Activity Name:	Initial Investigation / Federal Preliminary Assessment	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	Ecology
County Name:	King	***Project Manager:***	Trejo, Barbara
Applies to:	CleanupSite		
Applies to Description:			

Media Contaminants

Contaminant Type:	Petroleum Products-Unspecified	***Sediment:***	
Groundwater:	C	***Sediment Desc.:***	
Groundwater Desc.:	Confirmed Above Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

Contaminant Type:	Metals Priority Pollutants	***Sediment:***	
Groundwater:	S	***Sediment Desc.:***	
Groundwater Desc.:	Suspected	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	S	***Bedrock Desc.:***	
Soil Desc.:	Suspected	***County Name:***	King

Contaminant Type:	Non-Halogenated Solvents	***Sediment:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Groundwater: C
Groundwater Desc.: Confirmed Above Cleanup Level
Surface Water:
Surfacewater Desc.:
Soil: C
Soil Desc.: Confirmed Above Cleanup Level
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

---

34 | 6 of 8 | ENE | 0.12 / 629.45 | 121.78 / 16 | **Cascadian Therapeutics Seattle**
2601 4th Ave Ste 500
Seattle WA 98121 | ALL SITES

Facility/Site ID: 8504
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000053608
Facility Alternate: Cascadian Therapeutics Seattle
Interaction ID: 123645
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 10-Oct-2017
Interact End Dt: 31-Dec-2017
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Address
Location Verified:
GIS latitude: 47.61735
GIS longitude: -122.34791

---

34 | 7 of 8 | ENE | 0.12 / 629.45 | 121.78 / 16 | **CASCADIAN THERAPEUTICS SEATTLE**
2601 4TH AVE STE 500
SEATTLE WA 98121 | RCRA NON GEN

EPA Handler ID: WAH000053608
Gen Status Universe: No Report
Contact Name: MALIS WILDS
Contact Address: 2601 4TH AVE STE 500 , , SEATTLE , WA, 98121 , US
Contact Phone No and Ext: 206-801-2162
Contact Email: MWILDS@CASCADIANRX.COM
Contact Country: US
County Name: KING
EPA Region: 10
Land Type: Private
Receive Date: 20180228
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20171010
Handler Name:	CASCADIAN THERAPEUTICS SEATTLE
Source Type:	Notification
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator

Waste Code Details

Hazardous Waste Code:	D021
Waste Code Description:	CHLOROBENZENE
Hazardous Waste Code:	P043
Waste Code Description:	DIISOPROPYLFLUOROPHOSPHATE (DFP) (OR) PHOSPHOROFLUORIDIC ACID, BIS(1-METHYLETHYL) ESTER
Hazardous Waste Code:	U161
Waste Code Description:	4-METHYL-2-PENTANONE (I) (OR) METHYL ISOBUTYL KETONE (I) (OR) PENTANOL, 4-METHYL-
Hazardous Waste Code:	D001
Waste Code Description:	IGNITABLE WASTE
Hazardous Waste Code:	D038
Waste Code Description:	PYRIDINE
Hazardous Waste Code:	P087
Waste Code Description:	OSMIUM OXIDE OSO4, (T-4)- (OR) OSMIUM TETROXIDE
Hazardous Waste Code:	U010
Waste Code Description:	AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A, 2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C
Hazardous Waste Code:	U154
Waste Code Description:	METHANOL (I) (OR) METHYL ALCOHOL (I)
Hazardous Waste Code:	U219
Waste Code Description:	THIOUREA
Hazardous Waste Code:	D002
Waste Code Description:	CORROSIVE WASTE
Hazardous Waste Code:	P001
Waste Code Description:	2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%
Hazardous Waste Code:	U056
Waste Code Description:	BENZENE, HEXAHYDRO- (I) (OR) CYCLOHEXANE (I)

Hazardous Waste Code: U002
Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: U003
Waste Code Description: ACETONITRILE (I,T)

Hazardous Waste Code: P105
Waste Code Description: SODIUM AZIDE

Hazardous Waste Code: P098
Waste Code Description: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

Hazardous Waste Code: U404
Waste Code Description: ETHANAMINE, N,N-DIETHYL- (OR) TRIETHYLAMINE

Hazardous Waste Code: U220
Waste Code Description: BENZENE, METHYL- (OR) TOLUENE

Hazardous Waste Code: U213
Waste Code Description: FURAN, TETRAHYDRO-(I) (OR) TETRAHYDROFURAN (I)

Hazardous Waste Code: U236
Waste Code Description: 2,7-NAPHTHALENEDISULFONIC ACID,3,3'-[(3,3'-DIMETHYL[1,1'-BIPHENYL]-4,4'-DIYL)BIS(AZO)BIS[5-AMINO-4-HYDROXY]-, TETRASODIUM SALT (OR) TRYPAN BLUE

Hazardous Waste Code: WPCB
Waste Code Description: Washington State Dangerous PCB Waste containing polychlorinated biphenyls at concentrations of 2 parts per million or greater from specific sources: discarded transformers, capacitors or bushings containing (except when drained of all free flowing liquid) and the following wastes generated from the salvaging, rebuilding, or discarding of transformers, capacitors or bushings containing polychlorinated biphenyls (PCB) at concentrations of 2 parts per million or greater: Cooling and insulating fluids and cores, including core papers.

Hazardous Waste Code: WSC2
Waste Code Description: Washington State solid or semisolid corrosive Dangerous Waste with a pH less than or equal to 2, or greater than or equal to 12.5, based upon a specific testing method.

Hazardous Waste Code: WT01
Waste Code Description: Washington State Extremely Hazardous Toxic Waste with a toxic constituents concentration greater than or equal to 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D019
Waste Code Description: CARBON TETRACHLORIDE

Hazardous Waste Code: P012
Waste Code Description: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: U080
Waste Code Description: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

Hazardous Waste Code: U112
Waste Code Description: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

Hazardous Waste Code: U123
Waste Code Description: FORMIC ACID (C,T)

Hazardous Waste Code: U157
Waste Code Description: 3-METHYLCHOLANTHRENE (OR) BENZ[J]ACEANTHRYLENE, 1,2-DIHYDRO-3-METHYL-

Hazardous Waste Code: WP01
Waste Code Description: Washington State Extremely Hazardous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of Greater than 1.0%.

Hazardous Waste Code: WP02
Waste Code Description: Washington State Dangerous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of 0.01% to 1.0%.

Hazardous Waste Code: U196
Waste Code Description: PYRIDINE

Hazardous Waste Code: U187
Waste Code Description: ACETAMIDE, N-(4-ETHOXYPHENYL)- (OR) PHENACETIN

Hazardous Waste Code: U122
Waste Code Description: FORMALDEHYDE

Hazardous Waste Code: U103
Waste Code Description: DIMETHYL SULFATE (OR) SULFURIC ACID, DIMETHYL ESTER

Hazardous Waste Code: U077
Waste Code Description: ETHANE, 1,2-DICHLORO- (OR) ETHYLENE DICHLORIDE

Hazardous Waste Code: U044
Waste Code Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Hazardous Waste Code: U108
Waste Code Description: 1,4-DIETHYLENEOXIDE (OR) 1,4-DIOXANE

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20180129
Handler Name: CASCADIAN THERAPEUTICS SEATTLE
Source Type: Notification
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Waste Code Details

Hazardous Waste Code: D021
Waste Code Description: CHLOROBENZENE

Hazardous Waste Code: P043
Waste Code Description: DIISOPROPYLFLUOROPHOSPHATE (DFP) (OR) PHOSPHOROFLUORIDIC ACID, BIS(1-METHYLETHYL) ESTER

Hazardous Waste Code: U161
Waste Code Description: 4-METHYL-2-PENTANONE (I) (OR) METHYL ISOBUTYL KETONE (I) (OR) PENTANOL, 4-METHYL-

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D038
Waste Code Description: PYRIDINE

Hazardous Waste Code: P087
Waste Code Description: OSMIUM OXIDE OSO4, (T-4)- (OR) OSMIUM TETROXIDE

Hazardous Waste Code: U010
Waste Code Description: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A, 2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

Hazardous Waste Code: U154
Waste Code Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Hazardous Waste Code: U219
Waste Code Description: THIOUREA

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: U056
Waste Code Description: BENZENE, HEXAHYDRO- (I) (OR) CYCLOHEXANE (I)

Hazardous Waste Code: U002
Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: U003
Waste Code Description: ACETONITRILE (I,T)

Hazardous Waste Code: P105
Waste Code Description: SODIUM AZIDE

Hazardous Waste Code: P098
Waste Code Description: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

Hazardous Waste Code: U404
Waste Code Description: ETHANAMINE, N,N-DIETHYL- (OR) TRIETHYLAMINE

Hazardous Waste Code: U220
Waste Code Description: BENZENE, METHYL- (OR) TOLUENE

Hazardous Waste Code: U213
Waste Code Description: FURAN, TETRAHYDRO-(I) (OR) TETRAHYDROFURAN (I)

Hazardous Waste Code: U236
Waste Code Description: 2,7-NAPHTHALENEDISULFONIC ACID,3,3'-[(3,3'-DIMETHYL[1,1'-BIPHENYL]-4,4'-DIYL)BIS(AZO)BIS[5-AMINO-4-HYDROXY]-, TETRASODIUM SALT (OR) TRYPAN BLUE

Hazardous Waste Code: WPCB
Waste Code Description: Washington State Dangerous PCB Waste containing polychlorinated biphenyls at concentrations of 2 parts per million or greater from specific sources: discarded transformers, capacitors or bushings containing (except when drained of all free flowing liquid) and the following wastes generated from the salvaging, rebuilding, or discarding of transformers, capacitors or bushings containing polychlorinated biphenyls (PCB) at concentrations of 2 parts per million or greater: Cooling and insulating fluids and cores, including core papers.

Hazardous Waste Code: WSC2
Waste Code Description: Washington State solid or semisolid corrosive Dangerous Waste with a pH less than or equal to 2, or greater than or equal to 12.5, based upon a specific testing method.

Hazardous Waste Code: WT01
Waste Code Description: Washington State Extremely Hazardous Toxic Waste with a toxic constituents concentration greater than or equal to 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D019
Waste Code Description: CARBON TETRACHLORIDE

Hazardous Waste Code: P012
Waste Code Description: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: U080
Waste Code Description: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

Hazardous Waste Code: U112
Waste Code Description: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

Hazardous Waste Code: U123
Waste Code Description: FORMIC ACID (C,T)

Hazardous Waste Code: U157
Waste Code Description: 3-METHYLCHOLANTHRENE (OR) BENZ[J]ACEANTHRYLENE, 1,2-DIHYDRO-3-METHYL-

Hazardous Waste Code: WP01
Waste Code Description: Washington State Extremely Hazardous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of Greater than 1.0%.

Hazardous Waste Code: WP02
Waste Code Description: Washington State Dangerous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of 0.01% to 1.0%.

Hazardous Waste Code: U196
Waste Code Description: PYRIDINE

Hazardous Waste Code: U187
Waste Code Description: ACETAMIDE, N-(4-ETHOXYPHENYL)- (OR) PHENACETIN

Hazardous Waste Code: U122
Waste Code Description: FORMALDEHYDE

Hazardous Waste Code: U103
Waste Code Description: DIMETHYL SULFATE (OR) SULFURIC ACID, DIMETHYL ESTER

Hazardous Waste Code: U077
Waste Code Description: ETHANE, 1,2-DICHLORO- (OR) ETHYLENE DICHLORIDE

Hazardous Waste Code: U044
Waste Code Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Hazardous Waste Code: U108
Waste Code Description: 1,4-DIETHYLENEOXIDE (OR) 1,4-DIOXANE

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20180129
Handler Name: CASCADIAN THERAPEUTICS SEATTLE
Source Type: Annual/Biennial Report update with Notification
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Waste Code Details

Hazardous Waste Code: D021
Waste Code Description: CHLOROBENZENE

Hazardous Waste Code: P043
Waste Code Description: DIISOPROPYLFLUOROPHOSPHATE (DFP) (OR) PHOSPHOROFLUORIDIC ACID, BIS(1-METHYLETHYL) ESTER

Hazardous Waste Code: U161

Waste Code Description:	4-METHYL-2-PENTANONE (I) (OR) METHYL ISOBUTYL KETONE (I) (OR) PENTANOL, 4-METHYL-
Hazardous Waste Code:	D001
Waste Code Description:	IGNITABLE WASTE
Hazardous Waste Code:	D038
Waste Code Description:	PYRIDINE
Hazardous Waste Code:	P087
Waste Code Description:	OSMIUM OXIDE OSO4, (T-4)- (OR) OSMIUM TETROXIDE
Hazardous Waste Code:	U010
Waste Code Description:	AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A, 2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C
Hazardous Waste Code:	U154
Waste Code Description:	METHANOL (I) (OR) METHYL ALCOHOL (I)
Hazardous Waste Code:	U219
Waste Code Description:	THIOUREA
Hazardous Waste Code:	D002
Waste Code Description:	CORROSIVE WASTE
Hazardous Waste Code:	P001
Waste Code Description:	2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%
Hazardous Waste Code:	U056
Waste Code Description:	BENZENE, HEXAHYDRO- (I) (OR) CYCLOHEXANE (I)
Hazardous Waste Code:	D019
Waste Code Description:	CARBON TETRACHLORIDE
Hazardous Waste Code:	P012
Waste Code Description:	ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE
Hazardous Waste Code:	P075
Waste Code Description:	NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS
Hazardous Waste Code:	U080
Waste Code Description:	METHANE, DICHLORO- (OR) METHYLENE CHLORIDE
Hazardous Waste Code:	U112
Waste Code Description:	ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)
Hazardous Waste Code:	U123
Waste Code Description:	FORMIC ACID (C,T)
Hazardous Waste Code:	U157
Waste Code Description:	3-METHYLCHOLANTHRENE (OR) BENZ[J]ACEANTHRYLENE, 1,2-DIHYDRO-3-METHYL-
Hazardous Waste Code:	WP01
Waste Code Description:	Washington State Extremely Hazardous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of Greater than 1.0%.
Hazardous Waste Code:	WP02
Waste Code Description:	Washington State Dangerous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of 0.01% to 1.0%.
Hazardous Waste Code:	U108
Waste Code Description:	1,4-DIETHYLENEOXIDE (OR) 1,4-DIOXANE
Hazardous Waste Code:	P105
Waste Code Description:	SODIUM AZIDE
Hazardous Waste Code:	U003

Waste Code Description: ACETONITRILE (I,T)

Hazardous Waste Code: U002
Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: P098
Waste Code Description: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

Hazardous Waste Code: U213
Waste Code Description: FURAN, TETRAHYDRO-(I) (OR) TETRAHYDROFURAN (I)

Hazardous Waste Code: U404
Waste Code Description: ETHANAMINE, N,N-DIETHYL- (OR) TRIETHYLAMINE

Hazardous Waste Code: U220
Waste Code Description: BENZENE, METHYL- (OR) TOLUENE

Hazardous Waste Code: WSC2
Waste Code Description: Washington State solid or semisolid corrosive Dangerous Waste with a pH less than or equal to 2, or greater than or equal to 12.5, based upon a specific testing method.

Hazardous Waste Code: WT01
Waste Code Description: Washington State Extremely Hazardous Toxic Waste with a toxic constituents concentration greater than or equal to 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: U236
Waste Code Description: 2,7-NAPHTHALENEDISULFONIC ACID,3,3'-[(3,3'-DIMETHYL[1,1'-BIPHENYL]-4,4'-DIYL)BIS(AZO)BIS[5-AMINO-4-HYDROXY]-, TETRASODIUM SALT (OR) TRYPAN BLUE

Hazardous Waste Code: WPCB
Waste Code Description: Washington State Dangerous PCB Waste containing polychlorinated biphenyls at concentrations of 2 parts per million or greater from specific sources: discarded transformers, capacitors or bushings containing (except when drained of all free flowing liquid) and the following wastes generated from the salvaging, rebuilding, or discarding of transformers, capacitors or bushings containing polychlorinated biphenyls (PCB) at concentrations of 2 parts per million or greater: Cooling and insulating fluids and cores, including core papers.

Hazardous Waste Code: U196
Waste Code Description: PYRIDINE

Hazardous Waste Code: U187
Waste Code Description: ACETAMIDE, N-(4-ETHOXYPHENYL)- (OR) PHENACETIN

Hazardous Waste Code: U122
Waste Code Description: FORMALDEHYDE

Hazardous Waste Code: U103
Waste Code Description: DIMETHYL SULFATE (OR) SULFURIC ACID, DIMETHYL ESTER

Hazardous Waste Code: U077
Waste Code Description: ETHANE, 1,2-DICHLORO- (OR) ETHYLENE DICHLORIDE

Hazardous Waste Code: U044
Waste Code Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 20180228

Handler Name: CASCADIAN THERAPEUTICS SEATTLE
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20180227
Handler Name: CASCADIAN THERAPEUTICS SEATTLE
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: MARTIN SELIG
Date Became Current:
Date Ended Current:
Phone: 206-467-7600
Source Type: Notification
Street No:
Street 1: 1000 2ND AVENUE SUITE 1800
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98104

Owner/Operator Ind: Current Owner
Type: Private
Name: MARTIN SELIG
Date Became Current:
Date Ended Current:
Phone: 206-467-7600
Source Type: Annual/Biennial Report update with Notification
Street No:
Street 1: 1000 2ND AVENUE SUITE 1800
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98104

Owner/Operator Ind: Current Operator
Type: Private
Name: CASCADIAN THERAPEUTICS
Date Became Current:
Date Ended Current:
Phone: 206-801-2100
Source Type: Implementer
Street No:
Street 1: 2601 4TH AVE STE 500
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Owner
Type: Private
Name: SEILIG, MARTIN
Date Became Current:
Date Ended Current:
Phone: 206-467-7600
Source Type: Notification
Street No:
Street 1: 1000 2ND AVE STE 1800
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98104

Owner/Operator Ind: Current Operator
Type: Private
Name: CHRISTIANSON, GARY
Date Became Current:
Date Ended Current:
Phone: 206-801-2120
Source Type: Notification
Street No:
Street 1: 2601 4TH AVE STE 500
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Operator
Type: Private
Name: CASCADIAN THERAPEUTICS
Date Became Current:
Date Ended Current:
Phone: 206-801-2100
Source Type: Annual/Biennial Report update with Notification
Street No:
Street 1: 2601 4TH AVE STE 500
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Owner
Type: Private
Name: CASCADIAN THERAPEUTICS
Street No:
Street 1: 2601 4TH AVE STE 500
Street 2:

Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-801-2100	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2601 4TH AVE STE 500
Name:	CASCADIAN THERAPEUTICS	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-801-2100	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2601 4TH AVE STE 500
Name:	CASCADIAN THERAPEUTICS	**Street 2:**	
Date Became Current:	20111201	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-801-2100	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	1000 2ND AVENUE SUITE 1800
Name:	MARTIN SELIG	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-467-7600	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98104
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2601 4TH AVE STE 500
Name:	CASCADIAN THERAPEUTICS	**Street 2:**	
Date Became Current:	20111201	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-801-2100	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121

Historical Handler Details

Receive Dt:	20180129
Generator Code Description:	Large Quantity Generator
Handler Name:	CASCADIAN THERAPEUTICS SEATTLE
Receive Dt:	20180227
Generator Code Description:	Not a Generator, Verified
Handler Name:	CASCADIAN THERAPEUTICS SEATTLE
Receive Dt:	20171010
Generator Code Description:	Large Quantity Generator
Handler Name:	CASCADIAN THERAPEUTICS SEATTLE
Receive Dt:	20180129
Generator Code Description:	Large Quantity Generator
Handler Name:	CASCADIAN THERAPEUTICS SEATTLE

---

34 | ***8 of 8*** | ***ENE*** | ***0.12 / 629.45*** | ***121.78 / 16*** | ***2601 FOURTH AVE SEATTLE WA*** | ***ERTS***

Incident ID:	426801	**Latitude:**	
Incident Date:		**Longitude:**	
County:	KING		
Location:			

Initial Report Details

Initial Report Substance Name:	Gasoline
Initial Report Subst Catego:	Oil
Initial Report Subst Quanti:	
Initial Report Substance Unit:	
Initial Report Medium Name:	Soil
Initial Report Medium Category:	Ground
Initial Report Cause Category:	Human error
Initial Report Cause Name:	Unknown
Initial Report Source Name:	Undetermined
Initial Report Source Category:	Historical
Initial Report Activity Name:	Unknown
Initial Report Comment Desc:	PETE PARKER WITH MARTIN SELIG MAY BE AN ALTERNATE

Follow up Details

ERTS Follow up No:	13920
Follow up Substance Name:	Gasoline
Follow up Substance Quantity:	
Follow up Subst Unit of Meas:	
Follow up Cause Name:	Unknown
Follow up Medium Name:	Soil
Follow up Source Nname:	Undetermined
Follow up Activity Name:	Unknown

Potential Details

Pot Resp Party First Name:	JAY
Pot Resp Prty Last Name:	REEVES
Potentially Resp Party Org:	MARTIN SELIG REAL ESTATE

Follow up Comments

Follow up Comment:

ERTS Number 426801 - IRAP REVIEW DETERMINED FURTHER ACTION TO BE NECESSARY AT THE SITE BECAUSE THE EXTENT OF CONTAMINATION HAS NOT BEEN DETERMINED.

Follow up Comment:

ERTS Number 426801 - Historic Investigator Contact Information - FirstName: BARBARA MiddleName: LastName: TREJO OrganizationName: TOXICS CLEANUP WorkLocation: NWRO

Follow up Comment:

ERTS Number 426801 - Historic Referral Contact Information - ReferralDate: 1996-06-05 FirstName: MiddleName: LastName: GALLAGHER Email: PhoneNumber: OrganizationName: TOXICS CLEANUP WorkLocation: NWRO

Initial Comments

Initial Report Comment:

ERTS Number 426801 - PETE PARKER WITH MARTIN SELIG MAY BE AN ALTERNATE CONTACT. REPORTS SUBMITTED FOR REVIEW THROUGH IRAP.

Initial Report Comment:

ERTS Number 426801 - PETE PARKER WITH MARTIN SELIG MAY BE AN ALTERNATE CONTACT. REPORTS SUBMITTED FOR REVIEW THROUGH IRAP.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
35	1 of 2	SSE	0.12 / 637.31	83.69 / -22	Cottage Properties VINE ST SEATTLE WA 98121	CSCSL NFA

Fac Site ID:	55774658	**Fac Site ID (OD):**	55774658
Cleanup Site ID:	4828	**Cleanup SiteID(OD):**	4828
Site Status:	NFA	**Site Status (OD):**	No Further Action
NFA Date:	09/17/2008	**Rank (OD):**	
Responsible Unit:	Northwest	**Has Env Coven (OD):**	
Has Insti Control:		**Respon Unit (OD):**	Northwest
Region:	Northwest	**Region (OD):**	Northwest
County:	King	**County (OD):**	King
Latitude:	47.614805	**Latitude (OD):**	47.614805
Longitude:	-122.349694	**Longitude (OD):**	-122.349694

NFA Reason: Site Hazard Assessment
Alternate Site Names: SKYWAY LUGGAGE PROPERTY
Location (OD): ""
(47.614805, -122.349694)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

NFA Contaminants Detail(s)

Contaminant Name: Metals Priority Pollutants
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Metals Priority Pollutants
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
35	2 of 2	SSE	0.12 / 637.31	83.69 / -22	COTTAGE PROPERTIES VINE ST SEATTLE WA 98121	ALL SITES

Facility/Site ID: 55774658
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: COTTAGE PROPERTIES
Interaction ID: 51734
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: INDPNDNT
Interaction Desc: Independent Cleanup
Interact Start Dt: 03-Dec-1999
Interact End Dt: 17-Sep-2008
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: Unknown **Location Verified:** N

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Horizont 1:	NAD83	**GIS latitude:**	47.614805
Horizont 2:	Address	**GIS longitude:**	-122.349694

36 *1 of 2* **SSW** *0.12 / 651.76* *47.94 / -58* **CEDAR DEVELOPMENT LLC** **2627 WESTERN AVE** **Seattle WA 98121** **UST**

UST ID:	542217	**Region:**	Northwest
Facility Site ID:	96289861	**County:**	King
Site Active:	No	**Latitude:**	47.614825
Responsible Unit:	Northwest	**Longitude:**	-122.350861
Active Tag:			
Alternate Site Names:			

Tank Detail(s)

Tank Name:	1	**Tank Construction:**	
Status Date:	07/14/2000	**Tank Capacity:**	
Install Date:	01/01/1900	**Actual Capacity:**	500
Upgrade Date:		**Pipe Install Date:**	
Perm Closure Date:		**Endorsement Expire:**	
Tank Status:	Removed		
Tank Material:			
Tank Corrosion Protection:			
Tank Manifold:			
Tank Release Detection:			
Tank Tightness Test:			
Tank Spill Prevention:			
Tank Overfill Prevention:			
Pipe Material:			
Pipe Construction:			
Pipe Corrosion Protection:			
Tank SFC:			
Dispenser SFC:			
Primary Pipe Release Detection:			
Secondary Pipe Rel Detect:			
Pipe Pumping System:			
Turbine Sump Construction:			

Compartments

Compartment No:	1
Compart Capacity:	500
Stored Substance:	Unleaded Gasoline
Used Substance:	

36 *2 of 2* **SSW** *0.12 / 651.76* *47.94 / -58* **CEDAR DEVELOPMENT LLC** **2627 WESTERN AVE** **SEATTLE WA 98121** **ALL SITES**

Facility/Site ID:	96289861
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	542217
Facility Alternate:	
Interaction ID:	74729
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	UST
Interaction Desc:	Underground Storage Tank

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Interact Start Dt: 06-Sep-2000
Interact End Dt: 07-Sep-2000
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Facility Location Detail

Horizontal: 10ft
Horizont 1: NAD83
Horizont 2: Address
Location Verified: N
GIS latitude: 47.614825
GIS longitude: -122.350861

---

37 | ***1 of 1*** | ***ESE*** | ***0.13 / 661.01*** | ***109.94 / 4*** | ***2530 2ND AVE Seattle WA 98119*** | ***UST SEATTLE***

Permit No: 3-34303
Date Issued: 09/21/2000
Fill Material: No Fill
Tank Size: 675
Tank Age: 35+
Tank Content: #2 HEATING FUEL
Date Decommissioned: 09/26/2000
Type Decommissioned: Abandonment in Place

---

38 | ***1 of 2*** | ***E*** | ***0.13 / 661.67*** | ***117.47 / 12*** | ***WITS AIR FREIGHT 333 VINE ST SEATTLE WA 98121*** | ***RCRA NON GEN***

EPA Handler ID: WAD041331935
Gen Status Universe: No Report
Contact Name: WITS INC DBA WI WITS INC DBA WI
Contact Address: PO BOX 3805 , , SEATTLE , WA, 98124-3805 , US
Contact Phone No and Ext: 000-000-0000
Contact Email:
Contact Country: US
County Name: KING
EPA Region: 10
Land Type: Private
Receive Date: 19921203
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	19921203
Handler Name:	WITS AIR FREIGHT
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19921203
Handler Name:	WITS AIR FREIGHT
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	333 VINE ST
Name:	WITS INC DBA WITS AIR FREIGHT	***Street 2:***	
Date Became Current:	19960502	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	000-000-0000	***Country:***	US
Source Type:	Implementer	***Zip Code:***	98121

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	333 VINE ST
Name:	WITS INC DBA WI W	***Street 2:***	
Date Became Current:	19960502	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	000-000-0000	***Country:***	US
Source Type:	Implementer	***Zip Code:***	98121-0000

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	333 VINE ST
Name:	WITS AIR FREIGHT	***Street 2:***	
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	000-000-0000	***Country:***	US
Source Type:	Implementer	***Zip Code:***	98121

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	333 VINE ST
Name:	WITS AIR FREIGHT	***Street 2:***	
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	000-000-0000	***Country:***	US
Source Type:	Implementer	***Zip Code:***	98121

Historical Handler Details

Receive Dt:	19921203
Generator Code Description:	Not a Generator, Verified
Handler Name:	WITS AIR FREIGHT

38	*2 of 2*	*E*	*0.13 / 661.67*	*117.47 / 12*	***Wits Air Freight*** ***333 VINE ST*** ***SEATTLE WA 98121***	***ALL SITES***

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility/Site ID: 62845582
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAD041331935
Facility Alternate:
Interaction ID: 55430
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 07-Aug-1980
Interact End Dt: 31-Dec-1991
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6167364014
GIS longitude: -122.347552712

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
39	1 of 2	ESE	0.13 / 674.54	109.54 / 4	RITE AID 6977 DBA BARTELL DRUGS 077 2506 2ND AVE SEATTLE WA 98121	RCRA VSQG

EPA Handler ID: WAH000058410
Gen Status Universe: VSG
Contact Name: JOSEPH CHEST
Contact Address: PO BOX 3165 , , HARRISBURG , PA, 17105 , US
Contact Phone No and Ext: 717-975-8643
Contact Email: EHS@RITEAID.COM
Contact Country: US
County Name: KING
EPA Region: 10
Land Type: Private
Receive Date: 20220104
Location Latitude: 47.61545
Location Longitude: -122.34793

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No

Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20220104
Handler Name: RITE AID 6977 DBA BARTELL DRUGS 077
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: U002
Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: U117
Waste Code Description: ETHANE, 1,1'-OXYBIS-(I) (OR) ETHYL ETHER (I)

Hazardous Waste Code: U058
Waste Code Description: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

Hazardous Waste Code: U122
Waste Code Description: FORMALDEHYDE

Hazardous Waste Code: U044
Waste Code Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Hazardous Waste Code: P042
Waste Code Description: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

Hazardous Waste Code: D016
Waste Code Description: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D026
Waste Code Description: CRESOL

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: WP01
Waste Code Description: Washington State Extremely Hazardous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of Greater than 1.0%.

Hazardous Waste Code: WP02
Waste Code Description: Washington State Dangerous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of 0.01% to 1.0%.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: U154
Waste Code Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Hazardous Waste Code: U279
Waste Code Description: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: U035
Waste Code Description: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: U240
Waste Code Description: 2,4-D, SALTS & ESTERS (OR) ACETIC ACID, (2,4-DICHLOROPHENOXY)-, SALTS & ESTERS (OR) DICHLOROPHENOXYACETIC ACID 2,4-D

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20210119
Handler Name: RITE AID 6977 DBA BARTELL DRUGS 077
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: U002
Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: U117
Waste Code Description: ETHANE, 1,1'-OXYBIS-(I) (OR) ETHYL ETHER (I)

Hazardous Waste Code: U058
Waste Code Description: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

Hazardous Waste Code: P042
Waste Code Description: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

Hazardous Waste Code: D016
Waste Code Description: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

Hazardous Waste Code: D026
Waste Code Description: CRESOL

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: U112
Waste Code Description: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

Hazardous Waste Code: WP01
Waste Code Description: Washington State Extremely Hazardous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of Greater than 1.0%.

Hazardous Waste Code: WP02
Waste Code Description: Washington State Dangerous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of 0.01% to 1.0%.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: U154
Waste Code Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Hazardous Waste Code: U279
Waste Code Description: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: U035
Waste Code Description: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: U240
Waste Code Description: 2,4-D, SALTS & ESTERS (OR) ACETIC ACID, (2,4-DICHLOROPHENOXY)-, SALTS & ESTERS (OR) DICHLOROPHENOXYACETIC ACID 2,4-D

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: THE BARTELL DRUG CO
Date Became Current: 20201218
Date Ended Current:
Phone: 717-975-8643
Source Type: Notification
Street No:
Street 1: PO BOX 3165
Street 2:
City: HARRISBURG
State: WA
Country: US
Zip Code: 17105

Owner/Operator Ind: Current Owner
Type: Private
Street No:
Street 1: 4040 WILSON BLVD STE 1000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Name:	AVALON 210 WALL LLC	**Street 2:**	
Date Became Current:	20201218	**City:**	ARLINGTON
Date Ended Current:		**State:**	VA
Phone:	206-237-5363	**Country:**	US
Source Type:	Notification	**Zip Code:**	22203
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 3165
Name:	RITE AID CORP	**Street 2:**	
Date Became Current:	20201218	**City:**	HARRISBURG
Date Ended Current:		**State:**	WA
Phone:	717-975-8643	**Country:**	US
Source Type:	Notification	**Zip Code:**	17105

Historical Handler Details

Receive Dt:	20210119
Generator Code Description:	Very Small Quantity Generator
Handler Name:	RITE AID 6977 DBA BARTELL DRUGS 077

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
39	2 of 2	ESE	0.13 / 674.54	109.54 / 4	Rite Aid 6977 DBA Bartell Drugs 077 2506 2nd Ave Seattle WA 98121	ALL SITES

Facility/Site ID:	68309
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAH000058410
Facility Alternate:	Rite Aid 6977 DBA Bartell Drugs 077
Interaction ID:	137734
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	01-Jan-2021
Interact End Dt:	
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	
Horizont 1:	NAD83	**GIS latitude:**	47.61545
Horizont 2:	Address	**GIS longitude:**	-122.34793

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
40	1 of 1	WNW	0.13 / 679.50	92.70 / -13	FRANK JAMES AUTO & PEOPLES VOLKSWAGEN 2900 2922 1ST AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID:	9468585
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	10214

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility Alternate:
Interaction ID: 24660
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 29-Feb-2000
Interact End Dt: 03-May-2000
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83
Horizont 2: Address
Location Verified: N
GIS latitude: 47.61686
GIS longitude: -122.353768

---

41 | 1 of 5 | SSE | 0.13 / 689.65 | 86.81 / -19 | **Sailors Union of the Pacific Building**
2505 1ST AVE
SEATTLE WA 98121 | CSCSL NFA

Fac Site ID: 42839734
Cleanup Site ID: 9147
Site Status: NFA
NFA Date: 10/03/2011
Responsible Unit: Northwest
Has Insti Control:
Region: Northwest
County: King
Latitude: 47.61467
Longitude: -122.350106
Fac Site ID (OD): 42839734
Cleanup SiteID(OD): 9147
Site Status (OD): No Further Action
Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
Region (OD): Northwest
County (OD): King
Latitude (OD): 47.61467
Longitude (OD): -122.350106
NFA Reason: Initial Investigation
Alternate Site Names: SAILORS UNION OF THE PACIFIC BLDG
Location (OD): ""
(47.61467, -122.350106)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

NFA Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

41 | 2 of 5 | SSE | 0.13 / 689.65 | 86.81 / -19 | **SAILORS UNION OF THE PACIFIC BLDG**
2505 1ST AVE
Seattle WA 98121 | UST

UST ID: 319027
Facility Site ID: 42839734
Region: Northwest
County: King

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Active: No
Responsible Unit: Northwest
Active Tag:
Alternate Site Names: Sailors Union of the Pacific Building
Latitude: 47.61467
Longitude: -122.350106

Tank Detail(s)

Tank Name: 1
Status Date: 04/12/2001
Install Date: 01/01/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Closed in Place
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:
Tank Construction:
Tank Capacity:
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Bunker C
Used Substance:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
41	3 of 5	SSE	0.13 / 689.65	86.81 / -19	SAILORS UNION OF THE PACIFIC BLDG 2505 1ST AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID: 42839734
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 319027
Facility Alternate:
Interaction ID: 44061
Interaction Status: A
Interac Status Desc: Active
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 15-Jul-1999
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: 319027
Facility Alternate:

Interaction ID:	44060
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	LUST
Interaction Desc:	LUST Facility
Interact Start Dt:	10-Jul-1995
Interact End Dt:	02-Nov-1995
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Facility Location Detail

Horizontal:	40ft	***Location Verified:***	N
Horizont 1:	NAD83	***GIS latitude:***	47.61467
Horizont 2:	Address	***GIS longitude:***	-122.350106

---

41 | ***4 of 5*** | ***SSE*** | ***0.13 / 689.65*** | ***86.81 / -19*** | ***SAILOR'S UNION OF THE PACIFIC BLDG 2505 1ST AVE SEATTLE WA 98121*** | ***ICR***

Cleanup Site ID:	9147	***WRIA ID:***	8
Facility Site ID:	42839734	***Is NFA Site:***	Yes
Site Status:	No Further Action Required	***Responsible Unit:***	Northwest
Statute:	MTCA	***Latitude:***	47.614669999999997
Rank:		***Longitude:***	-122.350106
Rank Description:		***Legislative District:***	36
Has Env Covenant:		***Congr District:***	7
Is Brownfiled Site:		***County Name:***	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:	3971	***Start Date:***	1995-07-10
VCP Prj No:		***End Date:***	1995-07-10
Activity Name:	LUST - Notification	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	1995-07-10
Activity Name:	Site Discovery/Release Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	2011-08-08
Activity Name:	Initial Investigation / Federal Preliminary Assessment	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	Ecology w/ Contractor
County Name:	King	***Project Manager:***	Olsen, Russ
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	2011-10-03
Activity Name:	Site Status Changed to NFA	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	Olsen, Russ
Applies to:	CleanupSite		

Applies to Description:

Related ID:	3971	***Start Date:***	1995-06-27
VCP Prj No:		***End Date:***	1995-07-10
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Media Contaminants

Contaminant Type:	Petroleum-Other	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

---

41 | ***5 of 5*** | ***SSE*** | ***0.13 / 689.65*** | ***86.81 / -19*** | ***Sailors Union of the Pacific Building, 2505 1ST AVE, SEATTLE WA 98121*** | ***LUST***

Facility Site ID:	42839734	***County:***	King
Cleanup Site ID:	9147	***Latitude:***	47.61467
Responsible Unit:	Northwest	***Longitude:***	-122.350106
Region:	Northwest		
Alternate Site Names:	SAILORS UNION OF THE PACIFIC BLDG		

Tank Detail(s)

UST ID:	319027	***Status Date:***	10/03/2011
LUST ID:	3971	***Release Date:***	07/10/1995
LUST Status:	LUST - NFA		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Other	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		

---

42 | ***1 of 2*** | ***NNE*** | ***0.14 / 721.11*** | ***131.80 / 26*** | ***DEAN STRALEY'S BP, 351 BROAD ST, Seattle WA 98109*** | ***UST***

UST ID:	8217	***Region:***	Northwest
Facility Site ID:	60652649	***County:***	King
Site Active:	Yes	***Latitude:***	47.6187647564459
Responsible Unit:	Northwest	***Longitude:***	-122.349769010258
Active Tag:	A3657		
Alternate Site Names:	DEAN STRALEYS BP		

Tank Detail(s)

Tank Name:	1	***Tank Construction:***	Single Wall Tank
Status Date:	08/06/1996	***Tank Capacity:***	5,000 to 9,999 Gallons
Install Date:	07/01/1984	***Actual Capacity:***	6000
Upgrade Date:	09/01/1998	***Pipe Install Date:***	
Perm Closure Date:		***Endorsement Expire:***	08/31/2023
Tank Status:	Operational		

Tank Material: Dielectric Coated Steel
Tank Corrosion Protection: Sacrificial Anode
Tank Manifold:
Tank Release Detection: Automatic Tank Gauging
Tank Tightness Test:
Tank Spill Prevention: Single Wall Spill Bucket
Tank Overfill Prevention: Overfill Alarm
Pipe Material: Fiberglass
Pipe Construction: Single Wall Pipe
Pipe Corrosion Protection: Corrosion Resistant
Tank SFC:
Dispenser SFC: Single Wall Sump
Primary Pipe Release Detection: Automatic Line Leak Detector (ALLD)
Secondary Pipe Rel Detect: Annual Line Tightness Test (LTT)
Pipe Pumping System: Pressurized System
Turbine Sump Construction:

Compartments

Compartment No: 1
Compart Capacity: 6000
Stored Substance: Unleaded Gasoline
Used Substance: Motor Fuel for Vehicles

Tank Detail(s)

Tank Name: 3
Status Date: 08/06/1996
Install Date: 07/01/1984
Upgrade Date: 09/01/1998
Perm Closure Date:
Tank Status: Operational
Tank Material: Dielectric Coated Steel
Tank Corrosion Protection: Sacrificial Anode
Tank Manifold:
Tank Release Detection: Automatic Tank Gauging
Tank Tightness Test:
Tank Spill Prevention: Single Wall Spill Bucket
Tank Overfill Prevention: Overfill Alarm
Pipe Material: Fiberglass
Pipe Construction: Single Wall Pipe
Pipe Corrosion Protection: Corrosion Resistant
Tank SFC:
Dispenser SFC: Single Wall Sump
Primary Pipe Release Detection: Automatic Line Leak Detector (ALLD)
Secondary Pipe Rel Detect: Annual Line Tightness Test (LTT)
Pipe Pumping System: Pressurized System
Turbine Sump Construction:

Tank Construction: Single Wall Tank
Tank Capacity: 10,000 to 19,999 Gallons
Actual Capacity: 10000
Pipe Install Date:
Endorsement Expire: 08/31/2023

Compartments

Compartment No: 1
Compart Capacity: 10000
Stored Substance: Unleaded Gasoline
Used Substance: Motor Fuel for Vehicles

Tank Detail(s)

Tank Name: 4
Status Date: 08/06/1996
Install Date: 07/01/1984
Upgrade Date: 09/01/1998

Tank Construction: Single Wall Tank
Tank Capacity: 5,000 to 9,999 Gallons
Actual Capacity: 6000
Pipe Install Date:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Perm Closure Date:
Endorsement Expire: 08/31/2023
Tank Status: Operational
Tank Material: Dielectric Coated Steel
Tank Corrosion Protection: Sacrificial Anode
Tank Manifold:
Tank Release Detection: Automatic Tank Gauging
Tank Tightness Test:
Tank Spill Prevention: Single Wall Spill Bucket
Tank Overfill Prevention: Overfill Alarm
Pipe Material: Fiberglass
Pipe Construction: Single Wall Pipe
Pipe Corrosion Protection: Corrosion Resistant
Tank SFC:
Dispenser SFC: Single Wall Sump
Primary Pipe Release Detection: Automatic Line Leak Detector (ALLD)
Secondary Pipe Rel Detect: Annual Line Tightness Test (LTT)
Pipe Pumping System: Pressurized System
Turbine Sump Construction:

Compartments

Compartment No: 1
Compart Capacity: 6000
Stored Substance: Diesel
Used Substance: Motor Fuel for Vehicles

Tank Detail(s)

Tank Name: 2
Tank Construction: Single Wall Tank
Status Date: 08/06/1996
Tank Capacity: 10,000 to 19,999 Gallons
Install Date: 07/01/1984
Actual Capacity: 10000
Upgrade Date: 09/01/1998
Pipe Install Date:
Perm Closure Date:
Endorsement Expire: 08/31/2023
Tank Status: Operational
Tank Material: Dielectric Coated Steel
Tank Corrosion Protection: Sacrificial Anode
Tank Manifold:
Tank Release Detection: Automatic Tank Gauging
Tank Tightness Test:
Tank Spill Prevention: Single Wall Spill Bucket
Tank Overfill Prevention: Overfill Alarm
Pipe Material: Fiberglass
Pipe Construction: Single Wall Pipe
Pipe Corrosion Protection: Corrosion Resistant
Tank SFC:
Dispenser SFC: Single Wall Sump
Primary Pipe Release Detection: Automatic Line Leak Detector (ALLD)
Secondary Pipe Rel Detect: Annual Line Tightness Test (LTT)
Pipe Pumping System: Pressurized System
Turbine Sump Construction:

Compartments

Compartment No: 1
Compart Capacity: 10000
Stored Substance: Unleaded Gasoline
Used Substance: Motor Fuel for Vehicles

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
42	2 of 2	NNE	0.14 / 721.11	131.80 / 26	DEAN STRALEYS BP 351 BROAD ST SEATTLE WA 98109	ALL SITES

Facility/Site ID: 60652649

Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 8217
Facility Alternate:
Interaction ID: 54092
Interaction Status: A
Interac Status Desc: Active
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 07-Nov-1985
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID:
Facility Alternate:
Interaction ID: 54094
Interaction Status: A
Interac Status Desc: Active
Interaction Type: ENFORFNL
Interaction Desc: Enforcement Final
Interact Start Dt: 02-May-2008
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: DMS
Database Name Desc: Docket Management System

Program ID: CRK000025100
Facility Alternate:
Interaction ID: 54093
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: TIER2
Interaction Desc: Emergency/Haz Chem Rpt TIER2
Interact Start Dt: 01-Jan-1753
Interact End Dt: 01-Mar-1991
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: EPCRA
Database Name Desc: Emergency Planning & Community Right-to-Know Act

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6187647564
GIS longitude: -122.34976901

---

43 | ***1 of 6*** | ***SW*** | ***0.14 / 723.90*** | ***38.83 / -67*** | ***NORTHWEST PROTECTIVE SERVICE***
2700 ELLIOTT AVE
SEATTLE WA 98121 | ***CSCSL NFA***

Fac Site ID: 77333528
Cleanup Site ID: 10478
Site Status: NFA
NFA Date: 10/03/2011
Responsible Unit: Northwest
Has Insti Control:
Region: Northwest
County: King
Fac Site ID (OD): 77333528
Cleanup SiteID(OD): 10478
Site Status (OD): No Further Action
Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
Region (OD): Northwest
County (OD): King

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Latitude: 47.6146 **Latitude (OD):** 47.6146
Longitude: -122.35235 **Longitude (OD):** -122.35235
NFA Reason: Initial Investigation
Alternate Site Names: Northwest Protective Service Inc
Location (OD): ""
(47.6146, -122.35235)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

NFA Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Remediated-Below

43	2 of 6	SW	0.14 / 723.90	38.83 / -67	NORTHWEST PROTECTIVE SERVICE INC 2700 ELLIOTT AVE Seattle WA 98121	UST

UST ID: 1163 **Region:** Northwest
Facility Site ID: 77333528 **County:** King
Site Active: No **Latitude:** 47.6146
Responsible Unit: Northwest **Longitude:** -122.35235
Active Tag:
Alternate Site Names: NORTHWEST PROTECTIVE SERVICE

Tank Detail(s)

Tank Name: 1 **Tank Construction:**
Status Date: 08/06/1996 **Tank Capacity:** 111 TO 1,100 Gallons

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Steel
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material: Steel
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Unleaded Gasoline
Used Substance:

Tank Detail(s)

Tank Name: 2
Status Date: 08/06/1996
Install Date: 01/01/1978
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material:
Tank Corrosion Protection: None
Tank Manifold:
Tank Release Detection: Weekly Manual Gauging
Tank Tightness Test:
Tank Spill Prevention: None
Tank Overfill Prevention: None
Pipe Material:
Pipe Construction: Other
Pipe Corrosion Protection: None
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection: Other
Secondary Pipe Rel Detect:
Pipe Pumping System: Other
Turbine Sump Construction:
Tank Construction: Other
Tank Capacity:
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Unleaded Gasoline
Used Substance: Motor Fuel for Vehicles

43	*3 of 6*	*SW*	*0.14 / 723.90*	*38.83 / -67*	***Northwest Protective Service Inc*** ***2700 ELLIOTT AVE***	***ALL SITES***

Facility/Site ID: 77333528
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAR000009753
Facility Alternate:
Interaction ID: 63925
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 24-Jun-1996
Interact End Dt: 31-Dec-1997
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAR000009753
Facility Alternate: Belltown Development Partners II LLC
Interaction ID: 101700
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 23-May-2012
Interact End Dt: 31-Dec-2012
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: 1163
Facility Alternate:
Interaction ID: 63926
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 20-Mar-2000
Interact End Dt: 21-Mar-2000
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: 1163
Facility Alternate:
Interaction ID: 63924
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: LUST
Interaction Desc: LUST Facility
Interact Start Dt: 06-Jan-1993
Interact End Dt: 24-Dec-1998
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	
Horizont 1:	NAD83	**GIS latitude:**	47.6146
Horizont 2:	Unknown	**GIS longitude:**	-122.35235

43 | **4 of 6** | **SW** | **0.14 / 723.90** | **38.83 / -67** | **NORTHWEST PROTECTIVE SERVICE**
2700 ELLIOTT AVE
SEATTLE WA 98121 | **ICR**

Cleanup Site ID:	10478	**WRIA ID:**	8
Facility Site ID:	77333528	**Is NFA Site:**	Yes
Site Status:	No Further Action Required	**Responsible Unit:**	Northwest
Statute:	MTCA	**Latitude:**	47.614600000000003
Rank:		**Longitude:**	-122.35235
Rank Description:		**Legislative District:**	36
Has Env Covenant:		**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	1993-01-06
Activity Name:	Site Discovery/Release Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2011-10-03
Activity Name:	Site Status Changed to NFA	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Olsen, Russ
Applies to:	CleanupSite		
Applies to Description:			

Related ID:	2512	**Start Date:**	1993-01-06
VCP Prj No:		**End Date:**	1993-01-06
Activity Name:	LUST - Notification	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2011-08-08
Activity Name:	Initial Investigation / Federal Preliminary Assessment	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	Ecology w/ Contractor
County Name:	King	**Project Manager:**	Olsen, Russ
Applies to:	CleanupSite		
Applies to Description:			

Related ID:	2512	**Start Date:**	1998-12-16
VCP Prj No:		**End Date:**	1998-12-24
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2512	**Start Date:**	1993-03-30
VCP Prj No:		**End Date:**	1993-03-30
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	

Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Media Contaminants

Contaminant Type:	Petroleum-Other	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	RB	***Bedrock Desc.:***	
Soil Desc.:	Remediated-Below Cleanup Level	***County Name:***	King

Contaminant Type:	Benzene	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	RB	***Bedrock Desc.:***	
Soil Desc.:	Remediated-Below Cleanup Level	***County Name:***	King

Contaminant Type:	Petroleum-Gasoline	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	RB	***Bedrock Desc.:***	
Soil Desc.:	Remediated-Below Cleanup Level	***County Name:***	King

---

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
43	5 of 6	SW	0.14 / 723.90	38.83 / -67	BELLTOWN DEVELOPMENT PARTNERS II LLC 2700 ELLIOTT AVE SEATTLE WA 98121	RCRA NON GEN

EPA Handler ID: WAR000009753
Gen Status Universe: No Report
Contact Name: SCOTT BEVAN
Contact Address: 2505 2ND AVE , STE 520 , SEATTLE , WA, 98121 , US
Contact Phone No and Ext: 206-529-3900
Contact Email: SBEVAN@THESCHUSTERGROUP.COM
Contact Country: US
County Name: KING
EPA Region: 10
Land Type: Private
Receive Date: 20130109
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No

Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19970127
Handler Name: NORTHWEST PROTECTIVE SERVICE INC
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 6
Receive Date: 20120523
Handler Name: BELLTOWN DEVELOPMENT PARTNERS II LLC
Source Type: Notification
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Handler Details

Sequence No: 8
Receive Date: 20130109
Handler Name: BELLTOWN DEVELOPMENT PARTNERS II LLC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 19971226
Handler Name: NORTHWEST PROTECTIVE SERVICE INC
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20120523
Handler Name: BELLTOWN DEVELOPMENT PARTNERS II LLC
Source Type: Implementer
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19980518
Handler Name: NORTHWEST PROTECTIVE SERVICE INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19960624
Handler Name: NORTHWEST PROTECTIVE SERVICE INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 7
Receive Date: 20130108
Handler Name: BELLTOWN DEVELOPMENT PARTNERS II LLC
Source Type: Notification
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 19980519
Handler Name: NORTHWEST PROTECTIVE SERVICE INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 19980518
Handler Name: NORTHWEST PROTECTIVE SERVICE INC
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: NORTHWEST PROTECTIVE SERVICE INC
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 2700 ELLIOTT AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Owner
Street No:

Type:	Private	**Street 1:**	2700 ELLIOTT AVE
Name:	NORTHWEST PROTECTIVE SVC INC	**Street 2:**	
Date Became Current:	19961115	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-448-4040	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2505 2ND AVE
Name:	BELLTOWN DEVELOPMENT PARTNERS II LLC	**Street 2:**	STE 520
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-529-3900	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2505 2ND AVE
Name:	BELLTOWN DEVELOPMENT PARTNERS II LLC	**Street 2:**	STE 520
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-529-3900	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2700 ELLIOTT AVE
Name:	NORTHWEST PROTECTIVE SVC INC	**Street 2:**	
Date Became Current:	19960624	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-448-4040	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2505 2ND AVE
Name:	BELLTOWN DEVELOPMENT PARTNERS II LLC	**Street 2:**	STE 520
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-529-3900	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2700 ELLIOTT AVE
Name:	NORTHWEST PROTE N	**Street 2:**	
Date Became Current:	19961115	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-448-4040	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121-1189
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2700 ELLIOTT AVE
Name:	NORTHWEST PROTECTIVE SVC INC	**Street 2:**	
Date Became Current:	19961115	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-448-4040	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2700 ELLIOTT AVE
Name:	NORTHWEST PROTECTIVE SVC INC	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-448-4040	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2700 ELLIOTT AVE
Name:	NORTHWEST PROTECTIVE SVC INC	**Street 2:**	

Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-448-4040	***Country:***	US
Source Type:	Notification	***Zip Code:***	98121
Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	2700 ELLIOTT AVE
Name:	NORTHWEST PROTE N	***Street 2:***	
Date Became Current:	19961115	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-448-4040	***Country:***	US
Source Type:	Implementer	***Zip Code:***	98121-1189
Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	2700 ELLIOTT AVE
Name:	NORTHWEST PROTECTIVE SERVICE INC	***Street 2:***	
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	000-000-0000	***Country:***	US
Source Type:	Notification	***Zip Code:***	98121
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	2505 2ND AVE
Name:	BELLTOWN DEVELOPMENT PARTNERS II LLC	***Street 2:***	STE 520
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-529-3900	***Country:***	US
Source Type:	Implementer	***Zip Code:***	98121
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	2700 ELLIOTT AVE
Name:	NORTHWEST PROTECTIVE SVC INC	***Street 2:***	
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-448-4040	***Country:***	US
Source Type:	Implementer	***Zip Code:***	98121
Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	2700 ELLIOTT AVE
Name:	NORTHWEST PROTECTIVE SVC INC	***Street 2:***	
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-448-4040	***Country:***	US
Source Type:	Implementer	***Zip Code:***	98121

Historical Handler Details

Receive Dt:	20120523
Generator Code Description:	Large Quantity Generator
Handler Name:	BELLTOWN DEVELOPMENT PARTNERS II LLC
Receive Dt:	19980518
Generator Code Description:	Not a Generator, Verified
Handler Name:	NORTHWEST PROTECTIVE SERVICE INC
Receive Dt:	19970127
Generator Code Description:	Not a Generator, Verified
Handler Name:	NORTHWEST PROTECTIVE SERVICE INC
Receive Dt:	19971226
Generator Code Description:	Not a Generator, Verified
Handler Name:	NORTHWEST PROTECTIVE SERVICE INC
Receive Dt:	20130108
Generator Code Description:	Large Quantity Generator
Handler Name:	BELLTOWN DEVELOPMENT PARTNERS II LLC

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Receive Dt: 19960624
Generator Code Description: Very Small Quantity Generator
Handler Name: NORTHWEST PROTECTIVE SERVICE INC

Receive Dt: 19980519
Generator Code Description: Not a Generator, Verified
Handler Name: NORTHWEST PROTECTIVE SERVICE INC

Receive Dt: 20120523
Generator Code Description: Large Quantity Generator
Handler Name: BELLTOWN DEVELOPMENT PARTNERS II LLC

Receive Dt: 19980518
Generator Code Description: Not a Generator, Verified
Handler Name: NORTHWEST PROTECTIVE SERVICE INC

43	6 of 6	SW	0.14 / 723.90	38.83 / -67	NORTHWEST PROTECTIVE SERVICE 2700 ELLIOTT AVE SEATTLE WA 98121	LUST

Facility Site ID: 77333528
Cleanup Site ID: 10478
Responsible Unit: Northwest
Region: Northwest
Alternate Site Names: Northwest Protective Service Inc
County: King
Latitude: 47.6146
Longitude: -122.35235

Tank Detail(s)

UST ID: 1163
LUST ID: 2512
LUST Status: LUST - NFA
Status Date: 10/03/2011
Release Date: 01/06/1993

Contaminants Detail(s)

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

44	1 of 2	W	0.14 / 748.41	48.74 / -57	LA SCALA APARTMENTS 2922 WESTERN AVE SEATTLE WA 98121	RCRA NON GEN

EPA Handler ID: WAD988474540
Gen Status Universe: No Report
Contact Name: LA SCALA APARTM LA SCALA APARTM
Contact Address: 2922 WESTERN AVE , , SEATTLE , WA, 98121-1090 , US
Contact Phone No and Ext: 000-000-0000

Contact Email:
Contact Country: US
County Name: KING
EPA Region: 10
Land Type: Private
Receive Date: 19900625
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19900625
Handler Name: LA SCALA APARTMENTS
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19900625
Handler Name: LA SCALA APARTMENTS
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19900625
Handler Name: LA SCALA APARTMENTS
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator ***Street No:***

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Type:	Private	**Street 1:**	2922 WESTERN AVE
Name:	LA SCALA APARTMENTS	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2922 WESTERN AVE
Name:	LA SCALA APARTMENTS	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121-1090
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2922 WESTERN AVE
Name:	LA SCALA APARTM L	**Street 2:**	
Date Became Current:	19960502	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121-1090
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2922 WESTERN AVE
Name:	LA SCALA APARTMENTS	**Street 2:**	
Date Became Current:	19960502	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2922 WESTERN AVE
Name:	LA SCALA APARTMENTS	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2922 WESTERN AVE
Name:	SEE PAPER COPY	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	
Source Type:	Implementer	**Zip Code:**	98121

Historical Handler Details

Receive Dt:	19900625
Generator Code Description:	Not a Generator, Verified
Handler Name:	LA SCALA APARTMENTS

44	*2 of 2*	*W*	*0.14 / 748.41*	*48.74 / -57*	***La Scala Apartments 2922 WESTERN AVE SEATTLE WA 98121***	***ALL SITES***

Facility/Site ID:	96258359
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAD988474540
Facility Alternate:	
Interaction ID:	74710

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 25-Jun-1990
Interact End Dt: 11-Aug-1992
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.61664
GIS longitude: -122.35365

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
45	1 of 1	ENE	0.14 / 749.07	122.36 / 17	2618 4TH AVE Seattle WA 98119	UST SEATTLE

Permit No: 3-42668
Date Issued: 05/31/2002
Fill Material: No Fill
Date Decommissioned: 05/31/2002
Type Decommissioned: Abandonment in Place
Tank Size: 300
Tank Age: 20+
Tank Content: HEATING OIL

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
46	1 of 1	NE	0.14 / 758.42	129.54 / 24	K & N MEATS SEATTLE 2900 4TH AVE SEATTLE WA 98108	ALL SITES

Facility/Site ID: 77227688
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: CRK000022290
Facility Alternate:
Interaction ID: 63840
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: TIER2
Interaction Desc: Emergency/Haz Chem Rpt TIER2
Interact Start Dt: 01-Jan-1989
Interact End Dt: 01-Jan-1753
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: EPCRA
Database Name Desc: Emergency Planning & Community Right-to-Know Act

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.54972
GIS longitude: -122.309997

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
47	1 of 2	SSE	0.14 / 765.49	64.47 / -41	OENING CO 81 VINE 2518 WESTERN AVE SEATTLE WA 98121	RCRA NON GEN

EPA Handler ID: WA0000188722

Gen Status Universe: No Report
Contact Name: OENING CO OENING CO
Contact Address: 117 E LOUISA ST 296 , , SEATTLE , WA, 98102-3279 , US
Contact Phone No and Ext: 000-000-0000
Contact Email:
Contact Country: US
County Name: KING
EPA Region: 10
Land Type: Private
Receive Date: 19970926
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19970926
Handler Name: OENING CO 81 VINE
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19970926
Handler Name: OENING CO 81 VINE
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: OENING CO
Date Became Current: 19960501
Date Ended Current:
Phone: 000-000-0000
Source Type: Implementer
Street No:
Street 1: 2518 WESTERN AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2518 WESTERN AVE
Name:	OENING CO 81 VINE	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2518 WESTERN AVE
Name:	OENING CO 81 VINE	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2518 WESTERN AVE
Name:	OENING CO O	**Street 2:**	
Date Became Current:	19960501	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121-1308

Historical Handler Details

Receive Dt:	19970926
Generator Code Description:	Not a Generator, Verified
Handler Name:	OENING CO 81 VINE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
47	2 of 2	SSE	0.14 / 765.49	64.47 / -41	Oening Co 81 Vine 2518 WESTERN AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID:	92182618
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WA0000188722
Facility Alternate:	
Interaction ID:	72005
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	28-Mar-1994
Interact End Dt:	31-Dec-1994
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	N
Horizont 1:	NAD83	**GIS latitude:**	47.61433
Horizont 2:	Unknown	**GIS longitude:**	-122.34969

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
48	1 of 4	NW	0.15 / 771.91	112.29 / 7	Pacific Science Center Frol Building 204 DENNY WAY	CSCSL NFA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

SEATTLE WA 98109

Fac Site ID:	96879757	***Fac Site ID (OD):***	96879757
Cleanup Site ID:	2493	***Cleanup SiteID(OD):***	2493
Site Status:	NFA	***Site Status (OD):***	No Further Action
NFA Date:	11/04/1998	***Rank (OD):***	
Responsible Unit:	Northwest	***Has Env Coven (OD):***	
Has Insti Control:		***Respon Unit (OD):***	Northwest
Region:	Northwest	***Region (OD):***	Northwest
County:	King	***County (OD):***	King
Latitude:	47.6186958601095	***Latitude (OD):***	47.61851
Longitude:	-122.352717726517	***Longitude (OD):***	-122.353973

NFA Reason: Voluntary Cleanup Program Review
Alternate Site Names: CYRIL M FROL & PHYLLIS A FROL & STEVEN FROL ET AL,FROL BLDG,PACIFIC SCIENCE CTR FROL BLDG
Location (OD): ""
(47.61851, -122.353973)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

NFA Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Remediated
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Remediated

48	*2 of 4*	*NW*	*0.15 / 771.91*	*112.29 / 7*	***PACIFIC SCIENCE CTR FROL BLDG*** ***204 DENNY WAY*** ***SEATTLE WA 98109***	***ALL SITES***

Facility/Site ID: 96879757
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 443606
Facility Alternate: PACIFIC SCIENCE CTR FROL BLDG
Interaction ID: 75082
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 17-Apr-1998
Interact End Dt: 04-Nov-1998
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: NW0159
Facility Alternate: PACIFIC SCIENCE CTR FROL BLDG
Interaction ID: 75083
Interaction Status: I

Interac Status Desc:	Inactive
Interaction Type:	VOLCLNST
Interaction Desc:	Voluntary Cleanup Sites
Interact Start Dt:	27-May-1998
Interact End Dt:	28-May-1998
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Facility Location Detail

Horizontal:	40ft	***Location Verified:***	
Horizont 1:	NAD83HARN	***GIS latitude:***	47.6186958601
Horizont 2:	Digital map or GIS	***GIS longitude:***	-122.352717727

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
48	3 of 4	NW	0.15 / 771.91	112.29 / 7	Pacific Science Center Frol Building 204 DENNY WAY SEATTLE WA 98109	ICR

Cleanup Site ID:	2493	***WRIA ID:***	8
Facility Site ID:	96879757	***Is NFA Site:***	Yes
Site Status:	No Further Action Required	***Responsible Unit:***	Northwest
Statute:	MTCA	***Latitude:***	47.618510000000001
Rank:		***Longitude:***	-122.353973
Rank Description:		***Legislative District:***	36
Has Env Covenant:		***Congr District:***	7
Is Brownfiled Site:		***County Name:***	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		***Start Date:***	1998-04-07
VCP Prj No:	NW0060	***End Date:***	
Activity Name:	VCP Application	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Northwest Region
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	1998-05-28
VCP Prj No:		***End Date:***	1998-05-28
Activity Name:	Initial Investigation / Federal Preliminary Assessment	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	Ecology
County Name:	King	***Project Manager:***	Timm, Ron
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		***Start Date:***	1998-10-26
VCP Prj No:	NW0159	***End Date:***	
Activity Name:	VCP Application	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Northwest Region
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	
VCP Prj No:	NW0060	***End Date:***	1998-05-28
Activity Name:	VCP Opinion on Cleanup Action	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Timm, Ron
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Related ID: **Start Date:**
VCP Prj No: NW0159 ***End Date:*** 1998-11-04
Activity Name: VCP Termination ***Legal Mechanism:***
Activity Status: Completed ***Performed by:***
County Name: King ***Project Manager:***
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Related ID: **Start Date:**
VCP Prj No: NW0060 ***End Date:*** 1998-05-28
Activity Name: VCP Termination ***Legal Mechanism:***
Activity Status: Completed ***Performed by:***
County Name: King ***Project Manager:***
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Related ID: **Start Date:**
VCP Prj No: NW0159 ***End Date:*** 1999-05-28
Activity Name: VCP Opinion on Cleanup Action ***Legal Mechanism:***
Activity Status: Completed ***Performed by:***
County Name: King ***Project Manager:*** Timm, Ron
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Related ID: **Start Date:**
VCP Prj No: ***End Date:*** 1998-11-04
Activity Name: Site Status Changed to NFA ***Legal Mechanism:***
Activity Status: ***Performed by:***
County Name: King ***Project Manager:***
Applies to: CleanupSite
Applies to Description:

Media Contaminants

Contaminant Type: Petroleum Products-Unspecified ***Sediment:***
Groundwater: ***Sediment Desc.:***
Groundwater Desc.: ***Air:***
Surface Water: ***Air Desc.:***
Surfacewater Desc.: ***Bedrock:***
Soil: R ***Bedrock Desc.:***
Soil Desc.: Remediated ***County Name:*** King

---

48 | ***4 of 4*** | ***NW*** | ***0.15 / 771.91*** | ***112.29 / 7*** | ***Pacific Science Center Frol Building 204 DENNY WAY SEATTLE WA 98109*** | ***VCP***

Facility Site ID: 96879757 ***County:*** King
Cleanup Site ID: 2493 ***Latitude:*** 47.6186958601095
Region: Northwest ***Longitude:*** -122.352717726517
Alternate Site Names: CYRIL M FROL & PHYLLIS A FROL & STEVEN FROL ET AL,FROL BLDG,PACIFIC SCIENCE CTR FROL BLDG
Data Source(s): No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status: NFA
NFA Date: 11/04/1998
Responsible Unit: Northwest
Has Inst Control:
NFA Reason: Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name: Petroleum Products-Unspecified ***Sediment:***
Groundwater: ***Air:***

Surfacewater: ***Bedrock:***
Soil: Remediated

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: No Further Action
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Petroleum Products-Unspecified ***Sediment:***
Groundwater: ***Air:***
Surfacewater: ***Bedrock:***
Soil: Remediated

49	1 of 2	E	0.15 / 812.05	120.86 / 15	PUGET SOUND INSTITUTE OF PATHO 2600 4TH AVE SEATTLE WA 98111	RCRA NON GEN

EPA Handler ID: WAD063338339
Gen Status Universe: No Report
Contact Name:
Contact Address:
Contact Phone No and Ext:
Contact Email:
Contact Country:
County Name: KING
EPA Region: 10
Land Type: Other
Receive Date: 19850501
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19850430
Handler Name: PUGET SOUND INSTITUTE OF PATHO
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19850501
Handler Name: PUGET SOUND INSTITUTE OF PATHO
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19850430
Handler Name: PUGET SOUND INSTITUTE OF PATHO
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: PUGET SOUND INSTITUTE OF PATHO
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 2600 4TH AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98111

Owner/Operator Ind: Current Owner
Type: Private
Name: PUGET SOUND INSTITUTE OF PATHO
Date Became Current: 19960502
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 2600 4TH AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Owner
Type: Private
Name: SEE PAPER COPY
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Implementer
Street No:
Street 1: 2600 4TH AVE
Street 2:
City: SEATTLE
State: WA
Country:
Zip Code: 98111

Owner/Operator Ind: Current Operator
Type: Private
Name: PUGET SOUND INSTITUTE OF PATHO
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Implementer
Street No:
Street 1: 2600 4TH AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98111

Owner/Operator Ind: Current Owner
Type: Private
Name: PUGET SOUND INSTITUTE OF PATHO
Date Became Current: 19960502
Date Ended Current:
Street No:
Street 1: 2600 4TH AVE
Street 2:
City: SEATTLE
State: WA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2600 4TH AVE
Name:	PUGET SOUND INSTITUTE OF PATHO	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98111
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2600 4TH AVE
Name:	PUGET SOUND INSTITUTE OF PATHO	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121-1210
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2600 4TH AVE
Name:	PUGET SOUND INSTITUTE OF PATHO	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98111

Historical Handler Details

Receive Dt:	19850430
Generator Code Description:	Not a Generator, Verified
Handler Name:	PUGET SOUND INSTITUTE OF PATHO

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
49	2 of 2	E	0.15 / 812.05	120.86 / 15	Puget Sound Institute of Patho 2600 4TH AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID:	95948688
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAD063338339
Facility Alternate:	
Interaction ID:	74570
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	07-Jul-1980
Interact End Dt:	18-Jun-1982
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	40ft	**Location Verified:**	
Horizont 1:	NAD83HARN	**GIS latitude:**	47.6172725645
Horizont 2:	Digital map or GIS	**GIS longitude:**	-122.347039796

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
50	1 of 2	NE	0.16 / 820.79	129.20 / 23	THE FAMOUS PACIFIC DESSERT COMPANY 420 DENNY WAY Seattle WA 98109	UST

UST ID: 2732
Facility Site ID: 6751952
Site Active: No
Responsible Unit: Northwest
Active Tag:
Alternate Site Names: FAMOUS PACIFIC DESSERT COMPANY

Region: Northwest
County: King
Latitude: 47.6187931157
Longitude: -122.34867365855

Tank Detail(s)

Tank Name: 1.
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Closed in Place
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction:
Tank Capacity:
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance:
Used Substance:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
50	2 of 2	NE	0.16 / 820.79	129.20 / 23	FAMOUS PACIFIC DESSERT COMPANY 420 DENNY WAY SEATTLE WA 98109	ALL SITES

Facility/Site ID: 6751952
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 2732
Facility Alternate:
Interaction ID: 19519
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 29-Feb-2000
Interact End Dt: 03-May-2000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6187931157
GIS longitude: -122.348673659

---

51 | ***1 of 9*** | ***W*** | ***0.16 / 844.14*** | ***29.82 / -76*** | ***UNOCAL Seattle Marketing Terminal***
BROAD ST & WESTERN AVE & BAY ST
SEATTLE WA 98121 | ***INST***

Facility Site ID: 2208
Region: Northwest
County: King
Latitude: 47.6163808256758
Longitude: -122.355960132959
Cleanup Site ID: 1428
Region (OD): Northwest
County (OD): King
Latitude (OD): 47.616483
Longitude (OD): -122.355411
Site Name: UNOCAL Seattle Marketing Terminal
Address: BROAD ST & WESTERN AVE & BAY ST
City: SEATTLE
Zip: 98121
Site Name (OD): UNOCAL Seattle Marketing Terminal
Address (OD): BROAD ST & WESTERN AVE & BAY ST
City (OD): SEATTLE
Zipcode (OD): 98121
Location (OD): ""
(47.616483, -122.355411)
Data Source(s): Department of Ecology State of Washington - Environmental Covenants Registry List; Open Data Portal - Institutional Controls or Environmental Covenants Map

Environmental Covenants Registry List

NFA Date:
Site Status: Cleanup Started
Tax Parcel No: 7666202275 and 0698000095
Instrument Type: Environmental Covenant
Media Restrictions: Soil
Alternate Site Names: OLYMPIC SCULPTURE PARK,SAM,SEATTLE ART MUSEUM,UNOCAL MARKETING TERMINAL FORMER, UNOCAL SEATTLE MARKET ELLIOTT,UNOCAL SEATTLE MARKET OFF SITE,UNOCAL SEATTLE MARKET SED,UNOCAL SEATTLE MARKET UPLAND,UNOCAL SEATTLE MARKETING TERM
Cnty Recording No: 20050202000831
Cnty Recording Dt: 02/02/2005
Responsible Unit: Northwest
Active Control: Yes
Control Stormwater: No
Control Vapor Gas: No
Prevent Reuse/Relocation: Yes
Prohibit New Bldg Constr: No
Prohibit Removal or Alteration: No
Prohibit Soil Disturbance: No
Ongoing Maint of Remedy: No
Require Educational Programs: No
Restrict Access: No
Restrict All GW Extr: No
Restrict Domestic GW: No
Restrict Land Use: Yes
Restrict Sedmnt Cap Disturb: No
Restrict Shellfish and or Finf: No
Restrict Surface Water Use: No
Restrict Swim/Beach Play: No
Restrictive Signage: No

Maintain/Protect Monit System:	No
Other:	No
NFA Date:	
Site Status:	Cleanup Started
Tax Parcel No:	7666202275
Instrument Type:	Environmental Covenant
Media Restrictions:	Soil
Alternate Site Names:	OLYMPIC SCULPTURE PARK,SAM,SEATTLE ART MUSEUM,UNOCAL MARKETING TERMINAL FORMER, UNOCAL SEATTLE MARKET ELLIOTT,UNOCAL SEATTLE MARKET OFF SITE,UNOCAL SEATTLE MARKET SED,UNOCAL SEATTLE MARKET UPLAND,UNOCAL SEATTLE MARKETING TERM
Cnty Recording No:	20050202000832
Cnty Recording Dt:	02/02/2005
Responsible Unit:	Northwest
Active Control:	Yes
Control Stormwater:	No
Control Vapor Gas:	No
Prevent Reuse/Relocation:	Yes
Prohibit New Bldg Constr:	No
Prohibit Removal or Alteration:	No
Prohibit Soil Disturbance:	No
Ongoing Maint of Remedy:	No
Require Educational Programs:	No
Restrict Access:	No
Restrict All GW Extr:	No
Restrict Domestic GW:	No
Restrict Land Use:	Yes
Restrict Sedmnt Cap Disturb:	No
Restrict Shellfish and or Finf:	No
Restrict Surface Water Use:	No
Restrict Swim/Beach Play:	No
Restrictive Signage:	No
Maintain/Protect Monit System:	No
Other:	No

Open Data Portal - Environmental Covenants Map

Facility Site ID:	2208
Cleanup Status:	Cleanup Started
Has Env Covenant:	Yes
Rank:	4 - Low-Moderate Risk
Resp Section:	Northwest

51	*2 of 9*	*W*	*0.16 / 844.14*	*29.82 / -76*	***Unocal Seattle Market Lower BN ELLIOTT RR BAY & BROAD SEATTLE WA 98121***	***CSCSL***

Fac Site ID:	2210	***Responsible Unit:***	Northwest
Cleanup Site ID:	1148	***Fac Site ID (OD):***	2210
Site Status:	Cleanup Started	***Cleanup SiteID(OD):***	1148
Site Rank:	4 - Low-Moderate Risk	***Site Rank (OD):***	4 - Low-Moderate Risk
Current VCP:		***Has Env Coven (OD):***	
Past VCP:		***Respon Unit (OD):***	Northwest
Has Inst Control:		***County (OD):***	King
County:	King	***Region (OD):***	Northwest
Region:	Northwest	***Longitude (OD):***	-122.355018
Latitude:	47.6167513559969	***Latitude (OD):***	47.616751
Longitude:	-122.355018251261		
Site Name:	Unocal Seattle Market Lower		
Address:	BN ELLIOTT RR BAY & BROAD		
City:	SEATTLE		
Zip Code:	98121		
Site Status (OD):	Cleanup Started		
Site Name (OD):	UNOCAL SEATTLE MARKET LOWER		
Address (OD):	BN ELLIOTT RR BAY & BROAD		
City (OD):	SEATTLE		
Zipcode (OD):	98121		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Location (OD): ""
(47.616751, -122.355018)
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Non-Halogenated Solvents
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Non-Halogenated Solvents
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Non-Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

51	3 of 9	W	0.16 / 844.14	29.82 / -76	***UNOCAL Seattle Marketing Terminal*** ***BROAD ST & WESTERN AVE & BAY ST*** ***SEATTLE WA 98121***	***CSCSL***

Fac Site ID: 2208
Cleanup Site ID: 1428
Site Status: Cleanup Started
Responsible Unit: Northwest
Fac Site ID (OD): 2208
Cleanup SiteID(OD): 1428

Site Rank:	4 - Low-Moderate Risk	**Site Rank (OD):**	4 - Low-Moderate Risk
Current VCP:		**Has Env Coven (OD):**	Yes
Past VCP:		**Respon Unit (OD):**	Northwest
Has Inst Control:	Yes	**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.355411
Latitude:	47.6163808256758	**Latitude (OD):**	47.616483
Longitude:	-122.355960132959		

Site Name: UNOCAL Seattle Marketing Terminal
Address: BROAD ST & WESTERN AVE & BAY ST
City: SEATTLE
Zip Code: 98121
Site Status (OD): Cleanup Started
Site Name (OD): UNOCAL Seattle Marketing Terminal
Address (OD): BROAD ST & WESTERN AVE & BAY ST
City (OD): SEATTLE
Zipcode (OD): 98121
Location (OD): ""
(47.616483, -122.355411)
Alternate Site Names: OLYMPIC SCULPTURE PARK,SAM,SEATTLE ART MUSEUM,UNOCAL MARKETING TERMINAL FORMER, UNOCAL SEATTLE MARKET ELLIOTT,UNOCAL SEATTLE MARKET OFF SITE,UNOCAL SEATTLE MARKET SED,UNOCAL SEATTLE MARKET UPLAND,UNOCAL SEATTLE MARKETING TERM
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Metals - Other
Groundwater: Suspected
Surfacewater: Suspected
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Non-Halogenated Solvents
Groundwater: Confirmed Above Cleanup Levels
Surfacewater: Suspected
Soil: Confirmed Above Cleanup Levels
Sediment: Suspected
Air:
Bedrock:

Contaminant Name: Base/Neutral/Acid Organics
Groundwater: Suspected
Surfacewater: Suspected
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Conventional Contaminants, Inorganic
Groundwater: Suspected
Surfacewater: Suspected
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Halogenated Organics
Groundwater: Suspected
Surfacewater: Suspected
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Metals Priority Pollutants
Groundwater: Suspected

Surfacewater: Suspected
Soil: Confirmed Above Cleanup Levels
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater: Confirmed Above Cleanup Levels
Surfacewater: Suspected
Soil: Confirmed Above Cleanup Levels
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Confirmed Above Cleanup Levels
Surfacewater: Suspected
Soil: Confirmed Above Cleanup Levels
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

Contaminant Name: Polychlorinated biPhenyls (PCB)
Groundwater: Suspected
Surfacewater: Suspected
Soil: Suspected
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Non-Halogenated Solvents
Contaminant Media: Sediment
Contaminant Status: Suspected

Contaminant: Non-Halogenated Solvents
Contaminant Media: Surface Water
Contaminant Status: Suspected

Contaminant: Metals Priority Pollutants
Contaminant Media: Surface Water
Contaminant Status: Suspected

Contaminant: Conventional Contaminants, Inorganic
Contaminant Media: Surface Water
Contaminant Status: Suspected

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals Priority Pollutants
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals - Other
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Base/Neutral/Acid Organics
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Metals - Other
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Non-Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Conventional Contaminants, Inorganic
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Non-Halogenated Solvents
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Halogenated Organics
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Sediment
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Surface Water
Contaminant Status: Suspected

Contaminant: Polychlorinated biPhenyls (PCB)
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Halogenated Organics
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Polychlorinated biPhenyls (PCB)
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals - Other
Contaminant Media: Surface Water
Contaminant Status: Suspected

Contaminant: Base/Neutral/Acid Organics
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Sediment
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Conventional Contaminants, Inorganic
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Halogenated Organics
Contaminant Media: Surface Water
Contaminant Status: Suspected

Contaminant: Base/Neutral/Acid Organics

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant Media: Surface Water
Contaminant Status: Suspected

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Surface Water
Contaminant Status: Suspected

Contaminant: Metals Priority Pollutants
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Metals Priority Pollutants
Contaminant Media: Sediment
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polychlorinated biPhenyls (PCB)
Contaminant Media: Surface Water
Contaminant Status: Suspected

51	***4 of 9***	***W***	***0.16 / 844.14***	***29.82 / -76***	***UNOCAL Seattle Marketing Terminal*** ***BROAD ST & WESTERN AVE & BAY ST*** ***SEATTLE WA 98121***	***HSL***

Fac Site ID:	2208	***Fac Site ID (OD):***	2208
Cleanup Site ID:	1428	***Cleanup Site ID (OD):***	1428
Site Status:	Cleanup Started	***Site Status (OD):***	Cleanup Started
Site Rank:	4 - Low-Moderate Risk	***Site Rank (OD):***	4 - Low-Moderate Risk
Has Inst Control:	Yes	***Has Env Coven (OD):***	Yes
Responsible Unit:	Northwest	***Respon Unit (OD):***	Northwest
County:	King	***County (OD):***	King
Region:	Northwest	***Region (OD):***	Northwest
Latitude:	47.6163808256758	***Site Name (OD):***	UNOCAL Seattle Marketing Terminal
Longitude:	-122.355960132959	***Address (OD):***	BROAD ST & WESTERN AVE & BAY ST
Latitude (OD):	47.616483	***City (OD):***	SEATTLE
Longitude (OD):	-122.355411	***ZIP code (OD):***	98121
Current VCP:		***Past VCP:***	
Location (OD):	"" (47.616483, -122.355411)		
Alternate Site Names:	OLYMPIC SCULPTURE PARK,SAM,SEATTLE ART MUSEUM,UNOCAL MARKETING TERMINAL FORMER, UNOCAL SEATTLE MARKET ELLIOTT,UNOCAL SEATTLE MARKET OFF SITE,UNOCAL SEATTLE MARKET SED,UNOCAL SEATTLE MARKET UPLAND,UNOCAL SEATTLE MARKETING TERM		
Data Source(s):	Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)		

Contaminants Detail(s)

Contaminant Name:	Metals - Other	***Sediment:***	
Groundwater:	Suspected	***Soil:***	Suspected
Surfacewater:	Suspected	***Bedrock:***	
Air:			

Contaminant Name:	Base/Neutral/Acid Organics	***Sediment:***	
Groundwater:	Suspected	***Soil:***	Suspected
Surfacewater:	Suspected	***Bedrock:***	
Air:			

Contaminant Name:	Conventional Contaminants, Inorganic	***Sediment:***	
Groundwater:	Suspected	***Soil:***	Suspected
Surfacewater:	Suspected	***Bedrock:***	
Air:			

Contaminant Name:	Non-Halogenated Solvents	***Sediment:***	Suspected
Groundwater:	Confirmed Above Cleanup Levels	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:	Suspected	***Bedrock:***	
Air:			

Contaminant Name:	Metals Priority Pollutants	***Sediment:***	Confirmed Above Cleanup Levels
Groundwater:	Suspected	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:	Suspected	***Bedrock:***	
Air:			

Contaminant Name:	Polychlorinated biPhenyls (PCB)	***Sediment:***	
Groundwater:	Suspected	***Soil:***	Suspected
Surfacewater:	Suspected	***Bedrock:***	
Air:			

Contaminant Name:	Halogenated Organics	***Sediment:***	
Groundwater:	Suspected	***Soil:***	Suspected
Surfacewater:	Suspected	***Bedrock:***	
Air:			

Contaminant Name:	Polycyclic Aromatic Hydrocarbons	***Sediment:***	Confirmed Above Cleanup Levels
Groundwater:	Confirmed Above Cleanup Levels	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:	Suspected	***Bedrock:***	
Air:			

Contaminant Name:	Petroleum Products-Unspecified	***Sediment:***	Confirmed Above Cleanup Levels
Groundwater:	Confirmed Above Cleanup Levels	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:	Suspected	***Bedrock:***	
Air:			

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Metals Priority Pollutants	***Contaminant Media:***	Surface Water
Contaminant Status:	Suspected		

Contaminant:	Non-Halogenated Solvents	***Contaminant Media:***	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		

Contaminant:	Petroleum Products-Unspecified	***Contaminant Media:***	Sediment
Contaminant Status:	Confirmed Above Cleanup Levels		

Contaminant:	Halogenated Organics	***Contaminant Media:***	Groundwater
Contaminant Status:	Suspected		

Contaminant:	Metals Priority Pollutants	***Contaminant Media:***	Groundwater
Contaminant Status:	Suspected		

Contaminant:	Non-Halogenated Solvents	***Contaminant Media:***	Sediment
Contaminant Status:	Suspected		

Contaminant:	Conventional Contaminants, Inorganic	***Contaminant Media:***	Soil
Contaminant Status:	Suspected		

Contaminant:	Polychlorinated biPhenyls (PCB)	***Contaminant Media:***	Surface Water
Contaminant Status:	Suspected		

Contaminant:	Halogenated Organics	***Contaminant Media:***	Soil
Contaminant Status:	Suspected		

Contaminant:	Halogenated Organics	***Contaminant Media:***	Surface Water
Contaminant Status:	Suspected		

Contaminant:	Petroleum Products-Unspecified	***Contaminant Media:***	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		

Contaminant:	Conventional Contaminants, Inorganic	***Contaminant Media:***	Surface Water
Contaminant Status:	Suspected		

Contaminant:	Metals - Other	***Contaminant Media:***	Soil
Contaminant Status:	Suspected		

Contaminant:	Metals Priority Pollutants	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		

Contaminant:	Base/Neutral/Acid Organics	***Contaminant Media:***	Groundwater
Contaminant Status:	Suspected		
Contaminant:	Base/Neutral/Acid Organics	***Contaminant Media:***	Surface Water
Contaminant Status:	Suspected		
Contaminant:	Polycyclic Aromatic Hydrocarbons	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Metals - Other	***Contaminant Media:***	Surface Water
Contaminant Status:	Suspected		
Contaminant:	Petroleum Products-Unspecified	***Contaminant Media:***	Surface Water
Contaminant Status:	Suspected		
Contaminant:	Base/Neutral/Acid Organics	***Contaminant Media:***	Soil
Contaminant Status:	Suspected		
Contaminant:	Petroleum Products-Unspecified	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Metals Priority Pollutants	***Contaminant Media:***	Sediment
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Polycyclic Aromatic Hydrocarbons	***Contaminant Media:***	Surface Water
Contaminant Status:	Suspected		
Contaminant:	Polycyclic Aromatic Hydrocarbons	***Contaminant Media:***	Sediment
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Polychlorinated biPhenyls (PCB)	***Contaminant Media:***	Groundwater
Contaminant Status:	Suspected		
Contaminant:	Metals - Other	***Contaminant Media:***	Groundwater
Contaminant Status:	Suspected		
Contaminant:	Non-Halogenated Solvents	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Polychlorinated biPhenyls (PCB)	***Contaminant Media:***	Soil
Contaminant Status:	Suspected		
Contaminant:	Polycyclic Aromatic Hydrocarbons	***Contaminant Media:***	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Conventional Contaminants, Inorganic	***Contaminant Media:***	Groundwater
Contaminant Status:	Suspected		
Contaminant:	Non-Halogenated Solvents	***Contaminant Media:***	Surface Water
Contaminant Status:	Suspected		

51	5 of 9	W	0.16 / 844.14	29.82 / -76	**Unocal Seattle Market Lower** **BN ELLIOTT RR BAY & BROAD** **SEATTLE WA 98121**	HSL

Fac Site ID:	2210	***Fac Site ID (OD):***	2210
Cleanup Site ID:	1148	***Cleanup Site ID (OD):***	1148
Site Status:	Cleanup Started	***Site Status (OD):***	Cleanup Started
Site Rank:	4 - Low-Moderate Risk	***Site Rank (OD):***	4 - Low-Moderate Risk
Has Inst Control:		***Has Env Coven (OD):***	
Responsible Unit:	Northwest	***Respon Unit (OD):***	Northwest
County:	King	***County (OD):***	King
Region:	Northwest	***Region (OD):***	Northwest
Latitude:	47.6167513559969	***Site Name (OD):***	UNOCAL SEATTLE MARKET LOWER
Longitude:	-122.355018251261	***Address (OD):***	BN ELLIOTT RR BAY & BROAD
Latitude (OD):	47.616751	***City (OD):***	SEATTLE
Longitude (OD):	-122.355018	***ZIP code (OD):***	98121

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Current VCP: ***Past VCP:***
Location (OD): ""
(47.616751, -122.355018)
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Air:
Sediment:
Soil: Confirmed Above Cleanup Levels
Bedrock:

Contaminant Name: Non-Halogenated Solvents
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Air:
Sediment:
Soil: Confirmed Above Cleanup Levels
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Air:
Sediment:
Soil: Confirmed Above Cleanup Levels
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Soil

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Soil

Contaminant: Petroleum Products-Unspecified
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Groundwater

Contaminant: Non-Halogenated Solvents
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Soil

Contaminant: Non-Halogenated Solvents
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Groundwater

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Groundwater

51	6 of 9	W	0.16 / 844.14	29.82 / -76	UNOCAL SEATTLE MARKET LOWER BN ELLIOTT RR BAY & BROAD SEATTLE WA 98121	ALL SITES

Facility/Site ID: 2210
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: UNOCAL SEATTLE MARKET LOWER
Interaction ID: 3871
Interaction Status: A
Interac Status Desc: Active
Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 01-Jan-1900
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.616751356
GIS longitude: -122.355018251

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
51	7 of 9	W	0.16 / 844.14	29.82 / -76	UNOCAL SEATTLE MARKETING TERM BROAD ST & WESTERN AVE & BAY ST SEATTLE WA 98121	ALL SITES

Facility/Site ID: 2208
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: UNOCAL SEATTLE MARKETING TERM
Interaction ID: 3869
Interaction Status: A
Interac Status Desc: Active
Interaction Type: SEDIMENT
Interaction Desc: Sediments
Interact Start Dt: 01-Jan-1900
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID:
Facility Alternate: UNOCAL SEATTLE MARKETING TERM
Interaction ID: 3868
Interaction Status: A
Interac Status Desc: Active
Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 01-Jan-1900
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6163808257
GIS longitude: -122.355960133

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
51	8 of 9	W	0.16 / 844.14	29.82 / -76	UNOCAL SEATTLE MARKET LOWER BN ELLIOTT RR BAY & BROAD SEATTLE WA 98121	ICR

Cleanup Site ID: 1148
Facility Site ID: 2210
Site Status: Cleanup Started
Statute: Hazardous Waste Cleanup Act - (pre-MTCA)
WRIA ID: 8
Is NFA Site:
Responsible Unit: Northwest
Latitude: 47.616751355996925

Rank:	4	**Longitude:**	-122.35501825126111
Rank Description:		**Legislative District:**	36
Has Env Covenant:		**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		**Start Date:**	1997-06-30
VCP Prj No:		**End Date:**	1998-12-30
Activity Name:	Ecology Cleanup Construction	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	PLP
County Name:	King	**Project Manager:**	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	1995-08-22
Activity Name:	Hazardous Sites Listing/NPL	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	1999-01-01
VCP Prj No:		**End Date:**	1999-12-06
Activity Name:	Ecology Cleanup Action-Engineering Design	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	Ecology
County Name:	King	**Project Manager:**	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		**Start Date:**	1996-10-01
VCP Prj No:		**End Date:**	1997-04-30
Activity Name:	Ecology Cleanup Action Plan	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	PLP
County Name:	King	**Project Manager:**	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		**Start Date:**	1996-10-01
VCP Prj No:		**End Date:**	1997-12-24
Activity Name:	Ecology Cleanup Action-Engineering Design	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	PLP
County Name:	King	**Project Manager:**	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		**Start Date:**	2007-01-01
VCP Prj No:		**End Date:**	
Activity Name:	Ecology Post-Cleanup O & M	**Legal Mechanism:**	
Activity Status:	In Process	**Performed by:**	Ecology
County Name:	King	**Project Manager:**	O'Brien, Maura
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		**Start Date:**	1999-01-01
VCP Prj No:		**End Date:**	1999-12-06
Activity Name:	Ecology Cleanup Action Plan	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	Ecology
County Name:	King	**Project Manager:**	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		**Start Date:**	1993-03-01
VCP Prj No:		**End Date:**	1996-06-30
Activity Name:	Ecology Remedial Investigation and/or Feasilibity Study	**Legal Mechanism:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Activity Status:	Completed	**Performed by:**	PLP
County Name:	King	**Project Manager:**	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			
Related ID:		**Start Date:**	2004-05-01
VCP Prj No:		**End Date:**	2006-12-31
Activity Name:	Ecology Cleanup Construction	**Legal Mechanism:**	Consent Decree
Activity Status:	Completed	**Performed by:**	PLP
County Name:	King	**Project Manager:**	Sato, Brian
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Media Contaminants

Contaminant Type:	Polynuclear Aromatic Hydrocarbons	**Sediment:**	
Groundwater:	C	**Sediment Desc.:**	
Groundwater Desc.:	Confirmed Above Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King
Contaminant Type:	Non-Halogenated Solvents	**Sediment:**	
Groundwater:	C	**Sediment Desc.:**	
Groundwater Desc.:	Confirmed Above Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King
Contaminant Type:	Petroleum Products-Unspecified	**Sediment:**	
Groundwater:	C	**Sediment Desc.:**	
Groundwater Desc.:	Confirmed Above Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

51	9 of 9	W	0.16 / 844.14	29.82 / -76	**UNOCAL Seattle Marketing Terminal** **BROAD ST & WESTERN AVE & BAY ST** **SEATTLE WA 98121**	ICR

Cleanup Site ID:	1428	**WRIA ID:**	8
Facility Site ID:	2208	**Is NFA Site:**	
Site Status:	Cleanup Started	**Responsible Unit:**	Northwest
Statute:	Hazardous Waste Cleanup Act - (pre-MTCA)	**Latitude:**	47.616482768175189
Rank:	4	**Longitude:**	-122.3554107282593
Rank Description:		**Legislative District:**	36
Has Env Covenant:	Yes	**Congr District:**	7
Is Brownfiled Site:	Yes	**County Name:**	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		**Start Date:**	2007-01-01
VCP Prj No:		**End Date:**	
Activity Name:	Ecology Post-Cleanup O & M	**Legal Mechanism:**	Consent Decree
Activity Status:	In Process	**Performed by:**	Ecology
County Name:	King	**Project Manager:**	O'Brien, Maura
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			
Related ID:		**Start Date:**	1990-06-25

VCP Prj No:		***End Date:***	1990-08-15
Activity Name:	Site Hazard Assessment/Federal Site Inspection	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	Ecology
County Name:	King	***Project Manager:***	Madakor, Nnamdi
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		***Start Date:***	1996-09-30
VCP Prj No:		***End Date:***	1997-04-30
Activity Name:	Ecology Cleanup Action Plan	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	PLP
County Name:	King	***Project Manager:***	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		***Start Date:***	1996-10-01
VCP Prj No:		***End Date:***	1997-12-24
Activity Name:	Ecology Cleanup Action-Engineering Design	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	PLP
County Name:	King	***Project Manager:***	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		***Start Date:***	1999-01-01
VCP Prj No:		***End Date:***	2006-12-31
Activity Name:	Ecology Cleanup Action-Engineering Design	***Legal Mechanism:***	Consent Decree
Activity Status:	Completed	***Performed by:***	Ecology
County Name:	King	***Project Manager:***	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	1990-08-15
Activity Name:	Hazardous Sites Listing/NPL	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	Madakor, Nnamdi
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		***Start Date:***	1993-03-01
VCP Prj No:		***End Date:***	1996-06-30
Activity Name:	Ecology Remedial Investigation and/or Feasilibity Study	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	PLP
County Name:	King	***Project Manager:***	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		***Start Date:***	1989-05-09
VCP Prj No:		***End Date:***	1994-06-30
Activity Name:	Ecology Cleanup Construction	***Legal Mechanism:***	Independent
Activity Status:	Canceled	***Performed by:***	Ecology
County Name:	King	***Project Manager:***	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		***Start Date:***	1997-06-30
VCP Prj No:		***End Date:***	1998-01-14
Activity Name:	Ecology Cleanup Construction	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	PLP
County Name:	King	***Project Manager:***	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		***Start Date:***	1996-10-01
VCP Prj No:		***End Date:***	1997-04-30
Activity Name:	Ecology Cleanup Action Plan	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	Ecology

County Name:	King	**Project Manager:**	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		**Start Date:**	1996-09-30
VCP Prj No:		**End Date:**	1997-04-30
Activity Name:	Ecology Cleanup Action Plan	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	Ecology
County Name:	King	**Project Manager:**	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		**Start Date:**	1993-06-04
VCP Prj No:		**End Date:**	1996-12-30
Activity Name:	Ecology Remedial Investigation and/or Feasilibity Study	**Legal Mechanism:**	Independent
Activity Status:	Completed	**Performed by:**	PLP
County Name:	King	**Project Manager:**	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		**Start Date:**	1998-07-30
VCP Prj No:		**End Date:**	2004-05-01
Activity Name:	Ecology Cleanup Construction	**Legal Mechanism:**	Consent Decree
Activity Status:	Completed	**Performed by:**	Ecology
County Name:	King	**Project Manager:**	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		**Start Date:**	2007-01-01
VCP Prj No:		**End Date:**	
Activity Name:	Ecology Post-Cleanup O & M	**Legal Mechanism:**	
Activity Status:	In Process	**Performed by:**	Ecology
County Name:	King	**Project Manager:**	O'Brien, Maura
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		**Start Date:**	1996-10-01
VCP Prj No:		**End Date:**	1997-04-30
Activity Name:	Ecology Cleanup Action Plan	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	PLP
County Name:	King	**Project Manager:**	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		**Start Date:**	1999-01-01
VCP Prj No:		**End Date:**	1999-12-06
Activity Name:	Ecology Cleanup Action-Engineering Design	**Legal Mechanism:**	Consent Decree
Activity Status:	Completed	**Performed by:**	Ecology
County Name:	King	**Project Manager:**	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		**Start Date:**	2004-05-01
VCP Prj No:		**End Date:**	2006-12-31
Activity Name:	Ecology Cleanup Construction	**Legal Mechanism:**	Consent Decree
Activity Status:	Completed	**Performed by:**	PLP
County Name:	King	**Project Manager:**	Sato, Brian
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		**Start Date:**	1997-06-03
VCP Prj No:		**End Date:**	1998-12-30
Activity Name:	Ecology Cleanup Construction	**Legal Mechanism:**	Independent
Activity Status:	Completed	**Performed by:**	PLP
County Name:	King	**Project Manager:**	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		**Start Date:**	2000-01-01
VCP Prj No:		**End Date:**	
Activity Name:	Ecology Post-Cleanup O & M	**Legal Mechanism:**	Consent Decree
Activity Status:	In Process	**Performed by:**	PLP
County Name:	King	**Project Manager:**	O'Brien, Maura
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		**Start Date:**	1993-03-01
VCP Prj No:		**End Date:**	1996-12-30
Activity Name:	Ecology Remedial Investigation and/or Feasilibity Study	**Legal Mechanism:**	Independent
Activity Status:	Completed	**Performed by:**	PLP
County Name:	King	**Project Manager:**	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		**Start Date:**	1999-01-01
VCP Prj No:		**End Date:**	1999-12-06
Activity Name:	Ecology Cleanup Action-Engineering Design	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	Ecology
County Name:	King	**Project Manager:**	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		**Start Date:**	1989-02-01
VCP Prj No:		**End Date:**	1989-05-08
Activity Name:	Ecology Cleanup Action-Engineering Design	**Legal Mechanism:**	Independent
Activity Status:	Completed	**Performed by:**	PLP
County Name:	King	**Project Manager:**	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		**Start Date:**	1999-01-01
VCP Prj No:		**End Date:**	1999-12-06
Activity Name:	Ecology Cleanup Action Plan	**Legal Mechanism:**	Consent Decree
Activity Status:	Completed	**Performed by:**	Ecology
County Name:	King	**Project Manager:**	Madakor, Nnamdi
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Media Contaminants

Contaminant Type:	Metals - Other	**Sediment:**	
Groundwater:	S	**Sediment Desc.:**	
Groundwater Desc.:	Suspected	**Air:**	
Surface Water:	S	**Air Desc.:**	
Surfacewater Desc.:	Suspected	**Bedrock:**	
Soil:	S	**Bedrock Desc.:**	
Soil Desc.:	Suspected	**County Name:**	King

Contaminant Type:	Base/Neutral/Acid Organics	**Sediment:**	
Groundwater:	S	**Sediment Desc.:**	
Groundwater Desc.:	Suspected	**Air:**	
Surface Water:	S	**Air Desc.:**	
Surfacewater Desc.:	Suspected	**Bedrock:**	
Soil:	S	**Bedrock Desc.:**	
Soil Desc.:	Suspected	**County Name:**	King

Contaminant Type:	Halogenated Organics	**Sediment:**	
Groundwater:	S	**Sediment Desc.:**	
Groundwater Desc.:	Suspected	**Air:**	
Surface Water:	S	**Air Desc.:**	
Surfacewater Desc.:	Suspected	**Bedrock:**	
Soil:	S	**Bedrock Desc.:**	
Soil Desc.:	Suspected	**County Name:**	King

Contaminant Type:	Polynuclear Aromatic Hydrocarbons	**Sediment:**	C

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Groundwater:	C	**Sediment Desc.:**	Confirmed Above Cleanup Level
Groundwater Desc.:	Confirmed Above Cleanup Level	**Air:**	
Surface Water:	S	**Air Desc.:**	
Surfacewater Desc.:	Suspected	**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

Contaminant Type:	Conventional Contaminants, Inorganic	**Sediment:**	
Groundwater:	S	**Sediment Desc.:**	
Groundwater Desc.:	Suspected	**Air:**	
Surface Water:	S	**Air Desc.:**	
Surfacewater Desc.:	Suspected	**Bedrock:**	
Soil:	S	**Bedrock Desc.:**	
Soil Desc.:	Suspected	**County Name:**	King

Contaminant Type:	Non-Halogenated Solvents	**Sediment:**	S
Groundwater:	C	**Sediment Desc.:**	Suspected
Groundwater Desc.:	Confirmed Above Cleanup Level	**Air:**	
Surface Water:	S	**Air Desc.:**	
Surfacewater Desc.:	Suspected	**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

Contaminant Type:	Petroleum Products-Unspecified	**Sediment:**	C
Groundwater:	C	**Sediment Desc.:**	Confirmed Above Cleanup Level
Groundwater Desc.:	Confirmed Above Cleanup Level	**Air:**	
Surface Water:	S	**Air Desc.:**	
Surfacewater Desc.:	Suspected	**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

Contaminant Type:	Polychlorinated biPhenyls (PCB)	**Sediment:**	
Groundwater:	S	**Sediment Desc.:**	
Groundwater Desc.:	Suspected	**Air:**	
Surface Water:	S	**Air Desc.:**	
Surfacewater Desc.:	Suspected	**Bedrock:**	
Soil:	S	**Bedrock Desc.:**	
Soil Desc.:	Suspected	**County Name:**	King

Contaminant Type:	Metals Priority Pollutants	**Sediment:**	C
Groundwater:	S	**Sediment Desc.:**	Confirmed Above Cleanup Level
Groundwater Desc.:	Suspected	**Air:**	
Surface Water:	S	**Air Desc.:**	
Surfacewater Desc.:	Suspected	**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

---

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
52	1 of 2	SSE	0.16 / 856.05	71.66 / -34	ROSSMAN INDUSTRIAL SUPPLY CO 2500 WESTERN AVE SEATTLE WA 98121	RCRA NON GEN

EPA Handler ID:	WAD988517991
Gen Status Universe:	No Report
Contact Name:	
Contact Address:	
Contact Phone No and Ext:	
Contact Email:	
Contact Country:	
County Name:	KING
EPA Region:	10
Land Type:	Other
Receive Date:	19940129
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19940128
Handler Name:	ROSSMAN INDUSTRIAL SUPPLY CO
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	19940129
Handler Name:	ROSSMAN INDUSTRIAL SUPPLY CO
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19940128
Handler Name:	ROSSMAN INDUSTRIAL SUPPLY CO
Source Type:	Notification
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	2500 WESTERN AVE
Name:	ROSSMAN INDUSTRIAL SUPPLY CO	***Street 2:***	
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	000-000-0000	***Country:***	US
Source Type:	Notification	***Zip Code:***	98121

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	2500 WESTERN AVE
Name:	SEE PAPER COPY	***Street 2:***	
Date Became Current:		***City:***	SEATTLE

Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	
Source Type:	Implementer	**Zip Code:**	98121-1308
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2500 WESTERN AVE
Name:	ROSSMAN INDUSTRIAL SUPPLY CO	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2500 WESTERN AVE
Name:	ROSSMAN INDUSTRIAL SUPPLY CO	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121-1308
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2500 WESTERN AVE
Name:	ROSSMAN INDUSTRIAL SUPPLY CO	**Street 2:**	
Date Became Current:	19960503	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2500 WESTERN AVE
Name:	ROSSMAN INDUSTRIAL SUPPLY CO	**Street 2:**	
Date Became Current:	19960503	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2500 WESTERN AVE
Name:	ROSSMAN INDUSTRIAL SUPPLY CO	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2500 WESTERN AVE
Name:	ROSSMAN INDUSTRIAL SUPPLY CO	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121

Historical Handler Details

Receive Dt:	19940128
Generator Code Description:	Not a Generator, Verified
Handler Name:	ROSSMAN INDUSTRIAL SUPPLY CO

52	*2 of 2*	*SSE*	*0.16 / 856.05*	*71.66 / -34*	***Rossman Industrial Supply Co 2500 WESTERN AVE SEATTLE WA 98121-1308***	***ALL SITES***

Facility/Site ID:	28237942
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility/Site Interaction

Program ID:	WAD988517991
Facility Alternate:	
Interaction ID:	35921
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	16-Feb-1993
Interact End Dt:	31-Dec-1993
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	N
Horizont 1:	NAD83	***GIS latitude:***	47.61424
Horizont 2:	Unknown	***GIS longitude:***	-122.34954

53	*1 of 1*	*ESE*	*0.17 / 878.57*	*112.43 / 7*	***2439 2ND AVE*** ***Seattle WA 98119***	***UST SEATTLE***

Permit No:	3-47025	***Tank Size:***	880
Date Issued:	05/08/2003	***Tank Age:***	60
Fill Material:	No Fill	***Tank Content:***	OIL
Date Decommissioned:	05/08/2003		
Type Decommissioned:	Abandonment in Place		

54	*1 of 1*	*ESE*	*0.17 / 878.94*	*112.43 / 7*	***2434 2ND AVE*** ***Seattle WA 98109***	***UST SEATTLE***

Permit No:	3-46042	***Tank Size:***	300
Date Issued:	02/27/2003	***Tank Age:***	60
Fill Material:	No Fill	***Tank Content:***	OIL
Date Decommissioned:	02/27/2003		
Type Decommissioned:	Abandonment in Place		

55	*1 of 20*	*WNW*	*0.17 / 912.96*	*80.23 / -26*	***BRISTOL MYERS SQUIBB PHARM*** ***RES INST SEA*** ***3005 1ST AVE STE 200*** ***SEATTLE WA 98121***	***RCRA NON GEN***

EPA Handler ID:	WAD067194340
Gen Status Universe:	No Report
Contact Name:	BRISTOL MYERS S BRISTOL MYERS S
Contact Address:	3005 1ST AVE , , SEATTLE , WA, 98121-1010 , US
Contact Phone No and Ext:	206-727-3756
Contact Email:	
Contact Country:	US
County Name:	KING
EPA Region:	10
Land Type:	Private
Receive Date:	19980120
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	3
Receive Date:	19950101
Handler Name:	BRISTOL MYERS SQUIBB PHARM RES INST SEA
Source Type:	Notification
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	19980120
Handler Name:	BRISTOL MYERS SQUIBB PHARM RES INST SEA
Source Type:	Annual/Biennial Report
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator

Hazardous Waste Handler Details

Sequence No:	4
Receive Date:	19960221
Handler Name:	BRISTOL MYERS SQUIBB PHARM RES INST SEA
Source Type:	Notification
Federal Waste Generator Code:	2
Generator Code Description:	Small Quantity Generator

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19971218
Handler Name:	BRISTOL MYERS SQUIBB PHARM RES INST SEA
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	5
Receive Date:	19970221

Handler Name: BRISTOL MYERS SQUIBB PHARM RES INST SEA
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19901231
Handler Name: ONCOGEN
Source Type: Annual/Biennial Report
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Hazardous Waste Handler Details

Sequence No: 7
Receive Date: 19971219
Handler Name: BRISTOL MYERS SQUIBB PHARM RES INST SEA
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19931231
Handler Name: BRISTOL MYERS SQUIBB PHARM RES INST SEA
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19940101
Handler Name: BRISTOL MYERS SQUIBB PHARM RES INST SEA
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 8
Receive Date: 19980120
Handler Name: BRISTOL MYERS SQUIBB PHARM RES INST SEA
Source Type: Notification
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19980120
Handler Name: BRISTOL MYERS SQUIBB PHARM RES INST SEA
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 6
Receive Date: 19971218
Handler Name: BRISTOL MYERS SQUIBB PHARM RES INST SEA
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: BRISTOL MYERS SQUIBB PHARM RES INST SEA
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 3005 1ST AVE STE 200
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Operator
Type: Private
Name: BRISTOL MYERS SQUIBB PHARM RES INST SEA
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 3005 1ST AVE STE 200
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Operator
Type: Private
Name: WANG, DONALD
Date Became Current:
Date Ended Current:
Phone: 206-727-3756
Source Type: Notification
Street No:
Street 1: 3005 1ST AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Owner
Type: Private
Name: BRISTOL MYERS SQUIBB
Date Became Current:
Date Ended Current:
Street No:
Street 1: 345 PARK AVE
Street 2:
City: NEW YORK
State: NY

Phone:	212-546-4000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	10154-0004
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	345 PARK AVE
Name:	BRISTOL MYERS SQUIBB	**Street 2:**	
Date Became Current:		**City:**	NEW YORK
Date Ended Current:		**State:**	NY
Phone:	212-546-4000	**Country:**	US
Source Type:	Notification	**Zip Code:**	10154
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	3005 1ST AVE
Name:	DONALD W	**Street 2:**	
Date Became Current:	19960610	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-727-3756	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121-1010
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	345 PARK AVE
Name:	BRISTOL MYERS SQUIBB	**Street 2:**	
Date Became Current:		**City:**	NEW YORK
Date Ended Current:		**State:**	NY
Phone:	212-546-4000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	10154
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	345 PARK AVE
Name:	BRISTOL MYERS SQUIBB	**Street 2:**	
Date Became Current:		**City:**	NEW YORK
Date Ended Current:		**State:**	NY
Phone:	212-546-4000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	10154-0004
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	345 PARK AVE
Name:	BRISTOL MYERS SQUIBB	**Street 2:**	
Date Became Current:	19960610	**City:**	NEW YORK
Date Ended Current:		**State:**	NY
Phone:	212-546-4000	**Country:**	US
Source Type:	Notification	**Zip Code:**	10154
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	3005 1ST AVE
Name:	WANG, DONALD	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-727-3756	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	345 PARK AVE
Name:	BRISTOL MYERS S B	**Street 2:**	
Date Became Current:	19960610	**City:**	NEW YORK
Date Ended Current:		**State:**	NY
Phone:	212-546-4000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	10154-0004
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	345 PARK AVE
Name:	BRISTOL MYERS SQUIBB	**Street 2:**	
Date Became Current:	19960610	**City:**	NEW YORK
Date Ended Current:		**State:**	NY
Phone:	212-546-4000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	10154

Historical Handler Details

Receive Dt: 19940101
Generator Code Description: Not a Generator, Verified
Handler Name: BRISTOL MYERS SQUIBB PHARM RES INST SEA

Receive Dt: 19980120
Generator Code Description: Large Quantity Generator
Handler Name: BRISTOL MYERS SQUIBB PHARM RES INST SEA

Receive Dt: 19971218
Generator Code Description: Not a Generator, Verified
Handler Name: BRISTOL MYERS SQUIBB PHARM RES INST SEA

Receive Dt: 19901231
Generator Code Description: Large Quantity Generator
Handler Name: ONCOGEN

Receive Dt: 19970221
Generator Code Description: Small Quantity Generator
Handler Name: BRISTOL MYERS SQUIBB PHARM RES INST SEA

Receive Dt: 19980120
Generator Code Description: Large Quantity Generator
Handler Name: BRISTOL MYERS SQUIBB PHARM RES INST SEA

Receive Dt: 19971219
Generator Code Description: Not a Generator, Verified
Handler Name: BRISTOL MYERS SQUIBB PHARM RES INST SEA

Receive Dt: 19950101
Generator Code Description: Not a Generator, Verified
Handler Name: BRISTOL MYERS SQUIBB PHARM RES INST SEA

Receive Dt: 19960221
Generator Code Description: Small Quantity Generator
Handler Name: BRISTOL MYERS SQUIBB PHARM RES INST SEA

Receive Dt: 19931231
Generator Code Description: Small Quantity Generator
Handler Name: BRISTOL MYERS SQUIBB PHARM RES INST SEA

Receive Dt: 19971218
Generator Code Description: Not a Generator, Verified
Handler Name: BRISTOL MYERS SQUIBB PHARM RES INST SEA

---

55 | ***2 of 20*** | ***WNW*** | ***0.17 / 912.96*** | ***80.23 / -26*** | ***Bristol Myers Squibb 3005 1ST AVE SEATTLE WA 98121*** | ***CSCSL NFA***

Fac Site ID:	21448945	***Fac Site ID (OD):***	21448945
Cleanup Site ID:	8279	***Cleanup SiteID(OD):***	8279
Site Status:	NFA	***Site Status (OD):***	No Further Action
NFA Date:	10/25/1999	***Rank (OD):***	
Responsible Unit:	Northwest	***Has Env Coven (OD):***	Yes
Has Insti Control:	Yes	***Respon Unit (OD):***	Northwest
Region:	Northwest	***Region (OD):***	Northwest
County:	King	***County (OD):***	King
Latitude:	47.6177051955481	***Latitude (OD):***	47.617705
Longitude:	-122.354496473872	***Longitude (OD):***	-122.354496

NFA Reason: Voluntary Cleanup Program Review
Alternate Site Names: 3005 FIRST AVENUE,ARE Western Newbrook LLC,Bristol Myers Squibb Pharm Res Inst Sea,Bristol Myers Squibb Research Lab,Dendreon Corp,Econet Inc,Oncogen
Location (OD): ""
(47.617705, -122.354496)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State

NFA Contaminants Detail(s)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant Name: Petroleum-Other
Groundwater: Remediated-Above
Surfacewater:
Soil: Remediated-Above
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Remediated-Above
Sediment:
Air:
Bedrock:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
55	3 of 20	WNW	0.17 / 912.96	80.23 / -26	Bristol Myers Squibb 3005 1ST AVE SEATTLE WA 98121	INST

Facility Site ID: 21448945
Region: Northwest
County: King
Latitude: 47.6177051955481
Longitude: -122.354496473872
Site Name: Bristol Myers Squibb
Address: 3005 1ST AVE
City: SEATTLE
Zip: 98121
Site Name (OD): Bristol Myers Squibb
Address (OD): 3005 1ST AVE
City (OD): SEATTLE
Zipcode (OD): 98121
Location (OD): ""
(47.617705, -122.354496)
Data Source(s): Department of Ecology State of Washington - Environmental Covenants Registry List; Open Data Portal - Institutional Controls or Environmental Covenants Map

Cleanup Site ID: 8279
Region (OD): Northwest
County (OD): King
Latitude (OD): 47.617705
Longitude (OD): -122.354496

Environmental Covenants Registry List

NFA Date: 10/25/1999
Site Status: No Further Action
Tax Parcel No: 0695000135
Instrument Type: Environmental Covenant
Media Restrictions: Groundwater; Soil
Alternate Site Names: 3005 FIRST AVENUE,ARE Western Newbrook LLC,Bristol Myers Squibb Pharm Res Inst Sea,Bristol Myers Squibb Research Lab,Dendreon Corp,Econet Inc,Oncogen
Cnty Recording No: 19990709000794
Cnty Recording Dt: 07/09/1999
Responsible Unit: Northwest
Active Control: Yes
Control Stormwater: No
Control Vapor Gas: No
Prevent Reuse/Relocation: No
Prohibit New Bldg Constr: No
Prohibit Removal or Alteration: No
Prohibit Soil Disturbance: Yes
Ongoing Maint of Remedy: Yes
Require Educational Programs: No
Restrict Access: Yes
Restrict All GW Extr: Yes
Restrict Domestic GW: Yes
Restrict Land Use: Yes
Restrict Sedmnt Cap Disturb: No
Restrict Shellfish and or Finf: No
Restrict Surface Water Use: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Restrict Swim/Beach Play: No
Restrictive Signage: No
Maintain/Protect Monit System: No
Other: No

Open Data Portal - Environmental Covenants Map

Facility Site ID: 21448945
Cleanup Status: No Further Action
Has Env Covenant: Yes
Rank:
Resp Section: Northwest

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
55	4 of 20	WNW	0.17 / 912.96	80.23 / -26	ONCOGEN 3005 1ST AVE SEATTLE WA 98121	DELISTED SHWS

Delisted Contaminated/Hazardous Sites

Fac Site ID: 21448945
Cleanup Site ID: 8279
Brownfield?:
PSI?: Yes
VCP?:
Past VCP:
Has Inst Control:
Site Status: Cleanup Started
Alternate Site Names:
Original Source: CSCS
Record Date: 02-APR-2018
WARM Rank: N
Warm Rank Desc:
Respon Section: Northwest
County: King
Region: Northwest
Latitude: 47.6177051955481
Longitude: -122.354496473872

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
55	5 of 20	WNW	0.17 / 912.96	80.23 / -26	3005 FIRST AVENUE 3005 1ST AVE Seattle WA 98121	UST

UST ID: 102205
Facility Site ID: 21448945
Site Active: Yes
Responsible Unit: Northwest
Active Tag: A8095
Alternate Site Names: ARE Western Newbrook LLC,Bristol Myers Squibb,Bristol Myers Squibb Pharm Res Inst Sea,Bristol Myers Squibb Research Lab,Dendreon Corp,Econet Inc,Oncogen
Region: Northwest
County: King
Latitude: 47.6177051955481
Longitude: -122.354496473872

Tank Detail(s)

Tank Name: 1
Status Date: 08/06/1996
Install Date: 01/01/1979
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material:
Tank Corrosion Protection: None
Tank Manifold:
Tank Release Detection: Weekly Manual Gauging
Tank Tightness Test:
Tank Spill Prevention: None
Tank Overfill Prevention: None
Pipe Material:
Pipe Construction: Single Wall Pipe
Pipe Corrosion Protection: None
Tank SFC:
Dispenser SFC:
Tank Construction:
Tank Capacity:
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Primary Pipe Release Detection:	Other
Secondary Pipe Rel Detect:	
Pipe Pumping System:	
Turbine Sump Construction:	

Compartments

Compartment No:	1
Compart Capacity:	
Stored Substance:	
Used Substance:	

Tank Detail(s)

Tank Name:	2	***Tank Construction:***	Double Wall Tank
Status Date:	08/06/1996	***Tank Capacity:***	1,101 to 2,000 Gallons
Install Date:	07/25/1995	***Actual Capacity:***	2000
Upgrade Date:	07/25/1995	***Pipe Install Date:***	
Perm Closure Date:		***Endorsement Expire:***	09/30/2022

Tank Status:	Operational
Tank Material:	Dielectric Coated Steel
Tank Corrosion Protection:	Sacrificial Anode
Tank Manifold:	
Tank Release Detection:	Automatic Tank Gauging
Tank Tightness Test:	Not Performed
Tank Spill Prevention:	Single Wall Spill Bucket
Tank Overfill Prevention:	Overfill Alarm
Pipe Material:	Flexible Piping
Pipe Construction:	Double Wall Pipe
Pipe Corrosion Protection:	Corrosion Resistant
Tank SFC:	
Dispenser SFC:	
Primary Pipe Release Detection:	Every 3 years Line TT (Non-Safe Suction)
Secondary Pipe Rel Detect:	Interstitial Monitoring (or Sump Sensor)
Pipe Pumping System:	Non-Safe Suction
Turbine Sump Construction:	

Compartments

Compartment No:	1
Compart Capacity:	2000
Stored Substance:	Diesel
Used Substance:	Emergency Power Generation

55	***6 of 20***	***WNW***	***0.17 / 912.96***	***80.23 / -26***	***Bristol Myers Squibb Pharm Res Inst Sea 3005 1ST AVE STE 200 SEATTLE WA 98121***	***ALL SITES***

Facility/Site ID:	63234661
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAD067194340
Facility Alternate:	
Interaction ID:	55634
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG

Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	25-Oct-1985
Interact End Dt:	31-Dec-1997
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System
Program ID:	WAD067194340
Facility Alternate:	
Interaction ID:	55635
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWP
Interaction Desc:	Hazardous Waste Planner
Interact Start Dt:	01-Jan-1992
Interact End Dt:	01-Mar-1998
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	HWPPRT
Database Name Desc:	Hazardous Reporting
Program ID:	WAD067194340
Facility Alternate:	
Interaction ID:	55636
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	TIER2
Interaction Desc:	Emergency/Haz Chem Rpt TIER2
Interact Start Dt:	01-Jan-1996
Interact End Dt:	01-Mar-1997
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	EPCRA
Database Name Desc:	Emergency Planning & Community Right-to-Know Act

Facility Location Detail

Horizontal:	40ft	**Location Verified:**	
Horizont 1:	NAD83HARN	**GIS latitude:**	47.6177682784
Horizont 2:	Digital map or GIS	**GIS longitude:**	-122.35442134

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
55	7 of 20	WNW	0.17 / 912.96	80.23 / -26	Dendreon Corp 3005 1ST AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID:	21448945
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	
Facility Alternate:	Econet Inc
Interaction ID:	31828
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	UST
Interaction Desc:	Underground Storage Tank
Interact Start Dt:	01-Jan-1979
Interact End Dt:	
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	UST
Database Name Desc:	Underground Storage Tanks

Program ID:	WAD003095932
Facility Alternate:	
Interaction ID:	31829
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	30-May-1984
Interact End Dt:	27-Aug-1990
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Program ID:	NW0234
Facility Alternate:	Bristol Myers Squibb
Interaction ID:	126494
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	VOLCLNST
Interaction Desc:	Voluntary Cleanup Sites
Interact Start Dt:	30-Mar-1999
Interact End Dt:	25-Oct-1999
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Program ID:	WAD003095932
Facility Alternate:	Astellas Pharma US Inc
Interaction ID:	133568
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	05-Dec-2019
Interact End Dt:	
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Program ID:	WAD003095932
Facility Alternate:	Unigen Inc Seattle
Interaction ID:	101947
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	15-Jul-2012
Interact End Dt:	31-Dec-2018
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Program ID:	WAD003095932
Facility Alternate:	Dendreon Corp
Interaction ID:	100158
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	01-Dec-2011
Interact End Dt:	31-Dec-2011
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Program ID:	102205
Facility Alternate:	Bristol Myers Squibb
Interaction ID:	126493
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	LUST
Interaction Desc:	LUST Facility
Interact Start Dt:	14-Aug-1989
Interact End Dt:	25-Oct-1999
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Program ID:	WAD003095932
Facility Alternate:	
Interaction ID:	31834
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	01-Mar-2000
Interact End Dt:	31-Dec-2004
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	40ft	**Location Verified:**	
Horizont 1:	NAD83HARN	**GIS latitude:**	47.6177051955
Horizont 2:	Digital map or GIS	**GIS longitude:**	-122.354496474

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
55	8 of 20	WNW	0.17 / 912.96	80.23 / -26	ONCOGEN 3005 1ST AVE SEATTLE WA 98121	DELISTED LST

Delisted Leaking Storage Tanks

Facility Site ID:	21448945	**Latitude:**	47.6177051955481
Cleanup Site ID:	8279	**Longitude:**	-122.354496473872
Responsible Section:	Northwest	**Original Source:**	LUST
Region:	Northwest	**Record Date:**	01-FEB-2018
County:	King		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
55	9 of 20	WNW	0.17 / 912.96	80.23 / -26	Bristol Myers Squibb Pharm Res Inst Sea 3005 1ST AVE STE 200 SEATTLE WA 98121	ICR

Cleanup Site ID:	2341	**WRIA ID:**	8
Facility Site ID:	63234661	**Is NFA Site:**	Yes
Site Status:	No Further Action Required	**Responsible Unit:**	Northwest
Statute:	MTCA	**Latitude:**	47.617849999999997
Rank:		**Longitude:**	-122.35396
Rank Description:		**Legislative District:**	36
Has Env Covenant:	Yes	**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:	4127	**Start Date:**	1999-03-30
VCP Prj No:		**End Date:**	1999-10-25
Activity Name:	Independent Report Review - Paid	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	Ecology
County Name:	King	**Project Manager:**	Lillie, John T
Applies to:	CleanupUnit		
Applies to Description:			

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	
Activity Name:	Ecology Periodic Review	**Legal Mechanism:**	Independent
Activity Status:	Planned	**Performed by:**	Ecology
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	1999-10-25
Activity Name:	Site Status Changed to NFA	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	2009-12-09
VCP Prj No:		**End Date:**	2010-02-01
Activity Name:	Ecology Periodic Review	**Legal Mechanism:**	Independent
Activity Status:	Completed	**Performed by:**	Ecology
County Name:	King	**Project Manager:**	Hickey, Joe
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Media Contaminants

Contaminant Type:	Petroleum Products-Unspecified	**Sediment:**	
Groundwater:	R	**Sediment Desc.:**	
Groundwater Desc.:	Remediated	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	R	**Bedrock Desc.:**	
Soil Desc.:	Remediated	**County Name:**	King

---

55 | ***10 of 20*** | ***WNW*** | ***0.17 / 912.96*** | ***80.23 / -26*** | ***BRISTOL-MEYERS SQUIBB RESEARCH LAB
3005 1ST AVE
SEATTLE WA 98121*** | ***ICR***

Cleanup Site ID:	8280	**WRIA ID:**	8
Facility Site ID:	21448945	**Is NFA Site:**	Yes
Site Status:	No Further Action Required	**Responsible Unit:**	Northwest
Statute:	MTCA	**Latitude:**	47.617705195548126
Rank:		**Longitude:**	-122.35449647387226
Rank Description:		**Legislative District:**	36
Has Env Covenant:		**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:	4234	**Start Date:**	1994-06-22
VCP Prj No:		**End Date:**	1994-06-22
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Applies to Description: Leaking Underground Storage Tank

Related ID: 4234 **Start Date:** 1998-11-24
VCP Prj No: **End Date:** 1998-12-24
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: **Start Date:**
VCP Prj No: **End Date:** 1999-10-25
Activity Name: Site Status Changed to NFA **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: CleanupSite
Applies to Description:

Related ID: 4234 **Start Date:** 1993-10-05
VCP Prj No: **End Date:** 1993-10-05
Activity Name: LUST - Notification **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 4234 **Start Date:** 1995-11-08
VCP Prj No: **End Date:** 1996-01-10
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 4234 **Start Date:** 1994-03-08
VCP Prj No: **End Date:** 1994-03-08
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Media Contaminants

Contaminant Type: Petroleum-Other **Sediment:**
Groundwater: C **Sediment Desc.:**
Groundwater Desc.: Confirmed Above Cleanup Level **Air:**
Surface Water: **Air Desc.:**
Surfacewater Desc.: **Bedrock:**
Soil: C **Bedrock Desc.:**
Soil Desc.: Confirmed Above Cleanup Level **County Name:** King

---

55 | ***11 of 20*** | ***WNW*** | ***0.17 / 912.96*** | ***80.23 / -26*** | ***ONCOGEN 3005 1ST AVE SEATTLE WA 98121*** | ***ICR***

Cleanup Site ID: 8279 **WRIA ID:** 8
Facility Site ID: 21448945 **Is NFA Site:**
Site Status: Cleanup Started **Responsible Unit:** Northwest
Statute: MTCA **Latitude:** 47.617705195548126
Rank: **Longitude:** -122.35449647387226
Rank Description: **Legislative District:** 36
Has Env Covenant: **Congr District:** 7
Is Brownfiled Site: **County Name:** King
Is PSI Site: Yes

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Cleanup Activities

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	1989-08-14
Activity Name:	Site Discovery/Release Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		***Start Date:***	2013-04-08
VCP Prj No:		***End Date:***	2013-05-21
Activity Name:	Site Hazard Assessment/Federal Site Inspection	***Legal Mechanism:***	
Activity Status:	Canceled	***Performed by:***	Ecology w/ Contractor
County Name:	King	***Project Manager:***	Musa, Donna
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		***Start Date:***	2011-07-01
VCP Prj No:		***End Date:***	2011-07-01
Activity Name:	Initial Investigation / Federal Preliminary Assessment	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	Ecology w/ Contractor
County Name:	King	***Project Manager:***	Olsen, Russ
Applies to:	CleanupSite		
Applies to Description:			

Related ID:	384	***Start Date:***	1989-09-21
VCP Prj No:		***End Date:***	1989-09-21
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	384	***Start Date:***	1990-02-20
VCP Prj No:		***End Date:***	1990-02-20
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	384	***Start Date:***	1989-08-14
VCP Prj No:		***End Date:***	1989-08-14
Activity Name:	LUST - Notification	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Media Contaminants

Contaminant Type:	Petroleum-Other	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

55	***12 of 20***	***WNW***	***0.17 / 912.96***	***80.23 / -26***	***Dendreon Corp 3005 1ST AVE SEATTLE WA 98121***	***ICR***

Cleanup Site ID:	2608	***WRIA ID:***	8

Facility Site ID:	21448945	**Is NFA Site:**	Yes
Site Status:	No Further Action Required	**Responsible Unit:**	Northwest
Statute:	MTCA	**Latitude:**	47.617705195548126
Rank:		**Longitude:**	-122.35449647387226
Rank Description:		**Legislative District:**	36
Has Env Covenant:	Yes	**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	1999-10-25
Activity Name:	Site Status Changed to NFA	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	
VCP Prj No:	NW0234	**End Date:**	
Activity Name:	VCP Opinion on Cleanup Action	**Legal Mechanism:**	
Activity Status:	Canceled	**Performed by:**	
County Name:	King	**Project Manager:**	Lillie, John T
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	
VCP Prj No:	NW0234	**End Date:**	1999-10-25
Activity Name:	VCP Termination	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	2009-12-09
VCP Prj No:		**End Date:**	2010-02-01
Activity Name:	Ecology Periodic Review	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	Ecology
County Name:	King	**Project Manager:**	Hickey, Joe
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		**Start Date:**	1999-03-30
VCP Prj No:	NW0234	**End Date:**	
Activity Name:	VCP Application	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Media Contaminants

Contaminant Type:	Pesticides-Unspecified	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

55	***13 of 20***	***WNW***	***0.17 / 912.96***	***80.23 / -26***	***PLANT HEALTH CARE, INC 3005 1ST AVE SUITE 301 SEATTLE WA 98121***	***SSTS***

EPA Region:	10

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Establishment No:	71771-WA-1
Est Create Update Date:	
Est Site County:	King
Est Site Country:	USA
Est Mailing Address:	3005 1ST AVE
Est Mailing Address Line 2:	SUITE 301
Est Mail City:	SEATTLE
Est Mail State:	WA
Est Mail Zip:	98121
Est Mail Country:	USA
Company Name:	PLANT HEALTH CARE, INC.
Co Site Address Line 1:	2626 GLENWOOD AVENUE, SUITE 350
Co Site Address Line 2:	-
Co Site City:	RALEIGH
Co Site State:	NC
Co Site Zip:	27608-1004
Co Site Country:	USA
Co Mailing Address Line 1:	2626 GLENWOOD AVENUE, SUITE 350
Co Mail Address Line 2:	-
Co Mail City:	RALEIGH
Co Mail State:	NC
Co Mail Zip:	27608-1004
Co Mail Country:	USA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
55	14 of 20	WNW	0.17 / 912.96	80.23 / -26	Bristol Myers Squibb 3005 1ST AVE SEATTLE WA 98121	VCP

Facility Site ID:	21448945	**County:**	King
Cleanup Site ID:	8279	**Latitude:**	47.6177051955481
Region:	Northwest	**Longitude:**	-122.354496473872
Alternate Site Names:	3005 FIRST AVENUE,ARE Western Newbrook LLC,Bristol Myers Squibb Pharm Res Inst Sea,Bristol Myers Squibb Research Lab,Dendreon Corp,Econet Inc,Oncogen		
Data Source(s):	No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State		

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status:	NFA
NFA Date:	10/25/1999
Responsible Unit:	Northwest
Has Inst Control:	Yes
NFA Reason:	Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name:	Petroleum-Other	**Sediment:**	
Groundwater:	Remediated-Above	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Above		
Contaminant Name:	Petroleum-Diesel	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Above		

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status:	No Further Action
Site Rank:	
Has Inst Control:	Yes
Current VCP:	
Past VCP:	Yes
Responsible Unit:	Northwest

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name:	Petroleum-Diesel	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Remediated-Above		
Contaminant Name:	Petroleum-Other	***Sediment:***	
Groundwater:	Remediated-Above	***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Remediated-Above		

55	*15 of 20*	*WNW*	*0.17 / 912.96*	*80.23 / -26*	***Bristol Myers Squibb*** ***3005 1ST AVE*** ***SEATTLE WA 98121***	***LUST***

Facility Site ID:	21448945	***County:***	King
Cleanup Site ID:	8279	***Latitude:***	47.6177051955481
Responsible Unit:	Northwest	***Longitude:***	-122.354496473872
Region:	Northwest		

Alternate Site Names: 3005 FIRST AVENUE,ARE Western Newbrook LLC,Bristol Myers Squibb Pharm Res Inst Sea,Bristol Myers Squibb Research Lab,Dendreon Corp,Econet Inc,Oncogen

Tank Detail(s)

UST ID:	102205	***Status Date:***	10/25/1999
LUST ID:	384	***Release Date:***	08/14/1989
LUST Status:	LUST - NFA		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Diesel	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Remediated-Above		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Other	***Sediment:***	
Groundwater:	Remediated-Above	***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Remediated-Above		

55	*16 of 20*	*WNW*	*0.17 / 912.96*	*80.23 / -26*	***Cyrus Biotechnology Inc Seattle*** ***3005 1st Ave Ste 203*** ***Seattle WA 98121***	***ALL SITES***

Facility/Site ID: 76772
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAH000059595
Facility Alternate:	Cyrus Biotechnology Inc Seattle
Interaction ID:	143491
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	01-Apr-2022

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Address
Location Verified:
GIS latitude: 47.61783
GIS longitude: -122.35454

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
55	17 of 20	WNW	0.17 / 912.96	80.23 / -26	Affini-T Therapeutics Seattle 3005 1st Ave Ste 102 Seattle WA 98121	ALL SITES

Facility/Site ID: 77309
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000059535
Facility Alternate: Affini-T Therapeutics Seattle
Interaction ID: 143292
Interaction Status: A
Interac Status Desc: Active
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 15-Feb-2022
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Address
Location Verified:
GIS latitude: 47.61779
GIS longitude: -122.35455

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
55	18 of 20	WNW	0.17 / 912.96	80.23 / -26	CYRUS BIOTECHNOLOGY INC SEATTLE 3005 1ST AVE STE 203 SEATTLE WA 98121	RCRA VSQG

EPA Handler ID: WAH000059595
Gen Status Universe: VSG
Contact Name: ERIK PROCKO
Contact Address: 3005 1ST AVE STE 203 , , SEATTLE , WA, 98121 , US
Contact Phone No and Ext: 617-792-7868
Contact Email: ERIK.PROCKO@CYRUSBIO.COM
Contact Country: US
County Name: KING
EPA Region: 10
Land Type: Private
Receive Date: 20220303
Location Latitude: 47.61783
Location Longitude: -122.35454

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20220303
Handler Name: CYRUS BIOTECHNOLOGY INC SEATTLE
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: U002
Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: U236
Waste Code Description: 2,7-NAPHTHALENEDISULFONIC ACID,3,3'-[(3,3'-DIMETHYL[1,1'-BIPHENYL]-4,4'-DIYL)BIS(AZO)BIS[5-AMINO-4-HYDROXY]-, TETRASODIUM SALT (OR) TRYPAN BLUE

Hazardous Waste Code: U122
Waste Code Description: FORMALDEHYDE

Hazardous Waste Code: U044
Waste Code Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Hazardous Waste Code: P105
Waste Code Description: SODIUM AZIDE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: WP02
Waste Code Description: Washington State Dangerous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of 0.01% to 1.0%.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: U154

Waste Code Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Hazardous Waste Code: U188
Waste Code Description: PHENOL

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	400 9TH AVE N STE 122
Name:	BCAL 3005 PROPERTY LLC	**Street 2:**	
Date Became Current:	20200901	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-922-6330	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	3005 1ST AVE STE 203
Name:	ERIK PROCKO	**Street 2:**	
Date Became Current:	20220201	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	617-792-7868	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	3005 1ST AVE STE 203
Name:	LUCAS NIVON	**Street 2:**	
Date Became Current:	20140423	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	617-818-2334	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121

55	***19 of 20***	***WNW***	***0.17 / 912.96***	***80.23 / -26***	***AFFINI-T THERAPEUTICS SEATTLE 3005 1ST AVE STE 102 SEATTLE WA 98121***	***RCRA VSQG***

EPA Handler ID: WAH000059535
Gen Status Universe: VSG
Contact Name: KAILI CHICKERING
Contact Address: 3005 1ST AVE STE 102 , , SEATTLE , WA, 98121 , US
Contact Phone No and Ext: 253-232-8192
Contact Email: KAILI.CHICKERING@AFFINITTX.COM
Contact Country: US
County Name: KING
EPA Region: 10
Land Type: Private
Receive Date: 20220215
Location Latitude: 47.61779
Location Longitude: -122.35455

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No

Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20220215
Handler Name:	AFFINI-T THERAPEUTICS SEATTLE
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator
Source Type:	Notification

Waste Code Details

Hazardous Waste Code:	D001
Waste Code Description:	IGNITABLE WASTE

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	3005 1ST AVE STE 102
Name:	AFFINI-T THERAPEUTICS	***Street 2:***	
Date Became Current:	20220117	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	253-232-8192	***Country:***	US
Source Type:	Notification	***Zip Code:***	98121

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	3005 1ST AVE STE 102
Name:	AFFINI-T THERAPEUTICS	***Street 2:***	
Date Became Current:	20220117	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-785-9353	***Country:***	US
Source Type:	Notification	***Zip Code:***	98121

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	409 9TH AVE N
Name:	ELLIOTT BAY LABS/CBRE PROPERTY MANAGEMENT	***Street 2:***	STE 122
Date Became Current:	20200914	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-922-6330	***Country:***	US
Source Type:	Notification	***Zip Code:***	98109

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
55	*20 of 20*	*WNW*	*0.17 / 912.96*	*80.23 / -26*	***ASTELLAS PHARMA US INC 3005 1ST AVE SEATTLE WA 98121***	***RCRA NON GEN***

EPA Handler ID:	WAD003095932
Gen Status Universe:	No Report
Contact Name:	SHEILA LOCKWOOD
Contact Address:	3005 1ST AVE , , SEATTLE , WA, 98121 , US
Contact Phone No and Ext:	206-785-6333
Contact Email:	SHEILA.LOCKWOOD@UNIVERSALCELLS.COM
Contact Country:	US
County Name:	KING
EPA Region:	10

Land Type: Private
Receive Date: 20220225
Location Latitude: 47.61785
Location Longitude: -122.35396

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20000306
Handler Name: DENDREON CORP
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 18
Receive Date: 20160119
Handler Name: UNIGEN INC SEATTLE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON

DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 15
Receive Date: 20130228
Handler Name: UNIGEN INC SEATTLE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF

THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20000306
Handler Name: DENDREON CORP
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 23
Receive Date: 20190104
Handler Name: UNIGEN INC SEATTLE
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 11
Receive Date: 20120320
Handler Name: DENDREON CORP
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: D039
Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Code: WT01
Waste Code Description: Washington State Extremely Hazardous Toxic Waste with a toxic constituents concentration greater than or equal to 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: WSC2
Waste Code Description: Washington State solid or semisolid corrosive Dangerous Waste with a pH less than or equal to 2, or greater than or equal to 12.5, based upon a specific testing method.

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Handler Details

Sequence No: 12
Receive Date: 20120625
Handler Name: DENDREON CORP
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 9
Receive Date: 20050421
Handler Name: DENDREON CORP
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20150101
Handler Name: UNIGEN INC SEATTLE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE

CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 6
Receive Date: 20030203
Handler Name: DENDREON CORP
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 8
Receive Date: 20050420
Handler Name: DENDREON CORP
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 16
Receive Date: 20140221
Handler Name: UNIGEN INC SEATTLE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: F002

Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 25
Receive Date: 20210510
Handler Name: ASTELLAS PHARMA US INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: WP02
Waste Code Description: Washington State Dangerous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of 0.01% to 1.0%.

Hazardous Waste Code: U002
Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Handler Details

Sequence No: 26
Receive Date: 20220225
Handler Name: ASTELLAS PHARMA US INC
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19901231
Handler Name: GENETIC SYSTEMS CORP
Source Type: Annual/Biennial Report
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Hazardous Waste Handler Details

Sequence No: 14
Receive Date: 20120626
Handler Name: DENDREON CORP
Source Type: Implementer

Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 21
Receive Date: 20180103
Handler Name: UNIGEN INC SEATTLE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 22
Receive Date: 20190103
Handler Name: UNIGEN INC SEATTLE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19900919
Handler Name: DENDREON CORP
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 20020122
Handler Name: DENDREON CORP
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 19
Receive Date: 20170127
Handler Name: UNIGEN INC SEATTLE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 20
Receive Date: 20170502
Handler Name: UNIGEN INC SEATTLE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: WT02

Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 24
Receive Date: 20191210
Handler Name: ASTELLAS PHARMA US INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20031231
Handler Name: DENDREON CORP
Source Type: Annual/Biennial Report
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 20001218
Handler Name: DENDREON CORP
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19900918

Handler Name: DENDREON CORP
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 7
Receive Date: 20040122
Handler Name: DENDREON CORP
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 13
Receive Date: 20120625
Handler Name: UNIGEN INC SEATTLE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D022

Waste Code Description: CHLOROFORM

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20120320
Handler Name: DENDREON CORP
Source Type: Annual/Biennial Report update with Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: D039
Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: WSC2
Waste Code Description: Washington State solid or semisolid corrosive Dangerous Waste with a pH less than or equal to 2, or greater than or equal to 12.5, based upon a specific testing method.

Hazardous Waste Code: WT01
Waste Code Description: Washington State Extremely Hazardous Toxic Waste with a toxic constituents concentration greater than or equal to 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Handler Details

Sequence No: 10
Receive Date: 20120301
Handler Name: DENDREON CORP
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 17
Receive Date: 20150205
Handler Name: UNIGEN INC SEATTLE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	1301 2ND AVENUE
Name:	DENDREON CORP	***Street 2:***	STE 3200
Date Became Current:	20000301	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-256-4545	***Country:***	US
Source Type:	Implementer	***Zip Code:***	98101

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	3005 1ST AVE
Name:	DENDREON CORP	***Street 2:***	
Date Became Current:	20000301	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-256-4545	***Country:***	US
Source Type:	Notification	***Zip Code:***	98121

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	3005 1ST AVE
Name:	JEFF WILLIAMS	***Street 2:***	
Date Became Current:	19000101	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:		***Country:***	US
Source Type:	Annual/Biennial Report	***Zip Code:***	98121-1010

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	135 N LOS ROBLES AVE
Name:	ALEXANDREA REAL ESTATE EQUITAS INC	***Street 2:***	STE 250
Date Became Current:		***City:***	PASADENA
Date Ended Current:		***State:***	CA
Phone:	626-578-9693	***Country:***	US
Source Type:	Implementer	***Zip Code:***	91101

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	3005 1ST AVE
Name:	UNIGEN INC	***Street 2:***	
Date Became Current:	20100301	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	253-274-7160	***Country:***	US
Source Type:	Implementer	***Zip Code:***	98121

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	3005 1ST AVE
Name:	WILLIAMS, JEFF	***Street 2:***	
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-256-4545	***Country:***	US
Source Type:	Implementer	***Zip Code:***	98121

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	135 N LOS ROBLES AVE
Name:	ALEXANDREA REAL ESTATE EQUITAS INC	***Street 2:***	STE 250
Date Became Current:		***City:***	PASADENA
Date Ended Current:		***State:***	CA
Phone:	626-578-9693	***Country:***	US
Source Type:	Notification	***Zip Code:***	91101

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	3005 1ST AVE
Name:	WILLIAMS, JEFF	***Street 2:***	
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-256-4545	***Country:***	US
Source Type:	Notification	***Zip Code:***	98121

Owner/Operator Ind:	Current Owner	***Street No:***	

Type:	Private	**Street 1:**	3005 1ST AVE
Name:	ECONET INC	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	360-486-8300	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	3005 1ST AVE
Name:	DENDREON CORP	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	3005 1ST AVE
Name:	DENDREON CORP	**Street 2:**	
Date Became Current:	20000301	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	98121-1010
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	1208 EASTLAKE AVE E
Name:	YOUNG, JENNIFER	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-455-2240	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98102
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	1 ASTELLAS WAY
Name:	ASTELLAS PHARMA US INC	**Street 2:**	
Date Became Current:	20180214	**City:**	NORTHBROOK
Date Ended Current:		**State:**	IL
Phone:	206-785-6333	**Country:**	US
Source Type:	Notification	**Zip Code:**	60062
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	1208 EASTLAKE AVE E
Name:	JENNIFER YOUNG	**Street 2:**	
Date Became Current:	20111201	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-455-2240	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	98102-3703
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2121 S STATE ST
Name:	ECONET INC	**Street 2:**	STE 400
Date Became Current:	20171231	**City:**	TACOMA
Date Ended Current:		**State:**	WA
Phone:	253-274-7130	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98405
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	3005 1ST AVE
Name:	UNIGEN INC	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	360-486-8200	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2121 S STATE ST
Name:	ECONET INC	**Street 2:**	STE 400
Date Became Current:	20171231	**City:**	TACOMA
Date Ended Current:		**State:**	WA
Phone:	253-274-7130	**Country:**	US

Source Type:	Notification	**Zip Code:**	98405
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	1 ASTELLAS WAY
Name:	ASTELLAS PHARMA US INC,	**Street 2:**	
Date Became Current:	20180214	**City:**	NORTHBROOK
Date Ended Current:		**State:**	IL
Phone:	206-785-6333	**Country:**	US
Source Type:	Notification	**Zip Code:**	60062
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	3005 1ST AVE
Name:	UNIGEN INC	**Street 2:**	
Date Became Current:	20100301	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	360-486-8200	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	3005 1ST AVE
Name:	ECONET INC	**Street 2:**	
Date Became Current:	20100301	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	360-486-8300	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	3005 1ST AVE
Name:	ECONET INC	**Street 2:**	
Date Became Current:	20100301	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-629-3028	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	1942 4TH AVE W
Name:	ELLIOT BAY VENTURES LLC	**Street 2:**	
Date Became Current:	20180612	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-617-6988	**Country:**	US
Source Type:	Notification	**Zip Code:**	98119
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	1301 2ND AVENUE
Name:	DENDREON CORP	**Street 2:**	STE 3200
Date Became Current:	20000301	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-256-4545	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	98101-0004
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	3005 1ST AVE
Name:	DENDREON CORP	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-256-4545	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121-1010
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	3005 1ST AVE
Name:	DENDREON CORP	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	3005 1ST AVE
Name:	DENDREON CORP	**Street 2:**	

Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	1208 EASTLAKE AVE E
Name:	YOUNG, JENNIFER	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-455-2240	**Country:**	US
Source Type:	Notification	**Zip Code:**	98102
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	3005 1ST AVE
Name:	DENDREON CORP	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	3005 1ST AVE
Name:	DENDREON CORP	**Street 2:**	
Date Became Current:	20000301	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-256-4545	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	1 ASTELLAS WAY
Name:	ASTELLAS PHARMA US INC	**Street 2:**	
Date Became Current:	20180214	**City:**	NORTHBROOK
Date Ended Current:		**State:**	IL
Phone:	978-493-3043	**Country:**	US
Source Type:	Notification	**Zip Code:**	60062
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	1301 2ND AVENUE
Name:	DENDREON CORP	**Street 2:**	STE 3200
Date Became Current:	20000301	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-256-4545	**Country:**	US
Source Type:	Notification	**Zip Code:**	98101
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	1 ASTELLAS WAY
Name:	ASTELLAS PHARMA US INC	**Street 2:**	
Date Became Current:	20180214	**City:**	NORTHBROOK
Date Ended Current:		**State:**	IL
Phone:	224-205-5946	**Country:**	US
Source Type:	Notification	**Zip Code:**	60062
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	3005 1ST AVE
Name:	ECONET INC	**Street 2:**	
Date Became Current:	20100301	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-629-3028	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	3005 1ST AVE
Name:	UNIGEN INC	**Street 2:**	
Date Became Current:	20100301	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	253-274-7160	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121

Historical Handler Details

Receive Dt: 20001218
Generator Code Description: Very Small Quantity Generator
Handler Name: DENDREON CORP

Receive Dt: 20150101
Generator Code Description: Very Small Quantity Generator
Handler Name: UNIGEN INC SEATTLE

Receive Dt: 20130228
Generator Code Description: Very Small Quantity Generator
Handler Name: UNIGEN INC SEATTLE

Receive Dt: 20190103
Generator Code Description: Very Small Quantity Generator
Handler Name: UNIGEN INC SEATTLE

Receive Dt: 20040122
Generator Code Description: Very Small Quantity Generator
Handler Name: DENDREON CORP

Receive Dt: 20120625
Generator Code Description: Very Small Quantity Generator
Handler Name: UNIGEN INC SEATTLE

Receive Dt: 20170502
Generator Code Description: Very Small Quantity Generator
Handler Name: UNIGEN INC SEATTLE

Receive Dt: 20120320
Generator Code Description: Small Quantity Generator
Handler Name: DENDREON CORP

Receive Dt: 19900918
Generator Code Description: Not a Generator, Verified
Handler Name: DENDREON CORP

Receive Dt: 20120625
Generator Code Description: Not a Generator, Verified
Handler Name: DENDREON CORP

Receive Dt: 20170127
Generator Code Description: Very Small Quantity Generator
Handler Name: UNIGEN INC SEATTLE

Receive Dt: 20120301
Generator Code Description: Small Quantity Generator
Handler Name: DENDREON CORP

Receive Dt: 20210510
Generator Code Description: Very Small Quantity Generator
Handler Name: ASTELLAS PHARMA US INC

Receive Dt: 20020122
Generator Code Description: Very Small Quantity Generator
Handler Name: DENDREON CORP

Receive Dt: 20000306
Generator Code Description: Very Small Quantity Generator
Handler Name: DENDREON CORP

Receive Dt: 19901231
Generator Code Description: Large Quantity Generator
Handler Name: GENETIC SYSTEMS CORP

Receive Dt: 20190104
Generator Code Description: Not a Generator, Verified

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Handler Name: UNIGEN INC SEATTLE

Receive Dt: 20050420
Generator Code Description: Very Small Quantity Generator
Handler Name: DENDREON CORP

Receive Dt: 20180103
Generator Code Description: Very Small Quantity Generator
Handler Name: UNIGEN INC SEATTLE

Receive Dt: 20031231
Generator Code Description: Not a Generator, Verified
Handler Name: DENDREON CORP

Receive Dt: 19900919
Generator Code Description: Not a Generator, Verified
Handler Name: DENDREON CORP

Receive Dt: 20000306
Generator Code Description: Not a Generator, Verified
Handler Name: DENDREON CORP

Receive Dt: 20160119
Generator Code Description: Very Small Quantity Generator
Handler Name: UNIGEN INC SEATTLE

Receive Dt: 20140221
Generator Code Description: Very Small Quantity Generator
Handler Name: UNIGEN INC SEATTLE

Receive Dt: 20150205
Generator Code Description: Very Small Quantity Generator
Handler Name: UNIGEN INC SEATTLE

Receive Dt: 20050421
Generator Code Description: Not a Generator, Verified
Handler Name: DENDREON CORP

Receive Dt: 20030203
Generator Code Description: Very Small Quantity Generator
Handler Name: DENDREON CORP

Receive Dt: 20120626
Generator Code Description: Not a Generator, Verified
Handler Name: DENDREON CORP

Receive Dt: 20120320
Generator Code Description: Small Quantity Generator
Handler Name: DENDREON CORP

Receive Dt: 20191210
Generator Code Description: Very Small Quantity Generator
Handler Name: ASTELLAS PHARMA US INC

56	1 of 1	SE	0.18 / 931.34	104.13 / -2	2446 1ST AVE Seattle WA 98119	UST SEATTLE

Permit No: 3-39696
Date Issued: 09/24/2001
Fill Material: No Fill
Date Decommissioned: 09/24/2001
Type Decommissioned: Abandonment in Place
Tank Size: 300
Tank Age: 20+
Tank Content: HEATING OIL

57	1 of 3	SSW	0.18 / 931.76	30.43 / -75	Belltown Pea Patch ELLIOTT AVE & VINE ST	CSCSL NFA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

SEATTLE WA 98121

Fac Site ID:	55253681	**Fac Site ID (OD):**	55253681
Cleanup Site ID:	3968	**Cleanup SiteID(OD):**	3968
Site Status:	NFA	**Site Status (OD):**	No Further Action
NFA Date:	08/02/2002	**Rank (OD):**	
Responsible Unit:	Northwest	**Has Env Coven (OD):**	
Has Insti Control:		**Respon Unit (OD):**	Northwest
Region:	Northwest	**Region (OD):**	Northwest
County:	King	**County (OD):**	King
Latitude:	47.6140503550419	**Latitude (OD):**	47.61405
Longitude:	-122.351069929127	**Longitude (OD):**	-122.35107

NFA Reason: Site Hazard Assessment
Alternate Site Names:
Location (OD): ""
(47.61405, -122.35107)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

NFA Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Suspected
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Metals Priority Pollutants
Groundwater: Suspected
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Metals Priority Pollutants
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Metals Priority Pollutants
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Suspected

57	2 of 3	SSW	0.18 / 931.76	30.43 / -75	BELLTOWN PEA PATCH ELLIOTT AVE & VINE ST SEATTLE WA 98121	ALL SITES

Facility/Site ID: 55253681
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	
Facility Alternate:	BELLTOWN PEA PATCH
Interaction ID:	51299
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	SCS
Interaction Desc:	State Cleanup Site
Interact Start Dt:	01-Aug-1999
Interact End Dt:	02-Aug-2002
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Facility Location Detail

Horizontal:	40ft	**Location Verified:**	
Horizont 1:	NAD83HARN	**GIS latitude:**	47.614050355
Horizont 2:	Digital map or GIS	**GIS longitude:**	-122.351069929

57	3 of 3	SSW	0.18 / 931.76	30.43 / -75	BELLTOWN PEA PATCH ELLIOTT AVE & VINE ST SEATTLE WA 98121	ICR

Cleanup Site ID:	3968	**WRIA ID:**	8
Facility Site ID:	55253681	**Is NFA Site:**	Yes
Site Status:	No Further Action Required	**Responsible Unit:**	Northwest
Statute:	MTCA	**Latitude:**	47.614050355041897
Rank:		**Longitude:**	-122.35106992912699
Rank Description:		**Legislative District:**	36
Has Env Covenant:		**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		**Start Date:**	1999-10-26
VCP Prj No:		**End Date:**	1999-10-26
Activity Name:	Initial Investigation / Federal Preliminary Assessment	**Legal Mechanism:**	
Activity Status:	Canceled	**Performed by:**	Ecology
County Name:	King	**Project Manager:**	Polayes, Joanne
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	2000-12-12
VCP Prj No:		**End Date:**	2000-12-20
Activity Name:	Initial Investigation / Federal Preliminary Assessment	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	Ecology
County Name:	King	**Project Manager:**	Bremer, Steve
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2001-03-12
Activity Name:	Early Notice Letter(s)	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Bremer, Steve
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2002-08-02
Activity Name:	Site Status Changed to NFA	**Legal Mechanism:**	

Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	CleanupSite		
Applies to Description:			
Related ID:		**Start Date:**	2002-03-12
VCP Prj No:		**End Date:**	2002-08-02
Activity Name:	Site Hazard Assessment/Federal Site Inspection	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	Local Government
County Name:	King	**Project Manager:**	County Health-NW
Applies to:	CleanupSite		
Applies to Description:			

Media Contaminants

Contaminant Type:	Petroleum Products-Unspecified	**Sediment:**	
Groundwater:	S	**Sediment Desc.:**	
Groundwater Desc.:	Suspected	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	S	**Bedrock Desc.:**	
Soil Desc.:	Suspected	**County Name:**	King
Contaminant Type:	Metals Priority Pollutants	**Sediment:**	
Groundwater:	S	**Sediment Desc.:**	
Groundwater Desc.:	Suspected	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	B	**Bedrock Desc.:**	
Soil Desc.:	Below Cleanup Level	**County Name:**	King

58	1 of 8	NE	0.18 / 940.23	131.27 / 26	**Fisher Plaza KOMO TV** **100 4TH AVE N** **SEATTLE WA 98109**	CSCSL NFA

Fac Site ID:	15636867	**Fac Site ID (OD):**	15636867
Cleanup Site ID:	5585	**Cleanup SiteID(OD):**	5585
Site Status:	NFA	**Site Status (OD):**	No Further Action
NFA Date:	02/09/1999	**Rank (OD):**	
Responsible Unit:	Northwest	**Has Env Coven (OD):**	
Has Insti Control:		**Respon Unit (OD):**	Northwest
Region:	Northwest	**Region (OD):**	Northwest
County:	King	**County (OD):**	King
Latitude:	47.6191223899258	**Latitude (OD):**	47.619122
Longitude:	-122.348577946308	**Longitude (OD):**	-122.348578

NFA Reason: Voluntary Cleanup Program Review

Alternate Site Names: FISHER BROADCASTING,FISHER BROADCASTING INC KOMO TV,FISHER PLAZA PHASE I,KOMO RADIO & TV,KOMO TV

Location (OD): ""
(47.619122, -122.348578)

Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

NFA Contaminants Detail(s)

Contaminant Name:	Petroleum-Other
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Open Data Portal - Media and Contaminants as of 2021-09-15

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
58	2 of 8	NE	0.18 / 940.23	131.27 / 26	KOMO RADIO & TV 100 4TH AVE N Seattle WA 98109	UST

UST ID: 7404
Facility Site ID: 15636867
Site Active: No
Responsible Unit: Northwest
Active Tag: A3650
Alternate Site Names: FISHER BROADCASTING,FISHER BROADCASTING INC KOMO TV,FISHER PLAZA KOMO TV,FISHER PLAZA PHASE I,KOMO TV

Region: Northwest
County: King
Latitude: 47.6191223899258
Longitude: -122.348577946308

Tank Detail(s)

Tank Name: 2
Status Date: 08/06/1996
Install Date: 01/01/1984
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Steel
Tank Corrosion Protection: Sacrificial Anode
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material: Steel
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction:
Tank Capacity: 10,000 to 19,999 Gallons
Actual Capacity: 10000
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity: 10000
Stored Substance: Aviation Fuel
Used Substance:

Tank Detail(s)

Tank Name: 1
Status Date: 04/17/1992
Install Date: 01/01/1984
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Steel
Tank Corrosion Protection: Sacrificial Anode
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:

Tank Construction:
Tank Capacity: 2,001 to 4,999 Gallons
Actual Capacity: 4000
Pipe Install Date:
Endorsement Expire:

Pipe Material: Steel
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Compartments

Compartment No: 1
Compart Capacity: 4000
Stored Substance: Diesel
Used Substance:

Tank Detail(s)

Tank Name: 4
Status Date: 04/17/1992
Install Date: 01/06/1992
Upgrade Date: 04/17/1998
Perm Closure Date:
Tank Status: Removed
Tank Material: Dielectric Coated Steel
Tank Corrosion Protection: Sacrificial Anode
Tank Manifold:
Tank Release Detection: Interstitial Monitoring
Tank Tightness Test:
Tank Spill Prevention: Single Wall Spill Bucket
Tank Overfill Prevention: Automatic Shutoff (fill pipe)
Pipe Material: Flexible Piping
Pipe Construction: Double Wall Pipe
Pipe Corrosion Protection: Corrosion Resistant
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection: Interstitial Monitoring (or Sump Sensor)
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:
Tank Construction: Double Wall Tank
Tank Capacity: 10,000 to 19,999 Gallons
Actual Capacity: 15000
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity: 15000
Stored Substance: Diesel
Used Substance:

Tank Detail(s)

Tank Name: 5
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Construction:
Tank Capacity: 1,101 to 2,000 Gallons
Actual Capacity: 2000
Pipe Install Date:
Endorsement Expire:

Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Compartments

Compartment No: 1
Compart Capacity: 2000
Stored Substance: Diesel
Used Substance:

Tank Detail(s)

Tank Name: 3
Status Date: 04/17/1992
Install Date: 01/06/1992
Upgrade Date: 04/17/1998
Perm Closure Date:
Tank Status: Removed
Tank Material: Dielectric Coated Steel
Tank Corrosion Protection: Sacrificial Anode
Tank Manifold:
Tank Release Detection: Interstitial Monitoring
Tank Tightness Test:
Tank Spill Prevention: Single Wall Spill Bucket
Tank Overfill Prevention: Automatic Shutoff (fill pipe)
Pipe Material: Flexible Piping
Pipe Construction: Double Wall Pipe
Pipe Corrosion Protection: Corrosion Resistant
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection: Interstitial Monitoring (or Sump Sensor)
Secondary Pipe Rel Detect:
Pipe Pumping System: Pressurized System
Turbine Sump Construction:

Tank Construction: Double Wall Tank
Tank Capacity: 5,000 to 9,999 Gallons
Actual Capacity: 10000
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity: 10000
Stored Substance: Aviation Fuel
Used Substance: Other

58	*3 of 8*	*NE*	*0.18 / 940.23*	*131.27 / 26*	***FISHER PLAZA KOMO TV*** ***100 4TH AVE N*** ***SEATTLE WA 98109***	***ALL SITES***

Facility/Site ID: 15636867
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Program ID:	CRK000068400
Facility Alternate:	Verizon BUSINESS SETRWA GNI
Interaction ID:	123123
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	TIER2
Interaction Desc:	Emergency/Haz Chem Rpt TIER2
Interact Start Dt:	02-Aug-2007
Interact End Dt:	
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	EPCRA
Database Name Desc:	Emergency Planning & Community Right-to-Know Act

Program ID:	7404
Facility Alternate:	
Interaction ID:	28914
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	LUST
Interaction Desc:	LUST Facility
Interact Start Dt:	14-Jan-1999
Interact End Dt:	09-Feb-1999
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Program ID:	7404
Facility Alternate:	
Interaction ID:	28916
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	UST
Interaction Desc:	Underground Storage Tank
Interact Start Dt:	20-Mar-2000
Interact End Dt:	31-Dec-2000
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	UST
Database Name Desc:	Underground Storage Tanks

Program ID:	
Facility Alternate:	FISHER PLAZA KOMO TV
Interaction ID:	28915
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	VOLCLNST
Interaction Desc:	Voluntary Cleanup Sites
Interact Start Dt:	14-Jan-1999
Interact End Dt:	09-Feb-1999
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Facility Location Detail

Horizontal:	40ft	**Location Verified:**	
Horizont 1:	NAD83HARN	**GIS latitude:**	47.6191223899
Horizont 2:	Digital map or GIS	**GIS longitude:**	-122.348577946

58	4 of 8	NE	0.18 / 940.23	131.27 / 26	VADATA INC 4TH AVE 100 4TH AVE N STE 420 SEATTLE WA 98109	ALL SITES

Facility/Site ID: 15661

Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: CRK000083440
Facility Alternate: VADATA INC 4TH AVE
Interaction ID: 107816
Interaction Status: A
Interac Status Desc: Active
Interaction Type: TIER2
Interaction Desc: Emergency/Haz Chem Rpt TIER2
Interact Start Dt: 26-Feb-2014
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: EPCRA
Database Name Desc: Emergency Planning & Community Right-to-Know Act

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6191733943
GIS longitude: -122.348541408

---

58 | ***5 of 8*** | ***NE*** | ***0.18 / 940.23*** | ***131.27 / 26*** | ***Fisher Plaza KOMO TV 100 4TH AVE N SEATTLE WA 98109*** | ***ICR***

Cleanup Site ID: 5585
Facility Site ID: 15636867
Site Status: No Further Action Required
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site: Yes
WRIA ID: 8
Is NFA Site: Yes
Responsible Unit: Northwest
Latitude: 47.619122389925785
Longitude: -122.34857794630791
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID: 5145
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 1998-06-01
End Date: 1998-01-14
Legal Mechanism:
Performed by:
Project Manager:

Related ID: 5145
VCP Prj No:
Activity Name: LUST - Site Characterization Report
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date:
End Date:
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No: NW0194
Activity Name: VCP Opinion on Cleanup Action
Activity Status: Canceled
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date:
End Date:
Legal Mechanism:
Performed by:
Project Manager: Polayes, Joanne

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	1999-02-09
Activity Name:	Site Status Changed to NFA	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	CleanupSite		
Applies to Description:			

Related ID:	5145	**Start Date:**	1998-12-18
VCP Prj No:		**End Date:**	1999-01-14
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		**Start Date:**	
VCP Prj No:	NW0194	**End Date:**	1999-02-09
Activity Name:	VCP Termination	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	1999-01-14
VCP Prj No:	NW0194	**End Date:**	
Activity Name:	VCP Application	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:	5145	**Start Date:**	1999-01-14
VCP Prj No:		**End Date:**	1999-01-14
Activity Name:	LUST - Notification	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Lillie, John T
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	5145	**Start Date:**	1992-04-20
VCP Prj No:		**End Date:**	1999-01-14
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Media Contaminants

Contaminant Type:	Petroleum-Other	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

58	6 of 8	NE	0.18 / 940.23	131.27 / 26	**Fisher Plaza KOMO TV** **100 4TH AVE N** **SEATTLE WA 98109**	VCP

Facility Site ID:	15636867	**County:**	King
Cleanup Site ID:	5585	**Latitude:**	47.6191223899258
Region:	Northwest	**Longitude:**	-122.348577946308
Alternate Site Names:	FISHER BROADCASTING,FISHER BROADCASTING INC KOMO TV,FISHER PLAZA PHASE I,KOMO RADIO & TV,KOMO TV		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Data Source(s): No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status: NFA
NFA Date: 02/09/1999
Responsible Unit: Northwest
Has Inst Control:
NFA Reason: Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: No Further Action
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

---

58 | **7 of 8** | **NE** | **0.18 / 940.23** | **131.27 / 26** | **Fisher Plaza KOMO TV**
100 4TH AVE N
SEATTLE WA 98109 | **LUST**

Facility Site ID: 15636867
Cleanup Site ID: 5585
Responsible Unit: Northwest
Region: Northwest
County: King
Latitude: 47.6191223899258
Longitude: -122.348577946308
Alternate Site Names: FISHER BROADCASTING,FISHER BROADCASTING INC KOMO TV,FISHER PLAZA PHASE I,KOMO RADIO & TV,KOMO TV

Tank Detail(s)

UST ID: 7404
LUST ID: 5145
LUST Status: LUST - NFA
Status Date: 02/09/1999
Release Date: 01/14/1999

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

---

58 | **8 of 8** | **NE** | **0.18 / 940.23** | **131.27 / 26** | **FRONTIER COMMUNICATIONS**
WA79899
100 4TH AVE N STE 250 | **ALL SITES**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					SEATTLE WA 98109	

Facility/Site ID: 61274
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: CRK000066290
Facility Alternate: FRONTIER COMMUNICATIONS WA79899
Interaction ID: 139399
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: TIER2
Interaction Desc: Emergency/Haz Chem Rpt TIER2
Interact Start Dt: 26-Jun-2006
Interact End Dt: 06-Mar-2018
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: EPCRA
Database Name Desc: Emergency Planning & Community Right-to-Know Act

Facility Location Detail

Horizontal: Unknown
Horizont 1: WGS84
Horizont 2: Address
Location Verified:
GIS latitude: 47.61915
GIS longitude: -122.34857

59	1 of 1	WNW	0.18 / 943.25	72.80 / -33	Bristol Myers Squibb WA	DELISTED SHWS

Delisted Confirmed and Suspected Contaminated Sites

Fac Site ID:
Cleanup Site ID:
Site Status:
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
Responsible Unit:
County:
Region:
Latitude:
Longitude:
Fac Site ID (OD): 21448945
Clnup Site ID (OD): 8279
Site Rank (OD):
Respon Unit (OD):
Has Env Coven (OD):
County (OD):
Region (OD):
City (OD):
Zipcode (OD):
Latitude (OD): 47.61771
Longitude (OD): -122.3545
Site Status (OD): Cleanup Started
Site Name (OD): Bristol Myers Squibb
Address (OD):
Location (OD):
Alternate Site Names:
Data Source(s): Open Data Portal - Media and Contaminants
Original Source: CSCS
Record Date: 28-JUN-2021

60	1 of 8	WNW	0.18 / 945.58	95.95 / -10	UNOCAL SS NO 0355 159 DENNY WAY SEATTLE WA 98119	RCRA NON GEN

EPA Handler ID: WAD988493441
Gen Status Universe: No Report
Contact Name: GARY GUNDERSON

Contact Address:	PO BOX 399 , , EDMONDS , WA, 98020 , US
Contact Phone No and Ext:	360-640-7612
Contact Email:	
Contact Country:	US
County Name:	KING
EPA Region:	10
Land Type:	Other
Receive Date:	19970312
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	19940101
Handler Name:	UNOCAL SS NO 0355
Source Type:	Notification
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	6
Receive Date:	19970312
Handler Name:	UNOCAL SS NO 0355
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19931231
Handler Name:	UNOCAL SS NO 0355
Source Type:	Notification
Federal Waste Generator Code:	2
Generator Code Description:	Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19970311
Handler Name: UNOCAL SS NO 0355
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 19960229
Handler Name: UNOCAL SS NO 0355
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 19970221
Handler Name: UNOCAL SS NO 0355
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 19970311
Handler Name: UNOCAL SS NO 0355
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19970311
Handler Name: UNOCAL SS NO 0355
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: UNOCAL SS NO 0355
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 159 DENNY WAY
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98119

Owner/Operator Ind: Current Owner
Type: Private
Name: UNOCAL
Date Became Current: 19960828
Date Ended Current:
Phone: 360-640-7608
Source Type: Notification
Street No:
Street 1: PO BOX 399
Street 2:
City: EDMONDS
State: WA
Country: US
Zip Code: 98020

Owner/Operator Ind: Current Operator
Street No:

Type:	Private	**Street 1:**	PO BOX 399
Name:	UNOCAL CORP	**Street 2:**	
Date Became Current:		**City:**	EDMONDS
Date Ended Current:		**State:**	WA
Phone:	360-640-7612	**Country:**	US
Source Type:	Notification	**Zip Code:**	98020
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 399
Name:	UNOCAL	**Street 2:**	
Date Became Current:		**City:**	EDMONDS
Date Ended Current:		**State:**	WA
Phone:	360-640-7608	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98020
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 399
Name:	UNOCAL	**Street 2:**	
Date Became Current:	19960828	**City:**	EDMONDS
Date Ended Current:		**State:**	WA
Phone:	360-640-7608	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98020
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	159 DENNY WAY
Name:	UNOCAL SS NO 0355	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98119
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 399
Name:	UNOCAL	**Street 2:**	
Date Became Current:		**City:**	EDMONDS
Date Ended Current:		**State:**	WA
Phone:	360-640-7608	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98020
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 399
Name:	UNOCAL CORP	**Street 2:**	
Date Became Current:		**City:**	EDMONDS
Date Ended Current:		**State:**	WA
Phone:	360-640-7612	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98020
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 399
Name:	UNOCAL	**Street 2:**	
Date Became Current:		**City:**	EDMONDS
Date Ended Current:		**State:**	WA
Phone:	360-640-7608	**Country:**	US
Source Type:	Notification	**Zip Code:**	98020
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 399
Name:	UNOCAL CORP U	**Street 2:**	
Date Became Current:	19960828	**City:**	EDMONDS
Date Ended Current:		**State:**	WA
Phone:	360-640-7612	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98020
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 399
Name:	UNOCAL U	**Street 2:**	
Date Became Current:	19960828	**City:**	EDMONDS
Date Ended Current:		**State:**	WA
Phone:	360-640-7608	**Country:**	US

Source Type: Implementer ***Zip Code:*** 98020

Historical Handler Details

Receive Dt: 19931231
Generator Code Description: Small Quantity Generator
Handler Name: UNOCAL SS NO 0355

Receive Dt: 19940101
Generator Code Description: Not a Generator, Verified
Handler Name: UNOCAL SS NO 0355

Receive Dt: 19970311
Generator Code Description: Not a Generator, Verified
Handler Name: UNOCAL SS NO 0355

Receive Dt: 19970311
Generator Code Description: Very Small Quantity Generator
Handler Name: UNOCAL SS NO 0355

Receive Dt: 19970311
Generator Code Description: Not a Generator, Verified
Handler Name: UNOCAL SS NO 0355

Receive Dt: 19960229
Generator Code Description: Very Small Quantity Generator
Handler Name: UNOCAL SS NO 0355

Receive Dt: 19970221
Generator Code Description: Very Small Quantity Generator
Handler Name: UNOCAL SS NO 0355

---

60 ***2 of 8*** ***WNW*** ***0.18 / 945.58*** ***95.95 / -10*** ***Unocal 0355 159 DENNY WAY SEATTLE WA 98109*** ***CSCSL***

Fac Site ID: 32873776
Cleanup Site ID: 5879
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6183705410899
Longitude: -122.353705239465
Site Name: Unocal 0355
Address: 159 DENNY WAY
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Unocal 0355
Address (OD): 159 DENNY WAY
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): "" (47.618371, -122.353705)
Alternate Site Names: 0355,OVATION PARTNERS LLC,TOSCO 0355,UNION OIL 0355,UNOCAL SERVICE & TIRE INC,Unocal SS No 0355
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Pollution Liability Ins Agcy
Fac Site ID (OD): 32873776
Cleanup SiteID(OD): 5879
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Pollution Liability Insurance Agency
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.353705
Latitude (OD): 47.618371

Contaminants Detail(s)

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels

Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Halogenated Organics
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Halogenated Organics
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Groundwater
Contaminant Status: Below Cleanup Levels

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
60	3 of 8	WNW	0.18 / 945.58	95.95 / -10	UNION OIL 0355 159 DENNY WAY Seattle WA 98109	UST

UST ID: 8421
Facility Site ID: 32873776
Site Active: No
Responsible Unit: Northwest
Active Tag:
Region: Northwest
County: King
Latitude: 47.6183705410899
Longitude: -122.353705239465
Alternate Site Names: 0355,OVATION PARTNERS LLC,TOSCO 0355,Unocal 0355,UNOCAL SERVICE & TIRE INC,Unocal SS No 0355

Tank Detail(s)

Tank Name: TK 2
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:
Tank Construction:
Tank Capacity:
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Unleaded Gasoline

Used Substance:

Tank Detail(s)

Tank Name: TK 3
Status Date: 08/06/1996
Install Date: 01/01/1988
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Fiberglass Reinforced Plastic
Tank Corrosion Protection: Corrosion Resistant
Tank Manifold:
Tank Release Detection: Manual Inventory Control (daily)
Tank Tightness Test:
Tank Spill Prevention: Other
Tank Overfill Prevention: Other
Pipe Material: Fiberglass
Pipe Construction: Single Wall Pipe
Pipe Corrosion Protection: Corrosion Resistant
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System: Pressurized System
Turbine Sump Construction:
Tank Construction: Single Wall Tank
Tank Capacity:
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance:
Used Substance: Motor Fuel for Vehicles

Tank Detail(s)

Tank Name: TK 6
Status Date: 08/06/1996
Install Date: 01/01/1988
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:
Tank Construction:
Tank Capacity: 111 TO 1,100 Gallons
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1

Compart Capacity:
Stored Substance: Heating Fuel
Used Substance:

Tank Detail(s)

Tank Name: 4
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Steel
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material: Steel
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction: Single Wall Tank
Tank Capacity: 111 TO 1,100 Gallons
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Used Oil/Waste Oil
Used Substance:

Tank Detail(s)

Tank Name: 2
Status Date: 08/06/1996
Install Date: 01/01/1988
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Fiberglass Reinforced Plastic
Tank Corrosion Protection: Corrosion Resistant
Tank Manifold:
Tank Release Detection: Manual Inventory Control (daily)
Tank Tightness Test:
Tank Spill Prevention: Other
Tank Overfill Prevention: Other
Pipe Material: Fiberglass
Pipe Construction: Single Wall Pipe
Pipe Corrosion Protection: Corrosion Resistant
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System: Pressurized System
Turbine Sump Construction:

Tank Construction: Single Wall Tank
Tank Capacity:
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Unleaded Gasoline
Used Substance: Motor Fuel for Vehicles

Tank Detail(s)

Tank Name: 1
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Steel
Tank Corrosion Protection: Sacrificial Anode
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material: Fiberglass
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:
Tank Construction: Single Wall Tank
Tank Capacity:
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Leaded Gasoline
Used Substance:

Tank Detail(s)

Tank Name: TK 7
Status Date: 08/06/1996
Install Date: 01/01/1962
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:
Tank Construction:
Tank Capacity: 111 TO 1,100 Gallons
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Heating Fuel
Used Substance:

Tank Detail(s)

Tank Name: TK 1
Status Date: 08/06/1996
Install Date: 01/01/1988
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Fiberglass Reinforced Plastic
Tank Corrosion Protection: Corrosion Resistant
Tank Manifold:
Tank Release Detection: Manual Inventory Control (daily)
Tank Tightness Test:
Tank Spill Prevention: Other
Tank Overfill Prevention: Other
Pipe Material: Fiberglass
Pipe Construction: Single Wall Pipe
Pipe Corrosion Protection: Corrosion Resistant
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System: Pressurized System
Turbine Sump Construction:

Tank Construction: Single Wall Tank
Tank Capacity:
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Unleaded Gasoline
Used Substance: Motor Fuel for Vehicles

Tank Detail(s)

Tank Name: 3
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Steel
Tank Corrosion Protection: Sacrificial Anode
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material: Fiberglass
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction: Single Wall Tank
Tank Capacity:
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Unleaded Gasoline
Used Substance:

Tank Detail(s)

Tank Name: TK 5
Status Date: 08/06/1996
Install Date: 01/01/1962
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction:
Tank Capacity: 111 TO 1,100 Gallons
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Used Oil/Waste Oil
Used Substance:

Tank Detail(s)

Tank Name: TK 4
Status Date: 08/06/1996
Install Date: 01/01/1988
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Fiberglass Reinforced Plastic
Tank Corrosion Protection: Corrosion Resistant
Tank Manifold:
Tank Release Detection: Manual Inventory Control (daily)
Tank Tightness Test:
Tank Spill Prevention: Other
Tank Overfill Prevention: Other
Pipe Material: Fiberglass
Pipe Construction: Single Wall Pipe
Pipe Corrosion Protection: Corrosion Resistant
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:

Tank Construction: Single Wall Tank
Tank Capacity: 111 TO 1,100 Gallons
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Pipe Pumping System: Gravity Delivery System (No Pump)
Turbine Sump Construction:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Used Oil/Waste Oil
Used Substance:

Tank Detail(s)

Tank Name: TK 8
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction:
Tank Capacity: 111 TO 1,100 Gallons
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance:
Used Substance:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
60	4 of 8	WNW	0.18 / 945.58	95.95 / -10	Unocal SS No 0355 159 DENNY WAY SEATTLE WA 98109	ALL SITES

Facility/Site ID: 32873776
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: NW1307
Facility Alternate: Unocal SS No 0355
Interaction ID: 38231
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 03-Aug-2004
Interact End Dt: 25-Aug-2006
Ecology Program: TOXICS

Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System
Program ID:	WAD988493441
Facility Alternate:	
Interaction ID:	38229
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	11-Sep-1991
Interact End Dt:	31-Dec-1996
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System
Program ID:	WAD988493441
Facility Alternate:	
Interaction ID:	38228
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	TIER2
Interaction Desc:	Emergency/Haz Chem Rpt TIER2
Interact Start Dt:	01-Jan-1991
Interact End Dt:	01-Jan-1753
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	EPCRA
Database Name Desc:	Emergency Planning & Community Right-to-Know Act
Program ID:	8421
Facility Alternate:	
Interaction ID:	38227
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	LUST
Interaction Desc:	LUST Facility
Interact Start Dt:	26-Jun-1989
Interact End Dt:	
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System
Program ID:	NW2538
Facility Alternate:	Unocal SS No 0355
Interaction ID:	98237
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	VOLCLNST
Interaction Desc:	Voluntary Cleanup Sites
Interact Start Dt:	29-Aug-2011
Interact End Dt:	06-Jul-2012
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System
Program ID:	8421
Facility Alternate:	
Interaction ID:	38226
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	UST
Interaction Desc:	Underground Storage Tank
Interact Start Dt:	01-Jan-1962
Interact End Dt:	31-Dec-1992

Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID:
Facility Alternate: Unocal SS No 0355
Interaction ID: 38232
Interaction Status: A
Interac Status Desc: Active
Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 25-Aug-2006
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID:
Facility Alternate: Unocal SS No 0355
Interaction ID: 38230
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 08-Oct-1998
Interact End Dt: 14-Nov-2001
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: NW2203
Facility Alternate: Unocal SS No 0355
Interaction ID: 79522
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 04-Sep-2009
Interact End Dt: 24-Aug-2011
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6183705411
GIS longitude: -122.353705239

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
60	5 of 8	WNW	0.18 / 945.58	95.95 / -10	Unocal 0355 159 DENNY WAY SEATTLE WA 98109	LUST

Facility Site ID: 32873776
Cleanup Site ID: 5879
Responsible Unit: Pollution Liability Ins Agcy
Region: Northwest
County: King
Latitude: 47.6183705410899
Longitude: -122.353705239465
Alternate Site Names: 0355,OVATION PARTNERS LLC,TOSCO 0355,UNION OIL 0355,UNOCAL SERVICE & TIRE INC,Unocal SS No 0355

Tank Detail(s)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

UST ID:	8421	**Status Date:**	05/24/1991
LUST ID:	896	**Release Date:**	06/26/1989
LUST Status:	LUST - Cleanup Started		

Contaminants Detail(s)

Contaminant Name:	Benzene	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Confirmed Above Cleanup Levels		

Contaminants Detail(s)

Contaminant Name:	Polycyclic Aromatic Hydrocarbons	**Sediment:**	
Groundwater:	Below Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Below Cleanup Levels		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Other	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Confirmed Above Cleanup Levels		

Contaminants Detail(s)

Contaminant Name:	Halogenated Organics	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:			

Contaminants Detail(s)

Contaminant Name:	Petroleum-Gasoline	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Confirmed Above Cleanup Levels		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Diesel	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Confirmed Above Cleanup Levels		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
60	6 of 8	WNW	0.18 / 945.58	95.95 / -10	Unocal 0355 159 DENNY WAY SEATTLE WA 98109	ICR

Cleanup Site ID:	5879	**WRIA ID:**	8
Facility Site ID:	32873776	**Is NFA Site:**	
Site Status:	Cleanup Started	**Responsible Unit:**	Northwest
Statute:	MTCA	**Latitude:**	47.618370541089902
Rank:		**Longitude:**	-122.3537052394655
Rank Description:		**Legislative District:**	36
Has Env Covenant:		**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID: 896 ***Start Date:*** 1999-07-28
VCP Prj No: ***End Date:*** 1999-07-29
Activity Name: LUST - Report Received ***Legal Mechanism:***
Activity Status: ***Performed by:***
County Name: King ***Project Manager:***
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 896 ***Start Date:*** 2002-02-22
VCP Prj No: ***End Date:*** 2002-02-25
Activity Name: LUST - Report Received ***Legal Mechanism:***
Activity Status: ***Performed by:***
County Name: King ***Project Manager:***
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 896 ***Start Date:*** 2004-07-12
VCP Prj No: ***End Date:*** 2004-07-21
Activity Name: LUST - Report Received ***Legal Mechanism:***
Activity Status: ***Performed by:***
County Name: King ***Project Manager:***
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 896 ***Start Date:*** 1992-05-27
VCP Prj No: ***End Date:*** 1992-05-27
Activity Name: LUST - Report Received ***Legal Mechanism:***
Activity Status: ***Performed by:***
County Name: King ***Project Manager:***
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 896 ***Start Date:*** 1996-06-07
VCP Prj No: ***End Date:*** 1996-06-07
Activity Name: LUST - Report Received ***Legal Mechanism:***
Activity Status: ***Performed by:***
County Name: King ***Project Manager:***
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 896 ***Start Date:*** 2001-09-28
VCP Prj No: ***End Date:*** 2001-10-30
Activity Name: LUST - Report Received ***Legal Mechanism:***
Activity Status: ***Performed by:***
County Name: King ***Project Manager:***
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 896 ***Start Date:*** 2004-08-30
VCP Prj No: ***End Date:*** 2004-09-07
Activity Name: LUST - Report Received ***Legal Mechanism:***
Activity Status: ***Performed by:***
County Name: King ***Project Manager:***
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: ***Start Date:*** 2011-08-24
VCP Prj No: NW2538 ***End Date:***
Activity Name: VCP Application ***Legal Mechanism:***
Activity Status: Completed ***Performed by:***
County Name: King ***Project Manager:*** Northwest Region
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Related ID: ***Start Date:***
VCP Prj No: NW2538 ***End Date:*** 2012-07-06
Activity Name: VCP Termination ***Legal Mechanism:***

Activity Status: Completed
Performed by:
County Name: King
Project Manager: Fernandez, Sonia
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Related ID: 896
Start Date: 2002-09-26
VCP Prj No:
End Date: 2002-10-07
Activity Name: LUST - Report Received
Legal Mechanism:
Activity Status:
Performed by:
County Name: King
Project Manager:
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID:
Start Date: 2009-09-04
VCP Prj No: NW2203
End Date:
Activity Name: VCP Application
Legal Mechanism:
Activity Status: Completed
Performed by:
County Name: King
Project Manager: Northwest Region
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Related ID: 896
Start Date: 1993-03-01
VCP Prj No:
End Date: 1993-03-01
Activity Name: LUST - Report Received
Legal Mechanism:
Activity Status:
Performed by:
County Name: King
Project Manager:
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 896
Start Date: 1994-06-06
VCP Prj No:
End Date: 1994-06-06
Activity Name: LUST - Report Received
Legal Mechanism:
Activity Status:
Performed by:
County Name: King
Project Manager:
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 896
Start Date: 1995-07-07
VCP Prj No:
End Date: 1995-07-10
Activity Name: LUST - Report Received
Legal Mechanism:
Activity Status:
Performed by:
County Name: King
Project Manager:
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 896
Start Date: 1989-10-03
VCP Prj No:
End Date: 1989-10-03
Activity Name: LUST - Report Received
Legal Mechanism:
Activity Status:
Performed by:
County Name: King
Project Manager:
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 896
Start Date: 1998-09-29
VCP Prj No:
End Date: 1998-10-15
Activity Name: LUST - Report Received
Legal Mechanism:
Activity Status:
Performed by:
County Name: King
Project Manager:
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 896
Start Date: 2001-01-03
VCP Prj No:
End Date: 2001-01-09
Activity Name: LUST - Report Received
Legal Mechanism:
Activity Status:
Performed by:
County Name: King
Project Manager:
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID:	896	**Start Date:**	2001-02-05
VCP Prj No:		**End Date:**	2001-03-21
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		**Start Date:**	2004-08-03
VCP Prj No:	NW1307	**End Date:**	
Activity Name:	VCP Application	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	1989-06-29
Activity Name:	Site Discovery/Release Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:	896	**Start Date:**	1998-11-11
VCP Prj No:		**End Date:**	1998-11-16
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	896	**Start Date:**	2000-09-27
VCP Prj No:		**End Date:**	2000-09-29
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	896	**Start Date:**	2004-07-26
VCP Prj No:		**End Date:**	2004-07-29
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	896	**Start Date:**	2004-07-27
VCP Prj No:		**End Date:**	2004-10-06
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	896	**Start Date:**	1993-07-26
VCP Prj No:		**End Date:**	1993-07-26
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	896	**Start Date:**	2009-01-19
VCP Prj No:		**End Date:**	2009-01-23
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	

Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 896 **Start Date:** 1997-05-27
VCP Prj No: **End Date:** 1997-05-29
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 896 **Start Date:** 1998-05-20
VCP Prj No: **End Date:** 1998-05-22
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 896 **Start Date:** 2009-04-09
VCP Prj No: **End Date:** 2009-04-15
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: **Start Date:**
VCP Prj No: NW1307 **End Date:** 2006-08-25
Activity Name: VCP Termination **Legal Mechanism:**
Activity Status: Completed **Performed by:**
County Name: King **Project Manager:**
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Related ID: **Start Date:**
VCP Prj No: NW2203 **End Date:** 2011-08-24
Activity Name: VCP Termination **Legal Mechanism:**
Activity Status: Completed **Performed by:**
County Name: King **Project Manager:** Myers, Dale R
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Related ID: 896 **Start Date:** 2000-01-12
VCP Prj No: **End Date:** 2000-02-10
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 896 **Start Date:** 2001-01-29
VCP Prj No: **End Date:** 2001-01-30
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 896 **Start Date:** 2003-09-08
VCP Prj No: **End Date:** 2003-09-11
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 896 **Start Date:** 1989-06-26
VCP Prj No: **End Date:** 1989-06-26

Activity Name: LUST - Notification
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Legal Mechanism:
Performed by:
Project Manager:

Related ID: 896
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 2002-04-10
End Date: 2002-04-12
Legal Mechanism:
Performed by:
Project Manager:

Related ID: 896
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 2007-12-28
End Date: 2008-03-04
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No: NW0143
Activity Name: VCP Opinion on Cleanup Action
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date:
End Date: 2002-06-26
Legal Mechanism:
Performed by:
Project Manager: Hickey, Joe

Related ID: 896
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 2003-02-24
End Date: 2003-03-04
Legal Mechanism:
Performed by:
Project Manager:

Related ID: 896
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 2004-04-20
End Date: 2004-04-26
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No: NW0143
Activity Name: VCP Termination
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date:
End Date: 2002-06-26
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No:
Activity Name: Site Hazard Assessment/Federal Site Inspection
Activity Status: Canceled
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date: 2008-10-17
End Date: 2009-08-19
Legal Mechanism:
Performed by: Local Government
Project Manager: County Health-NW

Related ID: 896
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Start Date: 1999-05-06
End Date: 1999-05-07
Legal Mechanism:
Performed by:
Project Manager:

Applies to Description: Leaking Underground Storage Tank

Related ID: 896 **Start Date:** 1993-02-04
VCP Prj No: **End Date:** 1993-02-04
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 896 **Start Date:** 2009-01-12
VCP Prj No: **End Date:** 2009-01-15
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: **Start Date:** 1998-10-08
VCP Prj No: NW0143 **End Date:**
Activity Name: VCP Application **Legal Mechanism:**
Activity Status: Completed **Performed by:**
County Name: King **Project Manager:** Northwest Region
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Related ID: 896 **Start Date:** 2003-11-13
VCP Prj No: **End Date:** 2003-12-11
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 896 **Start Date:** 2007-03-06
VCP Prj No: **End Date:** 2007-04-05
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 896 **Start Date:** 2007-10-19
VCP Prj No: **End Date:** 2007-10-29
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: **Start Date:**
VCP Prj No: NW1307 **End Date:** 2004-08-03
Activity Name: VCP Opinion on Interim Action **Legal Mechanism:**
Activity Status: Completed **Performed by:**
County Name: King **Project Manager:** Hickey, Joe
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Related ID: 896 **Start Date:** 1995-04-12
VCP Prj No: **End Date:** 1995-07-27
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 896 **Start Date:** 1996-02-05
VCP Prj No: **End Date:** 1996-02-06
Activity Name: LUST - Report Received **Legal Mechanism:**

Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	896	**Start Date:**	1996-12-10
VCP Prj No:		**End Date:**	1996-12-11
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	896	**Start Date:**	1999-09-20
VCP Prj No:		**End Date:**	1999-09-22
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	896	**Start Date:**	2007-03-08
VCP Prj No:		**End Date:**	2007-04-05
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	896	**Start Date:**	2008-08-05
VCP Prj No:		**End Date:**	2008-08-07
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		**Start Date:**	1998-10-08
VCP Prj No:		**End Date:**	
Activity Name:	Initial Investigation / Federal Preliminary Assessment	**Legal Mechanism:**	
Activity Status:	Canceled	**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:	896	**Start Date:**	1991-05-21
VCP Prj No:		**End Date:**	1991-05-21
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	896	**Start Date:**	2008-11-06
VCP Prj No:		**End Date:**	2008-11-13
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		**Start Date:**	2012-04-05
VCP Prj No:	NW2538	**End Date:**	2012-05-24
Activity Name:	VCP Opinion on Site Cleanup	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Myers, Dale R
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:	896	***Start Date:***	1993-06-10
VCP Prj No:		***End Date:***	1993-06-10
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	896	***Start Date:***	2007-07-24
VCP Prj No:		***End Date:***	2007-08-13
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Media Contaminants

Contaminant Type:	Benzene	***Sediment:***	
Groundwater:	C	***Sediment Desc.:***	
Groundwater Desc.:	Confirmed Above Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

Contaminant Type:	Polynuclear Aromatic Hydrocarbons	***Sediment:***	
Groundwater:	B	***Sediment Desc.:***	
Groundwater Desc.:	Below Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	B	***Bedrock Desc.:***	
Soil Desc.:	Below Cleanup Level	***County Name:***	King

Contaminant Type:	Halogenated Organics	***Sediment:***	
Groundwater:	C	***Sediment Desc.:***	
Groundwater Desc.:	Confirmed Above Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:		***Bedrock Desc.:***	
Soil Desc.:		***County Name:***	King

Contaminant Type:	Petroleum-Other	***Sediment:***	
Groundwater:	C	***Sediment Desc.:***	
Groundwater Desc.:	Confirmed Above Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

Contaminant Type:	Petroleum-Diesel	***Sediment:***	
Groundwater:	C	***Sediment Desc.:***	
Groundwater Desc.:	Confirmed Above Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

Contaminant Type:	Petroleum-Gasoline	***Sediment:***	
Groundwater:	C	***Sediment Desc.:***	
Groundwater Desc.:	Confirmed Above Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
60	7 of 8	WNW	0.18 / 945.58	95.95 / -10	Unocal 0355 159 Denny Way, Seattle, WA 98109 WA	LUST PTAP

FSID No: 32873776
TAP: PNW032
Status: In Progress
Entry Date: 2/26/2018
URL: https://plia.box.com/s/u0qmofh55du43k9v6t2iehmrwbwsjq3a

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
60	8 of 8	WNW	0.18 / 945.58	95.95 / -10	Unocal 0355 159 DENNY WAY SEATTLE WA 98109	VCP

Facility Site ID: 32873776
Cleanup Site ID: 5879
Region: Northwest
County: King
Latitude: 47.6183705410899
Longitude: -122.353705239465
Alternate Site Names: 0355,OVATION PARTNERS LLC,TOSCO 0355,UNION OIL 0355,UNOCAL SERVICE & TIRE INC,Unocal SS No 0355
Data Source(s): Confirmed and Suspected Contaminated Sites; Confirmed and Suspected Contaminated Sites; All Cleanup Sites in Washington State

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List

Site Status: Cleanup Started
Current VCP:
Past VCP: Yes
Site Rank:
Responsible Unit: Pollution Liability Ins Agcy
Has Inst Control:

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List - Contaminants

Contaminant Name: Halogenated Organics
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: Cleanup Started
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Pollution Liability Ins Agcy

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Halogenated Organics
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
61	1 of 2	NNE	0.18 / 955.86	132.51 / 27	SPACE NEEDLE CORP 219 4TH AVE N SEATTLE WA 98109	RCRA NON GEN

EPA Handler ID: WAD988514014
Gen Status Universe: No Report
Contact Name: STEVE FREES
Contact Address: 400 BROAD ST , , SEATTLE , WA, 98109 , US
Contact Phone No and Ext: 206-905-2212
Contact Email:
Contact Country: US
County Name: KING
EPA Region: 10
Land Type: Private
Receive Date: 20030724
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19980522
Handler Name:	SPACE NEEDLE CORP
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	6
Receive Date:	20030724
Handler Name:	SPACE NEEDLE CORP
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	4
Receive Date:	20020111
Handler Name:	SPACE NEEDLE CORP
Source Type:	Notification
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	3
Receive Date:	19980522
Handler Name:	SPACE NEEDLE CORP
Source Type:	Notification
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	19940205
Handler Name:	SPACE NEEDLE CORP
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19940204
Handler Name: SPACE NEEDLE CORP
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 20030723
Handler Name: SPACE NEEDLE CORP
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: SPACE NEEDLE CORP
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 219 4TH AVE N
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98109

Owner/Operator Ind: Current Owner
Type: Private
Name: SPACE NEEDLE CORP
Date Became Current:
Date Ended Current:
Phone: 206-902-2200
Source Type: Implementer
Street No:
Street 1: 203 6TH AVE N
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98109

Owner/Operator Ind: Current Operator
Type: Private
Name: SPACE NEEDLE CORP
Date Became Current:
Date Ended Current:
Phone: 206-905-2200
Source Type: Implementer
Street No:
Street 1: 203 6TH AVE N
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98109

Owner/Operator Ind: Current Operator
Type: Private
Name: SPACE NEEDLE CORP
Date Became Current:
Date Ended Current:
Phone: 206-905-2200
Source Type: Notification
Street No:
Street 1: 203 6TH AVE N
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98109

Owner/Operator Ind: Current Owner
Type: Private
Name: SPACE NEEDLE CORP
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Implementer
Street No:
Street 1: 219 4TH AVE N
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98109

Owner/Operator Ind: Current Operator
Type: Private
Name: SPACE NEEDLE CORP
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Implementer
Street No:
Street 1: 219 4TH AVE N
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98109

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	203 6TH AVE N
Name:	SPACE NEEDLE CORP	**Street 2:**	
Date Became Current:	19980522	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-905-2200	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	203 6TH AVE N
Name:	SPACE NEEDLE CORP	**Street 2:**	
Date Became Current:	20011231	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-905-2200	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98109

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	203 6TH AVE N
Name:	SPACE NEEDLE CORP	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-902-2200	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	219 4TH AVE N
Name:	SPACE NEEDLE CORP	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	203 6TH AVE N
Name:	SPACE NEEDLE CORP	**Street 2:**	
Date Became Current:	20011231	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-905-2200	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109

Historical Handler Details

Receive Dt:	20020111
Generator Code Description:	Not a Generator, Verified
Handler Name:	SPACE NEEDLE CORP

Receive Dt:	20030723
Generator Code Description:	Not a Generator, Verified
Handler Name:	SPACE NEEDLE CORP

Receive Dt:	19980522
Generator Code Description:	Large Quantity Generator
Handler Name:	SPACE NEEDLE CORP

Receive Dt:	19980522
Generator Code Description:	Not a Generator, Verified
Handler Name:	SPACE NEEDLE CORP

Receive Dt:	19940205
Generator Code Description:	Not a Generator, Verified
Handler Name:	SPACE NEEDLE CORP

Receive Dt:	19940204
Generator Code Description:	Not a Generator, Verified
Handler Name:	SPACE NEEDLE CORP

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
61	2 of 2	NNE	0.18 / 955.86	132.51 / 27	Space Needle Corp 219 4TH AVE N SEATTLE WA 98109	ALL SITES

Facility/Site ID: 52529243
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAD988514014
Facility Alternate:
Interaction ID: 49428
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 09-Nov-1992
Interact End Dt: 31-Dec-1992
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAD988514014
Facility Alternate:
Interaction ID: 49429
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 22-May-1998
Interact End Dt: 31-Dec-2001
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.63221
GIS longitude: -122.35099

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
62	1 of 1	E	0.18 / 963.63	121.28 / 16	2517 4TH AVE Seattle WA 98109	UST SEATTLE

Permit No: 3-42651
Date Issued: 05/30/2002
Fill Material: No Fill
Date Decommissioned: 05/31/2002
Type Decommissioned: Abandonment in Place
Tank Size: 675
Tank Age: 20+
Tank Content: HEATING OIL

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
63	1 of 1	SE	0.18 / 964.88	104.77 / -1	2432 1ST AVE Seattle WA 98109	UST SEATTLE

Permit No: 3-36741
Date Issued: 02/23/2001
Fill Material: Foam
Date Decommissioned: 02/23/2001
Type Decommissioned: Abandonment in Place
Tank Size: 300
Tank Age: 20+
Tank Content: HEATING OIL

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
64	1 of 6	ENE	0.18 / 968.73	127.93 / 22	Chevron 97032 5TH AVE & DENNY WAY NW CORNER SEATTLE WA 98109	CSCSL NFA

Fac Site ID:	18935188	**Fac Site ID (OD):**	18935188
Cleanup Site ID:	5651	**Cleanup SiteID(OD):**	5651
Site Status:	NFA	**Site Status (OD):**	No Further Action
NFA Date:	01/05/1999	**Rank (OD):**	
Responsible Unit:	Northwest	**Has Env Coven (OD):**	
Has Insti Control:		**Respon Unit (OD):**	Northwest
Region:	Northwest	**Region (OD):**	Northwest
County:	King	**County (OD):**	King
Latitude:	47.618946	**Latitude (OD):**	47.618946
Longitude:	-122.347808	**Longitude (OD):**	-122.347808

NFA Reason: Voluntary Cleanup Program Review
Alternate Site Names: CHEVRON SERV STA 97032,FORMER CHEVRON STATION 97032,KOMO TV SITE
Location (OD): ""
(47.618946, -122.347808)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

NFA Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
64	2 of 6	ENE	0.18 / 968.73	127.93 / 22	CHEVRON 97032 5TH AVE & DENNY WAY Seattle WA 98109	UST

UST ID:	453155	**Region:**	Northwest
Facility Site ID:	18935188	**County:**	King
Site Active:	No	**Latitude:**	47.618946
Responsible Unit:	Northwest	**Longitude:**	-122.347808
Active Tag:			

Alternate Site Names: CHEVRON SERV STA 97032,FORMER CHEVRON STATION 97032,KOMO TV SITE

Tank Detail(s)

Tank Name:	1	**Tank Construction:**	
Status Date:	07/30/2001	**Tank Capacity:**	
Install Date:	01/01/1900	**Actual Capacity:**	
Upgrade Date:		**Pipe Install Date:**	
Perm Closure Date:		**Endorsement Expire:**	

Tank Status: Removed
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:

Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Compartments

Compartment No: 0
Compart Capacity:
Stored Substance:
Used Substance:

64	*3 of 6*	*ENE*	*0.18 / 968.73*	*127.93 / 22*	*CHEVRON SERV STA 97032* *5TH AVE & DENNY WAY NW* *CORNER* *SEATTLE WA 98109*	*ALL SITES*

Facility/Site ID: 18935188
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: CHEVRON SERV STA 97032
Interaction ID: 30854
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 29-Dec-1998
Interact End Dt: 05-Jan-1999
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: 453155
Facility Alternate:
Interaction ID: 30852
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: LUST
Interaction Desc: LUST Facility
Interact Start Dt: 16-Jun-1998
Interact End Dt: 05-Jan-1999
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID:
Facility Alternate:
Interaction ID: 30853
Interaction Status: A
Interac Status Desc: Active
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 30-Jun-1998

Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Address
Location Verified: N
GIS latitude: 47.618946
GIS longitude: -122.347808

---

64 | ***4 of 6*** | ***ENE*** | ***0.18 / 968.73*** | ***127.93 / 22*** | ***Chevron 97032***
5TH AVE & DENNY WAY NW
CORNER
SEATTLE WA 98109 | ***ICR***

Cleanup Site ID: 5651
Facility Site ID: 18935188
Site Status: No Further Action Required
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site: Yes
WRIA ID: 8
Is NFA Site: Yes
Responsible Unit: Northwest
Latitude: 47.618946000000001
Longitude: -122.347808
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID: 4895
VCP Prj No:
Activity Name: LUST - Notification
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 1998-06-16
End Date: 1998-06-16
Legal Mechanism:
Performed by:
Project Manager: Forson, Ben

Related ID: 4895
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 2001-01-31
End Date: 2001-07-06
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No: NW0187
Activity Name: VCP Termination
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date:
End Date: 1999-01-04
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No:
Activity Name: Site Status Changed to NFA
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date:
End Date: 1999-01-05
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No: NW0187
Activity Name: VCP Application
Activity Status: Completed
County Name: King
Start Date: 1998-12-29
End Date:
Legal Mechanism:
Performed by:
Project Manager:

Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Related ID:
VCP Prj No: NW0187
Activity Name: VCP Opinion on Cleanup Action
Activity Status: Canceled
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date:
End Date:
Legal Mechanism:
Performed by:
Project Manager: Polayes, Joanne

Related ID: 4895
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 1998-09-02
End Date: 1998-12-29
Legal Mechanism:
Performed by:
Project Manager:

Media Contaminants

Contaminant Type: Petroleum-Other
Groundwater:
Groundwater Desc.:
Surface Water:
Surfacewater Desc.:
Soil: C
Soil Desc.: Confirmed Above Cleanup Level
Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

64	5 of 6	ENE	0.18 / 968.73	127.93 / 22	Chevron 97032 5TH AVE & DENNY WAY NW CORNER SEATTLE WA 98109	VCP

Facility Site ID: 18935188
Cleanup Site ID: 5651
Region: Northwest
Alternate Site Names: CHEVRON SERV STA 97032,FORMER CHEVRON STATION 97032,KOMO TV SITE
Data Source(s): No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State
County: King
Latitude: 47.618946
Longitude: -122.347808

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status: NFA
NFA Date: 01/05/1999
Responsible Unit: Northwest
Has Inst Control:
NFA Reason: Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: No Further Action
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

---

64 | ***6 of 6*** | ***ENE*** | ***0.18 / 968.73*** | ***127.93 / 22*** | ***Chevron 97032 5TH AVE & DENNY WAY NW CORNER SEATTLE WA 98109*** | ***LUST***

Facility Site ID: 18935188
Cleanup Site ID: 5651
Responsible Unit: Northwest
Region: Northwest
Alternate Site Names: CHEVRON SERV STA 97032,FORMER CHEVRON STATION 97032,KOMO TV SITE
County: King
Latitude: 47.618946
Longitude: -122.347808

Tank Detail(s)

UST ID: 453155
LUST ID: 4895
LUST Status: LUST - NFA
Status Date: 01/05/1999
Release Date: 06/16/1998

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

---

65 | ***1 of 1*** | ***E*** | ***0.19 / 976.90*** | ***121.28 / 16*** | ***2500 4TH AVE Seattle WA 98121*** | ***UST SEATTLE***

Permit No: P990119-34187
Date Issued: 01/19/1999
Fill Material:
Date Decommissioned: 01/19/1999
Type Decommissioned: Removal
Tank Size: 1100
Tank Age: 50+
Tank Content: HEATING OIL

---

66 | ***1 of 1*** | ***SE*** | ***0.19 / 979.09*** | ***105.21 / -1*** | ***2426 1ST AVE Seattle WA 98109*** | ***UST SEATTLE***

Permit No: 3-45360
Date Issued: 12/12/2002
Fill Material: N/A
Date Decommissioned: 12/27/2002
Type Decommissioned: Removal
Tank Size: 300
Tank Age: 20+
Tank Content: HEATING OIL

---

67 | ***1 of 2*** | ***WNW*** | ***0.19 / 997.79*** | ***95.40 / -10*** | ***S EPA H INC 150 DENNY WAY SEATTLE WA 98109*** | ***RCRA NON GEN***

EPA Handler ID: WAD982821191
Gen Status Universe: No Report
Contact Name: S EPA H INC S EPA H INC
Contact Address: 150 DENNY WAY , , SEATTLE , WA, 98109-4915 , US

Contact Phone No and Ext:	000-000-0000
Contact Email:	
Contact Country:	US
County Name:	KING
EPA Region:	10
Land Type:	Private
Receive Date:	19890807
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19890807
Handler Name:	S EPA H INC
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19890807
Handler Name:	S EPA H INC
Source Type:	Notification
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	19890807
Handler Name:	S EPA H INC
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	150 DENNY WAY
Name:	S EPA H INC S	**Street 2:**	
Date Became Current:	19960502	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98109-4915

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	150 DENNY WAY
Name:	S EPA H INC	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	150 DENNY WAY
Name:	SEE PAPER COPY	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	
Source Type:	Implementer	**Zip Code:**	98109

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	150 DENNY WAY
Name:	S EPA H INC	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	150 DENNY WAY
Name:	S EPA H INC	**Street 2:**	
Date Became Current:	19960502	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	150 DENNY WAY
Name:	S EPA H INC	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98109-4915

Historical Handler Details

Receive Dt:	19890807
Generator Code Description:	Not a Generator, Verified
Handler Name:	S EPA H INC

67	*2 of 2*	*WNW*	*0.19 / 997.79*	*95.40 / -10*	***S EPA H Inc 150 DENNY WAY SEATTLE WA 98109***	***ALL SITES***

Facility/Site ID:	69274165
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAD982821191
Facility Alternate:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Interaction ID:	59344
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	07-Aug-1989
Interact End Dt:	17-Mar-1990
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	N
Horizont 1:	NAD83	**GIS latitude:**	47.61888
Horizont 2:	Unknown	**GIS longitude:**	-122.3301

68	*1 of 2*	*S*	*0.19 / 1,001.11*	*30.75 / -75*	***SEATTLE CITY PARKS & REC BELLTOWN PP 2512 ELLIOT AVE SEATTLE WA 98102***	***RCRA NON GEN***

EPA Handler ID:	WAH000016816
Gen Status Universe:	No Report
Contact Name:	JODI SINCLAIR
Contact Address:	4209 W MARGINAL WAY SW , WESTBRIDGE , SEATTLE , WA, 98106 , US
Contact Phone No and Ext:	206-684-7292
Contact Email:	
Contact Country:	US
County Name:	KING
EPA Region:	10
Land Type:	Municipal
Receive Date:	20040429
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1

Receive Date: 20011205
Handler Name: SEATTLE CITY PARKS & REC BELLTOWN PP
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20031231
Handler Name: SEATTLE CITY PARKS & REC BELLTOWN PP
Source Type: Annual/Biennial Report
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 20040429
Handler Name: SEATTLE CITY PARKS & REC BELLTOWN PP
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20020306
Handler Name: SEATTLE CITY PARKS & REC BELLTOWN PP
Source Type: Annual/Biennial Report
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20040428
Handler Name: SEATTLE CITY PARKS & REC BELLTOWN PP
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20040428
Handler Name: SEATTLE CITY PARKS & REC BELLTOWN PP
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 20040428
Handler Name: SEATTLE CITY PARKS & REC BELLTOWN PP
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20030310
Handler Name: SEATTLE CITY PARKS & REC BELLTOWN PP
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20020306
Handler Name: SEATTLE CITY PARKS & REC BELLTOWN PP
Source Type: Notification
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: SEATTLE CITY PARKS
Date Became Current: 20011205
Date Ended Current:
Phone: 206-684-7292
Source Type: Notification
Street No:
Street 1: 100 DEXTER AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98109

Owner/Operator Ind: Current Owner
Type: Private
Name: SEATTLE CITY PARKS
Date Became Current:
Date Ended Current:
Phone: 206-684-7292
Source Type: Notification
Street No:
Street 1: 100 DEXTER AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98109

Owner/Operator Ind: Current Owner
Type: Municipal
Name: SEATTLE CITY PARKS
Date Became Current: 20011205
Date Ended Current:
Phone:
Source Type: Annual/Biennial Report
Street No:
Street 1: 100 DEXTER AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98109

Owner/Operator Ind: Current Owner
Type: Municipal
Name: SEATTLE CITY PARKS
Date Became Current:
Date Ended Current:
Phone: 206-684-7292
Source Type: Implementer
Street No:
Street 1: 100 DEXTER AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98109

Owner/Operator Ind: Current Owner
Type: Municipal
Name: SEATTLE CITY PARKS
Date Became Current: 20031231
Date Ended Current:
Phone: 206-684-7292
Source Type: Notification
Street No:
Street 1: 100 DEXTER AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98109

Owner/Operator Ind: Current Operator
Type: Municipal
Name: SINCLAIR, JODI
Date Became Current:
Date Ended Current:
Phone: 206-684-7292
Source Type: Notification
Street No:
Street 1: 4209 W MARGINAL WAY SW
Street 2: WESTBRIDGE
City: SEATTLE
State: WA
Country: US
Zip Code: 98106

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Municipal	**Street 1:**	4209 W MARGINAL WAY SW
Name:	JODI SINCLAIR	**Street 2:**	WESTBRIDGE
Date Became Current:	19000101	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	98106

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	100 DEXTER AVE
Name:	SEATTLE CITY PA S	**Street 2:**	
Date Became Current:	20011205	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-684-7292	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98109

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	100 DEXTER AVE
Name:	SEATTLE CITY PARKS	**Street 2:**	
Date Became Current:	20011205	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-684-7292	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98109

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	4209 W MARGINAL WAY SW
Name:	JODI S	**Street 2:**	WESTBRIDGE
Date Became Current:	19000101	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-684-7292	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98106

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Municipal	**Street 1:**	100 DEXTER AVE
Name:	SEATTLE CITY PARKS	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-684-7292	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98109

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2512 ELLIOT AVE
Name:	SEATTLE CITY PARKS REC BELLTOWN PP	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98102

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	100 DEXTER AVE
Name:	SEATTLE CITY PARKS	**Street 2:**	
Date Became Current:	20031231	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-684-7292	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98109

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Municipal	**Street 1:**	100 DEXTER AVE
Name:	SEATTLE CITY PARKS	**Street 2:**	
Date Became Current:	20011205	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-684-7292	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	100 DEXTER AVE
Name:	SEATTLE CITY PARKS	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Phone:	206-684-7292	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	4209 W MARGINAL WAY SW
Name:	SINCLAIR, JODI	**Street 2:**	WESTBRIDGE
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-684-7292	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98106

Historical Handler Details

Receive Dt:	20030310
Generator Code Description:	Not a Generator, Verified
Handler Name:	SEATTLE CITY PARKS & REC BELLTOWN PP
Receive Dt:	20040428
Generator Code Description:	Not a Generator, Verified
Handler Name:	SEATTLE CITY PARKS & REC BELLTOWN PP
Receive Dt:	20040428
Generator Code Description:	Not a Generator, Verified
Handler Name:	SEATTLE CITY PARKS & REC BELLTOWN PP
Receive Dt:	20011205
Generator Code Description:	Not a Generator, Verified
Handler Name:	SEATTLE CITY PARKS & REC BELLTOWN PP
Receive Dt:	20020306
Generator Code Description:	Large Quantity Generator
Handler Name:	SEATTLE CITY PARKS & REC BELLTOWN PP
Receive Dt:	20020306
Generator Code Description:	Large Quantity Generator
Handler Name:	SEATTLE CITY PARKS & REC BELLTOWN PP
Receive Dt:	20040428
Generator Code Description:	Not a Generator, Verified
Handler Name:	SEATTLE CITY PARKS & REC BELLTOWN PP
Receive Dt:	20031231
Generator Code Description:	Not a Generator, Verified
Handler Name:	SEATTLE CITY PARKS & REC BELLTOWN PP

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
68	2 of 2	S	0.19 / 1,001.11	30.75 / -75	**Seattle City Parks & Rec Belltown PP** **2512 ELLIOT AVE** **SEATTLE WA 98102**	ALL SITES

Facility/Site ID:	44927466
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAH000016816
Facility Alternate:	
Interaction ID:	45474
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	05-Dec-2001
Interact End Dt:	31-Dec-2003
Ecology Program:	HAZWASTE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: Unknown
Horizont 2: Address
Location Verified: N
GIS latitude: 47.6136814508
GIS longitude: -122.351904272

---

69 | 1 of 6 | ENE | 0.19 / 1,002.02 | 125.47 / 20 | Edwards on Fifth, 2619 5TH AVE, SEATTLE WA 98121 | CSCSL

Fac Site ID: 55245214
Cleanup Site ID: 3896
Site Status: Cleanup Started
Site Rank: 5 - Lowest Assessed Risk
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6180578555127
Longitude: -122.347176455938
Site Name: Edwards on Fifth
Address: 2619 5TH AVE
City: SEATTLE
Zip Code: 98121
Site Status (OD): Cleanup Started
Site Name (OD): Edwards on Fifth
Address (OD): 2619 5TH AVE
City (OD): SEATTLE
Zipcode (OD): 98121
Location (OD): "" (47.618058, -122.347176)
Alternate Site Names: EDWARDS ON 5TH BLDG
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)
Responsible Unit: Northwest
Fac Site ID (OD): 55245214
Cleanup SiteID(OD): 3896
Site Rank (OD): 5 - Lowest Assessed Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.347176
Latitude (OD): 47.618058

Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

69 | 2 of 6 | ENE | 0.19 / 1,002.02 | 125.47 / 20 | Edwards on Fifth, 2619 5TH AVE, SEATTLE WA 98121 | HSL

Fac Site ID: 55245214
Cleanup Site ID: 3896
Site Status: Cleanup Started
Site Rank: 5 - Lowest Assessed Risk
Has Inst Control:
Fac Site ID (OD): 55245214
Cleanup Site ID (OD): 3896
Site Status (OD): Cleanup Started
Site Rank (OD): 5 - Lowest Assessed Risk
Has Env Coven (OD):

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Responsible Unit:	Northwest	**Respon Unit (OD):**	Northwest
County:	King	**County (OD):**	King
Region:	Northwest	**Region (OD):**	Northwest
Latitude:	47.6180578555127	**Site Name (OD):**	Edwards on Fifth
Longitude:	-122.347176455938	**Address (OD):**	2619 5TH AVE
Latitude (OD):	47.618058	**City (OD):**	SEATTLE
Longitude (OD):	-122.347176	**ZIP code (OD):**	98121
Current VCP:		**Past VCP:**	Yes
Location (OD):	"" (47.618058, -122.347176)		
Alternate Site Names:	EDWARDS ON 5TH BLDG		
Data Source(s):	Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)		

Contaminants Detail(s)

Contaminant Name:	Petroleum Products-Unspecified	**Sediment:**	
Groundwater:		**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Petroleum Products-Unspecified	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		

69	3 of 6	ENE	0.19 / 1,002.02	125.47 / 20	**EDWARDS ON 5TH BLDG** **2619 5TH AVE** **SEATTLE WA 98121**	ALL SITES

Facility/Site ID:	55245214
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	NW0371
Facility Alternate:	EDWARDS ON 5TH BLDG
Interaction ID:	51282
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	VOLCLNST
Interaction Desc:	Voluntary Cleanup Sites
Interact Start Dt:	10-Nov-1999
Interact End Dt:	17-Oct-2006
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Program ID:	
Facility Alternate:	EDWARDS ON 5TH BLDG
Interaction ID:	51283
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	SCS
Interaction Desc:	State Cleanup Site
Interact Start Dt:	17-Oct-2006
Interact End Dt:	
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Facility Location Detail

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Horizontal:	40ft	**Location Verified:**	
Horizont 1:	NAD83HARN	**GIS latitude:**	47.6180578555
Horizont 2:	Digital map or GIS	**GIS longitude:**	-122.347176456

69 **4 of 6** **ENE** **0.19 / 1,002.02** **125.47 / 20** **Edwards on Fifth**
2619 5TH AVE
SEATTLE WA 98121
ICR

Cleanup Site ID:	3896	**WRIA ID:**	8
Facility Site ID:	55245214	**Is NFA Site:**	
Site Status:	Cleanup Started	**Responsible Unit:**	Northwest
Statute:	MTCA	**Latitude:**	47.618057855512731
Rank:	5	**Longitude:**	-122.34717645593783
Rank Description:	Lowest assessed risk	**Legislative District:**	36
Has Env Covenant:		**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	1994-09-09
Activity Name:	Site Discovery/Release Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	1999-11-16
VCP Prj No:	NW0371	**End Date:**	
Activity Name:	VCP Application	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	1999-11-16
VCP Prj No:		**End Date:**	
Activity Name:	Initial Investigation / Federal Preliminary Assessment	**Legal Mechanism:**	
Activity Status:	Canceled	**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	
VCP Prj No:	NW0371	**End Date:**	
Activity Name:	VCP Opinion on Cleanup Action	**Legal Mechanism:**	
Activity Status:	Canceled	**Performed by:**	
County Name:	King	**Project Manager:**	Becker, Sunny
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	
VCP Prj No:	NW0371	**End Date:**	2006-10-17
Activity Name:	VCP Termination	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	2013-02-14
VCP Prj No:		**End Date:**	2013-06-28
Activity Name:	Site Hazard Assessment/Federal Site Inspection	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	Ecology w/ Contractor

County Name:	King	***Project Manager:***	Musa, Donna
Applies to:	CleanupSite		
Applies to Description:			
Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	2013-08-08
Activity Name:	Hazardous Sites Listing/NPL	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	Musa, Donna
Applies to:	CleanupSite		
Applies to Description:			

Media Contaminants

Contaminant Type:	Petroleum Products-Unspecified	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

69	5 of 6	ENE	0.19 / 1,002.02	125.47 / 20	Edwards on Fifth 2619 5TH AVE SEATTLE WA 98121	VCP

Facility Site ID:	55245214	***County:***	King
Cleanup Site ID:	3896	***Latitude:***	47.6180578555127
Region:	Northwest	***Longitude:***	-122.347176455938
Alternate Site Names:	EDWARDS ON 5TH BLDG		
Data Source(s):	Confirmed and Suspected Contaminated Sites; Confirmed and Suspected Contaminated Sites; All Cleanup Sites in Washington State		

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List

Site Status:	Cleanup Started
Current VCP:	
Past VCP:	Yes
Site Rank:	5 - Lowest Assessed Risk
Responsible Unit:	Northwest
Has Inst Control:	

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List - Contaminants

Contaminant Name:	Petroleum Products-Unspecified	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status:	Cleanup Started
Site Rank:	5 - Lowest Assessed Risk
Has Inst Control:	
Current VCP:	
Past VCP:	Yes
Responsible Unit:	Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name:	Petroleum Products-Unspecified	***Sediment:***	
Groundwater:		***Air:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Surfacewater:				Bedrock:		
Soil:	Confirmed Above Cleanup Levels					
69	6 of 6	ENE	0.19 / 1,002.02	125.47 / 20	EDWARDS ON 5TH BLDG 2619 5TH AVE SEATTLE WA 98121	RCRA LQG

EPA Handler ID: WAH000059830
Gen Status Universe: Large Quantity Generator
Contact Name: EVAN BROWN
Contact Address: 2801 ALASKAN WAY STE 310 , , SEATTLE , WA, 98121 , US
Contact Phone No and Ext: 206-805-2017
Contact Email: EBROWN@GRE-M.COM
Contact Country: US
County Name: KING
EPA Region: 10
Land Type: Private
Receive Date: 20220614
Location Latitude: 47.618058
Location Longitude: -122.347176

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20220614
Handler Name: EDWARDS ON 5TH BLDG
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	2801 ALASKAN WAY STE 310
Name:	EDWARDS ON 5TH A LIMITED PARTNERSHIP	***Street 2:***	
Date Became Current:	19970205	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-805-2017	***Country:***	US
Source Type:	Notification	***Zip Code:***	98121

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	2801 ALASKAN WAY STE 310
Name:	EDWARDS ON 5TH A LIMITED PARTNERSHIP	***Street 2:***	
Date Became Current:	19970205	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-805-2017	***Country:***	US
Source Type:	Notification	***Zip Code:***	98121

70	*1 of 1*	*ESE*	*0.19 / 1,003.12*	*118.08 / 12*	***2437 3RD AVE*** ***Seattle WA 98119***	***UST SEATTLE***

Permit No:	3-36933	***Tank Size:***	300
Date Issued:	03/12/2001	***Tank Age:***	1948
Fill Material:	N/A	***Tank Content:***	HOME HEATING OIL
Date Decommissioned:	03/12/2001		
Type Decommissioned:	Removal		

71	*1 of 4*	*SE*	*0.19 / 1,005.13*	*104.80 / -1*	***Belltown Court Condos*** ***2400 1ST AVE*** ***SEATTLE WA 98121***	***CSCSL NFA***

Fac Site ID:	16948552	***Fac Site ID (OD):***	16948552
Cleanup Site ID:	4701	***Cleanup SiteID(OD):***	4701
Site Status:	NFA	***Site Status (OD):***	No Further Action
NFA Date:	09/29/1998	***Rank (OD):***	
Responsible Unit:	Northwest	***Has Env Coven (OD):***	
Has Insti Control:		***Respon Unit (OD):***	Northwest
Region:	Northwest	***Region (OD):***	Northwest
County:	King	***County (OD):***	King
Latitude:	47.6145237016278	***Latitude (OD):***	47.614813
Longitude:	-122.347875575507	***Longitude (OD):***	-122.348294
NFA Reason:	Voluntary Cleanup Program Review		
Alternate Site Names:			
Location (OD):	"" (47.614813, -122.348294)		
Data Source(s):	Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants		

NFA Contaminants Detail(s)

Contaminant Name:	Petroleum Products-Unspecified
Groundwater:	
Surfacewater:	
Soil:	Remediated
Sediment:	
Air:	
Bedrock:	

Open Data Portal - Media and Contaminants as of 2021-09-15

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Remediated

---

71 | 2 of 4 | SE | 0.19 / 1,005.13 | 104.80 / -1 | BELLTOWN COURT CONDOS, 2400 1ST AVE, SEATTLE WA 98121 | ALL SITES

Facility/Site ID: 16948552
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: BELLTOWN COURT CONDOS
Interaction ID: 29708
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 10-Aug-1998
Interact End Dt: 29-Sep-1998
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6145237016
GIS longitude: -122.347875576

---

71 | 3 of 4 | SE | 0.19 / 1,005.13 | 104.80 / -1 | BELLTOWN COURT CONDOS, 2400 1ST AVE, SEATTLE WA 98121 | ICR

Cleanup Site ID: 4701
Facility Site ID: 16948552
Site Status: No Further Action Required
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site: Yes
WRIA ID: 8
Is NFA Site: Yes
Responsible Unit: Northwest
Latitude: 47.614812999999998
Longitude: -122.348294
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID:
VCP Prj No: NW0114
Activity Name: VCP Application
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 1998-08-10
End Date:
Legal Mechanism:
Performed by:
Project Manager: Northwest Region

Related ID:
VCP Prj No: NW0114
Activity Name: VCP Opinion on Cleanup Action
Activity Status: Canceled
County Name: King
Applies to: VcpProject
Start Date:
End Date:
Legal Mechanism:
Performed by:
Project Manager: Becker, Sunny

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Applies to Description: Voluntary Cleanup Program

Related ID:
VCP Prj No:
Activity Name: Site Status Changed to NFA
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date:
End Date: 1998-09-29
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No: NW0114
Activity Name: VCP Termination
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date:
End Date: 1998-09-29
Legal Mechanism:
Performed by:
Project Manager:

Media Contaminants

Contaminant Type: Petroleum Products-Unspecified
Groundwater:
Groundwater Desc.:
Surface Water:
Surfacewater Desc.:
Soil: R
Soil Desc.: Remediated
Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

71	4 of 4	SE	0.19 / 1,005.13	104.80 / -1	Belltown Court Condos 2400 1ST AVE SEATTLE WA 98121	VCP

Facility Site ID: 16948552
Cleanup Site ID: 4701
Region: Northwest
Alternate Site Names:
Data Source(s): No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State
County: King
Latitude: 47.6145237016278
Longitude: -122.347875575507

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status: NFA
NFA Date: 09/29/1998
Responsible Unit: Northwest
Has Inst Control:
NFA Reason: Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Remediated
Sediment:
Air:
Bedrock:

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: No Further Action
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Remediated
Sediment:
Air:
Bedrock:

---

72 | ***1 of 1*** | ***SE*** | ***0.19 / 1,006.48*** | ***104.57 / -1*** | ***2417 1ST AVE Seattle WA 98119*** | ***UST SEATTLE***

Permit No: 3-32958
Date Issued: 06/19/2000
Fill Material: No Fill
Date Decommissioned: 06/19/2000
Type Decommissioned: Abandonment in Place
Tank Size: 300
Tank Age: 35+
Tank Content: #2 HEATING FUEL

---

73 | ***1 of 3*** | ***W*** | ***0.19 / 1,010.03*** | ***46.54 / -59*** | ***WA UW Western Ave 3000 WESTERN AVE SEATTLE WA 98121*** | ***ALL SITES***

Facility/Site ID: 33515472
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000005462
Facility Alternate: WA UW Western Ave
Interaction ID: 116916
Interaction Status: A
Interac Status Desc: Active
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 31-Dec-2015
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAH000005462
Facility Alternate:
Interaction ID: 38615
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 04-Jun-1998
Interact End Dt: 31-Dec-2003
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAH000005462
Facility Alternate:
Interaction ID: 38616
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWOTHER
Interaction Desc: Haz Waste Management Activity
Interact Start Dt: 31-Dec-2003
Interact End Dt: 31-Dec-2004
Ecology Program: HAZWASTE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAH000005462
Facility Alternate: WA UW Western Ave
Interaction ID: 111521
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWOTHER
Interaction Desc: Haz Waste Management Activity
Interact Start Dt: 31-Dec-2014
Interact End Dt: 31-Dec-2015
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAH000005462
Facility Alternate: WA UW Western Ave
Interaction ID: 38617
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 31-Dec-2004
Interact End Dt: 31-Dec-2014
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Address
Location Verified: N
GIS latitude: 47.61726
GIS longitude: -122.356128

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
73	2 of 3	W	0.19 / 1,010.03	46.54 / -59	GENETIC SYSTEMS CORPORATION WESTERN 3000 WESTERN AVENUE SEATTLE WA 98121-0000	RCRA NON GEN

EPA Handler ID: WAD988469193
Gen Status Universe: No Report
Contact Name: JO WALENTINY
Contact Address: US
Contact Phone No and Ext: 206-861-5047
Contact Email:
Contact Country: US
County Name: KING
EPA Region: 10
Land Type:
Receive Date: 19940218
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Mixed Waste Generator:
Transporter Activity:
Transfer Facility:
Onsite Burner Exemption:
Furnace Exemption:
Underground Injection Activity:
Commercial TSD: No
Used Oil Transporter:
Used Oil Transfer Facility:
Used Oil Processor:
Used Oil Refiner:
Used Oil Burner:
Used Oil Market Burner:
Used Oil Spec Marketer:

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19930901
Handler Name: GENETIC SYSTEMS CORPORATION
Source Type: Annual/Biennial Report
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19940218
Handler Name: GENETIC SYSTEMS CORPORATION WESTERN
Source Type: Annual/Biennial Report
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Historical Handler Details

Receive Dt: 19930901
Generator Code Description: Large Quantity Generator
Handler Name: GENETIC SYSTEMS CORPORATION

73	*3 of 3*	*W*	*0.19 / 1,010.03*	*46.54 / -59*	***WA UW WESTERN AVE 3000 WESTERN AVE SEATTLE WA 98121***	***RCRA NON GEN***

EPA Handler ID: WAH000005462
Gen Status Universe: No Report
Contact Name: DOUG GALLUCCI
Contact Address: PO BOX 354400 , , SEATTLE , WA, 98195 , US
Contact Phone No and Ext: 206-543-0467
Contact Email: DOUGLASG@U.WASHINGTON.EDU
Contact Country: US
County Name: KING
EPA Region: 10
Land Type: State
Receive Date: 20220214
Location Latitude: 47.61726
Location Longitude: -122.356128

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	19980604
Handler Name:	WA UW WESTERN AVE
Source Type:	Notification
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19980903
Handler Name:	WA UW WESTERN AVE
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	15
Receive Date:	20100202
Handler Name:	WA UW WESTERN AVE
Source Type:	Notification
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code:	D001
Waste Code Description:	IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No:	16
Receive Date:	20110217
Handler Name:	WA UW WESTERN AVE
Source Type:	Notification
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code:	D001

Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 24
Receive Date: 20190211
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: P105
Waste Code Description: SODIUM AZIDE

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: WT01
Waste Code Description: Washington State Extremely Hazardous Toxic Waste with a toxic constituents concentration greater than or equal to 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: U122
Waste Code Description: FORMALDEHYDE

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Handler Details

Sequence No: 27
Receive Date: 20201110
Handler Name: WA UW WESTERN AVE
Source Type: Notification

Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20110217
Handler Name: WA UW WESTERN AVE
Source Type: Implementer
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 28
Receive Date: 20210223
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON

DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: WP01
Waste Code Description: Washington State Extremely Hazardous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of Greater than 1.0%.

Hazardous Waste Code: WP02
Waste Code Description: Washington State Dangerous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of 0.01% to 1.0%.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20100202
Handler Name: WA UW WESTERN AVE
Source Type: Annual/Biennial Report update with Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: WSQG
Waste Code Description: A placeholder to allow Handler and BR submissions to validate. In WA State federal and state waste codes were not collected on the Site Identification form until 2013 so they were not available for reporting.

Hazardous Waste Handler Details

Sequence No: 17
Receive Date: 20120214
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 18
Receive Date: 20130208
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 20
Receive Date: 20150204
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 25
Receive Date: 20200221
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Handler Details

Sequence No: 29
Receive Date: 20220214
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20071231
Handler Name: WA UW WESTERN AVE

Source Type: Annual/Biennial Report
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19940101
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 6
Receive Date: 20010302
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 12
Receive Date: 20070212
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 7
Receive Date: 20020301
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 10
Receive Date: 20050228
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 14
Receive Date: 20090212
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 23

Receive Date: 20180221
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Handler Details

Sequence No: 26
Receive Date: 20200222
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20031231
Handler Name: WA UW WESTERN AVE
Source Type: Annual/Biennial Report
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20120214
Handler Name: WA UW WESTERN AVE
Source Type: Annual/Biennial Report update with Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: WSQG
Waste Code Description: A placeholder to allow Handler and BR submissions to validate. In WA State federal and state waste codes were not collected on the Site Identification form until 2013 so they were not available for reporting.

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 19990817
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 19
Receive Date: 20140218
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: U007
Waste Code Description: 2-PROPENAMIDE (OR) ACRYLAMIDE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 20000302
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 11
Receive Date: 20060227
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 22
Receive Date: 20170223
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20051231
Handler Name: WA UW WESTERN AVE
Source Type: Annual/Biennial Report
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 19980903
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 8
Receive Date: 20030303
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 9
Receive Date: 20040331
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 13

Receive Date: 20080207
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 21
Receive Date: 20160216
Handler Name: WA UW WESTERN AVE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: WP01
Waste Code Description: Washington State Extremely Hazardous Persistent Waste containing Halogenated Organic Compounds (HOC) at a total concentration level of Greater than 1.0%.

Hazardous Waste Code: WT01
Waste Code Description: Washington State Extremely Hazardous Toxic Waste with a toxic constituents concentration greater than or equal to 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: U044
Waste Code Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: PHIPPEN, WENDY
Date Became Current: 19980604
Date Ended Current:
Phone: 206-685-2848
Source Type: Notification
Street No:
Street 1: PO BOX 354400
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98195

Owner/Operator Ind: Current Owner
Type: Private
Name: ALEXANDRIA REAL ESTATE EQUITIES INC
Date Became Current: 20171231
Date Ended Current:
Phone: 626-578-0770
Source Type: Notification
Street No:
Street 1: 135 NORTH LOS ROBLES AVE
Street 2:
City: PASADENA
State: CA
Country: US
Zip Code: 91101

Owner/Operator Ind: Current Owner
Street No:

Type:	State	**Street 1:**	PO BOX 354400
Name:	UNIVERSITY OF WASHINGTON	**Street 2:**	
Date Became Current:	19980604	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	98195-4400

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	11440 W BERNARDO CT STE 170
Name:	ALEXANDRIA REAL ESTATE EQUITIES INC	**Street 2:**	
Date Became Current:		**City:**	SAN DIEGO
Date Ended Current:		**State:**	CA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	92127

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	State	**Street 1:**	PO BOX 354400
Name:	UNIVERSITY OF WASHINGTON	**Street 2:**	
Date Became Current:	19980604	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-543-0467	**Country:**	US
Source Type:	Notification	**Zip Code:**	98195

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 354400
Name:	WA UW	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-685-2848	**Country:**	US
Source Type:	Notification	**Zip Code:**	98195

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	State	**Street 1:**	PO BOX 354400
Name:	WA UW	**Street 2:**	
Date Became Current:	19980604	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	98195-4400

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 354400
Name:	WA UW W	**Street 2:**	
Date Became Current:	19980604	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-543-0467	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98195-4400

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 354400
Name:	UNIVERSITY OF WASHINGTON	**Street 2:**	
Date Became Current:	19980604	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98195

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 354400
Name:	UNIVERSITY OF WASHINGTON	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98195-4400

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	3000 WESTERN AVE
Name:	WA UW WESTERN AVE	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US

Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 354400
Name:	UNIVERSITY OF WASHINGTON	**Street 2:**	
Date Became Current:	19980604	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-543-0467	**Country:**	US
Source Type:	Notification	**Zip Code:**	98195
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	State	**Street 1:**	PO BOX 354400
Name:	UNIVERSITY OF WASHINGTON	**Street 2:**	
Date Became Current:	19980604	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-543-0467	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	98195-4400
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	State	**Street 1:**	PO BOX 354400
Name:	WA UW	**Street 2:**	
Date Became Current:	19980604	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-543-0467	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	98195-4400
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 354400
Name:	UNIVERSITY OF W U	**Street 2:**	
Date Became Current:	19980604	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-543-0467	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98195-4400
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 354400
Name:	UNIVERSITY OF WASHINGTON	**Street 2:**	
Date Became Current:	19980604	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-685-2848	**Country:**	US
Source Type:	Notification	**Zip Code:**	98195
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	3000 WESTERN AVE
Name:	WA UW WESTERN AVE	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 354400
Name:	PHIPPEN, WENDY	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-685-2848	**Country:**	US
Source Type:	Notification	**Zip Code:**	98195
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 354400
Name:	WA UW	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-543-0467	**Country:**	US
Source Type:	Notification	**Zip Code:**	98195
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	11440 W BERNARDO CT STE 170
Name:	ALEXANDRIA REAL ESTATE EQUITIES INC	**Street 2:**	

Date Became Current:		**City:**	SAN DIEGO
Date Ended Current:		**State:**	CA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	92127
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	11440 W BERNARDO CT STE 170
Name:	ALEXANDRIA REAL ESTATE EQUITIES INC	**Street 2:**	
Date Became Current:	19980604	**City:**	SAN DIEGO
Date Ended Current:		**State:**	CA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	92127
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	State	**Street 1:**	PO BOX 354400
Name:	WA UW	**Street 2:**	
Date Became Current:	19980604	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-543-0467	**Country:**	US
Source Type:	Notification	**Zip Code:**	98195
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	135 NORTH LOS ROBLES AVE
Name:	ALEXANDRIA REAL ESTATE EQUITIES INC	**Street 2:**	
Date Became Current:		**City:**	PASADENA
Date Ended Current:		**State:**	CA
Phone:	626-578-0770	**Country:**	US
Source Type:	Notification	**Zip Code:**	91101

Historical Handler Details

Receive Dt:	20110217
Generator Code Description:	Very Small Quantity Generator
Handler Name:	WA UW WESTERN AVE
Receive Dt:	20010302
Generator Code Description:	Very Small Quantity Generator
Handler Name:	WA UW WESTERN AVE
Receive Dt:	20160216
Generator Code Description:	Very Small Quantity Generator
Handler Name:	WA UW WESTERN AVE
Receive Dt:	20200221
Generator Code Description:	Very Small Quantity Generator
Handler Name:	WA UW WESTERN AVE
Receive Dt:	20051231
Generator Code Description:	Not a Generator, Verified
Handler Name:	WA UW WESTERN AVE
Receive Dt:	19990817
Generator Code Description:	Very Small Quantity Generator
Handler Name:	WA UW WESTERN AVE
Receive Dt:	20000302
Generator Code Description:	Not a Generator, Verified
Handler Name:	WA UW WESTERN AVE
Receive Dt:	20180221
Generator Code Description:	Very Small Quantity Generator
Handler Name:	WA UW WESTERN AVE
Receive Dt:	20120214
Generator Code Description:	Very Small Quantity Generator
Handler Name:	WA UW WESTERN AVE
Receive Dt:	20031231

Generator Code Description: Not a Generator, Verified
Handler Name: WA UW WESTERN AVE

Receive Dt: 19980903
Generator Code Description: Not a Generator, Verified
Handler Name: WA UW WESTERN AVE

Receive Dt: 20050228
Generator Code Description: Very Small Quantity Generator
Handler Name: WA UW WESTERN AVE

Receive Dt: 20150204
Generator Code Description: Not a Generator, Verified
Handler Name: WA UW WESTERN AVE

Receive Dt: 19980604
Generator Code Description: Not a Generator, Verified
Handler Name: WA UW WESTERN AVE

Receive Dt: 19980903
Generator Code Description: Not a Generator, Verified
Handler Name: WA UW WESTERN AVE

Receive Dt: 20170223
Generator Code Description: Very Small Quantity Generator
Handler Name: WA UW WESTERN AVE

Receive Dt: 20190211
Generator Code Description: Very Small Quantity Generator
Handler Name: WA UW WESTERN AVE

Receive Dt: 20071231
Generator Code Description: Not a Generator, Verified
Handler Name: WA UW WESTERN AVE

Receive Dt: 20120214
Generator Code Description: Very Small Quantity Generator
Handler Name: WA UW WESTERN AVE

Receive Dt: 20090212
Generator Code Description: Very Small Quantity Generator
Handler Name: WA UW WESTERN AVE

Receive Dt: 20100202
Generator Code Description: Very Small Quantity Generator
Handler Name: WA UW WESTERN AVE

Receive Dt: 20070212
Generator Code Description: Very Small Quantity Generator
Handler Name: WA UW WESTERN AVE

Receive Dt: 20210223
Generator Code Description: Very Small Quantity Generator
Handler Name: WA UW WESTERN AVE

Receive Dt: 20040331
Generator Code Description: Not a Generator, Verified
Handler Name: WA UW WESTERN AVE

Receive Dt: 20110217
Generator Code Description: Very Small Quantity Generator
Handler Name: WA UW WESTERN AVE

Receive Dt: 19940101
Generator Code Description: Not a Generator, Verified
Handler Name: WA UW WESTERN AVE

Receive Dt: 20060227
Generator Code Description: Very Small Quantity Generator

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Handler Name: WA UW WESTERN AVE

Receive Dt: 20200222
Generator Code Description: Very Small Quantity Generator
Handler Name: WA UW WESTERN AVE

Receive Dt: 20080207
Generator Code Description: Very Small Quantity Generator
Handler Name: WA UW WESTERN AVE

Receive Dt: 20030303
Generator Code Description: Very Small Quantity Generator
Handler Name: WA UW WESTERN AVE

Receive Dt: 20100202
Generator Code Description: Very Small Quantity Generator
Handler Name: WA UW WESTERN AVE

Receive Dt: 20020301
Generator Code Description: Very Small Quantity Generator
Handler Name: WA UW WESTERN AVE

Receive Dt: 20140218
Generator Code Description: Very Small Quantity Generator
Handler Name: WA UW WESTERN AVE

Receive Dt: 20130208
Generator Code Description: Very Small Quantity Generator
Handler Name: WA UW WESTERN AVE

Receive Dt: 20201110
Generator Code Description: Very Small Quantity Generator
Handler Name: WA UW WESTERN AVE

---

74 | **1 of 4** | **WSW** | **0.19 / 1,017.60** | **15.63 / -90** | **Elliott & Broad**
10 BROAD ST
SEATTLE WA 98121 | **CSCSL**

Fac Site ID: 73229656
Cleanup Site ID: 675
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6155450091659
Longitude: -122.354836574426
Site Name: Elliott & Broad
Address: 10 BROAD ST
City: SEATTLE
Zip Code: 98121
Site Status (OD): Awaiting Cleanup
Site Name (OD): ELLIOTT & BROAD
Address (OD): 10 BROAD ST
City (OD): SEATTLE
Zipcode (OD): 98121
Location (OD): "" (47.616943, -122.347777)
Alternate Site Names: 10 BROAD STREET
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 73229656
Cleanup SiteID(OD): 675
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.347777
Latitude (OD): 47.616943

Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

74	2 of 4	WSW	0.19 / 1,017.60	15.63 / -90	ELLIOTT & BROAD 10 BROAD ST SEATTLE WA 98121	ALL SITES

Facility/Site ID: 73229656
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: ELLIOTT & BROAD
Interaction ID: 61190
Interaction Status: A
Interac Status Desc: Active
Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 17-Aug-2007
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: NW0131
Facility Alternate: ELLIOTT & BROAD
Interaction ID: 61189
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 02-Sep-1998
Interact End Dt: 17-Aug-2007
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6155450092
GIS longitude: -122.354836574

74	3 of 4	WSW	0.19 / 1,017.60	15.63 / -90	ELLIOTT & BROAD 10 BROAD ST SEATTLE WA 98121	ICR

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Cleanup Site ID:	675	**WRIA ID:**	8
Facility Site ID:	73229656	**Is NFA Site:**	
Site Status:	Awaiting Cleanup	**Responsible Unit:**	Northwest
Statute:	MTCA	**Latitude:**	47.616942999999999
Rank:		**Longitude:**	-122.34777699999999
Rank Description:		**Legislative District:**	36
Has Env Covenant:		**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	1998-09-02
Activity Name:	Site Discovery/Release Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Madakor, Nnamdi
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	
VCP Prj No:	NW0131	**End Date:**	1998-11-23
Activity Name:	VCP Termination	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	1998-09-16
VCP Prj No:	NW0131	**End Date:**	1998-11-23
Activity Name:	VCP Opinion on Remedial Investigation Work Plan	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Madakor, Nnamdi
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	1998-09-16
VCP Prj No:	NW0131	**End Date:**	
Activity Name:	VCP Application	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Media Contaminants

Contaminant Type:	Petroleum Products-Unspecified	**Sediment:**	
Groundwater:	C	**Sediment Desc.:**	
Groundwater Desc.:	Confirmed Above Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

---

74 | ***4 of 4*** | ***WSW*** | ***0.19 / 1,017.60*** | ***15.63 / -90*** | ***Elliott & Broad
10 BROAD ST
SEATTLE WA 98121*** | ***VCP***

Facility Site ID:	73229656	**County:**	King
Cleanup Site ID:	675	**Latitude:**	47.6155450091659
Region:	Northwest	**Longitude:**	-122.354836574426
Alternate Site Names:	10 BROAD STREET		
Data Source(s):	Confirmed and Suspected Contaminated Sites; Confirmed and Suspected Contaminated Sites; All Cleanup Sites in Washington State		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List

Site Status: Cleanup Started
Current VCP:
Past VCP: Yes
Site Rank:
Responsible Unit: Northwest
Has Inst Control:

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List - Contaminants

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: Cleanup Started
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

75	1 of 2	ESE	0.19 / 1,017.98	114.44 / 9	2ND AVE BELL DRUMS 2408 2ND AVE SEATTLE WA 98121	RCRA NON GEN

EPA Handler ID: WAD981770233
Gen Status Universe: No Report
Contact Name: WA ECY WA ECY
Contact Address: 4350 150TH AVE NE , , REDMOND , WA, 98052-5301 , US
Contact Phone No and Ext: 000-000-0000
Contact Email:
Contact Country: US
County Name: KING
EPA Region: 10
Land Type: Private
Receive Date: 19871211
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No

Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19871211
Handler Name:	2ND AVE BELL DRUMS
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19871211
Handler Name:	2ND AVE BELL DRUMS
Source Type:	Notification
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	19871211
Handler Name:	2ND AVE BELL DRUMS
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	2408 2ND AVE
Name:	WA ECY	***Street 2:***	
Date Became Current:	19960502	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	000-000-0000	***Country:***	US
Source Type:	Notification	***Zip Code:***	98121

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	2408 2ND AVE
Name:	2ND AVE BELL DRUMS	***Street 2:***	
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	000-000-0000	***Country:***	US
Source Type:	Notification	***Zip Code:***	98121

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	2408 2ND AVE
Name:	SEE PAPER COPY	***Street 2:***	
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	000-000-0000	***Country:***	
Source Type:	Implementer	***Zip Code:***	98121

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2408 2ND AVE
Name:	WA ECY W	**Street 2:**	
Date Became Current:	19960502	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121-1487

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2408 2ND AVE
Name:	WA ECY	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121-1487

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2408 2ND AVE
Name:	2ND AVE BELL DRUMS	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121

Historical Handler Details

Receive Dt:	19871211
Generator Code Description:	Not a Generator, Verified
Handler Name:	2ND AVE BELL DRUMS

75	*2 of 2*	*ESE*	*0.19 / 1,017.98*	*114.44 / 9*	***2nd Ave Bell Drums 2408 2ND AVE SEATTLE WA 98121***	***ALL SITES***

Facility/Site ID:	23378833
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAD981770233
Facility Alternate:	
Interaction ID:	33153
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	11-Dec-1987
Interact End Dt:	31-Dec-1991
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	N
Horizont 1:	NAD83	**GIS latitude:**	47.615
Horizont 2:	Unknown	**GIS longitude:**	-122.34705

76	*1 of 4*	*SE*	*0.19 / 1,026.78*	*103.77 / -2*	***A 1 Laundry Inc 2401 1st Ave Seattle WA 98121***	***DRYCLEANERS***

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility Site ID: 3442
Latitude: 47.61412
Longitude: -122.34823

Detaills

Program Sys Name: TURBOWASTE
Interaction Type: Hazardous Waste Generator
Status: Inactive
Start Date: 9/15/2015
End Date: 1/26/2017
Horizontal Acc Cd: Unknown
Program Facility Name: A 1 Laundry Inc
NAICS Description: Drycleaning and Laundry Services (except Coin-Operated)
SIC Description:
Definition: Facilities that generate any quantity of a dangerous waste. They may be classified as SQG, MQG, or LQG depending on hazardous waste generated for a given month.

76	2 of 4	SE	0.19 / 1,026.78	103.77 / -2	A 1 Laundry Inc 2401 1st Ave Seattle WA 98121	ALL SITES

Facility/Site ID: 3442
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000049635
Facility Alternate: A 1 Laundry Inc
Interaction ID: 114731
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 15-Sep-2015
Interact End Dt: 26-Jan-2017
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Address
Location Verified:
GIS latitude: 47.61412
GIS longitude: -122.34823

76	3 of 4	SE	0.19 / 1,026.78	103.77 / -2	A 1 LAUNDRY INC 2401 1ST AVE SEATTLE WA 98121	RCRA NON GEN

EPA Handler ID: WAH000049635
Gen Status Universe: No Report
Contact Name: JIMMY BLAIS
Contact Address: 9125 10TH AVE S , , SEATTLE , WA, 98108 , US
Contact Phone No and Ext: 206-255-5153
Contact Email: JBLAIS@GMCCINC.COM
Contact Country: US
County Name: KING
EPA Region: 10
Land Type: Private
Receive Date: 20170126
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20160314
Handler Name: A 1 LAUNDRY INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D040
Waste Code Description: TRICHLORETHYLENE

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20170126
Handler Name: A 1 LAUNDRY INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20150915
Handler Name: A 1 LAUNDRY INC
Source Type: Notification
Federal Waste Generator Code: 2

Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D040
Waste Code Description: TRICHLORETHYLENE

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: A 1 LAUNDRY INC
Date Became Current:
Date Ended Current:
Phone: 206-441-1570
Source Type: Notification
Street No:
Street 1: 2401 1ST AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Owner
Type: Private
Name: A 1 LAUNDRY INC
Date Became Current: 19850101
Date Ended Current:
Phone: 206-441-1570
Source Type: Notification
Street No:
Street 1: 2401 1ST AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Owner
Type: Private
Name: HULL BUILDING LLC
Date Became Current:
Date Ended Current:
Phone: 206-255-5153
Source Type: Notification
Street No:
Street 1: 5050 1ST AVE S.
Street 2: SUITE 102
City: SEATTLE
State: WA
Country: US
Zip Code: 98134

Owner/Operator Ind: Current Owner
Type: Private
Name: ENG, CHRISTOPHER
Date Became Current:
Date Ended Current:
Phone: 206-441-1570
Source Type: Notification
Street No:
Street 1: 2401 1ST AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Operator
Type: Private
Name: A 1 LAUNDRY INC
Date Became Current:
Date Ended Current:
Phone: 206-441-1570
Source Type: Implementer
Street No:
Street 1: 2401 1ST AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Owner
Type: Private
Name: A 1 LAUNDRY INC
Date Became Current: 19850101
Date Ended Current:
Phone: 206-441-1570
Source Type: Implementer
Street No:
Street 1: 2401 1ST AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Owner
Type: Private
Name: HULL BUILDING LLC
Date Became Current:
Date Ended Current:
Phone: 206-255-5153
Source Type: Implementer
Street No:
Street 1: 5050 1ST AVE S.
Street 2: SUITE 102
City: SEATTLE
State: WA
Country: US
Zip Code: 98134

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Historical Handler Details

Receive Dt:	20150915
Generator Code Description:	Small Quantity Generator
Handler Name:	A 1 LAUNDRY INC
Receive Dt:	20160314
Generator Code Description:	Very Small Quantity Generator
Handler Name:	A 1 LAUNDRY INC

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
76	4 of 4	SE	0.19 / 1,026.78	103.77 / -2	A 1 LAUNDRY INC 2401 1ST AVE SEATTLE WA 98121	FED DRYCLEANERS

FRS Facility ID:	110064832061
NPDES IDs:	
NAICS Codes:	812320
SIC Codes:	
Latitude:	47.61426
Longitude:	-122.34802

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	1 of 2	ENE	0.20 / 1,062.07	127.50 / 22	FAT CITY INC 508 DENNY WAY SEATTLE WA 98109	RCRA NON GEN

EPA Handler ID:	WAD988513578
Gen Status Universe:	No Report
Contact Name:	CAROL EDWARD
Contact Address:	508 DENNY WAY , , SEATTLE , WA, 98109 , US
Contact Phone No and Ext:	206-443-1999
Contact Email:	JESSEF@FATCITY.NET
Contact Country:	US
County Name:	KING
EPA Region:	10
Land Type:	Private
Receive Date:	20060420
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 19970305
Handler Name: FAT CITY INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 11
Receive Date: 20030218
Handler Name: FAT CITY INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20031231
Handler Name: FAT CITY INC
Source Type: Annual/Biennial Report
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 14
Receive Date: 20060419
Handler Name: FAT CITY INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20051231
Handler Name: FAT CITY INC
Source Type: Annual/Biennial Report
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 9
Receive Date: 20010305
Handler Name: FAT CITY INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 8
Receive Date: 20000314
Handler Name: FAT CITY INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 10
Receive Date: 20020206
Handler Name: FAT CITY INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 13
Receive Date: 20050426
Handler Name: FAT CITY INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060419
Handler Name: FAT CITY INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 19950101
Handler Name: FAT CITY INC
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19931231
Handler Name: FAT CITY INC
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19940101
Handler Name: FAT CITY INC
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 7
Receive Date: 19990106
Handler Name: FAT CITY INC
Source Type: Notification

Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060419
Handler Name: FAT CITY INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 15
Receive Date: 20060420
Handler Name: FAT CITY INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 19970701
Handler Name: FAT CITY INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 6
Receive Date: 19980319
Handler Name: FAT CITY INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 12
Receive Date: 20040430
Handler Name: FAT CITY INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: FAT CITY INC
Date Became Current:
Date Ended Current:
Phone: 206-443-1999
Source Type: Implementer
Street No:
Street 1: 508 DENNY WAY
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98109-5009

Owner/Operator Ind: Current Owner
Type: Private
Name: FAT CITY INC
Date Became Current: 19971106
Street No:
Street 1: 508 DENNY WAY
Street 2:
City: SEATTLE

Date Ended Current:		**State:**	WA
Phone:	206-443-1999	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98109
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	508 DENNY WAY
Name:	JESSE BERGER	**Street 2:**	
Date Became Current:	19941101	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	98119
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	508 DENNY WAY
Name:	FAT CITY INC	**Street 2:**	
Date Became Current:	19971106	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	98109-5009
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	508 DENNY WAY
Name:	FAT CITY INC F	**Street 2:**	
Date Became Current:	19971106	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-443-1999	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98109-5009
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	508 DENNY WAY
Name:	JESSE B	**Street 2:**	
Date Became Current:	19941101	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-443-1999	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98119
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	508 DENNY WAY
Name:	FAT CITY INC	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	508 DENNY WAY
Name:	BERGER, JESSE E	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-443-1999	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98119
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	508 DENNY WAY
Name:	FAT CITY INC	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2111 1ST AVE W
Name:	BERGER, JESSE	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-282-8757	**Country:**	US
Source Type:	Notification	**Zip Code:**	98119
Owner/Operator Ind:	Current Operator	**Street No:**	

Type:	Private	***Street 1:***	508 DENNY WAY
Name:	BERGER, JESSE E	***Street 2:***	
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-443-1999	***Country:***	US
Source Type:	Notification	***Zip Code:***	98119
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	2111 1ST AVE W
Name:	BERGER, JESSE	***Street 2:***	
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-282-8757	***Country:***	US
Source Type:	Implementer	***Zip Code:***	98119
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	508 DENNY WAY
Name:	FAT CITY INC	***Street 2:***	
Date Became Current:	19971106	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-443-1999	***Country:***	US
Source Type:	Notification	***Zip Code:***	98109

Historical Handler Details

Receive Dt:	20030218
Generator Code Description:	Very Small Quantity Generator
Handler Name:	FAT CITY INC
Receive Dt:	20060419
Generator Code Description:	Very Small Quantity Generator
Handler Name:	FAT CITY INC
Receive Dt:	20010305
Generator Code Description:	Very Small Quantity Generator
Handler Name:	FAT CITY INC
Receive Dt:	20060419
Generator Code Description:	Not a Generator, Verified
Handler Name:	FAT CITY INC
Receive Dt:	19940101
Generator Code Description:	Not a Generator, Verified
Handler Name:	FAT CITY INC
Receive Dt:	20050426
Generator Code Description:	Very Small Quantity Generator
Handler Name:	FAT CITY INC
Receive Dt:	20000314
Generator Code Description:	Very Small Quantity Generator
Handler Name:	FAT CITY INC
Receive Dt:	19970305
Generator Code Description:	Very Small Quantity Generator
Handler Name:	FAT CITY INC
Receive Dt:	19931231
Generator Code Description:	Small Quantity Generator
Handler Name:	FAT CITY INC
Receive Dt:	19990106
Generator Code Description:	Very Small Quantity Generator
Handler Name:	FAT CITY INC
Receive Dt:	20060419
Generator Code Description:	Not a Generator, Verified
Handler Name:	FAT CITY INC

Receive Dt: 19950101
Generator Code Description: Not a Generator, Verified
Handler Name: FAT CITY INC

Receive Dt: 19970701
Generator Code Description: Very Small Quantity Generator
Handler Name: FAT CITY INC

Receive Dt: 20020206
Generator Code Description: Very Small Quantity Generator
Handler Name: FAT CITY INC

Receive Dt: 20051231
Generator Code Description: Not a Generator, Verified
Handler Name: FAT CITY INC

Receive Dt: 20031231
Generator Code Description: Not a Generator, Verified
Handler Name: FAT CITY INC

Receive Dt: 20040430
Generator Code Description: Very Small Quantity Generator
Handler Name: FAT CITY INC

Receive Dt: 19980319
Generator Code Description: Very Small Quantity Generator
Handler Name: FAT CITY INC

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	2 of 2	ENE	0.20 / 1,062.07	127.50 / 22	Fat City Inc 508 DENNY WAY SEATTLE WA 98109-5009	ALL SITES

Facility/Site ID: 18619224
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAD988513578
Facility Alternate:
Interaction ID: 30667
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 09-Nov-1992
Interact End Dt: 31-Dec-2005
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.61871
GIS longitude: -122.34745

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
78	1 of 2	S	0.20 / 1,063.52	36.21 / -70	TRIAD VINE & ELLIOT LLC 10 WALL ST SEATTLE WA 98121	RCRA NON GEN

EPA Handler ID: WAH000013706
Gen Status Universe: No Report

Contact Name:	DAN RAMRAS
Contact Address:	2801 ALASKAN WAY , #107 , SEATTLE , WA, 98121 , US
Contact Phone No and Ext:	206-374-0414
Contact Email:	DAN@TRIADDEU.COM
Contact Country:	US
County Name:	KING
EPA Region:	10
Land Type:	Private
Receive Date:	20040225
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20040224
Handler Name:	TRIAD VINE & ELLIOT LLC
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20031231
Handler Name:	TRIAD VINE & ELLIOT LLC
Source Type:	Annual/Biennial Report
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	5
Receive Date:	20040225
Handler Name:	TRIAD VINE & ELLIOT LLC
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20020205
Handler Name: SKYWAY LUGGAGE BUILDING
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 20040224
Handler Name: TRIAD VINE & ELLIOT LLC
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20040224
Handler Name: TRIAD VINE & ELLIOT LLC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20030221
Handler Name: SKYWAY LUGGAGE BUILDING
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20010102
Handler Name: SKYWAY LUGGAGE BUILDING
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: TRIAD VINE ELLIOT LLC
Date Became Current: 20010102
Date Ended Current:
Phone: 206-374-0414
Source Type: Implementer
Street No:
Street 1: 2801 ALASKAN WAY
Street 2: #107
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Owner
Type: Private
Name: TRIAD VINE ELLIOT LLC
Date Became Current: 20010102
Date Ended Current:
Phone: 206-374-0414
Source Type: Notification
Street No:
Street 1: 2801 ALASKAN WAY
Street 2: #107
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2801 ALASKAN WAY
Name:	TRIAD VINE ELLIOTT LLC	**Street 2:**	#107
Date Became Current:	20031231	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-374-0414	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2801 ALASKAN WAY
Name:	TRIAD VINE ELLIOTT LLC	**Street 2:**	#107
Date Became Current:	20010102	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-374-0414	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2801 ALASKAN WAY
Name:	TRIAD VINE ELLIOTT LLC	**Street 2:**	#107
Date Became Current:	20010102	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-374-0414	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2801 ALASKAN WAY
Name:	DAN R	**Street 2:**	#107
Date Became Current:	20010102	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-374-0414	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2801 ALASKAN WAY
Name:	TRIAD VINE & ELLIOT LLC	**Street 2:**	#107
Date Became Current:	20010102	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	98121

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2801 ALASKAN WAY
Name:	TRIAD VINE & ELLIOTT LLC	**Street 2:**	#107
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-374-0414	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2801 ALASKAN WAY
Name:	TRIAD VINE & ELLIOT LLC	**Street 2:**	#107
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-374-0414	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2801 ALASKAN WAY
Name:	TRIAD VINE & ELLIOT LLC	**Street 2:**	#107
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-374-0414	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2801 ALASKAN WAY
Name:	TRIAD VINE & EL T	**Street 2:**	#107
Date Became Current:	20010102	**City:**	SEATTLE
Date Ended Current:		**State:**	WA

Phone:	206-374-0414	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2801 ALASKAN WAY
Name:	TRIAD VINE ELLIOTT LLC	**Street 2:**	#107
Date Became Current:	20010102	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-374-0414	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2801 ALASKAN WAY
Name:	TRIAD VINE & ELLIOTT LLC	**Street 2:**	#107
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-374-0414	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2801 ALASKAN WAY
Name:	TRIAD VINE & ELLIOTT LLC	**Street 2:**	#107
Date Became Current:	20010102	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2801 ALASKAN WAY
Name:	TRIAD VINE ELLIOTT LLC	**Street 2:**	#107
Date Became Current:	20031231	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-374-0414	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121

Historical Handler Details

Receive Dt:	20040224
Generator Code Description:	Not a Generator, Verified
Handler Name:	TRIAD VINE & ELLIOT LLC
Receive Dt:	20040224
Generator Code Description:	Not a Generator, Verified
Handler Name:	TRIAD VINE & ELLIOT LLC
Receive Dt:	20030221
Generator Code Description:	Not a Generator, Verified
Handler Name:	SKYWAY LUGGAGE BUILDING
Receive Dt:	20010102
Generator Code Description:	Not a Generator, Verified
Handler Name:	SKYWAY LUGGAGE BUILDING
Receive Dt:	20031231
Generator Code Description:	Not a Generator, Verified
Handler Name:	TRIAD VINE & ELLIOT LLC
Receive Dt:	20040224
Generator Code Description:	Not a Generator, Verified
Handler Name:	TRIAD VINE & ELLIOT LLC
Receive Dt:	20020205
Generator Code Description:	Not a Generator, Verified
Handler Name:	SKYWAY LUGGAGE BUILDING

78	*2 of 2*	*S*	*0.20 / 1,063.52*	*36.21 / -70*	*Triad Vine & Elliot LLC 10 WALL ST*	*ALL SITES*

SEATTLE WA 98121

Facility/Site ID: 13291732
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000013706
Facility Alternate:
Interaction ID: 27427
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWOTHER
Interaction Desc: Haz Waste Management Activity
Interact Start Dt: 31-Dec-2001
Interact End Dt: 31-Dec-2003
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAH000013706
Facility Alternate:
Interaction ID: 27426
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 02-Jan-2001
Interact End Dt: 31-Dec-2001
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Address
Location Verified: N
GIS latitude: 47.613333
GIS longitude: -122.350861

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
79	1 of 1	NE	0.21 / 1,095.97	130.36 / 25	FISHER PLAZA 140 4TH AVE N SEATTLE WA 98109	ALL SITES

Facility/Site ID: 6806
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: CRK000038170
Facility Alternate: FISHER PLAZA
Interaction ID: 123124
Interaction Status: A
Interac Status Desc: Active
Interaction Type: TIER2
Interaction Desc: Emergency/Haz Chem Rpt TIER2
Interact Start Dt: 18-Apr-2005
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: EPCRA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Database Name Desc: Emergency Planning & Community Right-to-Know Act

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	
Horizont 1:	WGS84	**GIS latitude:**	47.61941
Horizont 2:	Address	**GIS longitude:**	-122.34807

80	1 of 6	E	0.21 / 1,099.70	123.29 / 18	PARSON SEATRUST PARTNERSHIP 400 WALL ST SEATTLE WA 98121	RCRA NON GEN

EPA Handler ID: WA0000100503
Gen Status Universe: No Report
Contact Name: MICKEY SMITH
Contact Address: 18912 N CREEK PKWY STE 100 , , BOTHELL , WA, 98011 , US
Contact Phone No and Ext: 206-682-3300
Contact Email:
Contact Country: US
County Name: KING
EPA Region: 10
Land Type: Private
Receive Date: 20100125
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 19971210
Handler Name: PARSON SEATRUST PARTNERSHIP
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1

Receive Date: 19931231
Handler Name: PARSON SEATRUST PARTNERSHIP
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 19971209
Handler Name: PARSON SEATRUST PARTNERSHIP
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20100125
Handler Name: PARSON SEATRUST PARTNERSHIP
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19970107
Handler Name: PARSON SEATRUST PARTNERSHIP
Source Type: Notification
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19960301
Handler Name: PARSONS SEATRUST PARTNERSHIP
Source Type: Annual/Biennial Report
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20100125
Handler Name: PARSON SEATRUST PARTNERSHIP
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 20100125
Handler Name: PARSON SEATRUST PARTNERSHIP
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 6
Receive Date: 20100125
Handler Name: PARSON SEATRUST PARTNERSHIP
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: REPUBLIC PARKIN R
Date Became Current: 19000101
Date Ended Current:
Phone: 206-728-4457
Source Type: Implementer
Street No:
Street 1: 2819 ELLIOTT AVE
Street 2: SUITE 201
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Owner
Type: Private
Name: PARSONS SEATRUST PARTNERSHIP
Date Became Current:
Date Ended Current:
Phone: 212-622-3667
Source Type: Implementer
Street No:
Street 1: 380 MADISON AVE FL 9
Street 2:
City: NEW YORK
State: NY
Country: US
Zip Code: 10017

Owner/Operator Ind: Current Owner
Type: Private
Name: PARSONS SEATRUST PARTNERSHIP
Date Became Current: 19970110
Date Ended Current:
Phone: 212-622-3667
Source Type: Notification
Street No:
Street 1: 380 MADISON AVE FL 9
Street 2:
City: NEW YORK
State: NY
Country: US
Zip Code: 10017

Owner/Operator Ind: Current Operator
Type: Private
Name: PARSONS SEATRUST PARTNERSHIP
Date Became Current:
Date Ended Current:
Phone: 212-622-3667
Source Type: Implementer
Street No:
Street 1: 380 MADISON AVE FL 9
Street 2:
City: NEW YORK
State: NY
Country: US
Zip Code: 10017

Owner/Operator Ind: Current Owner
Type: Private
Name: PARSONS SEATRUST PARTNERSHIP
Date Became Current: 19970110
Date Ended Current:
Phone: 212-622-3667
Source Type: Implementer
Street No:
Street 1: 380 MADISON AVE FL 9
Street 2:
City: NEW YORK
State: NY
Country: US
Zip Code: 10017

Owner/Operator Ind: Current Owner
Type: Private
Name: PARSON SEATRUST PARTNERSHIP
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 2500 4TH AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Operator
Type: Private
Name: PARSONS SEATRUST PARTNERSHIP
Date Became Current:
Date Ended Current:
Phone: 212-622-3667
Source Type: Notification
Street No:
Street 1: 380 MADISON AVE FL 9
Street 2:
City: NEW YORK
State: NY
Country: US
Zip Code: 10017

Owner/Operator Ind: Current Owner
Type: Private
Street No:
Street 1: 380 MADISON AVE FL 9

Name:	PARSONS SEATRUS P	**Street 2:**	
Date Became Current:	19000101	**City:**	NEW YORK
Date Ended Current:		**State:**	NY
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	10017-2513

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	380 MADISON AVE FL 9
Name:	PARSONS SEATRUST PARTNERSHIP	**Street 2:**	
Date Became Current:		**City:**	NEW YORK
Date Ended Current:		**State:**	NY
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	10017

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	380 MADISON AVE FL 9
Name:	PARSONS SEATRUST PARTNERSHIP	**Street 2:**	
Date Became Current:		**City:**	NEW YORK
Date Ended Current:		**State:**	NY
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	10017

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2819 ELLIOTT AVE
Name:	REPUBLIC PARKING NORTHWEST	**Street 2:**	SUITE 201
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-4457	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	380 MADISON AVE FL 9
Name:	PARSONS SEATRUST PARTNERSHIP	**Street 2:**	
Date Became Current:		**City:**	NEW YORK
Date Ended Current:		**State:**	NY
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	10017-2513

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2819 ELLIOTT AVE
Name:	REPUBLIC PARKING NORTHWEST	**Street 2:**	SUITE 201
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-4457	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	380 MADISON AVE FL 9
Name:	PARSONS SEATRUST PARTNERSHIP	**Street 2:**	
Date Became Current:		**City:**	NEW YORK
Date Ended Current:		**State:**	NY
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	10017-2513

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	380 MADISON AVE FL 9
Name:	PARSONS SEATRUST PARTNERSHIP	**Street 2:**	
Date Became Current:		**City:**	NEW YORK
Date Ended Current:		**State:**	NY
Phone:	212-622-3667	**Country:**	US
Source Type:	Notification	**Zip Code:**	10017

Historical Handler Details

Receive Dt:	20100125
Generator Code Description:	Not a Generator, Verified
Handler Name:	PARSON SEATRUST PARTNERSHIP

Receive Dt: 19931231
Generator Code Description: Small Quantity Generator
Handler Name: PARSON SEATRUST PARTNERSHIP

Receive Dt: 19971210
Generator Code Description: Not a Generator, Verified
Handler Name: PARSON SEATRUST PARTNERSHIP

Receive Dt: 19971209
Generator Code Description: Not a Generator, Verified
Handler Name: PARSON SEATRUST PARTNERSHIP

Receive Dt: 20100125
Generator Code Description: Not a Generator, Verified
Handler Name: PARSON SEATRUST PARTNERSHIP

Receive Dt: 20100125
Generator Code Description: Not a Generator, Verified
Handler Name: PARSON SEATRUST PARTNERSHIP

Receive Dt: 19970107
Generator Code Description: Large Quantity Generator
Handler Name: PARSON SEATRUST PARTNERSHIP

Receive Dt: 19960301
Generator Code Description: Large Quantity Generator
Handler Name: PARSONS SEATRUST PARTNERSHIP

80	2 of 6	E	0.21 / 1,099.70	123.29 / 18	**Parson Seatrust Partnership** **400 WALL ST** **SEATTLE WA 98121**	CSCSL NFA

Fac Site ID: 2543
Cleanup Site ID: 5141
Site Status: NFA
NFA Date: 01/20/1999
Responsible Unit: Northwest
Has Insti Control:
Region: Northwest
County: King
Latitude: 47.6171874610111
Longitude: -122.346209744259

Fac Site ID (OD): 2543
Cleanup SiteID(OD): 5141
Site Status (OD): No Further Action
Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
Region (OD): Northwest
County (OD): King
Latitude (OD): 47.617081
Longitude (OD): -122.346435

NFA Reason: Independent Remedial Action Program Review
Alternate Site Names: KEY LOCK PARKING LOT,PARSONS BLOCK,Selig Property
Location (OD): ""
(47.617081, -122.346435)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

NFA Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Remediated
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Remediated

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
80	3 of 6	E	0.21 / 1,099.70	123.29 / 18	KEY LOCK PARKING LOT 400 WALL ST Seattle WA 98109	UST

UST ID: 102119
Facility Site ID: 2543
Site Active: No
Responsible Unit: Northwest
Active Tag:
Region: Northwest
County: King
Latitude: 47.6171874610111
Longitude: -122.346209744259
Alternate Site Names: Parson Seatrust Partnership,PARSONS BLOCK,Selig Property

Tank Detail(s)

Tank Name: 2
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:
Tank Construction:
Tank Capacity: 111 TO 1,100 Gallons
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance:
Used Substance:

Tank Detail(s)

Tank Name: 1
Status Date: 08/06/1996
Install Date: 01/01/1973
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material:
Tank Construction:
Tank Capacity:
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance:
Used Substance:

Tank Detail(s)

Tank Name: 3
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction:
Tank Capacity:
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance:
Used Substance:

Tank Detail(s)

Tank Name: 4
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:

Tank Construction:
Tank Capacity:
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Tank Status:	Removed
Tank Material:	
Tank Corrosion Protection:	
Tank Manifold:	
Tank Release Detection:	
Tank Tightness Test:	
Tank Spill Prevention:	
Tank Overfill Prevention:	
Pipe Material:	
Pipe Construction:	
Pipe Corrosion Protection:	
Tank SFC:	
Dispenser SFC:	
Primary Pipe Release Detection:	
Secondary Pipe Rel Detect:	
Pipe Pumping System:	
Turbine Sump Construction:	

Compartments

Compartment No:	1
Compart Capacity:	
Stored Substance:	
Used Substance:	

80	*4 of 6*	*E*	*0.21 / 1,099.70*	*123.29 / 18*	***Parson Seatrust Partnership*** ***400 WALL ST*** ***SEATTLE WA 98121***	***ALL SITES***

Facility/Site ID:	2543
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	102119
Facility Alternate:	Parson Seatrust Partnership
Interaction ID:	4748
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	IRAP
Interaction Desc:	Independent Remedial Actn Prg
Interact Start Dt:	27-Mar-1995
Interact End Dt:	19-Feb-1997
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Program ID:	WA0000100503
Facility Alternate:	
Interaction ID:	4747
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	24-Jan-1994
Interact End Dt:	09-Jun-1995
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Program ID:	102119
Facility Alternate:	

Interaction ID:	4746
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	UST
Interaction Desc:	Underground Storage Tank
Interact Start Dt:	18-Nov-1993
Interact End Dt:	
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	UST
Database Name Desc:	Underground Storage Tanks

Program ID:	WA0000100503
Facility Alternate:	PARSON SEATRUST PARTNERSHIP
Interaction ID:	90003
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	HWOTHER
Interaction Desc:	Haz Waste Management Activity
Interact Start Dt:	25-Jan-2010
Interact End Dt:	
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Program ID:	102119
Facility Alternate:	
Interaction ID:	4745
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	LUST
Interaction Desc:	LUST Facility
Interact Start Dt:	30-Sep-1993
Interact End Dt:	19-Feb-1997
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Facility Location Detail

Horizontal:	40ft	***Location Verified:***	
Horizont 1:	NAD83HARN	***GIS latitude:***	47.617187461
Horizont 2:	Digital map or GIS	***GIS longitude:***	-122.346209744

---

80 ***5 of 6*** ***E*** ***0.21 / 1,099.70*** ***123.29 / 18*** ***Parson Seatrust Partnership 400 WALL ST SEATTLE WA 98121*** ***ICR***

Cleanup Site ID:	5141	***WRIA ID:***	8
Facility Site ID:	2543	***Is NFA Site:***	Yes
Site Status:	No Further Action Required	***Responsible Unit:***	Northwest
Statute:	MTCA	***Latitude:***	47.6170811490761
Rank:		***Longitude:***	-122.346435050127
Rank Description:		***Legislative District:***	36
Has Env Covenant:		***Congr District:***	7
Is Brownfiled Site:		***County Name:***	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	1999-01-20
Activity Name:	Site Status Changed to NFA	***Legal Mechanism:***	
Activity Status:		***Performed by:***	

County Name: King
Applies to: CleanupSite
Applies to Description:
Project Manager:

Related ID:
VCP Prj No:
Activity Name: Site Discovery/Release Report Received
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date:
End Date: 1993-08-09
Legal Mechanism:
Performed by:
Project Manager: Atkinson, Elaine

Related ID: 3057
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 1992-03-13
End Date: 1992-03-13
Legal Mechanism:
Performed by:
Project Manager:

Related ID: 5724
VCP Prj No:
Activity Name: Independent Report Review - Paid
Activity Status: Completed
County Name: King
Applies to: CleanupUnit
Applies to Description:
Start Date: 1995-03-27
End Date: 1995-07-13
Legal Mechanism:
Performed by: Ecology
Project Manager: Atkinson, Elaine

Related ID: 3057
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 1995-03-16
End Date: 1995-03-17
Legal Mechanism:
Performed by:
Project Manager:

Related ID: 3057
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 1997-01-08
End Date: 1997-01-10
Legal Mechanism:
Performed by:
Project Manager:

Related ID: 3057
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 1998-10-21
End Date: 1998-11-19
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No:
Activity Name: Initial Investigation / Federal Preliminary Assessment
Activity Status: Completed
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date: 1995-07-05
End Date: 1995-07-05
Legal Mechanism:
Performed by: Ecology
Project Manager: Atkinson, Elaine

Related ID: 3057
VCP Prj No:
Activity Name: LUST - Notification
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 1993-09-30
End Date: 1993-09-30
Legal Mechanism:
Performed by:
Project Manager:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Related ID:	3057	**Start Date:**	1998-06-09
VCP Prj No:		**End Date:**	1998-11-19
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	3057	**Start Date:**	1999-01-18
VCP Prj No:		**End Date:**	1999-01-19
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Media Contaminants

Contaminant Type:	Petroleum-Other	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

Contaminant Type:	Petroleum Products-Unspecified	**Sediment:**	
Groundwater:	R	**Sediment Desc.:**	
Groundwater Desc.:	Remediated	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:		**Bedrock Desc.:**	
Soil Desc.:		**County Name:**	King

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
80	6 of 6	E	0.21 / 1,099.70	123.29 / 18	**Parson Seatrust Partnership** **400 WALL ST** **SEATTLE WA 98121**	LUST

Facility Site ID:	2543	**County:**	King
Cleanup Site ID:	5141	**Latitude:**	47.6171874610111
Responsible Unit:	Northwest	**Longitude:**	-122.346209744259
Region:	Northwest		
Alternate Site Names:	KEY LOCK PARKING LOT,PARSONS BLOCK,Selig Property		

Tank Detail(s)

UST ID:	102119	**Status Date:**	02/19/1997
LUST ID:	3057	**Release Date:**	09/30/1993
LUST Status:	LUST - NFA		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Other	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Confirmed Above Cleanup Levels		

Contaminants Detail(s)

Contaminant Name:	Petroleum Products-Unspecified	**Sediment:**	
Groundwater:	Remediated	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
81	1 of 1	E	0.21 / 1,111.03	122.36 / 17	2466 4TH AVE Seattle WA 98103	UST SEATTLE

Permit No: 3-43047
Date Issued: 06/25/2002
Fill Material: No Fill
Date Decommissioned: 07/02/2002
Type Decommissioned: Abandonment in Place
Tank Size: 300
Tank Age: 40
Tank Content: HEATINGOIL

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
82	1 of 8	W	0.21 / 1,117.79	46.12 / -60	GRAPHICOLOR INC 3018 WESTERN AVE SEATTLE WA 98121-1023	RCRA NON GEN

EPA Handler ID: WAD094627460
Gen Status Universe: No Report
Contact Name: GRAPHICOLOR INC GRAPHICOLOR INC
Contact Address: 3018 WESTERN AVE , , SEATTLE , WA, 98121-1023 , US
Contact Phone No and Ext: 000-000-0000
Contact Email:
Contact Country: US
County Name: KING
EPA Region: 10
Land Type: Private
Receive Date: 19851010
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19851010
Handler Name: GRAPHICOLOR INC
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19851010
Handler Name: GRAPHICOLOR INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19851010
Handler Name: GRAPHICOLOR INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: GRAPHICOLOR INC
Date Became Current: 19960502
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 3018 WESTERN AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Owner
Type: Private
Name: GRAPHICOLOR INC
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 3018 WESTERN AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Operator
Type: Private
Name: GRAPHICOLOR INC
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 3018 WESTERN AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Operator
Type: Private
Name: GRAPHICOLOR INC
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Implementer
Street No:
Street 1: 3018 WESTERN AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121-1023

Owner/Operator Ind: Current Owner
Type: Private
Name: SEE PAPER COPY
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Implementer
Street No:
Street 1: 3018 WESTERN AVE
Street 2:
City: SEATTLE
State: WA
Country:
Zip Code: 98121-1023

Owner/Operator Ind: Current Owner
Type: Private
Name: GRAPHICOLOR INC G
Date Became Current: 19960502
Date Ended Current:
Phone: 000-000-0000
Source Type: Implementer
Street No:
Street 1: 3018 WESTERN AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121-1023

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Historical Handler Details

Receive Dt:	19851010
Generator Code Description:	Not a Generator, Verified
Handler Name:	GRAPHICOLOR INC

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
82	2 of 8	W	0.21 / 1,117.79	46.12 / -60	Graphicolor Inc 3018 WESTERN AVE SEATTLE WA 98121	INST

Facility Site ID:	23682319	***Cleanup Site ID:***	5734
Region:	Northwest	***Region (OD):***	Northwest
County:	King	***County (OD):***	King
Latitude:	47.61742	***Latitude (OD):***	47.61742
Longitude:	-122.35498	***Longitude (OD):***	-122.35498
Site Name:	Graphicolor Inc		
Address:	3018 WESTERN AVE		
City:	SEATTLE		
Zip:	98121		
Site Name (OD):	Graphicolor Inc		
Address (OD):	3018 WESTERN AVE		
City (OD):	SEATTLE		
Zipcode (OD):	98121-1023		
Location (OD):	"" (47.61742, -122.35498)		
Data Source(s):	Department of Ecology State of Washington - Environmental Covenants Registry List; Open Data Portal - Institutional Controls or Environmental Covenants Map		

Environmental Covenants Registry List

NFA Date:	
Site Status:	Cleanup Started
Tax Parcel No:	0695000100
Instrument Type:	Environmental Covenant
Media Restrictions:	Soil
Alternate Site Names:	ALEXANDRIA RESEARCH CENTER,BRISTOL MEYER SQUIBB,Bristol Meyer Squibb Western Ave (Property NFA),Graphicolor (Off-Property),ONCOGEN FACILITY
Cnty Recording No:	19990709000795
Cnty Recording Dt:	07/09/1999
Responsible Unit:	Northwest
Active Control:	Yes
Control Stormwater:	No
Control Vapor Gas:	No
Prevent Reuse/Relocation:	No
Prohibit New Bldg Constr:	No
Prohibit Removal or Alteration:	No
Prohibit Soil Disturbance:	Yes
Ongoing Maint of Remedy:	Yes
Require Educational Programs:	No
Restrict Access:	Yes
Restrict All GW Extr:	Yes
Restrict Domestic GW:	Yes
Restrict Land Use:	Yes
Restrict Sedmnt Cap Disturb:	No
Restrict Shellfish and or Finf:	No
Restrict Surface Water Use:	No
Restrict Swim/Beach Play:	No
Restrictive Signage:	No
Maintain/Protect Monit System:	No
Other:	No

Open Data Portal - Environmental Covenants Map

Facility Site ID:	23682319
Cleanup Status:	Cleanup Started

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Has Env Covenant: Yes
Rank:
Resp Section: Northwest

---

82 **3 of 8** **W** **0.21 / 1,117.79** **46.12 / -60** **Graphicolor Inc**
3018 WESTERN AVE
SEATTLE WA 98121
CSCSL

Fac Site ID: 23682319
Cleanup Site ID: 5734
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control: Yes
County: King
Region: Northwest
Latitude: 47.61742
Longitude: -122.35498
Site Name: Graphicolor Inc
Address: 3018 WESTERN AVE
City: SEATTLE
Zip Code: 98121
Site Status (OD): Cleanup Started
Site Name (OD): Graphicolor Inc
Address (OD): 3018 WESTERN AVE
City (OD): SEATTLE
Zipcode (OD): 98121-1023
Location (OD): "" (47.61742, -122.35498)
Alternate Site Names: ALEXANDRIA RESEARCH CENTER,BRISTOL MEYER SQUIBB,Bristol Meyer Squibb Western Ave (Property NFA),Graphicolor (Off-Property),ONCOGEN FACILITY
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 23682319
Cleanup SiteID(OD): 5734
Site Rank (OD):
Has Env Coven (OD): Yes
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.35498
Latitude (OD): 47.61742

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

82 **4 of 8** **W** **0.21 / 1,117.79** **46.12 / -60** **GRAPHICOLOR INC**
3018 WESTERN AVE
Seattle WA 98121
UST

UST ID: 6604
Facility Site ID: 23682319
Site Active: No
Responsible Unit: Northwest
Active Tag:
Alternate Site Names: ALEXANDRIA RESEARCH CENTER,BRISTOL MEYER SQUIBB,Bristol Meyer Squibb Western Ave (Property NFA),Graphicolor (Off-Property),ONCOGEN FACILITY

Region: Northwest
County: King
Latitude: 47.61742
Longitude: -122.35498

Tank Detail(s)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Tank Name: 1
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Closed in Place
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction:
Tank Capacity: 111 TO 1,100 Gallons
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Leaded Gasoline
Used Substance:

82	5 of 8	W	0.21 / 1,117.79	46.12 / -60	Graphicolor Inc 3018 WESTERN AVE SEATTLE WA 98121-1023	ALL SITES

Facility/Site ID: 23682319
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 6604
Facility Alternate:
Interaction ID: 33372
Interaction Status: A
Interac Status Desc: Active
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 20-Mar-2000
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: WAD094627460
Facility Alternate:
Interaction ID: 33369
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 10-Oct-1985
Interact End Dt: 10-Apr-1990
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program

Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System
Program ID:	6604
Facility Alternate:	
Interaction ID:	33370
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	LUST
Interaction Desc:	LUST Facility
Interact Start Dt:	25-May-1994
Interact End Dt:	25-Oct-1999
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System
Program ID:	
Facility Alternate:	Graphicolor (Off-Property)
Interaction ID:	127349
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	SCS
Interaction Desc:	State Cleanup Site
Interact Start Dt:	28-Jun-2011
Interact End Dt:	
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System
Program ID:	6604
Facility Alternate:	Graphicolor Inc
Interaction ID:	33371
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	VOLCLNST
Interaction Desc:	Voluntary Cleanup Sites
Interact Start Dt:	24-Dec-1998
Interact End Dt:	25-Oct-1999
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	N
Horizont 1:	NAD83	**GIS latitude:**	47.61742
Horizont 2:	Unknown	**GIS longitude:**	-122.35498

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
82	6 of 8	W	0.21 / 1,117.79	46.12 / -60	Graphicolor Inc 3018 WESTERN AVE SEATTLE WA 98121	LUST

Facility Site ID:	23682319	**County:**	King
Cleanup Site ID:	5734	**Latitude:**	47.61742
Responsible Unit:	Northwest	**Longitude:**	-122.35498
Region:	Northwest		
Alternate Site Names:	ALEXANDRIA RESEARCH CENTER,BRISTOL MEYER SQUIBB,Bristol Meyer Squibb Western Ave (Property NFA),Graphicolor (Off-Property),ONCOGEN FACILITY		

Tank Detail(s)

UST ID:	6604	**Status Date:**	06/28/2011
LUST ID:	3506	**Release Date:**	05/25/1994

LUST Status: LUST - Cleanup Started

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

---

82 | ***7 of 8*** | ***W*** | ***0.21 / 1,117.79*** | ***46.12 / -60*** | ***Graphicolor Inc 3018 WESTERN AVE SEATTLE WA 98121-1023*** | ***ICR***

Cleanup Site ID: 5734
Facility Site ID: 23682319
Site Status: Cleanup Started
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant: Yes
Is Brownfiled Site:
Is PSI Site: Yes
WRIA ID: 8
Is NFA Site:
Responsible Unit: Northwest
Latitude: 47.617420000000003
Longitude: -122.35498
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID: 3506
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 1994-05-09
End Date: 1994-05-09
Legal Mechanism:
Performed by:
Project Manager:

Related ID: 3506
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 1995-07-12
End Date: 1995-07-13
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No: NW0186
Activity Name: VCP Application
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 1998-12-24
End Date:
Legal Mechanism:
Performed by:
Project Manager:

Related ID: 3506
VCP Prj No:
Activity Name: LUST - Notification
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 1994-05-25
End Date: 1994-05-25
Legal Mechanism:
Performed by:
Project Manager:

Related ID: 3506
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 1998-11-24
End Date: 1998-12-24
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
Start Date:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

VCP Prj No:	NW0186	**End Date:**	
Activity Name:	VCP Opinion on Cleanup Action	**Legal Mechanism:**	
Activity Status:	Canceled	**Performed by:**	
County Name:	King	**Project Manager:**	Lillie, John T
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	1999-10-25
Activity Name:	Site Status Changed to NFA	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	2009-12-09
VCP Prj No:		**End Date:**	2010-02-01
Activity Name:	Ecology Periodic Review	**Legal Mechanism:**	Governmental Action
Activity Status:	Completed	**Performed by:**	Ecology
County Name:	King	**Project Manager:**	Hickey, Joe
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		**Start Date:**	
VCP Prj No:	NW0186	**End Date:**	1999-10-25
Activity Name:	VCP Termination	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Media Contaminants

Contaminant Type:	Petroleum-Other	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

---

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
82	8 of 8	W	0.21 / 1,117.79	46.12 / -60	**Graphicolor Inc** **3018 WESTERN AVE** **SEATTLE WA 98121**	VCP

Facility Site ID:	23682319	**County:**	King
Cleanup Site ID:	5734	**Latitude:**	47.61742
Region:	Northwest	**Longitude:**	-122.35498
Alternate Site Names:	ALEXANDRIA RESEARCH CENTER,BRISTOL MEYER SQUIBB,Bristol Meyer Squibb Western Ave (Property NFA),Graphicolor (Off-Property),ONCOGEN FACILITY		
Data Source(s):	Confirmed and Suspected Contaminated Sites; Confirmed and Suspected Contaminated Sites; All Cleanup Sites in Washington State		

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List

Site Status:	Cleanup Started
Current VCP:	
Past VCP:	Yes
Site Rank:	
Responsible Unit:	Northwest
Has Inst Control:	Yes

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List - Contaminants

Contaminant Name:	Petroleum-Other	**Sediment:**	

Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: Cleanup Started
Site Rank:
Has Inst Control: Yes
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Petroleum-Other **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

83	1 of 5	ENE	0.21 / 1,118.54	125.97 / 20	**Faulkenbury Wright** **501 DENNY WAY** **SEATTLE WA 98109**	ALL SITES

Facility/Site ID: 81729752
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAD085811768
Facility Alternate:
Interaction ID: 66111
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWTRNSFR
Interaction Desc: Haz Waste Transfer Facility
Interact Start Dt: 31-Dec-2003
Interact End Dt: 31-Dec-2003
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAD085811768
Facility Alternate: Faulkenbury and Wright Drycleaners
Interaction ID: 119154
Interaction Status: A
Interac Status Desc: Active
Interaction Type: HWOTHER
Interaction Desc: Haz Waste Management Activity
Interact Start Dt: 16-Aug-2016
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID:
Facility Alternate: Faulkenbury & Wright
Interaction ID: 129093
Interaction Status: A
Interac Status Desc: Active
Interaction Type: SCS
Interaction Desc: State Cleanup Site

Interact Start Dt:	07-Sep-2018
Interact End Dt:	
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System
Program ID:	WAD085811768
Facility Alternate:	
Interaction ID:	66110
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	22-Aug-1986
Interact End Dt:	31-Dec-2003
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	40ft	**Location Verified:**	
Horizont 1:	NAD83HARN	**GIS latitude:**	47.6183965019
Horizont 2:	Digital map or GIS	**GIS longitude:**	-122.346608068

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
83	2 of 5	ENE	0.21 / 1,118.54	125.97 / 20	Faulkenbury Wright 501 DENNY WAY SEATTLE WA 98109	DRYCLEANERS

Facility Site ID:	81729752
Latitude:	47.6183965019162
Longitude:	-122.346608067886

Detaills

Program Sys Name:	TURBOWASTE	**Start Date:**	8/22/1986
Interaction Type:	Hazardous Waste Generator	**End Date:**	12/31/2003
Status:	Inactive	**Horizontal Acc Cd:**	40ft
Program Facility Name:			
NAICS Description:	Drycleaning and Laundry Services (except Coin-Operated)		
SIC Description:			
Definition:	Facilities that generate any quantity of a dangerous waste. They may be classified as SQG, MQG, or LQG depending on hazardous waste generated for a given month.		

Program Sys Name:	ISIS	**Start Date:**	9/7/2018
Interaction Type:	State Cleanup Site	**End Date:**	
Status:	Active	**Horizontal Acc Cd:**	40ft
Program Facility Name:	Faulkenbury & Wright		
NAICS Description:	Drycleaning and Laundry Services		
SIC Description:			
Definition:	A site is being cleaned up under state regulations. Regulations include Model Toxics Control Act or its predecessors.		

Program Sys Name:	TURBOWASTE	**Start Date:**	12/31/2003
Interaction Type:	Haz Waste Transfer Facility	**End Date:**	12/31/2003
Status:	Inactive	**Horizontal Acc Cd:**	40ft
Program Facility Name:			
NAICS Description:	Drycleaning and Laundry Services (except Coin-Operated)		
SIC Description:			
Definition:	Transfer facility is a site, owned, leased or operated by a transporter of regulated hazardous waste shipments where any of the following occurs: 1) receives wastes from another transporter, 2) transfers wastes from one transport vehicle to another, 3) transfers waste from one container to another, and 4) stores waste within a vehicle or on property for 10 days or less. Examples of transfer facilities include a parking lot, warehouse, truck terminal, barge or steamship loading and unloading facility, or railroad spur loading or unloading facility.		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
83	3 of 5	ENE	0.21 / 1,118.54	125.97 / 20	FAULKENBURY AND WRIGHT DRYCLEANERS 501 DENNY WAY SEATTLE WA 98109	FED DRYCLEANERS

FRS Facility ID: 110005327976
NPDES IDs:
NAICS Codes: 812320
SIC Codes:
Latitude: 47.61856
Longitude: -122.3466

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
83	4 of 5	ENE	0.21 / 1,118.54	125.97 / 20	Faulkenbury & Wright 501 DENNY WAY SEATTLE WA 98109	CSCSL

Fac Site ID: 81729752
Cleanup Site ID: 14831
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6183965019162
Longitude: -122.346608067886
Site Name: Faulkenbury & Wright
Address: 501 DENNY WAY
City: SEATTLE
Zip Code: 98109
Site Status (OD):
Site Name (OD):
Address (OD):
City (OD):
Zipcode (OD):
Location (OD):
Responsible Unit: Northwest
Fac Site ID (OD):
Cleanup SiteID(OD):
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD):
County (OD):
Region (OD):
Longitude (OD):
Latitude (OD):
Alternate Site Names: Faulkenbury & Wright Clothing Cleaners,Faulkenbury Wright
Data Source(s): Confirmed and Suspected Contaminated Sites

Contaminants Detail(s)

Contaminant Name: Halogenated Solvents
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air: Suspected
Bedrock:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
83	5 of 5	ENE	0.21 / 1,118.54	125.97 / 20	FAULKENBURY AND WRIGHT DRYCLEANERS 501 DENNY WAY SEATTLE WA 98109	RCRA LQG

EPA Handler ID: WAD085811768
Gen Status Universe: Large Quantity Generator
Contact Name: JEANNE REA
Contact Address: 8211 45TH AVE NE , , SEATTLE , WA, 98115 , US
Contact Phone No and Ext: 206-696-4118
Contact Email: JEANNEMAUI@GMAIL.COM
Contact Country: US
County Name: KING

EPA Region:	10
Land Type:	Private
Receive Date:	20220215
Location Latitude:	47.6187
Location Longitude:	-122.34754

Violation/Evaluation Summary

Note:	NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Jun, 2022.

Evaluation Details

Evaluation Start Date:	20070105
Evaluation Type Description:	COMPLIANCE ASSISTANCE VISIT
Violation Short Description:	
Return to Compliance Date:	
Evaluation Agency:	State

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19931231
Handler Name:	FAULKENBURY WRIGHT
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator
Source Type:	Notification

Waste Code Details

Hazardous Waste Code:	F001
Waste Code Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Hazardous Waste Code:	F002
Waste Code Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 19971026
Handler Name: FAULKENBURY WRIGHT
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 13
Receive Date: 20070206
Handler Name: FAULKENBURY WRIGHT
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20220215
Handler Name: FAULKENBURY AND WRIGHT DRYCLEANERS
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 10
Receive Date: 20020114
Handler Name: FAULKENBURY WRIGHT
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 15
Receive Date: 20180302
Handler Name: FAULKENBURY AND WRIGHT DRYCLEANERS
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 16
Receive Date: 20190507

Handler Name: FAULKENBURY AND WRIGHT DRYCLEANERS
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070206
Handler Name: FAULKENBURY WRIGHT
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 19
Receive Date: 20220215
Handler Name: FAULKENBURY AND WRIGHT DRYCLEANERS
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 6
Receive Date: 19980309
Handler Name: FAULKENBURY WRIGHT
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 14
Receive Date: 20160816
Handler Name: FAULKENBURY AND WRIGHT DRYCLEANERS
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 18
Receive Date: 20210408
Handler Name: FAULKENBURY AND WRIGHT DRYCLEANERS
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20031231
Handler Name: FAULKENBURY WRIGHT
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 19971027
Handler Name: FAULKENBURY WRIGHT
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19950101
Handler Name: FAULKENBURY WRIGHT
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 17
Receive Date: 20201109
Handler Name: FAULKENBURY AND WRIGHT DRYCLEANERS
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001%

and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 19971027
Handler Name: FAULKENBURY WRIGHT
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 7
Receive Date: 19990916
Handler Name: FAULKENBURY WRIGHT
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 8
Receive Date: 20000228
Handler Name: FAULKENBURY WRIGHT
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 9
Receive Date: 20010521
Handler Name: FAULKENBURY WRIGHT
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 12
Receive Date: 20040726
Handler Name: FAULKENBURY WRIGHT
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19971027
Handler Name: FAULKENBURY WRIGHT
Federal Waste Generator Code: N

Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 11
Receive Date: 20030805
Handler Name: FAULKENBURY WRIGHT
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D040
Waste Code Description: TRICHLORETHYLENE

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D039
Waste Code Description: TETRACHLOROETHYLENE

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: SEE PAPER COPY
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Implementer
Street No:
Street 1: 501 DENNY WAY
Street 2:
City: SEATTLE
State: WA
Country:
Zip Code: 98109-5010

Owner/Operator Ind: Current Owner
Type: Private
Name: FAULKENBURY WRIGHT
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 501 DENNY WAY
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98109

Owner/Operator Ind: Current Owner
Type: Private
Name: JEANNE REA
Date Became Current: 20171231
Date Ended Current:
Phone: 206-696-4118
Source Type: Notification
Street No:
Street 1: 8211 45TH AVE NE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98115

Owner/Operator Ind: Current Operator
Type: Private
Name: JONG CHA
Date Became Current: 20021231
Date Ended Current:
Phone:
Source Type: Annual/Biennial Report
Street No:
Street 1: 501 DENNY WAY
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98109

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	501 DENNY WAY
Name:	FAULKENBURY WRIGHT	**Street 2:**	
Date Became Current:	19900401	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	501 DENNY WAY
Name:	NONE-VACANT	**Street 2:**	
Date Became Current:	19750101	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-890-8123	**Country:**	US
Source Type:	Notification	**Zip Code:**	98115

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	501 DENNY WAY
Name:	NONE-VACANT	**Street 2:**	
Date Became Current:	19750101	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-890-8123	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	98115

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	501 DENNYWAY
Name:	FAULKENBURY WRIGHT	**Street 2:**	
Date Became Current:	20001120	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-1212	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	501 DENNYWAY
Name:	JONG C	**Street 2:**	
Date Became Current:	20021231	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-1212	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98109

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	501 DENNY WAY
Name:	FAULKENBURY WRIGHT	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	8211 45TH AVE NE
Name:	LARRY AND JEANNE REA	**Street 2:**	
Date Became Current:	19860328	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-890-8123	**Country:**	US
Source Type:	Notification	**Zip Code:**	98115

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	501 DENNY WAY
Name:	VARIOUS OPERATORS SINCE MID 1970'S	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-890-8123	**Country:**	US
Source Type:	Notification	**Zip Code:**	98115

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	501 DENNY WAY
Name:	JONG C	**Street 2:**	
Date Became Current:	20021231	**City:**	SEATTLE
Date Ended Current:		**State:**	WA

Phone:	206-728-1212	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98109
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2600 5TH AVE
Name:	REA, LARRY	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-8529	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	8211 45TH AVE NE
Name:	LARRY AND JEANNE REA	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-696-4118	**Country:**	US
Source Type:	Notification	**Zip Code:**	98115
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	501 DENNY WAY
Name:	VARIOUS OPERATORS SINCE MID 1970'S	**Street 2:**	
Date Became Current:	19750101	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-890-8123	**Country:**	US
Source Type:	Notification	**Zip Code:**	98115
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	501 DENNYWAY
Name:	FAULKENBURY WRIGHT	**Street 2:**	
Date Became Current:	20021231	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	98109
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	8211 45TH AVE NE
Name:	JEANNE REA	**Street 2:**	
Date Became Current:	20171231	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-696-4118	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	98115
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	501 DENNYWAY
Name:	FAULKENBURY WRIGHT	**Street 2:**	
Date Became Current:	20021231	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-1212	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98109
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2600 5TH AVE
Name:	REA, LARRY	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-8529	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	501 DENNY WAY
Name:	SHIN, BONG J	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-1212	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98109
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	501 DENNY WAY

Name:	CHA, JONG H	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-1212	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98109
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	501 DENNY WAY
Name:	CHA, JONG H	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-1212	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	8211 45TH AVE NE
Name:	LARRY AND JEANNE REA	**Street 2:**	
Date Became Current:	20171231	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-696-4118	**Country:**	US
Source Type:	Notification	**Zip Code:**	98115
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	8211 45TH AVE NE
Name:	LARRY AND JEANNE REA	**Street 2:**	
Date Became Current:	19860328	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-890-8123	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	98115
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	501 DENNY WAY
Name:	SHIN, BONG J	**Street 2:**	
Date Became Current:	19960601	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-1212	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	501 DENNYWAY
Name:	FAULKENBURY WRIGHT	**Street 2:**	
Date Became Current:	20021231	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-1212	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2600 5TH AVE
Name:	REA, LANNY	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-8529	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121

Historical Handler Details

Receive Dt:	19971027
Generator Code Description:	Very Small Quantity Generator
Handler Name:	FAULKENBURY WRIGHT
Receive Dt:	20000228
Generator Code Description:	Very Small Quantity Generator
Handler Name:	FAULKENBURY WRIGHT
Receive Dt:	20010521
Generator Code Description:	Very Small Quantity Generator
Handler Name:	FAULKENBURY WRIGHT

Receive Dt: 20190507
Generator Code Description: Large Quantity Generator
Handler Name: FAULKENBURY AND WRIGHT DRYCLEANERS

Receive Dt: 20030805
Generator Code Description: Very Small Quantity Generator
Handler Name: FAULKENBURY WRIGHT

Receive Dt: 20160816
Generator Code Description: Not a Generator, Verified
Handler Name: FAULKENBURY AND WRIGHT DRYCLEANERS

Receive Dt: 20210408
Generator Code Description: Large Quantity Generator
Handler Name: FAULKENBURY AND WRIGHT DRYCLEANERS

Receive Dt: 19971027
Generator Code Description: Not a Generator, Verified
Handler Name: FAULKENBURY WRIGHT

Receive Dt: 20220215
Generator Code Description: Large Quantity Generator
Handler Name: FAULKENBURY AND WRIGHT DRYCLEANERS

Receive Dt: 20070206
Generator Code Description: Not a Generator, Verified
Handler Name: FAULKENBURY WRIGHT

Receive Dt: 20040726
Generator Code Description: Very Small Quantity Generator
Handler Name: FAULKENBURY WRIGHT

Receive Dt: 20201109
Generator Code Description: Large Quantity Generator
Handler Name: FAULKENBURY AND WRIGHT DRYCLEANERS

Receive Dt: 19971027
Generator Code Description: Not a Generator, Verified
Handler Name: FAULKENBURY WRIGHT

Receive Dt: 20020114
Generator Code Description: Very Small Quantity Generator
Handler Name: FAULKENBURY WRIGHT

Receive Dt: 20070206
Generator Code Description: Not a Generator, Verified
Handler Name: FAULKENBURY WRIGHT

Receive Dt: 19971026
Generator Code Description: Not a Generator, Verified
Handler Name: FAULKENBURY WRIGHT

Receive Dt: 19980309
Generator Code Description: Very Small Quantity Generator
Handler Name: FAULKENBURY WRIGHT

Receive Dt: 20180302
Generator Code Description: Not a Generator, Verified
Handler Name: FAULKENBURY AND WRIGHT DRYCLEANERS

Receive Dt: 19931231
Generator Code Description: Very Small Quantity Generator
Handler Name: FAULKENBURY WRIGHT

Receive Dt: 20031231
Generator Code Description: Not a Generator, Verified
Handler Name: FAULKENBURY WRIGHT

Receive Dt: 19950101

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Generator Code Description: Not a Generator, Verified
Handler Name: FAULKENBURY WRIGHT

Receive Dt: 19990916
Generator Code Description: Very Small Quantity Generator
Handler Name: FAULKENBURY WRIGHT

84	1 of 7	E	0.21 / 1,118.74	121.24 / 15	HAWAIIAN MARINE LINES INC 2401 4TH AVE SEATTLE WA 98121	RCRA NON GEN

EPA Handler ID: WAD991281916
Gen Status Universe: No Report
Contact Name: HAWAIIAN MARINE HAWAIIAN MARINE
Contact Address: 4636 E MARGINAL WAY S , #215 , SEATTLE , WA, 98134 , US
Contact Phone No and Ext: 000-000-0000
Contact Email:
Contact Country: US
County Name: KING
EPA Region: 10
Land Type: Private
Receive Date: 19801125
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19801125
Handler Name: HAWAIIAN MARINE LINES INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19801125
Handler Name: HAWAIIAN MARINE LINES INC
Source Type: Notification

Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19801125
Handler Name: HAWAIIAN MARINE LINES INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: HAWAIIAN MARINE LINES INC
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 2401 4TH AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Owner
Type: Private
Name: HAWAIIAN MARINE LINES INC
Date Became Current: 19960503
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 2401 4TH AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Owner
Type: Private
Name: HAWAIIAN MARINE H
Date Became Current: 19960503
Date Ended Current:
Phone: 000-000-0000
Source Type: Implementer
Street No:
Street 1: 2401 4TH AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121-1438

Owner/Operator Ind: Current Owner
Type: Private
Name: SEE PAPER COPY
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Implementer
Street No:
Street 1: 2401 4TH AVE
Street 2:
City: SEATTLE
State: WA
Country:
Zip Code: 98121

Owner/Operator Ind: Current Operator
Type: Private
Name: HAWAIIAN MARINE LINES INC
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Implementer
Street No:
Street 1: 2401 4TH AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121-1438

Owner/Operator Ind: Current Operator
Type: Private
Name: HAWAIIAN MARINE LINES INC
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 2401 4TH AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Historical Handler Details

Receive Dt: 19801125

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Generator Code Description:	Not a Generator, Verified					
Handler Name:	HAWAIIAN MARINE LINES INC					

84	2 of 7	E	0.21 / 1,118.74	121.24 / 15	LIFESPAN BIOSCIENCES 2401 4TH AVE 12TH FLOOR SEATTLE WA 98121	RCRA VSQG

EPA Handler ID: WAH000017913
Gen Status Universe: VSG
Contact Name: KYLE GONSALVES
Contact Address: 2401 4TH AVE 9TH FLOOR , , SEATTLE , WA, 98121 , US
Contact Phone No and Ext: 206-374-1155
Contact Email: KYLEG@LSBIO.COM
Contact Country: US
County Name: KING
EPA Region: 10
Land Type: Private
Receive Date: 20220314
Location Latitude: 47.616472
Location Longitude: -122.345194

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 10
Receive Date: 20100226
Handler Name: LIFESPAN BIOSCIENCES
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 12
Receive Date: 20120228
Handler Name: LIFESPAN BIOSCIENCES
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 18
Receive Date: 20180227
Handler Name: LIFESPAN BIOSCIENCES
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20050210
Handler Name: LIFESPAN BIOSCIENCES 4TH & BATTERY
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 6
Receive Date: 20060120
Handler Name: LIFESPAN BIOSCIENCES
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 13
Receive Date: 20130227
Handler Name: LIFESPAN BIOSCIENCES
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 19
Receive Date: 20190226
Handler Name: LIFESPAN BIOSCIENCES
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: WSC2
Waste Code Description: Washington State solid or semisolid corrosive Dangerous Waste with a pH less than or equal to 2, or greater than or equal to 12.5, based upon a specific testing method.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: U404
Waste Code Description: ETHANAMINE, N,N-DIETHYL- (OR) TRIETHYLAMINE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D001

Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Handler Details

Sequence No: 8
Receive Date: 20080228
Handler Name: LIFESPAN BIOSCIENCES
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 15
Receive Date: 20150203
Handler Name: LIFESPAN BIOSCIENCES
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20040304
Handler Name: LIFESPAN BIOSCIENCES 4TH & BATTERY
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20100226
Handler Name: LIFESPAN BIOSCIENCES
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: WSQG
Waste Code Description: A placeholder to allow Handler and BR submissions to validate. In WA State federal and state waste codes were not collected on the Site Identification form until 2013 so they were not available for reporting.

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20030218
Handler Name: LIFESPAN BIOSCIENCES 4TH & BATTERY
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 22
Receive Date: 20220314
Handler Name: LIFESPAN BIOSCIENCES
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: WSC2
Waste Code Description: Washington State solid or semisolid corrosive Dangerous Waste with a pH less than or equal to 2, or greater than or equal to 12.5, based upon a specific testing method.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: U404
Waste Code Description: ETHANAMINE, N,N-DIETHYL- (OR) TRIETHYLAMINE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Handler Details

Sequence No: 20
Receive Date: 20200220
Handler Name: LIFESPAN BIOSCIENCES
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: WSC2
Waste Code Description: Washington State solid or semisolid corrosive Dangerous Waste with a pH less than or equal to 2, or greater than or equal to 12.5, based upon a specific testing method.

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: U404
Waste Code Description: ETHANAMINE, N,N-DIETHYL- (OR) TRIETHYLAMINE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20071231
Handler Name: LIFESPAN BIOSCIENCES
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 7
Receive Date: 20070227
Handler Name: LIFESPAN BIOSCIENCES
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 9
Receive Date: 20090226
Handler Name: LIFESPAN BIOSCIENCES
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 21
Receive Date: 20210222
Handler Name: LIFESPAN BIOSCIENCES
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20120228
Handler Name: LIFESPAN BIOSCIENCES
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: WSQG
Waste Code Description: A placeholder to allow Handler and BR submissions to validate. In WA State federal and state waste codes were not collected on the Site Identification form until 2013 so they were not available for reporting.

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20110224
Handler Name: LIFESPAN BIOSCIENCES
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20020109
Handler Name: LIFESPAN BIOSCIENCES 4TH & BATTERY
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 16
Receive Date: 20160212
Handler Name: LIFESPAN BIOSCIENCES
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 17
Receive Date: 20170221
Handler Name: LIFESPAN BIOSCIENCES
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20031231
Handler Name: LIFESPAN BIOSCIENCES 4TH & BATTERY
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 20050210
Handler Name: LIFESPAN BIOSCIENCES 4TH & BATTERY
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 20050303
Handler Name: LIFESPAN BIOSCIENCES 4TH & BATTERY
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 11
Receive Date: 20110224
Handler Name: LIFESPAN BIOSCIENCES
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 14
Receive Date: 20140220
Handler Name: LIFESPAN BIOSCIENCES
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20051231
Handler Name: LIFESPAN BIOSCIENCES
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Annual/Biennial Report

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: LIFESPAN BIOSCIENCES 4TH & BATTERY
Date Became Current: 20020109
Date Ended Current:
Phone: 206-464-1554
Source Type: Annual/Biennial Report update with Notification
Street No:
Street 1: 2401 4TH AVE
Street 2: 9TH FLR
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Operator
Type: Private
Name: LIFESPAN BIOSCI L
Date Became Current: 19000101
Date Ended Current:
Phone: 206-464-1554
Source Type: Implementer
Street No:
Street 1: 2401 4TH AVE
Street 2: 9TH FLR
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Operator
Type: Private
Name: LIFESPAN BIOSCIENCES 4TH BATTERY
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 2401 4TH AVE 12TH FLOOR
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Owner
Type: Private
Name: MARTIN SELIG REAL ESTATE
Date Became Current: 20171231
Date Ended Current:
Phone: 206-467-7600
Source Type: Notification
Street No:
Street 1: 1000 2ND AVE STE 1800
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98104

Owner/Operator Ind: Current Owner
Type: Private
Name: MARTIN SELIG REAL ESTATE
Date Became Current:
Date Ended Current:
Phone: 206-467-7600
Source Type: Implementer
Street No:
Street 1: 1000 2ND AVE STE 1800
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98104-1046

Owner/Operator Ind: Current Owner
Type: Private
Name: MARTIN SELIG REAL ESTATE
Date Became Current:
Date Ended Current:
Phone: 206-467-7600
Source Type: Notification
Street No:
Street 1: 1000 2ND AVE STE 1800
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98104

Owner/Operator Ind: Current Owner
Type: Private
Name: LIFESPAN BIOSCIENCES 4TH & BATTERY
Date Became Current: 20020109
Street No:
Street 1: 2401 4TH AVE
Street 2: 9TH FLR
City: SEATTLE

Date Ended Current:		**State:**	WA
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2401 4TH AVE
Name:	LIFESPAN BIOSCIENCES 4TH & BATTERY	**Street 2:**	9TH FLR
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-464-1554	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2401 4TH AVE
Name:	LIFESPAN BIOSCI L	**Street 2:**	9TH FLR
Date Became Current:	20020109	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-464-1554	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2401 4TH AVE
Name:	LIFESPAN BIOSCIENCES 4TH BATTERY	**Street 2:**	9TH FLR
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-464-1554	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2401 4TH AVE
Name:	LIFESPAN BIOSCIENCES 4TH BATTERY	**Street 2:**	9TH FLR
Date Became Current:	20020109	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-464-1554	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2401 4TH AVE
Name:	LIFESPAN BIOSCIENCES 4TH & BATTERY	**Street 2:**	9TH FLR
Date Became Current:	19000101	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-464-1554	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2401 4TH AVE
Name:	LIFESPAN BIOSCIENCES 4TH & BATTERY	**Street 2:**	9TH FLR
Date Became Current:	19000101	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	98121

Historical Handler Details

Receive Dt:	20110224
Generator Code Description:	Very Small Quantity Generator
Handler Name:	LIFESPAN BIOSCIENCES
Receive Dt:	20071231
Generator Code Description:	Not a Generator, Verified
Handler Name:	LIFESPAN BIOSCIENCES
Receive Dt:	20060120
Generator Code Description:	Very Small Quantity Generator
Handler Name:	LIFESPAN BIOSCIENCES
Receive Dt:	20090226
Generator Code Description:	Very Small Quantity Generator

Handler Name: LIFESPAN BIOSCIENCES

Receive Dt: 20150203
Generator Code Description: Very Small Quantity Generator
Handler Name: LIFESPAN BIOSCIENCES

Receive Dt: 20180227
Generator Code Description: Very Small Quantity Generator
Handler Name: LIFESPAN BIOSCIENCES

Receive Dt: 20050210
Generator Code Description: Very Small Quantity Generator
Handler Name: LIFESPAN BIOSCIENCES 4TH & BATTERY

Receive Dt: 20050210
Generator Code Description: Not a Generator, Verified
Handler Name: LIFESPAN BIOSCIENCES 4TH & BATTERY

Receive Dt: 20040304
Generator Code Description: Small Quantity Generator
Handler Name: LIFESPAN BIOSCIENCES 4TH & BATTERY

Receive Dt: 20100226
Generator Code Description: Very Small Quantity Generator
Handler Name: LIFESPAN BIOSCIENCES

Receive Dt: 20130227
Generator Code Description: Very Small Quantity Generator
Handler Name: LIFESPAN BIOSCIENCES

Receive Dt: 20140220
Generator Code Description: Very Small Quantity Generator
Handler Name: LIFESPAN BIOSCIENCES

Receive Dt: 20190226
Generator Code Description: Very Small Quantity Generator
Handler Name: LIFESPAN BIOSCIENCES

Receive Dt: 20080228
Generator Code Description: Very Small Quantity Generator
Handler Name: LIFESPAN BIOSCIENCES

Receive Dt: 20100226
Generator Code Description: Very Small Quantity Generator
Handler Name: LIFESPAN BIOSCIENCES

Receive Dt: 20020109
Generator Code Description: Small Quantity Generator
Handler Name: LIFESPAN BIOSCIENCES 4TH & BATTERY

Receive Dt: 20070227
Generator Code Description: Very Small Quantity Generator
Handler Name: LIFESPAN BIOSCIENCES

Receive Dt: 20120228
Generator Code Description: Very Small Quantity Generator
Handler Name: LIFESPAN BIOSCIENCES

Receive Dt: 20030218
Generator Code Description: Small Quantity Generator
Handler Name: LIFESPAN BIOSCIENCES 4TH & BATTERY

Receive Dt: 20051231
Generator Code Description: Not a Generator, Verified
Handler Name: LIFESPAN BIOSCIENCES

Receive Dt: 20170221
Generator Code Description: Very Small Quantity Generator
Handler Name: LIFESPAN BIOSCIENCES

Receive Dt: 20031231
Generator Code Description: Small Quantity Generator
Handler Name: LIFESPAN BIOSCIENCES 4TH & BATTERY

Receive Dt: 20210222
Generator Code Description: Very Small Quantity Generator
Handler Name: LIFESPAN BIOSCIENCES

Receive Dt: 20050303
Generator Code Description: Very Small Quantity Generator
Handler Name: LIFESPAN BIOSCIENCES 4TH & BATTERY

Receive Dt: 20160212
Generator Code Description: Very Small Quantity Generator
Handler Name: LIFESPAN BIOSCIENCES

Receive Dt: 20200220
Generator Code Description: Very Small Quantity Generator
Handler Name: LIFESPAN BIOSCIENCES

Receive Dt: 20120228
Generator Code Description: Very Small Quantity Generator
Handler Name: LIFESPAN BIOSCIENCES

Receive Dt: 20110224
Generator Code Description: Very Small Quantity Generator
Handler Name: LIFESPAN BIOSCIENCES

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
84	3 of 7	E	0.21 / 1,118.74	121.24 / 15	Lifespan Biosciences 2401 4TH AVE 12TH FLOOR SEATTLE WA 98121	ALL SITES

Facility/Site ID: 47373868
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000017913
Facility Alternate: Lifespan Biosciences
Interaction ID: 46995
Interaction Status: A
Interac Status Desc: Active
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 09-Jan-2002
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAH000017913
Facility Alternate:
Interaction ID: 46996
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWP
Interaction Desc: Hazardous Waste Planner
Interact Start Dt: 01-Jan-2004
Interact End Dt: 08-Nov-2005
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: HWPPRT
Database Name Desc: Hazardous Reporting

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	N
Horizont 1:	NAD83	***GIS latitude:***	47.6162942574
Horizont 2:	Address	***GIS longitude:***	-122.346430424

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
84	4 of 7	E	0.21 / 1,118.74	121.24 / 15	Hawaiian Marine Lines Inc 2401 4TH AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID:	14668484
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAD991281916
Facility Alternate:	
Interaction ID:	28308
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	25-Nov-1980
Interact End Dt:	31-Dec-1993
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	N
Horizont 1:	NAD83	***GIS latitude:***	47.61635
Horizont 2:	Unknown	***GIS longitude:***	-122.34534

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
84	5 of 7	E	0.21 / 1,118.74	121.24 / 15	PACIFIC ALASKA LINES WEST 2401 4 AVE SEATTLE WA 98121	PCB

Site ID:	WAD044592384	***Mail Address 1:***	PO BOX 2287
Receive Date:		***Mail Address 2:***	
Generator:	No	***Mail Street No:***	
Storer:	No	***Mail City:***	SEATTLE
Transporter:	Yes	***Mail State:***	WA
Disposer:	No	***Mail Zip:***	98111
Research:	No	***Mail Country:***	US
Smelter:	No	***Contact Name:***	GEORGE A BROOKS
Cert Title:		***Contact Title:***	
Cert Date:	7/24/1990 12:00:00 AM	***Contact Phone:***	206-443-7882
Cert Name:		***Contact Phone Ext:***	
Location Country:	US	***Contact Email:***	
State Name:	WASHINGTON	***Owner Name:***	CROWLWY MARITIME CORP
Region:	10		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
84	6 of 7	E	0.21 / 1,118.74	121.24 / 15	HAWAIIAN MARINE LINES 2401 4TH AVE SEATTLE WA 98121	PCB

Site ID:	WAD991281916	***Mail Address 1:***	PO BOX 2287
Receive Date:		***Mail Address 2:***	
Generator:	No	***Mail Street No:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Storer:	No	**Mail City:**	SEATTLE
Transporter:	Yes	**Mail State:**	WA
Disposer:	No	**Mail Zip:**	98111
Research:	No	**Mail Country:**	US
Smelter:	No	**Contact Name:**	GEORGE A BROOKS
Cert Title:		**Contact Title:**	
Cert Date:	5/30/1990 12:00:00 AM	**Contact Phone:**	206-443-7882
Cert Name:		**Contact Phone Ext:**	
Location Country:	US	**Contact Email:**	
State Name:	WASHINGTON	**Owner Name:**	CROWLEY MARITIME CORP
Region:	10		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
84	7 of 7	E	0.21 / 1,118.74	121.24 / 15	CROWLEY MARINE SERVICES 2401 4TH AVE SEATTLE WA 98121	PCB

Site ID:	WAD008958027	**Mail Address 1:**	PO BOX 2287
Receive Date:		**Mail Address 2:**	
Generator:	No	**Mail Street No:**	
Storer:	No	**Mail City:**	SEATTLE
Transporter:	Yes	**Mail State:**	WA
Disposer:	No	**Mail Zip:**	98111
Research:	No	**Mail Country:**	US
Smelter:	No	**Contact Name:**	STEPHEN WILSON
Cert Title:		**Contact Title:**	
Cert Date:	8/30/1994 12:00:00 AM	**Contact Phone:**	206-443-8100
Cert Name:		**Contact Phone Ext:**	
Location Country:	US	**Contact Email:**	
State Name:	WASHINGTON	**Owner Name:**	MARTIN SELIG
Region:	10		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
85	1 of 2	W	0.21 / 1,121.65	23.15 / -83	UNOCAL MARKETING TERMINAL NO TM0724 3001 ELLIOTT AVE SEATTLE WA 98121	RCRA NON GEN

EPA Handler ID:	WAD988497624
Gen Status Universe:	No Report
Contact Name:	GARY GUNDERSON
Contact Address:	PO BOX 399 , , EDMONDS , WA, 98020 , US
Contact Phone No and Ext:	360-640-7612
Contact Email:	
Contact Country:	US
County Name:	KING
EPA Region:	10
Land Type:	Other
Receive Date:	19970312
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No

Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19960229
Handler Name: UNOCAL MARKETING TERMINAL NO TM0724
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19970311
Handler Name: UNOCAL MARKETING TERMINAL NO TM0724
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19970311
Handler Name: UNOCAL MARKETING TERMINAL NO TM0724
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 19970312
Handler Name: UNOCAL MARKETING TERMINAL NO TM0724
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19931231
Handler Name: UNOCAL MARKETING TERMINAL NO TM0724
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 19970221
Handler Name: UNOCAL MARKETING TERMINAL NO TM0724
Source Type: Notification
Federal Waste Generator Code: 3

Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 19970311
Handler Name: UNOCAL MARKETING TERMINAL NO TM0724
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: UNOCAL
Date Became Current: 19960827
Date Ended Current:
Phone: 360-640-7608
Source Type: Notification
Street No:
Street 1: PO BOX 399
Street 2:
City: EDMONDS
State: WA
Country: US
Zip Code: 98020

Owner/Operator Ind: Current Owner
Type: Private
Name: UNOCAL
Date Became Current:
Date Ended Current:
Phone: 360-640-7608
Source Type: Implementer
Street No:
Street 1: PO BOX 399
Street 2:
City: EDMONDS
State: WA
Country: US
Zip Code: 98020

Owner/Operator Ind: Current Operator
Type: Private
Name: UNOCAL CORP
Date Became Current:
Date Ended Current:
Phone: 360-640-7612
Source Type: Notification
Street No:
Street 1: PO BOX 399
Street 2:
City: EDMONDS
State: WA
Country: US
Zip Code: 98020

Owner/Operator Ind: Current Owner
Type: Private
Name: UNOCAL MARKETING TERMINAL NO TM0724
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 3001 ELLIOTT AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Operator
Type: Private
Name: UNOCAL CORP U
Date Became Current: 19960827
Date Ended Current:
Phone: 360-640-7612
Source Type: Implementer
Street No:
Street 1: PO BOX 399
Street 2:
City: EDMONDS
State: WA
Country: US
Zip Code: 98020

Owner/Operator Ind: Current Operator
Type: Private
Name: UNOCAL CORP
Date Became Current:
Date Ended Current:
Phone: 360-640-7612
Source Type: Implementer
Street No:
Street 1: PO BOX 399
Street 2:
City: EDMONDS
State: WA
Country: US
Zip Code: 98020

Owner/Operator Ind: Current Owner
Type: Private
Name: UNOCAL
Date Became Current: 19960827
Date Ended Current:
Street No:
Street 1: PO BOX 399
Street 2:
City: EDMONDS
State: WA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Phone:	360-640-7608	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98020
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	3001 ELLIOTT AVE
Name:	UNOCAL MARKETING TERMINAL NO TM0724	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 399
Name:	UNOCAL	**Street 2:**	
Date Became Current:		**City:**	EDMONDS
Date Ended Current:		**State:**	WA
Phone:	360-640-7608	**Country:**	US
Source Type:	Notification	**Zip Code:**	98020
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 399
Name:	UNOCAL	**Street 2:**	
Date Became Current:		**City:**	EDMONDS
Date Ended Current:		**State:**	WA
Phone:	360-640-7608	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98020
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 399
Name:	UNOCAL U	**Street 2:**	
Date Became Current:	19960827	**City:**	EDMONDS
Date Ended Current:		**State:**	WA
Phone:	360-640-7608	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98020

Historical Handler Details

Receive Dt:	19970221
Generator Code Description:	Very Small Quantity Generator
Handler Name:	UNOCAL MARKETING TERMINAL NO TM0724
Receive Dt:	19931231
Generator Code Description:	Small Quantity Generator
Handler Name:	UNOCAL MARKETING TERMINAL NO TM0724
Receive Dt:	19960229
Generator Code Description:	Very Small Quantity Generator
Handler Name:	UNOCAL MARKETING TERMINAL NO TM0724
Receive Dt:	19970311
Generator Code Description:	Not a Generator, Verified
Handler Name:	UNOCAL MARKETING TERMINAL NO TM0724
Receive Dt:	19970311
Generator Code Description:	Very Small Quantity Generator
Handler Name:	UNOCAL MARKETING TERMINAL NO TM0724
Receive Dt:	19970311
Generator Code Description:	Not a Generator, Verified
Handler Name:	UNOCAL MARKETING TERMINAL NO TM0724

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
85	2 of 2	W	0.21 / 1,121.65	23.15 / -83	Unocal Marketing Terminal No TM0724 3001 ELLIOTT AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID: 34978766
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: Unocal Seattle Marketing Terminal
Interaction ID: 129220
Interaction Status: A
Interac Status Desc: Active
Interaction Type: UIC
Interaction Desc: Underground Injection Control
Interact Start Dt: 22-Dec-2005
Interact End Dt:
Ecology Program: WATQUAL
Program Name Desc: Water Quality Program
Prog Database Name: UIC
Database Name Desc: Underground Injection Control Program

Program ID: WAD988497624
Facility Alternate:
Interaction ID: 39673
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 03-Dec-1991
Interact End Dt: 31-Dec-1996
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.61668
GIS longitude: -122.35674

---

86 | ***1 of 4*** | ***WNW*** | ***0.22 / 1,143.70*** | ***85.24 / -21*** | ***Champion-Teutsch Property 124 DENNY WAY SEATTLE WA 98109*** | ***ICR***

Cleanup Site ID: 12831
Facility Site ID: 3860
Site Status: Cleanup Started
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site: Yes
WRIA ID: 8
Is NFA Site:
Responsible Unit: Northwest
Latitude: 47.618740000000003
Longitude: -122.35448
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID:
VCP Prj No: NW3002
Activity Name: VCP Application
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2015-09-14
End Date:
Legal Mechanism:
Performed by:
Project Manager: Escobedo, Diane

Related ID:
Start Date: 2015-09-18

VCP Prj No:	NW3002	***End Date:***	
Activity Name:	VCP Opinion on Property Cleanup Plan	***Legal Mechanism:***	
Activity Status:	In Process	***Performed by:***	
County Name:	King	***Project Manager:***	Cardona-Marek, Tamara
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	2015-07-22
VCP Prj No:	NW3002	***End Date:***	
Activity Name:	VCP Receipt of Plan or Report	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Northwest Region
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Media Contaminants

Contaminant Type:	Petroleum-Gasoline	***Sediment:***	
Groundwater:	C	***Sediment Desc.:***	
Groundwater Desc.:	Confirmed Above Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

Contaminant Type:	Other Non-Halogenated Organics	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

Contaminant Type:	Petroleum-Diesel	***Sediment:***	
Groundwater:	C	***Sediment Desc.:***	
Groundwater Desc.:	Confirmed Above Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:		***Bedrock Desc.:***	
Soil Desc.:		***County Name:***	King

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
86	2 of 4	WNW	0.22 / 1,143.70	85.24 / -21	Champion Teutsch Property 124 DENNY WAY SEATTLE WA 98109	ALL SITES

Facility/Site ID:	3860
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	NW3042
Facility Alternate:	Champion-Teutsch (Property NFA)
Interaction ID:	118588
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	VOLCLNST
Interaction Desc:	Voluntary Cleanup Sites
Interact Start Dt:	13-Jun-2016
Interact End Dt:	27-Feb-2017
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Program ID:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility Alternate: Champion Teutsch (Off-Property)
Interaction ID: 127338
Interaction Status: A
Interac Status Desc: Active
Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 27-Feb-2017
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: NW3002
Facility Alternate: Champion-Teutsch Property
Interaction ID: 114715
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 14-Sep-2015
Interact End Dt: 18-May-2016
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: Unknown
Horizont 1: WGS84
Horizont 2: Address
Location Verified:
GIS latitude: 47.61874
GIS longitude: -122.35448

---

86 | ***3 of 4*** | ***WNW*** | ***0.22 / 1,143.70*** | ***85.24 / -21*** | ***Champion-Teutsch 124 DENNY WAY SEATTLE WA 98109*** | ***CSCSL***

Fac Site ID: 3860
Cleanup Site ID: 12831
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.61874
Longitude: -122.35448
Responsible Unit: Northwest
Fac Site ID (OD): 3860
Cleanup SiteID(OD): 12831
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.35448
Latitude (OD): 47.61874
Site Name: Champion-Teutsch
Address: 124 DENNY WAY
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Champion-Teutsch Property
Address (OD): 124 DENNY WAY
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.61874, -122.35448)
Alternate Site Names: Champion Teutsch (Off-Property),Champion Teutsch Property,Champion-Teutsch (Property NFA),Champion-Teutsch Property
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum-Diesel

Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Other Non-Halogenated Organics
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Other Non-Halogenated Organics
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

86	*4 of 4*	*WNW*	*0.22 / 1,143.70*	*85.24 / -21*	***Champion-Teutsch*** ***124 DENNY WAY*** ***SEATTLE WA 98109***	***VCP***

Facility Site ID: 3860
Cleanup Site ID: 12831
Region: Northwest
County: King
Latitude: 47.61874
Longitude: -122.35448
Alternate Site Names: Champion Teutsch (Off-Property),Champion Teutsch Property,Champion-Teutsch (Property NFA),Champion-Teutsch Property
Data Source(s): Confirmed and Suspected Contaminated Sites; Confirmed and Suspected Contaminated Sites; All Cleanup Sites in Washington State

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List

Site Status: Cleanup Started
Current VCP:
Past VCP: Yes
Site Rank:
Responsible Unit: Northwest
Has Inst Control:

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List - Contaminants

Contaminant Name: Other Non-Halogenated Organics ***Sediment:***

Groundwater: ***Air:***
Surfacewater: ***Bedrock:***
Soil: Remediated-Below

Contaminant Name: Petroleum-Gasoline ***Sediment:***
Groundwater: Confirmed Above Cleanup Levels ***Air:***
Surfacewater: ***Bedrock:***
Soil: Remediated-Below

Contaminant Name: Petroleum-Diesel ***Sediment:***
Groundwater: Confirmed Above Cleanup Levels ***Air:***
Surfacewater: ***Bedrock:***
Soil:

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: Cleanup Started
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Petroleum-Gasoline ***Sediment:***
Groundwater: Remediated-Below ***Air:***
Surfacewater: ***Bedrock:***
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Other Non-Halogenated Organics ***Sediment:***
Groundwater: ***Air:***
Surfacewater: ***Bedrock:***
Soil: Remediated-Below

Contaminant Name: Petroleum-Diesel ***Sediment:***
Groundwater: Confirmed Above Cleanup Levels ***Air:***
Surfacewater: ***Bedrock:***
Soil:

---

87 ***1 of 3*** ***ESE*** ***0.22 / 1,151.76*** ***121.31 / 16*** ***303 Battery***
303 Battery St
Seattle WA 98121 ***UST***

UST ID: 620513 ***Region:*** Northwest
Facility Site ID: 71963 ***County:*** King
Site Active: No ***Latitude:*** 47.61554
Responsible Unit: Northwest ***Longitude:*** -122.34569
Active Tag:
Alternate Site Names:

Tank Detail(s)

Tank Name: 1 ***Tank Construction:***
Status Date: 01/24/2020 ***Tank Capacity:***
Install Date: ***Actual Capacity:*** 300
Upgrade Date: ***Pipe Install Date:***
Perm Closure Date: 11/21/2022 ***Endorsement Expire:***
Tank Status: Removed
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Compartments

Compartment No: 1
Compart Capacity: 300
Stored Substance: Unknown
Used Substance: Unknown

87	2 of 3	ESE	0.22 / 1,151.76	121.31 / 16	303 Battery 303 BATTERY ST SEATTLE WA 98121	ALL SITES

Facility/Site ID: 71963
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: 303 Battery
Interaction ID: 138236
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: INDPNDNT
Interaction Desc: Independent Cleanup
Interact Start Dt: 09-Mar-2021
Interact End Dt: 12-Nov-2021
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: 620513
Facility Alternate: 303 Battery
Interaction ID: 138237
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 09-Mar-2021
Interact End Dt: 12-Nov-2021
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Facility Location Detail

Horizontal: Unknown
Horizont 1: WGS84
Horizont 2: Address
Location Verified:
GIS latitude: 47.61554
GIS longitude: -122.34569

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
87	3 of 3	ESE	0.22 / 1,151.76	121.31 / 16	303 Battery 303 BATTERY ST SEATTLE WA 98121	CSCSL NFA

Fac Site ID:	71963	**Fac Site ID (OD):**	
Cleanup Site ID:	15384	**Cleanup SiteID(OD):**	
Site Status:	NFA	**Site Status (OD):**	
NFA Date:	11/12/2021	**Rank (OD):**	
Responsible Unit:	Pollution Liability Ins Agcy	**Has Env Coven (OD):**	
Has Insti Control:		**Respon Unit (OD):**	
Region:	Northwest	**Region (OD):**	
County:	King	**County (OD):**	
Latitude:	47.61554	**Latitude (OD):**	
Longitude:	-122.34569	**Longitude (OD):**	

NFA Reason: Petroleum Technical Assistance Program (PTAP) by PLIA
Alternate Site Names:
Location (OD):
Data Source(s): Department of Ecology - Washington

NFA Contaminants Detail(s)

Contaminant Name: Arsenic
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Metals - Other
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Mercury
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Lead
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

---

88 | ***1 of 2*** | ***WNW*** | ***0.22 / 1,162.18*** | ***82.85 / -23*** | ***Denny & Warren Petrol Plume***
101 DENNY WAY
SEATTLE WA 98109 | ***ALL SITES***

Facility/Site ID: 83661
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: Denny & Warren Petrol Plume
Interaction ID: 128246
Interaction Status: A
Interac Status Desc: Active
Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 14-Jul-2015
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6184976999
GIS longitude: -122.354712281

---

88 | ***2 of 2*** | ***WNW*** | ***0.22 / 1,162.18*** | ***82.85 / -23*** | ***Denny & Warren Petrol Plume***
101 DENNY WAY
SEATTLE WA 98109 | ***CSCSL***

Fac Site ID: 83661
Cleanup Site ID: 14751
Site Status: Awaiting Cleanup
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6184976999487
Longitude: -122.35471228089
Site Name: Denny & Warren Petrol Plume
Address: 101 DENNY WAY
City: SEATTLE
Responsible Unit: Northwest
Fac Site ID (OD): 83661
Cleanup SiteID(OD): 14751
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.354712
Latitude (OD): 47.618498

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Zip Code: 98109
Site Status (OD): Awaiting Cleanup
Site Name (OD): Denny & Warren Petrol Plume
Address (OD): 101 DENNY WAY
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.618498, -122.354712)
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Halogenated Solvents
Groundwater:
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

89	1 of 1	E	0.22 / 1,169.61	123.05 / 17	2434 4TH AVE Seattle WA 98119	UST SEATTLE

Permit No: 3-43775
Date Issued: 08/12/2002
Fill Material: No Fill
Date Decommissioned: 08/12/2002
Type Decommissioned: Abandonment in Place
Tank Size: 300
Tank Age: 20+
Tank Content: HEATING OIL

90	1 of 9	NW	0.22 / 1,184.23	138.89 / 33	PACIFIC SCIENCE CENTER 200 2ND AVE N SEATTLE WA 98109	RCRA NON GEN

EPA Handler ID: WAH000019513
Gen Status Universe: No Report
Contact Name: ERIC BORUD
Contact Address: 200 2ND AVE N , , SEATTLE , WA, 98109 , US
Contact Phone No and Ext: 206-269-2130
Contact Email: ERIC_BORUD@PACSCI.ORG

Contact Country: US
County Name: KING
EPA Region: 10
Land Type: Private
Receive Date: 20090804
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Jun, 2022.

Evaluation Details

Evaluation Start Date: 20061109
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 20090722
Evaluation Type Description: COMPLIANCE ASSISTANCE VISIT
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 20031218
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 8
Receive Date: 20080723
Handler Name: PACIFIC SCIENCE CENTER
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1

Receive Date: 20031231
Handler Name: PACIFIC SCIENCE CENTER
Source Type: Annual/Biennial Report
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20071231
Handler Name: PACIFIC SCIENCE CENTER
Source Type: Annual/Biennial Report
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20090803
Handler Name: PACIFIC SCIENCE CENTER
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 10
Receive Date: 20090804
Handler Name: PACIFIC SCIENCE CENTER
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20030210
Handler Name: PACIFIC SCIENCE CENTER
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 20070420
Handler Name: PACIFIC SCIENCE CENTER
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 20050222
Handler Name: PACIFIC SCIENCE CENTER
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20030210
Handler Name: PACIFIC SCIENCE CENTER
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20040203
Handler Name: PACIFIC SCIENCE CENTER
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 6
Receive Date: 20070420
Handler Name: PACIFIC SCIENCE CENTER
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 7
Receive Date: 20080528
Handler Name: PACIFIC SCIENCE CENTER
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 9
Receive Date: 20090803
Handler Name: PACIFIC SCIENCE CENTER

Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20021104
Handler Name: PACIFIC SCIENCE CENTER
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: ERIC BORUD
Date Became Current: 20050929
Date Ended Current:
Phone:
Source Type: Annual/Biennial Report
Street No:
Street 1: 200 2ND AVE N
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98109

Owner/Operator Ind: Current Operator
Type: Private
Name: BORUD, ERIC
Date Became Current: 20050929
Date Ended Current:
Phone: 206-269-2130
Source Type: Notification
Street No:
Street 1: 200 2ND AVE N
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98109

Owner/Operator Ind: Current Owner
Type: Private
Name: PACIFIC SCIENCE CENTER FOUNDATION
Date Became Current: 20081231
Date Ended Current:
Phone: 206-443-2001
Source Type: Implementer
Street No:
Street 1: 200 2ND AVE N
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98109

Owner/Operator Ind: Current Owner
Type: Private
Name: PACIFIC SCIENCE CENTER FOUNDATION
Date Became Current: 20021104
Date Ended Current:
Phone: 206-443-2001
Source Type: Notification
Street No:
Street 1: 200 2ND AVE N
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98109

Owner/Operator Ind: Current Owner
Type: Private
Name: PACIFIC SCIENCE CENTER FOUNDATION
Date Became Current:
Date Ended Current:
Phone: 206-443-2001
Source Type: Implementer
Street No:
Street 1: 200 2ND AVE N
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98109

Owner/Operator Ind: Current Owner
Type: Private
Name: PACIFIC SCIENCE P
Date Became Current: 20021104
Date Ended Current:
Phone: 206-443-2001
Source Type: Implementer
Street No:
Street 1: 200 2ND AVE N
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98109

Owner/Operator Ind: Current Owner
Type: Private
Name: PACIFIC SCIENCE CENTER FOUNDATION
Date Became Current: 20061231
Street No:
Street 1: 200 2ND AVE N
Street 2:
City: SEATTLE

Date Ended Current:		**State:**	WA
Phone:	206-443-2001	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	200 2ND AVE N
Name:	PACIFIC SCIENCE CENTER FOUNDATION	**Street 2:**	
Date Became Current:	20021104	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	98109

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	200 2ND AVE N
Name:	GOSLING, SUSAN	**Street 2:**	
Date Became Current:	20021104	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-269-2130	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	200 2ND AVE N
Name:	PACIFIC SCIENCE CENTER FOUNDATION	**Street 2:**	
Date Became Current:	20021104	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-443-2001	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98109

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	200 2ND AVE N
Name:	SUSAN GOSLING	**Street 2:**	
Date Became Current:	20021104	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	98109

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	200 2ND AVE N
Name:	PACIFIC SCIENCE CENTER FOUNDATION	**Street 2:**	
Date Became Current:	20041231	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-443-2001	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	200 2ND AVE N
Name:	PACIFIC SCIENCE CENTER FOUNDATION	**Street 2:**	
Date Became Current:	20051231	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-443-2001	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	200 2ND AVE N
Name:	BORUD, ERIC	**Street 2:**	
Date Became Current:	20050929	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-269-2130	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98109

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	200 2ND AVE N
Name:	PACIFIC SCIENCE CENTER FOUNDATION	**Street 2:**	
Date Became Current:	20071231	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-443-2001	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109

Owner/Operator Ind:	Current Operator	**Street No:**	

Type:	Private	***Street 1:***	200 2ND AVE N
Name:	PACIFIC SCIENCE CENTER FOUNDATION	***Street 2:***	
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-443-2001	***Country:***	US
Source Type:	Notification	***Zip Code:***	98109

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	200 2ND AVE N
Name:	PACIFIC SCIENCE CENTER FOUNDATION	***Street 2:***	
Date Became Current:	20080528	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-443-2001	***Country:***	US
Source Type:	Notification	***Zip Code:***	98109

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	200 2ND AVE N
Name:	PACIFIC SCIENCE CENTER FOUNDATION	***Street 2:***	
Date Became Current:	20081231	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-443-2001	***Country:***	US
Source Type:	Notification	***Zip Code:***	98109

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	200 2ND AVE N
Name:	ERIC B	***Street 2:***	
Date Became Current:	20050929	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-269-2130	***Country:***	US
Source Type:	Implementer	***Zip Code:***	98109

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	200 2ND AVE N
Name:	PACIFIC SCIENCE CENTER FOUNDATION	***Street 2:***	
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-443-2001	***Country:***	US
Source Type:	Notification	***Zip Code:***	98109

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	200 2ND AVE N
Name:	PACIFIC SCIENCE CENTER FOUNDATION	***Street 2:***	
Date Became Current:	20031231	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-443-2001	***Country:***	US
Source Type:	Notification	***Zip Code:***	98109

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	200 2ND AVE N
Name:	PACIFIC SCIENCE CENTER FOUNDATION	***Street 2:***	
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-443-2001	***Country:***	US
Source Type:	Implementer	***Zip Code:***	98109

Historical Handler Details

Receive Dt:	20050222
Generator Code Description:	Very Small Quantity Generator
Handler Name:	PACIFIC SCIENCE CENTER

Receive Dt:	20070420
Generator Code Description:	Very Small Quantity Generator
Handler Name:	PACIFIC SCIENCE CENTER

Receive Dt:	20040203
Generator Code Description:	Very Small Quantity Generator
Handler Name:	PACIFIC SCIENCE CENTER

Receive Dt: 20030210
Generator Code Description: Small Quantity Generator
Handler Name: PACIFIC SCIENCE CENTER

Receive Dt: 20080528
Generator Code Description: Very Small Quantity Generator
Handler Name: PACIFIC SCIENCE CENTER

Receive Dt: 20090803
Generator Code Description: Not a Generator, Verified
Handler Name: PACIFIC SCIENCE CENTER

Receive Dt: 20021104
Generator Code Description: Not a Generator, Verified
Handler Name: PACIFIC SCIENCE CENTER

Receive Dt: 20070420
Generator Code Description: Very Small Quantity Generator
Handler Name: PACIFIC SCIENCE CENTER

Receive Dt: 20090803
Generator Code Description: Very Small Quantity Generator
Handler Name: PACIFIC SCIENCE CENTER

Receive Dt: 20030210
Generator Code Description: Not a Generator, Verified
Handler Name: PACIFIC SCIENCE CENTER

Receive Dt: 20071231
Generator Code Description: Not a Generator, Verified
Handler Name: PACIFIC SCIENCE CENTER

Receive Dt: 20080723
Generator Code Description: Very Small Quantity Generator
Handler Name: PACIFIC SCIENCE CENTER

Receive Dt: 20031231
Generator Code Description: Not a Generator, Verified
Handler Name: PACIFIC SCIENCE CENTER

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
90	2 of 9	NW	0.22 / 1,184.23	138.89 / 33	Pacific Science Center 200 2ND AVE N Seattle WA 98109	UST

UST ID: 619795
Facility Site ID: 2868852
Site Active: No
Responsible Unit: Northwest
Active Tag:
Region: Northwest
County: King
Latitude: 47.6190159184278
Longitude: -122.35159070847
Alternate Site Names: Pacific Science Center UST Denny & Broad

Tank Detail(s)

Tank Name: 1
Status Date: 04/06/2011
Install Date:
Upgrade Date:
Perm Closure Date: 04/06/2011
Tank Status: Removed
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Tank Construction:
Tank Capacity: 111 TO 1,100 Gallons
Actual Capacity: 1000
Pipe Install Date:
Endorsement Expire:

Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Compartments

Compartment No: 1
Compart Capacity: 1000
Stored Substance: Leaded Gasoline
Used Substance: Motor Fuel for Vehicles

---

90 | ***3 of 9*** | ***NW*** | ***0.22 / 1,184.23*** | ***138.89 / 33*** | ***Pacific Science Center 200 2ND AVE N SEATTLE WA 98109*** | ***ALL SITES***

Facility/Site ID: 2868852
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000019513
Facility Alternate: PACIFIC SCIENCE CENTER
Interaction ID: 11499
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 04-Nov-2002
Interact End Dt: 31-Dec-2008
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: 619795
Facility Alternate: Pacific Science Center
Interaction ID: 96916
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 25-May-2011
Interact End Dt: 25-May-2011
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: 619795
Facility Alternate: Pacific Science Center
Interaction ID: 110611
Interaction Status: A
Interac Status Desc: Active
Interaction Type: LUST
Interaction Desc: LUST Facility
Interact Start Dt: 29-Sep-2014
Interact End Dt:
Ecology Program: TOXICS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6190159184
GIS longitude: -122.351590708

---

90 | **4 of 9** | **NW** | **0.22 / 1,184.23** | **138.89 / 33** | **Pacific Science Center UST Denny & Broad**
200 2ND AVE N
SEATTLE WA 98109 | **LUST**

Facility Site ID: 2868852
Cleanup Site ID: 12496
Responsible Unit: Northwest
Region: Northwest
Alternate Site Names: Pacific Science Center
County: King
Latitude: 47.6190159184278
Longitude: -122.35159070847

Tank Detail(s)

UST ID: 619795
LUST ID: 6866
LUST Status: LUST - Cleanup Started
Status Date: 04/18/2011
Release Date: 05/27/2011

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

---

90 | **5 of 9** | **NW** | **0.22 / 1,184.23** | **138.89 / 33** | **Pacific Science Center UST Denny & Broad**
200 2ND AVE N
SEATTLE WA 98109 | **CSCSL**

Fac Site ID: 2868852
Cleanup Site ID: 12496
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6190159184278
Longitude: -122.35159070847
Responsible Unit: Northwest
Fac Site ID (OD): 2868852
Cleanup SiteID(OD): 12496
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.351591
Latitude (OD): 47.619016
Site Name: Pacific Science Center UST Denny & Broad
Address: 200 2ND AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Pacific Science Center UST Denny & Broad
Address (OD): 200 2ND AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.619016, -122.351591)
Alternate Site Names: Pacific Science Center
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

90 | ***6 of 9*** | ***NW*** | ***0.22 / 1,184.23*** | ***138.89 / 33*** | ***Pacific Science Center UST Denny & Broad 200 2ND AVE N SEATTLE WA 98109*** | ***ICR***

Cleanup Site ID: 12496
Facility Site ID: 2868852
Site Status: Cleanup Started
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site: Yes

WRIA ID: 8
Is NFA Site:
Responsible Unit: Northwest
Latitude: 47.619015918427841
Longitude: -122.35159070847044
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID:
VCP Prj No:
Activity Name: Initial Investigation / Federal Preliminary Assessment
Activity Status: Completed
County Name: King
Applies to: CleanupSite
Applies to Description:

Start Date: 2014-08-29
End Date: 2014-08-29
Legal Mechanism:
Performed by: Ecology
Project Manager: Garbush, Gayle

Related ID: 6866
VCP Prj No:
Activity Name: LUST - Notification
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Start Date: 2011-05-27
End Date: 2011-05-27
Legal Mechanism:
Performed by:
Project Manager: Northwest Region

Related ID:
VCP Prj No:
Activity Name: Early Notice Letter(s)
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:

Start Date:
End Date: 2015-02-27
Legal Mechanism:
Performed by:
Project Manager: Musa, Donna

Related ID:
VCP Prj No:
Activity Name: Site Discovery/Release Report Received
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:

Start Date:
End Date: 2011-05-27
Legal Mechanism:
Performed by:
Project Manager: Northwest Region

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Related ID:	6866	**Start Date:**	2011-04-27
VCP Prj No:		**End Date:**	2011-05-27
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Media Contaminants

Contaminant Type:	Petroleum-Gasoline	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RA	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Above Cleanup Level	**County Name:**	King

90	7 of 9	NW	0.22 / 1,184.23	138.89 / 33	**DC CORRIDOR PAC SCI L2** **200 2nd Ave N** **Seattle WA 98109**	ALT FUELS

Fuel Type Code:	ELEC: Electric	**ID:**	104286
Station Phone:	888-758-4389	**Updated at:**	2022-08-01 01:12:02 UTC
Expected Date:		**CNG Dispenser No:**	
BD Blends:		**CNG Site Renew Src:**	
NG Fill Type Code:		**CNG Tot Compr Cap:**	
NG PSI:		**CNG Storage Cap:**	
Federal Agency ID:		**CNG Fill Type Code:**	
Open Date:	2018-10-20	**CNG PSI:**	
NG Vehicle Class:		**CNG Vehicle Class:**	
LPG Primary:		**LNG Site Renew Src:**	
E85 Blender Pump:		**LNG Vehicle Class:**	
NG Fill Type Desc:		**LPG Nozzle Types:**	
Hydrogen is Retail:		**Hydrogen Pressures:**	
Federal Agency:		**Hydrogen Standards:**	
Facility Type:		**Latitude:**	47.619056
Dt Last Confirmed:	2022-08-01	**Longitude:**	-122.352371
Restricted Access:	false		
Fed Agency Name:			
Hydrogen Status Link:			
Status:	Open: The station is open.		
Owner Type Desc:			
E85 Blender Pump Desc:			
NG Vehicle Class Desc:			
Geocode Status Desc:	The location is from a real GPS readout at the station.		
LPG Primary Desc:			
E85 Other Ethanol Blends:			
EV Pricing:			
EV Pricing French:			
EV on Site Renewable Source:			
Intersection Directions:			

90	8 of 9	NW	0.22 / 1,184.23	138.89 / 33	**DC CORRIDOR PAC SCI CENTER** **200 2nd Ave N** **Seattle WA 98109**	ALT FUELS

Fuel Type Code:	ELEC: Electric	**ID:**	173491
Station Phone:	888-758-4389	**Updated at:**	2022-08-01 00:50:03 UTC
Expected Date:		**CNG Dispenser No:**	
BD Blends:		**CNG Site Renew Src:**	
NG Fill Type Code:		**CNG Tot Compr Cap:**	
NG PSI:		**CNG Storage Cap:**	
Federal Agency ID:		**CNG Fill Type Code:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Open Date:	2021-01-27	**CNG PSI:**	
NG Vehicle Class:		**CNG Vehicle Class:**	
LPG Primary:		**LNG Site Renew Src:**	
E85 Blender Pump:		**LNG Vehicle Class:**	
NG Fill Type Desc:		**LPG Nozzle Types:**	
Hydrogen is Retail:		**Hydrogen Pressures:**	
Federal Agency:		**Hydrogen Standards:**	
Facility Type:		**Latitude:**	47.619058
Dt Last Confirmed:	2022-08-01	**Longitude:**	-122.352428
Restricted Access:	false		
Fed Agency Name:			
Hydrogen Status Link:			
Status:	Open: The station is open.		
Owner Type Desc:			
E85 Blender Pump Desc:			
NG Vehicle Class Desc:			
Geocode Status Desc:	The location is from a real GPS readout at the station.		
LPG Primary Desc:			
E85 Other Ethanol Blends:			
EV Pricing:			
EV Pricing French:			
EV on Site Renewable Source:			
Intersection Directions:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
90	9 of 9	NW	0.22 / 1,184.23	138.89 / 33	DC CORRIDOR PAC SCI DC2 200 2nd Ave N Seattle WA 98109	ALT FUELS

Fuel Type Code:	ELEC: Electric	**ID:**	173492
Station Phone:	888-758-4389	**Updated at:**	2022-08-01 00:50:02 UTC
Expected Date:		**CNG Dispenser No:**	
BD Blends:		**CNG Site Renew Src:**	
NG Fill Type Code:		**CNG Tot Compr Cap:**	
NG PSI:		**CNG Storage Cap:**	
Federal Agency ID:		**CNG Fill Type Code:**	
Open Date:	2021-01-27	**CNG PSI:**	
NG Vehicle Class:		**CNG Vehicle Class:**	
LPG Primary:		**LNG Site Renew Src:**	
E85 Blender Pump:		**LNG Vehicle Class:**	
NG Fill Type Desc:		**LPG Nozzle Types:**	
Hydrogen is Retail:		**Hydrogen Pressures:**	
Federal Agency:		**Hydrogen Standards:**	
Facility Type:		**Latitude:**	47.619059
Dt Last Confirmed:	2022-08-01	**Longitude:**	-122.352384
Restricted Access:	false		
Fed Agency Name:			
Hydrogen Status Link:			
Status:	Open: The station is open.		
Owner Type Desc:			
E85 Blender Pump Desc:			
NG Vehicle Class Desc:			
Geocode Status Desc:	The location is from a real GPS readout at the station.		
LPG Primary Desc:			
E85 Other Ethanol Blends:			
EV Pricing:			
EV Pricing French:			
EV on Site Renewable Source:			
Intersection Directions:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
91	1 of 1	ENE	0.23 / 1,188.92	124.25 / 19	2552 5TH AVE Seattle WA 98109	UST SEATTLE

Permit No:	3-46039	**Tank Size:**	300
Date Issued:	02/27/2003	**Tank Age:**	60

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Fill Material: No Fill
Tank Content: OIL
Date Decommissioned: 02/27/2003
Type Decommissioned: Abandonment in Place

92	1 of 2	ESE	0.23 / 1,200.38	121.38 / 16	303 Battery 2330 3RD AVE SEATTLE WA	DELISTED SHWS

Delisted Confirmed and Suspected Contaminated Sites

Fac Site ID: 71963
Cleanup Site ID: 15384
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
Responsible Unit: Pollution Liability Ins Agcy
County: King
Region: Northwest
Latitude: 47.6155412394319
Longitude: -122.345652449074
Site Status (OD):
Site Name (OD):
Address (OD):
Location (OD):
Alternate Site Names:
Fac Site ID (OD):
Clnup Site ID (OD):
Site Rank (OD):
Respon Unit (OD):
Has Env Coven (OD):
County (OD):
Region (OD):
City (OD):
Zipcode (OD):
Latitude (OD):
Longitude (OD):
Data Source(s): Confirmed and Suspected Contaminated Sites
Original Source: CSCS
Record Date: 30-NOV-2021

92	2 of 2	ESE	0.23 / 1,200.38	121.38 / 16	303 Battery 2330 3rd Avenue, Seattle, WA WA	LUST PTAP

FSID No: 71963
TAP: PNW265
Status: Complete
Entry Date: 3/8/2021
URL: https://plia.box.com/s/y9o78k6yw749iuhdytlgsuflmhp7gu9h

93	1 of 7	ESE	0.23 / 1,201.53	119.49 / 14	HOLMAN BODY & FENDER 2324 2ND AVE SEATTLE WA 98121	RCRA NON GEN

EPA Handler ID: WAD062788161
Gen Status Universe: No Report
Contact Name: HOLMANS BODY & HOLMANS BODY &
Contact Address: 7301 ROOSEVELT WAY NE , , SEATTLE , WA, 98155-5655 , US
Contact Phone No and Ext: 000-000-0000
Contact Email:
Contact Country: US
County Name: KING
EPA Region: 10
Land Type: Private
Receive Date: 19970611
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	4
Receive Date:	19960228
Handler Name:	HOLMAN BODY & FENDER
Source Type:	Notification
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No:	7
Receive Date:	19970611
Handler Name:	HOLMAN BODY & FENDER
Source Type:	Notification
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19960501
Handler Name:	HOLMAN BODY & FENDER
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	19970611
Handler Name:	HOLMAN BODY & FENDER
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19931231
Handler Name:	HOLMAN BODY & FENDER

Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 19950101
Handler Name: HOLMAN BODY & FENDER
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19940101
Handler Name: HOLMAN BODY & FENDER
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 19960501
Handler Name: HOLMAN BODY & FENDER
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 6
Receive Date: 19960502
Handler Name: HOLMAN BODY & FENDER
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: HOLMAN BODY FENDER
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Implementer
Street No:
Street 1: 2324 2ND AVE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Owner
Type: Private
Name: HOLMAN, DONALD E
Date Became Current: 19970611
Date Ended Current:
Phone: 206-522-6056
Source Type: Notification
Street No:
Street 1: 7301 ROOSEVELT WAY NE
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98115

Owner/Operator Ind: Current Operator
Type: Private
Name: HOLMAN BODY FENDER
Date Became Current:
Date Ended Current:
Street No:
Street 1: 2324 2ND AVE
Street 2:
City: SEATTLE
State: WA

Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2324 2ND AVE
Name:	HOLMAN BODY FENDER	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	925 WESTLAKE AVE N
Name:	DONALD H	**Street 2:**	
Date Became Current:	19970226	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-441-7871	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98109-3524
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2324 2ND AVE
Name:	SEE PAPER COPY	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2324 2ND AVE
Name:	SEE PAPER COPY	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	7301 ROOSEVELT WAY NE
Name:	DONALD H	**Street 2:**	
Date Became Current:	19970611	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-522-6056	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98115-5655
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	925 WESTLAKE AVE N
Name:	HOLMAN, DONALD E	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-441-7871	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2324 2ND AVE
Name:	HOLMAN BODY FENDER	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	8809 FAUNTLEROY WAY SW
Name:	SUYAMA, GEORGE	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98136

Historical Handler Details

Receive Dt: 19960502
Generator Code Description: Not a Generator, Verified
Handler Name: HOLMAN BODY & FENDER

Receive Dt: 19970611
Generator Code Description: Very Small Quantity Generator
Handler Name: HOLMAN BODY & FENDER

Receive Dt: 19950101
Generator Code Description: Not a Generator, Verified
Handler Name: HOLMAN BODY & FENDER

Receive Dt: 19960501
Generator Code Description: Not a Generator, Verified
Handler Name: HOLMAN BODY & FENDER

Receive Dt: 19960228
Generator Code Description: Very Small Quantity Generator
Handler Name: HOLMAN BODY & FENDER

Receive Dt: 19960501
Generator Code Description: Very Small Quantity Generator
Handler Name: HOLMAN BODY & FENDER

Receive Dt: 19940101
Generator Code Description: Not a Generator, Verified
Handler Name: HOLMAN BODY & FENDER

Receive Dt: 19931231
Generator Code Description: Small Quantity Generator
Handler Name: HOLMAN BODY & FENDER

---

93 | ***2 of 7*** | ***ESE*** | ***0.23 / 1,201.53*** | ***119.49 / 14*** | ***Holman Body & Fender***
2324 2ND AVE
SEATTLE WA 98121 | ***CSCSL***

Fac Site ID: 33457373
Cleanup Site ID: 8758
Site Status: Cleanup Started
Site Rank: 1 - Highest Assessed Risk
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6147864578656
Longitude: -122.346329504939
Site Name: Holman Body & Fender
Address: 2324 2ND AVE
City: SEATTLE
Zip Code: 98121
Site Status (OD): Cleanup Started
Site Name (OD): HOLMAN BODY & FENDER
Address (OD): 2324 2ND AVE
City (OD): SEATTLE
Zipcode (OD): 98121
Location (OD): ""
(47.614786, -122.34633)
Alternate Site Names: HOLMAN BODY AND FENDER,Suyama Peterson Deguchi
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 33457373
Cleanup SiteID(OD): 8758
Site Rank (OD): 1 - Highest Assessed Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.34633
Latitude (OD): 47.614786

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater: Suspected
Surfacewater:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater: Suspected
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Suspected
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

93	*3 of 7*	*ESE*	*0.23 / 1,201.53*	*119.49 / 14*	***Holman Body & Fender*** ***2324 2ND AVE*** ***SEATTLE WA 98121***	***HSL***

Fac Site ID:	33457373	***Fac Site ID (OD):***	33457373
Cleanup Site ID:	8758	***Cleanup Site ID (OD):***	8758
Site Status:	Cleanup Started	***Site Status (OD):***	Cleanup Started
Site Rank:	1 - Highest Assessed Risk	***Site Rank (OD):***	1 - Highest Assessed Risk
Has Inst Control:		***Has Env Coven (OD):***	
Responsible Unit:	Northwest	***Respon Unit (OD):***	Northwest
County:	King	***County (OD):***	King
Region:	Northwest	***Region (OD):***	Northwest
Latitude:	47.6147864578656	***Site Name (OD):***	HOLMAN BODY & FENDER
Longitude:	-122.346329504939	***Address (OD):***	2324 2ND AVE
Latitude (OD):	47.614786	***City (OD):***	SEATTLE
Longitude (OD):	-122.34633	***ZIP code (OD):***	98121
Current VCP:		***Past VCP:***	
Location (OD):	"" (47.614786, -122.34633)		
Alternate Site Names:	HOLMAN BODY AND FENDER,Suyama Peterson Deguchi		

Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name:	Benzene	***Sediment:***	
Groundwater:	Suspected	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:		***Bedrock:***	
Air:			
Contaminant Name:	Petroleum-Other	***Sediment:***	
Groundwater:	Suspected	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:		***Bedrock:***	
Air:			
Contaminant Name:	Petroleum-Gasoline	***Sediment:***	
Groundwater:	Suspected	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:		***Bedrock:***	
Air:			

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Benzene	***Contaminant Media:***	Groundwater
Contaminant Status:	Suspected		
Contaminant:	Petroleum-Other	***Contaminant Media:***	Groundwater
Contaminant Status:	Suspected		
Contaminant:	Petroleum-Gasoline	***Contaminant Media:***	Groundwater
Contaminant Status:	Suspected		
Contaminant:	Petroleum-Other	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Gasoline	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Benzene	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
93	4 of 7	ESE	0.23 / 1,201.53	119.49 / 14	HOLMAN BODY AND FENDER 2324 2ND AVE Seattle WA 98121	UST

UST ID:	323980	***Region:***	Northwest
Facility Site ID:	33457373	***County:***	King
Site Active:	No	***Latitude:***	47.6147864578656
Responsible Unit:	Northwest	***Longitude:***	-122.346329504939
Active Tag:			
Alternate Site Names:	Holman Body & Fender,Suyama Peterson Deguchi		

Tank Detail(s)

Tank Name:	1	***Tank Construction:***	
Status Date:	08/06/1996	***Tank Capacity:***	
Install Date:	01/01/1964	***Actual Capacity:***	500
Upgrade Date:		***Pipe Install Date:***	
Perm Closure Date:		***Endorsement Expire:***	
Tank Status:	Removed		
Tank Material:			
Tank Corrosion Protection:			
Tank Manifold:			
Tank Release Detection:			
Tank Tightness Test:			
Tank Spill Prevention:			
Tank Overfill Prevention:			

Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Compartments

Compartment No: 1
Compart Capacity: 500
Stored Substance: Leaded Gasoline
Used Substance: Motor Fuel for Vehicles

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
93	5 of 7	ESE	0.23 / 1,201.53	119.49 / 14	Holman Body & Fender 2324 2ND AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID: 33457373
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAD062788161
Facility Alternate:
Interaction ID: 38579
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWP
Interaction Desc: Hazardous Waste Planner
Interact Start Dt: 01-Jan-1993
Interact End Dt: 31-Dec-1993
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: HWPPRT
Database Name Desc: Hazardous Reporting

Program ID: 323980
Facility Alternate:
Interaction ID: 38581
Interaction Status: A
Interac Status Desc: Active
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 20-Nov-1995
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: WAD062788161
Facility Alternate:
Interaction ID: 38578
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 03-Mar-1986
Interact End Dt: 26-Apr-1996
Ecology Program: HAZWASTE

Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: 323980
Facility Alternate:
Interaction ID: 38580
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: LUST
Interaction Desc: LUST Facility
Interact Start Dt: 15-Sep-1995
Interact End Dt: 28-Dec-1995
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID:
Facility Alternate: Holman Body & Fender
Interaction ID: 103722
Interaction Status: A
Interac Status Desc: Active
Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 01-Jul-2011
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6147864579
GIS longitude: -122.346329505

---

93 | ***6 of 7*** | ***ESE*** | ***0.23 / 1,201.53*** | ***119.49 / 14*** | ***Holman Body & Fender***
2324 2ND AVE
SEATTLE WA 98121 | ***LUST***

Facility Site ID: 33457373
Cleanup Site ID: 8758
Responsible Unit: Northwest
Region: Northwest
Alternate Site Names: HOLMAN BODY AND FENDER,Suyama Peterson Deguchi
County: King
Latitude: 47.6147864578656
Longitude: -122.346329504939

Tank Detail(s)

UST ID: 323980
LUST ID: 3995
LUST Status: LUST - Cleanup Started
Status Date: 07/01/2011
Release Date: 09/15/1995

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater: Suspected
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name:	Petroleum-Other	**Sediment:**	
Groundwater:	Suspected	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Confirmed Above Cleanup Levels		

Contaminants Detail(s)

Contaminant Name:	Benzene	**Sediment:**	
Groundwater:	Suspected	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Confirmed Above Cleanup Levels		

---

93 | ***7 of 7*** | ***ESE*** | ***0.23 / 1,201.53*** | ***119.49 / 14*** | ***HOLMAN BODY & FENDER***
2324 2ND AVE
SEATTLE WA 98121 | ***ICR***

Cleanup Site ID:	8758	**WRIA ID:**	8
Facility Site ID:	33457373	**Is NFA Site:**	
Site Status:	Cleanup Started	**Responsible Unit:**	Northwest
Statute:	MTCA	**Latitude:**	47.614786457865605
Rank:	1	**Longitude:**	-122.34632950493932
Rank Description:	Highest assessed risk	**Legislative District:**	36
Has Env Covenant:		**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	1995-09-15
Activity Name:	Site Discovery/Release Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:	3995	**Start Date:**	1995-09-15
VCP Prj No:		**End Date:**	1995-09-15
Activity Name:	LUST - Notification	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2013-08-08
Activity Name:	Hazardous Sites Listing/NPL	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Musa, Donna
Applies to:	CleanupSite		
Applies to Description:			

Related ID:	3995	**Start Date:**	1995-12-28
VCP Prj No:		**End Date:**	1996-01-04
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		**Start Date:**	2013-02-15
VCP Prj No:		**End Date:**	2013-06-28
Activity Name:	Site Hazard Assessment/Federal Site Inspection	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	Ecology w/ Contractor
County Name:	King	**Project Manager:**	Musa, Donna

Applies to:	CleanupSite		
Applies to Description:			
Related ID:		**Start Date:**	2011-07-13
VCP Prj No:		**End Date:**	2011-10-03
Activity Name:	Initial Investigation / Federal Preliminary Assessment	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	Ecology w/ Contractor
County Name:	King	**Project Manager:**	Musa, Donna
Applies to:	CleanupSite		
Applies to Description:			

Media Contaminants

Contaminant Type:	Petroleum-Other	**Sediment:**	
Groundwater:	S	**Sediment Desc.:**	
Groundwater Desc.:	Suspected	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King
Contaminant Type:	Benzene	**Sediment:**	
Groundwater:	S	**Sediment Desc.:**	
Groundwater Desc.:	Suspected	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King
Contaminant Type:	Petroleum-Gasoline	**Sediment:**	
Groundwater:	S	**Sediment Desc.:**	
Groundwater Desc.:	Suspected	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
94	1 of 4	E	0.23 / 1,216.71	123.83 / 18	**Fountain Court Apartments** **2400 4TH AVE** **SEATTLE WA 98121**	CSCSL NFA

Fac Site ID:	48768395	**Fac Site ID (OD):**	48768395
Cleanup Site ID:	1705	**Cleanup SiteID(OD):**	1705
Site Status:	NFA	**Site Status (OD):**	No Further Action
NFA Date:	04/02/2001	**Rank (OD):**	
Responsible Unit:	Northwest	**Has Env Coven (OD):**	
Has Insti Control:		**Respon Unit (OD):**	Northwest
Region:	Northwest	**Region (OD):**	Northwest
County:	King	**County (OD):**	King
Latitude:	47.61615	**Latitude (OD):**	47.61615
Longitude:	-122.346518	**Longitude (OD):**	-122.346518
NFA Reason:	Voluntary Cleanup Program Review		
Alternate Site Names:			
Location (OD):	"" (47.61615, -122.346518)		
Data Source(s):	Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants		

NFA Contaminants Detail(s)

Contaminant Name:	Petroleum Products-Unspecified
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

94 | ***2 of 4*** | ***E*** | ***0.23 / 1,216.71*** | ***123.83 / 18*** | ***FOUNTAIN COURT APARTMENTS***
2400 4TH AVE
SEATTLE WA 98121 | ***ALL SITES***

Facility/Site ID: 48768395
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: FOUNTAIN COURT APARTMENTS
Interaction ID: 47667
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 31-Jan-2001
Interact End Dt: 02-Apr-2001
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83
Horizont 2: Address
Location Verified: N
GIS latitude: 47.61615
GIS longitude: -122.346518

---

94 | ***3 of 4*** | ***E*** | ***0.23 / 1,216.71*** | ***123.83 / 18*** | ***FOUNTAIN COURT APARTMENTS***
2400 4TH AVE
SEATTLE WA 98121 | ***ICR***

Cleanup Site ID: 1705
Facility Site ID: 48768395
Site Status: No Further Action Required
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site: Yes
WRIA ID: 8
Is NFA Site: Yes
Responsible Unit: Northwest
Latitude: 47.616149999999998
Longitude: -122.346518
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID:
VCP Prj No: NW0599
Activity Name: VCP Application
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2001-01-31
End Date:
Legal Mechanism:
Performed by:
Project Manager:

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2001-04-02
Activity Name:	Site Status Changed to NFA	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	
VCP Prj No:	NW0599	**End Date:**	
Activity Name:	VCP Opinion on Cleanup Action	**Legal Mechanism:**	
Activity Status:	Canceled	**Performed by:**	
County Name:	King	**Project Manager:**	Sato, Brian
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	
VCP Prj No:	NW0599	**End Date:**	2001-04-02
Activity Name:	VCP Termination	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Media Contaminants

Contaminant Type:	Petroleum Products-Unspecified	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
94	4 of 4	E	0.23 / 1,216.71	123.83 / 18	Fountain Court Apartments 2400 4TH AVE SEATTLE WA 98121	VCP

Facility Site ID:	48768395	**County:**	King
Cleanup Site ID:	1705	**Latitude:**	47.61615
Region:	Northwest	**Longitude:**	-122.346518
Alternate Site Names:			
Data Source(s):	No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State		

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status:	NFA
NFA Date:	04/02/2001
Responsible Unit:	Northwest
Has Inst Control:	
NFA Reason:	Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name:	Petroleum Products-Unspecified	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Confirmed Above Cleanup Levels		

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status:	No Further Action
Site Rank:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
95	1 of 3	NE	0.23 / 1,217.55	128.84 / 23	Da Li 5th Avenue Development 124 - 130 5TH AVE N SEATTLE WA 98109	CSCSL

Fac Site ID: 70550
Cleanup Site ID: 16565
Site Status: Cleanup Started
Site Rank:
Current VCP: Yes
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6195909629257
Longitude: -122.347249509377
Site Name: Da Li 5th Avenue Development
Address: 124 - 130 5TH AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD):
Site Name (OD):
Address (OD):
City (OD):
Zipcode (OD):
Location (OD):
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites

Responsible Unit: Headquarters
Fac Site ID (OD):
Cleanup SiteID(OD):
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD):
County (OD):
Region (OD):
Longitude (OD):
Latitude (OD):

Contaminants Detail(s)

Contaminant Name: Arsenic
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Halogenated Solvents
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant Name: Lead
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Mercury
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Metals - Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

95	2 of 3	NE	0.23 / 1,217.55	128.84 / 23	Da Li 5th Avenue Development 124 - 130 5TH AVE N SEATTLE WA 98109	VCP

Facility Site ID: 70550
Cleanup Site ID: 16565
Region: Northwest
Alternate Site Names:
County: King
Latitude: 47.6195909629257
Longitude: -122.347249509377
Data Source(s): Confirmed and Suspected Contaminated Sites; Confirmed and Suspected Contaminated Sites; All Cleanup Sites in Washington State

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List

Site Status: Cleanup Started
Current VCP: Yes
Past VCP: Yes
Site Rank:
Responsible Unit: Headquarters
Has Inst Control:

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List - Contaminants

Contaminant Name: Lead
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Mercury
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Metals - Other
Groundwater:
Sediment:
Air:

Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Petroleum-Gasoline **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Arsenic **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Halogenated Solvents **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Polycyclic Aromatic Hydrocarbons **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: Cleanup Started
Site Rank:
Has Inst Control:
Current VCP: Yes
Past VCP: Yes
Responsible Unit: Headquarters

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Metals - Other **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Mercury **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Petroleum-Gasoline **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Halogenated Solvents **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Lead **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Arsenic **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Polycyclic Aromatic Hydrocarbons **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Soil: Confirmed Above Cleanup Levels

---

95 | **3 of 3** | **NE** | **0.23 / 1,217.55** | **128.84 / 23** | **Da Li 5th Avenue Development**
124 - 130 5TH AVE N
SEATTLE WA 98109 | **ALL SITES**

Facility/Site ID: 70550
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: XN0022
Facility Alternate: Da Li 5th Avenue Development
Interaction ID: 143763
Interaction Status: A
Interac Status Desc: Active
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 25-Mar-2022
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6195909629
GIS longitude: -122.347249509

---

96 | **1 of 2** | **WNW** | **0.23 / 1,228.08** | **71.08 / -35** | **WRIGHT GROUP**
65 BAY ST
Seattle WA 98121 | **UST**

UST ID: 9847
Facility Site ID: 23282483
Site Active: No
Responsible Unit: Northwest
Active Tag:
Alternate Site Names: CONSTRUCTION SITE
Region: Northwest
County: King
Latitude: 47.61807
Longitude: -122.357208

Tank Detail(s)

Tank Name: 1
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material: Steel
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material: Steel
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release
Tank Construction:
Tank Capacity: 111 TO 1,100 Gallons
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Unleaded Gasoline
Used Substance:

---

96 | ***2 of 2*** | ***WNW*** | ***0.23 / 1,228.08*** | ***71.08 / -35*** | ***CONSTRUCTION SITE 65 BAY ST SEATTLE WA 98121-1015*** | ***ALL SITES***

Facility/Site ID: 23282483
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate:
Interaction ID: 33068
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 25-Apr-1990
Interact End Dt: 03-May-2000
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID:
Facility Alternate:
Interaction ID: 33069
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 29-Feb-2000
Interact End Dt: 03-May-2000
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83
Horizont 2: Address
Location Verified: N
GIS latitude: 47.61807
GIS longitude: -122.357208

---

97 | ***1 of 1*** | ***WSW*** | ***0.23 / 1,240.49*** | ***8.65 / -97*** | ***AT&T WIRELESS PIER 70 2815 ALASKAN WAY SEATTLE WA 98121*** | ***ALL SITES***

Facility/Site ID: 426132
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility/Site Interaction

Program ID: CRK000056580
Facility Alternate: AT&T WIRELESS PIER 70
Interaction ID: 127844
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: TIER2
Interaction Desc: Emergency/Haz Chem Rpt TIER2
Interact Start Dt: 01-Jan-2002
Interact End Dt: 31-Dec-2002
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: EPCRA
Database Name Desc: Emergency Planning & Community Right-to-Know Act

Program ID: CRK000056580
Facility Alternate: ATT MOBILITY PIER 70 11506
Interaction ID: 127845
Interaction Status: A
Interac Status Desc: Active
Interaction Type: TIER2
Interaction Desc: Emergency/Haz Chem Rpt TIER2
Interact Start Dt: 01-Jan-2009
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: EPCRA
Database Name Desc: Emergency Planning & Community Right-to-Know Act

Facility Location Detail

Horizontal: Unknown
Horizont 1: Unknown
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.6145556699
GIS longitude: -122.355156567

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
98	1 of 2	ENE	0.24 / 1,250.63	124.82 / 19	GROSVENOR HOUSE 505 VINE ST Seattle WA 98121	UST

UST ID: 97226
Facility Site ID: 21511577
Site Active: No
Responsible Unit: Northwest
Active Tag:
Alternate Site Names: GROSVENOR HOUSE VINE ST
Region: Northwest
County: King
Latitude: 47.61792
Longitude: -122.347548

Tank Detail(s)

Tank Name: TANK #2
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank Construction:
Tank Capacity: 111 TO 1,100 Gallons
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Unleaded Gasoline
Used Substance:

Tank Detail(s)

Tank Name: WASTEOIL
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:
Tank Construction:
Tank Capacity: 111 TO 1,100 Gallons
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Used Oil/Waste Oil
Used Substance:

Tank Detail(s)

Tank Name: TANK #1
Status Date: 08/06/1996
Install Date: 12/31/1964
Upgrade Date:
Perm Closure Date:
Tank Status: Removed
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material:
Tank Construction:
Tank Capacity: 111 TO 1,100 Gallons
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Unleaded Gasoline
Used Substance:

98	*2 of 2*	*ENE*	*0.24 / 1,250.63*	*124.82 / 19*	*GROSVENOR HOUSE VINE ST* *505 VINE ST* *SEATTLE WA 98121-1508*	*ALL SITES*

Facility/Site ID: 21511577
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 97226
Facility Alternate:
Interaction ID: 31882
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 29-Feb-2000
Interact End Dt: 03-May-2000
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83
Horizont 2: Address
Location Verified: N
GIS latitude: 47.61792
GIS longitude: -122.347548

99	*1 of 1*	*SW*	*0.24 / 1,254.28*	*8.55 / -97*	*CLIPPER NAVIGATION ELLIOTT BAY* *WA*	*ALL SITES*

Facility/Site ID: 4510
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate:
Interaction ID: 110588
Interaction Status: A
Interac Status Desc: Active

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Interaction Type: ENFORFNL
Interaction Desc: Enforcement Final
Interact Start Dt: 26-Nov-2014
Interact End Dt:
Ecology Program: SPILLS
Program Name Desc: Spills Program
Prog Database Name: DMS
Database Name Desc: Docket Management System

Facility Location Detail

Horizontal: Unknown
Horizont 1: WGS84
Horizont 2: Unknown
Location Verified:
GIS latitude: 47.613793
GIS longitude: -122.353891

100	*1 of 2*	*E*	*0.24 / 1,255.55*	*124.13 / 18*	***ARCTIC MARINE FREIGHTERS 4TH & BATTERY SEATTLE WA 98111***	***RCRA NON GEN***

EPA Handler ID: WAD980738009
Gen Status Universe: No Report
Contact Name:
Contact Address:
Contact Phone No and Ext:
Contact Email:
Contact Country:
County Name: KING
EPA Region: 10
Land Type: Other
Receive Date: 19940625
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19940625
Handler Name: ARCTIC MARINE FREIGHTERS
Source Type: Implementer
Federal Waste Generator Code: N

Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19940624
Handler Name: ARCTIC MARINE FREIGHTERS
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19940624
Handler Name: ARCTIC MARINE FREIGHTERS
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: ARCTIC MARINE FREIGHTERS
Date Became Current: 19960502
Date Ended Current:
Phone: 000-000-0000
Source Type: Implementer
Street No:
Street 1: 4TH & BATTERY
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Operator
Type: Private
Name: ARCTIC MARINE FREIGHTERS
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 4TH & BATTERY
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98111

Owner/Operator Ind: Current Owner
Type: Private
Name: ARCTIC MARINE FREIGHTERS
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Implementer
Street No:
Street 1: 4TH & BATTERY
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98111

Owner/Operator Ind: Current Owner
Type: Private
Name: SEE PAPER COPY
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Implementer
Street No:
Street 1: 4TH & BATTERY
Street 2:
City: SEATTLE
State: WA
Country:
Zip Code: 98111

Owner/Operator Ind: Current Owner
Type: Private
Name: ARCTIC MARINE FREIGHTERS
Date Became Current: 19960502
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 4TH & BATTERY
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Owner
Type: Private
Name: ARCTIC MARINE FREIGHTERS
Street No:
Street 1: 4TH & BATTERY
Street 2:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98111
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	4TH & BATTERY
Name:	ARCTIC MARINE FREIGHTERS	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98111
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	4TH & BATTERY
Name:	ARCTIC MARINE FREIGHTERS	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121-0000

Historical Handler Details

Receive Dt:	19940624
Generator Code Description:	Not a Generator, Verified
Handler Name:	ARCTIC MARINE FREIGHTERS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
100	2 of 2	E	0.24 / 1,255.55	124.13 / 18	Arctic Marine Freighters 4TH & BATTERY SEATTLE WA 98111	ALL SITES

Facility/Site ID:	51786725
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAD980738009
Facility Alternate:	
Interaction ID:	48946
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	25-Aug-1982
Interact End Dt:	28-Oct-1991
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	N
Horizont 1:	NAD83	**GIS latitude:**	47.61631
Horizont 2:	Unknown	**GIS longitude:**	-122.34525

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
101	1 of 3	SW	0.24 / 1,268.67	9.95 / -96	PORT OF SEATTLE PIER 69 PIER 69 SEATTLE WA 98111	ALL SITES

Facility/Site ID:	14837
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAR044701
Facility Alternate:	PORT OF SEATTLE
Interaction ID:	87186
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	MS4P1GP
Interaction Desc:	Municipal SW Phase I GP
Interact Start Dt:	09-Mar-2007
Interact End Dt:	
Ecology Program:	WATQUAL
Program Name Desc:	Water Quality Program
Prog Database Name:	PARIS
Database Name Desc:	Permitting & Reporting Information System

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	
Horizont 1:	WGS84	***GIS latitude:***	47.6139
Horizont 2:	Unknown	***GIS longitude:***	-122.353

101	***2 of 3***	***SW***	***0.24 / 1,268.67***	***9.95 / -96***	***Seattle Port Pier 69 2711 ALASKAN WAY SEATTLE WA 98121***	***ALL SITES***

Facility/Site ID:	13283421
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAD988519229
Facility Alternate:	Seattle Port Pier 69
Interaction ID:	111307
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	HWOTHER
Interaction Desc:	Haz Waste Management Activity
Interact Start Dt:	31-Dec-2013
Interact End Dt:	
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Program ID:	WAD988519229
Facility Alternate:	
Interaction ID:	27409
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	25-Mar-1993
Interact End Dt:	31-Dec-2007
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Program ID:	WAD988519229
Facility Alternate:	Seattle Port Pier 69
Interaction ID:	94878
Interaction Status:	I

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	01-Dec-2010
Interact End Dt:	31-Dec-2013
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System
Program ID:	WAD988519229
Facility Alternate:	
Interaction ID:	27410
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWOTHER
Interaction Desc:	Haz Waste Management Activity
Interact Start Dt:	31-Dec-2007
Interact End Dt:	01-Dec-2010
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	N
Horizont 1:	NAD83	***GIS latitude:***	47.61383
Horizont 2:	Unknown	***GIS longitude:***	-122.35275

101	*3 of 3*	*SW*	*0.24 / 1,268.67*	*9.95 / -96*	***SEATTLE PORT PIER 69 2711 ALASKAN WAY SEATTLE WA 98121***	***RCRA NON GEN***

EPA Handler ID:	WAD988519229
Gen Status Universe:	No Report
Contact Name:	MIKE DESOTA
Contact Address:	2711 ALASKAN WAY , , SEATTLE , WA, 98121 , US
Contact Phone No and Ext:	206-787-3344
Contact Email:	DESOTA.M@PORTSEATTLE.ORG
Contact Country:	US
County Name:	KING
EPA Region:	10
Land Type:	Municipal
Receive Date:	20220301
Location Latitude:	47.61383
Location Longitude:	-122.35275

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No

Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	7
Receive Date:	20020307
Handler Name:	SEATTLE PORT PIER 69
Source Type:	Notification
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20120130
Handler Name:	SEATTLE PORT PIER 69
Source Type:	Annual/Biennial Report update with Notification
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code:	WSQG
Waste Code Description:	A placeholder to allow Handler and BR submissions to validate. In WA State federal and state waste codes were not collected on the Site Identification form until 2013 so they were not available for reporting.
Hazardous Waste Code:	D002
Waste Code Description:	CORROSIVE WASTE

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19960515
Handler Name:	SEATTLE PORT PIER 69
Source Type:	Notification
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	19970627
Handler Name:	SEATTLE PORT PIER 69
Source Type:	Notification
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	10
Receive Date:	20050221
Handler Name:	SEATTLE PORT PIER 69
Source Type:	Notification
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 15
Receive Date: 20100219
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 21
Receive Date: 20150227
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 24
Receive Date: 20180228
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20071231
Handler Name: SEATTLE PORT PIER 69
Source Type: Annual/Biennial Report
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 19980303
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2

Receive Date: 20110224
Handler Name: SEATTLE PORT PIER 69
Source Type: Implementer
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 11
Receive Date: 20060218
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Handler Details

Sequence No: 16
Receive Date: 20101201
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 18
Receive Date: 20120130
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Handler Details

Sequence No: 20
Receive Date: 20140227
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 25
Receive Date: 20190228
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20101201
Handler Name: SEATTLE PORT PIER 69
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 20000218
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 9
Receive Date: 20040227
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 8
Receive Date: 20030228
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 13
Receive Date: 20080213
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 23
Receive Date: 20170228
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 28
Receive Date: 20220301
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 19990303
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 6
Receive Date: 20010215
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 12
Receive Date: 20070224
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 14
Receive Date: 20090218
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 19
Receive Date: 20130227
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002

Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Handler Details

Sequence No: 27
Receive Date: 20210302
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20031231
Handler Name: SEATTLE PORT PIER 69
Source Type: Annual/Biennial Report
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20100219
Handler Name: SEATTLE PORT PIER 69
Source Type: Annual/Biennial Report update with Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: WSQG
Waste Code Description: A placeholder to allow Handler and BR submissions to validate. In WA State federal and state waste codes were not collected on the Site Identification form until 2013 so they were not available for reporting.

Hazardous Waste Handler Details

Sequence No: 26
Receive Date: 20200318
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Handler Details

Sequence No: 17
Receive Date: 20110224
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 22
Receive Date: 20160229
Handler Name: SEATTLE PORT PIER 69
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20051231
Handler Name: SEATTLE PORT PIER 69
Source Type: Annual/Biennial Report
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: District
Name: SEATTLE PORT
Date Became Current: 19960715
Date Ended Current:
Phone: 206-728-3000
Source Type: Annual/Biennial Report update with Notification
Street No:
Street 1: 2711 ALASKAN WAY
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Operator
Type: Private
Name: RESSLER, PETER K
Date Became Current:
Date Ended Current:
Phone: 206-728-3763
Source Type: Notification
Street No:
Street 1: PO BOX 1209
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98111

Owner/Operator Ind: Current Owner
Type: Private
Name: PORT OF SEATTLE
Date Became Current:
Date Ended Current:
Phone: 206-728-3000
Source Type: Notification
Street No:
Street 1: 2711 ALASKAN WAY
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Operator
Type: Private
Name: PORT OF SEATTLE
Date Became Current:
Date Ended Current:
Phone: 206-728-3000
Source Type: Notification
Street No:
Street 1: 2711 ALASKAN WAY
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Operator
Type: Private
Name: COHEN, MICHAEL
Date Became Current:
Date Ended Current:
Phone: 206-728-3562
Street No:
Street 1: PO BOX 1209
Street 2:
City: SEATTLE
State: WA
Country: US

Source Type:	Notification	**Zip Code:**	98111
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2711 ALASKAN WAY
Name:	SEATTLE PORT	**Street 2:**	
Date Became Current:	19960715	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-3000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Municipal	**Street 1:**	2711 ALASKAN WAY
Name:	PORT OF SEATTLE	**Street 2:**	
Date Became Current:	20171231	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-787-3000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2711 ALASKAN WAY
Name:	SEATTLE PORT S	**Street 2:**	
Date Became Current:	19960715	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-787-3000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2711 ALASKAN WAY
Name:	PORT OF SEATTLE P	**Street 2:**	
Date Became Current:	19960715	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-787-3000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 1209
Name:	SEATTLE PORT	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-3201	**Country:**	US
Source Type:	Notification	**Zip Code:**	98111
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	District	**Street 1:**	PO BOX 1209
Name:	PETER RESSLER	**Street 2:**	
Date Became Current:	19960715	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	98111
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2711 ALASKAN WAY
Name:	SEATTLE PORT PIER 69	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	District	**Street 1:**	2711 ALASKAN WAY
Name:	PORT OF SEATTLE	**Street 2:**	
Date Became Current:	19960715	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2711 ALASKAN WAY
Name:	SEATTLE PORT PIER 69	**Street 2:**	

Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	000-000-0000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2711 ALASKAN WAY
Name:	SEATTLE PORT	**Street 2:**	
Date Became Current:	19960715	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-787-3000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	District	**Street 1:**	2711 ALASKAN WAY
Name:	SEATTLE PORT	**Street 2:**	
Date Became Current:	19960715	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	District	**Street 1:**	2711 ALASKAN WAY
Name:	PORT OF SEATTLE	**Street 2:**	
Date Became Current:	19960715	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-3000	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	District	**Street 1:**	2711 ALASKAN WAY
Name:	SEATTLE PORT	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-787-3000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 1209
Name:	SEATTLE PORT	**Street 2:**	
Date Became Current:	19960715	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-3201	**Country:**	US
Source Type:	Notification	**Zip Code:**	98111
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Municipal	**Street 1:**	2711 ALASKAN WAY
Name:	SEATTLE PORT	**Street 2:**	
Date Became Current:	19960715	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-787-3000	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2711 ALASKAN WAY
Name:	PORT OF SEATTLE	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-787-3000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Municipal	**Street 1:**	2711 ALASKAN WAY
Name:	PORT OF SEATTLE	**Street 2:**	
Date Became Current:	19960715	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-787-3000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	District	**Street 1:**	PO BOX 1209
Name:	SEATTLE PORT	**Street 2:**	
Date Became Current:	19960715	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	98111-1209

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2711 ALASKAN WAY
Name:	PORT OF SEATTLE	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-787-3000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Municipal	**Street 1:**	2711 ALASKAN WAY
Name:	SEATTLE PORT	**Street 2:**	
Date Became Current:	19960715	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-787-3000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	District	**Street 1:**	2711 ALASKAN WAY
Name:	PORT OF SEATTLE	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-787-3000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Municipal	**Street 1:**	2711 ALASKAN WAY
Name:	PORT OF SEATTLE	**Street 2:**	
Date Became Current:	19960715	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-787-3000	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	98121

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2711 ALASKAN WAY
Name:	PORT OF SEATTLE	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-3763	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121

Historical Handler Details

Receive Dt:	20060218
Generator Code Description:	Very Small Quantity Generator
Handler Name:	SEATTLE PORT PIER 69

Receive Dt:	20130227
Generator Code Description:	Very Small Quantity Generator
Handler Name:	SEATTLE PORT PIER 69

Receive Dt:	20050221
Generator Code Description:	Very Small Quantity Generator
Handler Name:	SEATTLE PORT PIER 69

Receive Dt:	20080213
Generator Code Description:	Not a Generator, Verified
Handler Name:	SEATTLE PORT PIER 69

Receive Dt:	20100219
Generator Code Description:	Very Small Quantity Generator

Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20110224
Generator Code Description: Very Small Quantity Generator
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20120130
Generator Code Description: Very Small Quantity Generator
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20040227
Generator Code Description: Very Small Quantity Generator
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20030228
Generator Code Description: Not a Generator, Verified
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20090218
Generator Code Description: Not a Generator, Verified
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20051231
Generator Code Description: Not a Generator, Verified
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20000218
Generator Code Description: Very Small Quantity Generator
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20150227
Generator Code Description: Not a Generator, Verified
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 19980303
Generator Code Description: Not a Generator, Verified
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 19970627
Generator Code Description: Not a Generator, Verified
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20210302
Generator Code Description: Not a Generator, Verified
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 19990303
Generator Code Description: Very Small Quantity Generator
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20170228
Generator Code Description: Not a Generator, Verified
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20190228
Generator Code Description: Not a Generator, Verified
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20010215
Generator Code Description: Not a Generator, Verified
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20070224
Generator Code Description: Very Small Quantity Generator
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20101201
Generator Code Description: Very Small Quantity Generator
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20140227
Generator Code Description: Not a Generator, Verified
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20101201
Generator Code Description: Not a Generator, Verified
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20020307
Generator Code Description: Not a Generator, Verified
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20200318
Generator Code Description: Very Small Quantity Generator
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20180228
Generator Code Description: Very Small Quantity Generator
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20110224
Generator Code Description: Very Small Quantity Generator
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20100219
Generator Code Description: Very Small Quantity Generator
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20120130
Generator Code Description: Very Small Quantity Generator
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20160229
Generator Code Description: Not a Generator, Verified
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 19960515
Generator Code Description: Very Small Quantity Generator
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20031231
Generator Code Description: Not a Generator, Verified
Handler Name: SEATTLE PORT PIER 69

Receive Dt: 20071231
Generator Code Description: Not a Generator, Verified
Handler Name: SEATTLE PORT PIER 69

102	1 of 4	WNW	0.24 / 1,268.70	76.13 / -30	Ivars Seafood Bar 3101 1ST AVE SEATTLE WA 98121	CSCSL NFA

Fac Site ID: 38551499
Cleanup Site ID: 1701
Site Status: NFA
NFA Date: 11/08/2002
Responsible Unit: Northwest
Has Insti Control:
Region: Northwest
County: King
Latitude: 47.618679
Longitude: -122.355472
NFA Reason: Voluntary Cleanup Program Review
Alternate Site Names:
Location (OD): ""
(47.618679, -122.355472)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and

Fac Site ID (OD): 38551499
Cleanup SiteID(OD): 1701
Site Status (OD): No Further Action
Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
Region (OD): Northwest
County (OD): King
Latitude (OD): 47.618679
Longitude (OD): -122.355472

Contaminants

NFA Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Metals Priority Pollutants
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Metals Priority Pollutants
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals Priority Pollutants
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

102	*2 of 4*	*WNW*	*0.24 / 1,268.70*	*76.13 / -30*	***IVARS SEAFOOD BAR*** ***3101 1ST AVE*** ***SEATTLE WA 98121-1051***	***ALL SITES***

Facility/Site ID: 38551499
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: IVARS SEAFOOD BAR
Interaction ID: 41973
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 02-Oct-2000
Interact End Dt: 26-Dec-2002
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 10ft
Horizont 1: NAD83
Horizont 2: Address
Location Verified: Y
GIS latitude: 47.618679
GIS longitude: -122.355472

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
102	3 of 4	WNW	0.24 / 1,268.70	76.13 / -30	IVARS SEAFOOD BAR 3101 1ST AVE SEATTLE WA 98121-1051	ICR

Cleanup Site ID: 1701
Facility Site ID: 38551499
Site Status: No Further Action Required
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site: Yes

WRIA ID: 8
Is NFA Site: Yes
Responsible Unit: Northwest
Latitude: 47.618679
Longitude: -122.35547200000001
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID:
VCP Prj No: NW0555
Activity Name: VCP Opinion on Cleanup Action Plan
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Start Date:
End Date:
Legal Mechanism:
Performed by:
Project Manager: Nye, Roger

Related ID:
VCP Prj No: NW0555B
Activity Name: VCP Opinion on Cleanup Action
Activity Status: Canceled
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Start Date:
End Date:
Legal Mechanism:
Performed by:
Project Manager: Nye, Roger

Related ID:
VCP Prj No: NW0555B
Activity Name: VCP Termination
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Start Date:
End Date: 2002-11-08
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No: NW0555
Activity Name: VCP Termination
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Start Date:
End Date: 2002-11-08
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No:
Activity Name: Site Status Changed to NFA
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:

Start Date:
End Date: 2002-11-08
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No:
Activity Name: Initial Investigation / Federal Preliminary Assessment
Activity Status: Completed
County Name: King
Applies to: CleanupSite
Applies to Description:

Start Date: 2001-10-01
End Date: 2001-10-30
Legal Mechanism:
Performed by: Ecology
Project Manager: Nye, Roger

Related ID:
VCP Prj No: NW0555

Start Date: 2000-10-02
End Date:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Activity Name: VCP Application
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No: NW0555B
Activity Name: VCP Application
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2000-12-19
End Date:
Legal Mechanism:
Performed by:
Project Manager:

Media Contaminants

Contaminant Type: Petroleum Products-Unspecified
Groundwater:
Groundwater Desc.:
Surface Water:
Surfacewater Desc.:
Soil: B
Soil Desc.: Below Cleanup Level
Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

Contaminant Type: Metals Priority Pollutants
Groundwater: C
Groundwater Desc.: Confirmed Above Cleanup Level
Surface Water:
Surfacewater Desc.:
Soil: B
Soil Desc.: Below Cleanup Level
Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

102	4 of 4	WNW	0.24 / 1,268.70	76.13 / -30	Ivars Seafood Bar 3101 1ST AVE SEATTLE WA 98121	VCP

Facility Site ID: 38551499
Cleanup Site ID: 1701
Region: Northwest
Alternate Site Names:
Data Source(s): No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State
County: King
Latitude: 47.618679
Longitude: -122.355472

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status: NFA
NFA Date: 11/08/2002
Responsible Unit: Northwest
Has Inst Control:
NFA Reason: Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name: Metals Priority Pollutants
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Status: No Further Action
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Metals Priority Pollutants
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

103	1 of 2	NE	0.24 / 1,273.55	127.21 / 21	PRIME CYTE INC 130 5TH AVE N SEATTLE WA 98109	RCRA NON GEN

EPA Handler ID: WAH000003616
Gen Status Universe: No Report
Contact Name: JENNIFER DAVIS BERGTHOLD
Contact Address: 130 5TH AVE N , , SEATTLE , WA, 98109 , US
Contact Phone No and Ext: 206-728-1575
Contact Email:
Contact Country: US
County Name: KING
EPA Region: 10
Land Type: Other
Receive Date: 20020702
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 12
Receive Date: 20020701
Handler Name: PRIME CYTE INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 9
Receive Date: 20010223
Handler Name: PRIME CYTE INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19970625
Handler Name: PRIME CYTE INC
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20011219
Handler Name: PRIME CYTE INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19931231
Handler Name: PRIME CYTE INC
Source Type: Notification
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 19971107
Handler Name: PRIME CYTE INC
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 8
Receive Date: 19991223
Handler Name: PRIME CYTE INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 19980202
Handler Name: PRIME CYTE INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 11
Receive Date: 20020122
Handler Name: PRIME CYTE INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20020701
Handler Name: PRIME CYTE INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 7
Receive Date: 19990201
Handler Name: PRIME CYTE INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 10
Receive Date: 20011219
Handler Name: PRIME CYTE INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 13
Receive Date: 20020701
Handler Name: PRIME CYTE INC
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 14
Receive Date: 20020702
Handler Name: PRIME CYTE INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	3
Receive Date:	19970626
Handler Name:	PRIME CYTE INC
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	6
Receive Date:	19980903
Handler Name:	PRIME CYTE INC
Source Type:	Notification
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	130 5TH AVE N
Name:	DAVIS BERGTHOLD, JENNIFER	***Street 2:***	
Date Became Current:	19971107	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-728-1575	***Country:***	US
Source Type:	Notification	***Zip Code:***	98109

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	3161 ELLIOTT AVE SUITE 101
Name:	RAINER PROPERTIS INC	***Street 2:***	
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-284-3950	***Country:***	US
Source Type:	Notification	***Zip Code:***	98121

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	130 5TH AVE N
Name:	DAVIS BERGTHOLD, JENNIFER	***Street 2:***	
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-728-1575	***Country:***	US
Source Type:	Notification	***Zip Code:***	98109

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	12951 BEL RED RD
Name:	DINA CORP	***Street 2:***	STE 150
Date Became Current:		***City:***	BELLEVUE
Date Ended Current:		***State:***	WA
Phone:	425-455-5825	***Country:***	US
Source Type:	Notification	***Zip Code:***	98005

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	475 BRANNAN ST
Name:	SIGNATURE BIOSCIENCE INC	***Street 2:***	
Date Became Current:	20020201	***City:***	SAN FRANCISCO
Date Ended Current:		***State:***	CA
Phone:	415-490-2400	***Country:***	US
Source Type:	Notification	***Zip Code:***	94107

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	16020 INDUSTRIAL DR
Name:	IGEN INC	***Street 2:***	
Date Became Current:	19921027	***City:***	GAITHESBURG

Date Ended Current:		**State:**	ME
Phone:	301-984-8000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	20877
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	12951 BEL RED RD
Name:	DINA CORP	**Street 2:**	STE 150
Date Became Current:		**City:**	BELLEVUE
Date Ended Current:		**State:**	WA
Phone:	425-455-5825	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98005
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	16020 INDUSTRIAL DR
Name:	IGEN INC	**Street 2:**	
Date Became Current:	19921027	**City:**	GAITHESBURG
Date Ended Current:		**State:**	ME
Phone:	301-984-8000	**Country:**	US
Source Type:	Notification	**Zip Code:**	20877
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	130 5TH AVE N
Name:	PRIME CYTE INC	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-1575	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98109
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	475 BRANNAN ST
Name:	SIGNATURE BIOSC S	**Street 2:**	
Date Became Current:	20020201	**City:**	SAN FRANCISCO
Date Ended Current:		**State:**	CA
Phone:	415-490-2400	**Country:**	US
Source Type:	Implementer	**Zip Code:**	94107
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	475 BRANNAN ST
Name:	SIGNATURE BIOSCIENCE INC	**Street 2:**	
Date Became Current:	20020201	**City:**	SAN FRANCISCO
Date Ended Current:		**State:**	CA
Phone:	415-490-2400	**Country:**	US
Source Type:	Implementer	**Zip Code:**	94107
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	130 5TH AVE N
Name:	DAVIS BERGTHOLD, JENNIFER	**Street 2:**	
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-1575	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98109
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	12951 BEL RED RD
Name:	DINA CORP	**Street 2:**	STE 150
Date Became Current:	19971107	**City:**	BELLEVUE
Date Ended Current:		**State:**	WA
Phone:	425-455-5825	**Country:**	US
Source Type:	Notification	**Zip Code:**	98005
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	130 5TH AVE N
Name:	JENNIFER D	**Street 2:**	
Date Became Current:	19971107	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-1575	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98109
Owner/Operator Ind:	Current Operator	**Street No:**	

Type:	Private	***Street 1:***	130 5TH AVE N
Name:	PRIME CYTE INC	***Street 2:***	
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	000-000-0000	***Country:***	US
Source Type:	Implementer	***Zip Code:***	98109
Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	130 5TH AVE N
Name:	PRIME CYTE INC	***Street 2:***	
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	000-000-0000	***Country:***	US
Source Type:	Notification	***Zip Code:***	98109
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	130 5TH AVE N
Name:	PRIME CYTE INC	***Street 2:***	
Date Became Current:	20011219	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-728-1575	***Country:***	US
Source Type:	Notification	***Zip Code:***	98109
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	3161 ELLIOTT AVE SUITE 101
Name:	RAINER PROPERTIS INC	***Street 2:***	
Date Became Current:		***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-284-3950	***Country:***	US
Source Type:	Implementer	***Zip Code:***	98121

Historical Handler Details

Receive Dt:	20020701
Generator Code Description:	Very Small Quantity Generator
Handler Name:	PRIME CYTE INC
Receive Dt:	20010223
Generator Code Description:	Very Small Quantity Generator
Handler Name:	PRIME CYTE INC
Receive Dt:	20011219
Generator Code Description:	Very Small Quantity Generator
Handler Name:	PRIME CYTE INC
Receive Dt:	20020701
Generator Code Description:	Not a Generator, Verified
Handler Name:	PRIME CYTE INC
Receive Dt:	19931231
Generator Code Description:	Large Quantity Generator
Handler Name:	PRIME CYTE INC
Receive Dt:	20011219
Generator Code Description:	Not a Generator, Verified
Handler Name:	PRIME CYTE INC
Receive Dt:	20020122
Generator Code Description:	Very Small Quantity Generator
Handler Name:	PRIME CYTE INC
Receive Dt:	19980202
Generator Code Description:	Very Small Quantity Generator
Handler Name:	PRIME CYTE INC
Receive Dt:	20020701
Generator Code Description:	Not a Generator, Verified
Handler Name:	PRIME CYTE INC

Receive Dt: 19980903
Generator Code Description: Not a Generator, Verified
Handler Name: PRIME CYTE INC

Receive Dt: 19970625
Generator Code Description: Not a Generator, Verified
Handler Name: PRIME CYTE INC

Receive Dt: 19971107
Generator Code Description: Small Quantity Generator
Handler Name: PRIME CYTE INC

Receive Dt: 19990201
Generator Code Description: Very Small Quantity Generator
Handler Name: PRIME CYTE INC

Receive Dt: 19991223
Generator Code Description: Very Small Quantity Generator
Handler Name: PRIME CYTE INC

Receive Dt: 19970626
Generator Code Description: Not a Generator, Verified
Handler Name: PRIME CYTE INC

103	2 of 2	NE	0.24 / 1,273.55	127.21 / 21	Prime Cyte Inc 130 5TH AVE N SEATTLE WA 98109	ALL SITES

Facility/Site ID: 56655391
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000003616
Facility Alternate:
Interaction ID: 52207
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 07-Nov-1997
Interact End Dt: 31-Jul-2002
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Address
Location Verified: N
GIS latitude: 47.37627
GIS longitude: -122.21858

104	1 of 6	ENE	0.24 / 1,275.61	125.99 / 20	Taylor & Denny Building 101 TAYLOR AVE N SEATTLE WA 98109	CSCSL

Fac Site ID: 9475
Cleanup Site ID: 12171
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest
Fac Site ID (OD): 9475
Cleanup SiteID(OD): 12171
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest

Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.346732
Latitude:	47.6191291873413	**Latitude (OD):**	47.619129
Longitude:	-122.346732186508		
Site Name:	Taylor & Denny Building		
Address:	101 TAYLOR AVE N		
City:	SEATTLE		
Zip Code:	98109		
Site Status (OD):	Cleanup Started		
Site Name (OD):	Taylor & Denny Building		
Address (OD):	101 TAYLOR AVE N		
City (OD):	SEATTLE		
Zipcode (OD):	98109		
Location (OD):	"" (47.619129, -122.346732)		
Alternate Site Names:	Taylor & Denny Building (Off-Property),Taylor & Denny Building (Property NFA),Taylor and Denny New Building		
Data Source(s):	Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Gasoline
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Petroleum-Other
Groundwater:	
Surfacewater:	
Soil:	Below Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Petroleum-Diesel
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Benzene
Groundwater:	
Surfacewater:	
Soil:	Below Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Lead
Groundwater:	
Surfacewater:	
Soil:	Below Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Polycyclic Aromatic Hydrocarbons
Groundwater:	
Surfacewater:	
Soil:	Below Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Lead
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

104	2 of 6	ENE	0.24 / 1,275.61	125.99 / 20	Taylor and Denny New Building 101 TAYLOR AVE N SEATTLE WA 98109	ALL SITES

Facility/Site ID: 9475
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: NW2763
Facility Alternate: Taylor and Denny New Building
Interaction ID: 105569
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 18-Jul-2013
Interact End Dt: 01-Apr-2014
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID:
Facility Alternate: Taylor & Denny Building (Off-Property)
Interaction ID: 127341
Interaction Status: A
Interac Status Desc: Active
Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 01-Apr-2014
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility Location Detail

Horizontal:	40ft	***Location Verified:***	
Horizont 1:	NAD83HARN	***GIS latitude:***	47.6191291873
Horizont 2:	Digital map or GIS	***GIS longitude:***	-122.346732187

---

104 ***3 of 6*** ***ENE*** ***0.24 / 1,275.61*** ***125.99 / 20*** ***Taylor & Denny Building***
101 TAYLOR AVE N
SEATTLE WA 98109 ***ICR***

Cleanup Site ID:	12171	***WRIA ID:***	8
Facility Site ID:	9475	***Is NFA Site:***	
Site Status:	Cleanup Started	***Responsible Unit:***	Northwest
Statute:	MTCA	***Latitude:***	47.619129187341294
Rank:		***Longitude:***	-122.34673218650811
Rank Description:		***Legislative District:***	36
Has Env Covenant:		***Congr District:***	7
Is Brownfiled Site:		***County Name:***	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		***Start Date:***	2013-07-18
VCP Prj No:	NW2763	***End Date:***	
Activity Name:	VCP Receipt of Plan or Report	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Garbush, Gayle
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	2014-01-31
VCP Prj No:	NW2763	***End Date:***	2014-04-01
Activity Name:	VCP Opinion on Site Cleanup	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Carrosino, Glynis
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	2013-07-18
VCP Prj No:	NW2763	***End Date:***	2013-08-27
Activity Name:	VCP Opinion on Site Cleanup	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Carrosino, Glynis
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	
VCP Prj No:	NW2763	***End Date:***	2014-04-01
Activity Name:	VCP Termination	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Fernandez, Sonia
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	2013-07-18
VCP Prj No:	NW2763	***End Date:***	
Activity Name:	VCP Application	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Carrosino, Glynis
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Media Contaminants

Contaminant Type:	Lead	***Sediment:***	

Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	B	***Bedrock Desc.:***	
Soil Desc.:	Below Cleanup Level	***County Name:***	King

Contaminant Type:	Petroleum-Gasoline	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

Contaminant Type:	Polynuclear Aromatic Hydrocarbons	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	B	***Bedrock Desc.:***	
Soil Desc.:	Below Cleanup Level	***County Name:***	King

Contaminant Type:	Petroleum-Diesel	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

Contaminant Type:	Petroleum-Other	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	B	***Bedrock Desc.:***	
Soil Desc.:	Below Cleanup Level	***County Name:***	King

Contaminant Type:	Benzene	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	B	***Bedrock Desc.:***	
Soil Desc.:	Below Cleanup Level	***County Name:***	King

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
104	4 of 6	ENE	0.24 / 1,275.61	125.99 / 20	Taylor & Denny Building 101 TAYLOR AVE N SEATTLE WA 98109	VCP

Facility Site ID:	9475	***County:***	King
Cleanup Site ID:	12171	***Latitude:***	47.6191291873413
Region:	Northwest	***Longitude:***	-122.346732186508

Alternate Site Names: Taylor & Denny Building (Off-Property),Taylor & Denny Building (Property NFA),Taylor and Denny New Building
Data Source(s): Confirmed and Suspected Contaminated Sites; Confirmed and Suspected Contaminated Sites; All Cleanup Sites in Washington State

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List

Site Status:	Cleanup Started
Current VCP:	
Past VCP:	Yes
Site Rank:	
Responsible Unit:	Northwest
Has Inst Control:	

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List - Contaminants

Contaminant Name:	Polycyclic Aromatic Hydrocarbons	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Below Cleanup Levels		
Contaminant Name:	Lead	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Below Cleanup Levels		
Contaminant Name:	Petroleum-Gasoline	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		
Contaminant Name:	Petroleum-Other	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Below Cleanup Levels		
Contaminant Name:	Petroleum-Diesel	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		
Contaminant Name:	Benzene	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Below Cleanup Levels		

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status:	Cleanup Started
Site Rank:	
Has Inst Control:	
Current VCP:	
Past VCP:	Yes
Responsible Unit:	Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name:	Benzene	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Below Cleanup Levels		
Contaminant Name:	Petroleum-Diesel	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		
Contaminant Name:	Polycyclic Aromatic Hydrocarbons	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Below Cleanup Levels		
Contaminant Name:	Petroleum-Gasoline	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Remediated-Below		
Contaminant Name:	Lead	***Sediment:***	
Groundwater:		***Air:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Surfacewater: **Bedrock:**
Soil: Below Cleanup Levels

Contaminant Name: Petroleum-Other **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Below Cleanup Levels

---

104 **5 of 6** **ENE** **0.24 / 1,275.61** **125.99 / 20** **The Century Apartments - Residential Parking**
101 Taylor Ave N
Seattle WA 98109
ALT FUELS

Fuel Type Code: ELEC: Electric
Station Phone: 888-998-2546
Expected Date:
BD Blends:
NG Fill Type Code:
NG PSI:
Federal Agency ID:
Open Date: 2021-08-12
NG Vehicle Class:
LPG Primary:
E85 Blender Pump:
NG Fill Type Desc:
Hydrogen is Retail:
Federal Agency:
Facility Type:
Dt Last Confirmed: 2022-07-31
Restricted Access:
Fed Agency Name:
Hydrogen Status Link:
Status: Open: The station is open.
Owner Type Desc:
E85 Blender Pump Desc:
NG Vehicle Class Desc:
Geocode Status Desc: The location is from a real GPS readout at the station.
LPG Primary Desc:
E85 Other Ethanol Blends:
EV Pricing: Level 2: $0.49 per kWh
EV Pricing French:
EV on Site Renewable Source:
Intersection Directions:

ID: 193830
Updated at: 2022-07-31 22:55:16 UTC
CNG Dispenser No:
CNG Site Renew Src:
CNG Tot Compr Cap:
CNG Storage Cap:
CNG Fill Type Code:
CNG PSI:
CNG Vehicle Class:
LNG Site Renew Src:
LNG Vehicle Class:
LPG Nozzle Types:
Hydrogen Pressures:
Hydrogen Standards:
Latitude: 47.619488
Longitude: -122.346886

---

104 **6 of 6** **ENE** **0.24 / 1,275.61** **125.99 / 20** **The Century Apartments - Retail Parking**
101 Taylor Ave N
Seattle WA 98109
ALT FUELS

Fuel Type Code: ELEC: Electric
Station Phone: 888-998-2546
Expected Date:
BD Blends:
NG Fill Type Code:
NG PSI:
Federal Agency ID:
Open Date: 2021-08-11
NG Vehicle Class:
LPG Primary:
E85 Blender Pump:
NG Fill Type Desc:
Hydrogen is Retail:
Federal Agency:
Facility Type:
Dt Last Confirmed: 2022-07-31
Restricted Access:

ID: 193780
Updated at: 2022-07-31 22:55:16 UTC
CNG Dispenser No:
CNG Site Renew Src:
CNG Tot Compr Cap:
CNG Storage Cap:
CNG Fill Type Code:
CNG PSI:
CNG Vehicle Class:
LNG Site Renew Src:
LNG Vehicle Class:
LPG Nozzle Types:
Hydrogen Pressures:
Hydrogen Standards:
Latitude: 47.618918
Longitude: -122.346874

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Fed Agency Name:
Hydrogen Status Link:
Status: Open: The station is open.
Owner Type Desc:
E85 Blender Pump Desc:
NG Vehicle Class Desc:
Geocode Status Desc: The location is from a real GPS readout at the station.
LPG Primary Desc:
E85 Other Ethanol Blends:
EV Pricing: Level 2: $0.49 per kWh
EV Pricing French:
EV on Site Renewable Source:
Intersection Directions: Access to Retail Garage is currently restricted.

105	1 of 6	ENE	0.24 / 1,284.97	124.15 / 18	GROSVENOR HOUSE 500 WALL ST STE 100 SEATTLE WA 98121	RCRA NON GEN

EPA Handler ID: WAD135034577
Gen Status Universe: No Report
Contact Name: GROSVENOR HOUSE GROSVENOR HOUSE
Contact Address: 500 WALL ST STE 100 , , SEATTLE , WA, 98121-1531 , US
Contact Phone No and Ext: 000-000-0000
Contact Email:
Contact Country: US
County Name: KING
EPA Region: 10
Land Type: Private
Receive Date: 19940101
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19940101
Handler Name: GROSVENOR HOUSE
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19940101
Handler Name: GROSVENOR HOUSE
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19901231
Handler Name: GROSVENOR HOUSE
Source Type: Annual/Biennial Report
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: GROSVENOR HOUSE
Date Became Current: 19960502
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 500 WALL ST STE 100
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Operator
Type: Private
Name: GROSVENOR HOUSE
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 500 WALL ST STE 100
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Owner/Operator Ind: Current Owner
Type: Private
Name: GROSVENOR HOUSE G
Date Became Current: 19960502
Date Ended Current:
Phone: 000-000-0000
Source Type: Implementer
Street No:
Street 1: 500 WALL ST STE 100
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121-1531

Owner/Operator Ind: Current Owner
Type: Private
Name: GROSVENOR HOUSE
Date Became Current:
Date Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street 1: 500 WALL ST STE 100
Street 2:
City: SEATTLE
State: WA
Country: US
Zip Code: 98121

Historical Handler Details

Receive Dt: 19940101
Generator Code Description: Not a Generator, Verified
Handler Name: GROSVENOR HOUSE

Receive Dt: 19901231
Generator Code Description: Large Quantity Generator
Handler Name: GROSVENOR HOUSE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
105	2 of 6	ENE	0.24 / 1,284.97	124.15 / 18	Archstone Belltown 500 WALL ST SEATTLE WA 98121	CSCSL

Fac Site ID:	1908878	**Responsible Unit:**	Northwest
Cleanup Site ID:	1767	**Fac Site ID (OD):**	1908878
Site Status:	Cleanup Started	**Cleanup SiteID(OD):**	1767
Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:	Yes	**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.345014
Latitude:	47.6179045349779	**Latitude (OD):**	47.617905
Longitude:	-122.345013729372		

Site Name: Archstone Belltown
Address: 500 WALL ST
City: SEATTLE
Zip Code: 98121
Site Status (OD): Cleanup Started
Site Name (OD): Archstone Belltown
Address (OD): 500 WALL ST
City (OD): SEATTLE
Zipcode (OD): 98121
Location (OD): ""
(47.617905, -122.345014)
Alternate Site Names: FORMER WALL STREET TOWERS
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater: Below Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Groundwater
Contaminant Status: Below Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
105	3 of 6	ENE	0.24 / 1,284.97	124.15 / 18	Grosvenor House 500 WALL ST STE 100 SEATTLE WA 98121	ALL SITES

Facility/Site ID: 5648737
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility/Site Interaction

Program ID:	WAD135034577
Facility Alternate:	
Interaction ID:	17202
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	13-Apr-1989
Interact End Dt:	10-Sep-1993
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	N
Horizont 1:	NAD83	***GIS latitude:***	47.61756
Horizont 2:	Unknown	***GIS longitude:***	-122.34528

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
105	4 of 6	ENE	0.24 / 1,284.97	124.15 / 18	Archstone Belltown 500 WALL ST SEATTLE WA 98121	ALL SITES

Facility/Site ID:	1908878
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	NW1787
Facility Alternate:	Archstone Belltown
Interaction ID:	9537
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	VOLCLNST
Interaction Desc:	Voluntary Cleanup Sites
Interact Start Dt:	06-Jun-2007
Interact End Dt:	07-Jan-2008
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Program ID:	NW1919
Facility Alternate:	Archstone Belltown
Interaction ID:	9538
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	VOLCLNST
Interaction Desc:	Voluntary Cleanup Sites
Interact Start Dt:	28-Mar-2008
Interact End Dt:	16-Feb-2012
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Facility Location Detail

Horizontal:	40ft	***Location Verified:***	
Horizont 1:	NAD83HARN	***GIS latitude:***	47.617904535

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Horizont 2: Digital map or GIS **GIS longitude:** -122.345013729

---

105 **5 of 6** **ENE** **0.24 / 1,284.97** **124.15 / 18** **Archstone Belltown**
500 WALL ST
SEATTLE WA 98121 **ICR**

Cleanup Site ID: 1767
Facility Site ID: 1908878
Site Status: Cleanup Started
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site: Yes

WRIA ID: 8
Is NFA Site:
Responsible Unit: Northwest
Latitude: 47.61790453497786
Longitude: -122.34501372937152
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID:
VCP Prj No: NW1787
Activity Name: VCP Application
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Start Date: 2007-06-06
End Date:
Legal Mechanism:
Performed by:
Project Manager: Northwest Region

Related ID:
VCP Prj No: NW1787
Activity Name: VCP Opinion on Interim Action
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Start Date:
End Date: 2007-07-09
Legal Mechanism:
Performed by:
Project Manager: Liu, Jing

Related ID:
VCP Prj No: NW1787
Activity Name: VCP Termination
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Start Date:
End Date: 2008-01-07
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No: NW1919
Activity Name: VCP Status Request
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Start Date: 2011-12-20
End Date: 2012-02-16
Legal Mechanism:
Performed by:
Project Manager: Olsen, Russ

Related ID:
VCP Prj No: NW1919
Activity Name: VCP Opinion on Interim Action
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Start Date:
End Date: 2010-05-17
Legal Mechanism:
Performed by:
Project Manager: Liu, Jing

Related ID:
VCP Prj No: NW1919
Activity Name: VCP Application
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Start Date: 2008-03-28
End Date:
Legal Mechanism:
Performed by:
Project Manager: Northwest Region

Related ID:

Start Date:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

VCP Prj No:	NW1919	**End Date:**	2012-02-16
Activity Name:	VCP Termination	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Olsen, Russ
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	
VCP Prj No:	NW1919	**End Date:**	2008-05-06
Activity Name:	VCP Opinion on Interim Action	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Liu, Jing
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Media Contaminants

Contaminant Type:	Petroleum Products-Unspecified	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

Contaminant Type:	Polynuclear Aromatic Hydrocarbons	**Sediment:**	
Groundwater:	B	**Sediment Desc.:**	
Groundwater Desc.:	Below Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:		**Bedrock Desc.:**	
Soil Desc.:		**County Name:**	King

105	6 of 6	ENE	0.24 / 1,284.97	124.15 / 18	**Archstone Belltown** **500 WALL ST** **SEATTLE WA 98121**	VCP

Facility Site ID:	1908878	**County:**	King
Cleanup Site ID:	1767	**Latitude:**	47.6179045349779
Region:	Northwest	**Longitude:**	-122.345013729372
Alternate Site Names:	FORMER WALL STREET TOWERS		
Data Source(s):	Confirmed and Suspected Contaminated Sites; Confirmed and Suspected Contaminated Sites; All Cleanup Sites in Washington State		

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List

Site Status:	Cleanup Started
Current VCP:	
Past VCP:	Yes
Site Rank:	
Responsible Unit:	Northwest
Has Inst Control:	

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List - Contaminants

Contaminant Name:	Polycyclic Aromatic Hydrocarbons	**Sediment:**	
Groundwater:	Below Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:			

Contaminant Name:	Petroleum Products-Unspecified	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Confirmed Above Cleanup Levels		

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: Cleanup Started
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater: Below Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

---

106 | ***1 of 8*** | ***NE*** | ***0.25 / 1,304.95*** | ***131.80 / 26*** | ***Fifth & Broad 417 BROAD ST SEATTLE WA 98109*** | ***CSCSL***

Fac Site ID: 21907
Cleanup Site ID: 12242
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control: Yes
County: King
Region: Northwest
Latitude: 47.6201052708217
Longitude: -122.348063699814
Site Name: Fifth & Broad
Address: 417 BROAD ST
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Fifth & Broad Property
Address (OD): 417 BROAD ST
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): "" (47.620105, -122.348064)
Alternate Site Names: Fifth & Broad Off-Property,Fifth & Broad Property,Fifth & Broad Property NFA,Fifth and Broad Property,Seattle Monorail Project
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 21907
Cleanup SiteID(OD): 12242
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.348064
Latitude (OD): 47.620105

Contaminants Detail(s)

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Other Halogenated Organics
Groundwater:
Surfacewater:
Soil: Remediated-Below

Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Remediated-Below
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Other Non-Halogenated Organics
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Other Halogenated Organics
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

106 | ***2 of 8*** | ***NE*** | ***0.25 / 1,304.95*** | ***131.80 / 26*** | ***Fifth and Broad Property
417 BROAD ST
Seattle WA 98109*** | ***UST***

UST ID: 620081
Facility Site ID: 21907
Site Active: No
Responsible Unit: Northwest
Active Tag:
Alternate Site Names: Fifth & Broad,Fifth & Broad Off-Property,Fifth & Broad Property,Fifth & Broad Property NFA,Seattle Monorail Project

Region: Northwest
County: King
Latitude: 47.6201052708217
Longitude: -122.348063699814

Tank Detail(s)

Tank Name: 1
Status Date: 10/22/2013
Tank Construction:
Tank Capacity:

Install Date:
Upgrade Date:
Perm Closure Date:
Tank Status: Unknown
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:
Actual Capacity: 550
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity: 550
Stored Substance: Unknown
Used Substance:

Tank Detail(s)

Tank Name: 3
Status Date: 10/22/2013
Install Date:
Upgrade Date:
Perm Closure Date:
Tank Status: Unknown
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:
Tank Construction:
Tank Capacity:
Actual Capacity: 1000
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity: 1000
Stored Substance: Unknown
Used Substance:

Tank Detail(s)

Tank Name: 5
Status Date: 10/22/2013
Install Date:
Upgrade Date:
Perm Closure Date:
Tank Status: Unknown
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction:
Tank Capacity:
Actual Capacity: 5000
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity: 5000
Stored Substance: Unknown
Used Substance:

Tank Detail(s)

Tank Name: 6
Status Date: 10/22/2013
Install Date:
Upgrade Date:
Perm Closure Date:
Tank Status: Unknown
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction:
Tank Capacity:
Actual Capacity:
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity:
Stored Substance: Used Oil/Waste Oil
Used Substance:

Tank Detail(s)

Tank Name: 2
Status Date: 10/22/2013
Install Date:
Upgrade Date:
Perm Closure Date:
Tank Status: Unknown
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction:
Tank Capacity:
Actual Capacity: 550
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity: 550
Stored Substance: Unknown
Used Substance:

Tank Detail(s)

Tank Name: 4
Status Date: 10/22/2013
Install Date:
Upgrade Date:
Perm Closure Date:
Tank Status: Unknown
Tank Material:
Tank Corrosion Protection:
Tank Manifold:
Tank Release Detection:
Tank Tightness Test:
Tank Spill Prevention:
Tank Overfill Prevention:
Pipe Material:
Pipe Construction:
Pipe Corrosion Protection:
Tank SFC:
Dispenser SFC:
Primary Pipe Release Detection:
Secondary Pipe Rel Detect:
Pipe Pumping System:
Turbine Sump Construction:

Tank Construction:
Tank Capacity:
Actual Capacity: 2000
Pipe Install Date:
Endorsement Expire:

Compartments

Compartment No: 1
Compart Capacity: 2000
Stored Substance: Unknown
Used Substance:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
106	3 of 8	NE	0.25 / 1,304.95	131.80 / 26	Fifth & Broad Property 417 BROAD ST SEATTLE WA 98109	ALL SITES

Facility/Site ID: 21907
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: NW2793
Facility Alternate: Fifth & Broad Property NFA
Interaction ID: 106442
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 22-Oct-2013
Interact End Dt: 29-Mar-2019
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: 620081
Facility Alternate: Fifth & Broad
Interaction ID: 106550
Interaction Status: A
Interac Status Desc: Active
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 22-Oct-2013
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID:
Facility Alternate: Fifth & Broad Off-Property
Interaction ID: 130524
Interaction Status: A
Interac Status Desc: Active
Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 29-Mar-2019
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: WAH000044432
Facility Alternate: 1221 Denny LLC
Interaction ID: 106532
Interaction Status: A
Interac Status Desc: Active
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 06-Nov-2013
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Program ID:	620081
Facility Alternate:	Fifth & Broad
Interaction ID:	106549
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	LUST
Interaction Desc:	LUST Facility
Interact Start Dt:	22-Oct-2013
Interact End Dt:	29-Mar-2019
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Facility Location Detail

Horizontal:	40ft	**Location Verified:**	
Horizont 1:	NAD83HARN	**GIS latitude:**	47.6201052708
Horizont 2:	Digital map or GIS	**GIS longitude:**	-122.3480637

106	4 of 8	NE	0.25 / 1,304.95	131.80 / 26	**Fifth & Broad** **417 BROAD ST** **SEATTLE WA 98109**	LUST

Facility Site ID:	21907	**County:**	King
Cleanup Site ID:	12242	**Latitude:**	47.6201052708217
Responsible Unit:	Northwest	**Longitude:**	-122.348063699814
Region:	Northwest		
Alternate Site Names:	Fifth & Broad Off-Property,Fifth & Broad Property,Fifth & Broad Property NFA,Fifth and Broad Property,Seattle Monorail Project		

Tank Detail(s)

UST ID:	620081	**Status Date:**	10/22/2013
LUST ID:	6754	**Release Date:**	10/22/2013
LUST Status:	LUST - Cleanup Started		

Contaminants Detail(s)

Contaminant Name:	Benzene	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Below		

Contaminants Detail(s)

Contaminant Name:	Other Non-Halogenated Organics	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Below		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Gasoline	**Sediment:**	
Groundwater:	Below Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Below		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Diesel	**Sediment:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Groundwater: Remediated-Below
Surfacewater:
Soil: Remediated-Below
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Other Halogenated Organics
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

---

106 | **5 of 8** | **NE** | **0.25 / 1,304.95** | **131.80 / 26** | **Fifth and Broad Property**
417 BROAD ST
SEATTLE WA 98109 | **ICR**

Cleanup Site ID: 12242
Facility Site ID: 21907
Site Status: Cleanup Started
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site: Yes
WRIA ID: 8
Is NFA Site:
Responsible Unit: Northwest
Latitude: 47.620105270821711
Longitude: -122.34806369981398
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID:
VCP Prj No:
Activity Name: Site Discovery/Release Report Received
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date:
End Date: 2013-10-24
Legal Mechanism:
Performed by:
Project Manager: Northwest Region

Related ID: 6754
VCP Prj No:
Activity Name: LUST - Notification
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 2013-10-22
End Date: 2013-10-22
Legal Mechanism:
Performed by:
Project Manager: Northwest Region

Related ID: 6754
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 2015-01-08
End Date: 2015-01-09
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No:
Activity Name: Initial Investigation / Federal Preliminary Assessment
Activity Status: Canceled
County Name: King
Applies to: CleanupSite
Start Date: 2013-10-24
End Date:
Legal Mechanism:
Performed by:
Project Manager: Northwest Region

Applies to Description:

Related ID:
VCP Prj No: NW2793
Activity Name: VCP Application
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2013-10-22
End Date:
Legal Mechanism:
Performed by:
Project Manager: Fernandez, Sonia

Related ID:
VCP Prj No: NW2793
Activity Name: VCP Opinion on Remedial Investigation
Activity Status: Canceled
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2013-10-22
End Date:
Legal Mechanism:
Performed by:
Project Manager: Sanchez, Maureen

Related ID:
VCP Prj No: NW2793
Activity Name: VCP Opinion on Remedial Investigation Work Plan
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2015-07-02
End Date: 2015-07-24
Legal Mechanism:
Performed by:
Project Manager: Cardona-Marek, Tamara

Related ID:
VCP Prj No: NW2793
Activity Name: VCP Opinion on Remedial Investigation
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2014-03-21
End Date: 2014-05-28
Legal Mechanism:
Performed by:
Project Manager: Sanchez, Maureen

Related ID: 6754
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 2013-08-31
End Date: 2013-08-30
Legal Mechanism:
Performed by:
Project Manager:

Related ID: 6754
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 2004-05-05
End Date: 2013-08-30
Legal Mechanism:
Performed by:
Project Manager:

Related ID: 6754
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 2014-03-21
End Date: 2014-03-21
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No: NW2793
Activity Name: VCP Opinion on Site Cleanup
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2015-01-09
End Date: 2015-03-25
Legal Mechanism:
Performed by:
Project Manager: Sanchez, Maureen

Related ID: 6754
VCP Prj No:
Start Date: 2015-06-30
End Date: 2015-07-02

Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Media Contaminants

Contaminant Type:	Benzene	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King
Contaminant Type:	Other Halogenated Organics	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King
Contaminant Type:	Petroleum-Other	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

106	6 of 8	NE	0.25 / 1,304.95	131.80 / 26	1221 DENNY LLC 417 BROAD ST SEATTLE WA 98109	RCRA NON GEN

EPA Handler ID:	WAH000044432
Gen Status Universe:	No Report
Contact Name:	KENT ANGIER
Contact Address:	2310 130TH AVE NE STE B100 , , BELLEVUE , WA, 98005 , US
Contact Phone No and Ext:	206-447-0303
Contact Email:	KENTA@KAURI.COM
Contact Country:	US
County Name:	KING
EPA Region:	10
Land Type:	Private
Receive Date:	20140301
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No

Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20140228
Handler Name: 1221 DENNY LLC
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20131106
Handler Name: 1221 DENNY LLC
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20140301
Handler Name: 1221 DENNY LLC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20140228
Handler Name: 1221 DENNY LLC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: 1221 DENNY LLC
Date Became Current: 20080101
Date Ended Current:
Street No:
Street 1: 2310 130TH AVE NE STE B100
Street 2:
City: BELLEVUE
State: WA

Phone:	206-447-0303	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98005
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2310 130TH AVE NE STE B100
Name:	1221 DENNY LLC	**Street 2:**	
Date Became Current:	20080101	**City:**	BELLEVUE
Date Ended Current:		**State:**	WA
Phone:	206-447-0303	**Country:**	US
Source Type:	Notification	**Zip Code:**	98005
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2310 130TH AVE NE STE B100
Name:	1221 DENNY LLC	**Street 2:**	
Date Became Current:		**City:**	BELLEVUE
Date Ended Current:		**State:**	WA
Phone:	206-447-0303	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98005
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2310 130TH AVE NE STE B100
Name:	1221 DENNY LLC	**Street 2:**	
Date Became Current:		**City:**	BELLEVUE
Date Ended Current:		**State:**	WA
Phone:	206-447-0303	**Country:**	US
Source Type:	Notification	**Zip Code:**	98005
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2310 130TH AVE NE STE B100
Name:	1221 DENNY LLC	**Street 2:**	
Date Became Current:		**City:**	BELLEVUE
Date Ended Current:		**State:**	WA
Phone:	206-447-0303	**Country:**	US
Source Type:	Notification	**Zip Code:**	98005
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2310 130TH AVE NE STE B100
Name:	1221 DENNY LLC	**Street 2:**	
Date Became Current:		**City:**	BELLEVUE
Date Ended Current:		**State:**	WA
Phone:	206-447-0303	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98005

Historical Handler Details

Receive Dt:	20131106
Generator Code Description:	Small Quantity Generator
Handler Name:	1221 DENNY LLC
Receive Dt:	20140228
Generator Code Description:	Small Quantity Generator
Handler Name:	1221 DENNY LLC
Receive Dt:	20140228
Generator Code Description:	Not a Generator, Verified
Handler Name:	1221 DENNY LLC

106 | ***7 of 8*** | ***NE*** | ***0.25 / 1,304.95*** | ***131.80 / 26*** | ***Fifth & Broad 417 BROAD ST SEATTLE WA 98109*** | ***INST***

Facility Site ID:	21907	**Cleanup Site ID:**	12242
Region:	Northwest	**Region (OD):**	
County:	King	**County (OD):**	
Latitude:	47.6201052708217	**Latitude (OD):**	
Longitude:	-122.348063699814	**Longitude (OD):**	
Site Name:	Fifth & Broad		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Address: 417 BROAD ST
City: SEATTLE
Zip: 98109
Site Name (OD):
Address (OD):
City (OD):
Zipcode (OD):
Location (OD):
Data Source(s): Department of Ecology State of Washington - Environmental Covenants Registry List

Environmental Covenants Registry List

NFA Date:
Site Status: Cleanup Started
Tax Parcel No: 1991200075
Instrument Type: Environmental Covenant
Media Restrictions: Groundwater; Soil
Alternate Site Names: Fifth & Broad Off-Property,Fifth & Broad Property,Fifth & Broad Property NFA,Fifth and Broad Property,Seattle Monorail Project
Cnty Recording No: 20190228000761
Cnty Recording Dt: 02/28/2019
Responsible Unit: Northwest
Active Control: Yes
Control Stormwater: No
Control Vapor Gas: No
Prevent Reuse/Relocation: No
Prohibit New Bldg Constr: Yes
Prohibit Removal or Alteration: Yes
Prohibit Soil Disturbance: Yes
Ongoing Maint of Remedy: Yes
Require Educational Programs: No
Restrict Access: No
Restrict All GW Extr: Yes
Restrict Domestic GW: Yes
Restrict Land Use: No
Restrict Sedmnt Cap Disturb: No
Restrict Shellfish and or Finf: No
Restrict Surface Water Use: No
Restrict Swim/Beach Play: No
Restrictive Signage: No
Maintain/Protect Monit System: Yes
Other: Yes

106	8 of 8	NE	0.25 / 1,304.95	131.80 / 26	Fifth & Broad 417 BROAD ST SEATTLE WA 98109	VCP

Facility Site ID: 21907
Cleanup Site ID: 12242
Region: Northwest
County: King
Latitude: 47.6201052708217
Longitude: -122.348063699814
Alternate Site Names: Fifth & Broad Off-Property,Fifth & Broad Property,Fifth & Broad Property NFA,Fifth and Broad Property,Seattle Monorail Project
Data Source(s): Confirmed and Suspected Contaminated Sites; Confirmed and Suspected Contaminated Sites; All Cleanup Sites in Washington State

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List

Site Status: Cleanup Started
Current VCP:
Past VCP: Yes
Site Rank:
Responsible Unit: Northwest
Has Inst Control: Yes

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List - Contaminants

Contaminant Name:	Benzene	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		
Contaminant Name:	Other Non-Halogenated Organics	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		
Contaminant Name:	Petroleum-Diesel	***Sediment:***	
Groundwater:	Remediated-Below	***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Remediated-Below		
Contaminant Name:	Petroleum-Gasoline	***Sediment:***	
Groundwater:	Below Cleanup Levels	***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		
Contaminant Name:	Other Halogenated Organics	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Remediated-Below		
Contaminant Name:	Petroleum-Other	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status:	Cleanup Started
Site Rank:	
Has Inst Control:	Yes
Current VCP:	
Past VCP:	Yes
Responsible Unit:	Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name:	Benzene	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Remediated-Below		
Contaminant Name:	Other Halogenated Organics	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Remediated-Below		
Contaminant Name:	Petroleum-Diesel	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		
Contaminant Name:	Other Non-Halogenated Organics	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Remediated-Below		
Contaminant Name:	Petroleum-Other	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant Name:	Petroleum-Gasoline	**Sediment:**	
Groundwater:	Below Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Below		

107	1 of 2	SSW	0.25 / 1,306.08	10.04 / -96	**EDGEWATER HOTEL** **2411 ALASKAN WAY PIER 67** **SEATTLE WA 98121**	**RCRA NON GEN**

EPA Handler ID:	WAH000037063
Gen Status Universe:	No Report
Contact Name:	SCOTT PETERSON
Contact Address:	2411 ALASKAN WAY , PIER 67 , SEATTLE , WA, 98121 , US
Contact Phone No and Ext:	206-269-4566
Contact Email:	SPETERSON@EDGEWATERHOTEL.COM
Contact Country:	US
County Name:	KING
EPA Region:	10
Land Type:	Private
Receive Date:	20110210
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20110209
Handler Name:	EDGEWATER HOTEL
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Waste Code Details

Hazardous Waste Code:	D008
Waste Code Description:	LEAD

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20110209
Handler Name: EDGEWATER HOTEL
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Waste Code Details

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20100819
Handler Name: EDGEWATER HOTEL
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: WT02
Waste Code Description: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20110209
Handler Name: EDGEWATER HOTEL
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20110210
Handler Name: EDGEWATER HOTEL
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Street No:
Street 1: 950 FARMAN AVE N

Name:	WA STATE DEPT OF NATURAL RESOURCES	**Street 2:**	PIER 67
Date Became Current:		**City:**	ENUMCLAW
Date Ended Current:		**State:**	WA
Phone:	360-902-1000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98022
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	950 FARMAN AVE N
Name:	WA STATE DEPT OF NATURAL RESOURCES	**Street 2:**	PIER 67
Date Became Current:		**City:**	ENUMCLAW
Date Ended Current:		**State:**	WA
Phone:	360-902-1000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98022
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2411 ALASKAN WAY
Name:	EDGEWATER HOTEL E	**Street 2:**	PIER 67
Date Became Current:	19871231	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-7000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2411 ALASKAN WAY
Name:	EDGEWATER HOTEL ASSOCIATES LLC	**Street 2:**	PIER 67
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-7000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2411 ALASKAN WAY
Name:	EDGEWATER HOTEL E	**Street 2:**	PIER 67
Date Became Current:	19871231	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-7000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2411 ALASKAN WAY
Name:	EDGEWATER HOTEL ASSOCIATES LLC	**Street 2:**	PIER 67
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-7000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	2411 ALASKAN WAY
Name:	EDGEWATER HOTEL	**Street 2:**	PIER 67
Date Became Current:		**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-7000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2411 ALASKAN WAY
Name:	EDGEWATER HOTEL	**Street 2:**	PIER 67
Date Became Current:	19871231	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	206-728-7000	**Country:**	US
Source Type:	Notification	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2411 ALASKAN WAY
Name:	EDGEWATER HOTEL	**Street 2:**	PIER 67
Date Became Current:	19871231	**City:**	SEATTLE
Date Ended Current:		**State:**	WA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Phone:	206-728-7000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98121
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	State	**Street 1:**	950 FARMAN AVE N
Name:	WA STATE DEPT OF NATURAL RESOURCES	**Street 2:**	
Date Became Current:		**City:**	ENUMCLAW
Date Ended Current:		**State:**	WA
Phone:	360-902-1000	**Country:**	US
Source Type:	Implementer	**Zip Code:**	98022

Historical Handler Details

Receive Dt:	20110209
Generator Code Description:	Very Small Quantity Generator
Handler Name:	EDGEWATER HOTEL
Receive Dt:	20110209
Generator Code Description:	Not a Generator, Verified
Handler Name:	EDGEWATER HOTEL
Receive Dt:	20110209
Generator Code Description:	Not a Generator, Verified
Handler Name:	EDGEWATER HOTEL
Receive Dt:	20100819
Generator Code Description:	Very Small Quantity Generator
Handler Name:	EDGEWATER HOTEL

107	2 of 2	SSW	0.25 / 1,306.08	10.04 / -96	**Edgewater Hotel** **2411 Alaskan Way Pier 67** **Seattle WA 98121**	ALL SITES

Facility/Site ID:	16154
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAH000037063
Facility Alternate:	Edgewater Hotel
Interaction ID:	93854
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	17-Aug-2010
Interact End Dt:	
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	
Horizont 1:	NAD83	**GIS latitude:**	47.612644
Horizont 2:	Address	**GIS longitude:**	-122.352612

108	1 of 1	E	0.25 / 1,309.94	124.06 / 18	**2459 5TH AVE** **Seattle WA 98199**	UST SEATTLE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Permit No: 3-34092
Date Issued: 09/07/2000
Fill Material: No Fill
Date Decommissioned: 09/07/2000
Type Decommissioned: Abandonment in Place
Tank Size: 300
Tank Age: 35+
Tank Content: #2 HEATING FUEL

---

109 | **1 of 1** | **SE** | **0.26 / 1,350.86** | **110.92 / 5** | **Interbay Redevelopment Property**
15TH AVE W
SEATTLE WA 98119 | **ICR**

Cleanup Site ID: 492
Facility Site ID: 5497936
Site Status: No Further Action Required
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site: Yes
WRIA ID: 8
Is NFA Site: Yes
Responsible Unit: Northwest
Latitude: 47.613748999999999
Longitude: -122.34686000000001
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID:
VCP Prj No: NW1782
Activity Name: VCP Opinion on Property Cleanup
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2010-10-25
End Date: 2011-02-01
Legal Mechanism:
Performed by:
Project Manager: Myers, Dale R

Related ID:
VCP Prj No: NW1782
Activity Name: VCP Opinion on Cleanup Action Plan
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date:
End Date:
Legal Mechanism:
Performed by:
Project Manager: Myers, Dale R

Related ID:
VCP Prj No: NW1782
Activity Name: VCP Application
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2007-06-01
End Date:
Legal Mechanism:
Performed by:
Project Manager: Northwest Region

Related ID:
VCP Prj No: NW1782
Activity Name: VCP Termination
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date:
End Date: 2011-02-01
Legal Mechanism:
Performed by:
Project Manager: Myers, Dale R

Related ID:
VCP Prj No:
Activity Name: Site Status Changed to NFA
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date:
End Date: 2011-02-01
Legal Mechanism:
Performed by:
Project Manager: Myers, Dale R

Media Contaminants

Contaminant Type: Metals Priority Pollutants
Sediment:

Groundwater:	RB	**Sediment Desc.:**	
Groundwater Desc.:	Remediated-Below Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	B	**Bedrock Desc.:**	
Soil Desc.:	Below Cleanup Level	**County Name:**	King

Contaminant Type:	Metals - Other	**Sediment:**	
Groundwater:	B	**Sediment Desc.:**	
Groundwater Desc.:	Below Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	B	**Bedrock Desc.:**	
Soil Desc.:	Below Cleanup Level	**County Name:**	King

Contaminant Type:	Petroleum Products-Unspecified	**Sediment:**	
Groundwater:	B	**Sediment Desc.:**	
Groundwater Desc.:	Below Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RB	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Below Cleanup Level	**County Name:**	King

Contaminant Type:	Polynuclear Aromatic Hydrocarbons	**Sediment:**	
Groundwater:	B	**Sediment Desc.:**	
Groundwater Desc.:	Below Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	B	**Bedrock Desc.:**	
Soil Desc.:	Below Cleanup Level	**County Name:**	King

110	1 of 5	E	0.26 / 1,354.65	125.67 / 20	Seattle Fire Station 2 2334 4TH AVE SEATTLE WA 98121	CSCSL

Fac Site ID:	29958424	**Responsible Unit:**	Northwest
Cleanup Site ID:	8644	**Fac Site ID (OD):**	29958424
Site Status:	Awaiting Cleanup	**Cleanup SiteID(OD):**	8644
Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:		**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.345598
Latitude:	47.6161502513189	**Latitude (OD):**	47.61561
Longitude:	-122.3446753195		
Site Name:	Seattle Fire Station 2		
Address:	2334 4TH AVE		
City:	SEATTLE		
Zip Code:	98121		
Site Status (OD):	Awaiting Cleanup		
Site Name (OD):	SEATTLE FIRE STATION 2		
Address (OD):	2334 4TH AVE		
City (OD):	SEATTLE		
Zipcode (OD):	98121-1718		
Location (OD):	"" (47.61561, -122.345598)		
Alternate Site Names:			
Data Source(s):	Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Diesel
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

110	2 of 5	E	0.26 / 1,354.65	125.67 / 20	SEATTLE FIRE STATION 2 2334 4TH AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID: 29958424
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 7913
Facility Alternate:
Interaction ID: 36964
Interaction Status: A
Interac Status Desc: Active
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 20-Mar-2000
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: 7913
Facility Alternate:
Interaction ID: 36963
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: LUST
Interaction Desc: LUST Facility
Interact Start Dt: 28-Feb-2000
Interact End Dt: 13-May-2002
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6161502513
GIS longitude: -122.34467532

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
110	3 of 5	E	0.26 / 1,354.65	125.67 / 20	Seattle Fire Station 2 2334 4TH AVE SEATTLE WA 98121	LUST

Facility Site ID: 29958424
Cleanup Site ID: 8644
Responsible Unit: Northwest
Region: Northwest
Alternate Site Names:

County: King
Latitude: 47.6161502513189
Longitude: -122.3446753195

Tank Detail(s)

UST ID: 7913
LUST ID: 5489
LUST Status: LUST - Awaiting Cleanup

Status Date: 07/01/2011
Release Date: 04/02/1991

Contaminants Detail(s)

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels

Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels

Sediment:
Air:
Bedrock:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
110	4 of 5	E	0.26 / 1,354.65	125.67 / 20	SEATTLE FIRE STATION 2 2334 4TH AVE SEATTLE WA 98121-1718	ICR

Cleanup Site ID: 8644
Facility Site ID: 29958424
Site Status: Awaiting Cleanup
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site: Yes

WRIA ID: 8
Is NFA Site:
Responsible Unit: Northwest
Latitude: 47.615609999999997
Longitude: -122.345598
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID:
VCP Prj No:
Activity Name: Initial Investigation / Federal Preliminary Assessment
Activity Status: Completed
County Name: King
Applies to: CleanupSite
Applies to Description:

Start Date: 2011-08-08
End Date: 2011-08-08
Legal Mechanism:
Performed by: Ecology w/ Contractor
Project Manager: Olsen, Russ

Related ID: 5489
VCP Prj No:
Activity Name: LUST - Site Characterization Report
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Start Date:
End Date:
Legal Mechanism:
Performed by:
Project Manager:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Related ID:	5489	**Start Date:**	2000-02-28
VCP Prj No:		**End Date:**	2000-02-28
Activity Name:	LUST - Notification	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Bremer, Steve
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2013-02-28
Activity Name:	Early Notice Letter(s)	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Olsen, Russ
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2000-02-28
Activity Name:	Site Discovery/Release Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Media Contaminants

Contaminant Type:	Petroleum-Diesel	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

Contaminant Type:	Petroleum-Other	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
110	5 of 5	E	0.26 / 1,354.65	125.67 / 20	Seattle Fire Station 2 4th Ave 2334 4TH AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID:	7551
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	33612
Facility Alternate:	Seattle Fire Station 2 - 4th Avd
Interaction ID:	123364
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	UIC
Interaction Desc:	Underground Injection Control
Interact Start Dt:	14-Aug-2017
Interact End Dt:	
Ecology Program:	WATQUAL
Program Name Desc:	Water Quality Program
Prog Database Name:	UIC
Database Name Desc:	Underground Injection Control Program

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility Location Detail

Horizontal:	40ft	***Location Verified:***	
Horizont 1:	NAD83HARN	***GIS latitude:***	47.6161192796
Horizont 2:	Digital map or GIS	***GIS longitude:***	-122.344793449

---

111 ***1 of 5*** ***WNW*** ***0.26 / 1,367.35*** ***54.08 / -52*** ***Valco Graphics Inc Western Ave 3104 WESTERN AVE SEATTLE WA 98121*** ***CSCSL NFA***

Fac Site ID:	19521513	***Fac Site ID (OD):***	19521513
Cleanup Site ID:	5657	***Cleanup SiteID(OD):***	5657
Site Status:	NFA	***Site Status (OD):***	No Further Action
NFA Date:	07/26/2006	***Rank (OD):***	
Responsible Unit:	Northwest	***Has Env Coven (OD):***	
Has Insti Control:		***Respon Unit (OD):***	Northwest
Region:	Northwest	***Region (OD):***	Northwest
County:	King	***County (OD):***	King
Latitude:	47.61807	***Latitude (OD):***	47.61807
Longitude:	-122.35611	***Longitude (OD):***	-122.35611

NFA Reason: Voluntary Cleanup Program Review
Alternate Site Names: GRANGE H Q,WESTERN & DENNY CONDOMINIUMS
Location (OD): ""
(47.61807, -122.35611)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

NFA Contaminants Detail(s)

Contaminant Name:	Benzene
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Petroleum-Gasoline
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Benzene
Contaminant Media:	Soil
Contaminant Status:	Confirmed Above Cleanup Levels

Contaminant:	Petroleum-Gasoline
Contaminant Media:	Soil
Contaminant Status:	Confirmed Above Cleanup Levels

---

111 ***2 of 5*** ***WNW*** ***0.26 / 1,367.35*** ***54.08 / -52*** ***Valco Graphics Inc Western Ave 3104 WESTERN AVE SEATTLE WA 98121*** ***ALL SITES***

Facility/Site ID: 19521513
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility/Site Interaction

Program ID: 619210
Facility Alternate:
Interaction ID: 31136
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 02-Feb-2006
Interact End Dt: 02-Feb-2006
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: NW1583
Facility Alternate: Valco Graphics Inc Western Ave
Interaction ID: 31135
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 07-Feb-2006
Interact End Dt: 26-Jul-2006
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: WAD009249368
Facility Alternate:
Interaction ID: 31134
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 15-Aug-1989
Interact End Dt: 12-Jun-1991
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: 619210
Facility Alternate:
Interaction ID: 31137
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: LUST
Interaction Desc: LUST Facility
Interact Start Dt: 02-Feb-2006
Interact End Dt: 26-Jul-2006
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.61807
GIS longitude: -122.35611

111	*3 of 5*	*WNW*	*0.26 / 1,367.35*	*54.08 / -52*	*Valco Graphics Inc Western Ave 3104 WESTERN AVE*	*ICR*

SEATTLE WA 98121

Cleanup Site ID:	5657	***WRIA ID:***	8
Facility Site ID:	19521513	***Is NFA Site:***	Yes
Site Status:	No Further Action Required	***Responsible Unit:***	Northwest
Statute:	MTCA	***Latitude:***	47.618070000000003
Rank:		***Longitude:***	-122.35611
Rank Description:		***Legislative District:***	36
Has Env Covenant:		***Congr District:***	7
Is Brownfiled Site:		***County Name:***	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:	6152	***Start Date:***	2006-02-02
VCP Prj No:		***End Date:***	2006-02-02
Activity Name:	LUST - Notification	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		***Start Date:***	
VCP Prj No:	NW1583	***End Date:***	2006-07-26
Activity Name:	VCP Opinion on Cleanup Action	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Maurer, Christopher
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:	6152	***Start Date:***	2006-01-18
VCP Prj No:		***End Date:***	2006-02-02
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	2006-07-26
Activity Name:	Site Status Changed to NFA	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		***Start Date:***	
VCP Prj No:	NW1583	***End Date:***	2006-07-26
Activity Name:	VCP Termination	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	2006-02-07
VCP Prj No:	NW1583	***End Date:***	
Activity Name:	VCP Application	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Northwest Region
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Media Contaminants

Contaminant Type:	Benzene	***Sediment:***	
Groundwater:		***Sediment Desc.:***	

Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King
Contaminant Type:	Petroleum-Gasoline	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
111	4 of 5	WNW	0.26 / 1,367.35	54.08 / -52	Valco Graphics Inc Western Ave 3104 WESTERN AVE SEATTLE WA 98121	VCP

Facility Site ID:	19521513	**County:**	King
Cleanup Site ID:	5657	**Latitude:**	47.61807
Region:	Northwest	**Longitude:**	-122.35611
Alternate Site Names:	GRANGE H Q,WESTERN & DENNY CONDOMINIUMS		
Data Source(s):	No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State		

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status:	NFA
NFA Date:	07/26/2006
Responsible Unit:	Northwest
Has Inst Control:	
NFA Reason:	Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name:	Petroleum-Gasoline	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Confirmed Above Cleanup Levels		
Contaminant Name:	Benzene	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Confirmed Above Cleanup Levels		

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status:	No Further Action
Site Rank:	
Has Inst Control:	
Current VCP:	
Past VCP:	Yes
Responsible Unit:	Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name:	Benzene	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Confirmed Above Cleanup Levels		
Contaminant Name:	Petroleum-Gasoline	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Soil: Confirmed Above Cleanup Levels

---

111 *5 of 5* | *WNW* | *0.26 / 1,367.35* | *54.08 / -52* | *Valco Graphics Inc Western Ave*
3104 WESTERN AVE
SEATTLE WA 98121 | *LUST*

Facility Site ID: 19521513
Cleanup Site ID: 5657
Responsible Unit: Northwest
Region: Northwest
Alternate Site Names: GRANGE H Q,WESTERN & DENNY CONDOMINIUMS
County: King
Latitude: 47.61807
Longitude: -122.35611

Tank Detail(s)

UST ID: 619210
LUST ID: 6152
LUST Status: LUST - NFA
Status Date: 07/26/2006
Release Date: 02/02/2006

Contaminants Detail(s)

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

---

112 *1 of 4* | *ESE* | *0.26 / 1,379.92* | *123.33 / 18* | *Second & Bell Building LLC*
2306 2ND AVE
SEATTLE WA 98121 | *CSCSL*

Fac Site ID: 967942
Cleanup Site ID: 1571
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.614142
Longitude: -122.345904
Site Name: Second & Bell Building LLC
Address: 2306 2ND AVE
City: SEATTLE
Zip Code: 98121
Site Status (OD): Cleanup Started
Site Name (OD): Second & Bell Building LLC
Address (OD): 2306 2ND AVE
City (OD): SEATTLE
Zipcode (OD): 98121
Location (OD): ""
(47.614142, -122.345904)
Alternate Site Names: Second & Bell Building LLC (Off-Property),Second & Bell Building LLC (Property NFA)
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)
Responsible Unit: Northwest
Fac Site ID (OD): 967942
Cleanup SiteID(OD): 1571
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.345904
Latitude (OD): 47.614142

Contaminants Detail(s)

Contaminant Name: Metals Priority Pollutants
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Arsenic
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Metals - Other
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Remediated-Below
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Arsenic
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals - Other
Contaminant Media: Groundwater
Contaminant Status: Below Cleanup Levels

Contaminant: Metals Priority Pollutants
Contaminant Media: Groundwater
Contaminant Status: Below Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant Status: Remediated-Below

Contaminant: Metals - Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Arsenic
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals Priority Pollutants
Contaminant Media: Soil
Contaminant Status: Remediated-Below

112	*2 of 4*	*ESE*	*0.26 / 1,379.92*	*123.33 / 18*	***Second & Bell Building LLC*** ***2306 2ND AVE*** ***SEATTLE WA 98121***	***ALL SITES***

Facility/Site ID: 967942
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: Second & Bell Building LLC (Off-Property)
Interaction ID: 128282
Interaction Status: A
Interac Status Desc: Active
Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 12-Dec-2012
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: WAH000034368
Facility Alternate: Second & Bell Building LLC
Interaction ID: 97504
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 22-Aug-2011
Interact End Dt: 31-Dec-2012
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: NW2263
Facility Alternate: Second & Bell Building LLC
Interaction ID: 91727
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 17-Mar-2010
Interact End Dt: 12-Dec-2012
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: WAH000034368

Facility Alternate:	SECOND & BELL BUILDING LLC
Interaction ID:	7579
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	12-Feb-2009
Interact End Dt:	31-Dec-2009
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	
Horizont 1:	NAD83	**GIS latitude:**	47.614142
Horizont 2:	Address	**GIS longitude:**	-122.345904

112	3 of 4	ESE	0.26 / 1,379.92	123.33 / 18	**Second & Bell Building LLC** **2306 2ND AVE** **SEATTLE WA 98121**	ICR

Cleanup Site ID:	1571	**WRIA ID:**	8
Facility Site ID:	967942	**Is NFA Site:**	
Site Status:	Cleanup Started	**Responsible Unit:**	Northwest
Statute:	MTCA	**Latitude:**	47.614142000000001
Rank:		**Longitude:**	-122.345904
Rank Description:		**Legislative District:**	36
Has Env Covenant:		**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		**Start Date:**	2010-07-19
VCP Prj No:	NW2263	**End Date:**	2010-07-29
Activity Name:	VCP Opinion on Property Cleanup Plan	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Swackhamer, Bob
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	2011-04-11
VCP Prj No:	NW2263	**End Date:**	2011-06-09
Activity Name:	VCP Opinion on Site Cleanup Plan	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Carrosino, Glynis
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	2010-10-04
VCP Prj No:	NW2263	**End Date:**	2010-10-12
Activity Name:	VCP Opinion on Site Cleanup Plan	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Carrosino, Glynis
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	
VCP Prj No:	NW2263	**End Date:**	2010-06-14
Activity Name:	VCP Opinion on Interim Action	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Swackhamer, Bob
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	2010-09-01
VCP Prj No:	NW2263	***End Date:***	
Activity Name:	VCP Receipt of Plan or Report	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Carrosino, Glynis
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	
VCP Prj No:	NW2263	***End Date:***	2012-12-12
Activity Name:	VCP Termination	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Pederson, Carrie
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	2011-06-09
VCP Prj No:	NW2263	***End Date:***	2012-12-12
Activity Name:	VCP Opinion on Property Cleanup	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Carrosino, Glynis
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	2010-03-17
VCP Prj No:	NW2263	***End Date:***	
Activity Name:	VCP Application	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Northwest Region
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Media Contaminants

Contaminant Type:	Metals Priority Pollutants	***Sediment:***	
Groundwater:	B	***Sediment Desc.:***	
Groundwater Desc.:	Below Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	RB	***Bedrock Desc.:***	
Soil Desc.:	Remediated-Below Cleanup Level	***County Name:***	King

Contaminant Type:	Petroleum Products-Unspecified	***Sediment:***	
Groundwater:	RB	***Sediment Desc.:***	
Groundwater Desc.:	Remediated-Below Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	RB	***Bedrock Desc.:***	
Soil Desc.:	Remediated-Below Cleanup Level	***County Name:***	King

Contaminant Type:	Petroleum-Other	***Sediment:***	
Groundwater:	C	***Sediment Desc.:***	
Groundwater Desc.:	Confirmed Above Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

Contaminant Type:	Arsenic	***Sediment:***	
Groundwater:	C	***Sediment Desc.:***	
Groundwater Desc.:	Confirmed Above Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

Contaminant Type:	Metals - Other	***Sediment:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Groundwater:	B	**Sediment Desc.:**	
Groundwater Desc.:	Below Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

112	4 of 4	ESE	0.26 / 1,379.92	123.33 / 18	**Second & Bell Building LLC** **2306 2ND AVE** **SEATTLE WA 98121**	VCP

Facility Site ID:	967942	**County:**	King
Cleanup Site ID:	1571	**Latitude:**	47.614142
Region:	Northwest	**Longitude:**	-122.345904

Alternate Site Names: Second & Bell Building LLC (Off-Property),Second & Bell Building LLC (Property NFA)
Data Source(s): Confirmed and Suspected Contaminated Sites; Confirmed and Suspected Contaminated Sites; All Cleanup Sites in Washington State

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List

Site Status:	Cleanup Started
Current VCP:	
Past VCP:	Yes
Site Rank:	
Responsible Unit:	Northwest
Has Inst Control:	

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List - Contaminants

Contaminant Name:	Arsenic	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Below		
Contaminant Name:	Petroleum Products-Unspecified	**Sediment:**	
Groundwater:	Remediated-Below	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Below		
Contaminant Name:	Petroleum-Other	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Confirmed Above Cleanup Levels		
Contaminant Name:	Metals - Other	**Sediment:**	
Groundwater:	Below Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Confirmed Above Cleanup Levels		
Contaminant Name:	Metals Priority Pollutants	**Sediment:**	
Groundwater:	Below Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Below		

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status:	Cleanup Started
Site Rank:	
Has Inst Control:	
Current VCP:	
Past VCP:	Yes
Responsible Unit:	Northwest

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name:	Metals - Other	***Sediment:***	
Groundwater:	Below Cleanup Levels	***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		
Contaminant Name:	Petroleum Products-Unspecified	***Sediment:***	
Groundwater:	Remediated-Below	***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Remediated-Below		
Contaminant Name:	Petroleum-Other	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		
Contaminant Name:	Arsenic	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Remediated-Below		
Contaminant Name:	Metals Priority Pollutants	***Sediment:***	
Groundwater:	Below Cleanup Levels	***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Remediated-Below		

113	***1 of 1***	***E***	***0.26 / 1,391.92***	***126.23 / 20***	***Seattle Fire Dept Sta 2318 4TH AVE SEATTLE WA 98121***	***ALL SITES***

Facility/Site ID:	43164951
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAD988492013
Facility Alternate:	
Interaction ID:	44267
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	03-Sep-1991
Interact End Dt:	31-Dec-1991
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	N
Horizont 1:	NAD83	***GIS latitude:***	47.61575
Horizont 2:	Unknown	***GIS longitude:***	-122.34426

114	***1 of 6***	***E***	***0.27 / 1,408.52***	***123.44 / 18***	***SEATTLE POST INTELLIGENCER 521 WALL ST SEATTLE WA 98121***	***CERCLIS***

Site ID:	1000576	***RNPL Status Code:***	N
Site EPA ID:	WAD001533538	***NPL Status:***	Not on the NPL
Site Street Address 2:		***RFED Facility Code:***	N
Site County Name:	KING	***RFED Facility Desc:***	Not a Federal Facility

Site FIPS Code:	53033	**USGS Hydro Unit No.:**	17110019
Region Code:	10	**Site Cong. Dist. Code:**	07
Site SMSA No.:	7600	**ROT Desc:**	Other
Site Prim. Latitude:	47D37M04S	**FR NPL Update No.:**	
Site Prim. Longitude:	122D20M35S	**RFRA Code:**	
Lat Long Source:			

RNON NPL Status Desc: NFRAP-Site does not qualify for the NPL based on existing information

CERCLIS Assess History

OU ID:	00	**RALT Short Name:**	EPA Fund
Act Code ID:	001	**Act Start Date:**	
RAT Code:	DS	**Act Complete Date:**	11/1/1979 00:00:00
RAT Short Name:	DISCVRY	**AGT Order No.:**	10
RAT Name:	DISCOVERY	**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:	00	**SH Complete Date:**	
RFBS Code:		**SH Lead:**	
SPA Code:	13		

RAT Def: The process by which a potential hazardous waste site is brought to the attention of the EPA. The process can occur through the use of several mechanisms such as a phone call or referral by another government agency.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	00	**RALT Short Name:**	State (Fund)
Act Code ID:	001	**Act Start Date:**	9/24/1984 00:00:00
RAT Code:	PA	**Act Complete Date:**	12/3/1984 00:00:00
RAT Short Name:	PA	**AGT Order No.:**	130
RAT Name:	PRELIMINARY ASSESSMENT	**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:	00	**SH Complete Date:**	
RFBS Code:	P	**SH Lead:**	
SPA Code:	13		

RAT Def: Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	00	**RALT Short Name:**	
Act Code ID:		**Act Start Date:**	
RAT Code:		**Act Complete Date:**	
RAT Short Name:		**AGT Order No.:**	0
RAT Name:		**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:		**SH Seq:**	
RAT Level:		**SH Start Date:**	
RAT DEF OU:		**SH Complete Date:**	
RFBS Code:		**SH Lead:**	
SPA Code:			
RAT Def:			

Site Desc: No description available
.
Site Alias: No alias data available

CERCLIS Assess History

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

OU ID:	00	**RALT Short Name:**	EPA In-House
Act Code ID:	001	**Act Start Date:**	
RAT Code:	VS	**Act Complete Date:**	12/3/1984 00:00:00
RAT Short Name:	ARCH SITE	**AGT Order No.:**	1500
RAT Name:	ARCHIVE SITE	**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:	00	**SH Complete Date:**	
RFBS Code:		**SH Lead:**	
SPA Code:	13		
RAT Def:	The decision is made that no further activity is planned at the site.		
Site Desc:			
Site Alias:			

114	2 of 6	E	0.27 / 1,408.52	123.44 / 18	**SEATTLE POST INTELLIGENCER** **521 WALL ST** **SEATTLE WA 98121**	**CERCLIS NFRAP**

Site ID:	1000576	**Site FIPS Code:**	53033
Site EPA ID:	WAD001533538	**Region Code:**	10
Site Parent ID:		**Site Cong. Dist. Code:**	7
Site County Name:	KING	**Federal Facility:**	
Parent Site Name:			

CERCLIS-NFRAP Assess History

OU ID:	0	**Act Start Date:**	9/24/1984
Act Code ID:	1	**Act Complete Date:**	12/3/1984
RAT Code:	PA	**AGT Order No.:**	130
RAT Short Name:	PA	**SH OU:**	
RAT Name:	PRELIMINARY ASSESSMENT	**SH Code:**	
RAT Hist. Only Flag:		**SH Seq:**	
RAT NSI Indicator:	B	**SH Start Date:**	
RAT Level:	1	**SH Complete Date:**	
RAT DEF OU:	00	**SH Lead:**	
RFBS Code:	P	**SH Qual:**	
SPA Code:	13	**RAQ Act. Qual Short:**	NFRAP
RALT Short Name:	State (Fund)	**RNPL Status Code:**	N
RAT Def:	Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.		
RNON NPL Status Desc:	NFRAP-Site does not qualify for the NPL based on existing information		

CERCLIS-NFRAP Assess History

OU ID:	0	**Act Start Date:**	
Act Code ID:	1	**Act Complete Date:**	11/1/1979
RAT Code:	DS	**AGT Order No.:**	10
RAT Short Name:	DISCVRY	**SH OU:**	
RAT Name:	DISCOVERY	**SH Code:**	
RAT Hist. Only Flag:		**SH Seq:**	
RAT NSI Indicator:	B	**SH Start Date:**	
RAT Level:	1	**SH Complete Date:**	
RAT DEF OU:	00	**SH Lead:**	
RFBS Code:		**SH Qual:**	
SPA Code:	13	**RAQ Act. Qual Short:**	
RALT Short Name:	EPA Fund	**RNPL Status Code:**	N
RAT Def:	The process by which a potential hazardous waste site is brought to the attention of the EPA. The process can occur through the use of several mechanisms such as a phone call or referral by another government agency.		
RNON NPL Status Desc:	NFRAP-Site does not qualify for the NPL based on existing information		

CERCLIS-NFRAP Assess History

OU ID:	0	**Act Start Date:**	
Act Code ID:	1	**Act Complete Date:**	12/3/1984

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

RAT Code:	VS	**AGT Order No.:**	1500
RAT Short Name:	ARCH SITE	**SH OU:**	
RAT Name:	ARCHIVE SITE	**SH Code:**	
RAT Hist. Only Flag:		**SH Seq:**	
RAT NSI Indicator:	B	**SH Start Date:**	
RAT Level:	1	**SH Complete Date:**	
RAT DEF OU:	00	**SH Lead:**	
RFBS Code:		**SH Qual:**	
SPA Code:	13	**RAQ Act. Qual Short:**	
RALT Short Name:	EPA In-House	**RNPL Status Code:**	N
RAT Def:	The decision is made that no further activity is planned at the site.		
RNON NPL Status Desc:	NFRAP-Site does not qualify for the NPL based on existing information		

---

114 | ***3 of 6*** | ***E*** | ***0.27 / 1,408.52*** | ***123.44 / 18*** | ***Seattle Post Intelligencer
521 WALL ST
SEATTLE WA 98121*** | ***CSCSL NFA***

Fac Site ID:	2173	**Fac Site ID (OD):**	2173
Cleanup Site ID:	1815	**Cleanup SiteID(OD):**	1815
Site Status:	NFA	**Site Status (OD):**	No Further Action
NFA Date:	09/13/1995	**Rank (OD):**	
Responsible Unit:	Northwest	**Has Env Coven (OD):**	
Has Insti Control:		**Respon Unit (OD):**	Northwest
Region:	Northwest	**Region (OD):**	Northwest
County:	King	**County (OD):**	King
Latitude:	47.6174408685715	**Latitude (OD):**	47.61766
Longitude:	-122.34461574491	**Longitude (OD):**	-122.34512
NFA Reason:	Cleaned up under Prior Authority		
Alternate Site Names:			
Location (OD):	"" (47.61766, -122.34512)		
Data Source(s):	Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants		

NFA Contaminants Detail(s)

Contaminant Name:	Halogenated Organics
Groundwater:	Suspected
Surfacewater:	
Soil:	
Sediment:	
Air:	
Bedrock:	

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Halogenated Organics
Contaminant Media:	Groundwater
Contaminant Status:	Suspected

---

114 | ***4 of 6*** | ***E*** | ***0.27 / 1,408.52*** | ***123.44 / 18*** | ***SEATTLE POST INTELLIGENCER
521 WALL ST
SEATTLE WA 98121*** | ***ALL SITES***

Facility/Site ID:	2173
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAD001533538
Facility Alternate:	
Interaction ID:	3773
Interaction Status:	I

Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	05-May-1986
Interact End Dt:	09-Feb-1988
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Program ID:	
Facility Alternate:	SEATTLE POST INTELLIGENCER
Interaction ID:	3774
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	SCS
Interaction Desc:	State Cleanup Site
Interact Start Dt:	01-Mar-1988
Interact End Dt:	13-Sep-1995
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Facility Location Detail

Horizontal:	40ft	**Location Verified:**	
Horizont 1:	NAD83HARN	**GIS latitude:**	47.6174408686
Horizont 2:	Digital map or GIS	**GIS longitude:**	-122.344615745

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
114	5 of 6	E	0.27 / 1,408.52	123.44 / 18	SEATTLE POST INTELLIGENCER 521 WALL ST SEATTLE WA 98121	ICR

Cleanup Site ID:	1815	**WRIA ID:**	8
Facility Site ID:	2173	**Is NFA Site:**	Yes
Site Status:	No Further Action Required	**Responsible Unit:**	Northwest
Statute:	MTCA	**Latitude:**	47.617660000000001
Rank:		**Longitude:**	-122.34511999999999
Rank Description:		**Legislative District:**	36
Has Env Covenant:		**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	1995-09-13
Activity Name:	Site Status Changed to NFA	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	1988-03-01
Activity Name:	Site Discovery/Release Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Media Contaminants

Contaminant Type:	Halogenated Organics	**Sediment:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Groundwater:	S	**Sediment Desc.:**	
Groundwater Desc.:	Suspected	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:		**Bedrock Desc.:**	
Soil Desc.:		**County Name:**	King

---

114 | ***6 of 6*** | ***E*** | ***0.27 / 1,408.52*** | ***123.44 / 18*** | ***SEATTLE POST INTELLIGENCER 521 WALL ST SEATTLE WA 98121*** | ***SEMS ARCHIVE***

Site ID:	1000576	**FIPS Code:**	53033
EPA ID:	WAD001533538	**Cong District:**	07
Superfund Alt Agmt:	No	**Region:**	10
Federal Facility:	No	**County:**	KING
FF Docket:	No		
NPL:	Not on the NPL		
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information		

Action Information

Operable Units:	00	**Start Actual:**	24-Sep-1984 05:00:00
Action Code:	PA	**Finish Actual:**	03-Dec-1984 06:00:00
Action Name:	PA	**Qual:**	N
SEQ:	1	**Curr Action Lead:**	St Perf
Operable Units:	00	**Start Actual:**	
Action Code:	VS	**Finish Actual:**	03-Dec-1984 06:00:00
Action Name:	ARCH SITE	**Qual:**	
SEQ:	1	**Curr Action Lead:**	EPA Perf In-Hse
Operable Units:	00	**Start Actual:**	01-Nov-1979 05:00:00
Action Code:	DS	**Finish Actual:**	01-Nov-1979 05:00:00
Action Name:	DISCVRY	**Qual:**	
SEQ:	1	**Curr Action Lead:**	EPA Perf

---

115 | ***1 of 3*** | ***WNW*** | ***0.27 / 1,410.34*** | ***55.98 / -50*** | ***AIRBORNE EXPRESS 3101 WESTERN AVE SEATTLE WA 98121*** | ***ALL SITES***

Facility/Site ID:	27428838
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	4608
Facility Alternate:	MARTIN SELIG REAL ESTATE
Interaction ID:	35507
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	UST
Interaction Desc:	Underground Storage Tank
Interact Start Dt:	20-Mar-2000
Interact End Dt:	
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	UST
Database Name Desc:	Underground Storage Tanks

Facility Location Detail

Horizontal:	40ft	**Location Verified:**	N
Horizont 1:	NAD83	**GIS latitude:**	47.61791

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Horizont 2: Address
GIS longitude: -122.357428

---

115 *2 of 3* **WNW** *0.27 / 1,410.34* *55.98 / -50*

3101 WESTERN
3101 WESTERN AVE
SEATTLE WA 98121

PCB

Site ID:	WAW000200600	**Mail Address 1:**	1000-2ND AVE
Receive Date:		**Mail Address 2:**	SUITE 1800
Generator:	Yes	**Mail Street No:**	
Storer:	No	**Mail City:**	SEATTLE
Transporter:	No	**Mail State:**	WA
Disposer:	No	**Mail Zip:**	98104
Research:	No	**Mail Country:**	US
Smelter:	No	**Contact Name:**	PAUL SCHMIDT
Cert Title:		**Contact Title:**	BUILDING MANAGER
Cert Date:	1/28/2016 12:00:00 AM	**Contact Phone:**	206-386-5100
Cert Name:		**Contact Phone Ext:**	
Location Country:	US	**Contact Email:**	
State Name:	WASHINGTON	**Owner Name:**	SELIG HOLDINGS COMPANY LLC
Region:	10		

---

115 *3 of 3* **WNW** *0.27 / 1,410.34* *55.98 / -50*

Invitae Seattle
3101 Western Ave Ste 100
Seattle WA 98121

ALL SITES

Facility/Site ID: 34085
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAH000058060
Facility Alternate:	Invitae Seattle
Interaction ID:	135788
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	14-Oct-2020
Interact End Dt:	
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	
Horizont 1:	NAD83	**GIS latitude:**	47.6177
Horizont 2:	Address	**GIS longitude:**	-122.35671

---

116 *1 of 5* **SSE** *0.27 / 1,411.12* *45.64 / -60*

55 Battery LLC
2334 ELLIOTT AVE / 55 BATTERY ST
SEATTLE WA 98121

CSCSL NFA

Fac Site ID:	16772747	**Fac Site ID (OD):**	16772747
Cleanup Site ID:	12148	**Cleanup SiteID(OD):**	12148
Site Status:	NFA	**Site Status (OD):**	No Further Action
NFA Date:	12/31/2013	**Rank (OD):**	
Responsible Unit:	Northwest	**Has Env Coven (OD):**	
Has Insti Control:		**Respon Unit (OD):**	Northwest
Region:	Northwest	**Region (OD):**	Northwest

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

County:	King	**County (OD):**	King
Latitude:	47.6128193090302	**Latitude (OD):**	47.612819
Longitude:	-122.348924254945	**Longitude (OD):**	-122.348924

NFA Reason: Voluntary Cleanup Program Review
Alternate Site Names: 55 Battery LLC Property,Art House,Pinnacle Productions International Inc
Location (OD): ""
(47.612819, -122.348924)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

NFA Contaminants Detail(s)

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Remediated-Below

116	2 of 5	SSE	0.27 / 1,411.12	45.64 / -60	Pinnacle Productions International Inc 2334 ELLIOTT AVE / 55 BATTERY ST	ALL SITES

Facility/Site ID: 16772747
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 619948
Facility Alternate: Pinnacle Productions International Inc
Interaction ID: 106134
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 19-Feb-2013
Interact End Dt: 04-Jun-2013
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: 619948
Facility Alternate: 55 Battery LLC
Interaction ID: 107803
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: LUST
Interaction Desc: LUST Facility
Interact Start Dt: 04-Jun-2013
Interact End Dt: 31-Dec-2013
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: WAD988479960
Facility Alternate:
Interaction ID: 29627
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 01-Nov-1990
Interact End Dt: 31-Dec-2000
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: NW2743
Facility Alternate: 55 Battery LLC
Interaction ID: 105086
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 04-Jun-2013
Interact End Dt: 31-Dec-2013
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Horizontal:	40ft	**Location Verified:**	
Horizont 1:	NAD83HARN	**GIS latitude:**	47.612819309
Horizont 2:	Digital map or GIS	**GIS longitude:**	-122.348924255

116 **3 of 5** **SSE** **0.27 / 1,411.12** **45.64 / -60**

55 Battery LLC
2334 ELLIOTT AVE / 55 BATTERY ST
SEATTLE WA 98121

ICR

Cleanup Site ID:	12148	**WRIA ID:**	8
Facility Site ID:	16772747	**Is NFA Site:**	Yes
Site Status:	No Further Action Required	**Responsible Unit:**	Northwest
Statute:	MTCA	**Latitude:**	47.612819309030243
Rank:		**Longitude:**	-122.34892425494471
Rank Description:		**Legislative District:**	36
Has Env Covenant:		**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		**Start Date:**	2013-06-05
VCP Prj No:	NW2743	**End Date:**	
Activity Name:	VCP Application	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Pederson, Carrie
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	
VCP Prj No:	NW2743	**End Date:**	2013-12-31
Activity Name:	VCP Termination	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Fernandez, Sonia
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:	6719	**Start Date:**	2013-11-12
VCP Prj No:		**End Date:**	2013-11-12
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	6719	**Start Date:**	2013-06-03
VCP Prj No:		**End Date:**	2013-06-04
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		**Start Date:**	2013-01-29
VCP Prj No:		**End Date:**	
Activity Name:	Initial Investigation / Federal Preliminary Assessment	**Legal Mechanism:**	
Activity Status:	Canceled	**Performed by:**	
County Name:	King	**Project Manager:**	Imke, Drew
Applies to:	CleanupSite		
Applies to Description:			

Related ID:	6719	**Start Date:**	2013-03-12
VCP Prj No:		**End Date:**	2013-04-12
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	

Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: | ***Start Date:*** 2013-04-12
VCP Prj No: NW2743 | ***End Date:***
Activity Name: VCP Receipt of Plan or Report | ***Legal Mechanism:***
Activity Status: Completed | ***Performed by:***
County Name: King | ***Project Manager:*** Pederson, Carrie
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Related ID: | ***Start Date:***
VCP Prj No: | ***End Date:*** 2013-01-29
Activity Name: Site Discovery/Release Report Received | ***Legal Mechanism:***
Activity Status: | ***Performed by:***
County Name: King | ***Project Manager:*** Northwest Region
Applies to: CleanupSite
Applies to Description:

Related ID: 6719 | ***Start Date:*** 2013-01-29
VCP Prj No: | ***End Date:*** 2013-01-29
Activity Name: LUST - Notification | ***Legal Mechanism:***
Activity Status: | ***Performed by:***
County Name: King | ***Project Manager:*** Northwest Region
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: | ***Start Date:***
VCP Prj No: | ***End Date:*** 2013-12-31
Activity Name: Site Status Changed to NFA | ***Legal Mechanism:***
Activity Status: | ***Performed by:***
County Name: King | ***Project Manager:*** Guenther, John
Applies to: CleanupSite
Applies to Description:

Related ID: | ***Start Date:*** 2013-06-04
VCP Prj No: NW2743 | ***End Date:*** 2013-12-31
Activity Name: VCP Opinion on Site Cleanup | ***Legal Mechanism:***
Activity Status: Completed | ***Performed by:***
County Name: King | ***Project Manager:*** Guenther, John
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Media Contaminants

Contaminant Type: Petroleum-Gasoline | ***Sediment:***
Groundwater: | ***Sediment Desc.:***
Groundwater Desc.: | ***Air:***
Surface Water: | ***Air Desc.:***
Surfacewater Desc.: | ***Bedrock:***
Soil: RB | ***Bedrock Desc.:***
Soil Desc.: Remediated-Below Cleanup Level | ***County Name:*** King

Contaminant Type: Petroleum-Diesel | ***Sediment:***
Groundwater: | ***Sediment Desc.:***
Groundwater Desc.: | ***Air:***
Surface Water: | ***Air Desc.:***
Surfacewater Desc.: | ***Bedrock:***
Soil: RB | ***Bedrock Desc.:***
Soil Desc.: Remediated-Below Cleanup Level | ***County Name:*** King

Contaminant Type: Petroleum-Other | ***Sediment:***
Groundwater: | ***Sediment Desc.:***
Groundwater Desc.: | ***Air:***
Surface Water: | ***Air Desc.:***
Surfacewater Desc.: | ***Bedrock:***
Soil: RB | ***Bedrock Desc.:***
Soil Desc.: Remediated-Below Cleanup Level | ***County Name:*** King

Contaminant Type: Benzene
Groundwater:
Groundwater Desc.:
Surface Water:
Surfacewater Desc.:
Soil: RB
Soil Desc.: Remediated-Below Cleanup Level
Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

---

116 | **4 of 5** | **SSE** | **0.27 / 1,411.12** | **45.64 / -60** | **55 Battery LLC**
2334 ELLIOTT AVE / 55 BATTERY ST
SEATTLE WA 98121 | **VCP**

Facility Site ID: 16772747
Cleanup Site ID: 12148
Region: Northwest
Alternate Site Names: 55 Battery LLC Property,Art House,Pinnacle Productions International Inc
Data Source(s): No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State
County: King
Latitude: 47.6128193090302
Longitude: -122.348924254945

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status: NFA
NFA Date: 12/31/2013
Responsible Unit: Northwest
Has Inst Control:
NFA Reason: Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: No Further Action
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Petroleum-Other
Groundwater:
Sediment:
Air:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Surfacewater: **Bedrock:**
Soil: Remediated-Below

Contaminant Name: Benzene **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Remediated-Below

Contaminant Name: Petroleum-Diesel **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Remediated-Below

Contaminant Name: Petroleum-Gasoline **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Remediated-Below

116	5 of 5	SSE	0.27 / 1,411.12	45.64 / -60	55 Battery LLC 2334 ELLIOTT AVE / 55 BATTERY ST SEATTLE WA 98121	LUST

Facility Site ID: 16772747 **County:** King
Cleanup Site ID: 12148 **Latitude:** 47.6128193090302
Responsible Unit: Northwest **Longitude:** -122.348924254945
Region: Northwest
Alternate Site Names: 55 Battery LLC Property,Art House,Pinnacle Productions International Inc

Tank Detail(s)

UST ID: 619948 **Status Date:** 12/31/2013
LUST ID: 6719 **Release Date:** 01/29/2013
LUST Status: LUST - NFA

Contaminants Detail(s)

Contaminant Name: Petroleum-Diesel **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Remediated-Below

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Remediated-Below

Contaminants Detail(s)

Contaminant Name: Petroleum-Other **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Remediated-Below

Contaminants Detail(s)

Contaminant Name: Benzene **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Remediated-Below

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
117	1 of 5	ENE	0.27 / 1,415.34	123.34 / 18	BRE Properties Inc 552 DENNY WAY & 553 JOHN ST SEATTLE WA 98109	CSCSL NFA

Fac Site ID:	609006	**Fac Site ID (OD):**	609006
Cleanup Site ID:	802	**Cleanup SiteID(OD):**	802
Site Status:	NFA	**Site Status (OD):**	No Further Action
NFA Date:	04/29/2008	**Rank (OD):**	
Responsible Unit:	Northwest	**Has Env Coven (OD):**	
Has Insti Control:		**Respon Unit (OD):**	Northwest
Region:	Northwest	**Region (OD):**	Northwest
County:	King	**County (OD):**	King
Latitude:	47.6191636790253	**Latitude (OD):**	47.619164
Longitude:	-122.345973898797	**Longitude (OD):**	-122.345974

NFA Reason: Voluntary Cleanup Program Review
Alternate Site Names: TEAMSTERS UNION PROPERTY
Location (OD): ""
(47.619164, -122.345974)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

NFA Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
117	2 of 5	ENE	0.27 / 1,415.34	123.34 / 18	BRE Properties Inc 552 DENNY WAY & 553 JOHN ST SEATTLE WA 98109	ALL SITES

Facility/Site ID: 609006
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: NW1894
Facility Alternate: BRE Properties Inc
Interaction ID: 7008
Interaction Status: I

Interac Status Desc:	Inactive
Interaction Type:	VOLCLNST
Interaction Desc:	Voluntary Cleanup Sites
Interact Start Dt:	13-Feb-2008
Interact End Dt:	29-Apr-2008
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System
Program ID:	WAH000029059
Facility Alternate:	
Interaction ID:	7007
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	20-Jun-2006
Interact End Dt:	31-Dec-2008
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	40ft	***Location Verified:***	
Horizont 1:	NAD83HARN	***GIS latitude:***	47.619163679
Horizont 2:	Digital map or GIS	***GIS longitude:***	-122.345973899

117 | ***3 of 5*** | ***ENE*** | ***0.27 / 1,415.34*** | ***123.34 / 18*** | ***BRE Properties Inc***
552 DENNY WAY & 553 JOHN ST
SEATTLE WA 98109 | ***ICR***

Cleanup Site ID:	802	***WRIA ID:***	8
Facility Site ID:	609006	***Is NFA Site:***	Yes
Site Status:	No Further Action Required	***Responsible Unit:***	Northwest
Statute:	MTCA	***Latitude:***	47.619163679025341
Rank:		***Longitude:***	-122.34597389879727
Rank Description:		***Legislative District:***	36
Has Env Covenant:		***Congr District:***	7
Is Brownfiled Site:		***County Name:***	King
Is PSI Site:			

Cleanup Activities

Related ID:		***Start Date:***	
VCP Prj No:	NW1894	***End Date:***	2008-09-05
Activity Name:	VCP Termination	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Olsen, Russ
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	2008-02-13
VCP Prj No:	NW1894	***End Date:***	
Activity Name:	VCP Application	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	
VCP Prj No:	NW1894	***End Date:***	
Activity Name:	VCP Opinion on Interim Action	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	

County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Related ID:
VCP Prj No:
Activity Name: Site Status Changed to NFA
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:

Project Manager: Hickey, Joe
Start Date:
End Date: 2008-04-29
Legal Mechanism:
Performed by:
Project Manager:

Media Contaminants

Contaminant Type: Petroleum Products-Unspecified
Groundwater:
Groundwater Desc.:
Surface Water:
Surfacewater Desc.:
Soil: C
Soil Desc.: Confirmed Above Cleanup Level

Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

Contaminant Type: Polynuclear Aromatic Hydrocarbons
Groundwater:
Groundwater Desc.:
Surface Water:
Surfacewater Desc.:
Soil: B
Soil Desc.: Below Cleanup Level

Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

117	4 of 5	ENE	0.27 / 1,415.34	123.34 / 18	**BRE Properties Inc** **552 DENNY WAY & 553 JOHN ST** **SEATTLE WA 98109**	VCP

Facility Site ID: 609006
Cleanup Site ID: 802
Region: Northwest
Alternate Site Names: TEAMSTERS UNION PROPERTY
Data Source(s): No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State

County: King
Latitude: 47.6191636790253
Longitude: -122.345973898797

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status: NFA
NFA Date: 04/29/2008
Responsible Unit: Northwest
Has Inst Control:
NFA Reason: Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Below Cleanup Levels

Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels

Sediment:
Air:
Bedrock:

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: No Further Action

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

117	5 of 5	ENE	0.27 / 1,415.34	123.34 / 18	BRE PROPERTIES INC 552 DENNY WAY & 553 JOHN ST SEATTLE WA 98109	RCRA TSD

EPA Handler ID: WAH000029059
Gen Status Universe: No Report
Contact Name: CRAIG KIRKENDALL
Contact Address: 5141 CALIFORNIA , SUITE 250 , SEATTLE , WA, 92617 , US
Contact Phone No and Ext: 949-863-4251
Contact Email: CKIRKENDALL@BREPROPERTIES.COM
Contact Country: US
Land Type: Private
County Name: KING
EPA Region: 10
Receive Date: 20110406
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jun 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Smelting, Melting and Refining: No
Underground Injection Control: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20070806

Handler Name: BRE PROPERTIES INC
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20110405
Handler Name: BRE PROPERTIES INC
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 6
Receive Date: 20110406
Handler Name: BRE PROPERTIES INC
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070806
Handler Name: BRE PROPERTIES INC
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20110405
Handler Name: BRE PROPERTIES INC
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20110405
Handler Name: BRE PROPERTIES INC
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 20110405
Handler Name: BRE PROPERTIES INC
Federal Waste Generator Code: N

Generator Code Description: Not a Generator, Verified
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 20110405
Handler Name: BRE PROPERTIES INC
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060620
Handler Name: BRE PROPERTIES INC
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Notification

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: BRE PROPERTIES INC
Date Became Current:
Date Ended Current:
Phone: 415-445-6531
Source Type: Implementer
Street No:
Street 1: 525 MARKET ST 4TH FLOOR
Street 2:
City: SAN FRANCISCO
State: CA
Country: US
Zip Code: 94104

Owner/Operator Ind: Current Owner
Type: Private
Name: BRE PROPERTIES INC
Date Became Current: 20081231
Date Ended Current:
Phone: 949-863-4251
Source Type: Implementer
Street No:
Street 1: 5141 CALLIFORNIA
Street 2: SUITE 250
City: IRVINE
State: CA
Country: US
Zip Code: 92617

Owner/Operator Ind: Current Owner
Type: Private
Name: BRE PROPERTIES INC
Date Became Current: 20060101
Date Ended Current:
Phone: 949-863-4251
Source Type: Notification
Street No:
Street 1: 5141 CALIFORNIA
Street 2: SUITE 250
City: IRVINE
State: CA
Country: US
Zip Code: 92617

Owner/Operator Ind: Current Owner
Type: Private
Name: BRE PROPERTIES INC
Date Became Current: 20061231
Date Ended Current:
Phone: 949-863-4251
Source Type: Notification
Street No:
Street 1: 5141 CALIFORNIA
Street 2: SUITE 250
City: IRVINE
State: CA
Country: US
Zip Code: 92617

Owner/Operator Ind: Current Owner
Type: Private
Name: BRE PROPERTIES INC
Date Became Current: 20060101
Street No:
Street 1: 5141 CALLIFORNIA
Street 2: SUITE 250
City: IRVINE

Date Ended Current:		**State:**	CA
Phone:	415-445-6531	**Country:**	US
Source Type:	Implementer	**Zip Code:**	92617
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	5141 CALLIFORNIA
Name:	BRE PROPERTIES INC	**Street 2:**	SUITE 250
Date Became Current:	20060101	**City:**	IRVINE
Date Ended Current:		**State:**	CA
Phone:	415-445-6531	**Country:**	US
Source Type:	Notification	**Zip Code:**	92617
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	5141 CALIFORNIA
Name:	CRAIG K	**Street 2:**	SUITE 250
Date Became Current:	20060101	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	949-863-4251	**Country:**	US
Source Type:	Implementer	**Zip Code:**	92617
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	552 DENNY WAY & 553 JOHN ST
Name:	BRE PROPERTIES INC	**Street 2:**	
Date Became Current:	20060101	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	949-863-4251	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	525 MARKET ST 4TH FLOOR
Name:	BRE PROPERTIES INC	**Street 2:**	
Date Became Current:		**City:**	SAN FRANCISCO
Date Ended Current:		**State:**	CA
Phone:	415-445-6531	**Country:**	US
Source Type:	Implementer	**Zip Code:**	94104
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	525 MARKET ST 4TH FLOOR
Name:	BRE PROPERTIES INC	**Street 2:**	
Date Became Current:	20060101	**City:**	SAN FRANCISCO
Date Ended Current:		**State:**	CA
Phone:	415-445-6531	**Country:**	US
Source Type:	Notification	**Zip Code:**	94104
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	525 MARKET ST 4TH FLOOR
Name:	BRE PROPERTIES INC	**Street 2:**	
Date Became Current:	20071231	**City:**	SAN FRANCISCO
Date Ended Current:		**State:**	CA
Phone:	415-445-6531	**Country:**	US
Source Type:	Notification	**Zip Code:**	94104
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	5141 CALIFORNIA
Name:	BRE PROPERTIES INC	**Street 2:**	SUITE 250
Date Became Current:	20060101	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	949-863-4251	**Country:**	US
Source Type:	Notification	**Zip Code:**	92617
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	5141 CALIFORNIA
Name:	BRE PROPERTIES INC	**Street 2:**	SUITE 250
Date Became Current:		**City:**	IRVINE
Date Ended Current:		**State:**	CA
Phone:	949-863-4251	**Country:**	US
Source Type:	Implementer	**Zip Code:**	92617
Owner/Operator Ind:	Current Owner	**Street No:**	

Type:	Private	**Street 1:**	5141 CALLIFORNIA
Name:	BRE PROPERTIES INC	**Street 2:**	SUITE 250
Date Became Current:	20081231	**City:**	IRVINE
Date Ended Current:		**State:**	CA
Phone:	949-863-4251	**Country:**	US
Source Type:	Notification	**Zip Code:**	92617

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	5141 CALLIFORNIA
Name:	BRE PROPERTIES B	**Street 2:**	SUITE 250
Date Became Current:	20060101	**City:**	IRVINE
Date Ended Current:		**State:**	CA
Phone:	415-445-6531	**Country:**	US
Source Type:	Implementer	**Zip Code:**	92617

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	525 MARKET ST 4TH FLOOR
Name:	BRE PROPERTIES INC	**Street 2:**	
Date Became Current:		**City:**	SAN FRANCISCO
Date Ended Current:		**State:**	CA
Phone:	415-445-6531	**Country:**	US
Source Type:	Notification	**Zip Code:**	94104

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	525 MARKET ST 4TH FLOOR
Name:	BRE PROPERTIES INC	**Street 2:**	
Date Became Current:	20070806	**City:**	SAN FRANCISCO
Date Ended Current:		**State:**	CA
Phone:	415-445-6531	**Country:**	US
Source Type:	Notification	**Zip Code:**	94104

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	5141 CALIFORNIA
Name:	BRE PROPERTIES INC	**Street 2:**	SUITE 250
Date Became Current:		**City:**	IRVINE
Date Ended Current:		**State:**	CA
Phone:	949-863-4251	**Country:**	US
Source Type:	Implementer	**Zip Code:**	92617

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	5141 CALIFORNIA
Name:	BRE PROPERTIES INC	**Street 2:**	SUITE 250
Date Became Current:	20060101	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	949-863-4251	**Country:**	US
Source Type:	Implementer	**Zip Code:**	92617

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	525 MARKET ST 4TH FLOOR
Name:	BRE PROPERTIES INC	**Street 2:**	
Date Became Current:		**City:**	SAN FRANCISCO
Date Ended Current:		**State:**	CA
Phone:	415-445-6531	**Country:**	US
Source Type:	Notification	**Zip Code:**	94104

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	552 DENNY WAY & 553 JOHN ST
Name:	BRE PROPERTIES INC	**Street 2:**	
Date Became Current:	20060101	**City:**	SEATTLE
Date Ended Current:		**State:**	WA
Phone:	415-445-6531	**Country:**	US
Source Type:	Notification	**Zip Code:**	98109

Historical Handler Details

Receive Dt:	20060620
Generator Code Description:	Not a Generator, Verified
Handler Name:	BRE PROPERTIES INC

Receive Dt: 20110405
Generator Code Description: Large Quantity Generator
Handler Name: BRE PROPERTIES INC

Receive Dt: 20110405
Generator Code Description: Not a Generator, Verified
Handler Name: BRE PROPERTIES INC

Receive Dt: 20110405
Generator Code Description: Small Quantity Generator
Handler Name: BRE PROPERTIES INC

Receive Dt: 20070806
Generator Code Description: Not a Generator, Verified
Handler Name: BRE PROPERTIES INC

Receive Dt: 20070806
Generator Code Description: Large Quantity Generator
Handler Name: BRE PROPERTIES INC

Receive Dt: 20110405
Generator Code Description: Not a Generator, Verified
Handler Name: BRE PROPERTIES INC

Receive Dt: 20110405
Generator Code Description: Not a Generator, Verified
Handler Name: BRE PROPERTIES INC

118	1 of 1	SE	0.27 / 1,417.61	80.09 / -26	VERIZON WIRELESS BATTERY STREET TUNNEL 2315 WESTERN AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID: 78163
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: CRK000068590
Facility Alternate: VERIZON WIRELESS BATTERY STREET TUNNEL
Interaction ID: 132114
Interaction Status: A
Interac Status Desc: Active
Interaction Type: TIER2
Interaction Desc: Emergency/Haz Chem Rpt TIER2
Interact Start Dt: 01-Jan-2007
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: EPCRA
Database Name Desc: Emergency Planning & Community Right-to-Know Act

Facility Location Detail

Horizontal: Unknown
Horizont 1: WGS84
Horizont 2: Address
Location Verified:
GIS latitude: 47.61285
GIS longitude: -122.34817

119	1 of 3	W	0.27 / 1,449.04	26.61 / -79	Unocal Elliott Ave N of Bay St GW Plume ELLIOTT AVE & BAY ST NEC SEATTLE WA 98121	CSCSL

Fac Site ID:	12120	**Responsible Unit:**	Northwest
Cleanup Site ID:	1285	**Fac Site ID (OD):**	12120
Site Status:	Awaiting Cleanup	**Cleanup SiteID(OD):**	1285
Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:		**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.357021
Latitude:	47.6175927675304	**Latitude (OD):**	47.617593
Longitude:	-122.357021458323		

Site Name: Unocal Elliott Ave N of Bay St GW Plume
Address: ELLIOTT AVE & BAY ST NEC
City: SEATTLE
Zip Code: 98121
Site Status (OD): Awaiting Cleanup
Site Name (OD): UNOCAL ELLIOTT AVE N OF BAY ST GW PLUME
Address (OD): ELLIOTT AVE & BAY ST NEC
City (OD): SEATTLE
Zipcode (OD): 98121
Location (OD): ""
(47.617593, -122.357021)
Alternate Site Names: UNOCAL ELLIOTT AVE N OF BAY ST
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Metals Priority Pollutants
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Non-Halogenated Solvents
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Non-Halogenated Solvents
Contaminant Media: Soil

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals Priority Pollutants
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals Priority Pollutants
Contaminant Media: Groundwater
Contaminant Status: Below Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Non-Halogenated Solvents
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

119	2 of 3	W	0.27 / 1,449.04	26.61 / -79	UNOCAL ELLIOTT AVE N OF BAY ST ELLIOTT AVE & BAY ST NEC SEATTLE WA 98121	ALL SITES

Facility/Site ID: 12120
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: UNOCAL ELLIOTT AVE N OF BAY ST GW PLUME
Interaction ID: 5838
Interaction Status: A
Interac Status Desc: Active
Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 17-Jun-1997
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6175927675
GIS longitude: -122.357021458

119	3 of 3	W	0.27 / 1,449.04	26.61 / -79	UNOCAL ELLIOTT AVE N OF BAY ST GW PLUME ELLIOTT AVE & BAY ST NEC SEATTLE WA 98121	ICR

Cleanup Site ID: 1285
Facility Site ID: 12120
Site Status: Awaiting Cleanup
WRIA ID: 8
Is NFA Site:
Responsible Unit: Northwest

Statute:	MTCA	***Latitude:***	47.617592767530418
Rank:		***Longitude:***	-122.35702145832271
Rank Description:		***Legislative District:***	36
Has Env Covenant:		***Congr District:***	7
Is Brownfiled Site:		***County Name:***	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		***Start Date:***	1996-03-25
VCP Prj No:		***End Date:***	1996-03-25
Activity Name:	Initial Investigation / Federal Preliminary Assessment	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	Ecology
County Name:	King	***Project Manager:***	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	1995-08-15
Activity Name:	Site Discovery/Release Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	1996-12-04
Activity Name:	Early Notice Letter(s)	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Media Contaminants

Contaminant Type:	Non-Halogenated Solvents	***Sediment:***	
Groundwater:	C	***Sediment Desc.:***	
Groundwater Desc.:	Confirmed Above Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

Contaminant Type:	Petroleum Products-Unspecified	***Sediment:***	
Groundwater:	C	***Sediment Desc.:***	
Groundwater Desc.:	Confirmed Above Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

Contaminant Type:	Metals Priority Pollutants	***Sediment:***	
Groundwater:	B	***Sediment Desc.:***	
Groundwater Desc.:	Below Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	B	***Bedrock Desc.:***	
Soil Desc.:	Below Cleanup Level	***County Name:***	King

Contaminant Type:	Polynuclear Aromatic Hydrocarbons	***Sediment:***	
Groundwater:	C	***Sediment Desc.:***	
Groundwater Desc.:	Confirmed Above Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
120	1 of 2	NE	0.28 / 1,479.78	121.23 / 15	Ride the Ducks 516 BROAD ST SEATTLE WA 98109	ALL SITES

Facility/Site ID: 38992
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: Ride the Ducks
Interaction ID: 128204
Interaction Status: A
Interac Status Desc: Active
Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 11-Apr-2018
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6214427694
GIS longitude: -122.347276034

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
120	2 of 2	NE	0.28 / 1,479.78	121.23 / 15	Ride the Ducks 516 BROAD ST SEATTLE WA 98109	CSCSL

Fac Site ID: 38992
Cleanup Site ID: 14733
Site Status: Awaiting Cleanup
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6214427694254
Longitude: -122.347276034393
Site Name: Ride the Ducks
Address: 516 BROAD ST
City: SEATTLE
Zip Code: 98109
Site Status (OD): Awaiting Cleanup
Site Name (OD): Ride the Ducks
Address (OD): 516 BROAD ST
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.621443, -122.347276)
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 38992
Cleanup SiteID(OD): 14733
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.347276
Latitude (OD): 47.621443

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Non-Halogenated Solvents
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Other Non-Halogenated Organics
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

121	*1 of 1*	*S*	*0.28 / 1,491.62*	*9.61 / -96*	***WA DOT Alaskan Way Viaduct Project*** ***ALASKAN WAY VIADUCT MP 28.61 TO 33.8*** ***SEATTLE WA 98104***	***ALL SITES***

Facility/Site ID: 1188246
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000018143
Facility Alternate:
Interaction ID: 7999
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWOTHER
Interaction Desc: Haz Waste Management Activity
Interact Start Dt: 31-Dec-2003
Interact End Dt: 31-Dec-2007
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAH000018143
Facility Alternate: WA DOT ALASKAN WAY VIADUCT PROJECT
Interaction ID: 7998

Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 02-May-2002
Interact End Dt: 31-Dec-2009
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAH000018143
Facility Alternate: WA DOT Alaskan Way Viaduct Project
Interaction ID: 91201
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWOTHER
Interaction Desc: Haz Waste Management Activity
Interact Start Dt: 31-Dec-2009
Interact End Dt: 31-Dec-2010
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAH000018143
Facility Alternate:
Interaction ID: 8000
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 31-Dec-2007
Interact End Dt: 31-Dec-2009
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAH000018143
Facility Alternate: WA DOT Alaskan Way Viaduct Project
Interaction ID: 96230
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 31-Dec-2010
Interact End Dt: 31-Dec-2011
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAH000018143
Facility Alternate: WA DOT Alaskan Way Viaduct Project
Interaction ID: 117078
Interaction Status: A
Interac Status Desc: Active
Interaction Type: HWOTHER
Interaction Desc: Haz Waste Management Activity
Interact Start Dt: 31-Dec-2015
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAH000018143
Facility Alternate: WA DOT Alaskan Way Viaduct Project

Interaction ID:	99587
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWOTHER
Interaction Desc:	Haz Waste Management Activity
Interact Start Dt:	31-Dec-2011
Interact End Dt:	31-Dec-2013
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Program ID:	WAH000018143
Facility Alternate:	WA DOT Alaskan Way Viaduct Project
Interaction ID:	111455
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	31-Dec-2013
Interact End Dt:	31-Dec-2015
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	N
Horizont 1:	Unknown	**GIS latitude:**	47.6123492497
Horizont 2:	Address	**GIS longitude:**	-122.350263478

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
122	1 of 1	E	0.28 / 1,503.26	127.36 / 22	**Konankada Inc., dba: Seattle Micro** **2310 4th Ave** **Seattle WA 98121-1718**	SWF/LF

ID:	1845	**Open to Public:**	No
Recycle Survey ID:	7193	**Regulation:**	
Permit Status:	Recycle Survey	**Ownership:**	
Operational Status:	Operating	**Region:**	Northwest Regional Office
Year Opened:	1900	**County:**	King
Year Closed:		**Latitude:**	
Ann Report Required:	No	**Longitude:**	
Rec Survey Required:	No	**Facility Phone:**	(206) 441-9111
Facility Type:	Recycling (non-regulated)		

Details

Permit No:		**Contact Address 1:**	Po Box 28459
Operator First Name:		**Contact Address 2:**	
Operator Last Name:		**Contact City:**	Seattle
Operator Title:		**Contact State:**	WA
Operator Email:		**Contact Zip:**	98118
Contact First Name:	Jim	**Contact Email:**	
Contact Last Name:	Denison	**Contact Phone:**	(206) 441-9111
Contact Title:	President	**Contact Phone Ext:**	
Contact Organization:	Konankada Inc., dba: Seattle Micro		
Operator Organization:	Konankada Inc., dba: Seattle Micro		
Web Address:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
123	1 of 1	SE	0.29 / 1,505.52	113.78 / 8	**Bell Street Park** **WA**	ALL SITES

Facility/Site ID:	6340

Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: Bell Street Park
Interaction ID: 104465
Interaction Status: A
Interac Status Desc: Active
Interaction Type: CONSTSWGP
Interaction Desc: Construction SW GP
Interact Start Dt: 03-Apr-2013
Interact End Dt:
Ecology Program: WATQUAL
Program Name Desc: Water Quality Program
Prog Database Name: PARIS
Database Name Desc: Permitting & Reporting Information System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.613416
GIS longitude: -122.346483

124	1 of 1	ESE	0.29 / 1,511.98	129.01 / 23	Import Doctors 211 BELL ST SEATTLE WA 98121-1715	ALL SITES

Facility/Site ID: 19547432
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAD988485264
Facility Alternate:
Interaction ID: 31165
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 21-Apr-1991
Interact End Dt: 31-Dec-2004
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.61424
GIS longitude: -122.34543

125	1 of 1	SE	0.29 / 1,513.98	116.57 / 11	Symetrix Inc Seattle 109 BELL ST SEATTLE WA 98121	ALL SITES

Facility/Site ID: 48544386
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility/Site Interaction

Program ID:	WAD091735753
Facility Alternate:	
Interaction ID:	47549
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	04-Dec-1985
Interact End Dt:	31-Jul-1989
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	N
Horizont 1:	NAD83	***GIS latitude:***	47.61357
Horizont 2:	Unknown	***GIS longitude:***	-122.34627

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
126	*1 of 1*	*E*	*0.29 / 1,517.85*	*127.69 / 22*	*4th and Bell Seattle 2306 4th Ave Seattle WA 98121*	*ALL SITES*

Facility/Site ID:	51033
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAH000058795
Facility Alternate:	4th and Bell Seattle
Interaction ID:	139128
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	06-Apr-2021
Interact End Dt:	
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	
Horizont 1:	NAD83	***GIS latitude:***	47.61575
Horizont 2:	Address	***GIS longitude:***	-122.34406

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
127	*1 of 5*	*WNW*	*0.29 / 1,552.46*	*69.05 / -37*	*Shell Station 121702 10 DENNY WAY SEATTLE WA 98109*	*CSCSL NFA*

Fac Site ID:	49674295	***Fac Site ID (OD):***	49674295
Cleanup Site ID:	6174	***Cleanup SiteID(OD):***	6174
Site Status:	NFA	***Site Status (OD):***	No Further Action
NFA Date:	06/14/2013	***Rank (OD):***	
Responsible Unit:	Northwest	***Has Env Coven (OD):***	
Has Insti Control:		***Respon Unit (OD):***	Northwest
Region:	Northwest	***Region (OD):***	Northwest

County:	King	**County (OD):**	King
Latitude:	47.6188075801311	**Latitude (OD):**	47.618808
Longitude:	-122.356361064685	**Longitude (OD):**	-122.356361

NFA Reason: Voluntary Cleanup Program Review
Alternate Site Names: Jacksons 654,SHELL 10 DENNY WAY,SEATTLE,SHELL 121702,TEXACO STAR MART 3725,TEXACO STATION DENNY WAY
Location (OD): ""
(47.618808, -122.356361)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

NFA Contaminants Detail(s)

Contaminant Name: Benzene
Groundwater: Remediated-Below
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Metals - Other
Groundwater: Remediated-Below
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Remediated-Below
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Methyl tertiary-butyl ether
Groundwater: Remediated-Below
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Metals - Other
Contaminant Media: Groundwater
Contaminant Status: Remediated-Below

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Remediated-Below

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Methyl tertiary-butyl ether
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Methyl tertiary-butyl ether
Contaminant Media: Groundwater
Contaminant Status: Remediated-Below

Contaminant: Metals - Other
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
127	2 of 5	WNW	0.29 / 1,552.46	69.05 / -37	Shell Station 121702 10 DENNY WAY SEATTLE WA 98109	ALL SITES

Facility/Site ID: 49674295
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 4460
Facility Alternate: Jacksons 654
Interaction ID: 48157
Interaction Status: A
Interac Status Desc: Active
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 28-Jul-1997
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: 4460
Facility Alternate:
Interaction ID: 48156
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: LUST
Interaction Desc: LUST Facility
Interact Start Dt: 31-Aug-1992
Interact End Dt: 14-Jun-2013
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: WAD988503652
Facility Alternate:
Interaction ID: 48159
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 20-Oct-2005
Interact End Dt: 31-Dec-2010
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAD988503652
Facility Alternate:
Interaction ID: 48155

Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	16-Mar-1992
Interact End Dt:	27-Feb-2004
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System
Program ID:	WAD988503652
Facility Alternate:	
Interaction ID:	48158
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWOTHER
Interaction Desc:	Haz Waste Management Activity
Interact Start Dt:	31-Dec-2002
Interact End Dt:	20-Oct-2005
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System
Program ID:	WAD988503652
Facility Alternate:	Shell Station 121702
Interaction ID:	95866
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWOTHER
Interaction Desc:	Haz Waste Management Activity
Interact Start Dt:	31-Dec-2010
Interact End Dt:	31-Dec-2010
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System
Program ID:	WAD988503652
Facility Alternate:	
Interaction ID:	48154
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	TIER2
Interaction Desc:	Emergency/Haz Chem Rpt TIER2
Interact Start Dt:	01-Jan-1991
Interact End Dt:	01-Jan-1753
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	EPCRA
Database Name Desc:	Emergency Planning & Community Right-to-Know Act
Program ID:	NW2060
Facility Alternate:	Shell 10 Denny Way, Seattle
Interaction ID:	48160
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	VOLCLNST
Interaction Desc:	Voluntary Cleanup Sites
Interact Start Dt:	14-Jan-2009
Interact End Dt:	14-Jun-2013
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Facility Location Detail

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Horizontal:	40ft	**Location Verified:**	
Horizont 1:	NAD83HARN	**GIS latitude:**	47.6188075801
Horizont 2:	Digital map or GIS	**GIS longitude:**	-122.356361065

127 **3 of 5** **WNW** **0.29 / 1,552.46** **69.05 / -37** **Shell Station 121702**
10 DENNY WAY
SEATTLE WA 98109 **ICR**

Cleanup Site ID:	6174	**WRIA ID:**	8
Facility Site ID:	49674295	**Is NFA Site:**	Yes
Site Status:	No Further Action Required	**Responsible Unit:**	Northwest
Statute:	MTCA	**Latitude:**	47.618540000000003
Rank:		**Longitude:**	-122.357788
Rank Description:		**Legislative District:**	36
Has Env Covenant:		**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:	2260	**Start Date:**	1993-11-05
VCP Prj No:		**End Date:**	1993-11-17
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	1995-10-12
VCP Prj No:		**End Date:**	1995-11-20
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	1998-10-12
VCP Prj No:		**End Date:**	1998-10-13
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	2007-04-10
VCP Prj No:		**End Date:**	2007-04-16
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	2009-02-26
VCP Prj No:		**End Date:**	2009-03-10
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		**Start Date:**	2011-11-18
VCP Prj No:	NW2060	**End Date:**	
Activity Name:	VCP Receipt of Plan or Report	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Goldstein, Libby
Applies to:	VcpProject		

Applies to Description: Voluntary Cleanup Program

Related ID: 5528 **Start Date:** 2009-01-14
VCP Prj No: **End Date:** 2009-04-14
Activity Name: Independent Report Review - Paid **Legal Mechanism:**
Activity Status: Completed **Performed by:** PLP
County Name: King **Project Manager:** Adams, Mark
Applies to: CleanupUnit
Applies to Description:

Related ID: 2260 **Start Date:** 1995-05-01
VCP Prj No: **End Date:** 1995-05-12
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 2260 **Start Date:** 1998-03-23
VCP Prj No: **End Date:** 1998-03-24
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 2260 **Start Date:** 1997-11-25
VCP Prj No: **End Date:** 1998-05-04
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 2260 **Start Date:** 1998-11-18
VCP Prj No: **End Date:** 1998-11-20
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 2260 **Start Date:** 2005-06-10
VCP Prj No: **End Date:** 2005-06-17
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 2260 **Start Date:** 2009-07-01
VCP Prj No: **End Date:** 2009-07-08
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: **Start Date:**
VCP Prj No: **End Date:** 2013-06-14
Activity Name: Site Status Changed to NFA **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:** Fernandez, Sonia
Applies to: CleanupSite
Applies to Description:

Related ID: 2260 **Start Date:** 1996-02-07
VCP Prj No: **End Date:** 1996-02-21
Activity Name: LUST - Report Received **Legal Mechanism:**

Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	1996-01-30
VCP Prj No:		**End Date:**	1996-02-21
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	1996-10-24
VCP Prj No:		**End Date:**	1996-10-28
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	2002-11-26
VCP Prj No:		**End Date:**	2002-12-04
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	2008-03-03
VCP Prj No:		**End Date:**	2008-03-06
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		**Start Date:**	2013-04-16
VCP Prj No:	NW2060	**End Date:**	2013-06-14
Activity Name:	VCP Opinion on Site Cleanup	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Fernandez, Sonia
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:	2260	**Start Date:**	1992-12-14
VCP Prj No:		**End Date:**	1992-12-14
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	1995-04-24
VCP Prj No:		**End Date:**	1995-07-17
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	1998-03-23
VCP Prj No:		**End Date:**	1998-07-02
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	1998-07-17
VCP Prj No:		**End Date:**	1998-07-22
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	2006-01-23
VCP Prj No:		**End Date:**	2006-02-01
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	2007-09-04
VCP Prj No:		**End Date:**	2007-09-06
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	2008-11-21
VCP Prj No:		**End Date:**	2008-12-01
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	2000-01-06
VCP Prj No:		**End Date:**	2000-02-10
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	2004-12-07
VCP Prj No:		**End Date:**	2004-12-09
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	2008-04-02
VCP Prj No:		**End Date:**	2008-04-07
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	2013-04-12
VCP Prj No:		**End Date:**	2013-04-16
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		**Start Date:**	2009-01-14
VCP Prj No:	NW2060	**End Date:**	
Activity Name:	VCP Application	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region

Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Related ID: 2260 **Start Date:** 2003-06-06
VCP Prj No: **End Date:** 2003-06-09
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 2260 **Start Date:** 1999-09-01
VCP Prj No: **End Date:** 1999-09-20
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 2260 **Start Date:** 2002-02-25
VCP Prj No: **End Date:** 2002-03-11
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 2260 **Start Date:** 2008-08-18
VCP Prj No: **End Date:** 2008-08-21
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 2260 **Start Date:** 1997-11-26
VCP Prj No: **End Date:** 1998-05-04
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 2260 **Start Date:** 1998-03-31
VCP Prj No: **End Date:** 1998-05-04
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 2260 **Start Date:** 1995-04-11
VCP Prj No: **End Date:** 1995-05-12
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 2260 **Start Date:** 1999-01-20
VCP Prj No: **End Date:** 1999-01-27
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 2260 **Start Date:** 2008-09-12
VCP Prj No: **End Date:** 2008-09-16

Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	2013-02-13
VCP Prj No:		**End Date:**	2013-02-25
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		**Start Date:**	
VCP Prj No:	NW2060	**End Date:**	
Activity Name:	VCP Opinion on Interim Action	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Adams, Mark
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:	2260	**Start Date:**	2004-04-13
VCP Prj No:		**End Date:**	2004-04-23
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	2004-06-22
VCP Prj No:		**End Date:**	2004-06-25
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	1998-07-06
VCP Prj No:		**End Date:**	1998-07-30
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	2010-02-05
VCP Prj No:		**End Date:**	2010-02-11
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	2000-05-02
VCP Prj No:		**End Date:**	2000-06-13
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	2000-11-09
VCP Prj No:		**End Date:**	2001-01-02
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	2006-10-02
VCP Prj No:		**End Date:**	2006-10-06
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	1992-08-31
VCP Prj No:		**End Date:**	1992-08-31
Activity Name:	LUST - Notification	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	1995-07-25
VCP Prj No:		**End Date:**	1995-09-20
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	1997-04-29
VCP Prj No:		**End Date:**	1997-05-01
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	2001-06-11
VCP Prj No:		**End Date:**	2001-08-03
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2260	**Start Date:**	2002-06-18
VCP Prj No:		**End Date:**	2002-08-12
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		**Start Date:**	
VCP Prj No:	NW2060	**End Date:**	2013-06-14
Activity Name:	VCP Termination	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Fernandez, Sonia
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Media Contaminants

Contaminant Type:	Methyl tertiary-butyl ether	**Sediment:**	
Groundwater:	RB	**Sediment Desc.:**	
Groundwater Desc.:	Remediated-Below Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RB	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Below Cleanup Level	**County Name:**	King

Contaminant Type:	Petroleum-Gasoline	**Sediment:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Groundwater:	RB	**Sediment Desc.:**	
Groundwater Desc.:	Remediated-Below Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RB	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Below Cleanup Level	**County Name:**	King
Contaminant Type:	Benzene	**Sediment:**	
Groundwater:	RB	**Sediment Desc.:**	
Groundwater Desc.:	Remediated-Below Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RB	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Below Cleanup Level	**County Name:**	King
Contaminant Type:	Metals - Other	**Sediment:**	
Groundwater:	RB	**Sediment Desc.:**	
Groundwater Desc.:	Remediated-Below Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RB	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Below Cleanup Level	**County Name:**	King

---

127	***4 of 5***	***WNW***	***0.29 / 1,552.46***	***69.05 / -37***	***Shell Station 121702 10 DENNY WAY SEATTLE WA 98109***	***VCP***

Facility Site ID:	49674295	**County:**	King
Cleanup Site ID:	6174	**Latitude:**	47.6188075801311
Region:	Northwest	**Longitude:**	-122.356361064685
Alternate Site Names:	Jacksons 654,SHELL 10 DENNY WAY,SEATTLE,SHELL 121702,TEXACO STAR MART 3725,TEXACO STATION DENNY WAY		
Data Source(s):	No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State		

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status:	NFA
NFA Date:	06/14/2013
Responsible Unit:	Northwest
Has Inst Control:	
NFA Reason:	Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name:	Metals - Other	**Sediment:**	
Groundwater:	Remediated-Below	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Below		
Contaminant Name:	Benzene	**Sediment:**	
Groundwater:	Remediated-Below	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Below		
Contaminant Name:	Methyl tertiary-butyl ether	**Sediment:**	
Groundwater:	Remediated-Below	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Below		
Contaminant Name:	Petroleum-Gasoline	**Sediment:**	
Groundwater:	Remediated-Below	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Below		

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: No Further Action
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Metals - Other
Groundwater: Remediated-Below
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Methyl tertiary-butyl ether
Groundwater: Remediated-Below
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Remediated-Below
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater: Remediated-Below
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

127	5 of 5	WNW	0.29 / 1,552.46	69.05 / -37	Shell Station 121702 10 DENNY WAY SEATTLE WA 98109	LUST

Facility Site ID: 49674295
Cleanup Site ID: 6174
Responsible Unit: Northwest
Region: Northwest
County: King
Latitude: 47.6188075801311
Longitude: -122.356361064685
Alternate Site Names: Jacksons 654,SHELL 10 DENNY WAY,SEATTLE,SHELL 121702,TEXACO STAR MART 3725,TEXACO STATION DENNY WAY

Tank Detail(s)

UST ID: 4460
LUST ID: 2260
LUST Status: LUST - NFA
Status Date: 06/14/2013
Release Date: 08/31/1992

Contaminants Detail(s)

Contaminant Name: Methyl tertiary-butyl ether
Groundwater: Remediated-Below
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Metals - Other
Groundwater: Remediated-Below
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater: Remediated-Below
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Benzene
Groundwater: Remediated-Below
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

---

128 | 1 of 4 | SE | 0.30 / 1,573.67 | 113.65 / 8 | First & Bell, 2233 1ST AVE, SEATTLE WA 98121 | CSCSL NFA

Fac Site ID: 83974793
Cleanup Site ID: 2966
Site Status: NFA
NFA Date: 03/11/2003
Responsible Unit: Northwest
Has Insti Control:
Region: Northwest
County: King
Latitude: 47.6128204786241
Longitude: -122.347821128335
Fac Site ID (OD): 83974793
Cleanup SiteID(OD): 2966
Site Status (OD): No Further Action
Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
Region (OD): Northwest
County (OD): King
Latitude (OD): 47.61282
Longitude (OD): -122.347821
NFA Reason: Voluntary Cleanup Program Review
Alternate Site Names:
Location (OD): ""
(47.61282, -122.347821)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

NFA Contaminants Detail(s)

Contaminant Name: Conventional Contaminants, Inorganic
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Conventional Contaminants, Inorganic
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

128 | 2 of 4 | SE | 0.30 / 1,573.67 | 113.65 / 8 | First & Bell, 2233 1ST AVE, SEATTLE WA 98121 | ALL SITES

Facility/Site ID: 83974793
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000014100
Facility Alternate:
Interaction ID: 67525

Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	20-Feb-2001
Interact End Dt:	31-Dec-2001
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Program ID:	NW1008
Facility Alternate:	First & Bell
Interaction ID:	67526
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	VOLCLNST
Interaction Desc:	Voluntary Cleanup Sites
Interact Start Dt:	05-Dec-2002
Interact End Dt:	11-Mar-2003
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	N
Horizont 1:	Unknown	***GIS latitude:***	47.6128204786
Horizont 2:	Address	***GIS longitude:***	-122.347821128

128	*3 of 4*	*SE*	*0.30 / 1,573.67*	*113.65 / 8*	***First & Bell*** ***2233 1ST AVE*** ***SEATTLE WA 98121***	*ICR*

Cleanup Site ID:	2966	***WRIA ID:***	8
Facility Site ID:	83974793	***Is NFA Site:***	Yes
Site Status:	No Further Action Required	***Responsible Unit:***	Northwest
Statute:	MTCA	***Latitude:***	47.612820478624101
Rank:		***Longitude:***	-122.347821128335
Rank Description:		***Legislative District:***	36
Has Env Covenant:		***Congr District:***	7
Is Brownfiled Site:		***County Name:***	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		***Start Date:***	2002-12-05
VCP Prj No:		***End Date:***	2003-03-05
Activity Name:	Ecology Site Characterization	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	PLP
County Name:	King	***Project Manager:***	Northwest Region
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		***Start Date:***	
VCP Prj No:	NW1008	***End Date:***	
Activity Name:	VCP Opinion on Cleanup Action	***Legal Mechanism:***	
Activity Status:	Canceled	***Performed by:***	
County Name:	King	***Project Manager:***	Sato, Brian
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	2002-12-05
VCP Prj No:	NW1008	***End Date:***	
Activity Name:	VCP Application	***Legal Mechanism:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		
Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2003-03-11
Activity Name:	Site Status Changed to NFA	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	CleanupSite		
Applies to Description:			
Related ID:		**Start Date:**	
VCP Prj No:	NW1008	**End Date:**	2003-03-11
Activity Name:	VCP Termination	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Media Contaminants

Contaminant Type:	Conventional Contaminants, Inorganic	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

---

128	4 of 4	SE	0.30 / 1,573.67	113.65 / 8	**First & Bell** **2233 1ST AVE** **SEATTLE WA 98121**	VCP

Facility Site ID:	83974793	**County:**	King
Cleanup Site ID:	2966	**Latitude:**	47.6128204786241
Region:	Northwest	**Longitude:**	-122.347821128335
Alternate Site Names:			
Data Source(s):	No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State		

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status:	NFA
NFA Date:	03/11/2003
Responsible Unit:	Northwest
Has Inst Control:	
NFA Reason:	Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name:	Conventional Contaminants, Inorganic	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Confirmed Above Cleanup Levels		

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status:	No Further Action
Site Rank:	
Has Inst Control:	
Current VCP:	
Past VCP:	Yes

Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Conventional Contaminants, Inorganic
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

---

129 | **1 of 6** | **ENE** | **0.30 / 1,583.60** | **120.12 / 14** | **Japanese Auto Clinic**
600 DENNY WAY
SEATTLE WA 98109 | **CSCSL NFA**

Fac Site ID:
Cleanup Site ID:
Site Status:
NFA Date:
Responsible Unit:
Has Insti Control:
Region:
County:
Latitude:
Longitude:
NFA Reason:
Alternate Site Names:
Location (OD): ""
(47.618827, -122.344766)
Data Source(s): Open Data Portal - Washington State; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

Fac Site ID (OD): 84772579
Cleanup SiteID(OD): 4408
Site Status (OD): No Further Action
Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
Region (OD): Northwest
County (OD): King
Latitude (OD): 47.618827
Longitude (OD): -122.344766

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Non-Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Metals Priority Pollutants
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Polychlorinated biPhenyls (PCB)
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
129	2 of 6	ENE	0.30 / 1,583.60	120.12 / 14	Japanese Auto Clinic 600 DENNY WAY SEATTLE WA 98109	ALL SITES

Facility/Site ID: 84772579
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 8428
Facility Alternate:
Interaction ID: 68041
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 20-Mar-2000
Interact End Dt: 20-Mar-2000
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: 8428
Facility Alternate:
Interaction ID: 68039
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: LUST
Interaction Desc: LUST Facility
Interact Start Dt: 24-Jun-1992
Interact End Dt: 01-Jun-1995
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: nw2242
Facility Alternate: Japanese Auto Clinic
Interaction ID: 89308
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 18-Dec-2009
Interact End Dt: 27-Aug-2010
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: WAD988516639
Facility Alternate:
Interaction ID: 68040
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 11-Jan-1993
Interact End Dt: 31-Dec-2001
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Horizontal:	40ft	**Location Verified:**	
Horizont 1:	NAD83HARN	**GIS latitude:**	47.6188265065
Horizont 2:	Digital map or GIS	**GIS longitude:**	-122.344765963

129	3 of 6	ENE	0.30 / 1,583.60	120.12 / 14	Japanese Auto Clinic 600 DENNY WAY SEATTLE WA 98109	ICR

Cleanup Site ID:	4408	**WRIA ID:**	8
Facility Site ID:	84772579	**Is NFA Site:**	Yes
Site Status:	No Further Action Required	**Responsible Unit:**	Northwest
Statute:	MTCA	**Latitude:**	47.618826506455548
Rank:		**Longitude:**	-122.34476596255116
Rank Description:		**Legislative District:**	36
Has Env Covenant:		**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:			

Cleanup Activities

Related ID:		**Start Date:**	
VCP Prj No:	NW2242	**End Date:**	2010-08-27
Activity Name:	VCP Termination	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Adams, Mark
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:	2045	**Start Date:**	2007-08-31
VCP Prj No:		**End Date:**	2009-12-18
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	2045	**Start Date:**	1992-06-24
VCP Prj No:		**End Date:**	1992-06-24
Activity Name:	LUST - Notification	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		**Start Date:**	2009-12-18
VCP Prj No:	NW2242	**End Date:**	
Activity Name:	VCP Application	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	2009-12-18
VCP Prj No:	NW2242	**End Date:**	2010-08-27
Activity Name:	VCP Opinion on Property Cleanup	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Adams, Mark
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:	2045	**Start Date:**	2010-03-10
VCP Prj No:		**End Date:**	2010-03-19
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		

Applies to Description: Leaking Underground Storage Tank

Related ID: 2045 **Start Date:** 2007-09-18
VCP Prj No: **End Date:** 2009-12-18
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: **Start Date:**
VCP Prj No: **End Date:** 2010-08-27
Activity Name: Site Status Changed to NFA **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:** Adams, Mark
Applies to: CleanupSite
Applies to Description:

Related ID: 2045 **Start Date:** 2008-08-08
VCP Prj No: **End Date:** 2009-12-18
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 2045 **Start Date:** 1992-10-06
VCP Prj No: **End Date:** 1992-10-06
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Media Contaminants

Contaminant Type: Polychlorinated biPhenyls (PCB) **Sediment:**
Groundwater: **Sediment Desc.:**
Groundwater Desc.: **Air:**
Surface Water: **Air Desc.:**
Surfacewater Desc.: **Bedrock:**
Soil: B **Bedrock Desc.:**
Soil Desc.: Below Cleanup Level **County Name:** King

Contaminant Type: Benzene **Sediment:**
Groundwater: **Sediment Desc.:**
Groundwater Desc.: **Air:**
Surface Water: **Air Desc.:**
Surfacewater Desc.: **Bedrock:**
Soil: RB **Bedrock Desc.:**
Soil Desc.: Remediated-Below Cleanup Level **County Name:** King

Contaminant Type: Metals Priority Pollutants **Sediment:**
Groundwater: **Sediment Desc.:**
Groundwater Desc.: **Air:**
Surface Water: **Air Desc.:**
Surfacewater Desc.: **Bedrock:**
Soil: B **Bedrock Desc.:**
Soil Desc.: Below Cleanup Level **County Name:** King

Contaminant Type: Non-Halogenated Solvents **Sediment:**
Groundwater: **Sediment Desc.:**
Groundwater Desc.: **Air:**
Surface Water: **Air Desc.:**
Surfacewater Desc.: **Bedrock:**
Soil: RB **Bedrock Desc.:**
Soil Desc.: Remediated-Below Cleanup Level **County Name:** King

Contaminant Type:	Petroleum-Gasoline	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RB	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Below Cleanup Level	**County Name:**	King

Contaminant Type:	Petroleum Products-Unspecified	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

Contaminant Type:	Petroleum-Diesel	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RB	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Below Cleanup Level	**County Name:**	King

Contaminant Type:	Petroleum-Other	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RB	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Below Cleanup Level	**County Name:**	King

---

129	4 of 6	ENE	0.30 / 1,583.60	120.12 / 14	**Japanese Auto Clinic** **600 DENNY WAY** **SEATTLE WA 98109**	VCP

Facility Site ID:	84772579	**County:**	King
Cleanup Site ID:	4408	**Latitude:**	47.6188265064555
Region:	Northwest	**Longitude:**	-122.344765962551
Alternate Site Names:			
Data Source(s):	Confirmed and Suspected Contaminated Sites; Confirmed and Suspected Contaminated Sites; All Cleanup Sites in Washington State		

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List

Site Status:	Cleanup Started
Current VCP:	
Past VCP:	Yes
Site Rank:	
Responsible Unit:	Northwest
Has Inst Control:	

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List - Contaminants

Contaminant Name:	Benzene	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Below		

Contaminant Name:	Non-Halogenated Solvents	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Below		

Contaminant Name:	Petroleum-Diesel	**Sediment:**	
Groundwater:		**Air:**	

Surfacewater: ***Bedrock:***
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Metals Priority Pollutants ***Sediment:***
Groundwater: ***Air:***
Surfacewater: ***Bedrock:***
Soil: Below Cleanup Levels

Contaminant Name: Polychlorinated biPhenyls (PCB) ***Sediment:***
Groundwater: ***Air:***
Surfacewater: ***Bedrock:***
Soil: Below Cleanup Levels

Contaminant Name: Petroleum-Gasoline ***Sediment:***
Groundwater: ***Air:***
Surfacewater: ***Bedrock:***
Soil: Remediated-Below

Contaminant Name: Petroleum-Other ***Sediment:***
Groundwater: ***Air:***
Surfacewater: ***Bedrock:***
Soil: Remediated-Below

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: Cleanup Started
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Benzene ***Sediment:***
Groundwater: ***Air:***
Surfacewater: ***Bedrock:***
Soil: Remediated-Below

Contaminant Name: Non-Halogenated Solvents ***Sediment:***
Groundwater: ***Air:***
Surfacewater: ***Bedrock:***
Soil: Remediated-Below

Contaminant Name: Petroleum-Gasoline ***Sediment:***
Groundwater: ***Air:***
Surfacewater: ***Bedrock:***
Soil: Remediated-Below

Contaminant Name: Petroleum-Other ***Sediment:***
Groundwater: ***Air:***
Surfacewater: ***Bedrock:***
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Metals Priority Pollutants ***Sediment:***
Groundwater: ***Air:***
Surfacewater: ***Bedrock:***
Soil: Below Cleanup Levels

Contaminant Name: Polychlorinated biPhenyls (PCB) ***Sediment:***
Groundwater: ***Air:***
Surfacewater: ***Bedrock:***
Soil: Below Cleanup Levels

Contaminant Name: Petroleum-Diesel ***Sediment:***
Groundwater: ***Air:***
Surfacewater: ***Bedrock:***

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Soil:	Confirmed Above Cleanup Levels					

129	5 of 6	ENE	0.30 / 1,583.60	120.12 / 14	Japanese Auto Clinic 600 DENNY WAY SEATTLE WA 98109	LUST

Facility Site ID: 84772579
Cleanup Site ID: 4408
Responsible Unit: Northwest
Region: Northwest
Alternate Site Names:

County: King
Latitude: 47.6188265064555
Longitude: -122.344765962551

Tank Detail(s)

UST ID: 8428
LUST ID: 2045
LUST Status: LUST - Cleanup Started

Status Date: 08/27/2010
Release Date: 06/24/1992

Contaminants Detail(s)

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Remediated-Below

Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Polychlorinated biPhenyls (PCB)
Groundwater:
Surfacewater:
Soil: Below Cleanup Levels

Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Remediated-Below

Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Non-Halogenated Solvents
Groundwater:
Surfacewater:
Soil: Remediated-Below

Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Remediated-Below

Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Metals Priority Pollutants
Groundwater:
Surfacewater:
Soil: Below Cleanup Levels

Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name:	Petroleum-Gasoline	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Remediated-Below		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
129	6 of 6	ENE	0.30 / 1,583.60	120.12 / 14	Japanese Auto Clinic 600 DENNY WAY SEATTLE WA 98109	CSCSL

Fac Site ID:	84772579	***Responsible Unit:***	Northwest
Cleanup Site ID:	4408	***Fac Site ID (OD):***	
Site Status:	Cleanup Started	***Cleanup SiteID(OD):***	
Site Rank:		***Site Rank (OD):***	
Current VCP:		***Has Env Coven (OD):***	
Past VCP:	Yes	***Respon Unit (OD):***	
Has Inst Control:		***County (OD):***	
County:	King	***Region (OD):***	
Region:	Northwest	***Longitude (OD):***	
Latitude:	47.6188265064555	***Latitude (OD):***	
Longitude:	-122.344765962551		
Site Name:	Japanese Auto Clinic		
Address:	600 DENNY WAY		
City:	SEATTLE		
Zip Code:	98109		
Site Status (OD):			
Site Name (OD):			
Address (OD):			
City (OD):			
Zipcode (OD):			
Location (OD):			
Alternate Site Names:			
Data Source(s):	Confirmed and Suspected Contaminated Sites		

Contaminants Detail(s)

Contaminant Name:	Non-Halogenated Solvents
Groundwater:	
Surfacewater:	
Soil:	Remediated-Below
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Metals Priority Pollutants
Groundwater:	
Surfacewater:	
Soil:	Below Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Petroleum-Diesel
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Petroleum-Gasoline
Groundwater:	
Surfacewater:	
Soil:	Remediated-Below
Sediment:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Polychlorinated biPhenyls (PCB)
Groundwater:
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

130	*1 of 1*	*ESE*	*0.30 / 1,586.57*	*130.04 / 24*	***Wilson Engraving Co Inc*** ***314 BELL ST*** ***SEATTLE WA 98121***	***ALL SITES***

Facility/Site ID: 66644718
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAR000004333
Facility Alternate:
Interaction ID: 57914
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 28-Aug-1995
Interact End Dt: 01-Dec-1995
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.61495
GIS longitude: -122.34458

131	*1 of 1*	*SE*	*0.30 / 1,601.47*	*73.33 / -32*	***Belltown Lofts*** ***66 BELL ST*** ***SEATTLE WA 98101***	***ALL SITES***

Facility/Site ID: 88228926
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility/Site Interaction

Program ID:	WAH000009670
Facility Alternate:	
Interaction ID:	70028
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	19-Nov-1999
Interact End Dt:	25-Apr-2000
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	1000ft	***Location Verified:***	N
Horizont 1:	NAD83	***GIS latitude:***	47.617193
Horizont 2:	Address	***GIS longitude:***	-122.341805

132	*1 of 5*	*ENE*	*0.30 / 1,607.90*	*118.76 / 13*	***600 Wall Street 600 WALL ST SEATTLE WA 98121***	***CSCSL***

Fac Site ID:	4456856	***Responsible Unit:***	Pollution Liability Ins Agcy
Cleanup Site ID:	3327	***Fac Site ID (OD):***	4456856
Site Status:	Cleanup Started	***Cleanup SiteID(OD):***	3327
Site Rank:		***Site Rank (OD):***	
Current VCP:		***Has Env Coven (OD):***	
Past VCP:	Yes	***Respon Unit (OD):***	Northwest
Has Inst Control:		***County (OD):***	King
County:	King	***Region (OD):***	Northwest
Region:	Northwest	***Longitude (OD):***	-122.344475
Latitude:	47.618065	***Latitude (OD):***	47.618065
Longitude:	-122.344475		
Site Name:	600 Wall Street		
Address:	600 WALL ST		
City:	SEATTLE		
Zip Code:	98121		
Site Status (OD):	Cleanup Started		
Site Name (OD):	600 Wall Street		
Address (OD):	600 WALL ST		
City (OD):	SEATTLE		
Zipcode (OD):	98121		
Location (OD):	"" (47.618065, -122.344475)		
Alternate Site Names:	600 Wall Street Apartments		
Data Source(s):	Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)		

Contaminants Detail(s)

Contaminant Name:	Polycyclic Aromatic Hydrocarbons
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Petroleum Products-Unspecified
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels

Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
132	2 of 5	ENE	0.30 / 1,607.90	118.76 / 13	600 wall street 600 WALL ST SEATTLE WA 98121	ALL SITES

Facility/Site ID: 4456856
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 620391
Facility Alternate: 600 Wall Street Apartments
Interaction ID: 129322
Interaction Status: A
Interac Status Desc: Active
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 07-Jun-2018
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: NW1836
Facility Alternate: 600 wall street
Interaction ID: 14750
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 12-Oct-2007
Interact End Dt: 19-Jan-2010
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Address
Location Verified: N
GIS latitude: 47.618065
GIS longitude: -122.344475

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
132	3 of 5	ENE	0.30 / 1,607.90	118.76 / 13	600 wall street 600 WALL ST SEATTLE WA 98121	ICR

Cleanup Site ID: 3327
Facility Site ID: 4456856
WRIA ID: 8
Is NFA Site:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Status:	Cleanup Started	**Responsible Unit:**	Northwest
Statute:	MTCA	**Latitude:**	47.618065000000001
Rank:		**Longitude:**	-122.344475
Rank Description:		**Legislative District:**	36
Has Env Covenant:		**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		**Start Date:**	
VCP Prj No:	NW1836	**End Date:**	
Activity Name:	VCP Opinion on Cleanup Action	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Liu, Jing
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	
VCP Prj No:	NW1836	**End Date:**	
Activity Name:	VCP Opinion on Interim Action	**Legal Mechanism:**	
Activity Status:	Canceled	**Performed by:**	
County Name:	King	**Project Manager:**	Liu, Jing
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	2007-10-12
VCP Prj No:	NW1836	**End Date:**	
Activity Name:	VCP Application	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	
VCP Prj No:	NW1836	**End Date:**	2010-01-19
Activity Name:	VCP Termination	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Media Contaminants

Contaminant Type:	Polynuclear Aromatic Hydrocarbons	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

Contaminant Type:	Petroleum Products-Unspecified	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

132	4 of 5	ENE	0.30 / 1,607.90	118.76 / 13	600 Wall Street 600 WALL ST SEATTLE WA 98121	VCP

Facility Site ID:	4456856	**County:**	King
Cleanup Site ID:	3327	**Latitude:**	47.618065

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Region: Northwest **Longitude:** -122.344475
Alternate Site Names: 600 Wall Street Apartments
Data Source(s): Confirmed and Suspected Contaminated Sites; Confirmed and Suspected Contaminated Sites; All Cleanup Sites in Washington State

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List

Site Status: Cleanup Started
Current VCP:
Past VCP: Yes
Site Rank:
Responsible Unit: Pollution Liability Ins Agcy
Has Inst Control:

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List - Contaminants

Contaminant Name: Petroleum Products-Unspecified **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Polycyclic Aromatic Hydrocarbons **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: Cleanup Started
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Pollution Liability Ins Agcy

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Petroleum Products-Unspecified **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Polycyclic Aromatic Hydrocarbons **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

132	5 of 5	ENE	0.30 / 1,607.90	118.76 / 13	600 Wall Street 600 Wall Street,Seattle, WA 98121 WA	LUST PTAP

FSID No: 4456856
TAP: PNW209
Status: In Progress
Entry Date: 3/31/2020
URL: https://plia.box.com/s/6ztlqdu2jxs7zv9z56ha0ouy3m9isy4z

133	1 of 1	SE	0.31 / 1,612.73	116.30 / 11	Consolidated Press Printing Co 2228 1ST AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID: 92236232

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAD004909305
Facility Alternate:
Interaction ID: 72031
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 26-Apr-1990
Interact End Dt: 31-Dec-1990
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.61297
GIS longitude: -122.34549

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
134	1 of 1	SE	0.31 / 1,619.72	71.06 / -35	Edelstein Assoc Advertising BE 50 BELL ST SEATTLE WA 98121	ALL SITES

Facility/Site ID: 65151445
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAD980986087
Facility Alternate:
Interaction ID: 56982
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 13-Aug-1986
Interact End Dt: 25-Feb-1988
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.61291
GIS longitude: -122.34716

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
135	1 of 5	E	0.31 / 1,620.12	128.73 / 23	Phom Property 2301 4th Ave / 314 Bell St SEATTLE WA 98121	CSCSL

Fac Site ID: 47763267
Cleanup Site ID: 2621
Site Status: Cleanup Started
Site Rank: 3 - Moderate Risk
Responsible Unit: Northwest
Fac Site ID (OD): 47763267
Cleanup SiteID(OD): 2621
Site Rank (OD): 3 - Moderate Risk

Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.615354210534
Longitude: -122.344506931987
Site Name: Phom Property
Address: 2301 4th Ave / 314 Bell St
City: SEATTLE
Zip Code: 98121
Site Status (OD): Cleanup Started
Site Name (OD): Phom Property
Address (OD): 2301 4th Ave / 314 Bell St
City (OD): SEATTLE
Zipcode (OD): 98121
Location (OD): ""
(47.615354, -122.344507)
Alternate Site Names: 314 Bell LLC,4th & Bell Property
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.344507
Latitude (OD): 47.615354

Contaminants Detail(s)

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air: Confirmed Above Cleanup Levels
Bedrock:

Contaminant Name: Other Non-Halogenated Organics
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Other Non-Halogenated Organics
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Air
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
135	2 of 5	E	0.31 / 1,620.12	128.73 / 23	Phom Property 2301 4th Ave / 314 Bell St SEATTLE WA 98121	HSL

Fac Site ID:	47763267	**Fac Site ID (OD):**	47763267
Cleanup Site ID:	2621	**Cleanup Site ID (OD):**	2621
Site Status:	Cleanup Started	**Site Status (OD):**	Cleanup Started
Site Rank:	3 - Moderate Risk	**Site Rank (OD):**	3 - Moderate Risk
Has Inst Control:		**Has Env Coven (OD):**	
Responsible Unit:	Northwest	**Respon Unit (OD):**	Northwest
County:	King	**County (OD):**	King
Region:	Northwest	**Region (OD):**	Northwest
Latitude:	47.615354210534	**Site Name (OD):**	Phom Property
Longitude:	-122.344506931987	**Address (OD):**	2301 4th Ave / 314 Bell St
Latitude (OD):	47.615354	**City (OD):**	SEATTLE
Longitude (OD):	-122.344507	**ZIP code (OD):**	98121
Current VCP:		**Past VCP:**	

Location (OD): ""
(47.615354, -122.344507)
Alternate Site Names: 314 Bell LLC,4th & Bell Property
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name:	Other Non-Halogenated Organics	**Sediment:**	
Groundwater:		**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Benzene	**Sediment:**	
Groundwater:		**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Petroleum-Gasoline	**Sediment:**	
Groundwater:		**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:	Confirmed Above Cleanup Levels		

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Benzene	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Other Non-Halogenated Organics	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Gasoline	**Contaminant Media:**	Air
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Gasoline	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
135	3 of 5	E	0.31 / 1,620.12	128.73 / 23	PHOM PROPERTY 2301 4th Ave / 314 Bell St SEATTLE WA 98121	ALL SITES

Facility/Site ID: 47763267
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 513632
Facility Alternate:

Interaction ID:	47209
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	LUST
Interaction Desc:	LUST Facility
Interact Start Dt:	04-Aug-1999
Interact End Dt:	
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System
Program ID:	513632
Facility Alternate:	
Interaction ID:	47210
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	UST
Interaction Desc:	Underground Storage Tank
Interact Start Dt:	24-Aug-1999
Interact End Dt:	
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	UST
Database Name Desc:	Underground Storage Tanks
Program ID:	
Facility Alternate:	PHOM PROPERTY
Interaction ID:	77889
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	SCS
Interaction Desc:	State Cleanup Site
Interact Start Dt:	10-Jul-2009
Interact End Dt:	
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Facility Location Detail

Horizontal:	40ft	**Location Verified:**	
Horizont 1:	NAD83HARN	**GIS latitude:**	47.6153542105
Horizont 2:	Digital map or GIS	**GIS longitude:**	-122.344506932

---

135 | ***4 of 5*** | ***E*** | ***0.31 / 1,620.12*** | ***128.73 / 23*** | ***Phom Property***
2301 4th Ave / 314 Bell St
SEATTLE WA 98121 | ***LUST***

Facility Site ID:	47763267	**County:**	King
Cleanup Site ID:	2621	**Latitude:**	47.615354210534
Responsible Unit:	Northwest	**Longitude:**	-122.344506931987
Region:	Northwest		
Alternate Site Names:	314 Bell LLC,4th & Bell Property		

Tank Detail(s)

UST ID:	513632	**Status Date:**	05/05/2015
LUST ID:	5384	**Release Date:**	08/04/1999
LUST Status:	LUST - Cleanup Started		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Gasoline	**Sediment:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Groundwater:		**Air:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Soil:	Confirmed Above Cleanup Levels		

Contaminants Detail(s)

Contaminant Name:	Other Non-Halogenated Organics	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Confirmed Above Cleanup Levels		

Contaminants Detail(s)

Contaminant Name:	Benzene	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Confirmed Above Cleanup Levels		

---

135 | **5 of 5** | **E** | **0.31 / 1,620.12** | **128.73 / 23** | **PHOM PROPERTY**
2301 4th Ave / 314 Bell St
SEATTLE WA 98121 | **ICR**

Cleanup Site ID:	2621	**WRIA ID:**	8
Facility Site ID:	47763267	**Is NFA Site:**	
Site Status:	Awaiting Cleanup	**Responsible Unit:**	Northwest
Statute:	MTCA	**Latitude:**	47.615354210533972
Rank:	3	**Longitude:**	-122.34450693198713
Rank Description:		**Legislative District:**	36
Has Env Covenant:		**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	1999-04-27
Activity Name:	Site Discovery/Release Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2013-02-27
Activity Name:	Early Notice Letter(s)	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Musa, Donna
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	2013-04-08
VCP Prj No:		**End Date:**	2013-06-28
Activity Name:	Site Hazard Assessment/Federal Site Inspection	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	Ecology w/ Contractor
County Name:	King	**Project Manager:**	Musa, Donna
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2013-03-22
Activity Name:	Early Notice Letter(s)	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Musa, Donna
Applies to:	CleanupSite		

Applies to Description:

Related ID:
VCP Prj No:
Activity Name: Hazardous Sites Listing/NPL
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date:
End Date: 2013-08-08
Legal Mechanism:
Performed by:
Project Manager: Musa, Donna

Related ID:
VCP Prj No:
Activity Name: Initial Investigation / Federal Preliminary Assessment
Activity Status: Completed
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date: 2009-03-12
End Date: 2009-04-07
Legal Mechanism:
Performed by: Ecology
Project Manager: Reid, Wallace

Related ID: 5384
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 2015-05-05
End Date: 2015-05-05
Legal Mechanism:
Performed by:
Project Manager:

Related ID: 5384
VCP Prj No:
Activity Name: LUST - Notification
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 1999-08-04
End Date: 1999-08-04
Legal Mechanism:
Performed by:
Project Manager: Colburn, Gail

Related ID: 5384
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 1999-04-27
End Date: 1999-08-04
Legal Mechanism:
Performed by:
Project Manager:

Related ID: 5384
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 2013-09-16
End Date: 2013-09-25
Legal Mechanism:
Performed by:
Project Manager:

Media Contaminants

Contaminant Type: Other Non-Halogenated Organics
Groundwater:
Groundwater Desc.:
Surface Water:
Surfacewater Desc.:
Soil: C
Soil Desc.: Confirmed Above Cleanup Level
Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

Contaminant Type: Benzene
Groundwater:
Groundwater Desc.:
Surface Water:
Surfacewater Desc.:
Soil: C
Soil Desc.: Confirmed Above Cleanup Level
Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant Type:	Petroleum-Gasoline	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	C
Surface Water:		**Air Desc.:**	Confirmed Above Cleanup Level
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

136	1 of 1	SE	0.31 / 1,637.74	117.55 / 12	The Belltown Collective LLC 2231 1st Ave Seattle WA 98121	ALL SITES

Facility/Site ID: 3723
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000050983
Facility Alternate: The Belltown Collective LLC
Interaction ID: 118594
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 10-Jun-2016
Interact End Dt: 31-Dec-2016
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	
Horizont 1:	NAD83	**GIS latitude:**	47.61294
Horizont 2:	Address	**GIS longitude:**	-122.34638

137	1 of 1	NE	0.32 / 1,665.56	117.29 / 12	LEVEL 3 COMMUNICATIONS SEATTLE STTLWATTA 223 TAYLOR AVE N SEATTLE WA 98109	ALL SITES

Facility/Site ID: 19494
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: CRK000085490
Facility Alternate: LEVEL 3 COMMUNICATIONS SEATTLE STTLWATTA
Interaction ID: 111744
Interaction Status: A
Interac Status Desc: Active
Interaction Type: TIER2
Interaction Desc: Emergency/Haz Chem Rpt TIER2
Interact Start Dt: 18-Feb-2015
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: EPCRA
Database Name Desc: Emergency Planning & Community Right-to-Know Act

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	
Horizont 1:	WGS84	***GIS latitude:***	47.62037
Horizont 2:	Address	***GIS longitude:***	-122.34667

138	*1 of 4*	*ENE*	*0.32 / 1,701.58*	*118.22 / 12*	***Stadium Shell*** ***620 DENNY WAY*** ***SEATTLE WA 98109***	***CSCSL NFA***

Fac Site ID:	41751629	***Fac Site ID (OD):***	41751629
Cleanup Site ID:	9568	***Cleanup SiteID(OD):***	9568
Site Status:	NFA	***Site Status (OD):***	No Further Action
NFA Date:	10/23/1997	***Rank (OD):***	
Responsible Unit:	Northwest	***Has Env Coven (OD):***	
Has Insti Control:		***Respon Unit (OD):***	Northwest
Region:	Northwest	***Region (OD):***	Northwest
County:	King	***County (OD):***	King
Latitude:	47.61889	***Latitude (OD):***	47.61889
Longitude:	-122.34407	***Longitude (OD):***	-122.34407

NFA Reason: Historic LUST
Alternate Site Names: DENNY WAY SHELL,DENNY WAY SHELL & LIQUOR,SPACE NEEDLE SHELL,STADIUM MARKET SHELL, Wrights Restaurant,WRIGHTS RESTAURANT FORMER
Location (OD): ""
(47.61889, -122.34407)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

NFA Contaminants Detail(s)

Contaminant Name:	Petroleum-Gasoline
Groundwater:	
Surfacewater:	
Soil:	Remediated
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Petroleum-Diesel
Groundwater:	
Surfacewater:	
Soil:	Remediated
Sediment:	
Air:	
Bedrock:	

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Petroleum-Gasoline
Contaminant Media:	Soil
Contaminant Status:	Remediated

Contaminant:	Petroleum-Diesel
Contaminant Media:	Soil
Contaminant Status:	Remediated

138	*2 of 4*	*ENE*	*0.32 / 1,701.58*	*118.22 / 12*	***DENNY WAY SHELL*** ***620 DENNY WAY*** ***SEATTLE WA 98109***	***ALL SITES***

Facility/Site ID: 41751629
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility/Site Interaction

Program ID:	459984
Facility Alternate:	
Interaction ID:	106772
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	LUST
Interaction Desc:	LUST Facility
Interact Start Dt:	22-Sep-1997
Interact End Dt:	23-Oct-1997
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Program ID:	459984
Facility Alternate:	DENNY WAY SHELL & LIQUOR
Interaction ID:	43352
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	UST
Interaction Desc:	Underground Storage Tank
Interact Start Dt:	10-Sep-1997
Interact End Dt:	
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	UST
Database Name Desc:	Underground Storage Tanks

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	
Horizont 1:	WGS84	***GIS latitude:***	47.61889
Horizont 2:	Address	***GIS longitude:***	-122.34407

138	*3 of 4*	*ENE*	*0.32 / 1,701.58*	*118.22 / 12*	***WRIGHTS RESTAURANT 620 DENNY WAY SEATTLE WA 98109***	*ICR*

Cleanup Site ID:	9568	***WRIA ID:***	8
Facility Site ID:	41751629	***Is NFA Site:***	Yes
Site Status:	No Further Action Required	***Responsible Unit:***	Northwest
Statute:	MTCA	***Latitude:***	47.61889
Rank:		***Longitude:***	-122.34407
Rank Description:		***Legislative District:***	36
Has Env Covenant:		***Congr District:***	7
Is Brownfiled Site:		***County Name:***	King
Is PSI Site:			

Cleanup Activities

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	1997-10-23
Activity Name:	Site Status Changed to NFA	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	CleanupSite		
Applies to Description:			

Related ID:	4722	***Start Date:***	1997-09-22
VCP Prj No:		***End Date:***	1997-09-22
Activity Name:	LUST - Notification	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	Cargill, Dan

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 4722
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Start Date: 1997-09-17
End Date: 1997-09-19
Legal Mechanism:
Performed by:
Project Manager:

Media Contaminants

Contaminant Type: Petroleum-Gasoline
Groundwater:
Groundwater Desc.:
Surface Water:
Surfacewater Desc.:
Soil: R
Soil Desc.: Remediated

Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

Contaminant Type: Petroleum-Diesel
Groundwater:
Groundwater Desc.:
Surface Water:
Surfacewater Desc.:
Soil: R
Soil Desc.: Remediated

Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

138	4 of 4	ENE	0.32 / 1,701.58	118.22 / 12	**Stadium Shell** **620 DENNY WAY** **SEATTLE WA 98109**	LUST

Facility Site ID: 41751629
Cleanup Site ID: 9568
Responsible Unit: Northwest
Region: Northwest
Alternate Site Names: DENNY WAY SHELL,DENNY WAY SHELL & LIQUOR,SPACE NEEDLE SHELL,STADIUM MARKET SHELL, Wrights Restaurant,WRIGHTS RESTAURANT FORMER

County: King
Latitude: 47.61889
Longitude: -122.34407

Tank Detail(s)

UST ID: 459984
LUST ID: 4722
LUST Status: LUST - NFA

Status Date: 10/23/1997
Release Date: 09/22/1997

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Remediated

Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Remediated

Sediment:
Air:
Bedrock:

139	1 of 1	W	0.33 / 1,758.53	27.79 / -78	**UNOCAL STATEWIDE LISTING** **3131 ELLIOTT AVE**	ALL SITES

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					SEATTLE WA 98121	

Facility/Site ID: 68176
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: CRK000015730
Facility Alternate: UNOCAL STATEWIDE LISTING
Interaction ID: 139326
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: TIER2
Interaction Desc: Emergency/Haz Chem Rpt TIER2
Interact Start Dt: 01-Jan-1987
Interact End Dt: 01-Jan-1988
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: EPCRA
Database Name Desc: Emergency Planning & Community Right-to-Know Act

Facility Location Detail

Horizontal: Unknown
Horizont 1: WGS84
Horizont 2: Address
Location Verified:
GIS latitude: 47.61789
GIS longitude: -122.35809

140	1 of 3	ESE	0.33 / 1,762.15	134.28 / 29	3rd Ave Redevelopment 2211 2217 3RD AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID: 15591
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: 3rd Ave Redevelopment
Interaction ID: 113600
Interaction Status: A
Interac Status Desc: Active
Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 24-Sep-2013
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: NW3038
Facility Alternate: 3rd Ave Redevelopment
Interaction ID: 117600
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 15-Jan-2016
Interact End Dt: 29-Sep-2016
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6140810343
GIS longitude: -122.344170777

---

140 **2 of 3** **ESE** **0.33 / 1,762.15** **134.28 / 29** **3rd Ave Redevelopment**
2211 2217 3RD AVE
SEATTLE WA 98121
VCP

Facility Site ID: 15591
Cleanup Site ID: 12690
Region: Northwest
Alternate Site Names: 3rd & Bell LLC,Grandview Condos
Data Source(s): No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State
County: King
Latitude: 47.6140810342905
Longitude: -122.344170777203

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status: NFA
NFA Date: 09/29/2016
Responsible Unit: Northwest
Has Inst Control:
NFA Reason: Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name: Other Non-Halogenated Organics
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: No Further Action
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Sediment:
Air:
Bedrock:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Soil: Remediated-Below

Contaminant Name: Other Non-Halogenated Organics
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

---

140 | ***3 of 3*** | ***ESE*** | ***0.33 / 1,762.15*** | ***134.28 / 29*** | ***3rd Ave Redevelopment***
2211 2217 3RD AVE
SEATTLE WA 98121 | ***CSCSL NFA***

Fac Site ID:	15591	***Fac Site ID (OD):***	15591
Cleanup Site ID:	12690	***Cleanup SiteID(OD):***	12690
Site Status:	NFA	***Site Status (OD):***	No Further Action
NFA Date:	09/29/2016	***Rank (OD):***	
Responsible Unit:	Northwest	***Has Env Coven (OD):***	
Has Insti Control:		***Respon Unit (OD):***	Northwest
Region:	Northwest	***Region (OD):***	Northwest
County:	King	***County (OD):***	King
Latitude:	47.6140810342905	***Latitude (OD):***	47.614081
Longitude:	-122.344170777203	***Longitude (OD):***	-122.344171

NFA Reason: Voluntary Cleanup Program Review
Alternate Site Names: 3rd & Bell LLC,Grandview Condos
Location (OD): ""
(47.614081, -122.344171)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

NFA Contaminants Detail(s)

Contaminant Name: Other Non-Halogenated Organics
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Other Non-Halogenated Organics
Contaminant Media: Soil
Contaminant Status: Remediated-Below

141	1 of 2	ESE	0.34 / 1,779.72	133.03 / 27	3rd Ave Redevelopment 2211 2217 3RD AVE SEATTLE WA 98121	DELISTED SHWS

Delisted Contaminated/Hazardous Sites

Fac Site ID: 15591
Cleanup Site ID: 12690
Brownfield?:
PSI?: Yes
VCP?: Yes
Past VCP:
Has Inst Control:
Site Status: Cleanup Started
Alternate Site Names:
Original Source: CSCS
Record Date: 21-NOV-2016

WARM Rank: N
Warm Rank Desc:
Respon Section: Northwest
County: King
Region: Northwest
Latitude: 47.6140810342905
Longitude: -122.344170777203

141	2 of 2	ESE	0.34 / 1,779.72	133.03 / 27	3rd Ave Redevelopment 2211 2217 3RD AVE SEATTLE WA 98121	ICR

Cleanup Site ID: 12690
Facility Site ID: 15591
Site Status: Awaiting Cleanup
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site: Yes

WRIA ID: 8
Is NFA Site:
Responsible Unit: Northwest
Latitude: 47.614081034290457
Longitude: -122.344170777203
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID:
VCP Prj No:
Activity Name: Site Discovery/Release Report Received
Activity Status:
County Name: King
Applies to: CleanupSite

Start Date:
End Date: 2013-07-08
Legal Mechanism:
Performed by:
Project Manager: Musa, Donna

Applies to Description:

Related ID:
VCP Prj No:
Activity Name: Initial Investigation / Federal Preliminary Assessment
Activity Status: Completed
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date: 2014-02-18
End Date: 2014-02-19
Legal Mechanism:
Performed by: Ecology
Project Manager: Myers, Dale R

Related ID:
VCP Prj No:
Activity Name: Ind - Report Received
Activity Status:
County Name: King
Applies to: Upland
Applies to Description:
Start Date:
End Date: 2013-06-24
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No:
Activity Name: Early Notice Letter(s)
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date:
End Date: 2015-09-09
Legal Mechanism:
Performed by:
Project Manager: Musa, Donna

Media Contaminants

Contaminant Type: Petroleum-Gasoline
Groundwater:
Groundwater Desc.:
Surface Water:
Surfacewater Desc.:
Soil: C
Soil Desc.: Confirmed Above Cleanup Level
Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

---

142 | ***1 of 5*** | ***WNW*** | ***0.34 / 1,790.09*** | ***79.97 / -26*** | ***133 Queen Anne Property 133 QUEEN ANNE AVE N SEATTLE WA 98109*** | ***CSCSL NFA***

Fac Site ID: 95244754
Cleanup Site ID: 6920
Site Status: NFA
NFA Date: 02/06/2001
Responsible Unit: Northwest
Has Insti Control:
Region: Northwest
County: King
Latitude: 47.6196234109109
Longitude: -122.35700667309
Fac Site ID (OD): 95244754
Cleanup SiteID(OD): 6920
Site Status (OD): No Further Action
Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
Region (OD): Northwest
County (OD): King
Latitude (OD): 47.619623
Longitude (OD): -122.357007
NFA Reason: Voluntary Cleanup Program Review
Alternate Site Names: 133 Queen Anne Ave N Property,Selano Condominium
Location (OD): ""
(47.619623, -122.357007)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

NFA Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
142	2 of 5	WNW	0.34 / 1,790.09	79.97 / -26	133 Queen Anne Ave N Property 133 QUEEN ANNE AVE N SEATTLE WA 98109	ALL SITES

Facility/Site ID: 95244754
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: 133 Queen Anne Ave N Property
Interaction ID: 74016
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 22-Nov-2000
Interact End Dt: 06-Feb-2001
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: 555461
Facility Alternate:
Interaction ID: 74014
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 11-Aug-2000
Interact End Dt: 12-Aug-2000
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: 555461
Facility Alternate:
Interaction ID: 74015
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: LUST
Interaction Desc: LUST Facility
Interact Start Dt: 21-Nov-2000
Interact End Dt: 06-Feb-2001
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6196234109
GIS longitude: -122.357006673

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
142	3 of 5	WNW	0.34 / 1,790.09	79.97 / -26	133 Queen Anne Property 133 QUEEN ANNE AVE N SEATTLE WA 98109	ICR

Cleanup Site ID: 6920
Facility Site ID: 95244754
Site Status: No Further Action Required
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site: Yes

WRIA ID: 8
Is NFA Site: Yes
Responsible Unit: Northwest
Latitude: 47.619623410910918
Longitude: -122.35700667309042
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID:
VCP Prj No:
Activity Name: Site Status Changed to NFA
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date:
End Date: 2001-02-06
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No: NW0577
Activity Name: VCP Opinion on Cleanup Action
Activity Status: Canceled
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date:
End Date:
Legal Mechanism:
Performed by:
Project Manager: Sato, Brian

Related ID: 5613
VCP Prj No:
Activity Name: LUST - Notification
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 2000-11-21
End Date: 2000-11-21
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No: NW0577
Activity Name: VCP Application
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2000-11-22
End Date:
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No: NW0577
Activity Name: VCP Termination
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date:
End Date: 2001-02-06
Legal Mechanism:
Performed by:
Project Manager:

Related ID: 5613
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 2000-11-15
End Date: 2000-11-21
Legal Mechanism:
Performed by:
Project Manager:

Media Contaminants

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant Type: Petroleum-Other
Groundwater:
Groundwater Desc.:
Surface Water:
Surfacewater Desc.:
Soil: C
Soil Desc.: Confirmed Above Cleanup Level
Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

---

142 **4 of 5** **WNW** **0.34 / 1,790.09** **79.97 / -26** **133 Queen Anne Property**
133 QUEEN ANNE AVE N
SEATTLE WA 98109 **VCP**

Facility Site ID: 95244754
Cleanup Site ID: 6920
Region: Northwest
Alternate Site Names: 133 Queen Anne Ave N Property,Selano Condominium
Data Source(s): No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State
County: King
Latitude: 47.6196234109109
Longitude: -122.35700667309

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status: NFA
NFA Date: 02/06/2001
Responsible Unit: Northwest
Has Inst Control:
NFA Reason: Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: No Further Action
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

---

142 **5 of 5** **WNW** **0.34 / 1,790.09** **79.97 / -26** **133 Queen Anne Property**
133 QUEEN ANNE AVE N
SEATTLE WA 98109 **LUST**

Facility Site ID: 95244754
Cleanup Site ID: 6920
Responsible Unit: Northwest
Region: Northwest
Alternate Site Names: 133 Queen Anne Ave N Property,Selano Condominium
County: King
Latitude: 47.6196234109109
Longitude: -122.35700667309

Tank Detail(s)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

UST ID: 555461
LUST ID: 5613
LUST Status: LUST - NFA
Status Date: 02/06/2001
Release Date: 11/21/2000

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

---

143 | 1 of 1 | ENE | 0.34 / 1,790.74 | 114.79 / 9 | Hauge & Hassain Inc, 207 6TH AVE N, SEATTLE WA 98109 | ALL SITES

Facility/Site ID: 14581645
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAD988477808
Facility Alternate:
Interaction ID: 28215
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 24-Sep-1990
Interact End Dt: 31-Jul-1997
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAD988477808
Facility Alternate:
Interaction ID: 28216
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWP
Interaction Desc: Hazardous Waste Planner
Interact Start Dt: 01-Jan-1993
Interact End Dt: 31-Dec-1993
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: HWPPRT
Database Name Desc: Hazardous Reporting

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.62007
GIS longitude: -122.34507

---

144 | 1 of 4 | WNW | 0.34 / 1,817.77 | 73.49 / -32 | Barrat Transfer & Storage, 123 QUEEN ANNE AVE N, SEATTLE WA 98109 | CSCSL NFA

Fac Site ID: 83727198
Cleanup Site ID: 10697
Site Status: NFA
NFA Date: 10/03/2011
Fac Site ID (OD): 83727198
Cleanup SiteID(OD): 10697
Site Status (OD): No Further Action
Rank (OD):

Responsible Unit:	Northwest	***Has Env Coven (OD):***	
Has Insti Control:		***Respon Unit (OD):***	Northwest
Region:	Northwest	***Region (OD):***	Northwest
County:	King	***County (OD):***	King
Latitude:	47.6193389959328	***Latitude (OD):***	47.619339
Longitude:	-122.357166252821	***Longitude (OD):***	-122.357166

NFA Reason: Initial Investigation
Alternate Site Names: BARRAT TRANSFER & STORAGE CO
Location (OD): ""
(47.619339, -122.357166)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

NFA Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Lead
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Benzene
Contaminant Media: Soil

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant Status: Remediated-Below

Contaminant: Lead
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Remediated-Below

---

144 **2 of 4** **WNW** **0.34 / 1,817.77** **73.49 / -32** **BARRAT TRANSFER & STORAGE CO**
123 QUEEN ANNE AVE N
SEATTLE WA 98109
ALL SITES

Facility/Site ID: 83727198
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 2454
Facility Alternate:
Interaction ID: 67342
Interaction Status: A
Interac Status Desc: Active
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 20-Mar-2000
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: 2454
Facility Alternate:
Interaction ID: 67341
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: LUST
Interaction Desc: LUST Facility
Interact Start Dt: 03-Dec-1998
Interact End Dt: 27-Nov-2001
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6193389959
GIS longitude: -122.357166253

---

144 **3 of 4** **WNW** **0.34 / 1,817.77** **73.49 / -32** **Barrat Transfer & Storage**
123 QUEEN ANNE AVE N
SEATTLE WA 98109
ICR

Cleanup Site ID: 10697
Facility Site ID: 83727198
Site Status: No Further Action Required
Statute: MTCA
Rank:
Rank Description:
WRIA ID: 8
Is NFA Site: Yes
Responsible Unit: Northwest
Latitude: 47.619338995932814
Longitude: -122.3571662528207
Legislative District: 36

Has Env Covenant:		***Congr District:***	7
Is Brownfiled Site:		***County Name:***	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	2011-10-03
Activity Name:	Site Status Changed to NFA	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	Olsen, Russ
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	1998-12-03
Activity Name:	Site Discovery/Release Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:	5242	***Start Date:***	1998-12-11
VCP Prj No:		***End Date:***	1998-12-18
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	2011-08-08
Activity Name:	Initial Investigation / Federal Preliminary Assessment	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	Ecology w/ Contractor
County Name:	King	***Project Manager:***	Olsen, Russ
Applies to:	CleanupSite		
Applies to Description:			

Related ID:	5242	***Start Date:***	1998-12-03
VCP Prj No:		***End Date:***	1998-12-03
Activity Name:	LUST - Notification	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	5242	***Start Date:***	1999-04-19
VCP Prj No:		***End Date:***	2001-12-04
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Media Contaminants

Contaminant Type:	Lead	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	RB	***Bedrock Desc.:***	
Soil Desc.:	Remediated-Below Cleanup Level	***County Name:***	King

Contaminant Type:	Petroleum-Diesel	***Sediment:***	
Groundwater:		***Sediment Desc.:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RB	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Below Cleanup Level	**County Name:**	King
Contaminant Type:	Petroleum-Other	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RB	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Below Cleanup Level	**County Name:**	King
Contaminant Type:	Benzene	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RB	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Below Cleanup Level	**County Name:**	King
Contaminant Type:	Petroleum-Gasoline	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RB	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Below Cleanup Level	**County Name:**	King

---

144 | ***4 of 4*** | ***WNW*** | ***0.34 / 1,817.77*** | ***73.49 / -32*** | ***Barrat Transfer & Storage***
123 QUEEN ANNE AVE N
SEATTLE WA 98109 | ***LUST***

Facility Site ID:	83727198	**County:**	King
Cleanup Site ID:	10697	**Latitude:**	47.6193389959328
Responsible Unit:	Northwest	**Longitude:**	-122.357166252821
Region:	Northwest		
Alternate Site Names:	BARRAT TRANSFER & STORAGE CO		

Tank Detail(s)

UST ID:	2454	**Status Date:**	10/03/2011
LUST ID:	5242	**Release Date:**	12/03/1998
LUST Status:	LUST - NFA		

Contaminants Detail(s)

Contaminant Name:	Benzene	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Below		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Other	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Below		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Diesel	**Sediment:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Remediated-Below

Contaminants Detail(s)

Contaminant Name: Lead **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Remediated-Below

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Remediated-Below

145	1 of 2	SSE	0.35 / 1,837.12	61.30 / -44	WA UW 2211 Elliott Ave 2211 ELLIOTT AVE SEATTLE WA 98101	ALL SITES

Facility/Site ID: 8218116
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000027427
Facility Alternate: WA UW 2211 Elliott Ave
Interaction ID: 117105
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 31-Dec-2015
Interact End Dt: 24-Aug-2016
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAH000027427
Facility Alternate: WA UW 2211 Elliott Ave
Interaction ID: 22258
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 25-Oct-2005
Interact End Dt: 31-Dec-2014
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAH000027427
Facility Alternate: WA UW 2211 Elliott Ave
Interaction ID: 111520
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWOTHER
Interaction Desc: Haz Waste Management Activity
Interact Start Dt: 31-Dec-2014
Interact End Dt: 31-Dec-2015

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Address
Location Verified:
GIS latitude: 47.61171
GIS longitude: -122.347389

145	2 of 2	SSE	0.35 / 1,837.12	61.30 / -44	Stratos Genomics 2211 Elliott Ave Ste 210 Seattle WA 98121	ALL SITES

Facility/Site ID: 36313
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000054514
Facility Alternate: Stratos Genomics
Interaction ID: 125881
Interaction Status: A
Interac Status Desc: Active
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 28-Mar-2018
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAH000054514
Facility Alternate: Stratos Genomics
Interaction ID: 131275
Interaction Status: A
Interac Status Desc: Active
Interaction Type: HWP
Interaction Desc: Hazardous Waste Planner
Interact Start Dt: 10-May-2019
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: HWPPRT
Database Name Desc: Hazardous Reporting

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Address
Location Verified:
GIS latitude: 47.61168
GIS longitude: -122.34778

146	1 of 1	ENE	0.35 / 1,846.67	113.11 / 7	Graphics West Typeline 217 6TH AVE N SEATTLE WA 98109	ALL SITES

Facility/Site ID: 48718895
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility/Site Interaction

Program ID: WAD020246237
Facility Alternate:
Interaction ID: 47643
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 01-Jul-1980
Interact End Dt: 20-Mar-1985
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.62017
GIS longitude: -122.34507

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
147	1 of 1	E	0.35 / 1,848.07	117.62 / 12	Frederick Cadillac 2301 6TH AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID: 42372258
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate:
Interaction ID: 43696
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 01-Jan-1976
Interact End Dt: 03-May-2000
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: WAD027473818
Facility Alternate:
Interaction ID: 43697
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 22-Aug-1986
Interact End Dt: 28-Dec-2000
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Location Verified: N
GIS latitude: 47.61687

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Horizont 2: Unknown **GIS longitude:** -122.34235

---

148 **1 of 1** **SSE** **0.35 / 1,851.81** **13.25 / -93**

Port of Seattle Pier 66
2201 ALASKAN WAY TERM 66
PIERCE MARINE
SEATTLE WA 98121

CSCSL

Fac Site ID: 94766722
Cleanup Site ID: 11167
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6107
Longitude: -122.348718

Responsible Unit: Northwest
Fac Site ID (OD): 94766722
Cleanup SiteID(OD): 11167
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.348718
Latitude (OD): 47.6107

Site Name: Port of Seattle Pier 66
Address: 2201 ALASKAN WAY TERM 66 PIERCE MARINE
City: SEATTLE
Zip Code: 98121
Site Status (OD): Cleanup Started
Site Name (OD): Port of Seattle Pier 66
Address (OD): 2201 ALASKAN WAY TERM 66 PIERCE MARINE
City (OD): SEATTLE
Zipcode (OD): 98121
Location (OD): ""
(47.6107, -122.348718)
Alternate Site Names: BELL ST TERMINAL PIER 66,Seattle Port Term 66
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Non-Halogenated Solvents
Groundwater: Suspected
Surfacewater: Suspected
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Organotins
Groundwater:
Surfacewater: Suspected
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater: Confirmed Above Cleanup Levels
Surfacewater: Suspected
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Arsenic
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel

Groundwater: Suspected
Surfacewater: Suspected
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Suspected
Surfacewater: Suspected
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater: Suspected
Surfacewater: Suspected
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Lead
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Metals - Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater: Suspected
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Suspected
Surfacewater: Suspected
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Tributyltin
Contaminant Media: Surface Water
Contaminant Status: Suspected

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Metals - Other
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Surface Water
Contaminant Status: Suspected

Contaminant: Lead
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals - Other
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum-Gasoline
Contaminant Media: Surface Water
Contaminant Status: Suspected

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Surface Water
Contaminant Status: Suspected

Contaminant: Petroleum-Diesel
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum-Diesel
Contaminant Media: Surface Water
Contaminant Status: Suspected

Contaminant: Metals - Other
Contaminant Media: Surface Water
Contaminant Status: Suspected

Contaminant: Arsenic
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Non-Halogenated Solvents
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Non-Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Surface Water
Contaminant Status: Suspected

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant: Non-Halogenated Solvents
Contaminant Media: Surface Water
Contaminant Status: Suspected

---

149 | 1 of 3 | SSE | 0.35 / 1,853.03 | 13.25 / -93 | **Seattle Port Term 66**
2201 ALASKAN WAY TERM 66
PIERCE MARINE
SEATTLE WA 98121 | ALL SITES

Facility/Site ID: 94766722
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAD009483694
Facility Alternate: Seattle Port Term 66
Interaction ID: 73718
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWOTHER
Interaction Desc: Haz Waste Management Activity
Interact Start Dt: 31-Dec-2003
Interact End Dt: 31-Dec-2011
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAD009483694
Facility Alternate: Seattle Port Term 66
Interaction ID: 104065
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWOTHER
Interaction Desc: Haz Waste Management Activity
Interact Start Dt: 31-Dec-2012
Interact End Dt: 31-Dec-2020
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: 6270
Facility Alternate:
Interaction ID: 73717
Interaction Status: A
Interac Status Desc: Active
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 20-Mar-2000
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: WAD009483694
Facility Alternate: Seattle Port Term 66
Interaction ID: 99493
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 31-Dec-2011
Interact End Dt: 31-Dec-2012
Ecology Program: HAZWASTE

Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: 6270
Facility Alternate:
Interaction ID: 73716
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: LUST
Interaction Desc: LUST Facility
Interact Start Dt: 27-Aug-1990
Interact End Dt: 14-Oct-1998
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: WAD009483694
Facility Alternate:
Interaction ID: 73715
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 30-May-1986
Interact End Dt: 02-Mar-2004
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAD009483694
Facility Alternate: Seattle Port Term 66
Interaction ID: 126774
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWP
Interaction Desc: Hazardous Waste Planner
Interact Start Dt: 16-Mar-2018
Interact End Dt: 01-May-2018
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: HWPPRT
Database Name Desc: Hazardous Reporting

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83
Horizont 2: Address
Location Verified: N
GIS latitude: 47.6107
GIS longitude: -122.348718

---

149 **2 of 3** **SSE** **0.35 / 1,853.03** **13.25 / -93**

Port of Seattle Pier 66
2201 ALASKAN WAY TERM 66
PIERCE MARINE
SEATTLE WA 98121

LUST

Facility Site ID: 94766722
Cleanup Site ID: 11167
Responsible Unit: Northwest
Region: Northwest
County: King
Latitude: 47.6107
Longitude: -122.348718
Alternate Site Names: BELL ST TERMINAL PIER 66,Seattle Port Term 66

Tank Detail(s)

UST ID: 6270
Status Date: 07/01/2011

LUST ID: 1347
LUST Status: LUST - Cleanup Started
Release Date: 08/27/1990

Contaminants Detail(s)

Contaminant Name: Metals - Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater: Suspected
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Non-Halogenated Solvents
Groundwater: Suspected
Surfacewater: Suspected
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Arsenic
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Organotins
Groundwater:
Surfacewater: Suspected
Soil:
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Lead
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater: Suspected
Surfacewater: Suspected
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater: Confirmed Above Cleanup Levels
Surfacewater: Suspected
Soil:
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Petroleum-Diesel
Groundwater: Suspected
Surfacewater: Suspected
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminants Detail(s)

Contaminant Name:	Benzene	***Sediment:***	
Groundwater:	Suspected	***Air:***	
Surfacewater:	Suspected	***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Gasoline	***Sediment:***	
Groundwater:	Suspected	***Air:***	
Surfacewater:	Suspected	***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		

149	*3 of 3*	*SSE*	*0.35 / 1,853.03*	*13.25 / -93*	***SEATTLE PORT OF BELL ST PIER 66*** ***2201 ALASKAN WAY TERM 66*** ***PIERCE MARINE*** ***SEATTLE WA 98121***	*ICR*

Cleanup Site ID:	11167	***WRIA ID:***	8
Facility Site ID:	94766722	***Is NFA Site:***	
Site Status:	Cleanup Started	***Responsible Unit:***	Northwest
Statute:	MTCA	***Latitude:***	47.610700000000001
Rank:		***Longitude:***	-122.34871800000001
Rank Description:		***Legislative District:***	36
Has Env Covenant:		***Congr District:***	7
Is Brownfiled Site:		***County Name:***	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:	1347	***Start Date:***	1990-08-21
VCP Prj No:		***End Date:***	1990-08-21
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	1347	***Start Date:***	1991-12-17
VCP Prj No:		***End Date:***	1991-12-17
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	1990-08-27
Activity Name:	Site Discovery/Release Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:	1347	***Start Date:***	1990-08-27
VCP Prj No:		***End Date:***	1990-08-27
Activity Name:	LUST - Notification	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	1347	***Start Date:***	1993-04-30

VCP Prj No:		**End Date:**	1993-04-30
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	1347	**Start Date:**	1990-09-20
VCP Prj No:		**End Date:**	1990-09-20
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	1347	**Start Date:**	1992-02-10
VCP Prj No:		**End Date:**	1992-02-10
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	1347	**Start Date:**	1995-09-21
VCP Prj No:		**End Date:**	1998-10-14
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2013-02-28
Activity Name:	Early Notice Letter(s)	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Olsen, Russ
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	2011-08-08
VCP Prj No:		**End Date:**	2011-08-08
Activity Name:	Initial Investigation / Federal Preliminary Assessment	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	Ecology w/ Contractor
County Name:	King	**Project Manager:**	Olsen, Russ
Applies to:	CleanupSite		
Applies to Description:			

Related ID:	1347	**Start Date:**	1994-07-15
VCP Prj No:		**End Date:**	1998-10-14
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	1347	**Start Date:**	1993-08-03
VCP Prj No:		**End Date:**	1993-08-03
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	1347	**Start Date:**	1995-09-15
VCP Prj No:		**End Date:**	1995-09-29
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	

Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Media Contaminants

Contaminant Type: Benzene
Groundwater: S
Groundwater Desc.: Suspected
Surface Water: S
Surfacewater Desc.: Suspected
Soil: C
Soil Desc.: Confirmed Above Cleanup Level
Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

Contaminant Type: Metals - Other
Groundwater: C
Groundwater Desc.: Confirmed Above Cleanup Level
Surface Water: S
Surfacewater Desc.: Suspected
Soil: S
Soil Desc.: Suspected
Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

Contaminant Type: Polynuclear Aromatic Hydrocarbons
Groundwater: C
Groundwater Desc.: Confirmed Above Cleanup Level
Surface Water: S
Surfacewater Desc.: Suspected
Soil:
Soil Desc.:
Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

Contaminant Type: Petroleum-Diesel
Groundwater: S
Groundwater Desc.: Suspected
Surface Water: S
Surfacewater Desc.: Suspected
Soil: C
Soil Desc.: Confirmed Above Cleanup Level
Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

Contaminant Type: Petroleum-Gasoline
Groundwater: S
Groundwater Desc.: Suspected
Surface Water: S
Surfacewater Desc.: Suspected
Soil: C
Soil Desc.: Confirmed Above Cleanup Level
Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

Contaminant Type: Lead
Groundwater: C
Groundwater Desc.: Confirmed Above Cleanup Level
Surface Water:
Surfacewater Desc.:
Soil:
Soil Desc.:
Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

Contaminant Type: Non-Halogenated Solvents
Groundwater: S
Groundwater Desc.: Suspected
Surface Water: S
Surfacewater Desc.: Suspected
Soil: C
Soil Desc.: Confirmed Above Cleanup Level
Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

Contaminant Type: Petroleum-Other
Groundwater: S
Groundwater Desc.: Suspected
Surface Water: S
Surfacewater Desc.: Suspected
Soil: C
Soil Desc.: Confirmed Above Cleanup Level
Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

Contaminant Type:	Tributyltin	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:	S	**Air Desc.:**	
Surfacewater Desc.:	Suspected	**Bedrock:**	
Soil:		**Bedrock Desc.:**	
Soil Desc.:		**County Name:**	King

Contaminant Type:	Arsenic	**Sediment:**	
Groundwater:	C	**Sediment Desc.:**	
Groundwater Desc.:	Confirmed Above Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:		**Bedrock Desc.:**	
Soil Desc.:		**County Name:**	King

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
150	1 of 6	E	0.35 / 1,867.33	116.95 / 11	ELEPHANT CAR WASH UST 4919 616 BATTERY ST SEATTLE WA 98121-1538	ALL SITES

Facility/Site ID: 66184117
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	4919
Facility Alternate:	
Interaction ID:	57581
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	LUST
Interaction Desc:	LUST Facility
Interact Start Dt:	20-Jan-1994
Interact End Dt:	19-Jun-2000
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Program ID:	NW2831
Facility Alternate:	ELEPHANT CAR WASH UST 4919
Interaction ID:	107252
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	VOLCLNST
Interaction Desc:	Voluntary Cleanup Sites
Interact Start Dt:	04-Feb-2014
Interact End Dt:	06-Apr-2015
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Program ID:	4919
Facility Alternate:	
Interaction ID:	57580
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	UST
Interaction Desc:	Underground Storage Tank
Interact Start Dt:	01-Jan-1978
Interact End Dt:	09-Dec-2013
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	UST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Database Name Desc: Underground Storage Tanks

Facility Location Detail

Horizontal:	20ft	**Location Verified:**	N
Horizont 1:	NAD83	**GIS latitude:**	47.6205
Horizont 2:	Address	**GIS longitude:**	-122.3462

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
150	2 of 6	E	0.35 / 1,867.33	116.95 / 11	ELEPHANT CAR WASH 616 BATTERY ST SEATTLE WA 98121-1538	DELISTED LST

Delisted Leaking Storage Tanks

Facility Site ID:	66184117	**Latitude:**	47.6205
Cleanup Site ID:	10077	**Longitude:**	-122.3462
Responsible Section:	Northwest	**Original Source:**	LUST
Region:	Northwest	**Record Date:**	22-JUL-2015
County:	King		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
150	3 of 6	E	0.35 / 1,867.33	116.95 / 11	Elephant Car Wash 616 Battery St Seattle WA 98121	CSCSL NFA

Fac Site ID:	66184117	**Fac Site ID (OD):**	66184117
Cleanup Site ID:	10077	**Cleanup SiteID(OD):**	10077
Site Status:	NFA	**Site Status (OD):**	No Further Action
NFA Date:	04/06/2015	**Rank (OD):**	
Responsible Unit:	Northwest	**Has Env Coven (OD):**	
Has Insti Control:		**Respon Unit (OD):**	Northwest
Region:	Northwest	**Region (OD):**	Northwest
County:	King	**County (OD):**	King
Latitude:	47.6180503045473	**Latitude (OD):**	47.6205
Longitude:	-122.343247561875	**Longitude (OD):**	-122.3462

NFA Reason: Voluntary Cleanup Program Review
Alternate Site Names: ELEPHANT CAR WASH UST 4919
Location (OD): ""
(47.6205, -122.3462)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

NFA Contaminants Detail(s)

Contaminant Name: Benzene
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Other Non-Halogenated Organics
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Remediated-Below

Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Below Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Below Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Below Cleanup Levels

Contaminant: Other Non-Halogenated Organics
Contaminant Media: Groundwater
Contaminant Status: Below Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Groundwater
Contaminant Status: Below Cleanup Levels

Contaminant: Other Non-Halogenated Organics
Contaminant Media: Soil
Contaminant Status: Remediated-Below

150	***4 of 6***	***E***	***0.35 / 1,867.33***	***116.95 / 11***	***ELEPHANT CAR WASH 616 BATTERY ST SEATTLE WA 98121-1538***	***ICR***

Cleanup Site ID: 10077 ***WRIA ID:*** 8

Facility Site ID:	66184117	**Is NFA Site:**	Yes
Site Status:	No Further Action Required	**Responsible Unit:**	Northwest
Statute:	MTCA	**Latitude:**	47.6205
Rank:		**Longitude:**	-122.3462
Rank Description:		**Legislative District:**	36
Has Env Covenant:		**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:			

Cleanup Activities

Related ID:	3288	**Start Date:**	2014-01-03
VCP Prj No:		**End Date:**	2014-01-28
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	1994-01-20
Activity Name:	Site Discovery/Release Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:	3288	**Start Date:**	2013-01-03
VCP Prj No:		**End Date:**	2014-01-28
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		**Start Date:**	2014-01-28
VCP Prj No:	NW2831	**End Date:**	
Activity Name:	VCP Application	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Fernandez, Sonia
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2015-04-06
Activity Name:	Site Status Changed to NFA	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Freier-Coppinger, Romy
Applies to:	CleanupSite		
Applies to Description:			

Related ID:	3288	**Start Date:**	2015-01-05
VCP Prj No:		**End Date:**	2015-01-20
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		**Start Date:**	2015-01-20
VCP Prj No:	NW2831	**End Date:**	2015-04-06
Activity Name:	VCP Opinion on Site Cleanup	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Freier-Coppinger, Romy
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	2011-08-08

VCP Prj No:		***End Date:***	2011-08-08
Activity Name:	Initial Investigation / Federal Preliminary Assessment	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	Ecology w/ Contractor
County Name:	King	***Project Manager:***	Olsen, Russ
Applies to:	CleanupSite		
Applies to Description:			

Related ID:	3288	***Start Date:***	1994-01-20
VCP Prj No:		***End Date:***	1994-01-20
Activity Name:	LUST - Notification	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	3288	***Start Date:***	1994-01-24
VCP Prj No:		***End Date:***	1994-01-24
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	3288	***Start Date:***	2013-12-12
VCP Prj No:		***End Date:***	2014-01-28
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	2013-05-07
Activity Name:	Early Notice Letter(s)	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	Bardy, Louise
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		***Start Date:***	
VCP Prj No:	NW2831	***End Date:***	2015-04-06
Activity Name:	VCP Termination	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Fernandez, Sonia
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	2014-02-04
VCP Prj No:	NW2831	***End Date:***	2014-02-28
Activity Name:	VCP Opinion on Site Cleanup	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Freier-Coppinger, Romy
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Media Contaminants

Contaminant Type:	Other Non-Halogenated Organics	***Sediment:***	
Groundwater:	B	***Sediment Desc.:***	
Groundwater Desc.:	Below Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	RB	***Bedrock Desc.:***	
Soil Desc.:	Remediated-Below Cleanup Level	***County Name:***	King

Contaminant Type:	Petroleum-Diesel	***Sediment:***	
Groundwater:	B	***Sediment Desc.:***	

Groundwater Desc.:	Below Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RB	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Below Cleanup Level	**County Name:**	King
Contaminant Type:	Petroleum-Gasoline	**Sediment:**	
Groundwater:	B	**Sediment Desc.:**	
Groundwater Desc.:	Below Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RB	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Below Cleanup Level	**County Name:**	King
Contaminant Type:	Benzene	**Sediment:**	
Groundwater:	B	**Sediment Desc.:**	
Groundwater Desc.:	Below Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RB	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Below Cleanup Level	**County Name:**	King
Contaminant Type:	Petroleum-Other	**Sediment:**	
Groundwater:	B	**Sediment Desc.:**	
Groundwater Desc.:	Below Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RB	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Below Cleanup Level	**County Name:**	King

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
150	5 of 6	E	0.35 / 1,867.33	116.95 / 11	**Elephant Car Wash** **616 Battery St** **Seattle WA 98121**	VCP

Facility Site ID:	66184117	**County:**	King
Cleanup Site ID:	10077	**Latitude:**	47.6180503045473
Region:	Northwest	**Longitude:**	-122.343247561875
Alternate Site Names:	ELEPHANT CAR WASH UST 4919		
Data Source(s):	No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State		

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status:	NFA
NFA Date:	04/06/2015
Responsible Unit:	Northwest
Has Inst Control:	
NFA Reason:	Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name:	Benzene	**Sediment:**	
Groundwater:	Below Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Below		
Contaminant Name:	Petroleum-Gasoline	**Sediment:**	
Groundwater:	Below Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Below		
Contaminant Name:	Petroleum-Diesel	**Sediment:**	
Groundwater:	Below Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Below		
Contaminant Name:	Other Non-Halogenated Organics	**Sediment:**	

Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: No Further Action
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Benzene
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Other Non-Halogenated Organics
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

---

150 | ***6 of 6*** | ***E*** | ***0.35 / 1,867.33*** | ***116.95 / 11*** | ***Elephant Car Wash***
616 Battery St
Seattle WA 98121 | ***LUST***

Facility Site ID: 66184117
Cleanup Site ID: 10077
Responsible Unit: Northwest
Region: Northwest
Alternate Site Names: ELEPHANT CAR WASH UST 4919
County: King
Latitude: 47.6180503045473
Longitude: -122.343247561875

Tank Detail(s)

UST ID: 4919
LUST ID: 3288
LUST Status: LUST - NFA
Status Date: 04/06/2015
Release Date: 01/20/1994

Contaminants Detail(s)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant Name: Petroleum-Diesel
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Other Non-Halogenated Organics
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Benzene
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

151	*1 of 7*	*SE*	*0.36 / 1,875.55*	*100.57 / -5*	***2200 Western Avenue LLC*** ***2200 Western Ave*** ***Seattle WA 98121***	***ALL SITES***

Facility/Site ID: 12551
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000047035
Facility Alternate: 2200 Western Avenue LLC
Interaction ID: 120740
Interaction Status: A
Interac Status Desc: Active
Interaction Type: HWOTHER
Interaction Desc: Haz Waste Management Activity
Interact Start Dt: 31-Dec-2016
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID:
Facility Alternate: 2200 Western Avenue LLC
Interaction ID: 113010
Interaction Status: A
Interac Status Desc: Active

Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 31-Dec-2014
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: WAH000047035
Facility Alternate: 2200 Western Avenue LLC
Interaction ID: 109112
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 10-Jun-2014
Interact End Dt: 31-Dec-2016
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: NW2988
Facility Alternate: 2200 Western Avenue LLC
Interaction ID: 113773
Interaction Status: A
Interac Status Desc: Active
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 16-Jun-2015
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Address
Location Verified:
GIS latitude: 47.6123
GIS longitude: -122.3461

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
151	2 of 7	SE	0.36 / 1,875.55	100.57 / -5	2200 Western Avenue LLC 2200 Western Ave Seattle WA 98121	VCP

Facility Site ID: 12551
Cleanup Site ID: 12648
Region: Northwest
Alternate Site Names:
Data Source(s): No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State
County: King
Latitude: 47.6123
Longitude: -122.3461

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status: NFA
NFA Date: 05/28/2019
Responsible Unit: Northwest
Has Inst Control: Yes
NFA Reason: Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name: Benzene
Groundwater:
Sediment:
Air: Remediated-Below

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Surfacewater: ***Bedrock:***
Soil: Remediated-Below

Contaminant Name: Petroleum-Gasoline ***Sediment:***
Groundwater: ***Air:*** Remediated-Below
Surfacewater: ***Bedrock:***
Soil: Remediated-Below

Contaminant Name: Petroleum-Other ***Sediment:***
Groundwater: ***Air:*** Remediated-Below
Surfacewater: ***Bedrock:***
Soil: Remediated-Below

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: No Further Action
Site Rank:
Has Inst Control: Yes
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Petroleum-Other ***Sediment:***
Groundwater: ***Air:*** Remediated-Below
Surfacewater: ***Bedrock:***
Soil: Remediated-Below

Contaminant Name: Benzene ***Sediment:***
Groundwater: ***Air:*** Remediated-Below
Surfacewater: ***Bedrock:***
Soil: Remediated-Below

Contaminant Name: Petroleum-Gasoline ***Sediment:***
Groundwater: ***Air:*** Remediated-Below
Surfacewater: ***Bedrock:***
Soil: Remediated-Below

151	*3 of 7*	*SE*	*0.36 / 1,875.55*	*100.57 / -5*	*2200 Western Avenue LLC* *2200 Western Ave* *Seattle WA 98121*	*DELISTED SHWS*

Delisted Contaminated/Hazardous Sites

Fac Site ID: 12551 ***WARM Rank:*** N
Cleanup Site ID: 12648 ***Warm Rank Desc:***
Brownfield?: ***Respon Section:*** Headquarters
PSI?: Yes ***County:*** King
VCP?: Yes ***Region:*** Northwest
Past VCP: ***Latitude:*** 47.6123
Has Inst Control: ***Longitude:*** -122.3461
Site Status: Cleanup Started
Alternate Site Names:
Original Source: CSCS
Record Date: 11-MAR-2019

151	*4 of 7*	*SE*	*0.36 / 1,875.55*	*100.57 / -5*	*2200 Western Avenue LLC* *2200 Western Ave* *Seattle WA 98121*	*ICR*

Cleanup Site ID: 12648 ***WRIA ID:*** 8
Facility Site ID: 12551 ***Is NFA Site:***

Site Status:	Cleanup Started	***Responsible Unit:***	Northwest
Statute:	MTCA	***Latitude:***	47.612299999999998
Rank:		***Longitude:***	-122.34610000000001
Rank Description:		***Legislative District:***	36
Has Env Covenant:		***Congr District:***	7
Is Brownfiled Site:		***County Name:***	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		***Start Date:***	2015-06-16
VCP Prj No:	NW2988	***End Date:***	
Activity Name:	VCP Receipt of Plan or Report	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Fernandez, Sonia
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	2015-06-16
VCP Prj No:	NW2988	***End Date:***	2015-08-10
Activity Name:	VCP Opinion on Remedial Investigation	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Cardona-Marek, Tamara
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	2015-06-16
VCP Prj No:	NW2988	***End Date:***	
Activity Name:	VCP Application	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Fernandez, Sonia
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	2014-07-18
Activity Name:	Site Discovery/Release Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	Musa, Donna
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	2015-05-01
Activity Name:	Early Notice Letter(s)	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	Musa, Donna
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		***Start Date:***	2014-12-08
VCP Prj No:		***End Date:***	2014-12-15
Activity Name:	Initial Investigation / Federal Preliminary Assessment	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	Ecology
County Name:	King	***Project Manager:***	Tomlinson, Priscilla
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	2014-06-16
Activity Name:	Ind - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	Upland		
Applies to Description:			

Media Contaminants

Contaminant Type:	Petroleum-Gasoline	***Sediment:***	
Groundwater:	S	***Sediment Desc.:***	
Groundwater Desc.:	Suspected	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

Contaminant Type:	Halogenated Solvents	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	B	***Bedrock Desc.:***	
Soil Desc.:	Below Cleanup Level	***County Name:***	King

Contaminant Type:	Petroleum-Diesel	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	B	***Bedrock Desc.:***	
Soil Desc.:	Below Cleanup Level	***County Name:***	King

Contaminant Type:	Mercury	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	B	***Bedrock Desc.:***	
Soil Desc.:	Below Cleanup Level	***County Name:***	King

Contaminant Type:	Polynuclear Aromatic Hydrocarbons	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	B	***Bedrock Desc.:***	
Soil Desc.:	Below Cleanup Level	***County Name:***	King

Contaminant Type:	Benzene	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	B	***Bedrock Desc.:***	
Soil Desc.:	Below Cleanup Level	***County Name:***	King

Contaminant Type:	Lead	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	B	***Bedrock Desc.:***	
Soil Desc.:	Below Cleanup Level	***County Name:***	King

Contaminant Type:	Arsenic	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	B	***Bedrock Desc.:***	
Soil Desc.:	Below Cleanup Level	***County Name:***	King

Contaminant Type:	Petroleum-Other	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	B	**Bedrock Desc.:**	
Soil Desc.:	Below Cleanup Level	**County Name:**	King
Contaminant Type:	Metals - Other	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	B	**Bedrock Desc.:**	
Soil Desc.:	Below Cleanup Level	**County Name:**	King
Contaminant Type:	Non-Halogenated Solvents	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	B	**Bedrock Desc.:**	
Soil Desc.:	Below Cleanup Level	**County Name:**	King
Contaminant Type:	Other Non-Halogenated Organics	**Sediment:**	
Groundwater:	S	**Sediment Desc.:**	
Groundwater Desc.:	Suspected	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

---

151	***5 of 7***	***SE***	***0.36 / 1,875.55***	***100.57 / -5***	***2200 Western Avenue LLC 2200 Western Ave Seattle WA 98121***	***CSCSL NFA***

Fac Site ID:	12551	**Fac Site ID (OD):**	
Cleanup Site ID:	12648	**Cleanup SiteID(OD):**	
Site Status:	NFA	**Site Status (OD):**	
NFA Date:	05/28/2019	**Rank (OD):**	
Responsible Unit:	Northwest	**Has Env Coven (OD):**	
Has Insti Control:	Yes	**Respon Unit (OD):**	
Region:	Northwest	**Region (OD):**	
County:	King	**County (OD):**	
Latitude:	47.6123	**Latitude (OD):**	
Longitude:	-122.3461	**Longitude (OD):**	
NFA Reason:	Voluntary Cleanup Program Review		
Alternate Site Names:			
Location (OD):			
Data Source(s):	Department of Ecology - Washington		

NFA Contaminants Detail(s)

Contaminant Name:	Petroleum-Gasoline
Groundwater:	
Surfacewater:	
Soil:	Remediated-Below
Sediment:	
Air:	Remediated-Below
Bedrock:	
Contaminant Name:	Benzene
Groundwater:	
Surfacewater:	
Soil:	Remediated-Below
Sediment:	
Air:	Remediated-Below
Bedrock:	
Contaminant Name:	Petroleum-Other

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air: Remediated-Below
Bedrock:

---

151 | ***6 of 7*** | ***SE*** | ***0.36 / 1,875.55*** | ***100.57 / -5*** | ***2200 Western Avenue LLC***
2200 Western Ave
Seattle WA 98121 | ***INST***

Facility Site ID: 12551
Region: Northwest
County: King
Latitude: 47.6123
Longitude: -122.3461
Site Name: 2200 Western Avenue LLC
Address: 2200 Western Ave
City: Seattle
Zip: 98121
Site Name (OD):
Address (OD):
City (OD):
Zipcode (OD):
Location (OD):
Data Source(s): Department of Ecology State of Washington - Environmental Covenants Registry List

Cleanup Site ID: 12648
Region (OD):
County (OD):
Latitude (OD):
Longitude (OD):

Environmental Covenants Registry List

NFA Date: 05/28/2019
Site Status: No Further Action
Tax Parcel No: 197720-0605
Instrument Type: Environmental Covenant
Media Restrictions: Soil
Alternate Site Names:
Cnty Recording No: 20190515000761
Cnty Recording Dt: 05/15/2019
Responsible Unit: Northwest
Active Control: Yes
Control Stormwater: No
Control Vapor Gas: Yes
Prevent Reuse/Relocation: No
Prohibit New Bldg Constr: No
Prohibit Removal or Alteration: Yes
Prohibit Soil Disturbance: Yes
Ongoing Maint of Remedy: No
Require Educational Programs: No
Restrict Access: No
Restrict All GW Extr: No
Restrict Domestic GW: No
Restrict Land Use: Yes
Restrict Sedmnt Cap Disturb: No
Restrict Shellfish and or Finf: No
Restrict Surface Water Use: No
Restrict Swim/Beach Play: No
Restrictive Signage: No
Maintain/Protect Monit System: No
Other: No

---

151 | ***7 of 7*** | ***SE*** | ***0.36 / 1,875.55*** | ***100.57 / -5*** | ***2200 Western Avenue LLC***
2200 Western Ave
Seattle WA 98121 | ***CSCSL***

Fac Site ID:
Cleanup Site ID:
Site Status:

Responsible Unit:
Fac Site ID (OD): 12551
Cleanup SiteID(OD): 12648

Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:		**Respon Unit (OD):**	Headquarters
Has Inst Control:		**County (OD):**	King
County:		**Region (OD):**	Northwest
Region:		**Longitude (OD):**	-122.3461
Latitude:		**Latitude (OD):**	47.6123
Longitude:			
Site Name:			
Address:			
City:			
Zip Code:			
Site Status (OD):	Cleanup Started		
Site Name (OD):	2200 Western Avenue LLC		
Address (OD):	2200 Western Ave		
City (OD):	Seattle		
Zipcode (OD):	98121		
Location (OD):	"" (47.6123, -122.3461)		
Alternate Site Names:			
Data Source(s):	Cleanup Sites (Open Data Portal)		

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Other Non-Halogenated Organics
Contaminant Media:	Soil
Contaminant Status:	Confirmed Above Cleanup Levels
Contaminant:	Halogenated Solvents
Contaminant Media:	Soil
Contaminant Status:	Below Cleanup Levels
Contaminant:	Petroleum-Gasoline
Contaminant Media:	Groundwater
Contaminant Status:	Suspected
Contaminant:	Polycyclic Aromatic Hydrocarbons
Contaminant Media:	Soil
Contaminant Status:	Below Cleanup Levels
Contaminant:	Petroleum-Other
Contaminant Media:	Soil
Contaminant Status:	Below Cleanup Levels
Contaminant:	Metals - Other
Contaminant Media:	Soil
Contaminant Status:	Below Cleanup Levels
Contaminant:	Petroleum-Diesel
Contaminant Media:	Soil
Contaminant Status:	Below Cleanup Levels
Contaminant:	Petroleum-Gasoline
Contaminant Media:	Soil
Contaminant Status:	Confirmed Above Cleanup Levels
Contaminant:	Other Non-Halogenated Organics
Contaminant Media:	Groundwater
Contaminant Status:	Suspected
Contaminant:	Mercury
Contaminant Media:	Soil
Contaminant Status:	Below Cleanup Levels
Contaminant:	Lead
Contaminant Media:	Soil
Contaminant Status:	Below Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Non-Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Arsenic
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
152	1 of 1	SE	0.36 / 1,877.46	125.04 / 19	Robbins Brothers 2200 1st Ave Seattle WA 98121	ALL SITES

Facility/Site ID: 9476
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000043769
Facility Alternate: Robbins Brothers
Interaction ID: 105423
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 02-Jul-2013
Interact End Dt: 31-Dec-2014
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAH000043769
Facility Alternate: Robbins Brothers
Interaction ID: 111958
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWOTHER
Interaction Desc: Haz Waste Management Activity
Interact Start Dt: 31-Dec-2014
Interact End Dt: 31-Dec-2015
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAH000043769
Facility Alternate: Robbins Brothers
Interaction ID: 117496
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 31-Dec-2015
Interact End Dt: 31-Dec-2016
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAH000043769
Facility Alternate: Robbins Brothers
Interaction ID: 120692

Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	HWOTHER
Interaction Desc:	Haz Waste Management Activity
Interact Start Dt:	31-Dec-2016
Interact End Dt:	
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	
Horizont 1:	NAD83	**GIS latitude:**	47.6128
Horizont 2:	Address	**GIS longitude:**	-122.34512

---

153 | ***1 of 1*** | ***ENE*** | ***0.36 / 1,879.54*** | ***112.31 / 7*** | ***AT&T WIRELESS DEXTER
618 JOHN ST
SEATTLE WA 98109*** | ***ALL SITES***

Facility/Site ID:	3296315
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	CRK000056790
Facility Alternate:	
Interaction ID:	12382
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	TIER2
Interaction Desc:	Emergency/Haz Chem Rpt TIER2
Interact Start Dt:	15-Sep-2003
Interact End Dt:	21-Apr-2004
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	EPCRA
Database Name Desc:	Emergency Planning & Community Right-to-Know Act

Program ID:	620155
Facility Alternate:	Quality Inn & Suites
Interaction ID:	109497
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	UST
Interaction Desc:	Underground Storage Tank
Interact Start Dt:	27-Aug-2013
Interact End Dt:	11-Aug-2014
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	UST
Database Name Desc:	Underground Storage Tanks

Facility Location Detail

Horizontal:	40ft	**Location Verified:**	
Horizont 1:	NAD83HARN	**GIS latitude:**	47.6203202685
Horizont 2:	Digital map or GIS	**GIS longitude:**	-122.344203165

---

154 | ***1 of 5*** | ***SE*** | ***0.36 / 1,891.41*** | ***123.35 / 18*** | ***Lewiston Hotel
2201 1ST AVE
SEATTLE WA 98121*** | ***CSCSL***

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Fac Site ID: 39341377
Cleanup Site ID: 1983
Site Status: Cleanup Started
Site Rank: 5 - Lowest Assessed Risk
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.61255
Longitude: -122.3453
Site Name: Lewiston Hotel
Address: 2201 1ST AVE
City: SEATTLE
Zip Code: 98121
Site Status (OD): Cleanup Started
Site Name (OD): Lewiston Hotel
Address (OD): 2201 1ST AVE
City (OD): SEATTLE
Zipcode (OD): 98121
Location (OD): "" (47.61255, -122.3453)
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 39341377
Cleanup SiteID(OD): 1983
Site Rank (OD): 5 - Lowest Assessed Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.3453
Latitude (OD): 47.61255

Contaminants Detail(s)

Contaminant Name: Halogenated Organics
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Metals Priority Pollutants
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Halogenated Organics
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Halogenated Organics
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals Priority Pollutants
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

154	2 of 5	SE	0.36 / 1,891.41	123.35 / 18	Lewiston Hotel 2201 1ST AVE SEATTLE WA 98121	HSL

Fac Site ID: 39341377
Cleanup Site ID: 1983
Site Status: Cleanup Started
Site Rank: 5 - Lowest Assessed Risk

Fac Site ID (OD): 39341377
Cleanup Site ID (OD): 1983
Site Status (OD): Cleanup Started
Site Rank (OD): 5 - Lowest Assessed Risk

Has Inst Control:		**Has Env Coven (OD):**	
Responsible Unit:	Northwest	**Respon Unit (OD):**	Northwest
County:	King	**County (OD):**	King
Region:	Northwest	**Region (OD):**	Northwest
Latitude:	47.61255	**Site Name (OD):**	Lewiston Hotel
Longitude:	-122.3453	**Address (OD):**	2201 1ST AVE
Latitude (OD):	47.61255	**City (OD):**	SEATTLE
Longitude (OD):	-122.3453	**ZIP code (OD):**	98121
Current VCP:		**Past VCP:**	Yes

Location (OD): ""
(47.61255, -122.3453)

Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name:	Metals Priority Pollutants	**Sediment:**	
Groundwater:		**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			

Contaminant Name:	Halogenated Organics	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Halogenated Organics	**Contaminant Media:**	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Halogenated Organics	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Metals Priority Pollutants	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
154	3 of 5	SE	0.36 / 1,891.41	123.35 / 18	LEWISTON HOTEL 2201 1ST AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID: 39341377
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: LEWISTON HOTEL
Interaction ID: 42370
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 28-May-1999
Interact End Dt: 13-Nov-2001
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID:
Facility Alternate: LEWISTON HOTEL
Interaction ID: 42372
Interaction Status: A

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Interac Status Desc:	Active
Interaction Type:	SCS
Interaction Desc:	State Cleanup Site
Interact Start Dt:	16-Jun-2006
Interact End Dt:	
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System
Program ID:	NW0798
Facility Alternate:	LEWISTON HOTEL
Interaction ID:	42371
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	VOLCLNST
Interaction Desc:	Voluntary Cleanup Sites
Interact Start Dt:	07-Nov-2001
Interact End Dt:	16-Jun-2006
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Facility Location Detail

Horizontal:	1000ft	**Location Verified:**	N
Horizont 1:	NAD83	**GIS latitude:**	47.61255
Horizont 2:	Address	**GIS longitude:**	-122.3453

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
154	4 of 5	SE	0.36 / 1,891.41	123.35 / 18	LEWISTON HOTEL 2201 1ST AVE SEATTLE WA 98121	ICR

Cleanup Site ID:	1983	**WRIA ID:**	8
Facility Site ID:	39341377	**Is NFA Site:**	
Site Status:	Cleanup Started	**Responsible Unit:**	Northwest
Statute:	MTCA	**Latitude:**	47.612549999999999
Rank:	5	**Longitude:**	-122.34529999999999
Rank Description:	Lowest assessed risk	**Legislative District:**	36
Has Env Covenant:		**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		**Start Date:**	2007-09-22
VCP Prj No:		**End Date:**	2008-01-08
Activity Name:	Site Hazard Assessment/Federal Site Inspection	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	Local Government
County Name:	King	**Project Manager:**	County Health-NW
Applies to:	CleanupSite		
Applies to Description:			
Related ID:		**Start Date:**	1999-05-13
VCP Prj No:		**End Date:**	1999-05-28
Activity Name:	Initial Investigation / Federal Preliminary Assessment	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	Ecology
County Name:	King	**Project Manager:**	Bremer, Steve
Applies to:	CleanupSite		
Applies to Description:			
Related ID:		**Start Date:**	
VCP Prj No:	NW0798	**End Date:**	2006-06-16

Activity Name:	VCP Termination	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Edens, Mark
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		
Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	1999-07-12
Activity Name:	Early Notice Letter(s)	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Bremer, Steve
Applies to:	CleanupSite		
Applies to Description:			
Related ID:		**Start Date:**	2001-11-13
VCP Prj No:	NW0798	**End Date:**	
Activity Name:	VCP Application	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		
Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2008-01-08
Activity Name:	Hazardous Sites Listing/NPL	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			
Related ID:		**Start Date:**	2001-11-13
VCP Prj No:	NW0798	**End Date:**	2001-12-21
Activity Name:	VCP Opinion on Remedial Investigation Work Plan	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Yang, Grant
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Media Contaminants

Contaminant Type:	Metals Priority Pollutants	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King
Contaminant Type:	Halogenated Organics	**Sediment:**	
Groundwater:	C	**Sediment Desc.:**	
Groundwater Desc.:	Confirmed Above Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

154	5 of 5	SE	0.36 / 1,891.41	123.35 / 18	**Lewiston Hotel** **2201 1ST AVE** **SEATTLE WA 98121**	VCP

Facility Site ID:	39341377	**County:**	King
Cleanup Site ID:	1983	**Latitude:**	47.61255
Region:	Northwest	**Longitude:**	-122.3453
Alternate Site Names:			
Data Source(s):	Confirmed and Suspected Contaminated Sites; Confirmed and Suspected Contaminated Sites; All Cleanup Sites in Washington State		

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List

Site Status:	Cleanup Started
Current VCP:	
Past VCP:	Yes
Site Rank:	5 - Lowest Assessed Risk
Responsible Unit:	Northwest
Has Inst Control:	

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List - Contaminants

Contaminant Name:	Halogenated Organics	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		

Contaminant Name:	Metals Priority Pollutants	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status:	Cleanup Started
Site Rank:	5 - Lowest Assessed Risk
Has Inst Control:	
Current VCP:	
Past VCP:	Yes
Responsible Unit:	Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name:	Metals Priority Pollutants	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		

Contaminant Name:	Halogenated Organics	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		

---

155 ***1 of 1*** ***E*** ***0.37 / 1,937.83*** ***115.58 / 10*** ***VARTEC SEATTLE SWITCH***
2308 N 6TH AVE
SEATTLE WA 98121 ***ALL SITES***

Facility/Site ID:	8019923
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	CRK000061340
Facility Alternate:	
Interaction ID:	21886
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	TIER2
Interaction Desc:	Emergency/Haz Chem Rpt TIER2
Interact Start Dt:	08-Jul-2004
Interact End Dt:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: EPCRA
Database Name Desc: Emergency Planning & Community Right-to-Know Act

Facility Location Detail

Horizontal: Unknown
Horizont 1: Unknown
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.6167273308
GIS longitude: -122.343628779

---

156 | **1 of 1** | **WNW** | **0.37 / 1,940.90** | **25.51 / -80** | **DIAMOND PARKING INC ELLIOTT AVE**
3161 ELLIOTT AVE
SEATTLE WA 98121-1054 | **ALL SITES**

Facility/Site ID: 13883456
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 9035
Facility Alternate:
Interaction ID: 27800
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 29-Feb-2000
Interact End Dt: 03-May-2000
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83
Horizont 2: Address
Location Verified: N
GIS latitude: 47.61811
GIS longitude: -122.358888

---

157 | **1 of 1** | **E** | **0.38 / 1,982.00** | **113.27 / 8** | **PRECISION TUNE 7TH AVE SEATTLE**
2331 7TH AVE
SEATTLE WA 98121-1903 | **ALL SITES**

Facility/Site ID: 7517855
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 3985
Facility Alternate:
Interaction ID: 20868
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 01-Sep-1982
Interact End Dt: 03-May-2000
Ecology Program: TOXICS

Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83
Horizont 2: Address
Location Verified: N
GIS latitude: 47.61755
GIS longitude: -122.343078

---

158 | 1 of 1 | WNW | 0.38 / 1,986.02 | 27.69 / -78 | **United Technologies Otis Elevator Settle**
3150 ELLIOT AVE
SEATTLE WA 98121 | ALL SITES

Facility/Site ID: 38473417
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAD988481552
Facility Alternate:
Interaction ID: 41909
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 07-Jan-1991
Interact End Dt: 31-Dec-1992
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.61812
GIS longitude: -122.35751

---

159 | 1 of 1 | E | 0.38 / 1,994.77 | 119.86 / 14 | **Sterling Engraving Co**
2218 5TH AVE E
SEATTLE WA 98121-1808 | ALL SITES

Facility/Site ID: 42844574
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAD001298710
Facility Alternate:
Interaction ID: 44082
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 12-May-1983
Interact End Dt: 10-Oct-1991
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	N
Horizont 1:	NAD83	**GIS latitude:**	47.61574
Horizont 2:	Unknown	**GIS longitude:**	-122.34335

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
160	1 of 1	ENE	0.38 / 2,003.50	108.27 / 3	ATT MOBILITY DEXTER 225 AURORA AVE N SEATTLE WA 98109	ALL SITES

Facility/Site ID: 67289
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: CRK000056790
Facility Alternate: ATT MOBILITY DEXTER
Interaction ID: 137824
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: TIER2
Interaction Desc: Emergency/Haz Chem Rpt TIER2
Interact Start Dt: 05-May-2002
Interact End Dt: 21-Apr-2004
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: EPCRA
Database Name Desc: Emergency Planning & Community Right-to-Know Act

Program ID: CRK000069570
Facility Alternate: Verizon Wireless GUMBALL W433SE
Interaction ID: 139015
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: TIER2
Interaction Desc: Emergency/Haz Chem Rpt TIER2
Interact Start Dt: 27-Feb-2007
Interact End Dt: 06-Mar-2015
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: EPCRA
Database Name Desc: Emergency Planning & Community Right-to-Know Act

Facility Location Detail

Horizontal:	40ft	**Location Verified:**	
Horizont 1:	NAD83HARN	**GIS latitude:**	47.620494962
Horizont 2:	Digital map or GIS	**GIS longitude:**	-122.344145713

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
161	1 of 2	S	0.38 / 2,022.77	7.56 / -98	Hebei Ocean Shipping Co Elliott Bay WA	ALL SITES

Facility/Site ID: 1425600
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Program ID:
Facility Alternate:
Interaction ID: 8496
Interaction Status: A
Interac Status Desc: Active
Interaction Type: ENFORFNL
Interaction Desc: Enforcement Final
Interact Start Dt: 10-Mar-2004
Interact End Dt:
Ecology Program: SPILLS
Program Name Desc: Spills Program
Prog Database Name: DMS
Database Name Desc: Docket Management System

Facility Location Detail

Horizontal: Unknown
Horizont 1: Unknown
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.6109322623
GIS longitude: -122.349566431

161	2 of 2	S	0.38 / 2,022.77	7.56 / -98	TSANGARIS BROS LTD ELLIOTT BAY WA	ALL SITES

Facility/Site ID: 6116135
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate:
Interaction ID: 18156
Interaction Status: A
Interac Status Desc: Active
Interaction Type: ENFORFNL
Interaction Desc: Enforcement Final
Interact Start Dt: 14-Jun-2005
Interact End Dt:
Ecology Program: SPILLS
Program Name Desc: Spills Program
Prog Database Name: DMS
Database Name Desc: Docket Management System

Facility Location Detail

Horizontal: Unknown
Horizont 1: Unknown
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.6109322623
GIS longitude: -122.349566431

162	1 of 2	ESE	0.39 / 2,047.44	145.66 / 40	Gem East Corp 2124 2ND AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID: 67231592
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAD009486762
Facility Alternate: Gem East Corp

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Interaction ID: 58163
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 29-Feb-1996
Interact End Dt: 17-Dec-2014
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.61285
GIS longitude: -122.34335

---

162 | **2 of 2** | **ESE** | **0.39 / 2,047.44** | **145.66 / 40** | **ATT MOBILITY LENORA & 3RD**
2124 2ND AVE
SEATTLE WA 98121 | **ALL SITES**

Facility/Site ID: 71302
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: CRK000082410
Facility Alternate: ATT MOBILITY LENORA AND 3RD
Interaction ID: 128120
Interaction Status: A
Interac Status Desc: Active
Interaction Type: TIER2
Interaction Desc: Emergency/Haz Chem Rpt TIER2
Interact Start Dt: 01-Jan-2013
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: EPCRA
Database Name Desc: Emergency Planning & Community Right-to-Know Act

Facility Location Detail

Horizontal: Unknown
Horizont 1: WGS84
Horizont 2: Address
Location Verified:
GIS latitude: 47.61324
GIS longitude: -122.3437

---

163 | **1 of 1** | **ESE** | **0.39 / 2,049.37** | **145.66 / 40** | **Action Small Appliance**
2125 2nd Ave
Seattle WA 98121 | **SWF/LF**

ID: 630
Recycle Survey ID: 6769
Permit Status: Recycle Survey
Operational Status: Operating
Year Opened: 1900
Year Closed:
Ann Report Required: No
Rec Survey Required: No
Facility Type: Recycling (non-regulated)
Open to Public: No
Regulation:
Ownership: PR
Region: Northwest Regional Office
County: King
Latitude:
Longitude:
Facility Phone: (206) 448-2020

Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Permit No:
Operator First Name:
Operator Last Name:
Operator Title:
Operator Email:
Contact First Name: David
Contact Last Name: King
Contact Title: President
Contact Organization: Action Small Appliance
Operator Organization: Action Small Appliance
Web Address:

Contact Address 1: 2125 2nd Ave
Contact Address 2:
Contact City: Seattle
Contact State: WA
Contact Zip: 98121
Contact Email:
Contact Phone: (206) 448-2020
Contact Phone Ext:

164	1 of 4	ESE	0.39 / 2,060.44	138.86 / 33	Rexland Co 2126 3RD AVE SEATTLE WA 98121	CSCSL

Fac Site ID: 54147485
Cleanup Site ID: 9627
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.61332
Longitude: -122.343748
Site Name: Rexland Co
Address: 2126 3RD AVE
City: SEATTLE
Zip Code: 98121
Site Status (OD): Cleanup Started
Site Name (OD): REXLAND CO
Address (OD): 2126 3RD AVE
City (OD): SEATTLE
Zipcode (OD): 98121-2306
Location (OD): ""
(47.61332, -122.343748)
Alternate Site Names: REXLAND CO INC
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 54147485
Cleanup SiteID(OD): 9627
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.343748
Latitude (OD): 47.61332

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

164 **2 of 4** **ESE** **0.39 / 2,060.44** **138.86 / 33** **REXLAND CO INC**
2126 3RD AVE
SEATTLE WA 98121-2306
ALL SITES

Facility/Site ID: 54147485
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 431966
Facility Alternate:
Interaction ID: 50560
Interaction Status: A
Interac Status Desc: Active
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 31-Dec-1928
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: 431966
Facility Alternate:
Interaction ID: 50561
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: LUST
Interaction Desc: LUST Facility
Interact Start Dt: 09-Dec-1997
Interact End Dt: 09-Dec-1997
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83
Horizont 2: Address
Location Verified: N
GIS latitude: 47.61332
GIS longitude: -122.343748

---

164 **3 of 4** **ESE** **0.39 / 2,060.44** **138.86 / 33** **Rexland Co**
2126 3RD AVE
SEATTLE WA 98121
LUST

Facility Site ID: 54147485
Cleanup Site ID: 9627
Responsible Unit: Northwest
Region: Northwest
Alternate Site Names: REXLAND CO INC
County: King
Latitude: 47.61332
Longitude: -122.343748

Tank Detail(s)

UST ID: 431966
LUST ID: 4694
LUST Status: LUST - Cleanup Started
Status Date: 07/01/2011
Release Date: 12/09/1997

Contaminants Detail(s)

Contaminant Name:	Petroleum-Diesel	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Other	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		

---

164 ***4 of 4*** ***ESE*** ***0.39 / 2,060.44*** ***138.86 / 33*** ***REXLAND CO***
2126 3RD AVE
SEATTLE WA 98121-2306 ***ICR***

Cleanup Site ID:	9627	***WRIA ID:***	8
Facility Site ID:	54147485	***Is NFA Site:***	
Site Status:	Cleanup Started	***Responsible Unit:***	Northwest
Statute:	MTCA	***Latitude:***	47.613320000000002
Rank:		***Longitude:***	-122.34374800000001
Rank Description:		***Legislative District:***	36
Has Env Covenant:		***Congr District:***	7
Is Brownfiled Site:		***County Name:***	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:	4694	***Start Date:***	1997-12-09
VCP Prj No:		***End Date:***	1997-12-09
Activity Name:	LUST - Notification	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	1997-12-09
Activity Name:	Site Discovery/Release Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:	4694	***Start Date:***	1997-12-05
VCP Prj No:		***End Date:***	1997-12-09
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Media Contaminants

Contaminant Type:	Petroleum-Diesel	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant Type:	Petroleum-Other	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

165	1 of 1	SE	0.39 / 2,073.47	97.51 / -8	Western and Blanchard Property WA	DELISTED SHWS

Delisted Confirmed and Suspected Contaminated Sites

Fac Site ID:		**Fac Site ID (OD):**	24588
Cleanup Site ID:		**Clnup Site ID (OD):**	13134
Site Status:		**Site Rank (OD):**	
Site Rank:		**Respon Unit (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:		**County (OD):**	
Has Inst Control:		**Region (OD):**	
Responsible Unit:		**City (OD):**	
County:		**Zipcode (OD):**	
Region:		**Latitude (OD):**	47.61192
Latitude:		**Longitude (OD):**	-122.34552
Longitude:			
Site Status (OD):	Cleanup Started		
Site Name (OD):	Western and Blanchard Property		
Address (OD):			
Location (OD):			
Alternate Site Names:			
Data Source(s):	Open Data Portal - Media and Contaminants		
Original Source:	CSCS		
Record Date:	28-JUN-2021		

166	1 of 1	SSE	0.39 / 2,073.50	7.57 / -98	BELL HARBOR MARINE CRUISE TERMINAL (PIER 66) SEATTLE WA	FUDS

FUDS Property No:	F10WA0664
EMS Map Link:	https://fudsportal.usace.army.mil/ems/inventory/map/map?id=64328
FUDS INST ID:	WA09799FA27700
Status:	Properties without projects
SDS ID:	
NPL Status Code:	Not on the NPL
Eligibility:	Ineligible
Site Eligib:	
Current Owner:	
Has Project:	No
DOD FUDS Pro:	
Project Required:	No
No Further Action:	
Congressional District:	07
EPA Region:	10
County:	KING
Latitude:	47.61083333
Longitude:	-122.34916667
Fiscal year:	2019
USACE Division:	NWD
USACE District:	Kansas City District (NWK)
Shape Area:	
Shape Len:	
Centroid Latitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: Bell Harbor Marine Cruise Terminal (Pier 66) has no known history of being utilized by the U. S. Navy, however, in June 2011 shell casings exhbiting U. S. Navy markings were found inside Bell Harbor Marine Cruise Terminal marina under the dock located th

---

167 | ***1 of 4*** | ***NNE*** | ***0.39 / 2,077.96*** | ***104.21 / -2*** | ***Basil Lee 505 HARRISON ST SEATTLE WA 98109*** | ***CSCSL***

Fac Site ID:	79418734	***Responsible Unit:***	Northwest
Cleanup Site ID:	10558	***Fac Site ID (OD):***	79418734
Site Status:	Cleanup Started	***Cleanup SiteID(OD):***	10558
Site Rank:		***Site Rank (OD):***	
Current VCP:		***Has Env Coven (OD):***	
Past VCP:		***Respon Unit (OD):***	Northwest
Has Inst Control:		***County (OD):***	King
County:	King	***Region (OD):***	Northwest
Region:	Northwest	***Longitude (OD):***	-122.347233
Latitude:	47.6219004515049	***Latitude (OD):***	47.6219
Longitude:	-122.347232512434		

Site Name: Basil Lee
Address: 505 HARRISON ST
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Basil Lee Property
Address (OD): 505 HARRISON ST
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.6219, -122.347233)
Alternate Site Names: BASIL LEE PROPERTY,Lee Site
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

167 | ***2 of 4*** | ***NNE*** | ***0.39 / 2,077.96*** | ***104.21 / -2*** | ***BASIL LEE PROPERTY 505 HARRISON ST SEATTLE WA 98109*** | ***ALL SITES***

Facility/Site ID: 79418734
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Program ID: 368789
Facility Alternate:
Interaction ID: 65151
Interaction Status: A
Interac Status Desc: Active
Interaction Type: LUST
Interaction Desc: LUST Facility
Interact Start Dt: 30-May-1996
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: WAR000008235
Facility Alternate:
Interaction ID: 65150
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 19-Mar-1996
Interact End Dt: 31-Dec-1996
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: 368789
Facility Alternate:
Interaction ID: 65152
Interaction Status: A
Interac Status Desc: Active
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 18-Mar-1999
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6219004515
GIS longitude: -122.347232512

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
167	3 of 4	NNE	0.39 / 2,077.96	104.21 / -2	Basil Lee 505 HARRISON ST SEATTLE WA 98109	LUST

Facility Site ID: 79418734
Cleanup Site ID: 10558
Responsible Unit: Northwest
Region: Northwest
Alternate Site Names: BASIL LEE PROPERTY,Lee Site
County: King
Latitude: 47.6219004515049
Longitude: -122.347232512434

Tank Detail(s)

UST ID: 368789
LUST ID: 4196
LUST Status: LUST - Cleanup Started
Status Date: 08/17/1999
Release Date: 05/30/1996

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

---

167 | **4 of 4** | **NNE** | **0.39 / 2,077.96** | **104.21 / -2** | **Basil Lee Property**
505 HARRISON ST
SEATTLE WA 98109 | **ICR**

Cleanup Site ID: 10558
Facility Site ID: 79418734
Site Status: Cleanup Started
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site:
WRIA ID: 8
Is NFA Site:
Responsible Unit: Northwest
Latitude: 47.621900451504906
Longitude: -122.34723251243402
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID: 4196
VCP Prj No:
Activity Name: LUST - Notification
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 1996-05-30
End Date: 1996-05-30
Legal Mechanism:
Performed by:
Project Manager: Hickey, Joe

Related ID:
VCP Prj No:
Activity Name: Early Notice Letter(s)
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date:
End Date: 2002-04-09
Legal Mechanism:
Performed by:
Project Manager: Pederson, Carrie

Related ID: 4196
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 1996-07-19
End Date: 1996-07-23
Legal Mechanism:
Performed by:
Project Manager:

Media Contaminants

Contaminant Type: Petroleum-Other
Groundwater:
Groundwater Desc.:
Surface Water:
Surfacewater Desc.:
Soil: C
Soil Desc.: Confirmed Above Cleanup Level
Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

---

168 | **1 of 2** | **WNW** | **0.39 / 2,079.33** | **71.30 / -34** | **Anacomp Inc 1st**
200 1ST AVE W STE 105
SEATTLE WA 98119-4219 | **ALL SITES**

Facility/Site ID: 35253939
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility/Site Interaction

Program ID:	WAD988485173
Facility Alternate:	
Interaction ID:	39801
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWP
Interaction Desc:	Hazardous Waste Planner
Interact Start Dt:	01-Jan-1993
Interact End Dt:	31-Mar-1994
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	HWPPRT
Database Name Desc:	Hazardous Reporting

Program ID:	WAD988485173
Facility Alternate:	
Interaction ID:	39800
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	16-Apr-1991
Interact End Dt:	31-Dec-1998
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	N
Horizont 1:	NAD83	***GIS latitude:***	47.62007
Horizont 2:	Unknown	***GIS longitude:***	-122.35783

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
168	*2 of 2*	*WNW*	*0.39 / 2,079.33*	*71.30 / -34*	***First West Investment Property LLC*** ***200 1ST AVE W ENTIRE BLDG*** ***SEATTLE WA 98119***	***ALL SITES***

Facility/Site ID:	892180
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAH000030856
Facility Alternate:	FIRST WEST INVESTMENT PROPERTY LLC
Interaction ID:	7463
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	16-Apr-2007
Interact End Dt:	09-Oct-2009
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Horizont 1: NAD83
Horizont 2: Address
GIS latitude: 47.619937
GIS longitude: -122.357895

---

169 | **1 of 1** | **ENE** | **0.40 / 2,090.19** | **107.09 / 1** | **DAVES AUTO ELECTRIC**
701 JOHN ST
SEATTLE WA 98109 | **ALL SITES**

Facility/Site ID: 41812322
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 486442
Facility Alternate:
Interaction ID: 43388
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 02-Mar-1999
Interact End Dt: 18-May-2000
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.619503046
GIS longitude: -122.343152844

---

170 | **1 of 3** | **NW** | **0.40 / 2,094.96** | **121.25 / 15** | **Astro Apartments**
315 1ST AVE N
SEATTLE WA 98109 | **ICR**

Cleanup Site ID: 12887
Facility Site ID: 20034
Site Status: Cleanup Started
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site: Yes
WRIA ID: 8
Is NFA Site:
Responsible Unit: Northwest
Latitude: 47.621560000000002
Longitude: -122.35568000000001
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID:
VCP Prj No:
Activity Name: Site Discovery/Release Report Received
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date:
End Date: 2013-10-29
Legal Mechanism:
Performed by:
Project Manager: Northwest Region

Related ID:
VCP Prj No:
Activity Name: Ind - Report Received
Activity Status:
County Name: King
Applies to: Upland
Applies to Description:
Start Date:
End Date: 2013-12-12
Legal Mechanism:
Performed by:
Project Manager:

Related ID:		**Start Date:**	2014-01-28
VCP Prj No:		**End Date:**	2014-10-02
Activity Name:	Initial Investigation / Federal Preliminary Assessment	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	Ecology
County Name:	King	**Project Manager:**	Freier-Coppinger, Romy
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2015-10-28
Activity Name:	Early Notice Letter(s)	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Musa, Donna
Applies to:	CleanupSite		
Applies to Description:			

Media Contaminants

Contaminant Type:	Petroleum-Diesel	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

Contaminant Type:	Petroleum-Other	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	B	**Bedrock Desc.:**	
Soil Desc.:	Below Cleanup Level	**County Name:**	King

170	2 of 3	NW	0.40 / 2,094.96	121.25 / 15	**Astro Apartments** **315 1ST AVE N** **SEATTLE WA 98109**	ALL SITES

Facility/Site ID:	20034
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	
Facility Alternate:	Astro Apartments
Interaction ID:	115056
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	SCS
Interaction Desc:	State Cleanup Site
Interact Start Dt:	13-Oct-2015
Interact End Dt:	
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	
Horizont 1:	WGS84	**GIS latitude:**	47.62156
Horizont 2:	Address	**GIS longitude:**	-122.35568

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
170	3 of 3	NW	0.40 / 2,094.96	121.25 / 15	Astro Apartments 315 1ST AVE N SEATTLE WA 98109	CSCSL

Fac Site ID: 20034
Cleanup Site ID: 12887
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.62156
Longitude: -122.35568
Site Name: Astro Apartments
Address: 315 1ST AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Astro Apartments
Address (OD): 315 1ST AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): "" (47.62156, -122.35568)
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 20034
Cleanup SiteID(OD): 12887
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.35568
Latitude (OD): 47.62156

Contaminants Detail(s)

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
171	1 of 4	SE	0.40 / 2,101.90	91.22 / -15	Western and Blanchard Property 2134 Western Ave Seattle WA 98121	VCP

Facility Site ID: 24588
Cleanup Site ID: 13134
Region: Northwest
County: King
Latitude: 47.6118917887348
Longitude: -122.345511537647

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Alternate Site Names:
Data Source(s): No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status: NFA
NFA Date: 03/24/2017
Responsible Unit: Northwest
Has Inst Control:
NFA Reason: Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: No Further Action
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

171	*2 of 4*	*SE*	*0.40 / 2,101.90*	*91.22 / -15*	***Western and Blanchard Property 2134 Western Avenue Seattle WA 98121***	***DELISTED SHWS***

Delisted Contaminated/Hazardous Sites

Fac Site ID: 24588
Cleanup Site ID: 13134
Brownfield?:
PSI?: Yes
VCP?: Yes
Past VCP:
Has Inst Control:
Site Status: Cleanup Started
Alternate Site Names:
Original Source: CSCS
Record Date: 17-MAR-2017
WARM Rank: N
Warm Rank Desc:
Respon Section: Headquarters
County: King
Region: Northwest
Latitude: 47.6119157381864
Longitude: -122.345517572368

171	*3 of 4*	*SE*	*0.40 / 2,101.90*	*91.22 / -15*	***Western and Blanchard Property 2134 Western Ave Seattle WA 98121***	***ALL SITES***

Facility/Site ID: 24588
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility/Site Interaction

Program ID:	NW3083
Facility Alternate:	Western and Blanchard Property
Interaction ID:	119851
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	VOLCLNST
Interaction Desc:	Voluntary Cleanup Sites
Interact Start Dt:	26-Jan-2016
Interact End Dt:	24-Mar-2017
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Facility Location Detail

Horizontal:	40ft	***Location Verified:***	
Horizont 1:	NAD83HARN	***GIS latitude:***	47.6118917887
Horizont 2:	Digital map or GIS	***GIS longitude:***	-122.345511538

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
171	4 of 4	SE	0.40 / 2,101.90	91.22 / -15	Western and Blanchard Property 2134 Western Ave Seattle WA 98121	CSCSL NFA

Fac Site ID:	24588	***Fac Site ID (OD):***	24588
Cleanup Site ID:	13134	***Cleanup SiteID(OD):***	13134
Site Status:	NFA	***Site Status (OD):***	No Further Action
NFA Date:	03/24/2017	***Rank (OD):***	
Responsible Unit:	Northwest	***Has Env Coven (OD):***	
Has Insti Control:		***Respon Unit (OD):***	Northwest
Region:	Northwest	***Region (OD):***	Northwest
County:	King	***County (OD):***	King
Latitude:	47.6118917887348	***Latitude (OD):***	47.611916
Longitude:	-122.345511537647	***Longitude (OD):***	-122.345518
NFA Reason:	Voluntary Cleanup Program Review		
Alternate Site Names:			
Location (OD):	"" (47.611916, -122.345518)		
Data Source(s):	Department of Ecology - Washington; Open Data Portal - Washington State		

NFA Contaminants Detail(s)

Contaminant Name:	Petroleum-Gasoline
Groundwater:	
Surfacewater:	
Soil:	Remediated-Below
Sediment:	
Air:	
Bedrock:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
172	1 of 1	NW	0.40 / 2,103.79	125.97 / 20	Seattle Center Arena 334 1st Ave N Seattle WA 98109	ALL SITES

Facility/Site ID:	90258
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAR307322

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility Alternate: Seattle Center Arena
Interaction ID: 129161
Interaction Status: A
Interac Status Desc: Active
Interaction Type: CONSTSWGP
Interaction Desc: Construction SW GP
Interact Start Dt: 21-Nov-2018
Interact End Dt:
Ecology Program: WATQUAL
Program Name Desc: Water Quality Program
Prog Database Name: PARIS
Database Name Desc: Permitting & Reporting Information System

Program ID: WAH000056355
Facility Alternate: Key Arena dba New Arena at Seattle Center
Interaction ID: 131225
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 13-Mar-2019
Interact End Dt: 31-Dec-2019
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: WGS84
Horizont 2: Address
Location Verified:
GIS latitude: 47.622253
GIS longitude: -122.353932

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
173	1 of 1	SE	0.40 / 2,111.73	126.46 / 21	PARKING LOT UST 510091 2120 1ST AVE SEATTLE WA 98121-2103	ALL SITES

Facility/Site ID: 87625787
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 510091
Facility Alternate:
Interaction ID: 69742
Interaction Status: A
Interac Status Desc: Active
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 24-Aug-1999
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83
Horizont 2: Address
Location Verified: N
GIS latitude: 47.612081
GIS longitude: -122.345168

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
174	1 of 1	NNE	0.40 / 2,112.79	104.09 / -2	SEATTLE CENTER N PARKING GARAGE 516 HARRISON ST SEATTLE WA 98109	ALL SITES

Facility/Site ID: 6571811
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 619325
Facility Alternate:
Interaction ID: 19148
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 30-Jan-2007
Interact End Dt: 30-Jan-2007
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Facility Location Detail

Horizontal: 1000ft
Horizont 1: NAD83
Horizont 2: Unknown
Location Verified: Y
GIS latitude: 47.622097
GIS longitude: -122.347083

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
175	1 of 5	WNW	0.40 / 2,119.04	44.48 / -61	Bay View Building 129 1ST AVE W SEATTLE WA 98119	CSCSL NFA

Fac Site ID: 2851894
Cleanup Site ID: 2099
Site Status: NFA
NFA Date: 11/03/2005
Responsible Unit: Northwest
Has Insti Control: Yes
Region: Northwest
County: King
Latitude: 47.6195944033036
Longitude: -122.355836080101
Fac Site ID (OD): 2851894
Cleanup SiteID(OD): 2099
Site Status (OD): No Further Action
Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
Region (OD): Northwest
County (OD): King
Latitude (OD): 47.619594
Longitude (OD): -122.355836
NFA Reason: Voluntary Cleanup Program Review
Alternate Site Names: BAY VIEW BLDG
Location (OD): ""
(47.619594, -122.355836)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

NFA Contaminants Detail(s)

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

175 | 2 of 5 | WNW | 0.40 / 2,119.04 | 44.48 / -61 | BAY VIEW BLDG, 129 1ST AVE W, SEATTLE WA 98119 | ALL SITES

Facility/Site ID: 2851894
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: NW1203
Facility Alternate: BAY VIEW BLDG
Interaction ID: 11461
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 29-Dec-2003
Interact End Dt: 09-Nov-2005
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6195944033
GIS longitude: -122.35583608

---

175 | 3 of 5 | WNW | 0.40 / 2,119.04 | 44.48 / -61 | BAY VIEW BLDG, 129 1ST AVE W, SEATTLE WA 98119 | ICR

Cleanup Site ID: 2099
Facility Site ID: 2851894
Site Status: No Further Action Required
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site: Yes
WRIA ID: 8
Is NFA Site: Yes
Responsible Unit: Northwest
Latitude: 47.619594403303616
Longitude: -122.35583608010094
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID:
VCP Prj No:
Start Date:
End Date: 2005-11-03

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Activity Name: Site Status Changed to NFA
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No: NW1203
Activity Name: VCP Termination
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date:
End Date: 2005-11-09
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No: NW1203
Activity Name: VCP Opinion on Cleanup Action
Activity Status: Canceled
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date:
End Date:
Legal Mechanism:
Performed by:
Project Manager: Kuntz, Michael

Related ID:
VCP Prj No: NW1203
Activity Name: VCP Application
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2003-12-29
End Date:
Legal Mechanism:
Performed by:
Project Manager: Northwest Region

Media Contaminants

Contaminant Type: Polynuclear Aromatic Hydrocarbons
Groundwater:
Groundwater Desc.:
Surface Water:
Surfacewater Desc.:
Soil: C
Soil Desc.: Confirmed Above Cleanup Level
Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

Contaminant Type: Petroleum Products-Unspecified
Groundwater:
Groundwater Desc.:
Surface Water:
Surfacewater Desc.:
Soil: C
Soil Desc.: Confirmed Above Cleanup Level
Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

175	4 of 5	WNW	0.40 / 2,119.04	44.48 / -61	Bay View Building 129 1ST AVE W SEATTLE WA 98119	VCP

Facility Site ID: 2851894
Cleanup Site ID: 2099
Region: Northwest
Alternate Site Names: BAY VIEW BLDG
Data Source(s): No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State
County: King
Latitude: 47.6195944033036
Longitude: -122.355836080101

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status: NFA
NFA Date: 11/03/2005
Responsible Unit: Northwest
Has Inst Control: Yes
NFA Reason: Voluntary Cleanup Program Review

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name:	Petroleum Products-Unspecified	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Confirmed Above Cleanup Levels		
Contaminant Name:	Polycyclic Aromatic Hydrocarbons	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Confirmed Above Cleanup Levels		

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status:	No Further Action
Site Rank:	
Has Inst Control:	Yes
Current VCP:	
Past VCP:	Yes
Responsible Unit:	Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name:	Petroleum Products-Unspecified	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Confirmed Above Cleanup Levels		
Contaminant Name:	Polycyclic Aromatic Hydrocarbons	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Confirmed Above Cleanup Levels		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
175	5 of 5	WNW	0.40 / 2,119.04	44.48 / -61	Bay View Building 129 1ST AVE W SEATTLE WA 98119	INST

Facility Site ID:	2851894	**Cleanup Site ID:**	2099
Region:	Northwest	**Region (OD):**	
County:	King	**County (OD):**	
Latitude:	47.6195944033036	**Latitude (OD):**	
Longitude:	-122.355836080101	**Longitude (OD):**	
Site Name:	Bay View Building		
Address:	129 1ST AVE W		
City:	SEATTLE		
Zip:	98119		
Site Name (OD):			
Address (OD):			
City (OD):			
Zipcode (OD):			
Location (OD):			
Data Source(s):	Department of Ecology State of Washington - Environmental Covenants Registry List		

Environmental Covenants Registry List

NFA Date:	11/03/2005
Site Status:	No Further Action
Tax Parcel No:	1992200400
Instrument Type:	Environmental Covenant
Media Restrictions:	Soil
Alternate Site Names:	BAY VIEW BLDG
Cnty Recording No:	20050912001201
Cnty Recording Dt:	09/12/2005

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Responsible Unit:	Northwest
Active Control:	Yes
Control Stormwater:	No
Control Vapor Gas:	No
Prevent Reuse/Relocation:	No
Prohibit New Bldg Constr:	Yes
Prohibit Removal or Alteration:	Yes
Prohibit Soil Disturbance:	Yes
Ongoing Maint of Remedy:	No
Require Educational Programs:	No
Restrict Access:	No
Restrict All GW Extr:	No
Restrict Domestic GW:	No
Restrict Land Use:	Yes
Restrict Sedmnt Cap Disturb:	No
Restrict Shellfish and or Finf:	No
Restrict Surface Water Use:	No
Restrict Swim/Beach Play:	No
Restrictive Signage:	No
Maintain/Protect Monit System:	No
Other:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
176	1 of 1	ESE	0.40 / 2,119.38	131.34 / 26	DOWNTOWN PUBLIC HEALTH CENTER 2124 4TH AVE SEATTLE WA 98121	RECYCLERS

Details

Organization ID:	1625	**E-Cycle:**	No
Organization Name:	King County Secure Medicine Return	**Lightr Recycle:**	No
Organization Contact:	No Longer Tracked	**County:**	KING
Organization Email:	No Longer Tracked	**Latitude:**	
Material Category:	Household Hazardous Waste	**Longitude:**	
Material Type:	Medications	**Residential:**	
Service Type:	Dropoff	**Commercial:**	
Customer Type:	Residential	**Phone:**	206-477-8250
Website:	https://kingcountysecuremedicinereturn.org/seattle/		
Hours:	Call for hours		
Comments:	Safely dispose of the medicines you no longer need **Note: Many records provided by the department have a truncated [Comments] field.		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
177	1 of 2	E	0.41 / 2,154.31	114.74 / 9	Blanchard Plaza 2201 6TH AVE STE 100 SEATTLE WA 98121	ALL SITES

Facility/Site ID:	78989452
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WA0000189407
Facility Alternate:	
Interaction ID:	64936
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	28-Mar-1994
Interact End Dt:	31-Dec-2001
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	N
Horizont 1:	NAD83	**GIS latitude:**	47.61612
Horizont 2:	Unknown	**GIS longitude:**	-122.34104

---

177 | ***2 of 2*** | ***E*** | ***0.41 / 2,154.31*** | ***114.74 / 9*** | ***WORLDCOM STFAWA***
2201 6TH AVE
SEATTLE WA 98121 | ***ALL SITES***

Facility/Site ID: 9157643
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: CRK000053610
Facility Alternate:
Interaction ID: 24074
Interaction Status: A
Interac Status Desc: Active
Interaction Type: TIER2
Interaction Desc: Emergency/Haz Chem Rpt TIER2
Interact Start Dt: 15-Sep-2003
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: EPCRA
Database Name Desc: Emergency Planning & Community Right-to-Know Act

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	N
Horizont 1:	Unknown	**GIS latitude:**	47.61589758
Horizont 2:	Unknown	**GIS longitude:**	-122.342168274

---

178 | ***1 of 6*** | ***NW*** | ***0.41 / 2,157.12*** | ***127.08 / 21*** | ***Qualex at Seattle Center***
305 HARRISON ST SEATTLE CTR
CENTER HOUSE
SEATTLE WA 98109 | ***ALL SITES***

Facility/Site ID: 1175362
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000002782
Facility Alternate:
Interaction ID: 7968
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 28-Aug-1997
Interact End Dt: 31-Dec-2002
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Program ID: WAH000002782
Facility Alternate: Qualex at Seattle Center
Interaction ID: 126266
Interaction Status: A
Interac Status Desc: Active
Interaction Type: HWOTHER
Interaction Desc: Haz Waste Management Activity
Interact Start Dt: 31-Dec-2003
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6211363013
GIS longitude: -122.355179853

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
178	2 of 6	NW	0.41 / 2,157.12	127.08 / 21	Seattle Center 305 HARRISON ST SEATTLE WA 98109	ALL SITES

Facility/Site ID: 42937592
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAD981768252
Facility Alternate: Seattle Center
Interaction ID: 104097
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWOTHER
Interaction Desc: Haz Waste Management Activity
Interact Start Dt: 31-Dec-2012
Interact End Dt: 31-Dec-2014
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAD981768252
Facility Alternate: Seattle Center
Interaction ID: 44153
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 09-Sep-1987
Interact End Dt: 31-Dec-2012
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: 7931
Facility Alternate:
Interaction ID: 44154
Interaction Status: A
Interac Status Desc: Active
Interaction Type: LUST
Interaction Desc: LUST Facility
Interact Start Dt: 05-Nov-1993

Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID:
Facility Alternate:
Interaction ID: 44152
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 01-Jan-1955
Interact End Dt: 31-Aug-1995
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: WAD981768252
Facility Alternate:
Interaction ID: 44155
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWP
Interaction Desc: Hazardous Waste Planner
Interact Start Dt: 01-Jan-1997
Interact End Dt: 27-Nov-2007
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: HWPPRT
Database Name Desc: Hazardous Reporting

Program ID: WAD981768252
Facility Alternate: Seattle Center
Interaction ID: 111997
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 31-Dec-2014
Interact End Dt: 31-Dec-2016
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAD981768252
Facility Alternate: Seattle Center
Interaction ID: 124913
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 31-Dec-2017
Interact End Dt: 31-Dec-2019
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAD981768252
Facility Alternate: Seattle Center
Interaction ID: 121215
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWOTHER
Interaction Desc: Haz Waste Management Activity

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Interact Start Dt: 31-Dec-2016
Interact End Dt: 31-Dec-2017
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6221853522
GIS longitude: -122.354655693

178	3 of 6	NW	0.41 / 2,157.12	127.08 / 21	**Fun Forest Ride Shop** **305 HARRISON ST RIDE SHOP** **SEATTLE WA 98109**	ALL SITES

Facility/Site ID: 99493951
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAD153714076
Facility Alternate:
Interaction ID: 76523
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 06-Nov-1989
Interact End Dt: 31-Dec-2003
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAR125017
Facility Alternate: Fun Forest Redevelopment
Interaction ID: 96688
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: CONSTSWGP
Interaction Desc: Construction SW GP
Interact Start Dt: 14-Apr-2011
Interact End Dt: 27-Jul-2012
Ecology Program: WATQUAL
Program Name Desc: Water Quality Program
Prog Database Name: PARIS
Database Name Desc: Permitting & Reporting Information System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.62196
GIS longitude: -122.35007

178	4 of 6	NW	0.41 / 2,157.12	127.08 / 21	**Seattle Center** **305 HARRISON ST** **SEATTLE WA 98109**	LUST

Facility Site ID: 42937592
Cleanup Site ID: 9151
Responsible Unit: Northwest
County: King
Latitude: 47.6221853522226
Longitude: -122.35465569257

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Region: Northwest
Alternate Site Names: SEATTLE CITY OF SEATTLE CENTER DEPT,SEATTLE CITY SEATTLE CENTER DEPT

Tank Detail(s)

UST ID: 7931
LUST ID: 3191
LUST Status: LUST - Cleanup Started
Status Date: 11/07/1995
Release Date: 11/05/1993

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

---

178 | 5 of 6 | NW | 0.41 / 2,157.12 | 127.08 / 21 | **SEATTLE CENTER**
305 HARRISON ST
SEATTLE WA 98109 | ICR

Cleanup Site ID: 9151
Facility Site ID: 42937592
Site Status: Cleanup Started
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site: Yes
WRIA ID: 8
Is NFA Site:
Responsible Unit: Northwest
Latitude: 47.622185352222601
Longitude: -122.35465569257001
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID: 3191
VCP Prj No:
Activity Name: LUST - Notification
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 1993-11-05
End Date: 1993-11-05
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No:
Activity Name: Site Discovery/Release Report Received
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date:
End Date: 1993-11-05
Legal Mechanism:
Performed by:
Project Manager: Northwest Region

Related ID: 3191
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 1995-11-07
End Date: 1998-12-09
Legal Mechanism:
Performed by:
Project Manager:

Media Contaminants

Contaminant Type: Petroleum-Gasoline
Groundwater:
Groundwater Desc.:
Surface Water:
Surfacewater Desc.:
Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Soil: C
Soil Desc.: Confirmed Above Cleanup Level
Bedrock Desc.:
County Name: King

---

178 **6 of 6** **NW** **0.41 / 2,157.12** **127.08 / 21** **Seattle Center**
305 HARRISON ST
SEATTLE WA 98109
CSCSL

Fac Site ID: 42937592
Cleanup Site ID: 9151
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6221853522226
Longitude: -122.35465569257
Site Name: Seattle Center
Address: 305 HARRISON ST
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): SEATTLE CENTER
Address (OD): 305 HARRISON ST
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): "" (47.622185, -122.354656)
Responsible Unit: Northwest
Fac Site ID (OD): 42937592
Cleanup SiteID(OD): 9151
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.354656
Latitude (OD): 47.622185
Alternate Site Names: SEATTLE CITY OF SEATTLE CENTER DEPT,SEATTLE CITY SEATTLE CENTER DEPT
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

179 **1 of 1** **ESE** **0.41 / 2,161.65** **142.26 / 37** **Martin Selig Real Estate Seattle**
2118 3RD AVE
SEATTLE WA 98121
ALL SITES

Facility/Site ID: 3835
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000049958
Facility Alternate: Martin Selig Real Estate
Interaction ID: 115845
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 13-Nov-2015
Interact End Dt: 31-Dec-2015
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: WGS84
Horizont 2: Address
Location Verified:
GIS latitude: 47.6137
GIS longitude: -122.34265

---

180 | *1 of 4* | *E* | *0.41 / 2,176.44* | *121.68 / 16* | ***Neuffer Construction 5TH & BLANCHARD SEATTLE WA 98121*** | ***CSCSL NFA***

Fac Site ID: 77948398
Cleanup Site ID: 10503
Site Status: NFA
NFA Date: 10/03/2011
Responsible Unit: Northwest
Has Insti Control:
Region: Northwest
County: King
Latitude: 47.61524
Longitude: -122.342968
Fac Site ID (OD): 77948398
Cleanup SiteID(OD): 10503
Site Status (OD): No Further Action
Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
Region (OD): Northwest
County (OD): King
Latitude (OD): 47.61524
Longitude (OD): -122.342968
NFA Reason: Initial Investigation
Alternate Site Names: NEUFFER CONSTRUCTION COMPANY
Location (OD): ""
(47.61524, -122.342968)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

NFA Contaminants Detail(s)

Contaminant Name: Benzene
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater

Contaminant Status: Below Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Below Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Below Cleanup Levels

180	*2 of 4*	*E*	*0.41 / 2,176.44*	*121.68 / 16*	***NEUFFER CONSTRUCTION COMPANY 5TH & BLANCHARD SEATTLE WA 98121***	***ALL SITES***

Facility/Site ID: 77948398
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 200621
Facility Alternate:
Interaction ID: 64359
Interaction Status: A
Interac Status Desc: Active
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 27-Jan-2000
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: 200621
Facility Alternate:
Interaction ID: 64358
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: LUST
Interaction Desc: LUST Facility
Interact Start Dt: 30-Jan-1991
Interact End Dt: 21-May-1995
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 100ft
Horizont 1: NAD83
Horizont 2: Address
Location Verified: N
GIS latitude: 47.61524
GIS longitude: -122.342968

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
180	3 of 4	E	0.41 / 2,176.44	121.68 / 16	NEUFFER CONSTRUCTION COMPANY 5TH & BLANCHARD SEATTLE WA 98121	ICR

Cleanup Site ID: 10503
Facility Site ID: 77948398
Site Status: No Further Action Required
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site: Yes

WRIA ID: 8
Is NFA Site: Yes
Responsible Unit: Northwest
Latitude: 47.61524
Longitude: -122.342968
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID:
VCP Prj No:
Activity Name: Site Status Changed to NFA
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:

Start Date:
End Date: 2011-10-03
Legal Mechanism:
Performed by:
Project Manager: Olsen, Russ

Related ID:
VCP Prj No:
Activity Name: Initial Investigation / Federal Preliminary Assessment
Activity Status: Completed
County Name: King
Applies to: CleanupSite
Applies to Description:

Start Date:
End Date: 2011-08-08
Legal Mechanism:
Performed by: Ecology w/ Contractor
Project Manager: Olsen, Russ

Related ID: 684
VCP Prj No:
Activity Name: LUST - Notification
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Start Date: 1991-01-30
End Date: 1991-01-30
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No:
Activity Name: Site Discovery/Release Report Received
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:

Start Date:
End Date: 1991-01-30
Legal Mechanism:
Performed by:
Project Manager: Northwest Region

Related ID: 684
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Start Date: 1991-04-12
End Date: 1991-04-12
Legal Mechanism:
Performed by:
Project Manager:

Media Contaminants

Contaminant Type: Benzene
Groundwater: B
Groundwater Desc.: Below Cleanup Level
Surface Water:
Surfacewater Desc.:

Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Soil:	RB	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Below Cleanup Level	**County Name:**	King
Contaminant Type:	Petroleum-Other	**Sediment:**	
Groundwater:	B	**Sediment Desc.:**	
Groundwater Desc.:	Below Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RA	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Above Cleanup Level	**County Name:**	King
Contaminant Type:	Petroleum-Gasoline	**Sediment:**	
Groundwater:	B	**Sediment Desc.:**	
Groundwater Desc.:	Below Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RB	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Below Cleanup Level	**County Name:**	King

---

180 | ***4 of 4*** | ***E*** | ***0.41 / 2,176.44*** | ***121.68 / 16*** | ***Neuffer Construction***
5TH & BLANCHARD
SEATTLE WA 98121 | ***LUST***

Facility Site ID:	77948398	**County:**	King
Cleanup Site ID:	10503	**Latitude:**	47.61524
Responsible Unit:	Northwest	**Longitude:**	-122.342968
Region:	Northwest		
Alternate Site Names:	NEUFFER CONSTRUCTION COMPANY		

Tank Detail(s)

UST ID:	200621	**Status Date:**	10/03/2011
LUST ID:	684	**Release Date:**	01/30/1991
LUST Status:	LUST - NFA		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Other	**Sediment:**	
Groundwater:	Below Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Below		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Gasoline	**Sediment:**	
Groundwater:	Below Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Below		

Contaminants Detail(s)

Contaminant Name:	Benzene	**Sediment:**	
Groundwater:	Below Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Below		

---

181 | ***1 of 1*** | ***E*** | ***0.41 / 2,180.91*** | ***107.76 / 2*** | ***Frederick Pontiac Buick***
2300 7TH AVE
SEATTLE WA 98121 | ***ALL SITES***

Facility/Site ID:	46155422
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAD988500377
Facility Alternate:	
Interaction ID:	46207
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	28-Jan-1992
Interact End Dt:	31-Dec-1993
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	N
Horizont 1:	NAD83	***GIS latitude:***	47.61752
Horizont 2:	Unknown	***GIS longitude:***	-122.34144

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
182	*1 of 1*	*NNE*	*0.42 / 2,201.27*	*100.43 / -5*	***Seattle School Dist 1 Memorial Stad*** ***401 5TH AVE N*** ***SEATTLE WA 98109***	***ALL SITES***

Facility/Site ID:	21791752
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAD988469508
Facility Alternate:	
Interaction ID:	32100
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	19-Jan-1990
Interact End Dt:	01-Mar-1999
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	N
Horizont 1:	NAD83	***GIS latitude:***	47.62234
Horizont 2:	Unknown	***GIS longitude:***	-122.34761

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
183	*1 of 2*	*WNW*	*0.42 / 2,204.43*	*23.35 / -82*	***Verizon Wireless WARE WEST DENNY WAY*** ***101 ELLIOTT AVE W*** ***SEATTLE WA 98119***	***ALL SITES***

Facility/Site ID:	3321
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility/Site Interaction

Program ID:	CRK000080410
Facility Alternate:	Verizon Wireless WARE-WEST DENNY WAY
Interaction ID:	103440
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	TIER2
Interaction Desc:	Emergency/Haz Chem Rpt TIER2
Interact Start Dt:	09-Jan-2013
Interact End Dt:	
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	EPCRA
Database Name Desc:	Emergency Planning & Community Right-to-Know Act

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	
Horizont 1:	WGS84	***GIS latitude:***	47.619077
Horizont 2:	Address	***GIS longitude:***	-122.359571

183	*2 of 2*	*WNW*	*0.42 / 2,204.43*	*23.35 / -82*	***Sabey Corp Seattle*** ***101 ELLIOTT AVE W STE 330*** ***SEATTLE WA 98119***	***ALL SITES***

Facility/Site ID:	77921451
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAD988523304
Facility Alternate:	
Interaction ID:	64337
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	20-Jul-1993
Interact End Dt:	31-Dec-1999
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	N
Horizont 1:	NAD83	***GIS latitude:***	47.61884
Horizont 2:	Unknown	***GIS longitude:***	-122.35843

184	*1 of 1*	*E*	*0.42 / 2,217.95*	*121.94 / 16*	***LEE COURT*** ***2133 5TH AVE*** ***SEATTLE WA 98121***	***ALL SITES***

Facility/Site ID:	21172814
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Program ID: 101574
Facility Alternate:
Interaction ID: 31604
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 24-Feb-1992
Interact End Dt: 03-May-2000
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83
Horizont 2: Address
Location Verified: N
GIS latitude: 47.61473
GIS longitude: -122.342087

185	1 of 4	SE	0.42 / 2,219.31	95.66 / -10	Elliott Bay Bicycles 2114 WESTERN AVE SEATTLE WA 98121	CSCSL

Fac Site ID: 301518
Cleanup Site ID: 3458
Site Status: Awaiting Cleanup
Site Rank: 5 - Lowest Assessed Risk
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6116211867192
Longitude: -122.345146871616
Site Name: Elliott Bay Bicycles
Address: 2114 WESTERN AVE
City: SEATTLE
Zip Code: 98121
Site Status (OD): Awaiting Cleanup
Site Name (OD): Elliott Bay Bicycles
Address (OD): 2114 WESTERN AVE
City (OD): SEATTLE
Zipcode (OD): 98121
Location (OD): "" (47.611621, -122.345147)
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)
Responsible Unit: Northwest
Fac Site ID (OD): 301518
Cleanup SiteID(OD): 3458
Site Rank (OD): 5 - Lowest Assessed Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.345147
Latitude (OD): 47.611621

Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Suspected
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Suspected

---

185 | **2 of 4** | **SE** | **0.42 / 2,219.31** | **95.66 / -10** | **Elliott Bay Bicycles, 2114 WESTERN AVE, SEATTLE WA 98121** | **HSL**

Fac Site ID:	301518	**Fac Site ID (OD):**	301518
Cleanup Site ID:	3458	**Cleanup Site ID (OD):**	3458
Site Status:	Awaiting Cleanup	**Site Status (OD):**	Awaiting Cleanup
Site Rank:	5 - Lowest Assessed Risk	**Site Rank (OD):**	5 - Lowest Assessed Risk
Has Inst Control:		**Has Env Coven (OD):**	
Responsible Unit:	Northwest	**Respon Unit (OD):**	Northwest
County:	King	**County (OD):**	King
Region:	Northwest	**Region (OD):**	Northwest
Latitude:	47.6116211867192	**Site Name (OD):**	Elliott Bay Bicycles
Longitude:	-122.345146871616	**Address (OD):**	2114 WESTERN AVE
Latitude (OD):	47.611621	**City (OD):**	SEATTLE
Longitude (OD):	-122.345147	**ZIP code (OD):**	98121
Current VCP:		**Past VCP:**	
Location (OD):	"" (47.611621, -122.345147)		

Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name:	Petroleum Products-Unspecified	**Sediment:**	
Groundwater:	Suspected	**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Petroleum Products-Unspecified	**Contaminant Media:**	Groundwater
Contaminant Status:	Suspected		
Contaminant:	Petroleum Products-Unspecified	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		

---

185 | **3 of 4** | **SE** | **0.42 / 2,219.31** | **95.66 / -10** | **Elliott Bay Bicycles, 2114 WESTERN AVE, SEATTLE WA 98121** | **ALL SITES**

Facility/Site ID: 301518
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: Elliott Bay Bicycles
Interaction ID: 6563
Interaction Status: A
Interac Status Desc: Active
Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 26-Sep-2006
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS

Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal:	40ft	**Location Verified:**	
Horizont 1:	NAD83HARN	**GIS latitude:**	47.6116211867
Horizont 2:	Digital map or GIS	**GIS longitude:**	-122.345146872

---

185 **4 of 4** **SE** **0.42 / 2,219.31** **95.66 / -10** **Elliott Bay Bicycles**
2114 WESTERN AVE
SEATTLE WA 98121 **ICR**

Cleanup Site ID:	3458	**WRIA ID:**	8
Facility Site ID:	301518	**Is NFA Site:**	
Site Status:	Awaiting Cleanup	**Responsible Unit:**	Northwest
Statute:	MTCA	**Latitude:**	47.611621186719198
Rank:	5	**Longitude:**	-122.34514687161597
Rank Description:	Lowest assessed risk	**Legislative District:**	36
Has Env Covenant:		**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2008-01-08
Activity Name:	Hazardous Sites Listing/NPL	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2006-08-04
Activity Name:	Site Discovery/Release Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	2006-10-20
VCP Prj No:		**End Date:**	2006-10-24
Activity Name:	Initial Investigation / Federal Preliminary Assessment	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	Ecology
County Name:	King	**Project Manager:**	Colburn, Gail
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2006-10-24
Activity Name:	Early Notice Letter(s)	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Brentlinger, David
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	2007-09-27
VCP Prj No:		**End Date:**	2008-01-08
Activity Name:	Site Hazard Assessment/Federal Site Inspection	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	Local Government
County Name:	King	**Project Manager:**	County Health-NW
Applies to:	CleanupSite		
Applies to Description:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Media Contaminants

Contaminant Type:	Petroleum Products-Unspecified	***Sediment:***	
Groundwater:	S	***Sediment Desc.:***	
Groundwater Desc.:	Suspected	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

---

186 | ***1 of 1*** | ***S*** | ***0.42 / 2,221.76*** | ***0.00 / -106*** | ***Norwegian Cruise Line Elliott Bay*** | ***ALL SITES***

WA

Facility/Site ID:	8224354
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	
Facility Alternate:	
Interaction ID:	22269
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	ENFORFNL
Interaction Desc:	Enforcement Final
Interact Start Dt:	05-Aug-2005
Interact End Dt:	
Ecology Program:	SPILLS
Program Name Desc:	Spills Program
Prog Database Name:	DMS
Database Name Desc:	Docket Management System

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	N
Horizont 1:	Unknown	***GIS latitude:***	47.6103822652
Horizont 2:	Unknown	***GIS longitude:***	-122.349566421

---

187 | ***1 of 4*** | ***WNW*** | ***0.42 / 2,236.09*** | ***13.64 / -92*** | ***King County Denny Way CSO 3165 ALASKAN WAY SEATTLE WA 98121*** | ***CSCSL***

Fac Site ID:	4455938	***Responsible Unit:***	Northwest
Cleanup Site ID:	2582	***Fac Site ID (OD):***	4455938
Site Status:	Cleanup Started	***Cleanup SiteID(OD):***	2582
Site Rank:		***Site Rank (OD):***	
Current VCP:		***Has Env Coven (OD):***	
Past VCP:		***Respon Unit (OD):***	Northwest
Has Inst Control:		***County (OD):***	King
County:	King	***Region (OD):***	Northwest
Region:	Northwest	***Longitude (OD):***	-122.3482
Latitude:	47.6127	***Latitude (OD):***	47.6127
Longitude:	-122.3482		
Site Name:	King County Denny Way CSO		
Address:	3165 ALASKAN WAY		
City:	SEATTLE		
Zip Code:	98121		
Site Status (OD):	Cleanup Started		
Site Name (OD):	King County Denny Way CSO		
Address (OD):	3165 ALASKAN WAY		
City (OD):	SEATTLE		
Zipcode (OD):	98121		

Location (OD): ""
(47.6127, -122.3482)
Alternate Site Names: DENNY WAY COMBINED SEWER OVERFLOW SITE,KING COUNTY DNRP DENNY WAY CSO SITE
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Lead
Groundwater:
Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

Contaminant Name: Mercury
Groundwater:
Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

Contaminant Name: Polychlorinated biPhenyls (PCB)
Groundwater:
Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

Contaminant Name: Arsenic
Groundwater:
Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Sediment
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Arsenic
Contaminant Media: Sediment
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polychlorinated biPhenyls (PCB)
Contaminant Media: Sediment
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals Priority Pollutants
Contaminant Media: Sediment
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
187	2 of 4	WNW	0.42 / 2,236.09	13.64 / -92	King Cnty DOT Metro Waterfront Streetcar 3001 ALASKAN WAY SEATTLE WA 98121	ALL SITES

Facility/Site ID: 44397248
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAD982652471
Facility Alternate:
Interaction ID: 45049
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 20-Jul-2006
Interact End Dt: 31-Dec-2006
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAD982652471
Facility Alternate:
Interaction ID: 45048
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 04-May-1988
Interact End Dt: 31-Dec-2005
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: CNE304874
Facility Alternate: King Cnty DOT Metro Waterfront Streetcar
Interaction ID: 101234
Interaction Status: A
Interac Status Desc: Active
Interaction Type: INDSWGP
Interaction Desc: Industrial SW GP
Interact Start Dt: 14-Nov-2002
Interact End Dt:
Ecology Program: WATQUAL
Program Name Desc: Water Quality Program
Prog Database Name: PARIS
Database Name Desc: Permitting & Reporting Information System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.61602
GIS longitude: -122.3563

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
187	3 of 4	WNW	0.42 / 2,236.09	13.64 / -92	King County Denny Way CSO 3165 ALASKAN WAY SEATTLE WA 98121	ALL SITES

Facility/Site ID: 4455938
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: King County Denny Way CSO
Interaction ID: 14747
Interaction Status: A
Interac Status Desc: Active
Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 11-Jun-2007
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID:
Facility Alternate:
Interaction ID: 14748
Interaction Status: A
Interac Status Desc: Active
Interaction Type: ENFORFNL
Interaction Desc: Enforcement Final
Interact Start Dt: 23-Aug-2007
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: DMS
Database Name Desc: Docket Management System

Facility Location Detail

Horizontal: 1000ft
Horizont 1: NAD83
Horizont 2: GPS consumer basic or unknown
Location Verified: N
GIS latitude: 47.6127
GIS longitude: -122.3482

---

187 | ***4 of 4*** | ***WNW*** | ***0.42 / 2,236.09*** | ***13.64 / -92*** | ***King County Denny Way CSO 3165 ALASKAN WAY SEATTLE WA 98121*** | ***ICR***

Cleanup Site ID: 2582
Facility Site ID: 4455938
Site Status: Cleanup Started
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site: Yes
Is PSI Site: Yes
WRIA ID: 8
Is NFA Site:
Responsible Unit: Northwest
Latitude: 47.612699999999997
Longitude: -122.34820000000001
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID:
VCP Prj No:
Activity Name: Site Discovery/Release Report Received
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date:
End Date: 2007-06-11
Legal Mechanism:
Performed by:
Project Manager: Northwest Region

Related ID:
VCP Prj No:
Activity Name: Early Notice Letter(s)
Activity Status:
Start Date:
End Date: 2007-06-18
Legal Mechanism:
Performed by:

County Name:	King	**Project Manager:**	Yang, Grant
Applies to:	CleanupSite		
Applies to Description:			
Related ID:		**Start Date:**	2007-06-11
VCP Prj No:		**End Date:**	2007-06-12
Activity Name:	Initial Investigation / Federal Preliminary Assessment	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	Ecology
County Name:	King	**Project Manager:**	Yang, Grant
Applies to:	CleanupSite		
Applies to Description:			
Related ID:		**Start Date:**	2007-11-19
VCP Prj No:		**End Date:**	
Activity Name:	Order/Decree/Amendment	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Media Contaminants

Contaminant Type:	Polychlorinated biPhenyls (PCB)	**Sediment:**	C
Groundwater:		**Sediment Desc.:**	Confirmed Above Cleanup Level
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:		**Bedrock Desc.:**	
Soil Desc.:		**County Name:**	King
Contaminant Type:	Polynuclear Aromatic Hydrocarbons	**Sediment:**	C
Groundwater:		**Sediment Desc.:**	Confirmed Above Cleanup Level
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:		**Bedrock Desc.:**	
Soil Desc.:		**County Name:**	King
Contaminant Type:	Metals Priority Pollutants	**Sediment:**	C
Groundwater:		**Sediment Desc.:**	Confirmed Above Cleanup Level
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:		**Bedrock Desc.:**	
Soil Desc.:		**County Name:**	King
Contaminant Type:	Arsenic	**Sediment:**	C
Groundwater:		**Sediment Desc.:**	Confirmed Above Cleanup Level
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:		**Bedrock Desc.:**	
Soil Desc.:		**County Name:**	King

188	1 of 4	E	0.42 / 2,236.45	106.70 / 1	**OLD BRITISH MOTORCAR** **7TH & BELL** **SEATTLE WA 98121**	CSCSL NFA

Fac Site ID:	47192364	**Fac Site ID (OD):**	47192364
Cleanup Site ID:	9356	**Cleanup SiteID(OD):**	9356
Site Status:	NFA	**Site Status (OD):**	No Further Action
NFA Date:	10/03/2011	**Rank (OD):**	
Responsible Unit:	Northwest	**Has Env Coven (OD):**	
Has Insti Control:		**Respon Unit (OD):**	Northwest
Region:	Northwest	**Region (OD):**	Northwest
County:	King	**County (OD):**	King

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Latitude: 47.61729 **Latitude (OD):** 47.61729
Longitude: -122.342618 **Longitude (OD):** -122.342618
NFA Reason: Initial Investigation
Alternate Site Names: BRITISH MOTORCAR
Location (OD): ""
(47.61729, -122.342618)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

NFA Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Remediated-Below

188	2 of 4	E	0.42 / 2,236.45	106.70 / 1	OLD BRITISH MOTORCAR 7TH & BELL SEATTLE WA 98121	ALL SITES

Facility/Site ID: 47192364
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 200851
Facility Alternate:
Interaction ID: 46883
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: LUST

Interaction Desc:	LUST Facility
Interact Start Dt:	19-Apr-1989
Interact End Dt:	21-May-1995
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System
Program ID:	200851
Facility Alternate:	
Interaction ID:	46884
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	UST
Interaction Desc:	Underground Storage Tank
Interact Start Dt:	14-Mar-2000
Interact End Dt:	
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	UST
Database Name Desc:	Underground Storage Tanks

Facility Location Detail

Horizontal:	100ft	***Location Verified:***	N
Horizont 1:	NAD83	***GIS latitude:***	47.61729
Horizont 2:	Address	***GIS longitude:***	-122.342618

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
188	3 of 4	E	0.42 / 2,236.45	106.70 / 1	OLD BRITISH MOTORCAR 7TH & BELL SEATTLE WA 98121	ICR

Cleanup Site ID:	9356	***WRIA ID:***	8
Facility Site ID:	47192364	***Is NFA Site:***	Yes
Site Status:	No Further Action Required	***Responsible Unit:***	Northwest
Statute:	MTCA	***Latitude:***	47.617289999999997
Rank:		***Longitude:***	-122.342618
Rank Description:		***Legislative District:***	36
Has Env Covenant:		***Congr District:***	7
Is Brownfiled Site:		***County Name:***	King
Is PSI Site:			

Cleanup Activities

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	2011-10-03
Activity Name:	Site Status Changed to NFA	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	Olsen, Russ
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	1989-04-19
Activity Name:	Site Discovery/Release Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	2011-08-08
Activity Name:	Initial Investigation / Federal Preliminary Assessment	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	Ecology w/ Contractor
County Name:	King	***Project Manager:***	Olsen, Russ

Applies to: CleanupSite
Applies to Description:

Related ID: 176 **Start Date:** 1989-04-06
VCP Prj No: **End Date:** 1989-04-06
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 176 **Start Date:** 1989-04-19
VCP Prj No: **End Date:** 1989-04-19
Activity Name: LUST - Notification **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Media Contaminants

Contaminant Type: Petroleum-Gasoline **Sediment:**
Groundwater: **Sediment Desc.:**
Groundwater Desc.: **Air:**
Surface Water: **Air Desc.:**
Surfacewater Desc.: **Bedrock:**
Soil: RB **Bedrock Desc.:**
Soil Desc.: Remediated-Below Cleanup Level **County Name:** King

Contaminant Type: Benzene **Sediment:**
Groundwater: **Sediment Desc.:**
Groundwater Desc.: **Air:**
Surface Water: **Air Desc.:**
Surfacewater Desc.: **Bedrock:**
Soil: RB **Bedrock Desc.:**
Soil Desc.: Remediated-Below Cleanup Level **County Name:** King

Contaminant Type: Petroleum-Other **Sediment:**
Groundwater: **Sediment Desc.:**
Groundwater Desc.: **Air:**
Surface Water: **Air Desc.:**
Surfacewater Desc.: **Bedrock:**
Soil: RB **Bedrock Desc.:**
Soil Desc.: Remediated-Below Cleanup Level **County Name:** King

---

188 | ***4 of 4*** | ***E*** | ***0.42 / 2,236.45*** | ***106.70 / 1*** | ***OLD BRITISH MOTORCAR 7TH & BELL SEATTLE WA 98121*** | ***LUST***

Facility Site ID: 47192364 **County:** King
Cleanup Site ID: 9356 **Latitude:** 47.61729
Responsible Unit: Northwest **Longitude:** -122.342618
Region: Northwest
Alternate Site Names: BRITISH MOTORCAR

Tank Detail(s)

UST ID: 200851 **Status Date:** 10/03/2011
LUST ID: 176 **Release Date:** 04/19/1989
LUST Status: LUST - NFA

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline **Sediment:**
Groundwater: **Air:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Surfacewater: **Bedrock:**
Soil: Remediated-Below

Contaminants Detail(s)

Contaminant Name: Petroleum-Other **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Remediated-Below

Contaminants Detail(s)

Contaminant Name: Benzene **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Remediated-Below

---

189 | 1 of 1 | E | 0.43 / 2,262.08 | 106.48 / 1 | **Seattle City Used Oil Collect 7th Ave**
2229 7TH AVE
SEATTLE WA 98121 | ALL SITES

Facility/Site ID: 39563173
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAD988494308
Facility Alternate:
Interaction ID: 42515
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 30-Sep-1991
Interact End Dt: 11-Oct-1993
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown **Location Verified:** N
Horizont 1: NAD83 **GIS latitude:** 47.61694
Horizont 2: Unknown **GIS longitude:** -122.34053

---

190 | 1 of 1 | NE | 0.43 / 2,275.57 | 97.46 / -8 | **Seattle City Broad St Substation**
319 6TH AVE N
SEATTLE WA 98109-4606 | ALL SITES

Facility/Site ID: 64238639
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 8828
Facility Alternate:
Interaction ID: 56301

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	UST
Interaction Desc:	Underground Storage Tank
Interact Start Dt:	29-Feb-2000
Interact End Dt:	03-May-2000
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	UST
Database Name Desc:	Underground Storage Tanks
Program ID:	CRK000052930
Facility Alternate:	
Interaction ID:	56302
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	TIER2
Interaction Desc:	Emergency/Haz Chem Rpt TIER2
Interact Start Dt:	15-Sep-2003
Interact End Dt:	
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	EPCRA
Database Name Desc:	Emergency Planning & Community Right-to-Know Act

Facility Location Detail

Horizontal:	40ft	**Location Verified:**	N
Horizont 1:	NAD83	**GIS latitude:**	47.62115
Horizont 2:	Address	**GIS longitude:**	-122.346318

191	*1 of 1*	***NNE***	***0.44 / 2,306.67***	***96.49 / -9***	***IRIS Holding LLC*** ***WA***	***DELISTED SHWS***

Delisted Confirmed and Suspected Contaminated Sites

Fac Site ID:		**Fac Site ID (OD):**	2593
Cleanup Site ID:		**Clnup Site ID (OD):**	758
Site Status:		**Site Rank (OD):**	
Site Rank:		**Respon Unit (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:		**County (OD):**	
Has Inst Control:		**Region (OD):**	
Responsible Unit:		**City (OD):**	
County:		**Zipcode (OD):**	
Region:		**Latitude (OD):**	47.62264
Latitude:		**Longitude (OD):**	-122.34687
Longitude:			
Site Status (OD):	Cleanup Started		
Site Name (OD):	IRIS Holding LLC		
Address (OD):			
Location (OD):			
Alternate Site Names:			
Data Source(s):	Open Data Portal - Media and Contaminants		
Original Source:	CSCS		
Record Date:	28-JUN-2021		

192	*1 of 3*	***ESE***	***0.44 / 2,308.82***	***129.96 / 24***	***Potala Tower Seattle*** ***2116 4TH AVE*** ***SEATTLE WA 98121***	***ALL SITES***

Facility/Site ID:	22365
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: Potala Tower Seattle
Interaction ID: 112762
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: INDPNDNT
Interaction Desc: Independent Cleanup
Interact Start Dt: 18-Nov-2014
Interact End Dt: 07-Apr-2015
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6143861625
GIS longitude: -122.341745831

---

192 ***2 of 3*** ***ESE*** ***0.44 / 2,308.82*** ***129.96 / 24*** ***Potala Tower Seattle 2116 4TH AVE SEATTLE WA 98121*** ***CSCSL NFA***

Fac Site ID: 22365
Cleanup Site ID: 12635
Site Status: NFA
NFA Date: 04/07/2015
Responsible Unit: Northwest
Has Insti Control:
Region: Northwest
County: King
Latitude: 47.6143861624637
Longitude: -122.341745830688
NFA Reason: Initial Investigation
Alternate Site Names: Dean Transmissions
Location (OD): ""
(47.614386, -122.341746)
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

Fac Site ID (OD): 22365
Cleanup SiteID(OD): 12635
Site Status (OD): No Further Action
Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
Region (OD): Northwest
County (OD): King
Latitude (OD): 47.614386
Longitude (OD): -122.341746

NFA Contaminants Detail(s)

Contaminant Name: Arsenic
Groundwater:
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Halogenated Solvents
Groundwater:
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Mercury
Groundwater:

Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Metals - Other
Groundwater:
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Non-Halogenated Solvents
Groundwater:
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Lead
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Arsenic
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Non-Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Metals - Other
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Mercury
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Lead
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
192	3 of 3	ESE	0.44 / 2,308.82	129.96 / 24	Potala Tower Seattle 2116 4TH AVE SEATTLE WA 98121	ICR

Cleanup Site ID:	12635	**WRIA ID:**	8
Facility Site ID:	22365	**Is NFA Site:**	Yes
Site Status:	No Further Action Required	**Responsible Unit:**	Northwest
Statute:	MTCA	**Latitude:**	47.614386162463731
Rank:		**Longitude:**	-122.34174583068847
Rank Description:		**Legislative District:**	36
Has Env Covenant:		**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2014-07-28
Activity Name:	Site Discovery/Release Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	2014-11-18
VCP Prj No:		**End Date:**	2015-03-30
Activity Name:	Initial Investigation / Federal Preliminary Assessment	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	Ecology
County Name:	King	**Project Manager:**	Tomlinson, Priscilla
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2015-04-07
Activity Name:	Site Status Changed to NFA	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Musa, Donna
Applies to:	CleanupSite		
Applies to Description:			

Media Contaminants

Contaminant Type:	Arsenic	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	B	**Bedrock Desc.:**	
Soil Desc.:	Below Cleanup Level	**County Name:**	King

Contaminant Type:	Mercury	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	B	**Bedrock Desc.:**	
Soil Desc.:	Below Cleanup Level	**County Name:**	King

Contaminant Type:	Lead	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RB	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Below Cleanup Level	**County Name:**	King

Contaminant Type:	Non-Halogenated Solvents	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	B	**Bedrock Desc.:**	
Soil Desc.:	Below Cleanup Level	**County Name:**	King

Contaminant Type:	Halogenated Solvents	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	B	**Bedrock Desc.:**	
Soil Desc.:	Below Cleanup Level	**County Name:**	King

Contaminant Type:	Petroleum-Other	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RB	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Below Cleanup Level	**County Name:**	King

Contaminant Type:	Metals - Other	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	B	**Bedrock Desc.:**	
Soil Desc.:	Below Cleanup Level	**County Name:**	King

193	1 of 1	E	0.44 / 2,318.58	107.86 / 2	WORLDCOM INTERMIEDIA FACILITY 2200 6TH AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID: 3266170
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	CRK000057820
Facility Alternate:	
Interaction ID:	12307
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	TIER2
Interaction Desc:	Emergency/Haz Chem Rpt TIER2
Interact Start Dt:	15-Sep-2003
Interact End Dt:	17-Jan-2006
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	EPCRA
Database Name Desc:	Emergency Planning & Community Right-to-Know Act

Program ID:	WAH000058065
Facility Alternate:	Tesla Inc 6th Ave
Interaction ID:	137153
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	01-Nov-2020
Interact End Dt:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: Unknown
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.61589758
GIS longitude: -122.342168274

---

194 | *1 of 3* | *WNW* | *0.44 / 2,338.32* | *89.16 / -17* | ***Uptown Flats Queen Anne*** ***300 1ST AVE W*** ***SEATTLE WA 98119*** | ***ALL SITES***

Facility/Site ID: 11691
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: NW3150
Facility Alternate: Uptown Flats Queen Anne
Interaction ID: 122912
Interaction Status: A
Interac Status Desc: Active
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 15-Jun-2017
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: Unknown
Horizont 1: WGS84
Horizont 2: Address
Location Verified:
GIS latitude: 47.62125
GIS longitude: -122.35765

---

194 | *2 of 3* | *WNW* | *0.44 / 2,338.32* | *89.16 / -17* | ***Uptown Flats Queen Anne*** ***300 1ST AVE W*** ***SEATTLE WA 98119*** | ***CSCSL***

Fac Site ID: 11691
Cleanup Site ID: 13319
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.62125
Longitude: -122.35765
Site Name: Uptown Flats Queen Anne
Address: 300 1ST AVE W
City: SEATTLE
Zip Code: 98119
Site Status (OD): Cleanup Started
Site Name (OD): Uptown Flats Queen Anne
Address (OD): 300 1ST AVE W
City (OD): SEATTLE
Responsible Unit: Northwest
Fac Site ID (OD): 11691
Cleanup SiteID(OD): 13319
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.35765
Latitude (OD): 47.62125

Zipcode (OD): 98119
Location (OD): "" (47.62125, -122.35765)
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

194	3 of 3	WNW	0.44 / 2,338.32	89.16 / -17	Uptown Flats Queen Anne 300 1ST AVE W SEATTLE WA 98119	VCP

Facility Site ID: 11691
Cleanup Site ID: 13319
Region: Northwest
Alternate Site Names:
County: King
Latitude: 47.62125
Longitude: -122.35765
Data Source(s): Confirmed and Suspected Contaminated Sites; Confirmed and Suspected Contaminated Sites; All Cleanup Sites in Washington State

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List

Site Status: Cleanup Started
Current VCP:
Past VCP: Yes
Site Rank:
Responsible Unit: Northwest
Has Inst Control:

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List - Contaminants

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Sediment:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: Cleanup Started
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Polycyclic Aromatic Hydrocarbons **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Petroleum-Other **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Petroleum-Diesel **Sediment:**
Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

195	1 of 1	ENE	0.45 / 2,350.25	97.07 / -9	PPG Industries Inc Loc 180 234 DEXTER AVE SEATTLE WA 98109	ALL SITES

Facility/Site ID: 11629262
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAD027463157
Facility Alternate:
Interaction ID: 26334
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 22-Apr-1985
Interact End Dt: 05-Dec-1986
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown **Location Verified:** N
Horizont 1: NAD83 **GIS latitude:** 47.62035
Horizont 2: Unknown **GIS longitude:** -122.3424

196	1 of 1	SE	0.45 / 2,351.72	143.46 / 38	Qwest Corporation W00A80 120 LENORA ST	ALL SITES

Facility/Site ID: 3472628
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAR000008136
Facility Alternate:
Interaction ID: 12759
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 31-Dec-2007
Interact End Dt: 31-Dec-2009
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAR000008136
Facility Alternate: QWEST CORPORATION W00A80
Interaction ID: 12757
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 01-Mar-1996
Interact End Dt: 31-Dec-2009
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAR000008136
Facility Alternate: Qwest Corporation W00A80
Interaction ID: 91073
Interaction Status: A
Interac Status Desc: Active
Interaction Type: HWOTHER
Interaction Desc: Haz Waste Management Activity
Interact Start Dt: 31-Dec-2009
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAR000008136
Facility Alternate:
Interaction ID: 12758
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWOTHER
Interaction Desc: Haz Waste Management Activity
Interact Start Dt: 31-Dec-2003
Interact End Dt: 31-Dec-2007
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: 10475
Facility Alternate: CENTURYLINK QC
Interaction ID: 12755

Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	UST
Interaction Desc:	Underground Storage Tank
Interact Start Dt:	01-Jan-1986
Interact End Dt:	
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	UST
Database Name Desc:	Underground Storage Tanks
Program ID:	WAR000008136
Facility Alternate:	
Interaction ID:	12756
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	TIER2
Interaction Desc:	Emergency/Haz Chem Rpt TIER2
Interact Start Dt:	01-Jan-1993
Interact End Dt:	
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	EPCRA
Database Name Desc:	Emergency Planning & Community Right-to-Know Act

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	N
Horizont 1:	NAD83	**GIS latitude:**	47.61215
Horizont 2:	Unknown	**GIS longitude:**	-122.34363

197 | ***1 of 5*** | ***SSE*** | ***0.45 / 2,352.02*** | ***8.80 / -97*** | ***Seattle Waterfront Marriott Hotel 2100 ALASKAN WAY SEATTLE WA 98121*** | ***CSCSL NFA***

Fac Site ID:	1938238	**Fac Site ID (OD):**	1938238
Cleanup Site ID:	5270	**Cleanup SiteID(OD):**	5270
Site Status:	NFA	**Site Status (OD):**	No Further Action
NFA Date:	06/26/2003	**Rank (OD):**	
Responsible Unit:	Northwest	**Has Env Coven (OD):**	
Has Insti Control:		**Respon Unit (OD):**	Northwest
Region:	Northwest	**Region (OD):**	Northwest
County:	King	**County (OD):**	King
Latitude:	47.61025	**Latitude (OD):**	47.61025
Longitude:	-122.346111	**Longitude (OD):**	-122.346111
NFA Reason:	Voluntary Cleanup Program Review		
Alternate Site Names:			
Location (OD):	"" (47.61025, -122.346111)		
Data Source(s):	Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants		

NFA Contaminants Detail(s)

Contaminant Name:	Petroleum-Diesel
Groundwater:	Confirmed Above Cleanup Levels
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Lead
Groundwater:	Confirmed Above Cleanup Levels
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels

Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Lead
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Lead
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
197	2 of 5	SSE	0.45 / 2,352.02	8.80 / -97	Seattle Waterfront Marriott Hotel 2100 ALASKAN WAY SEATTLE WA 98121	ALL SITES

Facility/Site ID: 1938238
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 618927
Facility Alternate:
Interaction ID: 9587
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 01-Nov-1991
Interact End Dt: 30-Aug-1992
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: 618927
Facility Alternate:
Interaction ID: 9588
Interaction Status: I

Interac Status Desc:	Inactive
Interaction Type:	LUST
Interaction Desc:	LUST Facility
Interact Start Dt:	23-May-2003
Interact End Dt:	25-Jul-2003
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Program ID:	NW1104
Facility Alternate:	Seattle Waterfront Marriott Hotel
Interaction ID:	9589
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	VOLCLNST
Interaction Desc:	Voluntary Cleanup Sites
Interact Start Dt:	26-May-2003
Interact End Dt:	26-Jun-2003
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	N
Horizont 1:	NAD83	***GIS latitude:***	47.61025
Horizont 2:	Address	***GIS longitude:***	-122.346111

---

197 | ***3 of 5*** | ***SSE*** | ***0.45 / 2,352.02*** | ***8.80 / -97*** | ***Seattle Waterfront Marriott Hotel***
2100 ALASKAN WAY
SEATTLE WA 98121 | ***ICR***

Cleanup Site ID:	5270	***WRIA ID:***	8
Facility Site ID:	1938238	***Is NFA Site:***	Yes
Site Status:	No Further Action Required	***Responsible Unit:***	Northwest
Statute:	MTCA	***Latitude:***	47.610250000000001
Rank:		***Longitude:***	-122.34611099999999
Rank Description:		***Legislative District:***	36
Has Env Covenant:		***Congr District:***	7
Is Brownfiled Site:		***County Name:***	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		***Start Date:***	2003-05-26
VCP Prj No:		***End Date:***	2003-08-26
Activity Name:	Ecology Site Characterization	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	PLP
County Name:	King	***Project Manager:***	Northwest Region
Applies to:	CleanupSiteMilestoneType		
Applies to Description:			

Related ID:		***Start Date:***	
VCP Prj No:	NW1104	***End Date:***	2003-06-23
Activity Name:	VCP Termination	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:	5872	***Start Date:***	2003-05-15
VCP Prj No:		***End Date:***	2003-05-23
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		
Related ID:		**Start Date:**	
VCP Prj No:	NW1104	**End Date:**	
Activity Name:	VCP Opinion on Cleanup Action	**Legal Mechanism:**	
Activity Status:	Canceled	**Performed by:**	
County Name:	King	**Project Manager:**	Sato, Brian
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		
Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2003-06-26
Activity Name:	Site Status Changed to NFA	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	CleanupSite		
Applies to Description:			
Related ID:	5872	**Start Date:**	2003-08-08
VCP Prj No:		**End Date:**	2003-08-08
Activity Name:	LUST - Notification	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		
Related ID:		**Start Date:**	2003-05-26
VCP Prj No:	NW1104	**End Date:**	
Activity Name:	VCP Application	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Media Contaminants

Contaminant Type:	Petroleum-Diesel	**Sediment:**	
Groundwater:	C	**Sediment Desc.:**	
Groundwater Desc.:	Confirmed Above Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King
Contaminant Type:	Lead	**Sediment:**	
Groundwater:	C	**Sediment Desc.:**	
Groundwater Desc.:	Confirmed Above Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King
Contaminant Type:	Petroleum-Gasoline	**Sediment:**	
Groundwater:	C	**Sediment Desc.:**	
Groundwater Desc.:	Confirmed Above Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

197	4 of 5	SSE	0.45 / 2,352.02	8.80 / -97	**Seattle Waterfront Marriott Hotel** **2100 ALASKAN WAY** **SEATTLE WA 98121**	VCP

Facility Site ID:	1938238	**County:**	King

Cleanup Site ID: 5270 **Latitude:** 47.61025
Region: Northwest **Longitude:** -122.346111
Alternate Site Names:
Data Source(s): No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status: NFA
NFA Date: 06/26/2003
Responsible Unit: Northwest
Has Inst Control:
NFA Reason: Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name: Lead **Sediment:**
Groundwater: Confirmed Above Cleanup Levels **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Petroleum-Diesel **Sediment:**
Groundwater: Confirmed Above Cleanup Levels **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Petroleum-Gasoline **Sediment:**
Groundwater: Confirmed Above Cleanup Levels **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: No Further Action
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Petroleum-Diesel **Sediment:**
Groundwater: Confirmed Above Cleanup Levels **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Lead **Sediment:**
Groundwater: Confirmed Above Cleanup Levels **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Petroleum-Gasoline **Sediment:**
Groundwater: Confirmed Above Cleanup Levels **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

197	5 of 5	SSE	0.45 / 2,352.02	8.80 / -97	**Seattle Waterfront Marriott Hotel** **2100 ALASKAN WAY** **SEATTLE WA 98121**	LUST

Facility Site ID: 1938238 **County:** King
Cleanup Site ID: 5270 **Latitude:** 47.61025
Responsible Unit: Northwest **Longitude:** -122.346111

Region: Northwest
Alternate Site Names:

Tank Detail(s)

UST ID: 618927
LUST ID: 5872
LUST Status: LUST - NFA
Status Date: 07/25/2003
Release Date: 05/26/2003

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Lead
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

---

198 | 1 of 1 | ESE | 0.45 / 2,355.41 | 132.65 / 27 | **Cinerama**
2100 4TH AVE
SEATTLE WA 98121 | ALL SITES

Facility/Site ID: 71954635
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000006833
Facility Alternate:
Interaction ID: 60410
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 25-Nov-1998
Interact End Dt: 06-Mar-1999
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Address
Location Verified: N
GIS latitude: 47.614430495
GIS longitude: -122.343658015

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
199	1 of 1	ESE	0.45 / 2,382.08	142.22 / 36	THE MAIL BOX 300 LENORA ST. SEATTLE WA 98121	RECYCLERS

Details

Organization ID:	1546	***E-Cycle:***	No
Organization Name:	The Mail Box	***Lightr Recycle:***	No
Organization Contact:	No Longer Tracked	***County:***	KING
Organization Email:	No Longer Tracked	***Latitude:***	
Material Category:	Plastic	***Longitude:***	
Material Type:	Bubble Wrap	***Residential:***	
Service Type:	Dropoff	***Commercial:***	
Customer Type:	Residential	***Phone:***	206-728-1228
Website:	https://www.mailboxseattle.com/		
Hours:	Mon-Fri, 8am-5pm; Sat, 9am-5pm		
Comments:	Call first.		

Organization ID:	1546	***E-Cycle:***	No
Organization Name:	The Mail Box	***Lightr Recycle:***	No
Organization Contact:	No Longer Tracked	***County:***	KING
Organization Email:	No Longer Tracked	***Latitude:***	
Material Category:	Paper	***Longitude:***	
Material Type:	Cardboard	***Residential:***	
Service Type:	Dropoff	***Commercial:***	
Customer Type:	Residential	***Phone:***	206-728-1228
Website:	https://www.mailboxseattle.com/		
Hours:	Mon-Fri, 8am-5pm; Sat, 9am-5pm		
Comments:	Call first.		

Organization ID:	1546	***E-Cycle:***	No
Organization Name:	The Mail Box	***Lightr Recycle:***	No
Organization Contact:	No Longer Tracked	***County:***	KING
Organization Email:	No Longer Tracked	***Latitude:***	
Material Category:	Plastic	***Longitude:***	
Material Type:	Styrofoam & Packing Peanuts	***Residential:***	
Service Type:	Dropoff	***Commercial:***	
Customer Type:	Residential	***Phone:***	206-728-1228
Website:	https://www.mailboxseattle.com/		
Hours:	Mon-Fri, 8am-5pm; Sat, 9am-5pm		
Comments:	Call first.		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
200	1 of 1	E	0.45 / 2,387.75	101.90 / -4	SEA43 Nitro North 2250 7TH AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID:	38667
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	CRK000095690
Facility Alternate:	SEA43 (Nitro North)
Interaction ID:	137765
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	TIER2
Interaction Desc:	Emergency/Haz Chem Rpt TIER2
Interact Start Dt:	08-Feb-2021
Interact End Dt:	
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	EPCRA
Database Name Desc:	Emergency Planning & Community Right-to-Know Act

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	
Horizont 1:	WGS84	***GIS latitude:***	47.61702
Horizont 2:	Address	***GIS longitude:***	-122.34066

201	*1 of 3*	*E*	*0.46 / 2,444.32*	*100.02 / -6*	***AMAZON SEA44 FRONTIER 2205 7TH AVE SEATTLE WA 98121***	***ALL SITES***

Facility/Site ID:	55825
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	CRK000096360
Facility Alternate:	AMAZON SEA44 FRONTIER
Interaction ID:	139254
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	TIER2
Interaction Desc:	Emergency/Haz Chem Rpt TIER2
Interact Start Dt:	13-Apr-2021
Interact End Dt:	
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	EPCRA
Database Name Desc:	Emergency Planning & Community Right-to-Know Act

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	
Horizont 1:	WGS84	***GIS latitude:***	47.61662
Horizont 2:	Address	***GIS longitude:***	-122.34064

201	*2 of 3*	*E*	*0.46 / 2,444.32*	*100.02 / -6*	***Block 18 Amazon Frontier 2205 7TH Avenue SEATTLE WA 98121***	***CSCSL***

Fac Site ID:	55825	***Responsible Unit:***	Northwest
Cleanup Site ID:	16642	***Fac Site ID (OD):***	
Site Status:	Awaiting Cleanup	***Cleanup SiteID(OD):***	
Site Rank:		***Site Rank (OD):***	
Current VCP:	Yes	***Has Env Coven (OD):***	
Past VCP:	Yes	***Respon Unit (OD):***	
Has Inst Control:		***County (OD):***	
County:	King	***Region (OD):***	
Region:	Northwest	***Longitude (OD):***	
Latitude:	47.6166200009392	***Latitude (OD):***	
Longitude:	-122.34064		
Site Name:	Block 18 Amazon Frontier		
Address:	2205 7TH Avenue		
City:	SEATTLE		
Zip Code:	98121		
Site Status (OD):			
Site Name (OD):			
Address (OD):			
City (OD):			
Zipcode (OD):			
Location (OD):			
Alternate Site Names:	AMAZON SEA44 FRONTIER,Block 18 Amazon Frontier		
Data Source(s):	Confirmed and Suspected Contaminated Sites		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminants Detail(s)

Contaminant Name:	Polycyclic Aromatic Hydrocarbons
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

201	*3 of 3*	*E*	*0.46 / 2,444.32*	*100.02 / -6*	***Block 18 Amazon Frontier*** ***2205 7TH Avenue*** ***SEATTLE WA 98121***	*VCP*

Facility Site ID:	55825	***County:***	King
Cleanup Site ID:	16642	***Latitude:***	47.6166200009392
Region:	Northwest	***Longitude:***	-122.34064
Alternate Site Names:	AMAZON SEA44 FRONTIER,Block 18 Amazon Frontier		
Data Source(s):	Voluntary Cleanup Program (VCP) Wait Lists - New; Confirmed and Suspected Contaminated Sites; All Cleanup Sites in Washington State		

WA ECY Toxics Cleanup Program - VCP Wait List - New

VCP Project No:	NW3342
Application Decision Date:	06/08/2022
Activity:	VCP Opinion on Site Cleanup
Activity Status Date:	06/08/2022
Activity Status:	In Process

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List

Site Status:	Awaiting Cleanup
Current VCP:	Yes
Past VCP:	Yes
Site Rank:	
Responsible Unit:	Northwest
Has Inst Control:	

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List - Contaminants

Contaminant Name:	Polycyclic Aromatic Hydrocarbons	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status:	Awaiting Cleanup
Site Rank:	
Has Inst Control:	
Current VCP:	Yes
Past VCP:	Yes
Responsible Unit:	Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name:	Polycyclic Aromatic Hydrocarbons	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
202	1 of 3	ESE	0.47 / 2,456.05	148.64 / 43	Lenora Holdings Company LLC 2031 3RD AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID: 15231
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000052882
Facility Alternate: Lenora Holdings Company LLC
Interaction ID: 122248
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 17-May-2017
Interact End Dt: 31-Dec-2017
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID:
Facility Alternate: Lenora Holdings
Interaction ID: 129047
Interaction Status: A
Interac Status Desc: Active
Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 04-Dec-2017
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6128216655
GIS longitude: -122.342197477

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
202	2 of 3	ESE	0.47 / 2,456.05	148.64 / 43	Lenora Holdings 2031 3RD AVE SEATTLE WA 98121	CSCSL

Fac Site ID: 15231
Cleanup Site ID: 14822
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6128216655474
Longitude: -122.342197476554
Site Name: Lenora Holdings
Address: 2031 3RD AVE
City: SEATTLE
Zip Code: 98121
Site Status (OD):
Responsible Unit: Pollution Liability Ins Agcy
Fac Site ID (OD):
Cleanup SiteID(OD):
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD):
County (OD):
Region (OD):
Longitude (OD):
Latitude (OD):

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Name (OD):
Address (OD):
City (OD):
Zipcode (OD):
Location (OD):
Alternate Site Names: Lenora Holdings Company LLC
Data Source(s): Confirmed and Suspected Contaminated Sites

Contaminants Detail(s)

Contaminant Name: Other Non-Halogenated Organics
Groundwater: Suspected
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Suspected
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Suspected
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater: Suspected
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

202	*3 of 3*	*ESE*	*0.47 / 2,456.05*	*148.64 / 43*	***Lenora Holdings 2031 3rd Avenue, Seattle, WA 98121 WA***	***LUST PTAP***

FSID No: 15231
TAP: PNW147
Status: In Progress
Entry Date: 6/19/2019
URL: https://plia.box.com/s/tm1zgzsa9unnvc32jbtfyapz9ay4xed4

203	*1 of 4*	*NE*	*0.47 / 2,459.32*	*89.24 / -17*	***Seattle Vagabond Inn 325 AURORA AVE N SEATTLE WA 98109***	***CSCSL***

Fac Site ID:	95376999	***Responsible Unit:***	Northwest
Cleanup Site ID:	4739	***Fac Site ID (OD):***	95376999
Site Status:	Cleanup Started	***Cleanup SiteID(OD):***	4739
Site Rank:		***Site Rank (OD):***	
Current VCP:		***Has Env Coven (OD):***	
Past VCP:	Yes	***Respon Unit (OD):***	Northwest
Has Inst Control:		***County (OD):***	King
County:	King	***Region (OD):***	Northwest

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Region: Northwest
Latitude: 47.6217448377164
Longitude: -122.344169670063
Site Name: Seattle Vagabond Inn
Address: 325 AURORA AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Seattle Vagabond Inn
Address (OD): 325 AURORA AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): "" (47.621263, -122.344987)
Longitude (OD): -122.344987
Latitude (OD): 47.621263
Alternate Site Names: Civic Hotel,Seattle Pacific Hotel,Vagabond Motel
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Halogenated Organics
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Halogenated Organics
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Halogenated Organics
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
203	2 of 4	NE	0.47 / 2,459.32	89.24 / -17	Seattle Vagabond Inn 325 AURORA AVE N 325 7th Ave N SEATTLE WA 98109	ALL SITES

Facility/Site ID: 95376999
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000009845
Facility Alternate:
Interaction ID: 74103
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 14-Oct-1999
Interact End Dt: 31-Dec-2002
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID:
Facility Alternate: Seattle Vagabond Inn
Interaction ID: 74105
Interaction Status: I

Interac Status Desc: Inactive
Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 11-Aug-2006
Interact End Dt: 26-Mar-2009
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: WAH000009845
Facility Alternate: Seattle City Light Vagabond Inn
Interaction ID: 100193
Interaction Status: A
Interac Status Desc: Active
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 10-Feb-2012
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: NW2133
Facility Alternate: Seattle Vagabond Inn
Interaction ID: 89408
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 26-Mar-2009
Interact End Dt: 30-Oct-2015
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: NW0484
Facility Alternate: Seattle Vagabond Inn
Interaction ID: 74104
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 23-May-2000
Interact End Dt: 11-Aug-2006
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID:
Facility Alternate: Seattle Vagabond Inn
Interaction ID: 131590
Interaction Status: A
Interac Status Desc: Active
Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 30-Oct-2015
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6217448377
GIS longitude: -122.34416967

---

203 *3 of 4* *NE* *0.47 / 2,459.32* *89.24 / -17*

Seattle Vagabond Inn
325 AURORA AVE N
SEATTLE WA 98109

ICR

Cleanup Site ID: 4739
Facility Site ID: 95376999
Site Status: Cleanup Started
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site:
WRIA ID: 8
Is NFA Site:
Responsible Unit: Northwest
Latitude: 47.621262999999999
Longitude: -122.344987
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID:
VCP Prj No: NW2133
Activity Name: VCP Application
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2009-03-26
End Date:
Legal Mechanism:
Performed by:
Project Manager: Northwest Region

Related ID:
VCP Prj No: NW0484
Activity Name: VCP Opinion on Remedial Investigation Work Plan
Activity Status: Canceled
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2000-05-23
End Date:
Legal Mechanism:
Performed by:
Project Manager: Madakor, Nnamdi

Related ID:
VCP Prj No: NW0484
Activity Name: VCP Termination
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date:
End Date: 2006-08-11
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No: NW0484
Activity Name: VCP Application
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2000-05-23
End Date:
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No: NW2133
Activity Name: VCP Termination
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date:
End Date: 2015-10-30
Legal Mechanism:
Performed by:
Project Manager: Bardy, Louise

Related ID:
VCP Prj No: NW2133
Activity Name: VCP Status Request
Activity Status: Completed
County Name: King
Applies to: VcpProject
Start Date: 2015-07-14
End Date:
Legal Mechanism:
Performed by:
Project Manager: Bardy, Louise

Applies to Description: Voluntary Cleanup Program

Media Contaminants

Contaminant Type:	Halogenated Organics	***Sediment:***	
Groundwater:	C	***Sediment Desc.:***	
Groundwater Desc.:	Confirmed Above Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

---

203 ***4 of 4*** ***NE*** ***0.47 / 2,459.32*** ***89.24 / -17*** ***Seattle Vagabond Inn***
325 AURORA AVE N
SEATTLE WA 98109 ***VCP***

Facility Site ID:	95376999	***County:***	King
Cleanup Site ID:	4739	***Latitude:***	47.6217448377164
Region:	Northwest	***Longitude:***	-122.344169670063

Alternate Site Names: Civic Hotel,Seattle Pacific Hotel,Vagabond Motel
Data Source(s): Confirmed and Suspected Contaminated Sites; Confirmed and Suspected Contaminated Sites; All Cleanup Sites in Washington State

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List

Site Status:	Cleanup Started
Current VCP:	
Past VCP:	Yes
Site Rank:	
Responsible Unit:	Northwest
Has Inst Control:	

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List - Contaminants

Contaminant Name:	Halogenated Organics	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status:	Cleanup Started
Site Rank:	
Has Inst Control:	
Current VCP:	
Past VCP:	Yes
Responsible Unit:	Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name:	Halogenated Organics	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		

---

204 ***1 of 1*** ***SE*** ***0.47 / 2,462.70*** ***138.34 / 33*** ***United Resource System***
2025 1ST AVE STE 500
SEATTLE WA 98121 ***ALL SITES***

Facility/Site ID: 55859337
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology

Facilties - Sites

Facility/Site Interaction

Program ID:	WAR000002196
Facility Alternate:	
Interaction ID:	51796
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	08-May-1995
Interact End Dt:	31-Dec-1995
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Program ID:	WAR000002196
Facility Alternate:	
Interaction ID:	51797
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	21-Feb-2001
Interact End Dt:	31-Dec-2001
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	N
Horizont 1:	NAD83	***GIS latitude:***	47.6114
Horizont 2:	Unknown	***GIS longitude:***	-122.34284

---

205 ***1 of 4*** ***ESE*** ***0.47 / 2,481.50*** ***122.22 / 16*** ***Martin Apartments 2101 2105 & 2111 5TH AVE SEATTLE WA 98121*** ***CSCSL***

Fac Site ID:	8826590	***Responsible Unit:***	Northwest
Cleanup Site ID:	4646	***Fac Site ID (OD):***	8826590
Site Status:	Cleanup Started	***Cleanup SiteID(OD):***	4646
Site Rank:		***Site Rank (OD):***	
Current VCP:		***Has Env Coven (OD):***	
Past VCP:	Yes	***Respon Unit (OD):***	Northwest
Has Inst Control:		***County (OD):***	King
County:	King	***Region (OD):***	Northwest
Region:	Northwest	***Longitude (OD):***	-122.340846
Latitude:	47.6145258611178	***Latitude (OD):***	47.614526
Longitude:	-122.340846374671		
Site Name:	Martin Apartments		
Address:	2101 2105 & 2111 5TH AVE		
City:	SEATTLE		
Zip Code:	98121		
Site Status (OD):	Cleanup Started		
Site Name (OD):	Martin Apartments		
Address (OD):	2101 2105 & 2111 5TH AVE		
City (OD):	SEATTLE		
Zipcode (OD):	98121		
Location (OD):	"" (47.614526, -122.340846)		
Alternate Site Names:	Martin Apartments (Off-Property),Martin Apartments (Property NFA),Tax Parcel 069600-0025,The Martin Apartments		

Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

205	*2 of 4*	*ESE*	*0.47 / 2,481.50*	*122.22 / 16*	***Tax Parcel 069600-0025*** ***2101 2105 & 2111 5TH AVE*** ***SEATTLE WA 98121***	***ALL SITES***

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility/Site ID: 8826590
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: NW2560
Facility Alternate: Tax Parcel 069600-0025
Interaction ID: 98611
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 30-Nov-2011
Interact End Dt: 15-Aug-2013
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID:
Facility Alternate: Martin Apartments (Off-Property)
Interaction ID: 128285
Interaction Status: A
Interac Status Desc: Active
Interaction Type: SCS
Interaction Desc: State Cleanup Site
Interact Start Dt: 15-Aug-2013
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: NW1654
Facility Alternate: Tax Parcel 069600-0025
Interaction ID: 23532
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 08-Aug-2006
Interact End Dt: 25-Jan-2010
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6145258611
GIS longitude: -122.340846375

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
205	3 of 4	ESE	0.47 / 2,481.50	122.22 / 16	Martin Apartments 2101 2105 & 2111 5TH AVE SEATTLE WA 98121	ICR

Cleanup Site ID: 4646
Facility Site ID: 8826590
Site Status: Cleanup Started
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
WRIA ID: 8
Is NFA Site:
Responsible Unit: Northwest
Latitude: 47.614525861117798
Longitude: -122.340846374671
Legislative District: 36
Congr District: 7
County Name: King

Is PSI Site: Yes

Cleanup Activities

Related ID:
VCP Prj No: NW2560
Activity Name: VCP Receipt of Plan or Report
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2013-05-17
End Date:
Legal Mechanism:
Performed by:
Project Manager: Pederson, Carrie

Related ID:
VCP Prj No: NW1654
Activity Name: VCP Application
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2006-08-08
End Date:
Legal Mechanism:
Performed by:
Project Manager: Northwest Region

Related ID:
VCP Prj No: NW2560
Activity Name: VCP Termination
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date:
End Date: 2013-08-15
Legal Mechanism:
Performed by:
Project Manager: Fernandez, Sonia

Related ID:
VCP Prj No:
Activity Name: Initial Investigation / Federal Preliminary Assessment
Activity Status: Canceled
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date: 2006-08-08
End Date:
Legal Mechanism:
Performed by:
Project Manager: Northwest Region

Related ID:
VCP Prj No: NW2560
Activity Name: VCP Application
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2011-11-30
End Date:
Legal Mechanism:
Performed by:
Project Manager: Northwest Region

Related ID:
VCP Prj No: NW1654
Activity Name: VCP Termination
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date:
End Date: 2010-01-25
Legal Mechanism:
Performed by:
Project Manager: Mitchell, Dolores

Related ID:
VCP Prj No: NW2560
Activity Name: VCP Opinion on Site Cleanup
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2013-05-17
End Date: 2013-08-15
Legal Mechanism:
Performed by:
Project Manager: Vick, Heather

Related ID:
VCP Prj No: NW2560
Activity Name: VCP Receipt of Plan or Report
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2011-11-30
End Date:
Legal Mechanism:
Performed by:
Project Manager: Fernandez, Sonia

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2006-08-08
Activity Name:	Site Discovery/Release Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	
VCP Prj No:	NW1654	**End Date:**	
Activity Name:	VCP Opinion on Cleanup Action Plan	**Legal Mechanism:**	
Activity Status:	Canceled	**Performed by:**	
County Name:	King	**Project Manager:**	Liu, Jing
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Media Contaminants

Contaminant Type:	Benzene	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

Contaminant Type:	Petroleum-Diesel	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

Contaminant Type:	Petroleum-Gasoline	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

Contaminant Type:	Petroleum Products-Unspecified	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King

---

205 **4 of 4** **ESE** **0.47 / 2,481.50** **122.22 / 16**

Martin Apartments
2101 2105 & 2111 5TH AVE
SEATTLE WA 98121

VCP

Facility Site ID:	8826590	**County:**	King
Cleanup Site ID:	4646	**Latitude:**	47.6145258611178
Region:	Northwest	**Longitude:**	-122.340846374671

Alternate Site Names: Martin Apartments (Off-Property),Martin Apartments (Property NFA),Tax Parcel 069600-0025,The Martin Apartments

Data Source(s): Confirmed and Suspected Contaminated Sites; Confirmed and Suspected Contaminated Sites; All Cleanup Sites in Washington State

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List

Site Status: Cleanup Started

Current VCP:
Past VCP: Yes
Site Rank:
Responsible Unit: Northwest
Has Inst Control:

WA ECY Toxics Cleanup Program - Confirmed and Suspected Contaminated Sites List - Contaminants

Contaminant Name: Petroleum-Other ***Sediment:***
Groundwater: ***Air:***
Surfacewater: ***Bedrock:***
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Petroleum-Diesel ***Sediment:***
Groundwater: ***Air:***
Surfacewater: ***Bedrock:***
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Benzene ***Sediment:***
Groundwater: ***Air:***
Surfacewater: ***Bedrock:***
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Petroleum Products-Unspecified ***Sediment:***
Groundwater: ***Air:***
Surfacewater: ***Bedrock:***
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Petroleum-Gasoline ***Sediment:***
Groundwater: ***Air:***
Surfacewater: ***Bedrock:***
Soil: Confirmed Above Cleanup Levels

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: Cleanup Started
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Benzene ***Sediment:***
Groundwater: ***Air:***
Surfacewater: ***Bedrock:***
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Petroleum-Gasoline ***Sediment:***
Groundwater: ***Air:***
Surfacewater: ***Bedrock:***
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Petroleum-Other ***Sediment:***
Groundwater: ***Air:***
Surfacewater: ***Bedrock:***
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Petroleum-Diesel ***Sediment:***
Groundwater: ***Air:***
Surfacewater: ***Bedrock:***
Soil: Confirmed Above Cleanup Levels

Contaminant Name: Petroleum Products-Unspecified ***Sediment:***

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Groundwater: **Air:**
Surfacewater: **Bedrock:**
Soil: Confirmed Above Cleanup Levels

---

206 *1 of 1* *WNW* *0.47 / 2,506.34* *83.12 / -23*

Adsco Printing
315 1ST AVE W
SEATTLE WA 98119-4196

ALL SITES

Facility/Site ID: 18466563
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAD009260266
Facility Alternate:
Interaction ID: 30589
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 08-Feb-1988
Interact End Dt: 03-Sep-1996
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.621388926
GIS longitude: -122.358352798

---

207 *1 of 1* *ESE* *0.48 / 2,510.52* *134.47 / 29*

CVS Pharmacy 10982
2035 4th Ave
Seattle WA 98121

ALL SITES

Facility/Site ID: 8715
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000052785
Facility Alternate: CVS Pharmacy 10982
Interaction ID: 122068
Interaction Status: A
Interac Status Desc: Active
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 02-May-2017
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Address
Location Verified:
GIS latitude: 47.61351
GIS longitude: -122.34138

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
208	1 of 4	ESE	0.48 / 2,521.17	121.79 / 16	Sterling Realty Organization Co 2101-2111 5TH AVE SEATTLE WA 98121	CSCSL

Fac Site ID: 92546394
Cleanup Site ID: 6867
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.614459
Longitude: -122.34184
Site Name: Sterling Realty Organization Co
Address: 2101-2111 5TH AVE
City: SEATTLE
Zip Code: 98121
Site Status (OD): Cleanup Started
Site Name (OD): Sterling Realty Organization Co
Address (OD): 2101-2111 5TH AVE
City (OD): SEATTLE
Zipcode (OD): 98121-2510
Location (OD): ""
(47.614459, -122.34184)
Alternate Site Names: CHEVON SERVICE STATION 20-7626,SIGNAL SERVICE STATION S-41-28,STERLING REALTY ORGANIZATION CO PROPERTY
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 92546394
Cleanup SiteID(OD): 6867
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.34184
Latitude (OD): 47.614459

Contaminants Detail(s)

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

208	2 of 4	ESE	0.48 / 2,521.17	121.79 / 16	STERLING REALTY ORGANIZATION CO 2101-2111 5TH AVE SEATTLE WA 98121-2510	ALL SITES

Facility/Site ID: 92546394
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 503123
Facility Alternate:
Interaction ID: 72215
Interaction Status: A
Interac Status Desc: Active
Interaction Type: LUST
Interaction Desc: LUST Facility
Interact Start Dt: 25-Sep-1997
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID:
Facility Alternate: STERLING REALTY ORGANIZATION CO
Interaction ID: 72217
Interaction Status: A
Interac Status Desc: Active
Interaction Type: INDPNDNT
Interaction Desc: Independent Cleanup
Interact Start Dt: 03-Aug-2006
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: 503123
Facility Alternate:
Interaction ID: 72216
Interaction Status: A
Interac Status Desc: Active
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 28-Jun-1999
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83
Horizont 2: Address
Location Verified: N
GIS latitude: 47.614459
GIS longitude: -122.34184

---

208 *3 of 4* *ESE* *0.48 / 2,521.17* *121.79 / 16* ***Sterling Realty Organization Co*** ***2101-2111 5TH AVE*** ***SEATTLE WA 98121*** ***LUST***

Facility Site ID: 92546394
Cleanup Site ID: 6867
Responsible Unit: Northwest
Region: Northwest
Alternate Site Names: CHEVON SERVICE STATION 20-7626,SIGNAL SERVICE STATION S-41-28,STERLING REALTY ORGANIZATION CO PROPERTY
County: King
Latitude: 47.614459
Longitude: -122.34184

Tank Detail(s)

UST ID: 503123
LUST ID: 5301
LUST Status: LUST - Cleanup Started
Status Date: 06/05/1997
Release Date: 09/25/1997

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

---

208 *4 of 4* *ESE* *0.48 / 2,521.17* *121.79 / 16* ***STERLING REALTY ORGANIZATION CO*** ***2101-2111 5TH AVE*** ***SEATTLE WA 98121-2510*** ***ICR***

Cleanup Site ID: 6867
Facility Site ID: 92546394
Site Status: Cleanup Started
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site: Yes
WRIA ID: 8
Is NFA Site:
Responsible Unit: Northwest
Latitude: 47.614458999999997
Longitude: -122.34184
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID:	5301	***Start Date:***	1998-06-04
VCP Prj No:		***End Date:***	2006-08-01
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	5301	***Start Date:***	1998-07-01
VCP Prj No:		***End Date:***	2006-08-01
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	5301	***Start Date:***	1997-09-23
VCP Prj No:		***End Date:***	1997-09-25
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	2006-11-03
Activity Name:	Site Discovery/Release Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:	5301	***Start Date:***	1997-09-25
VCP Prj No:		***End Date:***	1997-09-25
Activity Name:	LUST - Notification	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Media Contaminants

Contaminant Type:	Petroleum-Other	***Sediment:***	
Groundwater:	C	***Sediment Desc.:***	
Groundwater Desc.:	Confirmed Above Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

Contaminant Type:	Benzene	***Sediment:***	
Groundwater:	C	***Sediment Desc.:***	
Groundwater Desc.:	Confirmed Above Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

Contaminant Type:	Petroleum-Gasoline	***Sediment:***	
Groundwater:	C	***Sediment Desc.:***	
Groundwater Desc.:	Confirmed Above Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Soil Desc.: Confirmed Above Cleanup Level **County Name:** King

---

209 *1 of 1* **SE** *0.48 / 2,542.72* *10.06 / -96* **ELLIOTT BAY SEAWALL** **ALL SITES**

Seattle WA 98101

Facility/Site ID: 20858
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAR126930
Facility Alternate: Elliott Bay Seawall Project
Interaction ID: 104504
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: CONSTSWGP
Interaction Desc: Construction SW GP
Interact Start Dt: 15-Mar-2013
Interact End Dt: 13-Nov-2014
Ecology Program: WATQUAL
Program Name Desc: Water Quality Program
Prog Database Name: PARIS
Database Name Desc: Permitting & Reporting Information System

Program ID: 201100778
Facility Alternate: ELLIOTT BAY SEAWALL
Interaction ID: 104368
Interaction Status: A
Interac Status Desc: Active
Interaction Type: SEAPROJ
Interaction Desc: SEA Project Site
Interact Start Dt: 25-Mar-2013
Interact End Dt:
Ecology Program: SEA
Program Name Desc: Shorelines & Environmental Assistance Program
Prog Database Name: AQUATICS
Database Name Desc: Aquatics Site System

Facility Location Detail

Horizontal: 40ft **Location Verified:**
Horizont 1: NAD83HARN **GIS latitude:** 47.6101291972
Horizont 2: Digital map or GIS **GIS longitude:** -122.346214947

---

210 *1 of 1* **ESE** *0.48 / 2,550.13* *148.29 / 43* **Barg KH Cleaners** **ALL SITES**
2018 3RD AVE
SEATTLE WA 98121

Facility/Site ID: 68827
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: Barg KH Cleaners
Interaction ID: 137376
Interaction Status: A
Interac Status Desc: Active
Interaction Type: RSVP
Interaction Desc: Revised Site Visit Program
Interact Start Dt: 30-Dec-2020

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: RSVP
Database Name Desc: Revised Site Visit Program

Facility Location Detail

Horizontal: Unknown
Horizont 1: WGS84
Horizont 2: Address
Location Verified:
GIS latitude: 47.61306
GIS longitude: -122.34138

---

211 | ***1 of 1*** | ***ESE*** | ***0.48 / 2,555.35*** | ***121.24 / 15*** | ***Vulcan Construction 5th & Lenora Seattle WA 98121*** | ***ALL SITES***

Facility/Site ID: 21081
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: Vulcan Construction
Interaction ID: 80120
Interaction Status: A
Interac Status Desc: Active
Interaction Type: RSVP
Interaction Desc: Revised Site Visit Program
Interact Start Dt: 14-Aug-2008
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: RSVP
Database Name Desc: Revised Site Visit Program

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6144444444
GIS longitude: -122.340527778

---

212 | ***1 of 5*** | ***NW*** | ***0.48 / 2,556.68*** | ***134.27 / 29*** | ***USPS Queen Anne 415 1ST AVE N SEATTLE WA 98109*** | ***CSCSL NFA***

Fac Site ID: 31537996
Cleanup Site ID: 8673
Site Status: NFA
NFA Date: 02/24/2012
Responsible Unit: Northwest
Has Insti Control:
Region: Northwest
County: King
Latitude: 47.62296697714
Longitude: -122.355890422008
NFA Reason: Voluntary Cleanup Program Review
Alternate Site Names: 1st Ave N Post Office
Location (OD): "" (47.622967, -122.35589)
Fac Site ID (OD): 31537996
Cleanup SiteID(OD): 8673
Site Status (OD): No Further Action
Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
Region (OD): Northwest
County (OD): King
Latitude (OD): 47.622967
Longitude (OD): -122.35589
Data Source(s): Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

NFA Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

212	2 of 5	NW	0.48 / 2,556.68	134.27 / 29	USPS QUEEN ANNE 415 1ST AVE N SEATTLE WA 98109	ALL SITES

Facility/Site ID: 31537996
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 200539
Facility Alternate:
Interaction ID: 37398
Interaction Status: A
Interac Status Desc: Active
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 28-Feb-2000
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: NW2549
Facility Alternate: USPS QUEEN ANNE
Interaction ID: 98547
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 10-Nov-2011
Interact End Dt: 24-Feb-2012
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: 200539
Facility Alternate:
Interaction ID: 37397
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: LUST
Interaction Desc: LUST Facility

Interact Start Dt:	08-Feb-1993
Interact End Dt:	21-May-1995
Ecology Program:	TOXICS
Program Name Desc:	Toxics Cleanup Program
Prog Database Name:	ISIS
Database Name Desc:	Integrated Site Info System

Facility Location Detail

Horizontal:	40ft	**Location Verified:**	
Horizont 1:	NAD83HARN	**GIS latitude:**	47.6229669771
Horizont 2:	Digital map or GIS	**GIS longitude:**	-122.355890422

212 ***3 of 5*** ***NW*** ***0.48 / 2,556.68*** ***134.27 / 29*** ***USPS Queen Anne 415 1ST AVE N SEATTLE WA 98109*** ***ICR***

Cleanup Site ID:	8673	**WRIA ID:**	8
Facility Site ID:	31537996	**Is NFA Site:**	Yes
Site Status:	No Further Action Required	**Responsible Unit:**	Northwest
Statute:	MTCA	**Latitude:**	47.622966977140003
Rank:		**Longitude:**	-122.35589042200836
Rank Description:		**Legislative District:**	36
Has Env Covenant:		**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:	2546	**Start Date:**	1993-08-09
VCP Prj No:		**End Date:**	1993-08-09
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		**Start Date:**	2011-11-10
VCP Prj No:	NW2549	**End Date:**	
Activity Name:	VCP Application	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Fernandez, Sonia
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	1993-02-08
Activity Name:	Site Discovery/Release Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2011-08-08
Activity Name:	Initial Investigation / Federal Preliminary Assessment	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	Ecology w/ Contractor
County Name:	King	**Project Manager:**	Olsen, Russ
Applies to:	CleanupSite		
Applies to Description:			

Related ID:	2546	**Start Date:**	1993-04-30
VCP Prj No:		**End Date:**	1993-04-30
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Project Manager:

Related ID:
VCP Prj No:
Activity Name: Early Notice Letter(s)
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date:
End Date: 2011-10-03
Legal Mechanism:
Performed by:
Project Manager: Olsen, Russ

Related ID:
VCP Prj No:
Activity Name: Site Status Changed to NFA
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date:
End Date: 2012-02-24
Legal Mechanism:
Performed by:
Project Manager: Bails, John

Related ID: 2546
VCP Prj No:
Activity Name: LUST - Notification
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 1993-02-08
End Date: 1993-02-08
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No: NW2549
Activity Name: VCP Opinion on Site Cleanup
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2011-11-10
End Date: 2012-02-24
Legal Mechanism:
Performed by:
Project Manager: Bails, John

Related ID:
VCP Prj No: NW2549
Activity Name: VCP Termination
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date:
End Date: 2012-02-24
Legal Mechanism:
Performed by:
Project Manager: Bails, John

Media Contaminants

Contaminant Type: Petroleum-Other
Groundwater: C
Groundwater Desc.: Confirmed Above Cleanup Level
Surface Water:
Surfacewater Desc.:
Soil: C
Soil Desc.: Confirmed Above Cleanup Level
Sediment:
Sediment Desc.:
Air:
Air Desc.:
Bedrock:
Bedrock Desc.:
County Name: King

212	4 of 5	NW	0.48 / 2,556.68	134.27 / 29	USPS Queen Anne 415 1ST AVE N SEATTLE WA 98109	VCP

Facility Site ID: 31537996
Cleanup Site ID: 8673
Region: Northwest
Alternate Site Names: 1st Ave N Post Office
Data Source(s): No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State
County: King
Latitude: 47.62296697714
Longitude: -122.355890422008

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Status: NFA
NFA Date: 02/24/2012
Responsible Unit: Northwest
Has Inst Control:
NFA Reason: Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: No Further Action
Site Rank:
Has Inst Control:
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

212	5 of 5	NW	0.48 / 2,556.68	134.27 / 29	USPS Queen Anne 415 1ST AVE N SEATTLE WA 98109	LUST

Facility Site ID: 31537996
Cleanup Site ID: 8673
Responsible Unit: Northwest
Region: Northwest
Alternate Site Names: 1st Ave N Post Office
County: King
Latitude: 47.62296697714
Longitude: -122.355890422008

Tank Detail(s)

UST ID: 200539
LUST ID: 2546
LUST Status: LUST - NFA
Status Date: 02/24/2012
Release Date: 02/08/1993

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

213	1 of 1	NW	0.48 / 2,557.39	119.70 / 14	WA UW Queen Anne 401 QUEEN ANNE AVE N SEATTLE WA 98119	ALL SITES

Facility/Site ID: 15238964
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAD988507703
Facility Alternate: WA UW Queen Anne
Interaction ID: 28614
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 02-Jan-2005
Interact End Dt: 01-Jul-2020
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAD988507703
Facility Alternate: WA UW QUEEN ANNE
Interaction ID: 138313
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: TIER2
Interaction Desc: Emergency/Haz Chem Rpt TIER2
Interact Start Dt: 10-Mar-2005
Interact End Dt: 30-Jan-2015
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: EPCRA
Database Name Desc: Emergency Planning & Community Right-to-Know Act

Program ID: WAD988507703
Facility Alternate:
Interaction ID: 28610
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 12-Aug-1996
Interact End Dt: 31-Aug-1997
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAD988507703
Facility Alternate:
Interaction ID: 28611
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 30-Apr-1998
Interact End Dt: 31-Dec-2004
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAD988507703
Facility Alternate:
Interaction ID: 28613
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWOTHER
Interaction Desc: Haz Waste Management Activity
Interact Start Dt: 31-Dec-2004
Interact End Dt: 01-Jan-2004
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program

Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: WAD988507703
Facility Alternate:
Interaction ID: 28612
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWP
Interaction Desc: Hazardous Waste Planner
Interact Start Dt: 01-Jan-2000
Interact End Dt: 01-Mar-2001
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: HWPPRT
Database Name Desc: Hazardous Reporting

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6224016941
GIS longitude: -122.357099153

214	1 of 7	ESE	0.49 / 2,564.21	135.99 / 30	Jiffy Lube Store 2077 2025 4TH AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID: 31325769
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: CRK000060590
Facility Alternate:
Interaction ID: 37243
Interaction Status: A
Interac Status Desc: Active
Interaction Type: TIER2
Interaction Desc: Emergency/Haz Chem Rpt TIER2
Interact Start Dt: 13-Feb-2004
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: EPCRA
Database Name Desc: Emergency Planning & Community Right-to-Know Act

Program ID: 6781
Facility Alternate:
Interaction ID: 37241
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 01-Jan-1987
Interact End Dt: 27-Jan-2005
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: NW2072
Facility Alternate: Shell 2025 4th, Seattle
Interaction ID: 37244
Interaction Status: I
Interac Status Desc: Inactive

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 09-Feb-2009
Interact End Dt: 05-Dec-2014
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: 6781
Facility Alternate: Minit Lube 1113
Interaction ID: 37242
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: LUST
Interaction Desc: LUST Facility
Interact Start Dt: 26-Mar-1996
Interact End Dt: 05-Dec-2014
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: Unknown
Horizont 1: WGS84
Horizont 2: Address
Location Verified:
GIS latitude: 47.61334
GIS longitude: -122.34129

214	2 of 7	ESE	0.49 / 2,564.21	135.99 / 30	Jiffy Lube Store 2077 2025 4TH AVE SEATTLE WA 98121	DELISTED LST

Delisted Leaking Storage Tanks

Facility Site ID: 31325769
Cleanup Site ID: 5853
Responsible Section: Northwest
Region: Northwest
County: King
Latitude: 47.61317
Longitude: -122.342365
Original Source: LUST
Record Date: 27-May-2014

214	3 of 7	ESE	0.49 / 2,564.21	135.99 / 30	Jiffy Lube Store 2077 2025 4TH AVE SEATTLE WA 98121	INST

Facility Site ID: 31325769
Region: Northwest
County: King
Latitude: 47.61334
Longitude: -122.34129
Site Name: Jiffy Lube Store 2077
Address: 2025 4TH AVE
City: SEATTLE
Zip: 98121
Site Name (OD): Jiffy Lube Store 2077
Address (OD): 2025 4TH AVE
City (OD): SEATTLE
Zipcode (OD): 98121
Location (OD): "" (47.61317, -122.342365)
Cleanup Site ID: 5853
Region (OD): Northwest
County (OD): King
Latitude (OD): 47.61317
Longitude (OD): -122.342365
Data Source(s): Department of Ecology State of Washington - Environmental Covenants Registry List; Open Data Portal - Institutional Controls or Environmental Covenants Map

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Environmental Covenants Registry List

NFA Date:	12/05/2014
Site Status:	No Further Action
Tax Parcel No:	1977201215
Instrument Type:	Environmental Covenant
Media Restrictions:	Soil
Alternate Site Names:	MINIT LUBE 1113,MINIT-LUBE 1113,SHELL 2025 4TH,SEATTLE
Cnty Recording No:	20141114000530
Cnty Recording Dt:	11/14/2014
Responsible Unit:	Northwest
Active Control:	Yes
Control Stormwater:	No
Control Vapor Gas:	No
Prevent Reuse/Relocation:	No
Prohibit New Bldg Constr:	No
Prohibit Removal or Alteration:	Yes
Prohibit Soil Disturbance:	Yes
Ongoing Maint of Remedy:	Yes
Require Educational Programs:	No
Restrict Access:	No
Restrict All GW Extr:	No
Restrict Domestic GW:	No
Restrict Land Use:	Yes
Restrict Sedmnt Cap Disturb:	No
Restrict Shellfish and or Finf:	No
Restrict Surface Water Use:	No
Restrict Swim/Beach Play:	No
Restrictive Signage:	No
Maintain/Protect Monit System:	Yes
Other:	No

Open Data Portal - Environmental Covenants Map

Facility Site ID:	31325769
Cleanup Status:	No Further Action
Has Env Covenant:	Yes
Rank:	
Resp Section:	Northwest

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
214	4 of 7	ESE	0.49 / 2,564.21	135.99 / 30	Jiffy Lube Store 2077 2025 4TH AVE SEATTLE WA 98121	CSCSL NFA

Fac Site ID:	31325769	***Fac Site ID (OD):***	31325769
Cleanup Site ID:	5853	***Cleanup SiteID(OD):***	5853
Site Status:	NFA	***Site Status (OD):***	No Further Action
NFA Date:	12/05/2014	***Rank (OD):***	
Responsible Unit:	Northwest	***Has Env Coven (OD):***	Yes
Has Insti Control:	Yes	***Respon Unit (OD):***	Northwest
Region:	Northwest	***Region (OD):***	Northwest
County:	King	***County (OD):***	King
Latitude:	47.61334	***Latitude (OD):***	47.61317
Longitude:	-122.34129	***Longitude (OD):***	-122.342365
NFA Reason:	Voluntary Cleanup Program Review		
Alternate Site Names:	MINIT LUBE 1113,MINIT-LUBE 1113,SHELL 2025 4TH,SEATTLE		
Location (OD):	"" (47.61317, -122.342365)		
Data Source(s):	Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants		

NFA Contaminants Detail(s)

Contaminant Name:	Metals - Other
Groundwater:	Below Cleanup Levels
Surfacewater:	

Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Methyl tertiary-butyl ether
Groundwater: Below Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Remediated-Above
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Remediated-Above
Sediment:
Air:
Bedrock:

Contaminant Name: Lead
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Metals - Other
Contaminant Media: Groundwater
Contaminant Status: Below Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Remediated-Above

Contaminant: Lead
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Methyl tertiary-butyl ether
Contaminant Media: Groundwater
Contaminant Status: Below Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals - Other
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Lead
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel

Contaminant Media: Soil
Contaminant Status: Remediated-Above

---

214 | **5 of 7** | **ESE** | **0.49 / 2,564.21** | **135.99 / 30** | **Jiffy Lube Store 2077**
2025 4TH AVE
SEATTLE WA 98121 | **ICR**

Cleanup Site ID:	5853	**WRIA ID:**	8
Facility Site ID:	31325769	**Is NFA Site:**	Yes
Site Status:	No Further Action Required	**Responsible Unit:**	Northwest
Statute:	MTCA	**Latitude:**	47.613169999999997
Rank:		**Longitude:**	-122.342365
Rank Description:		**Legislative District:**	36
Has Env Covenant:		**Congr District:**	7
Is Brownfiled Site:		**County Name:**	King
Is PSI Site:	Yes		

Cleanup Activities

Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2014-12-05
Activity Name:	Site Status Changed to NFA	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Fernandez, Sonia
Applies to:	CleanupSite		
Applies to Description:			

Related ID:	4124	**Start Date:**	2009-10-06
VCP Prj No:		**End Date:**	2009-10-06
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	4124	**Start Date:**	2013-10-03
VCP Prj No:		**End Date:**	2013-10-07
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	4124	**Start Date:**	1996-03-06
VCP Prj No:		**End Date:**	1996-03-07
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	4124	**Start Date:**	2007-05-31
VCP Prj No:		**End Date:**	2007-06-06
Activity Name:	LUST - Report Received	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:		**Start Date:**	
VCP Prj No:	NW2072	**End Date:**	2014-12-05
Activity Name:	VCP Termination	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Fernandez, Sonia
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID: 4124 **Start Date:** 2008-01-03
VCP Prj No: **End Date:** 2008-01-07
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 4124 **Start Date:** 2009-02-27
VCP Prj No: **End Date:** 2009-03-11
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: **Start Date:** 2009-02-09
VCP Prj No: NW2072 **End Date:**
Activity Name: VCP Application **Legal Mechanism:**
Activity Status: Completed **Performed by:**
County Name: King **Project Manager:** Northwest Region
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Related ID: **Start Date:**
VCP Prj No: NW2072 **End Date:** 2009-03-05
Activity Name: VCP Opinion on Interim Action **Legal Mechanism:**
Activity Status: Completed **Performed by:**
County Name: King **Project Manager:** Adams, Mark
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Related ID: 4124 **Start Date:** 2007-10-25
VCP Prj No: **End Date:** 2007-10-30
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: **Start Date:** 2013-10-07
VCP Prj No: NW2072 **End Date:** 2014-12-05
Activity Name: VCP Opinion on Feasibility Study **Legal Mechanism:**
Activity Status: Completed **Performed by:**
County Name: King **Project Manager:** Fernandez, Sonia
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program

Related ID: 4124 **Start Date:** 2007-07-06
VCP Prj No: **End Date:** 2007-07-09
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 4124 **Start Date:** 2013-08-07
VCP Prj No: **End Date:** 2013-08-13
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID: 4124 **Start Date:** 2010-03-09
VCP Prj No: **End Date:** 2010-03-12
Activity Name: LUST - Report Received **Legal Mechanism:**
Activity Status: **Performed by:**
County Name: King **Project Manager:**

Applies to: LUST
Applies to Description: Leaking Underground Storage Tank

Related ID:
VCP Prj No: NW2072
Activity Name: VCP Opinion on Feasibility Study
Activity Status: Canceled
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2012-09-04
End Date:
Legal Mechanism:
Performed by:
Project Manager: Goldstein, Libby

Related ID: 4124
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 2008-07-16
End Date: 2008-07-18
Legal Mechanism:
Performed by:
Project Manager:

Related ID: 6049
VCP Prj No:
Activity Name: Independent Report Review - Paid
Activity Status: Completed
County Name: King
Applies to: CleanupUnit
Applies to Description:
Start Date: 2009-02-09
End Date: 2009-05-11
Legal Mechanism:
Performed by: PLP
Project Manager: Adams, Mark

Related ID: 4124
VCP Prj No:
Activity Name: LUST - Notification
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 1996-03-26
End Date: 1996-03-26
Legal Mechanism:
Performed by:
Project Manager: Klocke, Karen

Related ID: 4124
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 2008-10-31
End Date: 2008-11-05
Legal Mechanism:
Performed by:
Project Manager:

Related ID: 4124
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 2009-03-27
End Date: 2009-03-30
Legal Mechanism:
Performed by:
Project Manager:

Related ID: 4124
VCP Prj No:
Activity Name: LUST - Report Received
Activity Status:
County Name: King
Applies to: LUST
Applies to Description: Leaking Underground Storage Tank
Start Date: 2008-02-12
End Date: 2008-02-14
Legal Mechanism:
Performed by:
Project Manager:

Related ID:
VCP Prj No: NW2072
Activity Name: VCP Opinion on Remedial Investigation
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2009-10-06
End Date: 2009-12-30
Legal Mechanism:
Performed by:
Project Manager: Goldstein, Libby

Media Contaminants

Contaminant Type:	Petroleum-Other	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RA	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Above Cleanup Level	**County Name:**	King

Contaminant Type:	Lead	**Sediment:**	
Groundwater:	C	**Sediment Desc.:**	
Groundwater Desc.:	Confirmed Above Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	B	**Bedrock Desc.:**	
Soil Desc.:	Below Cleanup Level	**County Name:**	King

Contaminant Type:	Methyl tertiary-butyl ether	**Sediment:**	
Groundwater:	B	**Sediment Desc.:**	
Groundwater Desc.:	Below Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:		**Bedrock Desc.:**	
Soil Desc.:		**County Name:**	King

Contaminant Type:	Metals - Other	**Sediment:**	
Groundwater:	B	**Sediment Desc.:**	
Groundwater Desc.:	Below Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	B	**Bedrock Desc.:**	
Soil Desc.:	Below Cleanup Level	**County Name:**	King

Contaminant Type:	Petroleum-Diesel	**Sediment:**	
Groundwater:	C	**Sediment Desc.:**	
Groundwater Desc.:	Confirmed Above Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RA	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Above Cleanup Level	**County Name:**	King

---

214 **6 of 7** **ESE** **0.49 / 2,564.21** **135.99 / 30** **Jiffy Lube Store 2077**
2025 4TH AVE
SEATTLE WA 98121
VCP

Facility Site ID:	31325769	**County:**	King
Cleanup Site ID:	5853	**Latitude:**	47.61334
Region:	Northwest	**Longitude:**	-122.34129
Alternate Site Names:	MINIT LUBE 1113,MINIT-LUBE 1113,SHELL 2025 4TH,SEATTLE		
Data Source(s):	No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State		

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status:	NFA
NFA Date:	12/05/2014
Responsible Unit:	Northwest
Has Inst Control:	Yes
NFA Reason:	Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name:	Petroleum-Diesel	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Above		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant Name:	Lead	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Below Cleanup Levels		
Contaminant Name:	Petroleum-Other	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Above		
Contaminant Name:	Metals - Other	**Sediment:**	
Groundwater:	Below Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Below Cleanup Levels		
Contaminant Name:	Methyl tertiary-butyl ether	**Sediment:**	
Groundwater:	Below Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:			

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status:	No Further Action
Site Rank:	
Has Inst Control:	Yes
Current VCP:	
Past VCP:	Yes
Responsible Unit:	Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name:	Metals - Other	**Sediment:**	
Groundwater:	Below Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Below Cleanup Levels		
Contaminant Name:	Methyl tertiary-butyl ether	**Sediment:**	
Groundwater:	Below Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:			
Contaminant Name:	Petroleum-Diesel	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Above		
Contaminant Name:	Petroleum-Other	**Sediment:**	
Groundwater:		**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Remediated-Above		
Contaminant Name:	Lead	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Air:**	
Surfacewater:		**Bedrock:**	
Soil:	Below Cleanup Levels		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
214	7 of 7	ESE	0.49 / 2,564.21	135.99 / 30	Jiffy Lube Store 2077 2025 4TH AVE SEATTLE WA 98121	LUST

Facility Site ID:	31325769	**County:**	King
Cleanup Site ID:	5853	**Latitude:**	47.61334
Responsible Unit:	Northwest	**Longitude:**	-122.34129
Region:	Northwest		
Alternate Site Names:	MINIT LUBE 1113,MINIT-LUBE 1113,SHELL 2025 4TH,SEATTLE		

Tank Detail(s)

UST ID:	6781	***Status Date:***	12/05/2014
LUST ID:	4124	***Release Date:***	03/26/1996
LUST Status:	LUST - NFA		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Other	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Remediated-Above		

Contaminants Detail(s)

Contaminant Name:	Lead	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Below Cleanup Levels		

Contaminants Detail(s)

Contaminant Name:	Methyl tertiary-butyl ether	***Sediment:***	
Groundwater:	Below Cleanup Levels	***Air:***	
Surfacewater:		***Bedrock:***	
Soil:			

Contaminants Detail(s)

Contaminant Name:	Metals - Other	***Sediment:***	
Groundwater:	Below Cleanup Levels	***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Below Cleanup Levels		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Diesel	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Remediated-Above		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
215	*1 of 4*	*NNE*	*0.49 / 2,565.68*	*90.19 / -16*	***Seattle Mercer Ops Base 520 5TH AVE N SEATTLE WA 98109***	*CSCSL*

Fac Site ID:	8984	***Responsible Unit:***	Northwest
Cleanup Site ID:	7394	***Fac Site ID (OD):***	8984
Site Status:	Cleanup Started	***Cleanup SiteID(OD):***	7394
Site Rank:		***Site Rank (OD):***	
Current VCP:		***Has Env Coven (OD):***	
Past VCP:		***Respon Unit (OD):***	Northwest
Has Inst Control:		***County (OD):***	King
County:	King	***Region (OD):***	Northwest
Region:	Northwest	***Longitude (OD):***	-122.347418
Latitude:	47.6237297261867	***Latitude (OD):***	47.62373
Longitude:	-122.347418371668		
Site Name:	Seattle Mercer Ops Base		
Address:	520 5TH AVE N		
City:	SEATTLE		
Zip Code:	98109		
Site Status (OD):	Cleanup Started		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Name (OD): Seattle Mercer Ops Base
Address (OD): 520 5TH AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.62373, -122.347418)
Alternate Site Names: Mercer Operating Base
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Lead
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Lead
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Lead
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

215	2 of 4	NNE	0.49 / 2,565.68	90.19 / -16	Mercer Operating Base 520 5TH AVE N SEATTLE WA 98109	ALL SITES

Facility/Site ID: 8984

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 7884
Facility Alternate: Mercer Operating Base
Interaction ID: 93768
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 13-Aug-2010
Interact End Dt: 13-Aug-2010
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: 7884
Facility Alternate: Mercer Operating Base
Interaction ID: 93036
Interaction Status: A
Interac Status Desc: Active
Interaction Type: LUST
Interaction Desc: LUST Facility
Interact Start Dt: 17-Jun-2010
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6237297262
GIS longitude: -122.347418372

---

215 | ***3 of 4*** | ***NNE*** | ***0.49 / 2,565.68*** | ***90.19 / -16*** | ***Seattle Mercer Ops Base***
520 5TH AVE N
SEATTLE WA 98109 | ***LUST***

Facility Site ID: 8984
Cleanup Site ID: 7394
Responsible Unit: Northwest
Region: Northwest
Alternate Site Names: Mercer Operating Base
County: King
Latitude: 47.6237297261867
Longitude: -122.347418371668

Tank Detail(s)

UST ID: 7884
LUST ID: 136
LUST Status: LUST - Cleanup Started
Status Date: 06/01/1995
Release Date: 01/25/1989

Contaminants Detail(s)

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminants Detail(s)

Contaminant Name:	Petroleum-Gasoline	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		

Contaminants Detail(s)

Contaminant Name:	Lead	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Confirmed Above Cleanup Levels		

---

215 | ***4 of 4*** | ***NNE*** | ***0.49 / 2,565.68*** | ***90.19 / -16*** | ***Seattle Mercer Ops Base***
520 5TH AVE N
SEATTLE WA 98109 | ***ICR***

Cleanup Site ID:	7394	***WRIA ID:***	8
Facility Site ID:	8984	***Is NFA Site:***	
Site Status:	Cleanup Started	***Responsible Unit:***	Northwest
Statute:	MTCA	***Latitude:***	47.623729726186703
Rank:		***Longitude:***	-122.347418371668
Rank Description:		***Legislative District:***	36
Has Env Covenant:		***Congr District:***	7
Is Brownfiled Site:		***County Name:***	King
Is PSI Site:			

Cleanup Activities

Related ID:	136	***Start Date:***	1990-04-11
VCP Prj No:		***End Date:***	1990-04-11
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	136	***Start Date:***	2004-12-14
VCP Prj No:		***End Date:***	2005-08-31
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	136	***Start Date:***	1989-01-25
VCP Prj No:		***End Date:***	1989-01-25
Activity Name:	LUST - Notification	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	136	***Start Date:***	1990-07-06
VCP Prj No:		***End Date:***	1990-07-06
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	136	***Start Date:***	2004-09-21
VCP Prj No:		***End Date:***	2005-08-31
Activity Name:	LUST - Report Received	***Legal Mechanism:***	

Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	136	***Start Date:***	2005-01-12
VCP Prj No:		***End Date:***	2005-08-31
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	136	***Start Date:***	1991-09-12
VCP Prj No:		***End Date:***	1991-09-12
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	136	***Start Date:***	1996-09-20
VCP Prj No:		***End Date:***	1996-09-27
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	136	***Start Date:***	2010-01-29
VCP Prj No:		***End Date:***	2010-02-02
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Related ID:	136	***Start Date:***	2005-06-07
VCP Prj No:		***End Date:***	2005-08-31
Activity Name:	LUST - Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	LUST		
Applies to Description:	Leaking Underground Storage Tank		

Media Contaminants

Contaminant Type:	Lead	***Sediment:***	
Groundwater:	C	***Sediment Desc.:***	
Groundwater Desc.:	Confirmed Above Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

Contaminant Type:	Petroleum-Gasoline	***Sediment:***	
Groundwater:	C	***Sediment Desc.:***	
Groundwater Desc.:	Confirmed Above Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

Contaminant Type:	Benzene	***Sediment:***	
Groundwater:	C	***Sediment Desc.:***	
Groundwater Desc.:	Confirmed Above Cleanup Level	***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Soil: C
Soil Desc.: Confirmed Above Cleanup Level
Bedrock Desc.:
County Name: King

---

216 *1 of 1* | *NW* | *0.49 / 2,597.17* | *129.77 / 24* | *Queen Anne Auto Body, 420 QUEEN ANNE N, SEATTLE WA 98109* | *ALL SITES*

Facility/Site ID: 95877816
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAD980978910
Facility Alternate:
Interaction ID: 74515
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 10-Oct-1985
Interact End Dt: 31-Dec-1995
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Unknown
Location Verified: N
GIS latitude: 47.62257
GIS longitude: -122.35663

---

217 *1 of 1* | *E* | *0.49 / 2,610.89* | *99.97 / -6* | *Amazon Go ISE1, 2131 7th Ave, Seattle WA 98121* | *ALL SITES*

Facility/Site ID: 38809
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: WAH000059475
Facility Alternate: Amazon Go ISE1
Interaction ID: 143009
Interaction Status: A
Interac Status Desc: Active
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 12-Jan-2022
Interact End Dt:
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal: Unknown
Horizont 1: NAD83
Horizont 2: Address
Location Verified:
GIS latitude: 47.61621
GIS longitude: -122.33981

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
218	1 of 1	ENE	0.50 / 2,615.46	83.53 / -22	THE RILEY GROUP 215 8TH AVE N SEATTLE WA	LST HOT

ID:	56	**Real Status:**	
Cancelled:	FALSE	**Applicatn Created:**	
Date Received:	2/25/2011	**Project Created:**	
Site FA:		**Dt of Report Rec 1:**	
Property FA:		**Review Start Dt 1:**	
Site NFA Likely:		**90 Day Lettr Due 1:**	
Site NFA:		**Respond Date 1:**	
Site NFA W Ec:		**Dt of Report Rec 2:**	
Property NFA:		**Review Start Dt 2:**	
Payment Rec:		**90 Day Lettr Due 2:**	
ERTS No:		**Respond Date 2:**	
HO Claim Reg No:		**Dt of Report Rec 3:**	
Reten Met Destroyd:	FALSE	**Review Start Dt 3:**	
Last Name Contact:	SIMPSON	**90 Day Lettr Due 3:**	
First Name Contact:	RICHARD	**Respond Date 3:**	
Phone Contact:	(425) 415-0551	**Dt of Report Rec 4:**	
Letter Written Dt:		**Review Start Dt 4:**	
Tank State:	WA	**90 Day Lettr Due 4:**	
Mailing Address:	17522 BOTHELL WY NE	**Respond Date 4:**	
Mailing City:	BOTHELL	**Dt of Report Rec 5:**	
Mailing State:	WA	**Review Start Dt 5:**	
Mailing Zip:	98011	**90 Day Lettr Due 5:**	
Phone Home Owner:		**Respond Date 5:**	
Service Provider:	THE RILEY GROUP		
Service Provider Email:	mpoysnick@riley-group.com		
Consultant:			
Last Name Home Own:	HOLLY PRESS BLDG		
First Name Home Own:			
Name of Report Rec 1:			
Name of Report Rec 2:			
Name of Report Rec 3:			
Name of Report Rec 4:			
Name of Report Rec 5:			
Comments 1:			
Comments 2:			
Comments 3:			
Comments 4:			
Comments 5:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
219	1 of 1	E	0.50 / 2,616.97	93.20 / -13	Life Span Bio Sciences 700 BLANCHARD ST SEATTLE WA 98121	ALL SITES

Facility/Site ID:	5396837
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	WAH000001446
Facility Alternate:	
Interaction ID:	16643
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	11-Apr-1997
Interact End Dt:	14-Oct-2002
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Database Name Desc: Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	N
Horizont 1:	NAD83	***GIS latitude:***	47.61677
Horizont 2:	Unknown	***GIS longitude:***	-122.34006

---

220 ***1 of 6*** ***NNE*** ***0.50 / 2,618.41*** ***88.96 / -17*** ***IRIS Holding LLC***
500 5TH AVE N
SEATTLE WA 98109 ***VCP***

Facility Site ID:	2593	***County:***	King
Cleanup Site ID:	758	***Latitude:***	47.62264
Region:	Northwest	***Longitude:***	-122.34687

Alternate Site Names: IRIS HOLDINGS,LLC
Data Source(s): No Futher Action Sites List; No Futher Action Sites List; All Cleanup Sites in Washington State

WA ECY Toxics Cleanup Program - No Futher Action Sites List

Site Status: NFA
NFA Date: 10/17/2017
Responsible Unit: Northwest
Has Inst Control: Yes
NFA Reason: Voluntary Cleanup Program Review

WA ECY Toxics Cleanup Program - No Futher Action Sites List - Contaminants Info

Contaminant Name:	Polychlorinated biPhenyls (PCB)	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Remediated-Below		
Contaminant Name:	Petroleum-Other	***Sediment:***	
Groundwater:	Remediated-Below	***Air:***	
Surfacewater:		***Bedrock:***	
Soil:			
Contaminant Name:	Petroleum Products-Unspecified	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Remediated-Below		

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites

Site Status: No Further Action
Site Rank:
Has Inst Control: Yes
Current VCP:
Past VCP: Yes
Responsible Unit: Northwest

WA ECY Toxics Cleanup Program - All Statewide Cleanup Sites - Contaminants

Contaminant Name:	Polychlorinated biPhenyls (PCB)	***Sediment:***	
Groundwater:		***Air:***	
Surfacewater:		***Bedrock:***	
Soil:	Remediated-Below		
Contaminant Name:	Petroleum-Other	***Sediment:***	
Groundwater:	Remediated-Below	***Air:***	
Surfacewater:		***Bedrock:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Soil:

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

220	2 of 6	NNE	0.50 / 2,618.41	88.96 / -17	IRIS Holding LLC 500 5TH AVE N SEATTLE WA 98109	DELISTED SHWS

Delisted Contaminated/Hazardous Sites

Fac Site ID: 2593
Cleanup Site ID: 758
Brownfield?:
PSI?:
VCP?: Yes
Past VCP:
Has Inst Control:
Site Status: Cleanup Started
Alternate Site Names:
Original Source: CSCS
Record Date: 17-AUG-2017
WARM Rank: N
Warm Rank Desc:
Respon Section: Headquarters
County: King
Region: Northwest
Latitude: 47.62264
Longitude: -122.34687

220	3 of 6	NNE	0.50 / 2,618.41	88.96 / -17	IRIS Holding LLC 500 5TH AVE N SEATTLE WA 98109	ALL SITES

Facility/Site ID: 2593
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID: 7884
Facility Alternate: IRIS Holding LLC
Interaction ID: 92313
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 20-Mar-2000
Interact End Dt: 21-Mar-2000
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: 619694
Facility Alternate: IRIS Holding LLC
Interaction ID: 93788
Interaction Status: A
Interac Status Desc: Active
Interaction Type: UST
Interaction Desc: Underground Storage Tank
Interact Start Dt: 17-Jun-2010
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: UST
Database Name Desc: Underground Storage Tanks

Program ID: WAD981762206

Facility Alternate: IRIS Holding LLC
Interaction ID: 92317
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 01-Apr-2008
Interact End Dt: 23-Oct-2008
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID: NW1493
Facility Alternate: IRIS Holding LLC
Interaction ID: 92312
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: VOLCLNST
Interaction Desc: Voluntary Cleanup Sites
Interact Start Dt: 06-Sep-2005
Interact End Dt: 17-Oct-2017
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: 7884
Facility Alternate: IRIS Holding LLC
Interaction ID: 92314
Interaction Status: A
Interac Status Desc: Active
Interaction Type: LUST
Interaction Desc: LUST Facility
Interact Start Dt: 25-Jan-1989
Interact End Dt:
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Program ID: WAD981762206
Facility Alternate: IRIS Holding LLC
Interaction ID: 92316
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: HWG
Interaction Desc: Hazardous Waste Generator
Interact Start Dt: 30-Oct-1986
Interact End Dt: 18-Apr-1990
Ecology Program: HAZWASTE
Program Name Desc: Hazardous Waste & Toxics Reduction Program
Prog Database Name: TURBOWASTE
Database Name Desc: Hazardous Waste Inf Mgt System

Program ID:
Facility Alternate: IRIS Holding LLC
Interaction ID: 92315
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: INDPNDNT
Interaction Desc: Independent Cleanup
Interact Start Dt: 01-Jan-1900
Interact End Dt: 06-Sep-2005
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	
Horizont 1:	WGS84	***GIS latitude:***	47.62264
Horizont 2:	Address	***GIS longitude:***	-122.34687

---

220 | *4 of 6* | *NNE* | *0.50 / 2,618.41* | *88.96 / -17* | ***IRIS Holding LLC*** ***500 5TH AVE N*** ***SEATTLE WA 98109*** | *ICR*

Cleanup Site ID:	758	***WRIA ID:***	8
Facility Site ID:	2593	***Is NFA Site:***	
Site Status:	Cleanup Started	***Responsible Unit:***	Northwest
Statute:	MTCA	***Latitude:***	47.622639999999997
Rank:		***Longitude:***	-122.34687
Rank Description:		***Legislative District:***	36
Has Env Covenant:		***Congr District:***	7
Is Brownfiled Site:		***County Name:***	King
Is PSI Site:			

Cleanup Activities

Related ID:		***Start Date:***	2005-09-06
VCP Prj No:	NW1493	***End Date:***	
Activity Name:	VCP Opinion on Site Cleanup Plan	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Hickey, Joe
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	2015-05-26
VCP Prj No:	NW1493	***End Date:***	
Activity Name:	VCP Opinion on Site Cleanup	***Legal Mechanism:***	
Activity Status:	Canceled	***Performed by:***	
County Name:	King	***Project Manager:***	Myers, Dale R
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	2011-03-07
VCP Prj No:	NW1493	***End Date:***	
Activity Name:	VCP Receipt of Plan or Report	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Northwest Region
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	2011-03-08
VCP Prj No:	NW1493	***End Date:***	
Activity Name:	VCP Opinion on Feasibility Study	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	
County Name:	King	***Project Manager:***	Myers, Dale R
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	1996-05-03
Activity Name:	Early Notice Letter(s)	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	Northwest Region
Applies to:	CleanupSite		
Applies to Description:			

Related ID:		***Start Date:***	2005-09-06
VCP Prj No:		***End Date:***	2005-12-06
Activity Name:	Ecology Cleanup Action Plan	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	PLP

County Name: King
Applies to: CleanupSiteMilestoneType
Applies to Description:
Project Manager: Northwest Region

Related ID:
VCP Prj No: NW1493
Activity Name: VCP Receipt of Plan or Report
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2015-05-26
End Date:
Legal Mechanism:
Performed by:
Project Manager: Fernandez, Sonia

Related ID:
VCP Prj No: NW1493
Activity Name: VCP Receipt of Plan or Report
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2012-02-20
End Date:
Legal Mechanism:
Performed by:
Project Manager: Pederson, Carrie

Related ID:
VCP Prj No: NW1493
Activity Name: VCP Receipt of Plan or Report
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2012-02-07
End Date:
Legal Mechanism:
Performed by:
Project Manager: Pederson, Carrie

Related ID:
VCP Prj No: NW1493
Activity Name: VCP Opinion on Site Cleanup Plan
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2010-05-19
End Date: 2010-06-10
Legal Mechanism:
Performed by:
Project Manager: Myers, Dale R

Related ID:
VCP Prj No:
Activity Name: Site Discovery/Release Report Received
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date:
End Date: 1994-08-24
Legal Mechanism:
Performed by:
Project Manager: Northwest Region

Related ID:
VCP Prj No: NW1493
Activity Name: VCP Opinion on Remedial Investigation
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2010-01-29
End Date: 2010-02-09
Legal Mechanism:
Performed by:
Project Manager: Myers, Dale R

Related ID:
VCP Prj No:
Activity Name: Initial Investigation / Federal Preliminary Assessment
Activity Status: Completed
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date: 1994-10-19
End Date: 1994-10-19
Legal Mechanism:
Performed by: Ecology
Project Manager: Northwest Region

Related ID:
VCP Prj No: NW1493
Activity Name: VCP Receipt of Plan or Report
Activity Status: Completed
County Name: King
Applies to: VcpProject
Applies to Description: Voluntary Cleanup Program
Start Date: 2012-03-22
End Date:
Legal Mechanism:
Performed by:
Project Manager: Pederson, Carrie

Related ID:		**Start Date:**	2005-09-06
VCP Prj No:	NW1493	**End Date:**	
Activity Name:	VCP Application	**Legal Mechanism:**	
Activity Status:	Completed	**Performed by:**	
County Name:	King	**Project Manager:**	Myers, Dale R
Applies to:	VcpProject		
Applies to Description:	Voluntary Cleanup Program		

Media Contaminants

Contaminant Type:	Petroleum Products-Unspecified	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	C	**Bedrock Desc.:**	
Soil Desc.:	Confirmed Above Cleanup Level	**County Name:**	King
Contaminant Type:	Petroleum-Other	**Sediment:**	
Groundwater:	C	**Sediment Desc.:**	
Groundwater Desc.:	Confirmed Above Cleanup Level	**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:		**Bedrock Desc.:**	
Soil Desc.:		**County Name:**	King

---

220 | ***5 of 6*** | ***NNE*** | ***0.50 / 2,618.41*** | ***88.96 / -17*** | ***IRIS Holding LLC
500 5TH AVE N
SEATTLE WA 98109*** | ***CSCSL NFA***

Fac Site ID:	2593	**Fac Site ID (OD):**	2593
Cleanup Site ID:	758	**Cleanup SiteID(OD):**	758
Site Status:	NFA	**Site Status (OD):**	No Further Action
NFA Date:	10/17/2017	**Rank (OD):**	
Responsible Unit:	Northwest	**Has Env Coven (OD):**	Yes
Has Insti Control:	Yes	**Respon Unit (OD):**	Northwest
Region:	Northwest	**Region (OD):**	Northwest
County:	King	**County (OD):**	King
Latitude:	47.62264	**Latitude (OD):**	47.62264
Longitude:	-122.34687	**Longitude (OD):**	-122.34687
NFA Reason:	Voluntary Cleanup Program Review		
Alternate Site Names:	IRIS HOLDINGS,LLC		
Location (OD):	"" (47.62264, -122.34687)		
Data Source(s):	Department of Ecology - Washington; Open Data Portal - Washington State		

NFA Contaminants Detail(s)

Contaminant Name:	Polychlorinated biPhenyls (PCB)
Groundwater:	
Surfacewater:	
Soil:	Remediated-Below
Sediment:	
Air:	
Bedrock:	
Contaminant Name:	Petroleum Products-Unspecified
Groundwater:	
Surfacewater:	
Soil:	Remediated-Below
Sediment:	
Air:	
Bedrock:	
Contaminant Name:	Petroleum-Other
Groundwater:	Remediated-Below

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Surfacewater:						
Soil:						
Sediment:						
Air:						
Bedrock:						

220	6 of 6	NNE	0.50 / 2,618.41	88.96 / -17	IRIS Holding LLC 500 5TH AVE N SEATTLE WA 98109	INST

Facility Site ID: 2593
Region: Northwest
County: King
Latitude: 47.62264
Longitude: -122.34687
Site Name: IRIS Holding LLC
Address: 500 5TH AVE N
City: SEATTLE
Zip: 98109
Site Name (OD): IRIS Holding LLC
Address (OD): 500 5TH AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.62264, -122.34687)
Cleanup Site ID: 758
Region (OD): Northwest
County (OD): King
Latitude (OD): 47.62264
Longitude (OD): -122.34687
Data Source(s): Department of Ecology State of Washington - Environmental Covenants Registry List; Open Data Portal - Institutional Controls or Environmental Covenants Map

Environmental Covenants Registry List

NFA Date: 10/17/2017
Site Status: No Further Action
Tax Parcel No: 1988201155
Instrument Type: Environmental Covenant
Media Restrictions: Soil
Alternate Site Names: IRIS HOLDINGS,LLC
Cnty Recording No: 20170913000098
Cnty Recording Dt: 09/13/2017
Responsible Unit: Northwest
Active Control: Yes
Control Stormwater: No
Control Vapor Gas: No
Prevent Reuse/Relocation: No
Prohibit New Bldg Constr: No
Prohibit Removal or Alteration: No
Prohibit Soil Disturbance: Yes
Ongoing Maint of Remedy: No
Require Educational Programs: No
Restrict Access: No
Restrict All GW Extr: No
Restrict Domestic GW: No
Restrict Land Use: Yes
Restrict Sedmnt Cap Disturb: No
Restrict Shellfish and or Finf: No
Restrict Surface Water Use: No
Restrict Swim/Beach Play: No
Restrictive Signage: No
Maintain/Protect Monit System: No
Other: No

NFA Date: 10/17/2017
Site Status: No Further Action
Tax Parcel No: 2570400000
Instrument Type: Environmental Covenant
Media Restrictions: Soil
Alternate Site Names: IRIS HOLDINGS,LLC
Cnty Recording No: 20170913000099

Cnty Recording Dt:	09/13/2017
Responsible Unit:	Northwest
Active Control:	Yes
Control Stormwater:	No
Control Vapor Gas:	No
Prevent Reuse/Relocation:	No
Prohibit New Bldg Constr:	No
Prohibit Removal or Alteration:	No
Prohibit Soil Disturbance:	Yes
Ongoing Maint of Remedy:	No
Require Educational Programs:	No
Restrict Access:	No
Restrict All GW Extr:	No
Restrict Domestic GW:	No
Restrict Land Use:	Yes
Restrict Sedmnt Cap Disturb:	No
Restrict Shellfish and or Finf:	No
Restrict Surface Water Use:	No
Restrict Swim/Beach Play:	No
Restrictive Signage:	No
Maintain/Protect Monit System:	No
Other:	No

NFA Date:	10/17/2017
Site Status:	No Further Action
Tax Parcel No:	1988201155
Instrument Type:	Environmental Covenant
Media Restrictions:	Soil
Alternate Site Names:	IRIS HOLDINGS,LLC
Cnty Recording No:	20170915000106
Cnty Recording Dt:	09/15/2017
Responsible Unit:	Northwest
Active Control:	Yes
Control Stormwater:	No
Control Vapor Gas:	No
Prevent Reuse/Relocation:	No
Prohibit New Bldg Constr:	No
Prohibit Removal or Alteration:	No
Prohibit Soil Disturbance:	Yes
Ongoing Maint of Remedy:	No
Require Educational Programs:	No
Restrict Access:	No
Restrict All GW Extr:	No
Restrict Domestic GW:	No
Restrict Land Use:	Yes
Restrict Sedmnt Cap Disturb:	No
Restrict Shellfish and or Finf:	No
Restrict Surface Water Use:	No
Restrict Swim/Beach Play:	No
Restrictive Signage:	No
Maintain/Protect Monit System:	No
Other:	No

Open Data Portal - Environmental Covenants Map

Facility Site ID:	2593
Cleanup Status:	No Further Action
Has Env Covenant:	Yes
Rank:	
Resp Section:	Northwest

221	***1 of 1***	***E***	***0.50 / 2,619.59***	***93.20 / -13***	***SEA98 720 BLANCHARD ST SEATTLE WA 98121***	***ALL SITES***

Facility/Site ID:	53858
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facilties - Sites

Facility/Site Interaction

Program ID:	CRK000097200
Facility Alternate:	SEA98
Interaction ID:	143216
Interaction Status:	A
Interac Status Desc:	Active
Interaction Type:	TIER2
Interaction Desc:	Emergency/Haz Chem Rpt TIER2
Interact Start Dt:	10-Feb-2022
Interact End Dt:	
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	EPCRA
Database Name Desc:	Emergency Planning & Community Right-to-Know Act

Facility Location Detail

Horizontal:	Unknown	***Location Verified:***	
Horizont 1:	WGS84	***GIS latitude:***	47.61677
Horizont 2:	Address	***GIS longitude:***	-122.33992

222	***1 of 3***	***E***	***0.50 / 2,622.04***	***108.06 / 2***	***Sixth & Lenora Apartments 2121 6TH AVE SEATTLE WA 98121***	***CSCSL NFA***

Fac Site ID:	19519	***Fac Site ID (OD):***	19519
Cleanup Site ID:	11868	***Cleanup SiteID(OD):***	11868
Site Status:	NFA	***Site Status (OD):***	No Further Action
NFA Date:	06/04/2012	***Rank (OD):***	
Responsible Unit:	Northwest	***Has Env Coven (OD):***	
Has Insti Control:		***Respon Unit (OD):***	Northwest
Region:	Northwest	***Region (OD):***	Northwest
County:	King	***County (OD):***	King
Latitude:	47.6153088176346	***Latitude (OD):***	47.615309
Longitude:	-122.340450339951	***Longitude (OD):***	-122.34045
NFA Reason:	Initial Investigation		
Alternate Site Names:			
Location (OD):	"" (47.615309, -122.34045)		
Data Source(s):	Department of Ecology - Washington; Open Data Portal - Washington State; Open Data Portal - Media and Contaminants		

NFA Contaminants Detail(s)

Contaminant Name:	Petroleum-Other
Groundwater:	
Surfacewater:	
Soil:	Remediated-Below
Sediment:	
Air:	
Bedrock:	

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Petroleum-Other
Contaminant Media:	Soil
Contaminant Status:	Remediated-Below

222	***2 of 3***	***E***	***0.50 / 2,622.04***	***108.06 / 2***	***Sixth & Lenora Apartments 2121 6TH AVE***	***ALL SITES***

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					SEATTLE WA 98121	

Facility/Site ID: 19519
Source File: Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:
Facility Alternate: Sixth & Lenora Apartments
Interaction ID: 101723
Interaction Status: I
Interac Status Desc: Inactive
Interaction Type: INDPNDNT
Interaction Desc: Independent Cleanup
Interact Start Dt: 17-Jan-2012
Interact End Dt: 04-Jun-2012
Ecology Program: TOXICS
Program Name Desc: Toxics Cleanup Program
Prog Database Name: ISIS
Database Name Desc: Integrated Site Info System

Facility Location Detail

Horizontal: 40ft
Horizont 1: NAD83HARN
Horizont 2: Digital map or GIS
Location Verified:
GIS latitude: 47.6153088176
GIS longitude: -122.34045034

---

222 | 3 of 3 | E | 0.50 / 2,622.04 | 108.06 / 2 | **Sixth & Lenora Apartments**
2121 6TH AVE
SEATTLE WA 98121 | ICR

Cleanup Site ID: 11868
Facility Site ID: 19519
Site Status: No Further Action Required
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site: Yes
WRIA ID: 8
Is NFA Site: Yes
Responsible Unit: Northwest
Latitude: 47.615308817634599
Longitude: -122.34045033995061
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID:
VCP Prj No:
Activity Name: Initial Investigation / Federal Preliminary Assessment
Activity Status: Completed
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date: 2011-11-08
End Date: 2012-01-09
Legal Mechanism:
Performed by: Ecology
Project Manager: Musa, Donna

Related ID:
VCP Prj No:
Activity Name: Site Discovery/Release Report Received
Activity Status:
County Name: King
Applies to: CleanupSite
Applies to Description:
Start Date:
End Date: 2011-11-08
Legal Mechanism:
Performed by:
Project Manager: Northwest Region

Related ID:
VCP Prj No:
Activity Name: Ind - Report Received
Start Date:
End Date: 2000-10-31
Legal Mechanism:

Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	
Applies to:	Upland		
Applies to Description:			
Related ID:		**Start Date:**	
VCP Prj No:		**End Date:**	2012-06-04
Activity Name:	Site Status Changed to NFA	**Legal Mechanism:**	
Activity Status:		**Performed by:**	
County Name:	King	**Project Manager:**	Musa, Donna
Applies to:	CleanupSite		
Applies to Description:			

Media Contaminants

Contaminant Type:	Petroleum-Other	**Sediment:**	
Groundwater:		**Sediment Desc.:**	
Groundwater Desc.:		**Air:**	
Surface Water:		**Air Desc.:**	
Surfacewater Desc.:		**Bedrock:**	
Soil:	RB	**Bedrock Desc.:**	
Soil Desc.:	Remediated-Below Cleanup Level	**County Name:**	King

---

223 | **1 of 1** | **SE** | **0.50 / 2,630.66** | **98.32 / -7** | **MCI INTERNATIONAL**
2001 WESTERN AVE STE 425
SEATTLE WA 98121-2114 | **ALL SITES**

Facility/Site ID:	68883438
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	CRK000028300
Facility Alternate:	
Interaction ID:	59164
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	TIER2
Interaction Desc:	Emergency/Haz Chem Rpt TIER2
Interact Start Dt:	01-Jan-1991
Interact End Dt:	01-Mar-1994
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	EPCRA
Database Name Desc:	Emergency Planning & Community Right-to-Know Act

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	N
Horizont 1:	NAD27	**GIS latitude:**	47.610194503
Horizont 2:	Unknown	**GIS longitude:**	-122.345811028

---

224 | **1 of 1** | **ENE** | **0.50 / 2,637.06** | **85.35 / -20** | **Wilderman Refrigeration Co**
300 DEXTER AVE N
SEATTLE WA 98109-5106 | **ALL SITES**

Facility/Site ID:	62628328
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Program ID:	WA0000073122
Facility Alternate:	
Interaction ID:	55287
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	HWG
Interaction Desc:	Hazardous Waste Generator
Interact Start Dt:	07-Dec-1993
Interact End Dt:	31-Dec-1994
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	TURBOWASTE
Database Name Desc:	Hazardous Waste Inf Mgt System

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	N
Horizont 1:	NAD83	**GIS latitude:**	47.62119
Horizont 2:	Unknown	**GIS longitude:**	-122.34239

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
225	1 of 1	E	0.50 / 2,643.15	98.92 / -7	SEA47 The Summit 2122 7TH AVE SEATTLE WA 98121	ALL SITES

Facility/Site ID:	41363
Source File:	Washington State Department of Ecology Facilties - Sites Interactions; Washington State Department of Ecology Facilties - Sites

Facility/Site Interaction

Program ID:	CRK000095680
Facility Alternate:	SEA47 (The Summit)
Interaction ID:	137764
Interaction Status:	I
Interac Status Desc:	Inactive
Interaction Type:	TIER2
Interaction Desc:	Emergency/Haz Chem Rpt TIER2
Interact Start Dt:	08-Feb-2021
Interact End Dt:	18-Feb-2021
Ecology Program:	HAZWASTE
Program Name Desc:	Hazardous Waste & Toxics Reduction Program
Prog Database Name:	EPCRA
Database Name Desc:	Emergency Planning & Community Right-to-Know Act

Facility Location Detail

Horizontal:	Unknown	**Location Verified:**	
Horizont 1:	WGS84	**GIS latitude:**	47.61654
Horizont 2:	Address	**GIS longitude:**	-122.33944

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
226	1 of 1	WNW	0.51 / 2,676.99	8.40 / -97	Unocal Myrtle Edwards Park 3130 ALASKAN WAY W SEATTLE WA 98121	CSCSL

Fac Site ID:	23180	**Responsible Unit:**	Northwest
Cleanup Site ID:	2457	**Fac Site ID (OD):**	23180
Site Status:	Awaiting Cleanup	**Cleanup SiteID(OD):**	2457
Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:		**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.361948
Latitude:	47.6198324185841	**Latitude (OD):**	47.619832

Longitude: -122.361948212008
Site Name: Unocal Myrtle Edwards Park
Address: 3130 ALASKAN WAY W
City: SEATTLE
Zip Code: 98121
Site Status (OD): Awaiting Cleanup
Site Name (OD): UNOCAL MYRTLE EDWARDS PARK
Address (OD): 3130 ALASKAN WAY W
City (OD): SEATTLE
Zipcode (OD): 98121
Location (OD): ""
(47.619832, -122.361948)
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater: Suspected
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Metals Priority Pollutants
Groundwater: Suspected
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Suspected
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Non-Halogenated Solvents
Groundwater: Suspected
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Non-Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Non-Halogenated Solvents
Contaminant Media: Groundwater
Contaminant Status: Suspected

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant: Metals Priority Pollutants
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Metals Priority Pollutants
Contaminant Media: Soil
Contaminant Status: Suspected

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
227	1 of 1	ENE	0.51 / 2,699.58	80.72 / -25	8th & Thomas JV LLC 777 THOMAS ST SEATTLE WA 98109	DELISTED SHWS

Delisted Contaminated/Hazardous Sites

Fac Site ID: 59162297
Cleanup Site ID: 12679
Brownfield?:
PSI?:
VCP?: Yes
Past VCP:
Has Inst Control:
Site Status: Cleanup Started
Alternate Site Names:
Original Source: CSCS
Record Date: 06-SEP-2016
WARM Rank: N
Warm Rank Desc:
Respon Section: Northwest
County: King
Region: Northwest
Latitude: 47.620670567
Longitude: -122.34138959

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
228	1 of 1	E	0.51 / 2,700.42	86.37 / -19	Block 21 Amazon 8th & Bell 2205 8TH AVE SEATTLE WA 98121	CSCSL

Fac Site ID: 49369
Cleanup Site ID: 16643
Site Status: Cleanup Started
Site Rank:
Current VCP: Yes
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.61727
Longitude: -122.33933
Site Name: Block 21 Amazon 8th & Bell
Address: 2205 8TH AVE
City: SEATTLE
Zip Code: 98121
Site Status (OD):
Site Name (OD):
Address (OD):
City (OD):
Zipcode (OD):
Location (OD):
Alternate Site Names: SEA48
Data Source(s): Confirmed and Suspected Contaminated Sites
Responsible Unit: Northwest
Fac Site ID (OD):
Cleanup SiteID(OD):
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD):
County (OD):
Region (OD):
Longitude (OD):
Latitude (OD):

Contaminants Detail(s)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

229	*1 of 1*	*E*	*0.53 / 2,798.69*	*90.74 / -15*	***Block 20 8th & Blanchard*** ***2101 2121 8th Ave & 2130 2100 7th Ave*** ***Seattle WA 98121***	***CSCSL***

Fac Site ID:	23876	***Responsible Unit:***	Northwest
Cleanup Site ID:	13061	***Fac Site ID (OD):***	23876
Site Status:	Awaiting Cleanup	***Cleanup SiteID(OD):***	13061
Site Rank:		***Site Rank (OD):***	
Current VCP:	Yes	***Has Env Coven (OD):***	
Past VCP:	Yes	***Respon Unit (OD):***	Northwest
Has Inst Control:		***County (OD):***	King
County:	King	***Region (OD):***	Northwest
Region:	Northwest	***Longitude (OD):***	-122.339094
Latitude:	47.6166242331203	***Latitude (OD):***	47.616624
Longitude:	-122.339094390213		

Site Name: Block 20 8th & Blanchard
Address: 2101 2121 8th Ave & 2130 2100 7th Ave
City: Seattle
Zip Code: 98121
Site Status (OD): Awaiting Cleanup
Site Name (OD): Block 20 8th & Blanchard
Address (OD): 2101 2121 8th Ave & 2130 2100 7th Ave
City (OD): Seattle
Zipcode (OD): 98121
Location (OD): ""
(47.616624, -122.339094)
Alternate Site Names: Block 20 8th and Blanchard
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Lead
Groundwater:
Surfacewater:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Lead
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

230	*1 of 1*	*E*	*0.53 / 2,806.15*	*95.48 / -10*	***Block 19 7th & Lenora*** ***2101 7TH AVE*** ***SEATTLE WA 98119***	***DELISTED SHWS***

Delisted Contaminated/Hazardous Sites

Fac Site ID: 17031
Cleanup Site ID: 12918
Brownfield?:
PSI?:
VCP?: Yes
Past VCP:
Has Inst Control:
Site Status: Cleanup Started
Alternate Site Names:
Original Source: CSCS
Record Date: 21-NOV-2016

WARM Rank: N
Warm Rank Desc:
Respon Section: Northwest
County: King
Region: Northwest
Latitude: 47.6158575972349
Longitude: -122.339859761366

231	*1 of 1*	*ENE*	*0.54 / 2,832.36*	*77.37 / -28*	***Dexter Office Building*** ***400 DEXTER AVE N*** ***SEATTLE WA 98109***	***CSCSL***

Fac Site ID: 7324
Cleanup Site ID: 14392
Site Status: Cleanup Started
Site Rank:
Current VCP: Yes
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6227468166077
Longitude: -122.341974169311
Site Name: Dexter Office Building
Address: 400 DEXTER AVE N
City: SEATTLE
Zip Code: 98109

Responsible Unit: Northwest
Fac Site ID (OD): 7324
Cleanup SiteID(OD): 14392
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.341974
Latitude (OD): 47.622747

Site Status (OD): Cleanup Started
Site Name (OD): Dexter Office Building
Address (OD): 400 DEXTER AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): "" (47.622747, -122.341974)
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Other Non-Halogenated Organics
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

232	*1 of 1*	*NNE*	*0.55 / 2,877.70*	*94.10 / -12*	***Standish Property*** ***420 MERCER ST*** ***SEATTLE WA 98109***	***CSCSL***

Fac Site ID: 25678675
Cleanup Site ID: 8486
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.62463
Longitude: -122.349768

Responsible Unit: Northwest
Fac Site ID (OD): 25678675
Cleanup SiteID(OD): 8486
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.349768
Latitude (OD): 47.62463

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Name: Standish Property
Address: 420 MERCER ST
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): STANDISH PROPERTY
Address (OD): 420 MERCER ST
City (OD): SEATTLE
Zipcode (OD): 98109-4615
Location (OD): ""
(47.62463, -122.349768)
Alternate Site Names: MYLES STANDISH
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

233	1 of 1	ESE	0.55 / 2,924.95	149.84 / 44	**Barg French Cleaners** **1929 3RD AVE** **SEATTLE WA 98101**	CSCSL

Fac Site ID: 22254391
Cleanup Site ID: 4045
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control: Yes
County: King

Responsible Unit: Northwest
Fac Site ID (OD): 22254391
Cleanup SiteID(OD): 4045
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Region: Northwest
Latitude: 47.6120640260569
Longitude: -122.340647373894
Site Name: Barg French Cleaners
Address: 1929 3RD AVE
City: SEATTLE
Zip Code: 98101
Site Status (OD): Cleanup Started
Site Name (OD): Barg French Cleaners
Address (OD): 1929 3RD AVE
City (OD): SEATTLE
Zipcode (OD): 98101
Location (OD): "" (47.612064, -122.340647)
Alternate Site Names: BARG FRENCH DRY CLEANER,HEIDEN BLDG
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Longitude (OD): -122.340647
Latitude (OD): 47.612064

Contaminants Detail(s)

Contaminant Name: Halogenated Organics
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Halogenated Organics
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Halogenated Organics
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
234	1 of 2	NNW	0.55 / 2,926.82	135.94 / 30	Texaco Pro Investments 150 Mercer St / 600 Warren Ave N SEATTLE WA 98109	CSCSL

Fac Site ID: 25287143
Cleanup Site ID: 8463
Site Status: Cleanup Started
Site Rank: 3 - Moderate Risk
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6248061334665
Longitude: -122.353864876826
Site Name: Texaco Pro Investments
Address: 150 Mercer St / 600 Warren Ave N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): TEXACO PRO INVESTMENTS
Address (OD): 150 Mercer St / 600 Warren Ave N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): "" (47.624806, -122.353865)
Alternate Site Names: WILLIAM ARNOLD
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 25287143
Cleanup SiteID(OD): 8463
Site Rank (OD): 3 - Moderate Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.353865
Latitude (OD): 47.624806

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

234 | ***2 of 2*** | ***NNW*** | ***0.55 / 2,926.82*** | ***135.94 / 30*** | ***Texaco Pro Investments***
150 Mercer St / 600 Warren Ave N
SEATTLE WA 98109 | ***HSL***

Fac Site ID: 25287143
Cleanup Site ID: 8463
Site Status: Cleanup Started
Site Rank: 3 - Moderate Risk
Has Inst Control:
Responsible Unit: Northwest
County: King
Region: Northwest
Latitude: 47.6248061334665
Longitude: -122.353864876826
Latitude (OD): 47.624806
Longitude (OD): -122.353865
Current VCP:
Location (OD): "" (47.624806, -122.353865)
Fac Site ID (OD): 25287143
Cleanup Site ID (OD): 8463
Site Status (OD): Cleanup Started
Site Rank (OD): 3 - Moderate Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Site Name (OD): TEXACO PRO INVESTMENTS
Address (OD): 150 Mercer St / 600 Warren Ave N
City (OD): SEATTLE
ZIP code (OD): 98109
Past VCP:
Alternate Site Names: WILLIAM ARNOLD
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Air:
Sediment:
Soil: Confirmed Above Cleanup Levels
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

235 | ***1 of 2*** | ***ESE*** | ***0.56 / 2,980.94*** | ***129.81 / 24*** | ***4th & Virginia***
1920 4TH AVE
SEATTLE WA 98101 | ***CSCSL***

Fac Site ID: 3229556
Cleanup Site ID: 2152
Site Status: Cleanup Started
Site Rank: 3 - Moderate Risk
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Responsible Unit: Northwest
Fac Site ID (OD): 3229556
Cleanup SiteID(OD): 2152
Site Rank (OD): 3 - Moderate Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.339223

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Latitude: 47.6129141335208 **Latitude (OD):** 47.612914
Longitude: -122.33922260594
Site Name: 4th & Virginia
Address: 1920 4TH AVE
City: SEATTLE
Zip Code: 98101
Site Status (OD): Cleanup Started
Site Name (OD): 4th & Virginia
Address (OD): 1920 4TH AVE
City (OD): SEATTLE
Zipcode (OD): 98101
Location (OD): ""
(47.612914, -122.339223)
Alternate Site Names: Escala Condominiums,ESCALA OWNERS ASSOCIATION
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

235	2 of 2	ESE	0.56 / 2,980.94	129.81 / 24	4th & Virginia 1920 4TH AVE SEATTLE WA 98101	HSL

Fac Site ID: 3229556 **Fac Site ID (OD):** 3229556
Cleanup Site ID: 2152 **Cleanup Site ID (OD):** 2152
Site Status: Cleanup Started **Site Status (OD):** Cleanup Started
Site Rank: 3 - Moderate Risk **Site Rank (OD):** 3 - Moderate Risk
Has Inst Control: **Has Env Coven (OD):**
Responsible Unit: Northwest **Respon Unit (OD):** Northwest
County: King **County (OD):** King
Region: Northwest **Region (OD):** Northwest
Latitude: 47.6129141335208 **Site Name (OD):** 4th & Virginia
Longitude: -122.33922260594 **Address (OD):** 1920 4TH AVE
Latitude (OD): 47.612914 **City (OD):** SEATTLE
Longitude (OD): -122.339223 **ZIP code (OD):** 98101
Current VCP: **Past VCP:** Yes
Location (OD): ""
(47.612914, -122.339223)
Alternate Site Names: Escala Condominiums,ESCALA OWNERS ASSOCIATION
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified **Sediment:**
Groundwater: Confirmed Above Cleanup Levels **Soil:** Confirmed Above Cleanup Levels
Surfacewater: **Bedrock:**
Air:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Petroleum Products-Unspecified	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum Products-Unspecified	***Contaminant Media:***	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		

---

236 | ***1 of 2*** | ***NW*** | ***0.57 / 2,992.49*** | ***141.00 / 35*** | ***Uptown Bakery***
513-525 QUEEN ANNE AVE N
SEATTLE WA 98119 | ***CSCSL***

Fac Site ID:	6136999	***Responsible Unit:***	Northwest
Cleanup Site ID:	2713	***Fac Site ID (OD):***	6136999
Site Status:	Cleanup Started	***Cleanup SiteID(OD):***	2713
Site Rank:	5 - Lowest Assessed Risk	***Site Rank (OD):***	5 - Lowest Assessed Risk
Current VCP:	Yes	***Has Env Coven (OD):***	
Past VCP:	Yes	***Respon Unit (OD):***	Northwest
Has Inst Control:		***County (OD):***	King
County:	King	***Region (OD):***	Northwest
Region:	Northwest	***Longitude (OD):***	-122.35675
Latitude:	47.6239538253037	***Latitude (OD):***	47.62405
Longitude:	-122.356996763284		
Site Name:	Uptown Bakery		
Address:	513-525 QUEEN ANNE AVE N		
City:	SEATTLE		
Zip Code:	98119		
Site Status (OD):	Cleanup Started		
Site Name (OD):	Uptown Bakery		
Address (OD):	519-521 QUEEN ANNE AVE N		
City (OD):	SEATTLE		
Zipcode (OD):	98119		
Location (OD):	"" (47.62405, -122.35675)		
Alternate Site Names:	FORMER QUEEN ANNE DYE WORKS,SAMS SUSHI,ULTIMATE TAN,Uptown Bakery Former		
Data Source(s):	Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)		

Contaminants Detail(s)

Contaminant Name:	Non-Halogenated Solvents
Groundwater:	Confirmed Above Cleanup Levels
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Petroleum Products-Unspecified
Groundwater:	Confirmed Above Cleanup Levels
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Halogenated Organics
Groundwater:	Suspected
Surfacewater:	
Soil:	Suspected
Sediment:	
Air:	
Bedrock:	

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Non-Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Halogenated Organics
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Non-Halogenated Solvents
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Halogenated Organics
Contaminant Media: Groundwater
Contaminant Status: Suspected

---

236 | ***2 of 2*** | ***NW*** | ***0.57 / 2,992.49*** | ***141.00 / 35*** | ***Uptown Bakery 513-525 QUEEN ANNE AVE N SEATTLE WA 98119*** | ***HSL***

Fac Site ID:	6136999	***Fac Site ID (OD):***	6136999
Cleanup Site ID:	2713	***Cleanup Site ID (OD):***	2713
Site Status:	Cleanup Started	***Site Status (OD):***	Cleanup Started
Site Rank:	5 - Lowest Assessed Risk	***Site Rank (OD):***	5 - Lowest Assessed Risk
Has Inst Control:		***Has Env Coven (OD):***	
Responsible Unit:	Northwest	***Respon Unit (OD):***	Northwest
County:	King	***County (OD):***	King
Region:	Northwest	***Region (OD):***	Northwest
Latitude:	47.6239538253037	***Site Name (OD):***	Uptown Bakery
Longitude:	-122.356996763284	***Address (OD):***	519-521 QUEEN ANNE AVE N
Latitude (OD):	47.62405	***City (OD):***	SEATTLE
Longitude (OD):	-122.35675	***ZIP code (OD):***	98119
Current VCP:	Yes	***Past VCP:***	Yes

Location (OD): ""
(47.62405, -122.35675)
Alternate Site Names: FORMER QUEEN ANNE DYE WORKS,SAMS SUSHI,ULTIMATE TAN,Uptown Bakery Former
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name:	Non-Halogenated Solvents	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:		***Bedrock:***	
Air:			

Contaminant Name:	Petroleum Products-Unspecified	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:		***Bedrock:***	
Air:			

Contaminant Name:	Halogenated Organics	***Sediment:***	
Groundwater:	Suspected	***Soil:***	Suspected
Surfacewater:		***Bedrock:***	
Air:			

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Halogenated Organics ***Contaminant Media:*** Groundwater

Contaminant Status:	Suspected		
Contaminant:	Non-Halogenated Solvents	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum Products-Unspecified	**Contaminant Media:**	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum Products-Unspecified	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Halogenated Organics	**Contaminant Media:**	Soil
Contaminant Status:	Suspected		
Contaminant:	Non-Halogenated Solvents	**Contaminant Media:**	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		

237	1 of 1	SE	0.57 / 3,025.25	145.28 / 40	First & Stewart Hotel Owner LLC 1916 1ST AVE SEATTLE WA 98101	CSCSL

Fac Site ID:	14329	**Responsible Unit:**	Northwest
Cleanup Site ID:	12452	**Fac Site ID (OD):**	14329
Site Status:	Cleanup Started	**Cleanup SiteID(OD):**	12452
Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:	Yes	**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.341796
Latitude:	47.6108380776582	**Latitude (OD):**	47.610304
Longitude:	-122.341562103232		

Site Name: First & Stewart Hotel Owner LLC
Address: 1916 1ST AVE
City: SEATTLE
Zip Code: 98101
Site Status (OD): Cleanup Started
Site Name (OD): First & Stewart Hotel Owner LLC
Address (OD): 1916 1ST AVE
City (OD): SEATTLE
Zipcode (OD): 98101
Location (OD): ""
(47.610304, -122.341796)
Alternate Site Names: First & Stewart Hotel Owner LLC (Off-Property),First & Stewart Hotel Owner LLC (Property NFA)
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Lead
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Remediated-Below
Surfacewater:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Remediated-Below
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater: Remediated-Below
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Lead
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Diesel
Contaminant Media: Groundwater
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Remediated-Below

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Remediated-Below

238	*1 of 2*	*NW*	*0.57 / 3,033.03*	*142.05 / 36*	***Queen Anne Properties Mercer St*** ***541 QUEEN ANNE AVE N*** ***SEATTLE WA 98109***	***CSCSL***

Fac Site ID:	46659536	**Responsible Unit:**	Northwest
Cleanup Site ID:	395	**Fac Site ID (OD):**	46659536
Site Status:	Cleanup Started	**Cleanup SiteID(OD):**	395
Site Rank:	2 - Moderate-High Risk	**Site Rank (OD):**	2 - Moderate-High Risk
Current VCP:		**Has Env Coven (OD):**	
Past VCP:	Yes	**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.357117
Latitude:	47.62423	**Latitude (OD):**	47.624333
Longitude:	-122.35725		

Site Name: Queen Anne Properties Mercer St
Address: 541 QUEEN ANNE AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Queen Anne Properties Mercer St
Address (OD): 541 QUEEN ANNE AVE N
City (OD): SEATTLE
Zipcode (OD): 98109-4521
Location (OD): ""
(47.624333, -122.357117)
Alternate Site Names: JOHN K MORRIS,KIDD VALLEY PROPERTY,MORRIS JOHN K,Queen Anne Properties Mercer St (Off-Property), Queen Anne Properties Mercer St (Property NFA)
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Benzene
Groundwater: Remediated-Below
Surfacewater: Remediated-Below
Soil: Confirmed Above Cleanup Levels
Sediment:
Air: Remediated-Below
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Non-Halogenated Solvents
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Other Non-Halogenated Organics
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name:	Petroleum-Gasoline
Groundwater:	Remediated-Below
Surfacewater:	Remediated-Below
Soil:	Remediated-Below
Sediment:	
Air:	Remediated-Below
Bedrock:	

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Petroleum-Gasoline
Contaminant Media:	Groundwater
Contaminant Status:	Remediated-Below
Contaminant:	Petroleum-Gasoline
Contaminant Media:	Air
Contaminant Status:	Remediated-Below
Contaminant:	Benzene
Contaminant Media:	Surface Water
Contaminant Status:	Remediated-Below
Contaminant:	Non-Halogenated Solvents
Contaminant Media:	Soil
Contaminant Status:	Remediated-Below
Contaminant:	Petroleum-Diesel
Contaminant Media:	Soil
Contaminant Status:	Confirmed Above Cleanup Levels
Contaminant:	Benzene
Contaminant Media:	Air
Contaminant Status:	Remediated-Below
Contaminant:	Petroleum-Other
Contaminant Media:	Soil
Contaminant Status:	Remediated-Below
Contaminant:	Benzene
Contaminant Media:	Groundwater
Contaminant Status:	Remediated-Below
Contaminant:	Petroleum-Gasoline
Contaminant Media:	Surface Water
Contaminant Status:	Remediated-Below
Contaminant:	Other Non-Halogenated Organics
Contaminant Media:	Soil
Contaminant Status:	Confirmed Above Cleanup Levels
Contaminant:	Benzene
Contaminant Media:	Soil
Contaminant Status:	Confirmed Above Cleanup Levels
Contaminant:	Petroleum-Gasoline
Contaminant Media:	Soil
Contaminant Status:	Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
238	2 of 2	NW	0.57 / 3,033.03	142.05 / 36	Queen Anne Properties Mercer St 541 QUEEN ANNE AVE N SEATTLE WA 98109	HSL

Fac Site ID:	46659536	***Fac Site ID (OD):***	46659536
Cleanup Site ID:	395	***Cleanup Site ID (OD):***	395
Site Status:	Cleanup Started	***Site Status (OD):***	Cleanup Started
Site Rank:	2 - Moderate-High Risk	***Site Rank (OD):***	2 - Moderate-High Risk
Has Inst Control:		***Has Env Coven (OD):***	

Responsible Unit:	Northwest	**Respon Unit (OD):**	Northwest
County:	King	**County (OD):**	King
Region:	Northwest	**Region (OD):**	Northwest
Latitude:	47.62423	**Site Name (OD):**	Queen Anne Properties Mercer St
Longitude:	-122.35725	**Address (OD):**	541 QUEEN ANNE AVE N
Latitude (OD):	47.624333	**City (OD):**	SEATTLE
Longitude (OD):	-122.357117	**ZIP code (OD):**	98109-4521
Current VCP:		**Past VCP:**	Yes
Location (OD):	"" (47.624333, -122.357117)		
Alternate Site Names:	JOHN K MORRIS,KIDD VALLEY PROPERTY,MORRIS JOHN K,Queen Anne Properties Mercer St (Off-Property), Queen Anne Properties Mercer St (Property NFA)		
Data Source(s):	Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)		

Contaminants Detail(s)

Contaminant Name:	Other Non-Halogenated Organics	**Sediment:**	
Groundwater:		**Soil:**	Remediated-Below
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Non-Halogenated Solvents	**Sediment:**	
Groundwater:		**Soil:**	Remediated-Below
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Petroleum-Diesel	**Sediment:**	
Groundwater:		**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Petroleum-Other	**Sediment:**	
Groundwater:		**Soil:**	Remediated-Below
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Benzene	**Sediment:**	
Groundwater:	Remediated-Below	**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:	Remediated-Below	**Bedrock:**	
Air:	Remediated-Below		
Contaminant Name:	Petroleum-Gasoline	**Sediment:**	
Groundwater:	Remediated-Below	**Soil:**	Remediated-Below
Surfacewater:	Remediated-Below	**Bedrock:**	
Air:	Remediated-Below		

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Petroleum-Gasoline	**Contaminant Media:**	Air
Contaminant Status:	Remediated-Below		
Contaminant:	Benzene	**Contaminant Media:**	Groundwater
Contaminant Status:	Remediated-Below		
Contaminant:	Petroleum-Other	**Contaminant Media:**	Soil
Contaminant Status:	Remediated-Below		
Contaminant:	Petroleum-Gasoline	**Contaminant Media:**	Surface Water
Contaminant Status:	Remediated-Below		
Contaminant:	Benzene	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Gasoline	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Diesel	**Contaminant Media:**	Soil

Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Air
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Remediated-Below

Contaminant: Benzene
Contaminant Media: Surface Water
Contaminant Status: Remediated-Below

Contaminant: Non-Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Other Non-Halogenated Organics
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

239 | **1 of 1** | **SE** | **0.57 / 3,034.40** | **8.33 / -97** | **Pier 63 Sediments**
1915 ALASKAN WAY
SEATTLE WA 98101 | **CSCSL**

Fac Site ID: 39947
Cleanup Site ID: 15510
Site Status: Awaiting Cleanup
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6087966934046
Longitude: -122.345762937278
Site Name: Pier 63 Sediments
Address: 1915 ALASKAN WAY
City: SEATTLE
Zip Code: 98101
Site Status (OD):
Site Name (OD):
Address (OD):
City (OD):
Zipcode (OD):
Location (OD):
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites

Responsible Unit: Northwest
Fac Site ID (OD):
Cleanup SiteID(OD):
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD):
County (OD):
Region (OD):
Longitude (OD):
Latitude (OD):

Contaminants Detail(s)

Contaminant Name: Dioxins/Furans
Groundwater:
Surfacewater:
Soil:
Sediment: Suspected
Air:
Bedrock:

Contaminant Name: Mercury
Groundwater:
Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

Contaminant Name: Bioassay Failure
Groundwater:
Surfacewater:
Soil:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Sediment: Suspected
Air:
Bedrock:

Contaminant Name: Metals - Other
Groundwater:
Surfacewater:
Soil:
Sediment: Suspected
Air:
Bedrock:

Contaminant Name: Polychlorinated biPhenyls (PCB)
Groundwater:
Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

240	1 of 1	E	0.58 / 3,036.05	67.29 / -38	Kenney Property 100 WESTLAKE AVE N SEATTLE WA 98109	CSCSL

Fac Site ID: 59168749
Cleanup Site ID: 9831
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6192021425443
Longitude: -122.338153626446
Site Name: Kenney Property
Address: 100 WESTLAKE AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Kenney Property
Address (OD): 100 WESTLAKE AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.619202, -122.338154)

Responsible Unit: Northwest
Fac Site ID (OD): 59168749
Cleanup SiteID(OD): 9831
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.338154
Latitude (OD): 47.619202

Alternate Site Names: Frank Kenney Toyota Auto Repair and Sales,ROLLIN STREET FLATS,Rollin Street Flats (Property NFA)
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Other Non-Halogenated Organics
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
241	1 of 3	ESE	0.58 / 3,054.66	157.75 / 52	Second Avenue Garage 1915 2ND AVE SEATTLE WA 98101	CSCSL

Fac Site ID: 29947325
Cleanup Site ID: 7242
Site Status: Awaiting Cleanup
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6111127560278
Longitude: -122.341223897471
Site Name: Second Avenue Garage
Address: 1915 2ND AVE

Responsible Unit: Northwest
Fac Site ID (OD): 29947325
Cleanup SiteID(OD): 7242
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.341224
Latitude (OD): 47.611113

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

City:	SEATTLE
Zip Code:	98101
Site Status (OD):	Awaiting Cleanup
Site Name (OD):	Second Avenue Garage
Address (OD):	1915 2ND AVE
City (OD):	SEATTLE
Zipcode (OD):	98101
Location (OD):	"" (47.611113, -122.341224)
Alternate Site Names:	AUTOPARK USA INC,Belltown Towers,PROPARK,Viktoria Apartments
Data Source(s):	Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name:	Non-Halogenated Solvents
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Petroleum-Gasoline
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Benzene
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Non-Halogenated Solvents
Contaminant Media:	Soil
Contaminant Status:	Confirmed Above Cleanup Levels

Contaminant:	Petroleum-Gasoline
Contaminant Media:	Soil
Contaminant Status:	Confirmed Above Cleanup Levels

Contaminant:	Benzene
Contaminant Media:	Soil
Contaminant Status:	Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
241	2 of 3	ESE	0.58 / 3,054.66	157.75 / 52	**Viktoria Apartments** **1915 2ND AVE** **SEATTLE WA 98101**	CSCSL

Fac Site ID:	29947325	**Responsible Unit:**	Northwest
Cleanup Site ID:	7075	**Fac Site ID (OD):**	29947325
Site Status:	Cleanup Started	**Cleanup SiteID(OD):**	7075
Site Rank:	1 - Highest Assessed Risk	**Site Rank (OD):**	1 - Highest Assessed Risk
Current VCP:		**Has Env Coven (OD):**	
Past VCP:	Yes	**Respon Unit (OD):**	Northwest
Has Inst Control:	Yes	**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.341224
Latitude:	47.6111127560278	**Latitude (OD):**	47.611113

Longitude: -122.341223897471
Site Name: Viktoria Apartments
Address: 1915 2ND AVE
City: SEATTLE
Zip Code: 98101
Site Status (OD): Cleanup Started
Site Name (OD): Viktoria Apartments
Address (OD): 1915 2ND AVE
City (OD): SEATTLE
Zipcode (OD): 98101
Location (OD): ""
(47.611113, -122.341224)
Alternate Site Names: AUTOPARK USA INC,Belltown Towers,PROPARK,SECOND AVENUE GARAGE
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Halogenated Solvents
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater: Remediated-Below
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air: Remediated-Below
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater: Remediated-Below
Surfacewater:
Soil: Remediated-Above
Sediment:
Air: Remediated-Below
Bedrock:

Contaminant Name: Other Non-Halogenated Organics
Groundwater: Remediated-Below
Surfacewater:
Soil: Remediated-Above
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Remediated-Below
Surfacewater:
Soil: Remediated-Above
Sediment:
Air: Remediated-Below
Bedrock:

Contaminant Name: Lead
Groundwater:
Surfacewater:
Soil: Remediated-Above
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Remediated-Below
Surfacewater:

Soil: Remediated-Above
Sediment:
Air: Remediated-Below
Bedrock:

Contaminant Name: Other Halogenated Organics
Groundwater: Remediated-Below
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Remediated-Above
Sediment:
Air: Remediated-Below
Bedrock:

<u>Open Data Portal - Media and Contaminants as of 2021-09-15</u>

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Other Non-Halogenated Organics
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Other Non-Halogenated Organics
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Other Halogenated Organics
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other

Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Lead
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

241 | **3 of 3** | **ESE** | **0.58 / 3,054.66** | **157.75 / 52** | **Viktoria Apartments**
1915 2ND AVE
SEATTLE WA 98101 | **HSL**

Fac Site ID:	29947325	**Fac Site ID (OD):**	29947325
Cleanup Site ID:	7075	**Cleanup Site ID (OD):**	7075
Site Status:	Cleanup Started	**Site Status (OD):**	Cleanup Started
Site Rank:	1 - Highest Assessed Risk	**Site Rank (OD):**	1 - Highest Assessed Risk
Has Inst Control:	Yes	**Has Env Coven (OD):**	
Responsible Unit:	Northwest	**Respon Unit (OD):**	Northwest
County:	King	**County (OD):**	King
Region:	Northwest	**Region (OD):**	Northwest
Latitude:	47.6111127560278	**Site Name (OD):**	Viktoria Apartments
Longitude:	-122.341223897471	**Address (OD):**	1915 2ND AVE
Latitude (OD):	47.611113	**City (OD):**	SEATTLE
Longitude (OD):	-122.341224	**ZIP code (OD):**	98101
Current VCP:		**Past VCP:**	Yes

Location (OD): ""
(47.611113, -122.341224)
Alternate Site Names: AUTOPARK USA INC,Belltown Towers,PROPARK,SECOND AVENUE GARAGE
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name:	Petroleum-Other	**Sediment:**	
Groundwater:	Remediated-Below	**Soil:**	Remediated-Above
Surfacewater:		**Bedrock:**	
Air:	Remediated-Below		

Contaminant Name:	Other Halogenated Organics	**Sediment:**	
Groundwater:	Remediated-Below	**Soil:**	
Surfacewater:		**Bedrock:**	
Air:			

Contaminant Name:	Other Non-Halogenated Organics	**Sediment:**	
Groundwater:	Remediated-Below	**Soil:**	Remediated-Above
Surfacewater:		**Bedrock:**	
Air:			

Contaminant Name:	Halogenated Solvents	**Sediment:**	
Groundwater:		**Soil:**	Remediated-Below
Surfacewater:		**Bedrock:**	
Air:			

Contaminant Name:	Benzene	**Sediment:**	
Groundwater:	Remediated-Below	**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:	Remediated-Below		

Contaminant Name:	Petroleum-Diesel	**Sediment:**	
Groundwater:		**Soil:**	Remediated-Above
Surfacewater:		**Bedrock:**	
Air:	Remediated-Below		

Contaminant Name:	Polycyclic Aromatic Hydrocarbons	**Sediment:**	
Groundwater:	Remediated-Below	**Soil:**	Remediated-Above

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Surfacewater: ***Bedrock:***
Air: Remediated-Below

Contaminant Name: Lead ***Sediment:***
Groundwater: ***Soil:*** Remediated-Above
Surfacewater: ***Bedrock:***
Air:

Contaminant Name: Petroleum-Gasoline ***Sediment:***
Groundwater: Remediated-Below ***Soil:*** Remediated-Above
Surfacewater: ***Bedrock:***
Air: Remediated-Below

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Lead ***Contaminant Media:*** Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene ***Contaminant Media:*** Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Other Halogenated Organics ***Contaminant Media:*** Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other ***Contaminant Media:*** Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Other Non-Halogenated Organics ***Contaminant Media:*** Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Halogenated Solvents ***Contaminant Media:*** Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel ***Contaminant Media:*** Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons ***Contaminant Media:*** Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Other Non-Halogenated Organics ***Contaminant Media:*** Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other ***Contaminant Media:*** Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline ***Contaminant Media:*** Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene ***Contaminant Media:*** Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline ***Contaminant Media:*** Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons ***Contaminant Media:*** Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

242	1 of 1	NNW	0.59 / 3,103.10	125.91 / 20	**Seattle Opera Parking** **620 2ND AVE N** **SEATTLE WA 98109**	CSCSL

Fac Site ID: ***Responsible Unit:***
Cleanup Site ID: ***Fac Site ID (OD):*** 19244
Site Status: ***Cleanup SiteID(OD):*** 13198
Site Rank: ***Site Rank (OD):***
Current VCP: ***Has Env Coven (OD):***
Past VCP: ***Respon Unit (OD):*** Northwest

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Has Inst Control:		**County (OD):**	King
County:		**Region (OD):**	Northwest
Region:		**Longitude (OD):**	-122.35239
Latitude:		**Latitude (OD):**	47.62516
Longitude:			
Site Name:			
Address:			
City:			
Zip Code:			
Site Status (OD):	Cleanup Started		
Site Name (OD):	Seattle Opera Parking		
Address (OD):	620 2ND AVE N		
City (OD):	SEATTLE		
Zipcode (OD):	98109		
Location (OD):	"" (47.62516, -122.35239)		
Alternate Site Names:			
Data Source(s):	Cleanup Sites (Open Data Portal)		

243	*1 of 2*	*E*	*0.59 / 3,107.75*	*68.10 / -38*	***Nash Holland Denny Investors*** ***964 970 DENNY WAY*** ***SEATTLE WA 98109***	***CSCSL***

Fac Site ID:	2436937	**Responsible Unit:**	Northwest
Cleanup Site ID:	7478	**Fac Site ID (OD):**	2436937
Site Status:	Cleanup Started	**Cleanup SiteID(OD):**	7478
Site Rank:	3 - Moderate Risk	**Site Rank (OD):**	3 - Moderate Risk
Current VCP:	Yes	**Has Env Coven (OD):**	
Past VCP:	Yes	**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.337631
Latitude:	47.6189652273456	**Latitude (OD):**	47.618965
Longitude:	-122.337630830658		
Site Name:	Nash Holland Denny Investors		
Address:	964 970 DENNY WAY		
City:	SEATTLE		
Zip Code:	98109		
Site Status (OD):	Cleanup Started		
Site Name (OD):	Nash Holland Denny Investors		
Address (OD):	964 970 DENNY WAY		
City (OD):	SEATTLE		
Zipcode (OD):	98109-5201		
Location (OD):	"" (47.618965, -122.337631)		
Alternate Site Names:	BMS Investments,Brooke Matty Smith (BMS),Brooke Real Estate Venture,DUCKY'S OFFICE FURNITURE, WESTERN VAN LINES INC		
Data Source(s):	Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Gasoline
Groundwater:	Confirmed Above Cleanup Levels
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Halogenated Solvents
Groundwater:	Confirmed Above Cleanup Levels
Surfacewater:	
Soil:	
Sediment:	
Air:	Confirmed Above Cleanup Levels
Bedrock:	

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil:
Sediment:
Air: Confirmed Above Cleanup Levels
Bedrock:

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Other Non-Halogenated Organics
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air: Confirmed Above Cleanup Levels
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
243	2 of 2	E	0.59 / 3,107.75	68.10 / -38	Nash Holland Denny Investors 964 970 DENNY WAY SEATTLE WA 98109	HSL

Fac Site ID:	2436937	***Fac Site ID (OD):***	2436937
Cleanup Site ID:	7478	***Cleanup Site ID (OD):***	7478
Site Status:	Cleanup Started	***Site Status (OD):***	Cleanup Started
Site Rank:	3 - Moderate Risk	***Site Rank (OD):***	3 - Moderate Risk
Has Inst Control:		***Has Env Coven (OD):***	
Responsible Unit:	Northwest	***Respon Unit (OD):***	Northwest
County:	King	***County (OD):***	King
Region:	Northwest	***Region (OD):***	Northwest
Latitude:	47.6189652273456	***Site Name (OD):***	Nash Holland Denny Investors
Longitude:	-122.337630830658	***Address (OD):***	964 970 DENNY WAY
Latitude (OD):	47.618965	***City (OD):***	SEATTLE
Longitude (OD):	-122.337631	***ZIP code (OD):***	98109-5201
Current VCP:	Yes	***Past VCP:***	Yes

Location (OD): ""
(47.618965, -122.337631)
Alternate Site Names: BMS Investments,Brooke Matty Smith (BMS),Brooke Real Estate Venture,DUCKY'S OFFICE FURNITURE, WESTERN VAN LINES INC
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Other Non-Halogenated Organics
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Sediment:
Soil:
Bedrock:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Air: Confirmed Above Cleanup Levels

Contaminant Name: Halogenated Solvents
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Air: Confirmed Above Cleanup Levels
Sediment:
Soil:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Air:
Sediment:
Soil:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Air:
Sediment:
Soil: Confirmed Above Cleanup Levels
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Air: Confirmed Above Cleanup Levels
Sediment:
Soil:
Bedrock:

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Air:
Sediment:
Soil:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Soil

244	1 of 1	NE	0.59 / 3,113.84	72.54 / -33	**Seattle Center Property** **601-615 MERCER ST** **SEATTLE WA 98109**	CSCSL

Fac Site ID: 2594
Cleanup Site ID: 320
Site Status: Awaiting Cleanup
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.624268
Longitude: -122.346099
Site Name: Seattle Center Property
Address: 601-615 MERCER ST
City: SEATTLE
Zip Code: 98109
Site Status (OD): Awaiting Cleanup
Site Name (OD): Seattle Center Property
Address (OD): 601-615 MERCER ST
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.624268, -122.346099)
Alternate Site Names: SEATTLE CITY SEATTLE CTR PROP,Supersonics Training Facility
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 2594
Cleanup SiteID(OD): 320
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.346099
Latitude (OD): 47.624268

Contaminants Detail(s)

Contaminant Name: Non-Halogenated Solvents
Groundwater: Suspected
Surfacewater:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Suspected
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Metals Priority Pollutants
Groundwater: Suspected
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Metals Priority Pollutants
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Non-Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Non-Halogenated Solvents
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals Priority Pollutants
Contaminant Media: Soil
Contaminant Status: Suspected

245	*1 of 1*	*ENE*	*0.59 / 3,131.47*	*64.19 / -42*	***9th Space*** ***308 9TH AVE N*** ***SEATTLE WA 98109***	***CSCSL***

Fac Site ID: 98495354
Cleanup Site ID: 15263
Site Status: Awaiting Cleanup
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.62117
Longitude: -122.33942
Site Name: 9th Space
Address: 308 9TH AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD):

Responsible Unit: Northwest
Fac Site ID (OD):
Cleanup SiteID(OD):
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD):
County (OD):
Region (OD):
Longitude (OD):
Latitude (OD):

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Name (OD):
Address (OD):
City (OD):
Zipcode (OD):
Location (OD):
Alternate Site Names: United Electric Motor Inc
Data Source(s): Confirmed and Suspected Contaminated Sites

Contaminants Detail(s)

Contaminant Name: Halogenated Solvents
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air: Confirmed Above Cleanup Levels
Bedrock:

246	1 of 1	E	0.60 / 3,146.31	85.89 / -20	**Westlake Chevrolet** **2030 8TH AVE** **SEATTLE WA 98121**	**DELISTED SHWS**

Delisted Contaminated/Hazardous Sites

Fac Site ID: 1393421
Cleanup Site ID: 12495
Brownfield?:
PSI?:
VCP?: Yes
Past VCP:
Has Inst Control:
Site Status: Cleanup Started
Alternate Site Names:
Original Source: CSCS
Record Date: 11-DEC-2015

WARM Rank: N
Warm Rank Desc:
Respon Section: Northwest
County: King
Region: Northwest
Latitude: 47.61607
Longitude: -122.33707

247	1 of 1	E	0.60 / 3,147.70	96.86 / -9	**Budget Rent A Car Westlake** **2001 WESTLAKE AVE** **SEATTLE WA 98121-2605**	**DELISTED SHWS**

Delisted Contaminated/Hazardous Sites

Fac Site ID: 93116644
Cleanup Site ID: 6877
Brownfield?:
PSI?: Yes
VCP?: Yes
Past VCP:
Has Inst Control:
Site Status: Cleanup Started
Alternate Site Names:
Original Source: CSCS
Record Date: 14-MAR-2016

WARM Rank: N
Warm Rank Desc:
Respon Section: Northwest
County: King
Region: Northwest
Latitude: 47.61475
Longitude: -122.338987

248	1 of 2	WNW	0.60 / 3,161.27	22.15 / -84	**Coleman Creosoting Works** **333 ELLIOTT AVE W** **SEATTLE WA 98119**	**CSCSL**

Fac Site ID: 77732426
Cleanup Site ID: 1841
Site Status: Cleanup Started

Responsible Unit: Northwest
Fac Site ID (OD): 77732426
Cleanup SiteID(OD): 1841

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Rank:	5 - Lowest Assessed Risk	**Site Rank (OD):**	5 - Lowest Assessed Risk
Current VCP:		**Has Env Coven (OD):**	
Past VCP:	Yes	**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.361777
Latitude:	47.6209385584036	**Latitude (OD):**	47.621324
Longitude:	-122.361905745542		

Site Name: Coleman Creosoting Works
Address: 333 ELLIOTT AVE W
City: SEATTLE
Zip Code: 98119
Site Status (OD): Cleanup Started
Site Name (OD): Coleman Creosoting Works
Address (OD): 333 ELLIOTT AVE W
City (OD): SEATTLE
Zipcode (OD): 98119-4101
Location (OD): ""
(47.621324, -122.361777)
Alternate Site Names: CRAWFORD SEA GRILL,IVAR'S CAPTAIN'S TABLE,U.S. VINING & THE FURNACE OIL COMPANY
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Sediment
Contaminant Status: Suspected

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

248	2 of 2	WNW	0.60 / 3,161.27	22.15 / -84	**Coleman Creosoting Works** **333 ELLIOTT AVE W** **SEATTLE WA 98119**	HSL

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Fac Site ID:	77732426	**Fac Site ID (OD):**	77732426
Cleanup Site ID:	1841	**Cleanup Site ID (OD):**	1841
Site Status:	Cleanup Started	**Site Status (OD):**	Cleanup Started
Site Rank:	5 - Lowest Assessed Risk	**Site Rank (OD):**	5 - Lowest Assessed Risk
Has Inst Control:		**Has Env Coven (OD):**	
Responsible Unit:	Northwest	**Respon Unit (OD):**	Northwest
County:	King	**County (OD):**	King
Region:	Northwest	**Region (OD):**	Northwest
Latitude:	47.6209385584036	**Site Name (OD):**	Coleman Creosoting Works
Longitude:	-122.361905745542	**Address (OD):**	333 ELLIOTT AVE W
Latitude (OD):	47.621324	**City (OD):**	SEATTLE
Longitude (OD):	-122.361777	**ZIP code (OD):**	98119-4101
Current VCP:		**Past VCP:**	Yes

Location (OD): ""
(47.621324, -122.361777)

Alternate Site Names: CRAWFORD SEA GRILL,IVAR'S CAPTAIN'S TABLE,U.S. VINING & THE FURNACE OIL COMPANY
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name:	Petroleum Products-Unspecified	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			

Contaminant Name:	Polycyclic Aromatic Hydrocarbons	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Petroleum Products-Unspecified	**Contaminant Media:**	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Polycyclic Aromatic Hydrocarbons	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Polycyclic Aromatic Hydrocarbons	**Contaminant Media:**	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Polycyclic Aromatic Hydrocarbons	**Contaminant Media:**	Sediment
Contaminant Status:	Suspected		
Contaminant:	Petroleum Products-Unspecified	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
249	1 of 2	ESE	0.60 / 3,186.59	151.81 / 46	St Regis Hotel 116 STEWART ST SEATTLE WA 98101	CSCSL

Fac Site ID:	430937	**Responsible Unit:**	Northwest
Cleanup Site ID:	3981	**Fac Site ID (OD):**	430937
Site Status:	Cleanup Started	**Cleanup SiteID(OD):**	3981
Site Rank:	5 - Lowest Assessed Risk	**Site Rank (OD):**	5 - Lowest Assessed Risk
Current VCP:		**Has Env Coven (OD):**	
Past VCP:	Yes	**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.340914
Latitude:	47.6108593200054	**Latitude (OD):**	47.610859
Longitude:	-122.3409144062		
Site Name:	St Regis Hotel		
Address:	116 STEWART ST		
City:	SEATTLE		
Zip Code:	98101		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Status (OD): Cleanup Started
Site Name (OD): St Regis Hotel
Address (OD): 116 STEWART ST
City (OD): SEATTLE
Zipcode (OD): 98101
Location (OD): ""
(47.610859, -122.340914)
Alternate Site Names: PLYMOUTH ON STEWART APTS,SECOND & STEWART PROPERTY
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
249	2 of 2	ESE	0.60 / 3,186.59	151.81 / 46	St Regis Hotel 116 STEWART ST SEATTLE WA 98101	HSL

Fac Site ID: 430937
Cleanup Site ID: 3981
Site Status: Cleanup Started
Site Rank: 5 - Lowest Assessed Risk
Has Inst Control:
Responsible Unit: Northwest
County: King
Region: Northwest
Latitude: 47.6108593200054
Longitude: -122.3409144062
Latitude (OD): 47.610859
Longitude (OD): -122.340914
Current VCP:
Fac Site ID (OD): 430937
Cleanup Site ID (OD): 3981
Site Status (OD): Cleanup Started
Site Rank (OD): 5 - Lowest Assessed Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Site Name (OD): St Regis Hotel
Address (OD): 116 STEWART ST
City (OD): SEATTLE
ZIP code (OD): 98101
Past VCP: Yes
Location (OD): ""
(47.610859, -122.340914)
Alternate Site Names: PLYMOUTH ON STEWART APTS,SECOND & STEWART PROPERTY
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Air:
Sediment:
Soil: Confirmed Above Cleanup Levels
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

250 | **1 of 1** | **ENE** | **0.61 / 3,200.91** | **62.24 / -44** | **Block 52 East**
333 9TH AVE N
SEATTLE WA 98109 | **CSCSL**

Fac Site ID: 81725725
Cleanup Site ID: 14575
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6215316944073
Longitude: -122.339802186511
Site Name: Block 52 East
Address: 333 9TH AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Block 52 East
Address (OD): 333 9TH AVE N
City (OD): SEATTLE
Zipcode (OD): 98109-5187
Location (OD): ""
(47.621532, -122.339802)
Alternate Site Names: Analytical Resources Inc 333 Bldg
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 81725725
Cleanup SiteID(OD): 14575
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.339802
Latitude (OD): 47.621532

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater: Suspected
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Suspected
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Lead
Groundwater: Suspected
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Non-Halogenated Solvents
Groundwater: Suspected
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Mercury

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Suspected
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater: Suspected
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Halogenated Solvents
Groundwater:
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Other Non-Halogenated Organics
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

251	*1 of 1*	*NE*	*0.61 / 3,216.47*	*73.16 / -33*	***PCY Corp*** ***601 6TH AVE N*** ***SEATTLE WA 98109***	***CSCSL***

Fac Site ID: 36533718
Cleanup Site ID: 8889
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6248005958921
Longitude: -122.344630916648
Site Name: PCY Corp
Address: 601 6TH AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): PCY Corp
Address (OD): 601 6TH AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): "" (47.624801, -122.344631)
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 36533718
Cleanup SiteID(OD): 8889
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.344631
Latitude (OD): 47.624801

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

252	*1 of 1*	*E*	*0.61 / 3,224.00*	*87.34 / -18*	***Lenora Building*** ***2101 9TH AVE*** ***SEATTLE WA 98121***	***CSCSL***

Fac Site ID: 91413494
Cleanup Site ID: 1802
Site Status: Cleanup Started
Site Rank:
Current VCP: Yes
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6171673514249
Longitude: -122.337593187719
Site Name: Lenora Building
Address: 2101 9TH AVE
City: SEATTLE
Zip Code: 98121
Site Status (OD): Cleanup Started
Site Name (OD): Lenora Building
Address (OD): 2101 9TH AVE
City (OD): SEATTLE
Zipcode (OD): 98121
Location (OD): "" (47.617167, -122.337593)
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 91413494
Cleanup SiteID(OD): 1802
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.337593
Latitude (OD): 47.617167

Contaminants Detail(s)

Contaminant Name: Lead
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Other Non-Halogenated Organics
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

253	*1 of 2*	*ENE*	*0.62 / 3,259.01*	*64.11 / -42*	***Greiling Property*** ***222 WESTLAKE AVE N*** ***SEATTLE WA 98109***	***CSCSL***

Fac Site ID: 1197848
Cleanup Site ID: 1528
Site Status: Awaiting Cleanup
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6203621783771
Longitude: -122.338059329512

Responsible Unit: Northwest
Fac Site ID (OD): 1197848
Cleanup SiteID(OD): 1528
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.338059
Latitude (OD): 47.620362

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Name: Greiling Property
Address: 222 WESTLAKE AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Awaiting Cleanup
Site Name (OD): Greiling Property
Address (OD): 222 WESTLAKE AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.620362, -122.338059)
Alternate Site Names: CULINARY COURIERS INC,EVANGELICALS CONCERNED
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Non-Halogenated Solvents
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Non-Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

253	2 of 2	ENE	0.62 / 3,259.01	64.11 / -42	202 Westlake Office Building 202 WESTLAKE AVE N SEATTLE WA 98109	CSCSL

Fac Site ID: 19323
Cleanup Site ID: 11731
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6200193037335
Longitude: -122.338071000598
Site Name: 202 Westlake Office Building
Address: 202 WESTLAKE AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): 202 Westlake Office Building
Address (OD): 202 WESTLAKE AVE N
City (OD): SEATTLE
Zipcode (OD): 98109

Responsible Unit: Northwest
Fac Site ID (OD): 19323
Cleanup SiteID(OD): 11731
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.338071
Latitude (OD): 47.620019

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Location (OD): ""
(47.620019, -122.338071)
Alternate Site Names: 202 Westlake Office Building (Off-Property),202 Westlake Office Building (Property NFA)
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

254	*1 of 2*	*E*	*0.62 / 3,272.53*	*92.97 / -13*	***West 8th Building*** ***718 VIRGINIA ST & 2001 8TH AVE*** ***SEATTLE WA 98121***	***DELISTED SHWS***

Delisted Confirmed and Suspected Contaminated Sites

Fac Site ID: 800946
Cleanup Site ID: 484
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control:
Responsible Unit: Northwest
County: King
Region: Northwest
Latitude: 47.6157921921843
Longitude: -122.337373813603
Site Status (OD):
Site Name (OD):
Address (OD):
Location (OD):
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites
Original Source: CSCS
Record Date: 13-SEP-2021

Fac Site ID (OD):
Clnup Site ID (OD):
Site Rank (OD):
Respon Unit (OD):
Has Env Coven (OD):
County (OD):
Region (OD):
City (OD):
Zipcode (OD):
Latitude (OD):
Longitude (OD):

254	*2 of 2*	*E*	*0.62 / 3,272.53*	*92.97 / -13*	***West 8th Building*** ***718 VIRGINIA ST & 2001 8TH AVE*** ***SEATTLE WA 98121***	***CSCSL***

Fac Site ID: 800946
Cleanup Site ID: 484
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6157921921843
Longitude: -122.337373813603

Responsible Unit: Northwest
Fac Site ID (OD):
Cleanup SiteID(OD):
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD):
County (OD):
Region (OD):
Longitude (OD):
Latitude (OD):

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Name: West 8th Building
Address: 718 VIRGINIA ST & 2001 8TH AVE
City: SEATTLE
Zip Code: 98121
Site Status (OD):
Site Name (OD):
Address (OD):
City (OD):
Zipcode (OD):
Location (OD):
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites

Contaminants Detail(s)

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Metals Priority Pollutants
Groundwater:
Surfacewater:
Soil: Remediated
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Remediated
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

255	1 of 2	NNE	0.63 / 3,323.84	84.07 / -22	**Chevron Vacant Site** **707 TAYLOR AVE N 700 5TH AVE N** **SEATTLE WA 98109**	CSCSL

Fac Site ID: 24939396
Cleanup Site ID: 8452
Site Status: Cleanup Started
Site Rank: 3 - Moderate Risk
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6258397570506
Longitude: -122.346907707334
Site Name: Chevron Vacant Site
Address: 707 TAYLOR AVE N 700 5TH AVE N
City: SEATTLE
Zip Code: 98109

Responsible Unit: Northwest
Fac Site ID (OD): 24939396
Cleanup SiteID(OD): 8452
Site Rank (OD): 3 - Moderate Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.346908
Latitude (OD): 47.62584

Site Status (OD):	Cleanup Started
Site Name (OD):	Chevron Vacant Site
Address (OD):	707 TAYLOR AVE N / 700 5TH AVE N
City (OD):	SEATTLE
Zipcode (OD):	98109
Location (OD):	"" (47.62584, -122.346908)
Alternate Site Names:	ABC TOWING RYDER TRUCK,Hampton Inn
Data Source(s):	Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name:	Petroleum-Gasoline
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Benzene
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Non-Halogenated Solvents
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Non-Halogenated Solvents
Contaminant Media:	Soil
Contaminant Status:	Confirmed Above Cleanup Levels

Contaminant:	Benzene
Contaminant Media:	Soil
Contaminant Status:	Confirmed Above Cleanup Levels

Contaminant:	Petroleum-Gasoline
Contaminant Media:	Soil
Contaminant Status:	Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
255	2 of 2	NNE	0.63 / 3,323.84	84.07 / -22	**Chevron Vacant Site** **707 TAYLOR AVE N 700 5TH AVE N** **SEATTLE WA 98109**	HSL

Fac Site ID:	24939396	**Fac Site ID (OD):**	24939396
Cleanup Site ID:	8452	**Cleanup Site ID (OD):**	8452
Site Status:	Cleanup Started	**Site Status (OD):**	Cleanup Started
Site Rank:	3 - Moderate Risk	**Site Rank (OD):**	3 - Moderate Risk
Has Inst Control:		**Has Env Coven (OD):**	
Responsible Unit:	Northwest	**Respon Unit (OD):**	Northwest
County:	King	**County (OD):**	King
Region:	Northwest	**Region (OD):**	Northwest
Latitude:	47.6258397570506	**Site Name (OD):**	Chevron Vacant Site
Longitude:	-122.346907707334	**Address (OD):**	707 TAYLOR AVE N / 700 5TH AVE N
Latitude (OD):	47.62584	**City (OD):**	SEATTLE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Longitude (OD): -122.346908 **ZIP code (OD):** 98109
Current VCP: **Past VCP:**
Location (OD): ""
(47.62584, -122.346908)
Alternate Site Names: ABC TOWING RYDER TRUCK,Hampton Inn
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Non-Halogenated Solvents **Sediment:**
Groundwater: **Soil:** Confirmed Above Cleanup Levels
Surfacewater: **Bedrock:**
Air:

Contaminant Name: Benzene **Sediment:**
Groundwater: **Soil:** Confirmed Above Cleanup Levels
Surfacewater: **Bedrock:**
Air:

Contaminant Name: Petroleum-Gasoline **Sediment:**
Groundwater: **Soil:** Confirmed Above Cleanup Levels
Surfacewater: **Bedrock:**
Air:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline **Contaminant Media:** Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene **Contaminant Media:** Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Non-Halogenated Solvents **Contaminant Media:** Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

256 | **1 of 1** | **ENE** | **0.63 / 3,328.29** | **64.86 / -41** | **Seattle City ROW behind 222 Westlake N ALLEY 222 WESTLAKE & 219 TERRY AVES N SEATTLE WA 98109** | **CSCSL**

Fac Site ID: 5972599 **Responsible Unit:** Northwest
Cleanup Site ID: 3736 **Fac Site ID (OD):** 5972599
Site Status: Awaiting Cleanup **Cleanup SiteID(OD):** 3736
Site Rank: **Site Rank (OD):**
Current VCP: **Has Env Coven (OD):**
Past VCP: **Respon Unit (OD):** Northwest
Has Inst Control: **County (OD):** King
County: King **Region (OD):** Northwest
Region: Northwest **Longitude (OD):** -122.337845
Latitude: 47.6202175449037 **Latitude (OD):** 47.620218
Longitude: -122.337844752791
Site Name: Seattle City ROW behind 222 Westlake N
Address: ALLEY 222 WESTLAKE & 219 TERRY AVES N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Awaiting Cleanup
Site Name (OD): Seattle City ROW behind 222 Westlake N
Address (OD): ALLEY 222 WESTLAKE & 219 TERRY AVES N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.620218, -122.337845)
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Non-Halogenated Solvents
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Non-Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

257	*1 of 41*	*ESE*	*0.64 / 3,374.27*	*125.42 / 20*	***SEATTLE ARMY TERMINAL*** ***SEATTLE WA***	***FUDS***

FUDS Property No: F10WA0417
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=53959
FUDS INST ID: WA09799F337700
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: THE SITE WAS USED FOR RECEIVING, TEMPORARY STORAGE, AND SHIPMENT OF MILITARY MATERIAL TO AND FROM OVERSEAS.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
257	2 of 41	ESE	0.64 / 3,374.27	125.42 / 20	JEFFERSON PK VEHICLE STOR SEATTLE WA	FUDS

FUDS Property No: F10WA0340
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=60055
FUDS INST ID: WA09799F331000
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: The site was formerly used by the Dept of the Army during the mid 1940's. The property was acquired in 1945 for storage of motor
vehicles. The lease for 11.53 acres leased from the city of
Seattle terminated in 1947, and the remaining 41.96 acres

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
257	3 of 41	ESE	0.64 / 3,374.27	125.42 / 20	N/WEST RELAY (AUX) STA SEATTLE WA	FUDS

FUDS Property No: F10WA0387
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=60075
FUDS INST ID: WA09799F335100
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Metadata ID:
Feature Desc:
Property History: The site was acquired by permit from King Broadcasting Company and was used as a relay station from 1959-1962. The site was transferred to the U.S. Coast Guard when the permit was terminated in 1963, and the site is currently under the jurisdict

---

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
257	4 of 41	ESE	0.64 / 3,374.27	125.42 / 20	MASSACHUSETTS STREET OPEN STORAGE SITE SEATTLE WA	FUDS

FUDS Property No: F10WA0141
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=57182
FUDS INST ID: WA09799F837500
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: PROPERTY WAS ACQUIRED IN 1943 BY PERMIT AND LEASE; USED BY THE SEATTLE PORT OF EMBARKATION FOR AN OPEN STORAGE YARD. IMPROVEMENTS TO THE SITE INCLUDED GRAVELING AND ROLLING, PLANKING OF RAILROAD CR OSSING, GRADING AND CONCRETING, INSTALLATION OF

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
257	5 of 41	ESE	0.64 / 3,374.27	125.42 / 20	N SEATTLE NIKE 03 SEATTLE WA	FUDS

FUDS Property No: F10WA0093
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=59976
FUDS INST ID: WA09799F319600
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: CONTROL SITE ACQUIRED BETWEEN 1954-1959, DISPOSED OF BETWEEN 1966-1969. KING COUNTY OBTAINED PROPERTY AND CREATED HORIZON VIEW PARK. LAUNCH SITE ACQUIRED 1954. DOD RETAINED FEE LAND; LICENSED TO FE DERAL AGENCIES AND LOCAL COUNTY GOVERNMENT. FAMI

257	6 of 41	ESE	0.64 / 3,374.27	125.42 / 20	OLYMPIC GOLF COURSE AAA SEATTLE WA	FUDS

FUDS Property No: F10WA0114
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=56864
FUDS INST ID: WA09799F836500
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: SITE WAS A FORMER ANTI-AIRCRAFT ARTILLERY POSITION, PART OF SEATTLE AIR DEFENSE SYSTEM. CONSTRUCTED FOR THE U.S. ARMY BETWEEN 1952-1955, USED AS A TROOP TRAINING AND MANUEUVER AREA. FORMER BIVOUAC AREA AND GUN EMPLACEMENT PORTION HAVE BEEN REPLAC

257	7 of 41	ESE	0.64 / 3,374.27	125.42 / 20	CAMP GEORGE JORDAN SEATTLE WA	FUDS

FUDS Property No: F10WA0259
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=53982
FUDS INST ID: WA09799F323600
Status: Properties without projects
SDS ID:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

NPL Status Code:	Not on the NPL
Eligibility:	Eligible
Site Eligib:	
Current Owner:	
Has Project:	No
DOD FUDS Pro:	
Project Required:	No
No Further Action:	
Congressional District:	07
EPA Region:	10
County:	KING
Latitude:	47.61222222
Longitude:	-122.33833333
Fiscal year:	2019
USACE Division:	NWD
USACE District:	Kansas City District (NWK)
Shape Area:	
Shape Len:	
Centroid Latitude:	
Centroid Longitude:	
Media ID:	
Metadata ID:	
Feature Desc:	
Property History:	The 20.98 acre site was acquired under five leases (14.75 acres) and five permits (6.23 acres) between 1942 and 1947. The facility served as a sub-installation of the Seattle Port of Embarkation used to house Army troops. The property was declared excess

257	8 of 41	ESE	0.64 / 3,374.27	125.42 / 20	COLLEGE ST OPEN STOR SITE SEATTLE WA	FUDS

FUDS Property No:	F10WA0268
EMS Map Link:	https://fudsportal.usace.army.mil/ems/inventory/map/map?id=60020
FUDS INST ID:	WA09799F324500
Status:	Properties without projects
SDS ID:	
NPL Status Code:	Not on the NPL
Eligibility:	Eligible
Site Eligib:	
Current Owner:	
Has Project:	No
DOD FUDS Pro:	
Project Required:	No
No Further Action:	
Congressional District:	07
EPA Region:	10
County:	KING
Latitude:	47.61222222
Longitude:	-122.33833333
Fiscal year:	2019
USACE Division:	NWD
USACE District:	Kansas City District (NWK)
Shape Area:	
Shape Len:	
Centroid Latitude:	
Centroid Longitude:	
Media ID:	
Metadata ID:	
Feature Desc:	
Property History:	THE COLLEGE STREET OPEN STORAGE, ACQUIRED IN 1943 BY THE WAR DEPARTMENT CONSISTED OF 1.77 ACRES USED FOR STORAGE WAS RELEASED AND TERMINATED ON JUNE 1,1947.

257	9 of 41	ESE	0.64 / 3,374.27	125.42 / 20	SEATTLE DRUM STORAGE SEATTLE WA	FUDS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

FUDS Property No: F10WA0433
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=60100
FUDS INST ID: WA09799F338600
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: The site was used for the storage of gasoline and oil containers.

257	10 of 41	ESE	0.64 / 3,374.27	125.42 / 20	SEATTLE NAVAL INDUSTRIAL RESERVE SHIPYARD PLANT A SEATTLE WA	FUDS

FUDS Property No: F10WA0435
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=60102
FUDS INST ID: WA09799F338800
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: The site was used for building and launching destroyers.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
257	11 of 41	ESE	0.64 / 3,374.27	125.42 / 20	LAKE WA SHIP CAN STORAGE SEATTLE WA	FUDS

FUDS Property No: F10WA0346
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=60052
FUDS INST ID: WA09799F331600
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: The property was acquired in 1944 as an open storage yard.
The leases were terminated in 1946 and 1947.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
257	12 of 41	ESE	0.64 / 3,374.27	125.42 / 20	HQS SEATTLE REGION SEATTLE WA	FUDS

FUDS Property No: F10WA0339
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=54982
FUDS INST ID: WA09799F330900
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Feature Desc:
Property History: Most of the property was acquired in 1945, with additional portions acquired in 1947 and 1959. The property was used as a cold storage warehouse. The 0.02 acre permit was released in 1948, and in 1960 the plant was placed in inactive status.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
257	13 of 41	ESE	0.64 / 3,374.27	125.42 / 20	GUN BATTERY SITE GW9-41 SEATTLE WA	FUDS

FUDS Property No: F10WA0116
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=57185
FUDS INST ID: WA09799F836600
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: SITE WAS ACQUIRED FOR DEPARTMENT OF THE ARMY DURING THE EARLY 1940'S AND USED PRIMARILY FOR AIR DEFENSE AS PART OF THE SEATTLE AIR DEFENSE SYSTEM. SITE CONTAINED 13 STRUCTURES WHICH HAVE SINCE BEEN REMOVED AND IS NOW A BUSINESS DISTRICT USED EXC

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
257	14 of 41	ESE	0.64 / 3,374.27	125.42 / 20	SEATTLE TROOP TRA SIDING SEATTLE WA	FUDS

FUDS Property No: F10WA0443
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=54071
FUDS INST ID: WA09799F339600
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: THIS INSTALLATION WAS AN AUXILIARY OR A SUB BASE TO THE SEATTLE PORT OF EMBARKATION, FOR THE FORT LAWTON STAGING AREA.

257	15 of 41	ESE	0.64 / 3,374.27	125.42 / 20	SEATTLE PORT EMBARKATION SEATTLE WA	FUDS

FUDS Property No: F10WA0437
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=60098
FUDS INST ID: WA09799F339000
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: This site was formerly used as an auxiliary fire station.

257	16 of 41	ESE	0.64 / 3,374.27	125.42 / 20	SEATTLE WAC HOUSING SITE SEATTLE WA	FUDS

FUDS Property No: F10WA0445
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=54072
FUDS INST ID: WA09799F339800
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Congressional District:	07
EPA Region:	10
County:	KING
Latitude:	47.61222222
Longitude:	-122.33833333
Fiscal year:	2019
USACE Division:	NWD
USACE District:	Kansas City District (NWK)
Shape Area:	
Shape Len:	
Centroid Latitude:	
Centroid Longitude:	
Media ID:	
Metadata ID:	
Feature Desc:	
Property History:	THE INSTALLATION WAS USED AS A HOUSING SITE

257	17 of 41	ESE	0.64 / 3,374.27	125.42 / 20	U.S. ENGINEER WAREHOUSE (FREMONT) SEATTLE WA	FUDS

FUDS Property No:	F10WA0129
EMS Map Link:	https://fudsportal.usace.army.mil/ems/inventory/map/map?id=57162
FUDS INST ID:	WA09799F837300
Status:	Properties without projects
SDS ID:	
NPL Status Code:	Not on the NPL
Eligibility:	Eligible
Site Eligib:	
Current Owner:	
Has Project:	No
DOD FUDS Pro:	
Project Required:	No
No Further Action:	
Congressional District:	07
EPA Region:	10
County:	KING
Latitude:	47.61222222
Longitude:	-122.33833333
Fiscal year:	2019
USACE Division:	NWD
USACE District:	Kansas City District (NWK)
Shape Area:	
Shape Len:	
Centroid Latitude:	
Centroid Longitude:	
Media ID:	
Metadata ID:	
Feature Desc:	
Property History:	SITE ACQUIRED IN 1942 TO PROVIDE STORAGE AND SHOP REQUIREMENTS FOR THE SEATTLE DISTRICT, COE. PROPERTY PREVIOUSLY USED BY CITY OF SEATTLE AS A STREETCAR BARN AND YARD. A ONE-STORY BRICK BUILDING, P AVED STORAGE AREA AND GRAVELED HARD STANDINGS WERE C

257	18 of 41	ESE	0.64 / 3,374.27	125.42 / 20	GREAT NORTHERN PIER 88 SEATTLE WA	FUDS

FUDS Property No:	F10WA0576
EMS Map Link:	https://fudsportal.usace.army.mil/ems/inventory/map/map?id=55164
FUDS INST ID:	WA09799F932700
Status:	Properties without projects
SDS ID:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

NPL Status Code:	Not on the NPL
Eligibility:	Eligible
Site Eligib:	
Current Owner:	
Has Project:	No
DOD FUDS Pro:	
Project Required:	No
No Further Action:	
Congressional District:	07
EPA Region:	10
County:	KING
Latitude:	47.61222222
Longitude:	-122.33833333
Fiscal year:	2019
USACE Division:	NWD
USACE District:	Kansas City District (NWK)
Shape Area:	
Shape Len:	
Centroid Latitude:	
Centroid Longitude:	
Media ID:	
Metadata ID:	
Feature Desc:	
Property History:	The lease was transferred to the Navy in 1946. The Navy terminated the lease in 1950. The property is presently owned by the Port of Seattle.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
257	19 of 41	ESE	0.64 / 3,374.27	125.42 / 20	AIR FORCE PLANT NO. 17 SEATTLE WA	FUDS

FUDS Property No:	F10WA0236
EMS Map Link:	https://fudsportal.usace.army.mil/ems/inventory/map/map?id=56835
FUDS INST ID:	WA09799F321400
Status:	Properties without projects
SDS ID:	
NPL Status Code:	Not on the NPL
Eligibility:	Eligible
Site Eligib:	
Current Owner:	
Has Project:	No
DOD FUDS Pro:	
Project Required:	No
No Further Action:	
Congressional District:	07
EPA Region:	10
County:	KING
Latitude:	47.61222222
Longitude:	-122.33833333
Fiscal year:	2019
USACE Division:	NWD
USACE District:	Kansas City District (NWK)
Shape Area:	
Shape Len:	
Centroid Latitude:	
Centroid Longitude:	
Media ID:	
Metadata ID:	
Feature Desc:	
Property History:	SITE OF THE FORMER AIR FORCE PLANT NUMBER 17 (AFP 17) WAS ORIGINALLY A PORTION OF BOEING AIRPLANE COMPANY PLANCOR 1577 AND BOEING FIELD (F10WA025400).LEASES WERE TERMINATED AFTER WW II; SITE REACQU IRED IN THE EARLY 1950'S AND CONTINUED TO BE USE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
257	20 of 41	ESE	0.64 / 3,374.27	125.42 / 20	SEATTLE NAVAL INDUSTRIAL RESERVE SHIPYARD PLANT B SEATTLE WA	FUDS

FUDS Property No: F10WA0436
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=60099
FUDS INST ID: WA09799F338900
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: The site was used to outfit Navy destroyers that were built and launched at Plant A.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
257	21 of 41	ESE	0.64 / 3,374.27	125.42 / 20	SEATTLE SAL SEG SITE SEATTLE WA	FUDS

FUDS Property No: F10WA0438
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=60096
FUDS INST ID: WA09799F339100
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Property History: The site was formerly used as a salvage segregation site.

---

257 | **22 of 41** | **ESE** | **0.64 / 3,374.27** | **125.42 / 20** | **ACS CABLE STORAGE AREA**
SEATTLE WA | **FUDS**

FUDS Property No: F10WA0573
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=54917
FUDS INST ID: WA09799F932400
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: The Signal Corps used the site for cable storage. Seven small wood-frame buildings were constructed. In 1952, the lease was terminated.

---

257 | **23 of 41** | **ESE** | **0.64 / 3,374.27** | **125.42 / 20** | **ARGO REDISTRIBUTION SITE**
SEATTLE WA | **FUDS**

FUDS Property No: F10WA0242
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=56797
FUDS INST ID: WA09799F322000
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: SITE WAS ACQUIRED BY THE WAR DEPARTMENT IN 1943 UNDER THREE PERMITS, FOUR LEASES; USED BY THE ARMY AS AN OPEN STORAGE YARD AND REDISTRIBUTION CENTER. IMPROVEMENTS TO THE SITE INCLUDED CONSTRUCTION OF A CARPENTER SHOP, GUARD TOWER, WATER AND ELECT

257	24 of 41	ESE	0.64 / 3,374.27	125.42 / 20	ALASKA COMMUNICATION SYS SEATTLE WA	FUDS

FUDS Property No: F10WA0241
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=56832
FUDS INST ID: WA09799F321900
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: SITE WAS ACQUIRED THROUGH CONDEMNATION BY THE DOD BETWEEN 1942-1945. PROPERTY WAS USED BY THE ARMY SIGNAL CORPS AS A TRANSMITTING STATION SERVING THE TERRITORY OF ALASKA. CONSTRUCTED RADIO ANTENNAE , TUNING HUTS, UNDERGROUND TRANSMITTER BUILDING.

257	25 of 41	ESE	0.64 / 3,374.27	125.42 / 20	HOLGATE ST SALVAGE SITE SEATTLE WA	FUDS

FUDS Property No: F10WA0338
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=60056
FUDS INST ID: WA09799F330800
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: The property was acquired in 1942 and declared excess in 1945. The possession was returned to the city of Seattle in 1945.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
257	26 of 41	ESE	0.64 / 3,374.27	125.42 / 20	BOEING FIELD SEATTLE WA	FUDS

FUDS Property No: F10WA0254
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=60004
FUDS INST ID: WA09799F323200
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: BOEING FIELD WAS INITIALLY ACQUIRED BY THE WAR DEPT. FOR USE BY THE ARMY AIR CORPS. DURING THE PERIOD 1941 TO 1947, THE FACILITY WAS AN ACTIVE COMPONENT OF THE AREA'S DEFENSES. THE BOEING MANUFACTURED AND TESTED B-17 AND B-29 AIRCRAFT AT THE SITE.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
257	27 of 41	ESE	0.64 / 3,374.27	125.42 / 20	SEATTLE BEACON TRAN SITE SEATTLE WA	FUDS

FUDS Property No: F10WA0419
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=60108
FUDS INST ID: WA09799F337900
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Eligibility:	Eligible
Site Eligib:	
Current Owner:	
Has Project:	No
DOD FUDS Pro:	
Project Required:	No
No Further Action:	
Congressional District:	07
EPA Region:	10
County:	KING
Latitude:	47.61222222
Longitude:	-122.33833333
Fiscal year:	2019
USACE Division:	NWD
USACE District:	Kansas City District (NWK)
Shape Area:	
Shape Len:	
Centroid Latitude:	
Centroid Longitude:	
Media ID:	
Metadata ID:	
Feature Desc:	
Property History:	This site was formerly used as a navigation direction marker for the transmission of signals to vessels entering the harbor area from 1944 to 1950.

257	28 of 41	ESE	0.64 / 3,374.27	125.42 / 20	SEATTLE TUG&BARGE MOORING SEATTLE WA	FUDS

FUDS Property No:	F10WA0444
EMS Map Link:	https://fudsportal.usace.army.mil/ems/inventory/map/map?id=60095
FUDS INST ID:	WA09799F339700
Status:	Properties without projects
SDS ID:	
NPL Status Code:	Not on the NPL
Eligibility:	Eligible
Site Eligib:	
Current Owner:	
Has Project:	No
DOD FUDS Pro:	
Project Required:	No
No Further Action:	
Congressional District:	07
EPA Region:	10
County:	KING
Latitude:	47.61222222
Longitude:	-122.33833333
Fiscal year:	2019
USACE Division:	NWD
USACE District:	Kansas City District (NWK)
Shape Area:	
Shape Len:	
Centroid Latitude:	
Centroid Longitude:	
Media ID:	
Metadata ID:	
Feature Desc:	
Property History:	THE SITE WAS USED FOR STORAGE AND MOORAGE PURPOSES

257	29 of 41	ESE	0.64 / 3,374.27	125.42 / 20	US DIST ENG INT STOR SITE SEATTLE WA	FUDS

FUDS Property No:	F10WA0467
EMS Map Link:	https://fudsportal.usace.army.mil/ems/inventory/map/map?id=60109

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

FUDS INST ID:	WA09799F341700
Status:	Properties without projects
SDS ID:	
NPL Status Code:	Not on the NPL
Eligibility:	Eligible
Site Eligib:	
Current Owner:	
Has Project:	No
DOD FUDS Pro:	
Project Required:	No
No Further Action:	
Congressional District:	07
EPA Region:	10
County:	KING
Latitude:	47.61222222
Longitude:	-122.33833333
Fiscal year:	2019
USACE Division:	NWD
USACE District:	Kansas City District (NWK)
Shape Area:	
Shape Len:	
Centroid Latitude:	
Centroid Longitude:	
Media ID:	
Metadata ID:	
Feature Desc:	
Property History:	THE SITE WAS FORMERLY USED BY THE SEATTLE DISTRICT ENGINEER AS A STORAGE SITE FROM 1942 TO 1948.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
257	30 of 41	ESE	0.64 / 3,374.27	125.42 / 20	AUTOMATIC WEAPONS BATTERY HEADQUARTERS SW9-29 SEATTLE WA	FUDS

FUDS Property No:	F10WA0587
EMS Map Link:	https://fudsportal.usace.army.mil/ems/inventory/map/map?id=55148
FUDS INST ID:	WA09799F933800
Status:	Properties without projects
SDS ID:	
NPL Status Code:	Not on the NPL
Eligibility:	Eligible
Site Eligib:	
Current Owner:	
Has Project:	No
DOD FUDS Pro:	
Project Required:	No
No Further Action:	
Congressional District:	07
EPA Region:	10
County:	KING
Latitude:	47.61222222
Longitude:	-122.33833333
Fiscal year:	2019
USACE Division:	NWD
USACE District:	Kansas City District (NWK)
Shape Area:	
Shape Len:	
Centroid Latitude:	
Centroid Longitude:	
Media ID:	
Metadata ID:	
Feature Desc:	
Property History:	The undeveloped property was leased from the C. B. Dodge Company in the early 1940's. The Army constructed several office buildings to serve as the HQ for the 39th AAA Brigade. In 1944, the property was transferred to the Navy for use by a grou

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
257	31 of 41	ESE	0.64 / 3,374.27	125.42 / 20	US DIST ENG WAREHOUSE SEATTLE WA	FUDS

FUDS Property No:	F10WA0468
EMS Map Link:	https://fudsportal.usace.army.mil/ems/inventory/map/map?id=60107
FUDS INST ID:	WA09799F341800
Status:	Properties without projects
SDS ID:	
NPL Status Code:	Not on the NPL
Eligibility:	Eligible
Site Eligib:	
Current Owner:	
Has Project:	No
DOD FUDS Pro:	
Project Required:	No
No Further Action:	
Congressional District:	07
EPA Region:	10
County:	KING
Latitude:	47.61222222
Longitude:	-122.33833333
Fiscal year:	2019
USACE Division:	NWD
USACE District:	Kansas City District (NWK)
Shape Area:	
Shape Len:	
Centroid Latitude:	
Centroid Longitude:	
Media ID:	
Metadata ID:	
Feature Desc:	
Property History:	THE SITE WAS FORMERLY USED AS A TRANSIT WAREHOUSE FOR THE ALASKA COMMUNICATION SYSTEM.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
257	32 of 41	ESE	0.64 / 3,374.27	125.42 / 20	BOEING SEATTLE PLANT #12 SEATTLE WA	FUDS

FUDS Property No:	F10WA0255
EMS Map Link:	https://fudsportal.usace.army.mil/ems/inventory/map/map?id=60006
FUDS INST ID:	WA09799F323300
Status:	Properties without projects
SDS ID:	
NPL Status Code:	Not on the NPL
Eligibility:	Eligible
Site Eligib:	
Current Owner:	
Has Project:	No
DOD FUDS Pro:	
Project Required:	No
No Further Action:	
Congressional District:	07
EPA Region:	10
County:	KING
Latitude:	47.61222222
Longitude:	-122.33833333
Fiscal year:	2019
USACE Division:	NWD
USACE District:	Kansas City District (NWK)
Shape Area:	
Shape Len:	
Centroid Latitude:	
Centroid Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Media ID:
Metadata ID:
Feature Desc:
Property History: A TOTAL OF 34.66 ACRES WERE ACQUIRED FOR THE DEPT.OF THE ARMY, QUARTERMASTER CORPS, BY CONDEMNATION AND PURCHASE, IN 1942-1943.THE FACILITY CONSISTED OF 3 WAREHOUSES PARKING AND ACCESS AREAS AND RELATED STRUCTURES, WAREHOUSES WERE USED FOR STORAGE OF ALL

257	33 of 41	ESE	0.64 / 3,374.27	125.42 / 20	NG GD FAC PIER 91 SEATTLE SEATTLE WA	FUDS

FUDS Property No: F10WA0398
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=54707
FUDS INST ID: WA09799F336000
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: The site of 24.75 acres was part of a U.S. Naval Supply Depot consisting of 242.97 acres acquired in 1942. The site was transferred from the Navy to the Army in 1967. In 1971, 15 acres were conveyed to the State of Washington and are the locati

---

257	34 of 41	ESE	0.64 / 3,374.27	125.42 / 20	ISAACSON IRON WORKS SEATTLE WA	FUDS

FUDS Property No: F10WA0536
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=60123
FUDS INST ID: WA09799F344000
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: THE ISSSACSON IRON WORKS, PLANT NO 2 WAS CONSTRUCTED AS A STEEL FORGE PLANT FOR THE MANUFACTURING, TREATING AND MACHINING OF HEAVY EQUIPMENT FOR THE NAVY.

257	35 of 41	ESE	0.64 / 3,374.27	125.42 / 20	LAKE WA SHIP CAN MIL RES SEATTLE WA	FUDS

FUDS Property No: F10WA0345
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=53965
FUDS INST ID: WA09799F331500
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: The site was acquired in 1943 from the Alaskan Steamship Company for a storage and terminal facility. The property was transferred to the Lake Washington Ship Canal and Locks Civil Project in 1954.

257	36 of 41	ESE	0.64 / 3,374.27	125.42 / 20	SEATTLE STOCKPILE STORAGE SEATTLE WA	FUDS

FUDS Property No: F10WA0440
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=57171
FUDS INST ID: WA09799F339300
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Current Owner:	
Has Project:	No
DOD FUDS Pro:	
Project Required:	No
No Further Action:	
Congressional District:	07
EPA Region:	10
County:	KING
Latitude:	47.61222222
Longitude:	-122.33833333
Fiscal year:	2019
USACE Division:	NWD
USACE District:	Kansas City District (NWK)
Shape Area:	
Shape Len:	
Centroid Latitude:	
Centroid Longitude:	
Media ID:	
Metadata ID:	
Feature Desc:	
Property History:	

257	37 of 41	ESE	0.64 / 3,374.27	125.42 / 20	SEATTLE TRAN LAB CAM SITE SEATTLE WA	FUDS

FUDS Property No:	F10WA0441
EMS Map Link:	https://fudsportal.usace.army.mil/ems/inventory/map/map?id=57156
FUDS INST ID:	WA09799F339400
Status:	Properties without projects
SDS ID:	
NPL Status Code:	Not on the NPL
Eligibility:	Eligible
Site Eligib:	
Current Owner:	
Has Project:	No
DOD FUDS Pro:	
Project Required:	No
No Further Action:	
Congressional District:	07
EPA Region:	10
County:	KING
Latitude:	47.61222222
Longitude:	-122.33833333
Fiscal year:	2019
USACE Division:	NWD
USACE District:	Kansas City District (NWK)
Shape Area:	
Shape Len:	
Centroid Latitude:	
Centroid Longitude:	
Media ID:	
Metadata ID:	
Feature Desc:	
Property History:	THE SITE WAS USED AS A TRANNNSIENT LABOR CAMMP BY THE 6TH ARMY.

257	38 of 41	ESE	0.64 / 3,374.27	125.42 / 20	Western Processing KENT WA	FUDS

FUDS Property No:	F10WA0095
EMS Map Link:	https://fudsportal.usace.army.mil/ems/inventory/map/map?id=56865
FUDS INST ID:	WA09799F319800
Status:	Properties without projects
SDS ID:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: SITE LISTED ON THE NPL BECAUSE OF POST DOD OWNER ACTIVITIES. LEASE ON TRACT A100 TERMINATED IN 1960, SOLD TO WESTERN PROCESSING IN 1961. BETWEEN THEN AND 1983, SITE USED FOR TREATING, RECYCLING, STORING INDUSTRIAL WASTE PRODUCTS. EXTENSIVE FILLIN

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
257	39 of 41	ESE	0.64 / 3,374.27	125.42 / 20	SEATTLE AREA DISPOSAL CEN SEATTLE WA	FUDS

FUDS Property No: F10WA0415
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=60084
FUDS INST ID: WA09799F337500
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: THE DISPOSAL CENTER CONSISTED OF 4.88 ACRES, PERMIT FOR 1.62 ACRES GRANTED BY THE CITY OF SEATTLE, IN 1945 AND 3.26 ACRES ACQUIRED FROM OREGON-WASHINGTON RAILROAD AND NAVIGATION CO, AND THE UNION PACIFIC RAILROAD CO. USED FOR BARREL STORAGE. AUG.1 1959 P

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
257	40 of 41	ESE	0.64 / 3,374.27	125.42 / 20	TODD-SEATTLE DRYDOCK INC SEATTLE WA	FUDS

FUDS Property No: F10WA0550
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=54062
FUDS INST ID: WA09799F345400
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: DURING WORLD WAR II, THE SITE WAS UTILIZED BY THE NAVY FOR SHIP BUILDING AND SHIP REPAIR.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
257	41 of 41	ESE	0.64 / 3,374.27	125.42 / 20	SEATTLE AUT MAINT SHOP SEATTLE WA	FUDS

FUDS Property No: F10WA0418
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map/map?id=60082
FUDS INST ID: WA09799F337800
Status: Properties without projects
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: No
DOD FUDS Pro:
Project Required: No
No Further Action:
Congressional District: 07
EPA Region: 10
County: KING
Latitude: 47.61222222
Longitude: -122.33833333
Fiscal year: 2019
USACE Division: NWD
USACE District: Kansas City District (NWK)
Shape Area:
Shape Len:
Centroid Latitude:
Centroid Longitude:
Media ID:
Metadata ID:
Feature Desc:
Property History: THIS SITE WAS USED BY THE D.O.D. FOR STORAGE, MAINTENANCE,

AND REFUELING OF MILITARY VEHICLES.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
258	1 of 1	SE	0.65 / 3,414.65	12.26 / -93	Seattle DOT Promenade & Overlook Walk 1500 1524 1528 ALASKAN WAY SEATTLE WA 98101	CSCSL

Fac Site ID: 81775
Cleanup Site ID: 14871
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6085407022917
Longitude: -122.343065205358
Site Name: Seattle DOT Promenade & Overlook Walk
Address: 1500 1524 1528 ALASKAN WAY
City: SEATTLE
Zip Code: 98101
Site Status (OD):
Site Name (OD):
Address (OD):
City (OD):
Zipcode (OD):
Location (OD):
Alternate Site Names: SDOT Harborscape Building,SDOT Whetzel Property
Data Source(s): Confirmed and Suspected Contaminated Sites

Responsible Unit: Northwest
Fac Site ID (OD):
Cleanup SiteID(OD):
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD):
County (OD):
Region (OD):
Longitude (OD):
Latitude (OD):

Contaminants Detail(s)

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Halogenated Solvents
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Lead
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Metals - Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

---

259 | ***1 of 1*** | ***ENE*** | ***0.65 / 3,433.49*** | ***66.67 / -39*** | ***United Furniture Refinishers***
219 TERRY AVE N
SEATTLE WA 98109 | ***CSCSL***

Fac Site ID:	16345761	***Responsible Unit:***	Northwest
Cleanup Site ID:	2607	***Fac Site ID (OD):***	16345761
Site Status:	Cleanup Started	***Cleanup SiteID(OD):***	2607
Site Rank:		***Site Rank (OD):***	
Current VCP:		***Has Env Coven (OD):***	
Past VCP:	Yes	***Respon Unit (OD):***	Northwest
Has Inst Control:		***County (OD):***	King
County:	King	***Region (OD):***	Northwest
Region:	Northwest	***Longitude (OD):***	-122.33726
Latitude:	47.6202	***Latitude (OD):***	47.6202
Longitude:	-122.33726		

Site Name: United Furniture Refinishers
Address: 219 TERRY AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): United Furniture Refinishers
Address (OD): 219 TERRY AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.6202, -122.33726)
Alternate Site Names: RELOCATION SVC INC
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Suspected
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:

Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

260 | ***1 of 1*** | ***ENE*** | ***0.65 / 3,446.36*** | ***53.44 / -52*** | ***Bayless Book Bindery 427 9TH AVE N SEATTLE WA 98109*** | ***CSCSL***

Fac Site ID: 35788635
Cleanup Site ID: 12533
Site Status: Cleanup Started
Site Rank:
Current VCP: Yes
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6227707823437
Longitude: -122.340094052045
Site Name: Bayless Book Bindery
Address: 427 9TH AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Bayless Book Bindery
Address (OD): 427 9TH AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): "" (47.622771, -122.340094)
Alternate Site Names: Ivey Imaging LLC Seattle,PHOTOBITION 9TH AVE
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 35788635
Cleanup SiteID(OD): 12533
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.340094
Latitude (OD): 47.622771

Contaminants Detail(s)

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Halogenated Solvents
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

261 | **1 of 1** | **ENE** | **0.65 / 3,446.84** | **56.78 / -49** | **Block 40 East & West Westlake & Terry**
320 WESTLAKE AVE N
SEATTLE WA 98109 | **CSCSL**

Fac Site ID: 602477
Cleanup Site ID: 333
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6211763786399
Longitude: -122.338176982636
Site Name: Block 40 East & West Westlake & Terry
Address: 320 WESTLAKE AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Block 40 East & West Westlake & Terry
Address (OD): 320 WESTLAKE AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): "" (47.621176, -122.338177)
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Pollution Liability Ins Agcy
Fac Site ID (OD): 602477
Cleanup SiteID(OD): 333
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.338177
Latitude (OD): 47.621176

Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

262 | **1 of 1** | **NE** | **0.65 / 3,449.87** | **55.33 / -50** | **Broad Street Alignment Contaminated Fill**
DEXTER AVE N & MERCER ST
SEATTLE WA 98102 | **CSCSL**

Fac Site ID: 26292
Cleanup Site ID: 15446
Site Status: Awaiting Cleanup
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest

Responsible Unit: Northwest
Fac Site ID (OD):
Cleanup SiteID(OD):
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD):
County (OD):
Region (OD):
Longitude (OD):

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Latitude: 47.6246710849134 **Latitude (OD):**
Longitude: -122.342161587394
Site Name: Broad Street Alignment Contaminated Fill
Address: DEXTER AVE N & MERCER ST
City: SEATTLE
Zip Code: 98102
Site Status (OD):
Site Name (OD):
Address (OD):
City (OD):
Zipcode (OD):
Location (OD):
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites

Contaminants Detail(s)

Contaminant Name: Arsenic
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

263	1 of 2	NW	0.66 / 3,494.40	150.67 / 45	Unocal 306568 700 QUEEN ANNE AVE N SEATTLE WA 98109	CSCSL

Fac Site ID: 59972834
Cleanup Site ID: 6364
Site Status: Cleanup Started
Site Rank: 5 - Lowest Assessed Risk
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6257279877206
Longitude: -122.356473542783
Site Name: Unocal 306568
Address: 700 QUEEN ANNE AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Unocal 306568
Address (OD): 700 Queen Anne Ave N
City (OD): Seattle
Zipcode (OD): 98119
Location (OD): "" (47.6256, -122.356495)
Alternate Site Names: UNOCAL 0255,Unocal 306566
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 59972834
Cleanup SiteID(OD): 6364
Site Rank (OD): 5 - Lowest Assessed Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.356495
Latitude (OD): 47.6256

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

263	*2 of 2*	*NW*	*0.66 / 3,494.40*	*150.67 / 45*	***Unocal 306568*** ***700 QUEEN ANNE AVE N*** ***SEATTLE WA 98109***	***HSL***

Fac Site ID:	59972834	***Fac Site ID (OD):***	59972834
Cleanup Site ID:	6364	***Cleanup Site ID (OD):***	6364
Site Status:	Cleanup Started	***Site Status (OD):***	Cleanup Started
Site Rank:	5 - Lowest Assessed Risk	***Site Rank (OD):***	5 - Lowest Assessed Risk
Has Inst Control:		***Has Env Coven (OD):***	
Responsible Unit:	Northwest	***Respon Unit (OD):***	Northwest
County:	King	***County (OD):***	King
Region:	Northwest	***Region (OD):***	Northwest
Latitude:	47.6257279877206	***Site Name (OD):***	Unocal 306568
Longitude:	-122.356473542783	***Address (OD):***	700 Queen Anne Ave N
Latitude (OD):	47.6256	***City (OD):***	Seattle
Longitude (OD):	-122.356495	***ZIP code (OD):***	98119
Current VCP:		***Past VCP:***	Yes
Location (OD):	"" (47.6256, -122.356495)		

Alternate Site Names: UNOCAL 0255,Unocal 306566
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name:	Petroleum-Gasoline	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Petroleum-Diesel	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Petroleum-Other	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Petroleum-Gasoline	**Contaminant Media:**	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Gasoline	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Diesel	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Other	**Contaminant Media:**	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Other	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Diesel	**Contaminant Media:**	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
264	1 of 1	WNW	0.66 / 3,496.38	35.08 / -71	**Gilead Sciences Inc** **410 W HARRISON ST 2ND FLOOR** **SEATTLE WA 98119**	CSCSL

Fac Site ID:	69317824	**Responsible Unit:**	Northwest
Cleanup Site ID:	3743	**Fac Site ID (OD):**	69317824
Site Status:	Cleanup Started	**Cleanup SiteID(OD):**	3743
Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:	Yes	**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.36199
Latitude:	47.62231	**Latitude (OD):**	47.62231
Longitude:	-122.36199		
Site Name:	Gilead Sciences Inc		
Address:	410 W HARRISON ST 2ND FLOOR		
City:	SEATTLE		
Zip Code:	98119		
Site Status (OD):	Cleanup Started		
Site Name (OD):	Gilead Sciences Inc		
Address (OD):	410 W HARRISON ST 2ND FLOOR		
City (OD):	SEATTLE		
Zipcode (OD):	98119-4007		
Location (OD):	"" (47.62231, -122.36199)		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Alternate Site Names: ARE-SEATTLE NO.10,LLC,NEORX CORP SEATTLE,Northwest Medical Laboratories
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Halogenated Organics
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Arsenic
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Arsenic
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Halogenated Organics
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

265	1 of 2	NW	0.66 / 3,504.36	143.61 / 38	Texaco 211577 Monterey 631 QUEEN ANNE AVE N SEATTLE WA 98109	CSCSL

Fac Site ID: 77774779
Cleanup Site ID: 6663
Site Status: Cleanup Started
Site Rank: 1 - Highest Assessed Risk
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6254638624635
Longitude: -122.357085248866
Site Name: Texaco 211577 Monterey
Address: 631 QUEEN ANNE AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Texaco 211577
Address (OD): 631 QUEEN ANNE AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.62505, -122.35664)

Responsible Unit: Northwest
Fac Site ID (OD): 77774779
Cleanup SiteID(OD): 6663
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.35664
Latitude (OD): 47.62505

Alternate Site Names: Arnolds Mini Mart,Former Texaco Station 211577,Manhattan Express Deli,Monterey Apartments,Queen Anne Texaco,Royston on Queen Anne,Texaco Downstream 211577,Young H Yoo
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Halogenated Solvents
Groundwater: Confirmed Above Cleanup Levels

Surfacewater:
Soil:
Sediment:
Air: Suspected
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air: Suspected
Bedrock:

Contaminant Name: Non-Halogenated Solvents
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air: Confirmed Above Cleanup Levels
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air: Confirmed Above Cleanup Levels
Bedrock:

Contaminant Name: Lead
Groundwater: Suspected
Surfacewater:
Soil: Suspected
Sediment:
Air: Suspected
Bedrock:

Contaminant Name: Metals - Other
Groundwater: Suspected
Surfacewater:
Soil: Suspected
Sediment:
Air: Suspected
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air: Confirmed Above Cleanup Levels
Bedrock:

Contaminant Name: Arsenic
Groundwater: Suspected
Surfacewater:
Soil: Suspected
Sediment:
Air: Suspected
Bedrock:

Contaminant Name: Mercury
Groundwater: Suspected
Surfacewater:
Soil: Suspected
Sediment:
Air: Suspected
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air: Confirmed Above Cleanup Levels
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Lead
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Halogenated Solvents
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

265	2 of 2	NW	0.66 / 3,504.36	143.61 / 38	**Texaco 211577 Monterey** **631 QUEEN ANNE AVE N** **SEATTLE WA 98109**	HSL

Fac Site ID: 77774779
Cleanup Site ID: 6663
Site Status: Cleanup Started
Site Rank: 1 - Highest Assessed Risk
Fac Site ID (OD): 77774779
Cleanup Site ID (OD): 6663
Site Status (OD): Cleanup Started
Site Rank (OD):

Has Inst Control:		***Has Env Coven (OD):***	
Responsible Unit:	Northwest	***Respon Unit (OD):***	Northwest
County:	King	***County (OD):***	King
Region:	Northwest	***Region (OD):***	Northwest
Latitude:	47.6254638624635	***Site Name (OD):***	Texaco 211577
Longitude:	-122.357085248866	***Address (OD):***	631 QUEEN ANNE AVE N
Latitude (OD):	47.62505	***City (OD):***	SEATTLE
Longitude (OD):	-122.35664	***ZIP code (OD):***	98109
Current VCP:		***Past VCP:***	Yes

Location (OD): ""
(47.62505, -122.35664)

Alternate Site Names: Arnolds Mini Mart,Former Texaco Station 211577,Manhattan Express Deli,Monterey Apartments,Queen Anne Texaco,Royston on Queen Anne,Texaco Downstream 211577,Young H Yoo

Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name:	Arsenic	***Sediment:***	
Groundwater:	Suspected	***Soil:***	Suspected
Surfacewater:		***Bedrock:***	
Air:	Suspected		
Contaminant Name:	Halogenated Solvents	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Soil:***	
Surfacewater:		***Bedrock:***	
Air:	Suspected		
Contaminant Name:	Benzene	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:		***Bedrock:***	
Air:	Suspected		
Contaminant Name:	Petroleum-Gasoline	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:		***Bedrock:***	
Air:	Confirmed Above Cleanup Levels		
Contaminant Name:	Lead	***Sediment:***	
Groundwater:	Suspected	***Soil:***	Suspected
Surfacewater:		***Bedrock:***	
Air:	Suspected		
Contaminant Name:	Petroleum-Other	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:		***Bedrock:***	
Air:	Confirmed Above Cleanup Levels		
Contaminant Name:	Mercury	***Sediment:***	
Groundwater:	Suspected	***Soil:***	Suspected
Surfacewater:		***Bedrock:***	
Air:	Suspected		
Contaminant Name:	Polycyclic Aromatic Hydrocarbons	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:		***Bedrock:***	
Air:			
Contaminant Name:	Metals - Other	***Sediment:***	
Groundwater:	Suspected	***Soil:***	Suspected
Surfacewater:		***Bedrock:***	
Air:	Suspected		
Contaminant Name:	Non-Halogenated Solvents	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:		***Bedrock:***	
Air:	Confirmed Above Cleanup Levels		
Contaminant Name:	Petroleum-Diesel	***Sediment:***	

Groundwater:	Confirmed Above Cleanup Levels	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:		***Bedrock:***	
Air:	Confirmed Above Cleanup Levels		

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Lead	***Contaminant Media:***	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Diesel	***Contaminant Media:***	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Polycyclic Aromatic Hydrocarbons	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Polycyclic Aromatic Hydrocarbons	***Contaminant Media:***	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Benzene	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Benzene	***Contaminant Media:***	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Halogenated Solvents	***Contaminant Media:***	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Gasoline	***Contaminant Media:***	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Gasoline	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Diesel	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		

266	***1 of 4***	***NW***	***0.67 / 3,523.61***	***138.43 / 33***	***MONTEREY APARTMENTS 622 1ST AVE W & QUEEN AVE N SEATTLE WA 98119***	***DELISTED SHWS***

Delisted Contaminated/Hazardous Sites

Fac Site ID:	2047	***WARM Rank:***	3
Cleanup Site ID:	4813	***Warm Rank Desc:***	Moderate Risk
Brownfield?:		***Respon Section:***	Northwest
PSI?:	Yes	***County:***	King
VCP?:		***Region:***	Northwest
Past VCP:		***Latitude:***	47.62501
Has Inst Control:		***Longitude:***	-122.35779
Site Status:	Construction Complete-Performance Monitoring		
Alternate Site Names:			
Original Source:	CSCS		
Record Date:	11-MAR-2019		

266	***2 of 4***	***NW***	***0.67 / 3,523.61***	***138.43 / 33***	***MONTEREY APARTMENTS 622 1ST AVE W & QUEEN AVE N SEATTLE WA 98119***	***DELISTED SHWS***

Delisted Contaminated/Hazardous Sites

Fac Site ID:	2047	***WARM Rank:***	3
Cleanup Site ID:	4813	***Warm Rank Desc:***	Moderate Risk

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Brownfield?:		**Respon Section:**	Northwest
PSI?:	Yes	**County:**	King
VCP?:		**Region:**	Northwest
Past VCP:		**Latitude:**	47.62501
Has Inst Control:		**Longitude:**	-122.35779
Site Status:	Construction Complete-Performance Monitoring		
Alternate Site Names:			
Original Source:	HSL		
Record Date:	11-MAR-2019		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
266	3 of 4	NW	0.67 / 3,523.61	138.43 / 33	MONTEREY APARTMENTS 622 1ST AVE W & QUEEN AVE N SEATTLE WA 98119	CSCSL

Fac Site ID:		**Responsible Unit:**	
Cleanup Site ID:		**Fac Site ID (OD):**	2047
Site Status:		**Cleanup SiteID(OD):**	4813
Site Rank:		**Site Rank (OD):**	3 - Moderate Risk
Current VCP:		**Has Env Coven (OD):**	
Past VCP:		**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:		**Region (OD):**	Northwest
Region:		**Longitude (OD):**	-122.35779
Latitude:		**Latitude (OD):**	47.62501
Longitude:			
Site Name:			
Address:			
City:			
Zip Code:			
Site Status (OD):	Construction Complete-Performance Monitoring		
Site Name (OD):	MONTEREY APARTMENTS		
Address (OD):	622 1ST AVE W & QUEEN AVE N		
City (OD):	SEATTLE		
Zipcode (OD):	98119		
Location (OD):	"" (47.62501, -122.35779)		
Alternate Site Names:			
Data Source(s):	Cleanup Sites (Open Data Portal)		

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Petroleum Products-Unspecified
Contaminant Media:	Soil
Contaminant Status:	Confirmed Above Cleanup Levels
Contaminant:	Non-Halogenated Solvents
Contaminant Media:	Air
Contaminant Status:	Confirmed Above Cleanup Levels
Contaminant:	Non-Halogenated Solvents
Contaminant Media:	Soil
Contaminant Status:	Confirmed Above Cleanup Levels
Contaminant:	Metals Priority Pollutants
Contaminant Media:	Air
Contaminant Status:	Suspected
Contaminant:	Non-Halogenated Solvents
Contaminant Media:	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels
Contaminant:	Metals Priority Pollutants
Contaminant Media:	Groundwater
Contaminant Status:	Suspected
Contaminant:	Petroleum Products-Unspecified
Contaminant Media:	Air

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals Priority Pollutants
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

---

266 | **4 of 4** | **NW** | **0.67 / 3,523.61** | **138.43 / 33** | **MONTEREY APARTMENTS**
622 1ST AVE W & QUEEN AVE N
SEATTLE WA 98119 | **HSL**

Fac Site ID:
Cleanup Site ID:
Site Status:
Site Rank:
Has Inst Control:
Responsible Unit:
County:
Region:
Latitude:
Longitude:
Latitude (OD): 47.62501
Longitude (OD): -122.35779
Current VCP:
Location (OD): "" (47.62501, -122.35779)
Alternate Site Names:
Data Source(s): Cleanup Sites (Open Data Portal)

Fac Site ID (OD): 2047
Cleanup Site ID (OD): 4813
Site Status (OD): Construction Complete-Performance Monitoring
Site Rank (OD): 3 - Moderate Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Site Name (OD): MONTEREY APARTMENTS
Address (OD): 622 1ST AVE W & QUEEN AVE N
City (OD): SEATTLE
ZIP code (OD): 98119
Past VCP:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Non-Halogenated Solvents
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Groundwater

Contaminant: Metals Priority Pollutants
Contaminant Status: Suspected
Contaminant Media: Soil

Contaminant: Metals Priority Pollutants
Contaminant Status: Suspected
Contaminant Media: Air

Contaminant: Petroleum Products-Unspecified
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Soil

Contaminant: Non-Halogenated Solvents
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Air

Contaminant: Metals Priority Pollutants
Contaminant Status: Suspected
Contaminant Media: Groundwater

Contaminant: Petroleum Products-Unspecified
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Groundwater

Contaminant: Non-Halogenated Solvents
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Soil

Contaminant: Petroleum Products-Unspecified
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Air

---

267 | **1 of 1** | **NE** | **0.67 / 3,542.80** | **54.77 / -51** | **601 Dexter**
601 DEXTER AVE N
SEATTLE WA 98109 | **CSCSL**

Fac Site ID:	56257757	***Responsible Unit:***	Northwest
Cleanup Site ID:	15113	***Fac Site ID (OD):***	
Site Status:	Awaiting Cleanup	***Cleanup SiteID(OD):***	
Site Rank:		***Site Rank (OD):***	
Current VCP:		***Has Env Coven (OD):***	
Past VCP:		***Respon Unit (OD):***	
Has Inst Control:		***County (OD):***	
County:	King	***Region (OD):***	
Region:	Northwest	***Longitude (OD):***	
Latitude:	47.6247923692459	***Latitude (OD):***	
Longitude:	-122.342988963893		
Site Name:	601 Dexter		
Address:	601 DEXTER AVE N		
City:	SEATTLE		
Zip Code:	98109		
Site Status (OD):			
Site Name (OD):			
Address (OD):			
City (OD):			
Zipcode (OD):			
Location (OD):			
Alternate Site Names:	ARE-Seattle 32 LLC,Quik Sign Inc		
Data Source(s):	Confirmed and Suspected Contaminated Sites		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Gasoline
Groundwater:	Confirmed Above Cleanup Levels
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Methyl tertiary-butyl ether
Groundwater:	Below Cleanup Levels
Surfacewater:	
Soil:	Below Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Petroleum-Other
Groundwater:	Below Cleanup Levels
Surfacewater:	
Soil:	Below Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Arsenic
Groundwater:	Confirmed Above Cleanup Levels
Surfacewater:	
Soil:	Below Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Benzene
Groundwater:	Below Cleanup Levels
Surfacewater:	
Soil:	Below Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Polycyclic Aromatic Hydrocarbons
Groundwater:	Below Cleanup Levels

Surfacewater:	
Soil:	Below Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Halogenated Solvents
Groundwater:	Below Cleanup Levels
Surfacewater:	
Soil:	Below Cleanup Levels
Sediment:	
Air:	Confirmed Above Cleanup Levels
Bedrock:	

Contaminant Name:	Metals - Other
Groundwater:	Confirmed Above Cleanup Levels
Surfacewater:	
Soil:	Below Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Polychlorinated biPhenyls (PCB)
Groundwater:	
Surfacewater:	
Soil:	Below Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Mercury
Groundwater:	Below Cleanup Levels
Surfacewater:	
Soil:	Below Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Petroleum-Diesel
Groundwater:	Below Cleanup Levels
Surfacewater:	
Soil:	Below Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Lead
Groundwater:	Confirmed Above Cleanup Levels
Surfacewater:	
Soil:	Below Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Non-Halogenated Solvents
Groundwater:	
Surfacewater:	
Soil:	Below Cleanup Levels
Sediment:	
Air:	Confirmed Above Cleanup Levels
Bedrock:	

Contaminant Name:	Other Non-Halogenated Organics
Groundwater:	Below Cleanup Levels
Surfacewater:	
Soil:	Below Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
268	1 of 1	E	0.67 / 3,544.11	101.30 / -4	1918 Eighth Office Tower 1918 8TH AVE SEATTLE WA 98101	CSCSL

Fac Site ID: 6625
Cleanup Site ID: 12346
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6154672826766
Longitude: -122.335746084656
Site Name: 1918 Eighth Office Tower
Address: 1918 8TH AVE
City: SEATTLE
Zip Code: 98101
Site Status (OD): Cleanup Started
Site Name (OD): 1918 Eighth Office Tower
Address (OD): 1918 8TH AVE
City (OD): SEATTLE
Zipcode (OD): 98101
Location (OD): "" (47.615467, -122.335746)
Alternate Site Names: 8th & Virginia Building
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 6625
Cleanup SiteID(OD): 12346
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.335746
Latitude (OD): 47.615467

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Diesel
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

269 | **1 of 1** | **E** | **0.68 / 3,603.76** | **105.35 / 0** | **Dollar Rent a Car, 7TH & STEWART, SEATTLE WA 98101** | **CSCSL**

Fac Site ID: 37162797
Cleanup Site ID: 8918
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6145858352253
Longitude: -122.336213040262
Site Name: Dollar Rent a Car
Address: 7TH & STEWART
City: SEATTLE
Zip Code: 98101
Site Status (OD): Cleanup Started
Site Name (OD): Dollar Rent a Car
Address (OD): 7TH & STEWART
City (OD): SEATTLE
Zipcode (OD): 98101
Location (OD): "" (47.614586, -122.336213)
Responsible Unit: Northwest
Fac Site ID (OD): 37162797
Cleanup SiteID(OD): 8918
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.336213
Latitude (OD): 47.614586
Alternate Site Names: DOLLAR RENT A CAR SEATTLE,DOLLAR RENT A CAR UST 4366
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

270 | **1 of 1** | **ENE** | **0.68 / 3,604.52** | **49.99 / -56** | **Firestone Tire & Rubber Co, 400 WESTLAKE AVE N, SEATTLE WA 98109** | **CSCSL**

Fac Site ID: 32145888
Cleanup Site ID: 12005
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.622356156236
Longitude: -122.338066676655
Site Name: Firestone Tire & Rubber Co
Responsible Unit: Northwest
Fac Site ID (OD): 32145888
Cleanup SiteID(OD): 12005
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.338067
Latitude (OD): 47.622356

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Address: 400 WESTLAKE AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Firestone Tire & Rubber Co
Address (OD): 400 WESTLAKE AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): "" (47.622356, -122.338067)
Alternate Site Names: FIRESTONE 31A9,FIRESTONE STORE 31A9
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater: Suspected
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Suspected

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
271	1 of 2	NE	0.69 / 3,619.17	56.56 / -49	Seattle DOT Dexter Parcel 615 DEXTER AVE N SEATTLE WA 98109	CSCSL

Fac Site ID: 81735
Cleanup Site ID: 14785
Site Status: Cleanup Started
Site Rank: 2 - Moderate-High Risk
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6251744629371
Longitude: -122.343022186508
Site Name: Seattle DOT Dexter Parcel
Address: 615 DEXTER AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD):
Site Name (OD):
Address (OD):
City (OD):
Zipcode (OD):
Location (OD):
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites

Responsible Unit: Northwest
Fac Site ID (OD):
Cleanup SiteID(OD):
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD):
County (OD):
Region (OD):
Longitude (OD):
Latitude (OD):

Contaminants Detail(s)

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

---

271 | ***2 of 2*** | ***NE*** | ***0.69 / 3,619.17*** | ***56.56 / -49*** | ***Seattle DOT Dexter Parcel 615 DEXTER AVE N SEATTLE WA 98109*** | ***HSL***

Fac Site ID:	81735	***Fac Site ID (OD):***	
Cleanup Site ID:	14785	***Cleanup Site ID (OD):***	
Site Status:	Cleanup Started	***Site Status (OD):***	
Site Rank:	2 - Moderate-High Risk	***Site Rank (OD):***	
Has Inst Control:		***Has Env Coven (OD):***	
Responsible Unit:	Northwest	***Respon Unit (OD):***	
County:	King	***County (OD):***	
Region:	Northwest	***Region (OD):***	
Latitude:	47.6251744629371	***Site Name (OD):***	
Longitude:	-122.343022186508	***Address (OD):***	
Latitude (OD):		***City (OD):***	
Longitude (OD):		***ZIP code (OD):***	
Current VCP:		***Past VCP:***	Yes
Location (OD):			
Alternate Site Names:			
Data Source(s):	Confirmed and Suspected Contaminated Sites		

Contaminants Detail(s)

Contaminant Name:	Benzene	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Soil:***	
Surfacewater:		***Bedrock:***	
Air:			

Contaminant Name:	Petroleum-Diesel	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Soil:***	
Surfacewater:		***Bedrock:***	
Air:			

Contaminant Name:	Petroleum-Gasoline	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:		***Bedrock:***	
Air:			

---

272 | ***1 of 1*** | ***E*** | ***0.69 / 3,664.88*** | ***108.79 / 3*** | ***Federal Courthouse 700 STEWART ST SEATTLE WA 98101*** | ***CSCSL***

Fac Site ID:	51352493	***Responsible Unit:***	Northwest
Cleanup Site ID:	3966	***Fac Site ID (OD):***	51352493

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Status:	Awaiting Cleanup	**Cleanup SiteID(OD):**	3966
Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:		**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.33631
Latitude:	47.6149402316466	**Latitude (OD):**	47.61494
Longitude:	-122.336309729145		
Site Name:	Federal Courthouse		
Address:	700 STEWART ST		
City:	SEATTLE		
Zip Code:	98101		
Site Status (OD):	Awaiting Cleanup		
Site Name (OD):	Federal Courthouse		
Address (OD):	700 STEWART ST		
City (OD):	SEATTLE		
Zipcode (OD):	98101		
Location (OD):	"" (47.61494, -122.33631)		
Alternate Site Names:	GENERAL SERVICES ADMINISTRATION FEDERAL BUILDING,US GENERAL SERVICES ADMINISTRATION		
Data Source(s):	Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)		

Contaminants Detail(s)

Contaminant Name:	Petroleum Products-Unspecified
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Petroleum Products-Unspecified
Contaminant Media:	Soil
Contaminant Status:	Confirmed Above Cleanup Levels

273	*1 of 2*	*NE*	*0.72 / 3,779.34*	*49.08 / -57*	***Seattle DOT Mercer Parcels 800 MERCER ST SEATTLE WA 98109***	***CSCSL***

Fac Site ID:	27913	**Responsible Unit:**	Northwest
Cleanup Site ID:	14784	**Fac Site ID (OD):**	
Site Status:	Cleanup Started	**Cleanup SiteID(OD):**	
Site Rank:	2 - Moderate-High Risk	**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:	Yes	**Respon Unit (OD):**	
Has Inst Control:		**County (OD):**	
County:	King	**Region (OD):**	
Region:	Northwest	**Longitude (OD):**	
Latitude:	47.6250683256473	**Latitude (OD):**	
Longitude:	-122.341096559525		
Site Name:	Seattle DOT Mercer Parcels		
Address:	800 MERCER ST		
City:	SEATTLE		
Zip Code:	98109		
Site Status (OD):			
Site Name (OD):			
Address (OD):			
City (OD):			
Zipcode (OD):			
Location (OD):			
Alternate Site Names:			
Data Source(s):	Confirmed and Suspected Contaminated Sites		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminants Detail(s)

Contaminant Name:	Petroleum-Diesel
Groundwater:	Confirmed Above Cleanup Levels
Surfacewater:	
Soil:	
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Petroleum-Gasoline
Groundwater:	Confirmed Above Cleanup Levels
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Benzene
Groundwater:	Confirmed Above Cleanup Levels
Surfacewater:	
Soil:	
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Lead
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Petroleum-Other
Groundwater:	Confirmed Above Cleanup Levels
Surfacewater:	
Soil:	Below Cleanup Levels
Sediment:	
Air:	
Bedrock:	

273	***2 of 2***	***NE***	***0.72 / 3,779.34***	***49.08 / -57***	***Seattle DOT Mercer Parcels 800 MERCER ST SEATTLE WA 98109***	***HSL***

Fac Site ID:	27913	***Fac Site ID (OD):***	
Cleanup Site ID:	14784	***Cleanup Site ID (OD):***	
Site Status:	Cleanup Started	***Site Status (OD):***	
Site Rank:	2 - Moderate-High Risk	***Site Rank (OD):***	
Has Inst Control:		***Has Env Coven (OD):***	
Responsible Unit:	Northwest	***Respon Unit (OD):***	
County:	King	***County (OD):***	
Region:	Northwest	***Region (OD):***	
Latitude:	47.6250683256473	***Site Name (OD):***	
Longitude:	-122.341096559525	***Address (OD):***	
Latitude (OD):		***City (OD):***	
Longitude (OD):		***ZIP code (OD):***	
Current VCP:		***Past VCP:***	Yes
Location (OD):			
Alternate Site Names:			
Data Source(s):	Confirmed and Suspected Contaminated Sites		

Contaminants Detail(s)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant Name:	Lead	**Sediment:**	
Groundwater:		**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Benzene	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Soil:**	
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Petroleum-Other	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Soil:**	Below Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Petroleum-Gasoline	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Petroleum-Diesel	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Soil:**	
Surfacewater:		**Bedrock:**	
Air:			

274	1 of 1	NE	0.72 / 3,811.48	60.86 / -45	701 Dexter 701 DEXTER AVE N SEATTLE WA 98109	CSCSL

Fac Site ID:	78082	**Responsible Unit:**	Northwest
Cleanup Site ID:	15112	**Fac Site ID (OD):**	
Site Status:	Awaiting Cleanup	**Cleanup SiteID(OD):**	
Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:		**Respon Unit (OD):**	
Has Inst Control:		**County (OD):**	
County:	King	**Region (OD):**	
Region:	Northwest	**Longitude (OD):**	
Latitude:	47.6257084481311	**Latitude (OD):**	
Longitude:	-122.342870728836		
Site Name:	701 Dexter		
Address:	701 DEXTER AVE N		
City:	SEATTLE		
Zip Code:	98109		
Site Status (OD):			
Site Name (OD):			
Address (OD):			
City (OD):			
Zipcode (OD):			
Location (OD):			
Alternate Site Names:	ARE-Seattle 33 LLC		
Data Source(s):	Confirmed and Suspected Contaminated Sites		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Other
Groundwater:	Below Cleanup Levels
Surfacewater:	
Soil:	Below Cleanup Levels
Sediment:	
Air:	
Bedrock:	
Contaminant Name:	Non-Halogenated Solvents
Groundwater:	
Surfacewater:	
Soil:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Sediment:
Air: Confirmed Above Cleanup Levels
Bedrock:

Contaminant Name: Metals - Other
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Halogenated Solvents
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air: Confirmed Above Cleanup Levels
Bedrock:

---

275 | ***1 of 1*** | ***E*** | ***0.72 / 3,815.25*** | ***120.09 / 14*** | ***City Mini Storage***
2000 TERRY AVE & 1000 VIRGINIA ST
SEATTLE WA 98121 | ***CSCSL***

Fac Site ID: 2494
Cleanup Site ID: 2665
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6174819833691
Longitude: -122.334887045047
Site Name: City Mini Storage
Address: 2000 TERRY AVE & 1000 VIRGINIA ST
City: SEATTLE
Zip Code: 98121
Site Status (OD):
Site Name (OD):
Address (OD):
City (OD):
Zipcode (OD):
Location (OD):
Alternate Site Names: CITY MINI Whse
Data Source(s): Confirmed and Suspected Contaminated Sites

Responsible Unit: Pollution Liability Ins Agcy
Fac Site ID (OD):
Cleanup SiteID(OD):
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD):
County (OD):
Region (OD):
Longitude (OD):
Latitude (OD):

Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

---

276 | ***1 of 2*** | ***NE*** | ***0.73 / 3,831.49*** | ***58.86 / -47*** | ***American Linen Supply Co Dexter Ave***
700 DEXTER AVE N
SEATTLE WA 98109 | ***CSCSL***

Fac Site ID: 3573
Cleanup Site ID: 12004

Responsible Unit: Northwest
Fac Site ID (OD): 3573

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Status:	Cleanup Started	**Cleanup SiteID(OD):**	12004
Site Rank:	1 - Highest Assessed Risk	**Site Rank (OD):**	1 - Highest Assessed Risk
Current VCP:		**Has Env Coven (OD):**	
Past VCP:	Yes	**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.341671
Latitude:	47.62582	**Latitude (OD):**	47.62582
Longitude:	-122.341671		

Site Name: American Linen Supply Co Dexter Ave
Address: 700 DEXTER AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): American Linen Supply Co Dexter Ave
Address (OD): 700 DEXTER AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.62582, -122.341671)
Alternate Site Names: Maryatt Industries
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Other Non-Halogenated Organics
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant: Other Non-Halogenated Organics
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Other Non-Halogenated Organics
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

276	2 of 2	NE	0.73 / 3,831.49	58.86 / -47	American Linen Supply Co Dexter Ave 700 DEXTER AVE N SEATTLE WA 98109	HSL

Fac Site ID: 3573
Cleanup Site ID: 12004
Site Status: Cleanup Started
Site Rank: 1 - Highest Assessed Risk
Has Inst Control:
Responsible Unit: Northwest
County: King
Region: Northwest
Latitude: 47.62582
Longitude: -122.341671
Latitude (OD): 47.62582
Longitude (OD): -122.341671
Current VCP:
Location (OD): "" (47.62582, -122.341671)
Alternate Site Names: Maryatt Industries
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Fac Site ID (OD): 3573
Cleanup Site ID (OD): 12004
Site Status (OD): Cleanup Started
Site Rank (OD): 1 - Highest Assessed Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Site Name (OD): American Linen Supply Co Dexter Ave
Address (OD): 700 DEXTER AVE N
City (OD): SEATTLE
ZIP code (OD): 98109
Past VCP: Yes

Contaminants Detail(s)

Contaminant Name: Other Non-Halogenated Organics
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Air:
Sediment:
Soil: Confirmed Above Cleanup Levels
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Air:
Sediment:
Soil:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Air:
Sediment:
Soil:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Sediment:
Soil:
Bedrock:

Air:

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Air:
Sediment:
Soil:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Diesel
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Groundwater

Contaminant: Other Non-Halogenated Organics
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Soil

Contaminant: Petroleum-Gasoline
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Groundwater

Contaminant: Benzene
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Groundwater

Contaminant: Other Non-Halogenated Organics
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Groundwater

Contaminant: Petroleum-Other
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Groundwater

277	1 of 1	E	0.73 / 3,841.51	116.24 / 10	Stewart Court Apartments 1835 8TH AVE SEATTLE WA 98101	CSCSL

Fac Site ID: 68676891
Cleanup Site ID: 6514
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control: Yes
County: King
Region: Northwest
Latitude: 47.614587410034
Longitude: -122.335275662507
Site Name: Stewart Court Apartments
Address: 1835 8TH AVE
City: SEATTLE
Zip Code: 98101
Site Status (OD): Cleanup Started
Site Name (OD): Stewart Court Apartments
Address (OD): 1835 8TH AVE
City (OD): SEATTLE
Zipcode (OD): 98121
Location (OD): "" (47.614416, -122.334471)
Responsible Unit: Northwest
Fac Site ID (OD): 68676891
Cleanup SiteID(OD): 6514
Site Rank (OD):
Has Env Coven (OD): Yes
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.334471
Latitude (OD): 47.614416
Alternate Site Names: Stewart Court Apartments (Off-Property),Stewart Court Apartments (Property NFA)
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Metals Priority Pollutants
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Metals Priority Pollutants
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

278 | ***1 of 1*** | ***E*** | ***0.74 / 3,889.33*** | ***121.60 / 16*** | ***818 Stewart St
818 STEWART ST
SEATTLE WA 98101*** | ***CSCSL***

Fac Site ID: 8747213
Cleanup Site ID: 3096
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6156898190573
Longitude: -122.335020068104
Site Name: 818 Stewart St
Address: 818 STEWART ST
City: SEATTLE
Zip Code: 98101
Site Status (OD): Cleanup Started
Site Name (OD): 818 Stewart St
Address (OD): 818 STEWART ST
City (OD): SEATTLE
Zipcode (OD): 98101
Location (OD): "" (47.61569, -122.33502)
Alternate Site Names: 818 Stewart St Construction Site
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 8747213
Cleanup SiteID(OD): 3096
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.33502
Latitude (OD): 47.61569

Contaminants Detail(s)

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Air:
Bedrock:

Contaminant Name: Metals Priority Pollutants
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Metals Priority Pollutants
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

279	1 of 1	E	0.74 / 3,896.87	121.71 / 16	Boren and Lenora 2019 - 2031 BOREN AVE SEATTLE WA 98121	DELISTED SHWS

Delisted Confirmed and Suspected Contaminated Sites

Fac Site ID: 62202
Cleanup Site ID: 15279
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
Responsible Unit: Pollution Liability Ins Agcy
County: King
Region: Northwest
Latitude: 47.618016125509
Longitude: -122.335240620813
Site Status (OD):
Site Name (OD):
Address (OD):
Location (OD):
Alternate Site Names:
Data Source(s): WA ECY Toxics Cleanup Program
Original Source: CSCS
Record Date: 26-JAN-2021

Fac Site ID (OD):
Clnup Site ID (OD):
Site Rank (OD):
Respon Unit (OD):
Has Env Coven (OD):
County (OD):
Region (OD):
City (OD):
Zipcode (OD):
Latitude (OD):
Longitude (OD):

280	1 of 1	NE	0.75 / 3,947.06	45.59 / -60	Seattle Roy Aloha Shops 802 ROY ST SEATTLE WA 98109	CSCSL

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Fac Site ID:	95811428	**Responsible Unit:**	Northwest
Cleanup Site ID:	11216	**Fac Site ID (OD):**	95811428
Site Status:	Cleanup Started	**Cleanup SiteID(OD):**	11216
Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:		**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.34063
Latitude:	47.6256558799842	**Latitude (OD):**	47.625656
Longitude:	-122.34063001268		

Site Name: Seattle Roy Aloha Shops
Address: 802 ROY ST
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Seattle Roy Aloha Shops
Address (OD): 802 ROY ST
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.625656, -122.34063)
Alternate Site Names: ROY ST SHOPS 89,Seattle City Roy Street Facility
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

281	1 of 2	ENE	0.75 / 3,979.68	36.01 / -70	Block 38 West 520 Westlake Ave N Seattle WA 98109	CSCSL

Fac Site ID: 62773 **Responsible Unit:** Northwest

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Cleanup Site ID: 15008
Site Status: Cleanup Started
Site Rank: 3 - Moderate Risk
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6239592980284
Longitude: -122.338112508262
Site Name: Block 38 West
Address: 520 Westlake Ave N
City: Seattle
Zip Code: 98109
Site Status (OD):
Site Name (OD):
Address (OD):
City (OD):
Zipcode (OD):
Location (OD):
Alternate Site Names: Block 38
Data Source(s): Confirmed and Suspected Contaminated Sites

Fac Site ID (OD):
Cleanup SiteID(OD):
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD):
County (OD):
Region (OD):
Longitude (OD):
Latitude (OD):

Contaminants Detail(s)

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

281	2 of 2	ENE	0.75 / 3,979.68	36.01 / -70	Block 38 West 520 Westlake Ave N	HSL

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					Seattle WA 98109	

Fac Site ID:	62773	**Fac Site ID (OD):**	
Cleanup Site ID:	15008	**Cleanup Site ID (OD):**	
Site Status:	Cleanup Started	**Site Status (OD):**	
Site Rank:	3 - Moderate Risk	**Site Rank (OD):**	
Has Inst Control:		**Has Env Coven (OD):**	
Responsible Unit:	Northwest	**Respon Unit (OD):**	
County:	King	**County (OD):**	
Region:	Northwest	**Region (OD):**	
Latitude:	47.6239592980284	**Site Name (OD):**	
Longitude:	-122.338112508262	**Address (OD):**	
Latitude (OD):		**City (OD):**	
Longitude (OD):		**ZIP code (OD):**	
Current VCP:		**Past VCP:**	
Location (OD):			
Alternate Site Names:	Block 38		
Data Source(s):	Confirmed and Suspected Contaminated Sites		

Contaminants Detail(s)

Contaminant Name:	Benzene	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Soil:**	
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Petroleum-Gasoline	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Soil:**	
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Petroleum-Diesel	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Soil:**	
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Petroleum-Other	**Sediment:**	
Groundwater:		**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Polycyclic Aromatic Hydrocarbons	**Sediment:**	
Groundwater:		**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			

282	1 of 1	ENE	0.75 / 3,982.54	55.25 / -51	**Lake Union III** **410 TERRY N 415 BOREN N** **SEATTLE WA 98109**	CSCSL

Fac Site ID:	7165	**Responsible Unit:**	Northwest
Cleanup Site ID:	11900	**Fac Site ID (OD):**	7165
Site Status:	Cleanup Started	**Cleanup SiteID(OD):**	11900
Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:		**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.336456
Latitude:	47.6226885512492	**Latitude (OD):**	47.622689
Longitude:	-122.336455822713		
Site Name:	Lake Union III		
Address:	410 TERRY N 415 BOREN N		
City:	SEATTLE		
Zip Code:	98109		
Site Status (OD):	Cleanup Started		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Name (OD): Lake Union III
Address (OD): 410 TERRY N 415 BOREN N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.622689, -122.336456)
Alternate Site Names: LAKE UNION III LLC
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

283	1 of 1	E	0.76 / 3,998.58	120.86 / 15	Seattle Times 1120 JOHN ST SEATTLE WA 98109	CSCSL

Fac Site ID: 4377754
Cleanup Site ID: 14495
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.620556
Longitude: -122.335389
Site Name: Seattle Times
Address: 1120 JOHN ST
City: SEATTLE
Zip Code: 98109
Site Status (OD): Awaiting Cleanup
Site Name (OD): Seattle Times
Address (OD): 1120 JOHN ST
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.620556, -122.335389)
Alternate Site Names: SEATTLE TIMES COMPANY,SEATTLE TIMES SEATTLE,Seattle Times UST 7350
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 4377754
Cleanup SiteID(OD): 14495
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.335389
Latitude (OD): 47.620556

Contaminants Detail(s)

Contaminant Name: Halogenated Solvents
Groundwater: Suspected
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
284	1 of 1	ENE	0.76 / 4,035.61	39.63 / -66	Rosen Property 960 REPUBLICAN ST SEATTLE WA 98109	CSCSL

Fac Site ID:	2500	**Responsible Unit:**	Northwest
Cleanup Site ID:	5123	**Fac Site ID (OD):**	2500
Site Status:	Cleanup Started	**Cleanup SiteID(OD):**	5123
Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:	Yes	**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.337511
Latitude:	47.623439	**Latitude (OD):**	47.623439
Longitude:	-122.337511		
Site Name:	Rosen Property		
Address:	960 REPUBLICAN ST		
City:	SEATTLE		
Zip Code:	98109		
Site Status (OD):	Cleanup Started		
Site Name (OD):	Rosen Property		
Address (OD):	960 REPUBLICAN ST		
City (OD):	SEATTLE		
Zipcode (OD):	98109		
Location (OD):	"" (47.623439, -122.337511)		
Alternate Site Names:	H & A INVESTMENT PROPERTY,H & A INVESTMENTS PROPERTY,INTERURBAN EXCHANGE 2,Rosen Property (Property NFA),Rosen Site (Off-Property),TECH II,WA UW ROSEN BLDG		
Data Source(s):	Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Diesel
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Petroleum-Other
Groundwater:	Remediated-Below
Surfacewater:	
Soil:	Remediated-Below
Sediment:	
Air:	
Bedrock:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
285	1 of 1	NE	0.77 / 4,042.16	54.26 / -51	Maryatt Industries 771 VALLEY ST SEATTLE WA 98109	CSCSL

Fac Site ID:	2455	**Responsible Unit:**	Northwest
Cleanup Site ID:	3167	**Fac Site ID (OD):**	2455
Site Status:	Awaiting Cleanup	**Cleanup SiteID(OD):**	3167
Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:		**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.34176
Latitude:	47.6259018409465	**Latitude (OD):**	47.625902
Longitude:	-122.341759811017		
Site Name:	Maryatt Industries		
Address:	771 VALLEY ST		
City:	SEATTLE		
Zip Code:	98109		

Site Status (OD): Awaiting Cleanup
Site Name (OD): Maryatt Industries
Address (OD): 771 VALLEY ST
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.625902, -122.34176)
Alternate Site Names: American Linen Supply
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Non-Halogenated Solvents
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Halogenated Organics
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Non-Halogenated Solvents
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Halogenated Organics
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Halogenated Organics
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Non-Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Suspected

286	*1 of 1*	*E*	*0.77 / 4,045.51*	*124.42 / 19*	***Seattle Times Parcel 1B*** ***100 FAIRVIEW AVE*** ***SEATTLE WA 98109***	***CSCSL***

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Fac Site ID:	8396751	**Responsible Unit:**	Northwest
Cleanup Site ID:	5458	**Fac Site ID (OD):**	8396751
Site Status:	Cleanup Started	**Cleanup SiteID(OD):**	5458
Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:	Yes	**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.334139
Latitude:	47.61931581996	**Latitude (OD):**	47.619316
Longitude:	-122.334139483498		

Site Name: Seattle Times Parcel 1B
Address: 100 FAIRVIEW AVE
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Seattle Times Parcel 1B
Address (OD): 100 FAIRVIEW AVE
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.619316, -122.334139)
Alternate Site Names: 100 FAIRVIEW AVE N,PARCEL 1B TAX#2468400025,TAX#2468400025
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Non-Halogenated Solvents
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil

Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Non-Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Non-Halogenated Solvents
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

287	*1 of 2*	*NE*	*0.78 / 4,112.63*	*39.68 / -66*	***Block 79 East*** ***701 9TH AVE N*** ***SEATTLE WA 98109***	***CSCSL***

Fac Site ID: 84466254
Cleanup Site ID: 13006
Site Status: Cleanup Started
Site Rank: 2 - Moderate-High Risk
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.625874157992
Longitude: -122.340184983543
Site Name: Block 79 East
Address: 701 9TH AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Awaiting Cleanup
Site Name (OD): Buca di Beppo Ducati
Address (OD): 701 9TH AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.625874, -122.340185)
Alternate Site Names: Buca di Beppo,Buca di Beppo Ducati,Ducati,Seattle Motor Sports
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 84466254
Cleanup SiteID(OD): 13006
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.340185
Latitude (OD): 47.625874

Contaminants Detail(s)

Contaminant Name: Mercury
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Suspected

Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Suspected
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Other Non-Halogenated Organics
Groundwater: Suspected
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Halogenated Solvents
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Lead
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Suspected
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Halogenated Solvents
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Lead
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Mercury
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

---

287 | ***2 of 2*** | ***NE*** | ***0.78 / 4,112.63*** | ***39.68 / -66*** | ***Block 79 East
701 9TH AVE N
SEATTLE WA 98109*** | ***HSL***

Fac Site ID:	84466254	***Fac Site ID (OD):***	84466254
Cleanup Site ID:	13006	***Cleanup Site ID (OD):***	13006
Site Status:	Cleanup Started	***Site Status (OD):***	Awaiting Cleanup
Site Rank:	2 - Moderate-High Risk	***Site Rank (OD):***	
Has Inst Control:		***Has Env Coven (OD):***	
Responsible Unit:	Northwest	***Respon Unit (OD):***	Northwest
County:	King	***County (OD):***	King
Region:	Northwest	***Region (OD):***	Northwest
Latitude:	47.625874157992	***Site Name (OD):***	Buca di Beppo Ducati
Longitude:	-122.340184983543	***Address (OD):***	701 9TH AVE N
Latitude (OD):	47.625874	***City (OD):***	SEATTLE
Longitude (OD):	-122.340185	***ZIP code (OD):***	98109
Current VCP:		***Past VCP:***	Yes
Location (OD):	"" (47.625874, -122.340185)		
Alternate Site Names:	Buca di Beppo,Buca di Beppo Ducati,Ducati,Seattle Motor Sports		
Data Source(s):	Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Other	***Sediment:***	
Groundwater:	Suspected	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:		***Bedrock:***	
Air:			
Contaminant Name:	Polycyclic Aromatic Hydrocarbons	***Sediment:***	
Groundwater:		***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:		***Bedrock:***	
Air:			
Contaminant Name:	Lead	***Sediment:***	
Groundwater:		***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:		***Bedrock:***	
Air:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant Name:	Other Non-Halogenated Organics	**Sediment:**	
Groundwater:	Suspected	**Soil:**	Suspected
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Petroleum-Diesel	**Sediment:**	
Groundwater:	Suspected	**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Halogenated Solvents	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Petroleum-Gasoline	**Sediment:**	
Groundwater:	Suspected	**Soil:**	Suspected
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Benzene	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Mercury	**Sediment:**	
Groundwater:		**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Mercury	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Halogenated Solvents	**Contaminant Media:**	Groundwater
Contaminant Status:	Suspected		
Contaminant:	Petroleum-Gasoline	**Contaminant Media:**	Groundwater
Contaminant Status:	Suspected		
Contaminant:	Petroleum-Diesel	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Other	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Gasoline	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Lead	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Diesel	**Contaminant Media:**	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		

288	1 of 1	NE	0.78 / 4,142.85	59.61 / -46	**Seattle SD 1 Facilities Bldg** **810 DEXTER AVE N** **SEATTLE WA 98109**	CSCSL

Fac Site ID:	56583225	**Responsible Unit:**	Northwest
Cleanup Site ID:	9747	**Fac Site ID (OD):**	56583225
Site Status:	Cleanup Started	**Cleanup SiteID(OD):**	9747
Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:		**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King

County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.341666
Latitude:	47.6267326923518	**Latitude (OD):**	47.626733
Longitude:	-122.341666		

Site Name: Seattle SD 1 Facilities Bldg
Address: 810 DEXTER AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Seattle SD 1 Facilities Bldg
Address (OD): 810 DEXTER AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.626733, -122.341666)
Alternate Site Names: Seattle School Dist 1 Facilities Bldg,SEATTLE SCHOOL DISTRICT 1
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Below Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Below Cleanup Levels

Contaminant: Petroleum-Gasoline

Contaminant Media: Groundwater
Contaminant Status: Below Cleanup Levels

---

289 | **1 of 1** | **SE** | **0.78 / 4,143.65** | **13.24 / -93** | **Pier 58 Sediments**
1401 ALASKAN WAY
SEATTLE WA 98101 | **CSCSL**

Fac Site ID: 67655
Cleanup Site ID: 15509
Site Status: Awaiting Cleanup
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6068830982776
Longitude: -122.341429213799
Site Name: Pier 58 Sediments
Address: 1401 ALASKAN WAY
City: SEATTLE
Zip Code: 98101
Site Status (OD):
Site Name (OD):
Address (OD):
City (OD):
Zipcode (OD):
Location (OD):
Alternate Site Names: Waterfront Park
Data Source(s): Confirmed and Suspected Contaminated Sites

Responsible Unit: Northwest
Fac Site ID (OD):
Cleanup SiteID(OD):
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD):
County (OD):
Region (OD):
Longitude (OD):
Latitude (OD):

Contaminants Detail(s)

Contaminant Name: Dioxins/Furans
Groundwater:
Surfacewater:
Soil:
Sediment: Suspected
Air:
Bedrock:

Contaminant Name: Metals - Other
Groundwater:
Surfacewater:
Soil:
Sediment: Suspected
Air:
Bedrock:

Contaminant Name: Polychlorinated biPhenyls (PCB)
Groundwater:
Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

Contaminant Name: Bioassay Failure
Groundwater:
Surfacewater:
Soil:
Sediment: Suspected
Air:
Bedrock:

Contaminant Name: Mercury
Groundwater:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

---

290 | ***1 of 2*** | ***ENE*** | ***0.79 / 4,176.53*** | ***42.67 / -63*** | ***Ivars Commissary
500 TERRY AVE N
SEATTLE WA 98109*** | ***CSCSL***

Fac Site ID: 85883854
Cleanup Site ID: 6774
Site Status: Cleanup Started
Site Rank: 3 - Moderate Risk
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6234263816955
Longitude: -122.336855703893
Site Name: Ivars Commissary
Address: 500 TERRY AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Ivars Commissary
Address (OD): 500 TERRY AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.623426, -122.336856)
Alternate Site Names: IVAR S COMMISSARY,TERRY DRUM
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 85883854
Cleanup SiteID(OD): 6774
Site Rank (OD): 3 - Moderate Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.336856
Latitude (OD): 47.623426

Contaminants Detail(s)

Contaminant Name: Benzene
Groundwater: Suspected
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Suspected
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Suspected
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Suspected

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
290	2 of 2	ENE	0.79 / 4,176.53	42.67 / -63	Ivars Commissary 500 TERRY AVE N SEATTLE WA 98109	HSL

Fac Site ID: 85883854
Cleanup Site ID: 6774
Site Status: Cleanup Started
Site Rank: 3 - Moderate Risk
Has Inst Control:
Responsible Unit: Northwest
County: King
Region: Northwest
Latitude: 47.6234263816955
Longitude: -122.336855703893
Latitude (OD): 47.623426
Longitude (OD): -122.336856
Current VCP:
Location (OD): ""
(47.623426, -122.336856)

Fac Site ID (OD): 85883854
Cleanup Site ID (OD): 6774
Site Status (OD): Cleanup Started
Site Rank (OD): 3 - Moderate Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Site Name (OD): Ivars Commissary
Address (OD): 500 TERRY AVE N
City (OD): SEATTLE
ZIP code (OD): 98109
Past VCP: Yes

Alternate Site Names: IVAR S COMMISSARY,TERRY DRUM
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminants Detail(s)

Contaminant Name:	Petroleum-Diesel	***Sediment:***	
Groundwater:	Suspected	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:		***Bedrock:***	
Air:			
Contaminant Name:	Benzene	***Sediment:***	
Groundwater:	Suspected	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:		***Bedrock:***	
Air:			
Contaminant Name:	Petroleum-Other	***Sediment:***	
Groundwater:	Suspected	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:		***Bedrock:***	
Air:			
Contaminant Name:	Petroleum-Gasoline	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:		***Bedrock:***	
Air:			

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Petroleum-Diesel	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Other	***Contaminant Media:***	Groundwater
Contaminant Status:	Suspected		
Contaminant:	Benzene	***Contaminant Media:***	Groundwater
Contaminant Status:	Suspected		
Contaminant:	Petroleum-Diesel	***Contaminant Media:***	Groundwater
Contaminant Status:	Suspected		
Contaminant:	Petroleum-Gasoline	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Gasoline	***Contaminant Media:***	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Other	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Benzene	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
291	1 of 1	E	0.79 / 4,185.63	133.87 / 28	8th & Howell 808 HOWELL ST SEATTLE WA 98101	CSCSL

Fac Site ID:	1754553	***Responsible Unit:***	Northwest
Cleanup Site ID:	15060	***Fac Site ID (OD):***	
Site Status:	Cleanup Started	***Cleanup SiteID(OD):***	
Site Rank:		***Site Rank (OD):***	
Current VCP:		***Has Env Coven (OD):***	
Past VCP:		***Respon Unit (OD):***	
Has Inst Control:		***County (OD):***	
County:	King	***Region (OD):***	
Region:	Northwest	***Longitude (OD):***	
Latitude:	47.6148990219163	***Latitude (OD):***	
Longitude:	-122.334320143754		
Site Name:	8th & Howell		
Address:	808 HOWELL ST		
City:	SEATTLE		
Zip Code:	98101		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Status (OD):
Site Name (OD):
Address (OD):
City (OD):
Zipcode (OD):
Location (OD):
Alternate Site Names: Verizon Wireless Saw
Data Source(s): Confirmed and Suspected Contaminated Sites

Contaminants Detail(s)

Contaminant Name: Petroleum-Diesel
Groundwater: Suspected
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Polychlorinated biPhenyls (PCB)
Groundwater:
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

292	1 of 1	NE	0.80 / 4,198.75	33.85 / -72	**AIBS Building Block 43** **601 WESTLAKE AVE N** **SEATTLE WA 98109**	CSCSL

Fac Site ID: 32368748
Cleanup Site ID: 12637
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6251634926553
Longitude: -122.338979942461
Responsible Unit: Northwest
Fac Site ID (OD): 32368748
Cleanup SiteID(OD): 12637
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.33898
Latitude (OD): 47.625163
Site Name: AIBS Building Block 43
Address: 601 WESTLAKE AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): AIBS Building Block 43
Address (OD): 601 WESTLAKE AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.625163, -122.33898)
Alternate Site Names: AIBS BUILDING LLC BLK 43,AIBS BULDING LLC BLK 43,PACIFIC LINCOLN MERCURY NISSAN,Seattle Auto Center
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Other Non-Halogenated Organics
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Suspected
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Lead
Groundwater: Suspected
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Metals - Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Lead

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Other Non-Halogenated Organics
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals - Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Lead
Contaminant Media: Groundwater
Contaminant Status: Suspected

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
293	1 of 1	NE	0.80 / 4,238.40	35.70 / -70	Seattle City DOT ROW 710 9th Ave N 710 9TH AVE N SEATTLE WA 98109	CSCSL

Fac Site ID: 21735
Cleanup Site ID: 12379
Site Status: Awaiting Cleanup
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.625965
Longitude: -122.339619
Site Name: Seattle City DOT ROW 710 9th Ave N
Address: 710 9TH AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Awaiting Cleanup
Site Name (OD): Seattle City DOT ROW 710 9th Ave N
Address (OD): 710 9TH AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): "" (47.625965, -122.339619)
Alternate Site Names: SDOT 9th Ave N,Seattle DOT Mercer Corridor Project
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 21735
Cleanup SiteID(OD): 12379
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.339619
Latitude (OD): 47.625965

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminants Detail(s)

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

294	1 of 1	ENE	0.80 / 4,245.61	46.34 / -59	**Moxy Hotel** **1016 REPUBLICAN ST** **SEATTLE WA 98109**	CSCSL

Fac Site ID: 65520
Cleanup Site ID: 14730
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6235324756348
Longitude: -122.336200728836
Site Name: Moxy Hotel
Address: 1016 REPUBLICAN ST
City: SEATTLE
Zip Code: 98109
Site Status (OD): Awaiting Cleanup
Site Name (OD): Moxy Hotel
Address (OD): 1016 REPUBLICAN ST
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): "" (47.623532, -122.336201)
Alternate Site Names: SLU Lodging LLC
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 65520
Cleanup SiteID(OD): 14730
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.336201
Latitude (OD): 47.623532

Contaminants Detail(s)

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Air:						
Bedrock:						
295	1 of 2	E	0.80 / 4,249.17	126.03 / 20	Red Carpet Car Wash 1164 DENNY WAY SEATTLE WA 98109	CSCSL

Fac Site ID: 21844229
Cleanup Site ID: 3230
Site Status: Cleanup Started
Site Rank: 3 - Moderate Risk
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6188183843888
Longitude: -122.333315431283
Site Name: Red Carpet Car Wash
Address: 1164 DENNY WAY
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Red Carpet Car Wash
Address (OD): 1164 DENNY WAY
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.618818, -122.333315)
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 21844229
Cleanup SiteID(OD): 3230
Site Rank (OD): 3 - Moderate Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.333315
Latitude (OD): 47.618818

Contaminants Detail(s)

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Remediated
Surfacewater:
Soil: Remediated
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater

Contaminant Status: Remediated

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Remediated

---

295 | ***2 of 2*** | ***E*** | ***0.80 / 4,249.17*** | ***126.03 / 20*** | ***Red Carpet Car Wash***
1164 DENNY WAY
SEATTLE WA 98109 | ***HSL***

Fac Site ID:	21844229	***Fac Site ID (OD):***	21844229
Cleanup Site ID:	3230	***Cleanup Site ID (OD):***	3230
Site Status:	Cleanup Started	***Site Status (OD):***	Cleanup Started
Site Rank:	3 - Moderate Risk	***Site Rank (OD):***	3 - Moderate Risk
Has Inst Control:		***Has Env Coven (OD):***	
Responsible Unit:	Northwest	***Respon Unit (OD):***	Northwest
County:	King	***County (OD):***	King
Region:	Northwest	***Region (OD):***	Northwest
Latitude:	47.6188183843888	***Site Name (OD):***	Red Carpet Car Wash
Longitude:	-122.333315431283	***Address (OD):***	1164 DENNY WAY
Latitude (OD):	47.618818	***City (OD):***	SEATTLE
Longitude (OD):	-122.333315	***ZIP code (OD):***	98109
Current VCP:		***Past VCP:***	
Location (OD):	"" (47.618818, -122.333315)		
Alternate Site Names:			
Data Source(s):	Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)		

Contaminants Detail(s)

Contaminant Name:	Petroleum Products-Unspecified	***Sediment:***	
Groundwater:	Remediated	***Soil:***	Remediated
Surfacewater:		***Bedrock:***	
Air:			
Contaminant Name:	Benzene	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:		***Bedrock:***	
Air:			
Contaminant Name:	Petroleum-Gasoline	***Sediment:***	
Groundwater:	Confirmed Above Cleanup Levels	***Soil:***	Confirmed Above Cleanup Levels
Surfacewater:		***Bedrock:***	
Air:			

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Benzene	***Contaminant Media:***	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Gasoline	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Gasoline	***Contaminant Media:***	Groundwater

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Remediated

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Remediated

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

296	1 of 1	E	0.81 / 4,252.57	134.26 / 29	Creases Dry Cleaner 1820 TERRY AVE SEATTLE WA 98101	DELISTED SHWS

Delisted Contaminated/Hazardous Sites

Fac Site ID: 18615
Cleanup Site ID: 12453
Brownfield?:
PSI?:
VCP?: Yes
Past VCP:
Has Inst Control:
Site Status: Cleanup Started
Alternate Site Names:
Original Source: CSCS
Record Date: 21-NOV-2016

WARM Rank: N
Warm Rank Desc:
Respon Section: Northwest
County: King
Region: Northwest
Latitude: 47.61617
Longitude: -122.332891101852

297	1 of 1	ENE	0.81 / 4,262.76	51.71 / -54	South Lake Union 293 Parcel A 424 BOREN AVE N SEATTLE WA 98109	CSCSL

Fac Site ID: 11720
Cleanup Site ID: 11893
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.622986387822
Longitude: -122.335489822091
Site Name: South Lake Union 293 Parcel A
Address: 424 BOREN AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): South Lake Union 293 Parcel A
Address (OD): 424 BOREN AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.622986, -122.33549)
Alternate Site Names: SLU 293 Parcel A,SLU 293 Parcel A (Off-Property),SLU 293 Parcel A (Property NFA)
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 11720
Cleanup SiteID(OD): 11893
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.33549
Latitude (OD): 47.622986

Contaminants Detail(s)

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Remediated-Below

Sediment:
Air:
Bedrock:

Contaminant Name: Arsenic
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Lead
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Lead
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Arsenic
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

298	*1 of 2*	*ENE*	*0.81 / 4,299.01*	*31.90 / -74*	***Block 37*** ***600 WESTLAKE AVE N*** ***SEATTLE WA 98109***	*CSCSL*

Fac Site ID: 46445373
Cleanup Site ID: 6134
Site Status: Cleanup Started
Site Rank: 1 - Highest Assessed Risk
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6249263484114
Longitude: -122.338220640364
Site Name: Block 37
Address: 600 WESTLAKE AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): TOSCO 25535330857

Responsible Unit: Northwest
Fac Site ID (OD): 46445373
Cleanup SiteID(OD): 6134
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.338221
Latitude (OD): 47.624926

Address (OD):	600 WESTLAKE AVE N
City (OD):	SEATTLE
Zipcode (OD):	98109
Location (OD):	"" (47.624926, -122.338221)
Alternate Site Names:	CONOCOPHILLIPS 30857,CONOCOPHILLIPS COMPANY 255353,TOSCO 25535330857,UNOCAL 5353, WESTLAKE/MERCER CLEANUP SITE
Data Source(s):	Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name:	Methyl tertiary-butyl ether
Groundwater:	Below Cleanup Levels
Surfacewater:	
Soil:	
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Non-Halogenated Solvents
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Petroleum-Other
Groundwater:	Confirmed Above Cleanup Levels
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Polycyclic Aromatic Hydrocarbons
Groundwater:	Confirmed Above Cleanup Levels
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Benzene
Groundwater:	Confirmed Above Cleanup Levels
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Petroleum Products-Unspecified
Groundwater:	
Surfacewater:	
Soil:	
Sediment:	
Air:	Confirmed Above Cleanup Levels
Bedrock:	

Contaminant Name:	Lead
Groundwater:	Confirmed Above Cleanup Levels
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Petroleum-Diesel

Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Diesel
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Lead
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Air
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Methyl tertiary-butyl ether
Contaminant Media: Groundwater
Contaminant Status: Below Cleanup Levels

Contaminant: Lead
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

298 **2 of 2** **ENE** **0.81 / 4,299.01** **31.90 / -74** **Block 37**
600 WESTLAKE AVE N
SEATTLE WA 98109 **HSL**

Fac Site ID:	46445373	**Fac Site ID (OD):**	46445373
Cleanup Site ID:	6134	**Cleanup Site ID (OD):**	6134
Site Status:	Cleanup Started	**Site Status (OD):**	Cleanup Started
Site Rank:	1 - Highest Assessed Risk	**Site Rank (OD):**	
Has Inst Control:		**Has Env Coven (OD):**	
Responsible Unit:	Northwest	**Respon Unit (OD):**	Northwest
County:	King	**County (OD):**	King
Region:	Northwest	**Region (OD):**	Northwest
Latitude:	47.6249263484114	**Site Name (OD):**	TOSCO 25535330857
Longitude:	-122.338220640364	**Address (OD):**	600 WESTLAKE AVE N
Latitude (OD):	47.624926	**City (OD):**	SEATTLE
Longitude (OD):	-122.338221	**ZIP code (OD):**	98109
Current VCP:		**Past VCP:**	Yes

Location (OD): ""
(47.624926, -122.338221)
Alternate Site Names: CONOCOPHILLIPS 30857,CONOCOPHILLIPS COMPANY 255353,TOSCO 25535330857,UNOCAL 5353, WESTLAKE/MERCER CLEANUP SITE
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name:	Petroleum-Gasoline	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Methyl tertiary-butyl ether	**Sediment:**	
Groundwater:	Below Cleanup Levels	**Soil:**	
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Benzene	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Non-Halogenated Solvents	**Sediment:**	
Groundwater:		**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Petroleum Products-Unspecified	**Sediment:**	
Groundwater:		**Soil:**	
Surfacewater:		**Bedrock:**	
Air:	Confirmed Above Cleanup Levels		
Contaminant Name:	Petroleum-Diesel	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Petroleum-Other	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Polycyclic Aromatic Hydrocarbons	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Soil:**	Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Surfacewater: ***Bedrock:***
Air:

Contaminant Name: Lead
Groundwater: Confirmed Above Cleanup Levels ***Sediment:*** ***Soil:*** Confirmed Above Cleanup Levels
Surfacewater: ***Bedrock:***
Air:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Polycyclic Aromatic Hydrocarbons	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Benzene	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Polycyclic Aromatic Hydrocarbons	***Contaminant Media:***	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Lead	***Contaminant Media:***	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Diesel	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Other	***Contaminant Media:***	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Methyl tertiary-butyl ether	***Contaminant Media:***	Groundwater
Contaminant Status:	Below Cleanup Levels		
Contaminant:	Petroleum-Gasoline	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Benzene	***Contaminant Media:***	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Gasoline	***Contaminant Media:***	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Other	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Diesel	***Contaminant Media:***	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum Products-Unspecified	***Contaminant Media:***	Air
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Lead	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		

299	*1 of 1*	*ENE*	*0.82 / 4,323.01*	*115.26 / 10*	***Cascade 1 & 2 Apartments*** ***Minor & Fairview Ave N Thomas & John*** ***Seattle WA 98109***	***CSCSL***

Fac Site ID:	18688	***Responsible Unit:***	Northwest
Cleanup Site ID:	12649	***Fac Site ID (OD):***	18688
Site Status:	Cleanup Started	***Cleanup SiteID(OD):***	12649
Site Rank:		***Site Rank (OD):***	
Current VCP:		***Has Env Coven (OD):***	
Past VCP:	Yes	***Respon Unit (OD):***	Northwest
Has Inst Control:		***County (OD):***	King
County:	King	***Region (OD):***	Northwest
Region:	Northwest	***Longitude (OD):***	-122.333631
Latitude:	47.6202155366341	***Latitude (OD):***	47.620216

Longitude: -122.333631457672
Site Name: Cascade 1 & 2 Apartments
Address: Minor & Fairview Ave N Thomas & John
City: Seattle
Zip Code: 98109
Site Status (OD): Awaiting Cleanup
Site Name (OD): Cascade 1 & 2 Apartments
Address (OD): Minor & Fairview Ave N Thomas & John
City (OD): Seattle
Zipcode (OD): 98109
Location (OD): ""
(47.620216, -122.333631)
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Lead
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Other Non-Halogenated Organics
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Halogenated Solvents
Groundwater: Below Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Metals - Other
Groundwater:
Surfacewater:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Remediated-Below
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals - Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Lead
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

300	*1 of 1*	*ENE*	*0.82 / 4,333.90*	*43.49 / -62*	***525 Boren Building*** ***525 BOREN AVE N*** ***SEATTLE WA 98109***	*CSCSL*

Fac Site ID: 20345
Cleanup Site ID: 12132
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.623703
Longitude: -122.336211
Site Name: 525 Boren Building
Address: 525 BOREN AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): 525 Boren Building
Address (OD): 525 BOREN AVE N
City (OD): SEATTLE
Zipcode (OD): 98109

Responsible Unit: Northwest
Fac Site ID (OD): 20345
Cleanup SiteID(OD): 12132
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.336211
Latitude (OD): 47.623703

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Location (OD): ""
(47.623703, -122.336211)
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Non-Halogenated Solvents
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Diesel
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Non-Halogenated Solvents
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

301	*1 of 1*	*NE*	*0.82 / 4,337.49*	*34.13 / -72*	***Maaco Auto Painting Bodywork*** ***9th Ave*** ***739 9TH AVE N*** ***SEATTLE WA 98109***	*CSCSL*

Fac Site ID:
Cleanup Site ID:
Site Status:
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County:
Region:
Latitude:
Longitude:
Site Name:
Address:
City:
Zip Code:
Site Status (OD): Cleanup Started

Responsible Unit:
Fac Site ID (OD): 2224749
Cleanup SiteID(OD): 12571
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.340056
Latitude (OD): 47.626436

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Name (OD): Maaco Auto Painting Bodywork 9th Ave
Address (OD): 739 9TH AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): "" (47.626436, -122.340056)
Alternate Site Names:
Data Source(s): Cleanup Sites (Open Data Portal)

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Lead
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Halogenated Solvents
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Mercury
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

302	1 of 1	ENE	0.83 / 4,358.45	91.67 / -14	Troy Laundry Seattle 399 FAIRVIEW AVE N SEATTLE WA 98109	CSCSL

Fac Site ID: 19135499
Cleanup Site ID: 11690
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.62193
Longitude: -122.33435
Site Name: Troy Laundry Seattle
Address: 399 FAIRVIEW AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Troy Laundry Seattle
Address (OD): 307 FAIRVIEW AVE N
City (OD): SEATTLE
Zipcode (OD): 98109

Responsible Unit: Northwest
Fac Site ID (OD): 19135499
Cleanup SiteID(OD): 11690
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.334821
Latitude (OD): 47.621247

Location (OD): ""
(47.621247, -122.334821)
Alternate Site Names: SEATTLE TIMES,Seattle Times Co Fairview Ave,TROY LAUNDRY
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Other Halogenated Organics
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Halogenated Solvents
Groundwater:
Surfacewater:
Soil:
Sediment:
Air: Suspected
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Other Halogenated Organics
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Other Halogenated Organics
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Halogenated Solvents
Contaminant Media: Air
Contaminant Status: Suspected

Contaminant: Petroleum-Diesel
Contaminant Media: Soil

Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

303 | ***1 of 2*** | ***SE*** | ***0.83 / 4,368.01*** | ***26.14 / -80*** | ***Seattle Steam Co Western Ave***
1319 WESTERN AVE
SEATTLE WA 98101 | ***CSCSL***

Fac Site ID: 2243
Cleanup Site ID: 5075
Site Status: Cleanup Started
Site Rank: 5 - Lowest Assessed Risk
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6067114897247
Longitude: -122.340146708226
Site Name: Seattle Steam Co Western Ave
Address: 1319 WESTERN AVE
City: SEATTLE
Zip Code: 98101
Site Status (OD): Cleanup Started
Site Name (OD): Seattle Steam Co Western Ave
Address (OD): 1319 WESTERN AVE
City (OD): SEATTLE
Zipcode (OD): 98101
Location (OD): ""
(47.606711, -122.340147)
Alternate Site Names: ENWAVE SEATTLE,SEATTLE STEAM,SEATTLE STEAM CO WESTERN AV,SEATTLE STEAM CORP UST 3736,Seattle Steam Corporation,WESTERN AVENUE STEAM PLANT
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 2243
Cleanup SiteID(OD): 5075
Site Rank (OD): 5 - Lowest Assessed Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.340147
Latitude (OD): 47.606711

Contaminants Detail(s)

Contaminant Name: Metals Priority Pollutants
Groundwater: Suspected
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Polychlorinated biPhenyls (PCB)
Groundwater: Suspected
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:

Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater: Suspected
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Metals - Other
Groundwater: Suspected
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals Priority Pollutants
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polychlorinated biPhenyls (PCB)
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Metals - Other
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Metals - Other
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Metals Priority Pollutants
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Polychlorinated biPhenyls (PCB)
Contaminant Media: Soil
Contaminant Status: Suspected

303	*2 of 2*	*SE*	*0.83 / 4,368.01*	*26.14 / -80*	***Seattle Steam Co Western Ave*** ***1319 WESTERN AVE*** ***SEATTLE WA 98101***	*HSL*

Fac Site ID: 2243
Cleanup Site ID: 5075
Fac Site ID (OD): 2243
Cleanup Site ID (OD): 5075

Site Status:	Cleanup Started	**Site Status (OD):**	Cleanup Started
Site Rank:	5 - Lowest Assessed Risk	**Site Rank (OD):**	5 - Lowest Assessed Risk
Has Inst Control:		**Has Env Coven (OD):**	
Responsible Unit:	Northwest	**Respon Unit (OD):**	Northwest
County:	King	**County (OD):**	King
Region:	Northwest	**Region (OD):**	Northwest
Latitude:	47.6067114897247	**Site Name (OD):**	Seattle Steam Co Western Ave
Longitude:	-122.340146708226	**Address (OD):**	1319 WESTERN AVE
Latitude (OD):	47.606711	**City (OD):**	SEATTLE
Longitude (OD):	-122.340147	**ZIP code (OD):**	98101
Current VCP:		**Past VCP:**	Yes
Location (OD):	"" (47.606711, -122.340147)		
Alternate Site Names:	ENWAVE SEATTLE,SEATTLE STEAM,SEATTLE STEAM CO WESTERN AV,SEATTLE STEAM CORP UST 3736,Seattle Steam Corporation,WESTERN AVENUE STEAM PLANT		
Data Source(s):	Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)		

Contaminants Detail(s)

Contaminant Name:	Polycyclic Aromatic Hydrocarbons	**Sediment:**	
Groundwater:	Suspected	**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Petroleum-Other	**Sediment:**	
Groundwater:	Confirmed Above Cleanup Levels	**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Polychlorinated biPhenyls (PCB)	**Sediment:**	
Groundwater:	Suspected	**Soil:**	Suspected
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Metals Priority Pollutants	**Sediment:**	
Groundwater:	Suspected	**Soil:**	Suspected
Surfacewater:		**Bedrock:**	
Air:			
Contaminant Name:	Metals - Other	**Sediment:**	
Groundwater:	Suspected	**Soil:**	Suspected
Surfacewater:		**Bedrock:**	
Air:			

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Metals Priority Pollutants	**Contaminant Media:**	Soil
Contaminant Status:	Suspected		
Contaminant:	Polychlorinated biPhenyls (PCB)	**Contaminant Media:**	Groundwater
Contaminant Status:	Suspected		
Contaminant:	Polycyclic Aromatic Hydrocarbons	**Contaminant Media:**	Groundwater
Contaminant Status:	Suspected		
Contaminant:	Metals - Other	**Contaminant Media:**	Groundwater
Contaminant Status:	Suspected		
Contaminant:	Metals Priority Pollutants	**Contaminant Media:**	Groundwater
Contaminant Status:	Suspected		
Contaminant:	Polycyclic Aromatic Hydrocarbons	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Other	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant: Petroleum-Other
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Groundwater

Contaminant: Metals - Other
Contaminant Status: Suspected
Contaminant Media: Soil

Contaminant: Polychlorinated biPhenyls (PCB)
Contaminant Status: Suspected
Contaminant Media: Soil

---

304 **1 of 2** **NW** **0.83 / 4,407.43** **121.66 / 16** **Oden Investment Condos**
619 5TH AVE W
SEATTLE WA 98119
CSCSL

Fac Site ID: 52738943
Cleanup Site ID: 9551
Site Status: Cleanup Started
Site Rank: 5 - Lowest Assessed Risk
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6253013095644
Longitude: -122.363581322656
Site Name: Oden Investment Condos
Address: 619 5TH AVE W
City: SEATTLE
Zip Code: 98119
Site Status (OD): Cleanup Started
Site Name (OD): Oden Investment Condos
Address (OD): 619 5TH AVE W
City (OD): SEATTLE
Zipcode (OD): 98119
Location (OD): "" (47.625301, -122.363581)
Alternate Site Names: Anderson Place Condominium
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 52738943
Cleanup SiteID(OD): 9551
Site Rank (OD): 5 - Lowest Assessed Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.363581
Latitude (OD): 47.625301

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

304 **2 of 2** **NW** **0.83 / 4,407.43** **121.66 / 16** **Oden Investment Condos**
619 5TH AVE W
SEATTLE WA 98119
HSL

Fac Site ID: 52738943
Cleanup Site ID: 9551
Site Status: Cleanup Started
Site Rank: 5 - Lowest Assessed Risk
Has Inst Control:
Responsible Unit: Northwest
County: King

Fac Site ID (OD): 52738943
Cleanup Site ID (OD): 9551
Site Status (OD): Cleanup Started
Site Rank (OD): 5 - Lowest Assessed Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Region: Northwest
Latitude: 47.6253013095644
Longitude: -122.363581322656
Latitude (OD): 47.625301
Longitude (OD): -122.363581
Current VCP:
Location (OD): ""
(47.625301, -122.363581)
Alternate Site Names: Anderson Place Condominium
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Region (OD): Northwest
Site Name (OD): Oden Investment Condos
Address (OD): 619 5TH AVE W
City (OD): SEATTLE
ZIP code (OD): 98119
Past VCP:

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Air:
Sediment:
Soil: Confirmed Above Cleanup Levels
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Soil

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
305	1 of 2	NE	0.84 / 4,415.51	29.76 / -76	Auto Service Company 630 WESTLAKE AVE N SEATTLE WA 98109	CSCSL

Fac Site ID:
Cleanup Site ID:
Site Status:
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County:
Region:
Latitude:
Longitude:
Site Name:
Address:
City:
Zip Code:
Site Status (OD): Cleanup Started
Site Name (OD): Auto Service Company
Address (OD): 630 WESTLAKE AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.625382, -122.337753)
Alternate Site Names:
Data Source(s): Cleanup Sites (Open Data Portal)

Responsible Unit:
Fac Site ID (OD): 24436664
Cleanup SiteID(OD): 5749
Site Rank (OD): 5 - Lowest Assessed Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.337753
Latitude (OD): 47.625382

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals Priority Pollutants
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Conventional Contaminants, Organic
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Non-Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Non-Halogenated Solvents
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Conventional Contaminants, Organic
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Metals - Other
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Metals Priority Pollutants
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals - Other
Contaminant Media: Soil
Contaminant Status: Suspected

---

305 | ***2 of 2*** | ***NE*** | ***0.84 / 4,415.51*** | ***29.76 / -76*** | ***Auto Service Company***
630 WESTLAKE AVE N
SEATTLE WA 98109 | ***HSL***

Fac Site ID:
Cleanup Site ID:
Site Status:
Site Rank:
Has Inst Control:
Responsible Unit:
County:
Region:
Latitude:
Longitude:
Latitude (OD): 47.625382
Longitude (OD): -122.337753
Current VCP:
Location (OD): "" (47.625382, -122.337753)
Alternate Site Names:
Data Source(s): Cleanup Sites (Open Data Portal)

Fac Site ID (OD): 24436664
Cleanup Site ID (OD): 5749
Site Status (OD): Cleanup Started
Site Rank (OD): 5 - Lowest Assessed Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Site Name (OD): Auto Service Company
Address (OD): 630 WESTLAKE AVE N
City (OD): SEATTLE
ZIP code (OD): 98109
Past VCP:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Petroleum-Gasoline	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Metals Priority Pollutants	***Contaminant Media:***	Soil
Contaminant Status:	Suspected		
Contaminant:	Conventional Contaminants, Organic	***Contaminant Media:***	Groundwater
Contaminant Status:	Suspected		
Contaminant:	Non-Halogenated Solvents	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Other	***Contaminant Media:***	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Non-Halogenated Solvents	***Contaminant Media:***	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Conventional Contaminants, Organic	***Contaminant Media:***	Soil
Contaminant Status:	Suspected		
Contaminant:	Petroleum-Gasoline	***Contaminant Media:***	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Petroleum-Other	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Metals - Other	***Contaminant Media:***	Groundwater
Contaminant Status:	Suspected		
Contaminant:	Benzene	***Contaminant Media:***	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		
Contaminant:	Metals Priority Pollutants	***Contaminant Media:***	Groundwater
Contaminant Status:	Suspected		
Contaminant:	Metals - Other	***Contaminant Media:***	Soil
Contaminant Status:	Suspected		
Contaminant:	Benzene	***Contaminant Media:***	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels		

306	***1 of 1***	***E***	***0.84 / 4,436.57***	***131.02 / 25***	***Crescent Heights 1901 - 1933 Minor Ave SEATTLE WA 98101***	***CSCSL***

Fac Site ID:	81018	***Responsible Unit:***	Northwest
Cleanup Site ID:	15275	***Fac Site ID (OD):***	
Site Status:	Awaiting Cleanup	***Cleanup SiteID(OD):***	
Site Rank:		***Site Rank (OD):***	
Current VCP:		***Has Env Coven (OD):***	
Past VCP:		***Respon Unit (OD):***	
Has Inst Control:		***County (OD):***	
County:	King	***Region (OD):***	
Region:	Northwest	***Longitude (OD):***	
Latitude:	47.6178285245562	***Latitude (OD):***	
Longitude:	-122.332790442036		
Site Name:	Crescent Heights		
Address:	1901 - 1933 Minor Ave		
City:	SEATTLE		
Zip Code:	98101		
Site Status (OD):			
Site Name (OD):			
Address (OD):			
City (OD):			
Zipcode (OD):			

Location (OD):
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites

Contaminants Detail(s)

Contaminant Name: Other Non-Halogenated Organics
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Lead
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Arsenic
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Metals - Other
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Mercury
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Suspected
Sediment:
Air:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Halogenated Solvents
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

307	1 of 1	ESE	0.84 / 4,441.52	146.63 / 41	WA State Convention & Trade Center 8TH & PINE SEATTLE WA 98101	CSCSL

Fac Site ID: 77746366
Cleanup Site ID: 1842
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6127012341508
Longitude: -122.333167629316
Site Name: WA State Convention & Trade Center
Address: 8TH & PINE
City: SEATTLE
Zip Code: 98101
Site Status (OD): Cleanup Started
Site Name (OD): WA State Convention & Trade Center
Address (OD): 8TH & PINE
City (OD): SEATTLE
Zipcode (OD): 98101
Location (OD): ""
(47.612701, -122.333168)
Alternate Site Names: ELLIOTT HOTEL,Seattle Fire Dept,WSCTC
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 77746366
Cleanup SiteID(OD): 1842
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.333168
Latitude (OD): 47.612701

Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

308 | ***1 of 1*** | ***E*** | ***0.84 / 4,441.61*** | ***133.96 / 28*** | ***Goodyear Stewart St 1105 STEWART ST SEATTLE WA 98101*** | ***CSCSL***

Fac Site ID: 39199977
Cleanup Site ID: 8998
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6167973956972
Longitude: -122.331842301111
Site Name: Goodyear Stewart St
Address: 1105 STEWART ST
City: SEATTLE
Zip Code: 98101
Site Status (OD): Cleanup Started
Site Name (OD): Goodyear Stewart St
Address (OD): 1105 STEWART ST
City (OD): SEATTLE
Zipcode (OD): 98101
Location (OD): "" (47.616797, -122.331842)
Alternate Site Names: Goodyear 8841 (Off-Property),GOODYEAR ASC 8841,Goodyear Stewart St (Property NFA),Goodyear Stewart Street,Goodyear Svc Store Seattle 8841
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 39199977
Cleanup SiteID(OD): 8998
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.331842
Latitude (OD): 47.616797

Contaminants Detail(s)

Contaminant Name: Metals - Other
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air: Confirmed Above Cleanup Levels
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:

Air: Confirmed Above Cleanup Levels
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air: Confirmed Above Cleanup Levels
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air: Confirmed Above Cleanup Levels
Bedrock:

Contaminant Name: Lead
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Other Non-Halogenated Organics
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air: Confirmed Above Cleanup Levels
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Air
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Air
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Other Non-Halogenated Organics
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals - Other
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Lead
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Other Non-Halogenated Organics
Contaminant Media: Air
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Air
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Air
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Other Non-Halogenated Organics
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

---

309 | ***1 of 1*** | ***NE*** | ***0.84 / 4,443.47*** | ***53.54 / -52*** | ***Jarvie Paint
760 ALOHA ST
SEATTLE WA 98109*** | ***CSCSL***

Fac Site ID: 2137
Cleanup Site ID: 59
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control: Yes
County: King
Region: Northwest
Latitude: 47.6273195367499
Longitude: -122.341445540999
Site Name: Jarvie Paint
Address: 760 ALOHA ST
City: SEATTLE
Zip Code: 98109
Site Status (OD):
Site Name (OD):
Address (OD):
City (OD):
Zipcode (OD):
Location (OD):
Alternate Site Names: JARVIE PAINT MFG CO,JARVIE PAINT MFG CO INC,Neptune Apartments,Neptune Apartments Proposed, PAMECO AIRE SEA

Responsible Unit: Northwest
Fac Site ID (OD):
Cleanup SiteID(OD):
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD):
County (OD):
Region (OD):
Longitude (OD):
Latitude (OD):

Data Source(s): Confirmed and Suspected Contaminated Sites

Contaminants Detail(s)

Contaminant Name: Other Non-Halogenated Organics
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Non-Halogenated Solvents
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

---

310 | ***1 of 1*** | ***ENE*** | ***0.85 / 4,491.52*** | ***82.17 / -24*** | ***400 Fairview LLC Seattle***
412 Fairview Ave N
Seattle WA 98109 | ***CSCSL***

Fac Site ID: 15119
Cleanup Site ID: 12065
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6224192073785
Longitude: -122.334022050755
Site Name: 400 Fairview LLC Seattle
Address: 412 Fairview Ave N
City: Seattle
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): 400 Fairview LLC Seattle
Address (OD): 412 Fairview Ave N
City (OD): Seattle
Zipcode (OD): 98109
Location (OD): ""
(47.622419, -122.334022)
Responsible Unit: Northwest
Fac Site ID (OD): 15119
Cleanup SiteID(OD): 12065
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.334022
Latitude (OD): 47.622419
Alternate Site Names: 400 Fairview LLC Seattle (Off-Property),400 Fairview LLC Seattle (Property NFA)
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant Name: Halogenated Solvents
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Halogenated Solvents
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

311	1 of 1	NE	0.85 / 4,495.30	60.21 / -46	Neptune Apartments proposed 900 912 DEXTER AVE N SEATTLE WA 98121	CSCSL

Fac Site ID: 4345275
Cleanup Site ID: 3885
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6272544611192
Longitude: -122.342084271614
Site Name: Neptune Apartments proposed
Address: 900 912 DEXTER AVE N
City: SEATTLE
Zip Code: 98121
Site Status (OD): Cleanup Started
Site Name (OD): Neptune Apartments proposed
Address (OD): 900 912 DEXTER AVE N
City (OD): SEATTLE
Zipcode (OD): 98121
Location (OD): ""
(47.627254, -122.342084)
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 4345275
Cleanup SiteID(OD): 3885
Site Rank (OD):
Has Env Coven (OD): Yes
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.342084
Latitude (OD): 47.627254

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant Media: Groundwater
Contaminant Status: Below Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Below Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Below Cleanup Levels

312	1 of 1	SE	0.85 / 4,503.78	19.01 / -87	Western & University Property WA	DELISTED SHWS

Delisted Confirmed and Suspected Contaminated Sites

Fac Site ID:
Cleanup Site ID:
Site Status:
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
Responsible Unit:
County:
Region:
Latitude:
Longitude:
Site Status (OD): Cleanup Started
Site Name (OD): Western & University Property
Address (OD):
Location (OD):
Alternate Site Names:
Data Source(s): Open Data Portal - Media and Contaminants
Original Source: CSCS
Record Date: 28-JUN-2021

Fac Site ID (OD): 19875
Clnup Site ID (OD): 12477
Site Rank (OD):
Respon Unit (OD):
Has Env Coven (OD):
County (OD):
Region (OD):
City (OD):
Zipcode (OD):
Latitude (OD): 47.60648
Longitude (OD): -122.33982

313	1 of 1	ENE	0.85 / 4,511.05	36.69 / -69	Block 32 North Bldg City Place III LLC 1001 & 1021 Mercer St 500 Terry Ave N Seattle WA 98109	CSCSL

Fac Site ID: 14637
Cleanup Site ID: 1761
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest

Responsible Unit: Northwest
Fac Site ID (OD): 14637
Cleanup SiteID(OD): 1761
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.336864

Latitude: 47.6238865085479 **Latitude (OD):** 47.623887
Longitude: -122.336863600426
Site Name: Block 32 North Bldg City Place III LLC
Address: 1001 & 1021 Mercer St 500 Terry Ave N
City: Seattle
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Block 32 North Bldg City Place III LLC
Address (OD): 1001 & 1021 Mercer St 500 Terry Ave N
City (OD): Seattle
Zipcode (OD): 98109
Location (OD): ""
(47.623887, -122.336864)
Alternate Site Names: Block 32,North Bldg,City Place III LLC
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Halogenated Organics
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Metals - Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Arsenic
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Metals Priority Pollutants
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Metals - Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Arsenic
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Halogenated Organics
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals Priority Pollutants
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

314	1 of 1	WNW	0.86 / 4,524.17	27.90 / -78	**Blackstock Lumber** **601 Elliott Ave W** **Seattle WA 98119**	CSCSL

Fac Site ID: 2540
Cleanup Site ID: 2544
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control: Yes
County: King
Region: Northwest
Latitude: 47.6246274042648
Longitude: -122.366333438168
Site Name: Blackstock Lumber
Address: 601 Elliott Ave W
City: Seattle
Zip Code: 98119
Site Status (OD): Cleanup Started
Site Name (OD): Blackstock Lumber
Address (OD): 601 ELLIOTT AVE W
City (OD): SEATTLE
Zipcode (OD): 98119-3911
Location (OD): "" (47.625693, -122.367277)
Alternate Site Names: LUMBER SUPPLY & WAREHOUSE CO INC
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 2540
Cleanup SiteID(OD): 2544
Site Rank (OD):
Has Env Coven (OD): Yes
Respon Unit (OD): Headquarters
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.367277
Latitude (OD): 47.625693

Contaminants Detail(s)

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Soil: Remediated
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Remediated

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

315	1 of 1	SE	0.86 / 4,556.50	18.52 / -87	Western & University Property 50 UNIVERSITY ST SEATTLE WA 98101	DELISTED SHWS

Delisted Contaminated/Hazardous Sites

Fac Site ID: 19875
Cleanup Site ID: 12477
Brownfield?:
PSI?: Yes
VCP?: Yes
Past VCP:
Has Inst Control:
Site Status: Cleanup Started
Alternate Site Names:
Original Source: CSCS
Record Date: 18-JAN-2018
WARM Rank: N
Warm Rank Desc:
Respon Section: Northwest
County: King
Region: Northwest
Latitude: 47.6064786864874
Longitude: -122.339819529201

316	1 of 1	ENE	0.87 / 4,600.01	34.86 / -71	Shell 23714 601 BOREN AVE N SEATTLE WA 98109	CSCSL

Fac Site ID: 99377872
Cleanup Site ID: 11355
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6248526271954
Longitude: -122.336124840587
Site Name: Shell 23714
Address: 601 BOREN AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Shell 23714
Address (OD): 601 BOREN AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): "" (47.624853, -122.336125)
Alternate Site Names: Shell Oil Product US SAP 121433,TEXACO 63-232-0400,Texaco 632320258,TEXACO STATION 632320400 UST
Responsible Unit: Pollution Liability Ins Agcy
Fac Site ID (OD): 99377872
Cleanup SiteID(OD): 11355
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Pollution Liability Insurance Agency
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.336125
Latitude (OD): 47.624853

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

3320,TEXACO STATION 632321472,TEXACO STATION BOREN AVE
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

---

317 | ***1 of 1*** | ***SE*** | ***0.87 / 4,614.53*** | ***16.46 / -89*** | ***Immunex Corporation 51 U***
51 UNIVERSITY ST
SEATTLE WA 98101 | ***CSCSL***

Fac Site ID: 11765899
Cleanup Site ID: 11818
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6060019454034
Longitude: -122.339452389883
Site Name: Immunex Corporation 51 U
Address: 51 UNIVERSITY ST
City: SEATTLE
Zip Code: 98101
Site Status (OD): Cleanup Started
Site Name (OD): Immunex Corporation 51 U
Address (OD): 51 UNIVERSITY ST
City (OD): SEATTLE
Zipcode (OD): 98101
Location (OD): ""
(47.606002, -122.339452)
Alternate Site Names: 51 University Street,IMMUNEX CORP
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 11765899
Cleanup SiteID(OD): 11818
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.339452
Latitude (OD): 47.606002

Contaminants Detail(s)

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

318 | ***1 of 2*** | ***ENE*** | ***0.88 / 4,639.38*** | ***97.40 / -8*** | ***Mastercraft Metal Finishing 1175 HARRISON ST SEATTLE WA 98109*** | ***CSCSL***

Fac Site ID: 51379913
Cleanup Site ID: 3590
Site Status: Awaiting Cleanup
Site Rank: 4 - Low-Moderate Risk
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6222
Longitude: -122.33362
Site Name: Mastercraft Metal Finishing
Address: 1175 HARRISON ST
City: SEATTLE
Zip Code: 98109
Site Status (OD): Awaiting Cleanup
Site Name (OD): Mastercraft Metal Finishing
Address (OD): 1175 HARRISON ST
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.6222, -122.33362)
Alternate Site Names: Mastercraft Metal Finishing Inc
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 51379913
Cleanup SiteID(OD): 3590
Site Rank (OD): 4 - Low-Moderate Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.33362
Latitude (OD): 47.6222

Contaminants Detail(s)

Contaminant Name: Metals Priority Pollutants
Groundwater:
Surfacewater: Suspected
Soil: Confirmed Above Cleanup Levels
Sediment:
Air: Suspected
Bedrock:

Contaminant Name: Corrosive Wastes
Groundwater:
Surfacewater: Suspected
Soil: Suspected
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Metals Priority Pollutants
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Corrosive Wastes
Contaminant Media: Surface Water
Contaminant Status: Suspected

Contaminant: Metals Priority Pollutants
Contaminant Media: Surface Water
Contaminant Status: Suspected

Contaminant: Metals Priority Pollutants
Contaminant Media: Air
Contaminant Status: Suspected

Contaminant: Corrosive Wastes
Contaminant Media: Soil
Contaminant Status: Suspected

---

318 | **2 of 2** | **ENE** | **0.88 / 4,639.38** | **97.40 / -8** | **Mastercraft Metal Finishing**
1175 HARRISON ST
SEATTLE WA 98109 | **HSL**

Fac Site ID: 51379913
Cleanup Site ID: 3590
Site Status: Awaiting Cleanup
Site Rank: 4 - Low-Moderate Risk
Has Inst Control:
Responsible Unit: Northwest
County: King
Region: Northwest
Latitude: 47.6222
Longitude: -122.33362
Latitude (OD): 47.6222
Longitude (OD): -122.33362
Current VCP:
Location (OD): "" (47.6222, -122.33362)
Alternate Site Names: Mastercraft Metal Finishing Inc
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Fac Site ID (OD): 51379913
Cleanup Site ID (OD): 3590
Site Status (OD): Awaiting Cleanup
Site Rank (OD): 4 - Low-Moderate Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Site Name (OD): Mastercraft Metal Finishing
Address (OD): 1175 HARRISON ST
City (OD): SEATTLE
ZIP code (OD): 98109
Past VCP:

Contaminants Detail(s)

Contaminant Name: Corrosive Wastes
Groundwater:
Surfacewater: Suspected
Air:
Sediment:
Soil: Suspected
Bedrock:

Contaminant Name: Metals Priority Pollutants
Groundwater:
Surfacewater: Suspected
Air: Suspected
Sediment:
Soil: Confirmed Above Cleanup Levels
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Corrosive Wastes
Contaminant Status: Suspected
Contaminant Media: Surface Water

Contaminant: Metals Priority Pollutants
Contaminant Status: Suspected
Contaminant Media: Surface Water

Contaminant: Metals Priority Pollutants
Contaminant Status: Confirmed Above Cleanup Levels
Contaminant Media: Soil

Contaminant: Corrosive Wastes
Contaminant Status: Suspected
Contaminant Media: Soil

Contaminant: Metals Priority Pollutants
Contaminant Status: Suspected
Contaminant Media: Air

---

319 | **1 of 1** | **E** | **0.88 / 4,646.91** | **120.99 / 15** | **Seattle Cancer Care Alliance House**
1216 JOHN ST
SEATTLE WA 98109 | **CSCSL**

Fac Site ID: 6661095
Responsible Unit: Northwest

Cleanup Site ID:	4847	**Fac Site ID (OD):**	6661095
Site Status:	Cleanup Started	**Cleanup SiteID(OD):**	4847
Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:	Yes	**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.332133
Latitude:	47.619669	**Latitude (OD):**	47.619669
Longitude:	-122.332133		

Site Name: Seattle Cancer Care Alliance House
Address: 1216 JOHN ST
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Seattle Cancer Care Alliance House
Address (OD): 1216 JOHN ST
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.619669, -122.332133)
Alternate Site Names: Seattle Cancer Care Alliance House (Off-Property),Seattle Cancer Care Alliance House (Property NFA)
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Benzene
Groundwater: Suspected
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Non-Halogenated Solvents
Groundwater: Suspected
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Suspected
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Below Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Non-Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Below Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

---

320 | **1 of 1** | **ENE** | **0.88 / 4,667.83** | **50.36 / -55** | **Staybridge Suite Even Hotel**
527 FAIRVIEW AVE N
SEATTLE WA 98109 | **CSCSL**

Fac Site ID:
Cleanup Site ID:
Site Status:
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County:
Region:
Latitude:
Longitude:
Site Name:
Address:
City:
Zip Code:
Site Status (OD): Cleanup Started
Site Name (OD): Staybridge Suite Even Hotel
Address (OD): 527 FAIRVIEW AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): "" (47.624048, -122.334848)
Alternate Site Names:
Data Source(s): Cleanup Sites (Open Data Portal)

Responsible Unit:
Fac Site ID (OD): 4747
Cleanup SiteID(OD): 13213
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Pollution Liability Insurance Agency
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.334848
Latitude (OD): 47.624048

---

321 | **1 of 2** | **ESE** | **0.89 / 4,673.80** | **147.42 / 42** | **Washington Athletic Club Garage**
1405 6TH AVE
SEATTLE WA 98101 | **CSCSL**

Fac Site ID: 65657666
Cleanup Site ID: 10062
Site Status: Cleanup Started
Site Rank: 3 - Moderate Risk
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6102849961216
Longitude: -122.333929325343
Site Name: Washington Athletic Club Garage
Address: 1405 6TH AVE
City: SEATTLE
Zip Code: 98101
Site Status (OD): Cleanup Started
Site Name (OD): Washington Athletic Club Garage

Responsible Unit: Northwest
Fac Site ID (OD): 65657666
Cleanup SiteID(OD): 10062
Site Rank (OD): 3 - Moderate Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.333929
Latitude (OD): 47.610285

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Address (OD): 1405 6TH AVE
City (OD): SEATTLE
Zipcode (OD): 98101
Location (OD): ""
(47.610285, -122.333929)
Alternate Site Names: Washington Athletic Club
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

321	2 of 2	ESE	0.89 / 4,673.80	147.42 / 42	**Washington Athletic Club Garage** **1405 6TH AVE** **SEATTLE WA 98101**	HSL

Fac Site ID: 65657666
Cleanup Site ID: 10062
Site Status: Cleanup Started
Site Rank: 3 - Moderate Risk
Has Inst Control:
Responsible Unit: Northwest
County: King
Region: Northwest
Latitude: 47.6102849961216
Longitude: -122.333929325343
Latitude (OD): 47.610285
Longitude (OD): -122.333929
Current VCP:
Location (OD): ""
(47.610285, -122.333929)
Alternate Site Names: Washington Athletic Club
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Fac Site ID (OD): 65657666
Cleanup Site ID (OD): 10062
Site Status (OD): Cleanup Started
Site Rank (OD): 3 - Moderate Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Site Name (OD): Washington Athletic Club Garage
Address (OD): 1405 6TH AVE
City (OD): SEATTLE
ZIP code (OD): 98101
Past VCP:

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Air:
Sediment:
Soil: Confirmed Above Cleanup Levels
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
322	1 of 1	E	0.89 / 4,680.61	129.68 / 24	Greyhound Denny Way 1250 DENNY WAY SEATTLE WA 98109	CSCSL

Fac Site ID:		**Responsible Unit:**	
Cleanup Site ID:		**Fac Site ID (OD):**	89512719
Site Status:		**Cleanup SiteID(OD):**	10976
Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:		**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:		**Region (OD):**	Northwest
Region:		**Longitude (OD):**	-122.33226
Latitude:		**Latitude (OD):**	47.61872
Longitude:			
Site Name:			
Address:			
City:			
Zip Code:			
Site Status (OD):	Cleanup Started		
Site Name (OD):	Greyhound Denny Way		
Address (OD):	1250 DENNY WAY		
City (OD):	SEATTLE		
Zipcode (OD):	98109		
Location (OD):	"" (47.61872, -122.33226)		
Alternate Site Names:			
Data Source(s):	Cleanup Sites (Open Data Portal)		

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Benzene
Contaminant Media:	Soil
Contaminant Status:	Confirmed Above Cleanup Levels
Contaminant:	Petroleum-Other
Contaminant Media:	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels
Contaminant:	Petroleum-Gasoline
Contaminant Media:	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels
Contaminant:	Petroleum-Diesel
Contaminant Media:	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels
Contaminant:	Petroleum-Diesel
Contaminant Media:	Soil
Contaminant Status:	Confirmed Above Cleanup Levels
Contaminant:	Halogenated Solvents
Contaminant Media:	Groundwater
Contaminant Status:	Suspected
Contaminant:	Benzene
Contaminant Media:	Groundwater
Contaminant Status:	Confirmed Above Cleanup Levels
Contaminant:	Petroleum-Other
Contaminant Media:	Soil
Contaminant Status:	Confirmed Above Cleanup Levels
Contaminant:	Halogenated Solvents
Contaminant Media:	Soil
Contaminant Status:	Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
323	1 of 1	E	0.90 / 4,730.26	161.02 / 55	Paramount Theatre 911 PINE ST SEATTLE WA 98101	CSCSL

Fac Site ID:	5025986	**Responsible Unit:**	Northwest
Cleanup Site ID:	2110	**Fac Site ID (OD):**	5025986
Site Status:	Awaiting Cleanup	**Cleanup SiteID(OD):**	2110
Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:		**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.331692
Latitude:	47.6136043978035	**Latitude (OD):**	47.613604
Longitude:	-122.331691717171		

Site Name: Paramount Theatre
Address: 911 PINE ST
City: SEATTLE
Zip Code: 98101
Site Status (OD): Awaiting Cleanup
Site Name (OD): Paramount Theatre
Address (OD): 911 PINE ST
City (OD): SEATTLE
Zipcode (OD): 98101
Location (OD): ""
(47.613604, -122.331692)
Alternate Site Names: SOUND TRANSIT PINE ST STUB TUNNEL
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
324	1 of 2	ENE	0.90 / 4,738.21	30.89 / -75	Seattle S Lake Union Park 1000 VALLEY ST 815 BOREN AVE N SEATTLE WA 98109	DELISTED SHWS

Delisted Confirmed and Suspected Contaminated Sites

Fac Site ID:	29938898	**Fac Site ID (OD):**	29938898
Cleanup Site ID:	8641	**Clnup Site ID (OD):**	8641
Site Status:	Cleanup Started	**Site Rank (OD):**	
Site Rank:		**Respon Unit (OD):**	Northwest
Current VCP:		**Has Env Coven (OD):**	
Past VCP:		**County (OD):**	King

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Has Inst Control:
Responsible Unit: Northwest
County: King
Region: Northwest
Latitude: 47.6265694719416
Longitude: -122.336715332226
Region (OD): Northwest
City (OD): SEATTLE
Zipcode (OD): 98109
Latitude (OD): 47.626569
Longitude (OD): -122.336715
Site Status (OD): Cleanup Started
Site Name (OD): Seattle S Lake Union Park
Address (OD): 1000 VALLEY ST 815 BOREN AVE N
Location (OD): "" (47.626569, -122.336715)
Alternate Site Names: Seattle City Dept of Admin SV,SEATTLE CITY OF BOREN AVE,SEATTLE CITY UST BOREN AVE
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)
Original Source: CSCS
Record Date: 13-SEP-2021

324	2 of 2	ENE	0.90 / 4,738.21	30.89 / -75	**Seattle S Lake Union Park** **1000 VALLEY ST 815 BOREN AVE N** **SEATTLE WA 98109**	CSCSL

Fac Site ID: 29938898
Cleanup Site ID: 8641
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6265694719416
Longitude: -122.336715332226
Responsible Unit: Northwest
Fac Site ID (OD): 29938898
Cleanup SiteID(OD): 8641
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.336715
Latitude (OD): 47.626569
Site Name: Seattle S Lake Union Park
Address: 1000 VALLEY ST 815 BOREN AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Seattle S Lake Union Park
Address (OD): 1000 VALLEY ST 815 BOREN AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): "" (47.626569, -122.336715)
Alternate Site Names: Seattle City Dept of Admin SV,SEATTLE CITY OF BOREN AVE,SEATTLE CITY UST BOREN AVE
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Non-Halogenated Solvents
Groundwater:
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Non-Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Suspected

325	1 of 1	E	0.90 / 4,757.37	140.15 / 34	**Tritell Parking Lot** **1821-1823 MINOR AVE** **SEATTLE WA 98101**	CSCSL

Fac Site ID: 22279988
Cleanup Site ID: 3478
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6172331252603
Longitude: -122.331596406889
Site Name: Tritell Parking Lot
Address: 1821-1823 MINOR AVE
City: SEATTLE
Zip Code: 98101
Site Status (OD): Awaiting Cleanup
Site Name (OD): Tritell Parking Lot
Address (OD): 1821-1823 MINOR AVE
City (OD): SEATTLE
Zipcode (OD): 98101

Responsible Unit: Northwest
Fac Site ID (OD): 22279988
Cleanup SiteID(OD): 3478
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.331596
Latitude (OD): 47.617233

Location (OD): ""
(47.617233, -122.331596)
Alternate Site Names: Kinects Tower,TRITELL LLC PARKING LOT
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Other Non-Halogenated Organics
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Non-Halogenated Solvents
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil

Contaminant Status: Remediated-Below

Contaminant: Non-Halogenated Solvents
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Non-Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Other Non-Halogenated Organics
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
326	1 of 1	SE	0.91 / 4,791.06	8.73 / -97	Central Seattle Waterfront PIERS 53-58 ALASKAN WAY SEATTLE WA 98101	CSCSL

Fac Site ID: 2553
Cleanup Site ID: 2545
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.60538
Longitude: -122.34013
Site Name: Central Seattle Waterfront
Address: PIERS 53-58 ALASKAN WAY
City: SEATTLE
Zip Code: 98101
Site Status (OD): Cleanup Started
Site Name (OD): Central Seattle Waterfront
Address (OD): PIERS 53-58 ALASKAN WAY
City (OD): SEATTLE
Zipcode (OD): 98101
Location (OD): ""
(47.60538, -122.34013)
Alternate Site Names: PIER 53 - 55
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 2553
Cleanup SiteID(OD): 2545
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.34013
Latitude (OD): 47.60538

Contaminants Detail(s)

Contaminant Name: Metals Priority Pollutants
Groundwater:
Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels
Air:

Bedrock:

Contaminant Name: Phenolic Compounds
Groundwater:
Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

Contaminant Name: Base/Neutral/Acid Organics
Groundwater:
Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

Contaminant Name: Halogenated Organics
Groundwater:
Surfacewater:
Soil:
Sediment: Suspected
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

Contaminant Name: Polychlorinated biPhenyls (PCB)
Groundwater:
Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Halogenated Organics
Contaminant Media: Sediment
Contaminant Status: Suspected

Contaminant: Phenolic Compounds
Contaminant Media: Sediment
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals Priority Pollutants
Contaminant Media: Sediment
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Base/Neutral/Acid Organics
Contaminant Media: Sediment
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Sediment
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polychlorinated biPhenyls (PCB)
Contaminant Media: Sediment
Contaminant Status: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Sediment
Contaminant Status: Confirmed Above Cleanup Levels

---

327 *1 of 2* *E* *0.91 / 4,826.28* *124.83 / 19* ***New Richmond Laundry***
224 PONTIUS ST N
SEATTLE WA 98109 ***CSCSL***

Fac Site ID: 53565712
Cleanup Site ID: 2118
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.62005
Longitude: -122.332827
Site Name: New Richmond Laundry
Address: 224 PONTIUS ST N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): New Richmond Laundry
Address (OD): 224 PONTIUS ST N
City (OD): SEATTLE
Zipcode (OD): 98109-5418
Location (OD): ""
(47.62005, -122.332827)
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 53565712
Cleanup SiteID(OD): 2118
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.332827
Latitude (OD): 47.62005

Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Suspected
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Suspected

---

327 *2 of 2* *E* *0.91 / 4,826.28* *124.83 / 19* ***Alley 24 West LLC***
224 PONTIUS AVE N
SEATTLE WA 98109 ***CSCSL***

Fac Site ID: 45455657
Cleanup Site ID: 3611
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King

Responsible Unit: Northwest
Fac Site ID (OD):
Cleanup SiteID(OD):
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD):
County (OD):
Region (OD):

Region: Northwest
Latitude: 47.620411863801
Longitude: -122.331451983434
Site Name: Alley 24 West LLC
Address: 224 PONTIUS AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD):
Site Name (OD):
Address (OD):
City (OD):
Zipcode (OD):
Location (OD):
Longitude (OD):
Latitude (OD):
Alternate Site Names: RICHMOND PEMCO,TOMLINSON INC PONTIUS AVE
Data Source(s): Confirmed and Suspected Contaminated Sites

Contaminants Detail(s)

Contaminant Name: Lead
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Metals Priority Pollutants
Groundwater: Remediated-Below
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Remediated-Below
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Arsenic
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Metals - Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
328	1 of 1	NNE	0.91 / 4,828.71	127.13 / 21	Freymuller Enterprises 1108 AURORA AVE N SEATTLE WA 98109	DELISTED SHWS

Delisted Contaminated/Hazardous Sites

Fac Site ID:	1996895	**WARM Rank:**	N
Cleanup Site ID:	5272	**Warm Rank Desc:**	
Brownfield?:		**Respon Section:**	Northwest
PSI?:		**County:**	King
VCP?:	Yes	**Region:**	Northwest
Past VCP:		**Latitude:**	47.629144037
Has Inst Control:		**Longitude:**	-122.34304894
Site Status:	Cleanup Started		
Alternate Site Names:			
Original Source:	CSCS		
Record Date:	14-MAR-2016		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
329	1 of 1	ENE	0.93 / 4,894.82	94.88 / -11	Cascade Supportive Housing 424 MINOR AVE N SEATTLE WA 98109	CSCSL

Fac Site ID:	10210	**Responsible Unit:**	Northwest
Cleanup Site ID:	1338	**Fac Site ID (OD):**	10210
Site Status:	Cleanup Started	**Cleanup SiteID(OD):**	1338
Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:	Yes	**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.332633
Latitude:	47.62279	**Latitude (OD):**	47.62279
Longitude:	-122.332633		
Site Name:	Cascade Supportive Housing		
Address:	424 MINOR AVE N		
City:	SEATTLE		
Zip Code:	98109		
Site Status (OD):	Cleanup Started		
Site Name (OD):	Cascade Supportive Housing		
Address (OD):	424 MINOR AVE N		
City (OD):	SEATTLE		
Zipcode (OD):	98109		
Location (OD):	"" (47.62279, -122.332633)		
Alternate Site Names:			
Data Source(s):	Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)		

Contaminants Detail(s)

Contaminant Name:	Petroleum Products-Unspecified
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Petroleum Products-Unspecified
Contaminant Media:	Soil
Contaminant Status:	Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
330	1 of 1	NE	0.93 / 4,895.52	24.27 / -81	Seattle City Parks NW Seaport 1002 VALLEY ST SEATTLE WA 98109	CSCSL

Fac Site ID: 14237126
Cleanup Site ID: 596
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6261076119906
Longitude: -122.336998072997
Site Name: Seattle City Parks NW Seaport
Address: 1002 VALLEY ST
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Seattle City Parks NW Seaport
Address (OD): 1002 VALLEY ST
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.626108, -122.336998)
Alternate Site Names:
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 14237126
Cleanup SiteID(OD): 596
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.336998
Latitude (OD): 47.626108

Contaminants Detail(s)

Contaminant Name: Bioassay Benthic Failures
Groundwater:
Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater:
Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

Contaminant Name: Metals Priority Pollutants
Groundwater:
Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

Contaminant Name: Polychlorinated biPhenyls (PCB)
Groundwater:
Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

Contaminant Name: Metals - Other
Groundwater:
Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater:
Surfacewater:
Soil:
Sediment: Confirmed Above Cleanup Levels
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Polychlorinated biPhenyls (PCB)
Contaminant Media: Sediment
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Bioassay Benthic Failures
Contaminant Media: Sediment
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Sediment
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals Priority Pollutants
Contaminant Media: Sediment
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals - Other
Contaminant Media: Sediment
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Sediment
Contaminant Status: Confirmed Above Cleanup Levels

331	*1 of 1*	*ENE*	*0.95 / 5,025.27*	*83.73 / -22*	***Kerner Scott Building*** ***510 MINOR AVE N*** ***SEATTLE WA 98109***	***CSCSL***

Fac Site ID: 4919889
Cleanup Site ID: 1509
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6235290157596
Longitude: -122.332670167434
Site Name: Kerner Scott Building
Address: 510 MINOR AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Kerner Scott Building
Address (OD): 510 MINOR AVE N
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.623529, -122.33267)
Alternate Site Names: KERNER SCOTT HOUSE
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 4919889
Cleanup SiteID(OD): 1509
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.33267
Latitude (OD): 47.623529

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

332	1 of 2	ESE	0.95 / 5,030.76	141.11 / 35	Qwest W00294 1200 3RD AVE SEATTLE WA 98104	CSCSL

Fac Site ID: 10733774
Cleanup Site ID: 7872
Site Status: Cleanup Started
Site Rank: 5 - Lowest Assessed Risk
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6074336423127
Longitude: -122.335134688113
Site Name: Qwest W00294
Address: 1200 3RD AVE
City: SEATTLE
Zip Code: 98104
Site Status (OD): Cleanup Started
Site Name (OD): US WEST SEATTLE
Address (OD): 1200 3RD AVE
City (OD): SEATTLE
Zipcode (OD): 98104
Location (OD): ""
(47.607434, -122.335135)
Alternate Site Names: 1200 THIRD AVE CO 070294,QWEST COMMUNICATIONS W00294,QWEST CORP W00294,Qwest Corporation W00294,US WEST COMMUNICATIONS INC W00294
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 10733774
Cleanup SiteID(OD): 7872
Site Rank (OD): 5 - Lowest Assessed Risk
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.335135
Latitude (OD): 47.607434

Contaminants Detail(s)

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Diesel
Contaminant Media: Soil

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminant Status: Confirmed Above Cleanup Levels

---

332 | **2 of 2** | **ESE** | **0.95 / 5,030.76** | **141.11 / 35** | **Qwest W00294**
1200 3RD AVE
SEATTLE WA 98104 | **HSL**

Fac Site ID:	10733774	**Fac Site ID (OD):**	10733774
Cleanup Site ID:	7872	**Cleanup Site ID (OD):**	7872
Site Status:	Cleanup Started	**Site Status (OD):**	Cleanup Started
Site Rank:	5 - Lowest Assessed Risk	**Site Rank (OD):**	5 - Lowest Assessed Risk
Has Inst Control:		**Has Env Coven (OD):**	
Responsible Unit:	Northwest	**Respon Unit (OD):**	Northwest
County:	King	**County (OD):**	King
Region:	Northwest	**Region (OD):**	Northwest
Latitude:	47.6074336423127	**Site Name (OD):**	US WEST SEATTLE
Longitude:	-122.335134688113	**Address (OD):**	1200 3RD AVE
Latitude (OD):	47.607434	**City (OD):**	SEATTLE
Longitude (OD):	-122.335135	**ZIP code (OD):**	98104
Current VCP:		**Past VCP:**	

Location (OD): ""
(47.607434, -122.335135)

Alternate Site Names: 1200 THIRD AVE CO 070294,QWEST COMMUNICATIONS W00294,QWEST CORP W00294,Qwest Corporation W00294,US WEST COMMUNICATIONS INC W00294

Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name:	Petroleum-Diesel	**Sediment:**	
Groundwater:		**Soil:**	Confirmed Above Cleanup Levels
Surfacewater:		**Bedrock:**	
Air:			

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Petroleum-Diesel	**Contaminant Media:**	Soil
Contaminant Status:	Confirmed Above Cleanup Levels		

---

333 | **1 of 1** | **ESE** | **0.96 / 5,045.15** | **173.38 / 68** | **Seattle Hilton Hotel Parking Garage**
1301 6TH AVE
SEATTLE WA 98101 | **CSCSL**

Fac Site ID:	56642815	**Responsible Unit:**	Northwest
Cleanup Site ID:	436	**Fac Site ID (OD):**	56642815
Site Status:	Cleanup Started	**Cleanup SiteID(OD):**	436
Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	Yes
Past VCP:	Yes	**Respon Unit (OD):**	Northwest
Has Inst Control:	Yes	**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.333107
Latitude:	47.6093094897802	**Latitude (OD):**	47.609309
Longitude:	-122.333106556596		
Site Name:	Seattle Hilton Hotel Parking Garage		
Address:	1301 6TH AVE		
City:	SEATTLE		
Zip Code:	98101		
Site Status (OD):	Cleanup Started		
Site Name (OD):	Seattle Hilton Hotel Parking Garage		
Address (OD):	1301 6TH AVE		
City (OD):	SEATTLE		
Zipcode (OD):	98101		

Location (OD): ""
(47.609309, -122.333107)

Alternate Site Names: AMPCO PARKING HILTON HOTEL GARAGE,Hilton Hotel Parking Garage,Seattle Hilton Hotel

Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Lead
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Other Non-Halogenated Organics
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Benzene
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Other Non-Halogenated Organics
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Benzene
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Lead
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Other Non-Halogenated Organics
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Lead
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Contaminant Media:	Soil					
Contaminant Status:	Confirmed Above Cleanup Levels					
334	1 of 2	E	0.96 / 5,063.88	130.25 / 24	PEMCO Property 221 YALE AVE SEATTLE WA 98109	DELISTED SHWS

Delisted Confirmed and Suspected Contaminated Sites

Fac Site ID:	27279158	**Fac Site ID (OD):**	27279158
Cleanup Site ID:	8536	**Clnup Site ID (OD):**	8536
Site Status:	Cleanup Started	**Site Rank (OD):**	
Site Rank:		**Respon Unit (OD):**	Northwest
Current VCP:		**Has Env Coven (OD):**	
Past VCP:		**County (OD):**	King
Has Inst Control:		**Region (OD):**	Northwest
Responsible Unit:	Northwest	**City (OD):**	SEATTLE
County:	King	**Zipcode (OD):**	98109-5430
Region:	Northwest	**Latitude (OD):**	47.62001
Latitude:	47.62001	**Longitude (OD):**	-122.331587
Longitude:	-122.331587		
Site Status (OD):	Cleanup Started		
Site Name (OD):	PEMCO Property		
Address (OD):	221 YALE AVE		
Location (OD):	"" (47.62001, -122.331587)		
Alternate Site Names:			
Data Source(s):	Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)		
Original Source:	CSCS		
Record Date:	13-SEP-2021		

334	2 of 2	E	0.96 / 5,063.88	130.25 / 24	Pemco Property 221 YALE AVE N SEATTLE WA 98109	CSCSL

Fac Site ID:	27279158	**Responsible Unit:**	Northwest
Cleanup Site ID:	8536	**Fac Site ID (OD):**	27279158
Site Status:	Cleanup Started	**Cleanup SiteID(OD):**	8536
Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:		**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.331587
Latitude:	47.6201018427445	**Latitude (OD):**	47.62001
Longitude:	-122.330675049554		
Site Name:	Pemco Property		
Address:	221 YALE AVE N		
City:	SEATTLE		
Zip Code:	98109		
Site Status (OD):	Cleanup Started		
Site Name (OD):	PEMCO Property		
Address (OD):	221 YALE AVE		
City (OD):	SEATTLE		
Zipcode (OD):	98109-5430		
Location (OD):	"" (47.62001, -122.331587)		
Alternate Site Names:			
Data Source(s):	Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Gasoline
Groundwater:	Suspected

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Suspected
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Suspected

---

335 | ***1 of 1*** | ***E*** | ***0.96 / 5,068.94*** | ***132.69 / 27*** | ***Overall Laundry***
200 222 YALE AVE N
SEATTLE WA 98109 | ***CSCSL***

Fac Site ID: 39131231
Cleanup Site ID: 1662
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6199215244553
Longitude: -122.331414609901
Site Name: Overall Laundry
Address: 200 222 YALE AVE N
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Overall Laundry
Address (OD): 200 222 YALE AVE N
City (OD): SEATTLE
Zipcode (OD): 98109-5429
Location (OD): ""
(47.619922, -122.331415)
Alternate Site Names: OVERALL LAUNDRY SERVICES INC,OVERALL LAUNDRY SERVICES INC SEATTLE
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 39131231
Cleanup SiteID(OD): 1662
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.331415
Latitude (OD): 47.619922

Contaminants Detail(s)

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Suspected
Surfacewater:

Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Suspected
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Suspected

---

336 | ***1 of 1*** | ***ENE*** | ***0.97 / 5,099.54*** | ***112.33 / 7*** | ***Seattle SD Warehouse 1255 Harrison St Seattle WA 98109*** | ***CSCSL***

Fac Site ID: 69141722
Cleanup Site ID: 10188
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP:
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6220356182888
Longitude: -122.332751897486
Site Name: Seattle SD Warehouse
Address: 1255 Harrison St
City: Seattle
Zip Code: 98109
Site Status (OD):
Site Name (OD):
Address (OD):
City (OD):
Zipcode (OD):
Location (OD):
Alternate Site Names: Block 11,Old School Warehouse,SEATTLE SCHOOL DIST 1 CENTRAL WH,Seattle School Dist 1 Sch Support Svc,SEATTLE SCHOOL DISTRICT 1 CENTRAL W H
Data Source(s): Confirmed and Suspected Contaminated Sites

Responsible Unit: Pollution Liability Ins Agcy
Fac Site ID (OD):
Cleanup SiteID(OD):
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD):
County (OD):
Region (OD):
Longitude (OD):
Latitude (OD):

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater:
Surfacewater:
Soil: Remediated-Below

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Sediment:
Air:
Bedrock:

Contaminant Name: Benzene
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
337	1 of 1	ENE	0.98 / 5,162.16	107.58 / 2	Tomlinson UST 101457 Block 10 414 420 Pontius Ave N & 1260 Harrison Seattle WA 98109	CSCSL

Fac Site ID: 83346748
Cleanup Site ID: 1903
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control:
County: King
Region: Northwest
Latitude: 47.6223670553995
Longitude: -122.331377495916
Site Name: Tomlinson UST 101457 Block 10
Address: 414 420 Pontius Ave N & 1260 Harrison
City: Seattle
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): Tomlinson UST 101457
Address (OD): 414 420 Pontius Ave N & 1260 Harrison
City (OD): Seattle
Zipcode (OD): 98109-5422
Location (OD): ""
(47.622367, -122.331377)
Alternate Site Names: Block 10 West,New Richmond Laundry UST F,TOMLINSON INC,TOMLINSON INC UST 101457,West Block 10 City Investors,West Bock 10 City Investors
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 83346748
Cleanup SiteID(OD): 1903
Site Rank (OD):
Has Env Coven (OD):
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.331377
Latitude (OD): 47.622367

Contaminants Detail(s)

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:

Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater:
Surfacewater:
Soil: Suspected
Sediment:
Air:
Bedrock:

Contaminant Name: Halogenated Solvents
Groundwater:
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Petroleum-Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Suspected

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

338	*1 of 1*	*NE*	*0.98 / 5,166.64*	*26.32 / -79*	***Seattle City South Lake Union Naval Reserve Ctr 860 TERRY AVE N SEATTLE WA 98109***	*CSCSL*

Fac Site ID: 22338497
Cleanup Site ID: 3494
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes

Responsible Unit: Northwest
Fac Site ID (OD): 22338497
Cleanup SiteID(OD): 3494
Site Rank (OD):
Has Env Coven (OD): Yes
Respon Unit (OD): Northwest

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Has Inst Control:	Yes	**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.32511
Latitude:	47.6276299874575	**Latitude (OD):**	47.60799
Longitude:	-122.336622040871		
Site Name:	Seattle City South Lake Union Naval Reserve Ctr		
Address:	860 TERRY AVE N		
City:	SEATTLE		
Zip Code:	98109		
Site Status (OD):	Cleanup Started		
Site Name (OD):	Seattle City South Lake Union Naval Reserve Ctr		
Address (OD):	860 TERRY AVE N		
City (OD):	SEATTLE		
Zipcode (OD):	98109		
Location (OD):	"" (47.60799, -122.32511)		
Alternate Site Names:	Museum of History and Industry,NAVAL RESERVE CENTER SEATTLE,NW Seaport Center for Wooden Boats, Seattle City South Lake Union,US NAVAL RESERVE READINESS CENTER,US NAVY COOPMINERON ELEVEN		
Data Source(s):	Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)		

Contaminants Detail(s)

Contaminant Name:	Petroleum Products-Unspecified
Groundwater:	Remediated
Surfacewater:	
Soil:	Remediated
Sediment:	
Air:	
Bedrock:	

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant:	Petroleum Products-Unspecified
Contaminant Media:	Groundwater
Contaminant Status:	Remediated
Contaminant:	Petroleum Products-Unspecified
Contaminant Media:	Soil
Contaminant Status:	Remediated

---

339 | ***1 of 1*** | ***WNW*** | ***0.98 / 5,195.13*** | ***27.75 / -78*** | ***Elliott Holding Company LLC 635 Elliott Ave W Seattle WA 98119*** | ***CSCSL***

Fac Site ID:	21722841	**Responsible Unit:**	Northwest
Cleanup Site ID:	7070	**Fac Site ID (OD):**	21722841
Site Status:	Cleanup Started	**Cleanup SiteID(OD):**	7070
Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:	Yes	**Respon Unit (OD):**	Northwest
Has Inst Control:		**County (OD):**	King
County:	King	**Region (OD):**	Northwest
Region:	Northwest	**Longitude (OD):**	-122.367068
Latitude:	47.6255329125611	**Latitude (OD):**	47.62454
Longitude:	-122.368003234463		
Site Name:	Elliott Holding Company LLC		
Address:	635 Elliott Ave W		
City:	Seattle		
Zip Code:	98119		
Site Status (OD):	Cleanup Started		
Site Name (OD):	Elliott Holding Company LLC		
Address (OD):	635 ELLIOTT AVE W		
City (OD):	SEATTLE		
Zipcode (OD):	98119		
Location (OD):	"" (47.62454, -122.367068)		

Alternate Site Names: DARIGOLD ELLIOTT AVENUE FORMER,DARIGOLD INC SEATTLE,DARIGOLD INC SEATTLE ELLIOT AV, DARIGOLD INC UST 9477,DARIGOLD SEATTLE ELLIOTT,Darigold Seattle Elliott (Property NFA),ELLIOTT HOLDING

Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Contaminants Detail(s)

Contaminant Name: Other Halogenated Organics
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Contaminant Name: Halogenated Organics
Groundwater: Remediated-Below
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Arsenic
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Diesel
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Polycyclic Aromatic Hydrocarbons
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Remediated-Below
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum-Gasoline
Groundwater: Remediated-Below
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Metals - Other
Groundwater: Confirmed Above Cleanup Levels
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:

Air:
Bedrock:

Contaminant Name: Metals Priority Pollutants
Groundwater: Remediated-Below
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Remediated-Below
Surfacewater:
Soil:
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Arsenic
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals - Other
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals Priority Pollutants
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Remediated-Below

Contaminant: Petroleum-Gasoline
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Metals - Other
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Arsenic
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Polycyclic Aromatic Hydrocarbons
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Diesel
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Other
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Other Halogenated Organics
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Petroleum-Gasoline
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Other Halogenated Organics
Contaminant Media: Groundwater
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Halogenated Organics
Contaminant Media: Soil
Contaminant Status: Remediated-Below

Contaminant: Halogenated Organics
Contaminant Media: Groundwater
Contaminant Status: Remediated-Below

Contaminant: Metals Priority Pollutants
Contaminant Media: Groundwater
Contaminant Status: Remediated-Below

340	1 of 1	E	0.99 / 5,247.01	146.48 / 41	**First Choice Business Machines** **1333 STEWART ST** **SEATTLE WA 98109**	CSCSL

Fac Site ID: 7028351
Cleanup Site ID: 1516
Site Status: Cleanup Started
Site Rank:
Current VCP:
Past VCP: Yes
Has Inst Control: Yes
County: King
Region: Northwest
Latitude: 47.6191659123304
Longitude: -122.32942693154
Site Name: First Choice Business Machines
Address: 1333 STEWART ST
City: SEATTLE
Zip Code: 98109
Site Status (OD): Cleanup Started
Site Name (OD): First Choice Business Machines
Address (OD): 1333 STEWART ST
City (OD): SEATTLE
Zipcode (OD): 98109
Location (OD): ""
(47.619166, -122.329427)
Alternate Site Names: AT&T WIRELESS DENNY WAY & STEWART,First Choice Business Machines (Off-Property),First Choice Business Machines (Property NFA)
Data Source(s): Confirmed and Suspected Contaminated Sites; Cleanup Sites (Open Data Portal)

Responsible Unit: Northwest
Fac Site ID (OD): 7028351
Cleanup SiteID(OD): 1516
Site Rank (OD):
Has Env Coven (OD): Yes
Respon Unit (OD): Northwest
County (OD): King
Region (OD): Northwest
Longitude (OD): -122.329427
Latitude (OD): 47.619166

Contaminants Detail(s)

Contaminant Name: Metals Priority Pollutants
Groundwater:
Surfacewater:
Soil: Below Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Petroleum Products-Unspecified
Groundwater: Suspected

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Contaminant Name: Non-Halogenated Solvents
Groundwater: Suspected
Surfacewater:
Soil: Confirmed Above Cleanup Levels
Sediment:
Air:
Bedrock:

Open Data Portal - Media and Contaminants as of 2021-09-15

Contaminant: Metals Priority Pollutants
Contaminant Media: Soil
Contaminant Status: Below Cleanup Levels

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

Contaminant: Non-Halogenated Solvents
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Petroleum Products-Unspecified
Contaminant Media: Groundwater
Contaminant Status: Suspected

Contaminant: Non-Halogenated Solvents
Contaminant Media: Soil
Contaminant Status: Confirmed Above Cleanup Levels

341	*1 of 3*	*ENE*	*1.00 / 5,263.38*	*132.34 / 27*	***PEMCO Parking Concrete Cutter*** ***300-320 Yale Ave N & 325 Eastlake Ave E*** ***SEATTLE WA 98109***	***DELISTED SHWS***

Delisted Contaminated/Hazardous Sites

Fac Site ID: 92673819
Cleanup Site ID: 11077
Brownfield?:
PSI?:
VCP?: Yes
Past VCP:
Has Inst Control:
Site Status: Cleanup Started
Alternate Site Names:
Original Source: CSCS
Record Date: 18-JAN-2018

WARM Rank: 3
Warm Rank Desc: Moderate Risk
Respon Section: Headquarters
County: King
Region: Northwest
Latitude: 47.6214166837133
Longitude: -122.329804820484

341	*2 of 3*	*ENE*	*1.00 / 5,263.38*	*132.34 / 27*	***PEMCO Parking Concrete Cutter*** ***300-320 Yale Ave N & 325 Eastlake Ave E*** ***SEATTLE WA 98109***	***DELISTED SHWS***

Delisted Contaminated/Hazardous Sites

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Fac Site ID:	92673819	**WARM Rank:**	3
Cleanup Site ID:	11077	**Warm Rank Desc:**	Moderate Risk
Brownfield?:		**Respon Section:**	Headquarters
PSI?:		**County:**	King
VCP?:	Yes	**Region:**	Northwest
Past VCP:		**Latitude:**	47.6214166837133
Has Inst Control:		**Longitude:**	-122.329804820484
Site Status:	Cleanup Started		
Alternate Site Names:			
Original Source:	HSL		
Record Date:	18-JAN-2018		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
341	3 of 3	ENE	1.00 / 5,263.38	132.34 / 27	Yale & Harrison Development 300-320 Yale Ave N & 325 Eastlake Ave E SEATTLE WA 98109	CSCSL

Fac Site ID:	92673819	**Responsible Unit:**	Northwest
Cleanup Site ID:	15444	**Fac Site ID (OD):**	
Site Status:	Cleanup Started	**Cleanup SiteID(OD):**	
Site Rank:		**Site Rank (OD):**	
Current VCP:		**Has Env Coven (OD):**	
Past VCP:	Yes	**Respon Unit (OD):**	
Has Inst Control:		**County (OD):**	
County:	King	**Region (OD):**	
Region:	Northwest	**Longitude (OD):**	
Latitude:	47.6214166837133	**Latitude (OD):**	
Longitude:	-122.329804820484		
Site Name:	Yale & Harrison Development		
Address:	300-320 Yale Ave N & 325 Eastlake Ave E		
City:	SEATTLE		
Zip Code:	98109		
Site Status (OD):			
Site Name (OD):			
Address (OD):			
City (OD):			
Zipcode (OD):			
Location (OD):			
Alternate Site Names:	PEMCO Ethylene Glycol Spill,Pemco Mutual Insurance Co,PEMCO MUTUAL INSURANCE COMPANY,PEMCO PARKING,PEMCO Parking Concrete Center,PEMCO Parking Concrete Cutter,PEMCO UST Removal 2012,Yale Ave N Parking Garage,Yale Ave N Parking Garage - Concrete Cutter,YALE ST PARKING GARAGE		
Data Source(s):	Confirmed and Suspected Contaminated Sites		

Contaminants Detail(s)

Contaminant Name:	Petroleum-Gasoline
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Benzene
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	
Bedrock:	

Contaminant Name:	Polycyclic Aromatic Hydrocarbons
Groundwater:	
Surfacewater:	
Soil:	Confirmed Above Cleanup Levels
Sediment:	
Air:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Bedrock:

Unplottable Summary

Total: 16 Unplottable sites

DB	Company Name/Site Name	Address	City	Zip	ERIS ID
ERNS		CLAY ST ***NRC Report No:*** 629879	SEATTLE WA		806964919
ERTS		2ND AVE	SEATTLE WA		880942288
ERTS	BECLAN PLACE PLAT	NE 2ND PL	RENTON WA		880962921
ERTS	Bank of America	2nd Street	YAKIMA WA		880971550
ERTS	PIER 90, PORT OF SEATTLE	WESTERN AVE	SEATTLE WA		880990691
ERTS	BETWEEN A ST & YAKIMA AVE	2ND AVE	YAKIMA WA		881021127
ERTS	CSO Outfall 174	2nd Ave NW	Seattle WA		893397040
ERTS		2ND STREET	KENT WA		880923288
ICR	COTTAGE PROPERTIES	VINE ST	SEATTLE WA	98121	827258292
SPILLS		2ND AVE ***Incident ID*** **|** ***Incident Date:*** 646062 **|**	SEATTLE WA		891759799
SPILLS		2ND AVE S ***Incident ID*** **|** ***Incident Date:*** 624269 **|**	SEATTLE WA		891784905
SPILLS		2ND AVE	YAKIMA WA		891799758

Incident ID **|** ***Incident Date:*** 623974 |

SPILLS		WESTERN AVE	SEATTLE WA	891804602
		Incident ID **|** ***Incident Date:*** 529378		
SPILLS		DENNY RD	SEATTLE WA	891849152
		Incident ID **|** ***Incident Date:*** 646897		
SPILLS	ELLIOTT BAY	WESTERN AVE	SEATTLE WA	891692888
		Incident ID **|** ***Incident Date:*** 529378	10/2/2002	
SPILLS		3RD AVENUE	SEATTLE WA	891751003
		Incident ID **|** ***Incident Date:*** 633802		

Unplottable Report

Site:

CLAY ST SEATTLE WA

ERNS

NRC Report No:	629879	***Latitude Degrees:***	
Type of Incident:	RAILROAD NON-RELEASE	***Latitude Minutes:***	
Incident Cause:	UNKNOWN	***Latitude Seconds:***	
Incident Date:	21-Nov-2002 23:30:00	***Longitude Degrees:***	
Incident Location:	NORTH PORTAL RAILROAD STATION	***Longitude Minutes:***	
Incident Dtg:	OCCURRED	***Longitude Seconds:***	
Distance from City:		***Lat Quad:***	
Distance Units:		***Long Quad:***	
Direction from City:		***Location Section:***	
Location County:	KING	***Location Township:***	
Potential Flag:	No	***Location Range:***	
Year:	Year 2002 Reports		

Description of Incident: CALLER REPORTS THAT A FREIGHT TRAIN STRUCK AND KILLED A PEDESTRIAN AT A GRADE CROSSING.

Calls Information

Date Time Received:	22-Nov-2002 03:04:31	***Responsible City:***	
Date Time Complete:	22-Nov-2002 03:11:31	***Responsible State:***	XX
Call Type:	INC	***Responsible Zip:***	
Resp Company:		***Source:***	TELEPHONE
Resp Org Type:	UNKNOWN		

Incident Information

Tank ID:		***Building ID:***	
Tank Regulated:	U	***Location Area ID:***	
Tank Regulated By:		***Location Block ID:***	
Capacity of Tank:		***OCSG No:***	
Capacity Tank Units:		***OCSP No:***	
Description of Tank:		***State Lease No:***	
Actual Amount:		***Pier Dock No:***	
Actual Amount Units:		***Berth Slip No:***	
Tank Above Ground:	ABOVE	***Brake Failure:***	N
NPDES:		***Airbag Deployed:***	
NPDES Compliance:	U	***Transport Contain:***	U
Init Contin Rel No:		***Location Subdiv:***	SCENIC
Contin Rel Permit:		***Platform Rig Name:***	
Contin Release Type:		***Platform Letter:***	
Aircraft ID:		***Allision:***	N
Aircraft Runway No:		***Type of Structure:***	
Aircraft Spot No:		***Structure Name:***	
Aircraft Type:	UNKNOWN	***Structure Oper:***	U
Aircraft Model:		***Transit Bus Flag:***	
Aircraft Fuel Cap:		***Date Time Norm Serv:***	
Aircraft Fuel Cap U:		***Serv Disrupt Time:***	
Aircraft Fuel on Brd:		***Serv Disrupt Units:***	
Aircraft Fuel OB U:		***CR Begin Date:***	
Aircraft Hanger:		***CR End Date:***	
Road Mile Marker:		***CR Change Date:***	
Power Gen Facility:	U	***FBI Contact:***	
Generating Capacity:		***FBI Contact Dt Tm:***	
Type of Fixed Obj:	UNKNOWN	***Passenger Handling:***	
Type of Fuel:		***Passenger Route:***	XXX
DOT Crossing No:	085413E	***Passenger Delay:***	XXX
DOT Regulated:	U	***Sub Part C Test Req:***	XXX
Pipeline Type:		***Conductor Test:***	

Pipeline Abv Ground:	ABOVE	***Engineer Test:***	
Pipeline Covered:	U	***Trainman Test:***	
Exposed Underwater:	N	***Yard Foreman Test:***	
Railroad Hotline:		***RCL Operator Test:***	
Railroad Milepost:	1.68	***Brakeman Test:***	
Grade Crossing:	N	***Train Dispat Test:***	
Crossing Device Ty:	GATES/LIGHTS/BELLS	***Signalman Test:***	
Ty Vehicle Involved:		***Oth Employee Test:***	
Device Operational:	Y	***Unknown Test:***	

Incident Details Information

Release Secured:	U	***State Agen Report No:***	NO REPORT #
Release Rate:		***State Agen on Scene:***	POLICE AND FIRE
Release Rate Unit:		***State Agen Notified:***	WA EMERGENCY OPERATION CENTER
Release Rate Rate:		***Fed Agency Notified:***	
Est Duration of Rel:		***Oth Agency Notified:***	
Desc Remedial Act:	INVESTIGATION UNDERWAY	***Body of Water:***	
Fire Involved:	N	***Tributary of:***	
Fire Extinguished:	U	***Near River Mile Make:***	
Any Evacuations:	N	***Near River Mile Mark:***	
No Evacuated:		***Offshore:***	N
Who Evacuated:		***Weather Conditions:***	
Radius of Evacu:		***Air Temperature:***	
Any Injuries:	N	***Wind Direction:***	
No. Injured:		***Wind Speed:***	
No. Hospitalized:		***Wind Speed Unit:***	
No. Fatalities:	1	***Water Supp Contam:***	U
Any Fatalities:	Y	***Water Temperature:***	
Any Damages:	N	***Wave Condition:***	
Damage Amount:		***Current Speed:***	
Air Corridor Closed:	N	***Current Direction:***	
Air Corridor Desc:		***Current Speed Unit:***	
Air Closure Time:		***EMPL Fatality:***	
Waterway Closed:	N	***Pass Fatality:***	
Waterway Desc:		***Community Impact:***	N
Waterway Close Time:		***Passengers Transfer:***	UNK
Road Closed:	N	***Passenger Injuries:***	
Road Desc:		***Employee Injuries:***	
Road Closure Time:		***Occupant Fatality:***	
Road Closure Units:		***Sheen Size:***	
Closure Direction:		***Sheen Size Units:***	
Major Artery:	No	***Sheen Size Length:***	
Track Closed:	N	***Sheen Size Length U:***	
Track Desc:		***Sheen Size Width:***	
Track Closure Time:		***Sheen Size Width U:***	
Track Closure Units:		***Sheen Color:***	
Track Close Dir:		***Dir of Sheen Travel:***	
Media Interest:	NONE	***Sheen Odor Desc:***	
Medium Desc:	RAIL REPORT (N/A)	***Duration Unit:***	
Addl Medium Info:		***Additional Info:***	LOCAL POLICE ARE TREATING THIS INCIDENT AS A SUICIDE.

Site:

2ND AVE SEATTLE WA

ERTS

Incident ID:	662828	***Latitude:***	
Incident Date:	2016-02-10	***Longitude:***	
County:	KING		
Location:			

Initial Report Details

Initial Report Substance Name:	
Initial Report Subst Catego:	
Initial Report Subst Quanti:	
Initial Report Substance Unit:	
Initial Report Medium Name:	Storm drain pipe

Initial Report Medium Category: Water
Initial Report Cause Category: Equipment failure
Initial Report Cause Name: Unknown
Initial Report Source Name: Truck
Initial Report Source Category: Vehicle
Initial Report Activity Name:
Initial Report Comment Desc: CALLER IS REPORTING THAT SEVERAL SEMI TRUCKS ARE P

Follow up Details

ERTS Follow up No: 150345
Follow up Substance Name:
Follow up Substance Quantity:
Follow up Subst Unit of Meas:
Follow up Cause Name: Unknown
Follow up Medium Name: Storm drain pipe
Follow up Source Nname: Truck
Follow up Activity Name:

Potential Details

Pot Resp Party First Name:
Pot Resp Prty Last Name:
Potentially Resp Party Org: TRI-PAC

Follow up Comments

Follow up Comment:

ERTS Number 662828 - From: Haberman, Dave [mailto:Dave.Haberman@kingcounty.gov]
Sent: Thursday, February 18, 2016 2:57 PM
To: Sacayanan, Tamara L. (ECY) <TSAC461@ECY.WA.GOV>; McCrea, Rachel (ECY) <rmcc461@ECY.WA.GOV>
Cc: Magnuson, Patricia <Patricia.Magnuson@kingcounty.gov>; Strong, Despina <Despina.Strong@kingcounty.gov>; Tiffany, Bruce <Bruce.Tiffany@kingcounty.gov>; Girard, Arnaud <Arnaud.Girard@kingcounty.gov>; Abbasi, Hamid (Ed) <Ed.Abbasi@kingcounty.gov>
Subject: RE: You've got ERTS! 662828 Duwamish FYI

This is in a combined sewer area and King County Industrial Waste will follow up.

Dave Haberman
Industrial Waste Compliance Investigator

Phone 206-477-5465
Fax 206-263-3001

The highest education is that which does not merely give us information but makes our life in harmony with all existence. – Rabindranath Tagore

From: Strong, Despina
Sent: Tuesday, February 16, 2016 1:51 PM
To: Haberman, Dave
Cc: Magnuson, Patricia
Subject: FW: You've got ERTS! 662828 Duwamish FYI

FYI

Despina Strong, Ph.D
Industrial Waste Program Manager
despina.strong@kingcounty.gov
206-477-5444

From: Cooper, Betsy
Sent: Tuesday, February 16, 2016 1:28 PM
To: Navetski, Doug; Strong, Despina
Cc: Phillips, John; Kaufman-Una, Susan; Knapp, Tiffany
Subject: FW: You've got ERTS! 662828 Duwamish FYI

Good Afternoon folks,
Interesting email from our Ecology Permit Manager.
I would presume that since this event occurred in Seattle that the Seattle spill response folks would respond if notified. And that they or Ecology would contact the company mentioned. Not seeing any authority or interface for KC IW or SW folks today.

Is my interpretation correct?

Betsy

From: McKone, Shawn (ECY) [mailto:SHMC461@ECY.WA.GOV]
Sent: Tuesday, February 16, 2016 11:33 AM
To: Cooper, Betsy; Meyer, Betty
Cc: McCrea, Rachel (ECY)
Subject: FW: You've got ERTS! 662828 Duwamish FYI

Hi Betsy and Betty,
Rachel McCrea forwarded this ERTS to me last week and I thought I would forward to both of you as a FYI. The incident reported is in the Brandon Basin and is a good example of where pollution prevention source control BMPs required by NMC #7 (current West Point and upcoming SPU permits) would play a role. This was referred to Eric Autry at SPU, but I'm not sure what actions he has taken.

Shawn

Follow up Comment:

ERTS Number 662828 - Historic Investigator Contact Information - FirstName: DESPINA STRONG MiddleName: LastName: KING CO INDUSTRIAL WASTE PROGRAM - SANITARY SEWER OrganizationName: INDUSTRIAL WASTE PROGRAM WorkLocation: NWRO

Follow up Comment:

ERTS Number 662828 - Historic Referral Contact Information - ReferralDate: 2016-02-19 FirstName: DESPINA STRONG MiddleName: LastName: KING CO INDUSTRIAL WASTE PROGRAM - SANITARY SEWER Email: EMAIL KING CO INDUSTRIAL WASTE PROGRAM PhoneNumber: (206) 263-3010 OrganizationName: INDUSTRIAL WASTE PROGRAM WorkLocation: NWRO

Follow up Comment:

ERTS Number 662828 - Historic Referral Contact Information - ReferralDate: 2016-02-10 FirstName: KIMBERLY MiddleName: LastName: MEDICUS Email: KMED461@ECY.WA.GOV;4254571964@OnPage.com PhoneNumber: (425) 649-7291 OrganizationName: SPILLS, PREVENTION, PREPAREDNESS AND RESPONSE WorkLocation: NWRO

Follow up Comment:

ERTS Number 662828 - Historic Referral Contact Information - ReferralDate: 2016-02-10 FirstName: RACHEL MiddleName: LastName: MCCREA Email: RMCC461@ECY.WA.GOV PhoneNumber: (425) 649-7223 OrganizationName: WATER QUALITY WorkLocation: NWRO

Follow up Comment:

ERTS Number 662828 - Historic Referral Contact Information - ReferralDate: 2016-02-10 FirstName: ERIC AUTRY MiddleName: LastName: SEATTLE PUBLIC UTIL WQ Email: Email Seattle WQ PhoneNumber: (206) 684-7988 OrganizationName: SEATTLE WorkLocation: PUBLIC UTILITIES

Initial Comments

Initial Report Comment:

ERTS Number 662828 - CALLER IS REPORTING THAT SEVERAL SEMI TRUCKS ARE PARKED ON THE STREET, THERE IS A LARGE BLUE ONE THAT IS FREELY FLOWING ANTI-FREEZE AFTER A COMPANY WAS DOING MAINTENCE ON THE VEHICLE AND THEN LEFT. THERE ARE POOLS OF ANTI-FREEZE ON THE ROADWAY AND LIKELY WENT DOWN STORM DRAINS. CALLER SAYS A COMPANY CALLED TRI-PAK USES THE ROADWAY FOR REGULAR MAINTENANCE AND THERE IS OFTEN VARIOUS VEHICLE FLUIDS ON THE ROAD AND GETTING WASHED INTO DRAINS. CALLER HAS SPOKEN TO THE COMPANY PREVIOUSLY BUT NO CHANGES HAVE OCCURRED.

LICENSE PLATE: C48829B

Site: ***BECLAN PLACE PLAT***
NE 2ND PL RENTON WA

ERTS

Incident ID: 649367
Incident Date: 2014-06-09
County: KING
Location: BECLAN PLACE PLAT
Latitude:
Longitude:

Initial Report Details

Initial Report Substance Name:	Undetermined
Initial Report Subst Catego:	Historical
Initial Report Subst Quanti:	
Initial Report Substance Unit:	
Initial Report Medium Name:	Catch Basin
Initial Report Medium Category:	Historical
Initial Report Cause Category:	Accident
Initial Report Cause Name:	Other
Initial Report Source Name:	Construction site
Initial Report Source Category:	Facility
Initial Report Activity Name:	Construction, building
Initial Report Comment Desc:	REPORT RECEIVED VIA EMAIL: This is an ERTS noti

Follow up Details

ERTS Follow up No:	137814
Follow up Substance Name:	Undetermined
Follow up Substance Quantity:	
Follow up Subst Unit of Meas:	
Follow up Cause Name:	Other
Follow up Medium Name:	Catch Basin
Follow up Source Nname:	Construction site
Follow up Activity Name:	Construction, building

Follow up Details

ERTS Follow up No:	137687
Follow up Substance Name:	Undetermined
Follow up Substance Quantity:	
Follow up Subst Unit of Meas:	
Follow up Cause Name:	Other
Follow up Medium Name:	Catch Basin
Follow up Source Nname:	Construction site
Follow up Activity Name:	Construction, building

Follow up Details

ERTS Follow up No:	137694
Follow up Substance Name:	Undetermined
Follow up Substance Quantity:	
Follow up Subst Unit of Meas:	
Follow up Cause Name:	Other
Follow up Medium Name:	Catch Basin
Follow up Source Nname:	Construction site
Follow up Activity Name:	Construction, building

Potential Details

Pot Resp Party First Name:	
Pot Resp Prty Last Name:	
Potentially Resp Party Org:	QUADRANT HOMES

Follow up Comments

Follow up Comment:

ERTS Number 649367 - From: Edward Mulhern [mailto:EMulhern@Rentonwa.gov]
Sent: Thursday, June 12, 2014 8:56 AM
To: Sacayanan, Tamara L. (ECY)
Cc: Richard W Marshall; Neil R. Watts; Craig Burnell; Pat Miller; Walters, Tracie (ECY)
Subject: Update to ERTS 649367 (Beclan Place Plat)

Tami,

This is an update to ERTS 649367

Incident location: Beclan Place Plat, NE 2nd Pl. (between Jericho Ave. NE & Hoquiam Ave. NE)

The home builder (Quadrant Homes) has completed cleaning the impacted drainage system.

Sincerely,
Edward Mulhern
Civil Engineer III
City of Renton | Public Works | Surface Water Utility
1055 S. Grady Way | 5th Floor | Renton, WA 98057
Direct: 425.430.7323
FAX: 425.430.7241

Follow up Comment:

ERTS Number 649367 - Historic Investigator Contact Information - FirstName: RICHARD MARSHALL MiddleName: LastName: RENTON PUB WKS OrganizationName: RENTON WorkLocation: PUBLIC WORKS

Follow up Comment:

ERTS Number 649367 - I put a call into the reporting party, Ed Mulhern, City of Renton. Waiting for a call back.

UPDATE 6/12/14:

From: Edward Mulhern [mailto:EMulhern@Rentonwa.gov]
Sent: Thursday, June 12, 2014 8:56 AM
To: Sacayanan, Tamara L. (ECY)
Cc: Richard W Marshall; Neil R. Watts; Craig Burnell; Pat Miller; Walters, Tracie (ECY)
Subject: Update to ERTS 649367 (Beclan Place Plat)

Tami,

This is an update to ERTS 649367

Incident location: Beclan Place Plat, NE 2nd Pl. (between Jericho Ave. NE & Hoquiam Ave. NE)

The home builder (Quadrant Homes) has completed cleaning the impacted drainage system.

Sincerely,
Edward Mulhern
Civil Engineer III
City of Renton | Public Works | Surface Water Utility
1055 S. Grady Way | 5th Floor | Renton, WA 98057
Direct: 425.430.7323
FAX: 425.430.7241

Follow up Comment:

ERTS Number 649367 - Historic Investigator Contact Information - FirstName: TRACIE MiddleName: LastName: WALTERS OrganizationName: WATER QUALITY WorkLocation: NWRO

Follow up Comment:

ERTS Number 649367 - Renton response under Phase II Municipal Stormwater Permit requirements.

Also forwarded ERTS to CSGP inspectors.

Follow up Comment:

ERTS Number 649367 - Historic Investigator Contact Information - FirstName: RACHEL MiddleName: LastName: MCCREA OrganizationName: WATER QUALITY WorkLocation: NWRO

Follow up Comment:

ERTS Number 649367 - Historic Referral Contact Information - ReferralDate: 2014-06-11 FirstName: TRACIE MiddleName: LastName: WALTERS Email: EMAIL NW STRM H20 PhoneNumber: (425) 649-4484 OrganizationName: WATER QUALITY WorkLocation: NWRO

Follow up Comment:

ERTS Number 649367 - Historic Referral Contact Information - ReferralDate: 2014-06-10 FirstName: RACHEL MiddleName: LastName: MCCREA Email: RMCC461@ECY.WA.GOV PhoneNumber: (425) 649-7223 OrganizationName: WATER QUALITY WorkLocation: NWRO

Follow up Comment:

ERTS Number 649367 - Historic Referral Contact Information - ReferralDate: 2014-06-10 FirstName: RICHARD MARSHALL MiddleName: LastName: RENTON PUB WKS Email: RWMarshall@RentonWa.gov; emulhern@rentonwa.gov PhoneNumber: (425) 430-7400 OrganizationName: RENTON WorkLocation: PUBLIC WORKS

Initial Comments

Initial Report Comment:

ERTS Number 649367 - REPORT RECEIVED VIA EMAIL:

This is an ERTS notification.

Incident location: Beclan Place Plat, NE 2nd Pl. (between Jericho Ave. NE & Hoquiam Ave. NE)

Incident Observed by: Edward Mulhern, City of Renton, Public Works, 425-430-7323

Incident Date: 6-9-14

There is new house construction activity at Beclan Place Plat. While inspecting the Plat stormwater facility detention pond and catch basins per the S5. C4.c.iv requirement, I observed concrete wash-off material in the sums of several catch basins. No wash-off material was observed in the pond.

Renton staff notified the Superintendent for the home builder (Quadrant Homes), and directed him to immediately remove all concrete material from of the CB and connecting pipes.

EMAIL AVAILABLE AT:
X:\NWRO ERTS\ERTS Online Forms\2014\EMAILS

Site: ***Bank of America***
2nd Street YAKIMA WA

ERTS

Incident ID:	606639	***Latitude:***	
Incident Date:		***Longitude:***	
County:	YAKIMA		
Location:	Bank of America		

Initial Report Details

Initial Report Substance Name:	Undetermined
Initial Report Subst Catego:	Historical
Initial Report Subst Quanti:	
Initial Report Substance Unit:	Unknown
Initial Report Medium Name:	Undetermined
Initial Report Medium Category:	Historical
Initial Report Cause Category:	Human error
Initial Report Cause Name:	Unknown
Initial Report Source Name:	Undetermined
Initial Report Source Category:	Historical
Initial Report Activity Name:	Unknown
Initial Report Comment Desc:	JOHNIE TOOK CALL FROM BILL ALMON JR (509) 961-7575

Follow up Details

ERTS Follow up No:	89632
Follow up Substance Name:	Water
Follow up Substance Quantity:	1
Follow up Subst Unit of Meas:	Other
Follow up Cause Name:	Other
Follow up Medium Name:	Undetermined

Follow up Source Nname: Commercial/Industrial facility
Follow up Activity Name: Routine/Normal operations

Potential Details

Pot Resp Party First Name:
Pot Resp Prty Last Name:
Potentially Resp Party Org: UNKNOWN

Follow up Comments

Follow up Comment:

ERTS Number 606639 - Historic Investigator Contact Information - FirstName: WILL MiddleName: LastName: STRAND OrganizationName: SPILLS, PREVENTION, PREPAREDNESS AND RESPONSE WorkLocation: CRO

Follow up Comment:

ERTS Number 606639 - Historic Referral Contact Information - ReferralDate: 2008-06-25 FirstName: WILL MiddleName: LastName: STRAND Email: WSTR461@ECY.WA.GOV PhoneNumber: (509) 454-7899 OrganizationName: SPILLS, PREVENTION, PREPAREDNESS AND RESPONSE WorkLocation: CRO

Follow up Comment:

ERTS Number 606639 - The realtor is acting on behalf of the building owner.
The room that was flooded was in a deep basement. 2 inches of water entered the room through the sump pumps. Picatti was called out to check the sump pumps, then ServiceMaster`s was called to pump out water, clean and disinfect.
Several days later, Picatti`s called back and stated that they thought the flooding was sewage, not groundwater and they needed to replace the electrical panel.
Realtor said no because the panel was never affected. Picatti told him that if they didn`t agree to replace the panel in 10 days then they would call Dept. of Ecology and report a biohazard spill. The realtor was upset because the price of the panel had doubled in the time that he was disagreeing with the Picatti desire to replace the panel. He wanted to know if something like this was actually something that he should have reported and if Picatti reported it what would happen as a result.
After some phone calls, I determined that L&I had no interest in requiring a electrical panel replacement unless it got wet, regardless of the material in the building.
I attempted to call county Health, but could not reach anyone.
I called the local wastewater treatment plant and the local landfill (has a treatment lagoon for disposal). ServiceMaster`s is not able to legally dispose of sewage water, only a certified septic pumper can do that (implying it was not sewage water).

Called realtor back, gave him L&I contact and suggested he double check with Health, but that there would be no Ecology action if this were reported to us.
End.

Initial Comments

Initial Report Comment:

ERTS Number 606639 - JOHNIE TOOK CALL FROM BILL ALMON JR (509) 961-7575

BILL HAS A CUSTOMER THAT OWNS A BUILDING
THAT BUILDING HAD A FLOOD, DON`T KNOW IF IT WAS GROUNDWATER OR SEWAGE
CALLED IN ELECTRICAL-PLUMBING CONTRACTOR, THEY CHECKED ALL THE PUMPS
THEY ALSO DRAINED AND DISINFECTED THE AREA
AREA IS CLEANED UP AND NO TESTS WERE TAKEN TO DETERMINE WHAT THE FLOOD WAS, GROUNDWATER OR SEWAGE

NOW ELECTRICAL-PLUMBING CONTRACTOR IS TELLLING BILL`S CUSTOMER (WHO OWNS THE BUILDING) THAT THEY MUST PAY TO REPLACE AN ELECTRICAL PANEL, OR THEY WILL REPORT THEM TO ECOLOGY AS HAVING HAD A HAZARDOUS SPILL

BILL ALMON WANTS TO KNOW - IF ECOLOGY RECEIVES A COMPLAINT, WHAT WILL ECOLOGY DO?

Site: ***PIER 90, PORT OF SEATTLE***
WESTERN AVE SEATTLE WA

ERTS

Incident ID: 529378
Incident Date: 2002-10-02
Latitude:
Longitude:

County: KING
Location: PIER 90, PORT OF SEATTLE

Initial Report Details

Initial Report Substance Name: Diesel oil/Marine gas
Initial Report Subst Catego: Oil
Initial Report Subst Quanti: 5
Initial Report Substance Unit: U.S. gallons
Initial Report Medium Name: Undetermined
Initial Report Medium Category: Historical
Initial Report Cause Category: Equipment failure
Initial Report Cause Name: Unknown
Initial Report Source Name: Undetermined
Initial Report Source Category: Historical
Initial Report Activity Name: Construction, other
Initial Report Comment Desc: REPORT OF SPILL THAT DID NOT HIT WATER. QUANTITY

Follow up Details

ERTS Follow up No: 46002
Follow up Substance Name: Diesel oil/Marine gas
Follow up Substance Quantity:
Follow up Subst Unit of Meas:
Follow up Cause Name: Unknown
Follow up Medium Name: Undetermined
Follow up Source Nname: Undetermined
Follow up Activity Name: Construction, other

Potential Details

Pot Resp Party First Name:
Pot Resp Prty Last Name:
Potentially Resp Party Org: EMERALD SERVICES

Follow up Comments

Follow up Comment:

ERTS Number 529378 - Historic Investigator Contact Information - FirstName: DICK MiddleName: LastName: WALKER OrganizationName: SPILLS, PREVENTION, PREPAREDNESS AND RESPONSE WorkLocation: NWRO

Follow up Comment:

ERTS Number 529378 - Historic Referral Contact Information - ReferralDate: 2002-10-02 FirstName: DICK MiddleName: LastName: WALKER Email: rwal461@ecy.wa.gov PhoneNumber: (425) 649-7116 OrganizationName: SPILLS, PREVENTION, PREPAREDNESS AND RESPONSE WorkLocation: NWRO

Initial Comments

Initial Report Comment:

ERTS Number 529378 - REPORT OF SPILL THAT DID NOT HIT WATER.
QUANTITY OF MATERIAL IS 2-5 GALLONS DIESEL, DURATION OF SPILL IS 5-10 SECONDS. IT HIT THE ASPHALT. THEY WERE PUMPING FROM A HARD LINE AND TAKING APART THE PIER. A 3/4`` BALL ON A VACUUM TRUCK BLEW OUT.
PLEASE CALL HER IF YOU HAVE QUESTIONS.

Site: ***BETWEEN A ST & YAKIMA AVE 2ND AVE YAKIMA WA***

ERTS

Incident ID: 623974
Incident Date: 2010-12-10
County: YAKIMA
Latitude:
Longitude:

Location: BETWEEN A ST & YAKIMA AVE

Initial Report Details

Initial Report Substance Name: Waste water
Initial Report Subst Catego: Water
Initial Report Subst Quanti:
Initial Report Substance Unit: Unknown
Initial Report Medium Name: Surface water-Fresh
Initial Report Medium Category: Water
Initial Report Cause Category: Human error
Initial Report Cause Name: Policy/Procedure; Incorrect
Initial Report Source Name: Construction site
Initial Report Source Category: Facility
Initial Report Activity Name: Construction, other
Initial Report Comment Desc: INFO RECEIVED BY EMAIL FROM RAY LATHAM, WQ:

Com

Follow up Details

ERTS Follow up No: 108734
Follow up Substance Name: Waste water
Follow up Substance Quantity:
Follow up Subst Unit of Meas: Unknown
Follow up Cause Name: Policy/Procedure; Incorrect
Follow up Medium Name: Surface water-Fresh
Follow up Source Nname: Construction site
Follow up Activity Name: Construction, other

Potential Details

Pot Resp Party First Name:
Pot Resp Prty Last Name: UNKNOWN
Potentially Resp Party Org: CITY OF YAKIMA

Follow up Comments

Follow up Comment:

ERTS Number 623974 - Randy: I was contacted on the phone today by Ray Latham of the Department of Ecology. Mr. Latham informed me that a City Water Truck and a private contractor had been cutting concrete by Michelsen's Packaging on 2nd Avenue near Yakima Avenue. The crew was washing the concrete cutting tailwater into the 2nd Avenue gutter which drained to a stormwater drain at the intersection of 2nd Avenue and Yakima Avenue. Mr. Latham said that neither the City crew nor the private contractor had installed a filter sock in the storm drain and that the crew was not aware that this was required. Mr. Latham said that the incident was entered into the Ecology Environmental Tracking System. This is not good.

I drove to the site and met Mr. Ron Davis from Interstate Sawing & Drilling. He was a private contractor working for Pendleton Paving, who had contracted with Michelsen Packaging to do the work. Apparently both he and the City crew were doing street pavement cutting. Jim Dees, City Wastewater Division, met me at the site. I observed that Mr. Latham had stopped the work in time for very little of the tailwaters to reach the Yakima Avenue storm drain, about a block and a half away from the street cutting area. Most of it remained onsite. I then called Wayne Deason, City Street Department, who brought over a City street sweeper and cleaned up the tailwaters at the location.

I then called Ray Latham back and informed him that the water had been cleaned up. I also informed him that this email would go out and City crews would be educated so this hopefully won't happen in the future.

This is a good opportunity to educate all City crews who may be doing street cutting, now and in the future, regarding stormwater and water quality State laws and City requirements. As you know, the City stormwater drains discharge to the Yakima River. The high pH content of street cutting tailwater is toxic to aquatic life. These discharges may constitute water quality violations.

Although the City construction stormwater permit does not go into effect until February 2011, City crews should be aware, educated, and provided with filters and proper equipment. Please address this with the appropriate departments, and keep me and Scott Schafer informed.

Thanks,
David Schneider, Assistant Manager
City of Yakima, Wastewater Division
509-249-6854

At about 2:30 PM on 12/10/2010 I observed that a street sweeper had cleaned the concrete cutting out of the curb on 2nd St.

This incident is closed.

Follow up Comment:

ERTS Number 623974 - Historic Investigator Contact Information - FirstName: RAY MiddleName: LastName: LATHAM OrganizationName: WATER QUALITY WorkLocation: CRO

Follow up Comment:

ERTS Number 623974 - Historic Referral Contact Information - ReferralDate: 2010-12-10 FirstName: RAY MiddleName: LastName: LATHAM Email: rlat461@ecy.wa.gov PhoneNumber: 509-575-2807 OrganizationName: WATER QUALITY WorkLocation: CRO

Initial Comments

Initial Report Comment:

ERTS Number 623974 - INFO RECEIVED BY EMAIL FROM RAY LATHAM, WQ:

Complaint is the city of Yakima is cutting concrete on 2nd Avenue. Concrete cuttings mixed with water are discharged down the gutter to the drain on the NW corner of 2nd Ave. and Yakima Avenue. A layer of mud approximately 1/2 in deep was in the gutter near the site of the cutting.
I (RAY LATHAM) approached the City`s service van and talked with Rich Peck. He was unaware that he needed to protect the drain from the discharge.

I came back to the office and called Arlene Carter, City Waste Water Division. She was out but I informed Dave Schneider, her supervisor of the problem. He said he would look into it and file an email reply.

Site: ***CSO Outfall 174***
2nd Ave NW Seattle WA

ERTS

Incident ID: 704685
Incident Date: 2021-03-02
County: King
Location: CSO Outfall 174
Latitude:
Longitude:

Initial Report Details

Initial Report Substance Name:	Sewage/Sludge
Initial Report Subst Catego:	Waste
Initial Report Subst Quanti:	6820
Initial Report Substance Unit:	U.S. gallons
Initial Report Medium Name:	Lake
Initial Report Medium Category:	Water
Initial Report Cause Category:	Equipment failure
Initial Report Cause Name:	Other-Equipment/Material failure
Initial Report Source Name:	Sewage/Collection system
Initial Report Source Category:	Facility
Initial Report Activity Name:	Construction
Initial Report Comment Desc:	Dry weather overflows occurred at SPU CSO Outfall

Follow up Details

ERTS Follow up No:	189190
Follow up Substance Name:	Sewage/Sludge
Follow up Substance Quantity:	6820
Follow up Subst Unit of Meas:	U.S. gallons
Follow up Cause Name:	Other-Equipment/Material failure
Follow up Medium Name:	Lake
Follow up Source Nname:	Sewage/Collection system
Follow up Activity Name:	Construction

Follow up Details

ERTS Follow up No:	189189
Follow up Substance Name:	
Follow up Substance Quantity:	

Follow up Subst Unit of Meas:
Follow up Cause Name: Other-Org/Management failure
Follow up Medium Name: Lake
Follow up Source Nname:
Follow up Activity Name: Construction

Follow up Details

ERTS Follow up No: 189188
Follow up Substance Name:
Follow up Substance Quantity:
Follow up Subst Unit of Meas:
Follow up Cause Name: Other-Equipment/Material failure
Follow up Medium Name:
Follow up Source Nname:
Follow up Activity Name: Construction

Follow up Details

ERTS Follow up No: 189187
Follow up Substance Name: Sewage/Sludge
Follow up Substance Quantity: 6820
Follow up Subst Unit of Meas: U.S. gallons
Follow up Cause Name: Other-Equipment/Material failure
Follow up Medium Name: Lake
Follow up Source Nname: Sewage/Collection system
Follow up Activity Name: Construction

Potential Details

Pot Resp Party First Name:
Pot Resp Prty Last Name:
Potentially Resp Party Org: Seattle Public Utilities (SPU)

Follow up Comments

Follow up Comment:

ERTS Number 704685 - Unpermitted discharge of wastewater - overflow from regulated CSO outfall during dry weather.

The city's NPDES permit (WA0031682) requires submission of a written follow up report within 5 business days of the initial report as well as submission of a summary report on a quarterly basis. Sewage overflows such as the one reported in this ERTS may trigger stipulated penalties under the city's CSO consent decree. Ecology and EPA will consider information from the 5-day and quarterly reports when making a final enforcement decision as part of our periodic CSO compliance reviews.

Initial Comments

Initial Report Comment:

ERTS Number 704685 - Dry weather overflows occurred at SPU CSO Outfall 174. A pump and bypass system operated by the Ship Canal Water Quality Facility contractor exceeded the capacity of the downstream system which overflowed during dry weather on 3 occasions. The overflow volume, date, time, and duration for each overflow is as follows: 1,320 gallons on 3/2/21 at 13:25 for a duration of 5 minutes; 1,880 gallons on 3/9/21 at 7:55 for a duration of 5 mins; and 3,620 gallons on 3/12/21 at 7:55 for a duration of 5 mins.

Site:
2ND STREET KENT WA

ERTS

Incident ID: 426213
Incident Date:
County: KING
Location:

Latitude:
Longitude:

Initial Report Details

Initial Report Substance Name: Other
Initial Report Subst Catego: Oil
Initial Report Subst Quanti:
Initial Report Substance Unit:
Initial Report Medium Name: Soil
Initial Report Medium Category: Ground
Initial Report Cause Category: Human error
Initial Report Cause Name: Judgment
Initial Report Source Name: Commercial/Industrial facility
Initial Report Source Category: Facility
Initial Report Activity Name: Other
Initial Report Comment Desc: REFERRED FROM CRIMINAL INVESTIGATOR. REPORTS OF EX

Follow up Details

ERTS Follow up No: 79126
Follow up Substance Name: Other
Follow up Substance Quantity:
Follow up Subst Unit of Meas:
Follow up Cause Name: Judgment
Follow up Medium Name: Soil
Follow up Source Nname: Commercial/Industrial facility
Follow up Activity Name: Other

Potential Details

Pot Resp Party First Name:
Pot Resp Prty Last Name:
Potentially Resp Party Org: WELDCO -BEAL

Follow up Comments

Follow up Comment:

ERTS Number 426213 - SEE ERTS 425795

Follow up Comment:

ERTS Number 426213 - Historic Investigator Contact Information - FirstName: DONNA MiddleName: K LastName: MUSA TCP OrganizationName: TOXICS CLEANUP WorkLocation: NWRO

Follow up Comment:

ERTS Number 426213 - Historic Referral Contact Information - ReferralDate: 1997-02-03 FirstName: MiddleName: LastName: GALLAGHER Email: PhoneNumber: OrganizationName: TOXICS CLEANUP WorkLocation: NWRO

Site: ***COTTAGE PROPERTIES***
VINE ST SEATTLE WA 98121

ICR

Cleanup Site ID: 4828
Facility Site ID: 55774658
Site Status: No Further Action Required
Statute: MTCA
Rank:
Rank Description:
Has Env Covenant:
Is Brownfiled Site:
Is PSI Site: Yes

WRIA ID: 8
Is NFA Site: Yes
Responsible Unit: Northwest
Latitude: 47.614804999999997
Longitude: -122.349694
Legislative District: 36
Congr District: 7
County Name: King

Cleanup Activities

Related ID:
VCP Prj No:
Activity Name: Initial Investigation / Federal Preliminary

Start Date: 1999-11-10
End Date: 1999-11-15
Legal Mechanism:

	Assessment		
Activity Status:	Completed	***Performed by:***	Ecology
County Name:	King	***Project Manager:***	Polayes, Joanne
Applies to:	CleanupSite		
Applies to Description:			
Related ID:		***Start Date:***	2008-02-27
VCP Prj No:		***End Date:***	2008-09-17
Activity Name:	Site Hazard Assessment/Federal Site Inspection	***Legal Mechanism:***	
Activity Status:	Completed	***Performed by:***	Local Government
County Name:	King	***Project Manager:***	County Health-NW
Applies to:	CleanupSite		
Applies to Description:			
Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	2008-09-17
Activity Name:	Site Status Changed to NFA	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	
Applies to:	CleanupSite		
Applies to Description:			
Related ID:		***Start Date:***	
VCP Prj No:		***End Date:***	1999-11-10
Activity Name:	Site Discovery/Release Report Received	***Legal Mechanism:***	
Activity Status:		***Performed by:***	
County Name:	King	***Project Manager:***	Polayes, Joanne
Applies to:	CleanupSite		
Applies to Description:			

Media Contaminants

Contaminant Type:	Metals Priority Pollutants	***Sediment:***	
Groundwater:		***Sediment Desc.:***	
Groundwater Desc.:		***Air:***	
Surface Water:		***Air Desc.:***	
Surfacewater Desc.:		***Bedrock:***	
Soil:	C	***Bedrock Desc.:***	
Soil Desc.:	Confirmed Above Cleanup Level	***County Name:***	King

---

Site:

2ND AVE SEATTLE WA SPILLS

Incident ID:	646062	***Location:***	
Incident Date:		***Address:***	2ND AVE
Latitude:		***City:***	SEATTLE
Longitude:		***County:***	KING

Spill Information

Incident Date:	1/4/2014
Latitude:	47.60897
Longitude:	122.33892

Spill Details Historical

Material:	PETROLEUM - HYDRAULIC OIL	***Source:***	TRANSPORTATION-VEHICLE TRUCK
Qty:	1	***Sheen Only:***	0
Medium:	IMPERMEABLE CONTAINMENT	***Waterway:***	NULL
Impact:	CONTAMINATED ROADWAY/PARKING LOT	***Prp Business Name:***	CLEANSCAPES
Cause:	NULL	***Prp First Name:***	NULL
Activity:	Underway/Transiting/Pipeline in Operation	***Prp Last Name:***	NULL

Site:

2ND AVE S SEATTLE WA SPILLS

Incident ID: 624269
Incident Date:
Latitude:
Longitude:

Location:
Address: 2ND AVE S
City: SEATTLE
County: KING

Spill Information

Incident Date: 12/29/2010
Latitude: NULL
Longitude: NULL

Spill Details Historical

Material: PETROLEUM - UNKNOWN
Qty: NULL
Medium: IMPERMEABLE CONTAINMENT
Impact: POTENTIAL POLLUTION/RELEASE
Cause: NULL
Activity: UNKNOWN

Source: TRANSPORTATION-VEHICLE TRUCK
Sheen Only: 0
Waterway: NULL
Prp Business Name: NORTHLAND SERVICE FUEL
Prp First Name: NULL
Prp Last Name: NULL

Site:
2ND AVE YAKIMA WA

SPILLS

Incident ID: 623974
Incident Date:
Latitude:
Longitude:

Location:
Address: 2ND AVE
City: YAKIMA
County: YAKIMA

Spill Information

Incident Date: 12/10/2010
Latitude: NULL
Longitude: NULL

Spill Details Historical

Material: WASTE WATER
Qty: NULL
Medium: SURFACE WATER-FRESH
Impact: WATER POLLUTION
Cause: IMPROPER PROCEDURE
Activity: OTHER CONSTRUCTION

Source: CONSTRUCTION SITE
Sheen Only: 0
Waterway: NULL
Prp Business Name: CITY OF YAKIMA
Prp First Name: NULL
Prp Last Name: UNKNOWN

Site:
WESTERN AVE SEATTLE WA

SPILLS

Incident ID: 529378
Incident Date:
Latitude:
Longitude:

Location:
Address: WESTERN AVE
City: SEATTLE
County: KING

Spill Information

Incident Date: 10/2/2002
Latitude: NULL
Longitude: NULL

Spill Details Historical

Material: PETROLEUM - DIESEL FUEL
Qty: 5
Medium: OTHER
Impact: NONE
Cause: EQUIPMENT FAILURE

Source: OTHER
Sheen Only: 0
Waterway: ELLIOTT BAY
Prp Business Name: EMERALD SERVICES
Prp First Name: NULL

Activity:	OTHER CONSTRUCTION	***Prp Last Name:***	NULL

Site:
DENNY RD SEATTLE WA

SPILLS

Incident ID:	646897	***Location:***	
Incident Date:		***Address:***	DENNY RD
Latitude:		***City:***	SEATTLE
Longitude:		***County:***	KING

Spill Information

Incident Date:	2/16/2014
Latitude:	NULL
Longitude:	NULL

Spill Information

Incident Date:	2/16/2014
Latitude:	NULL
Longitude:	NULL

Spill Information

Incident Date:	2/16/2014
Latitude:	NULL
Longitude:	NULL

Spill Information

Incident Date:	2/16/2014
Latitude:	47.618607
Longitude:	122.330374

Spill Information

Incident Date:	2/16/2014
Latitude:	47.618607
Longitude:	122.330374

Spill Information

Incident Date:	2/16/2014
Latitude:	47.618607
Longitude:	122.330374

Spill Information

Incident Date:	2/16/2014
Latitude:	47.618607
Longitude:	122.330374

Spill Information

Incident Date:	2/16/2014
Latitude:	47.618607
Longitude:	122.330374

Spill Information

Incident Date:	2/16/2014
Latitude:	47.618607

Longitude: 122.330374

Spill Information

Incident Date: 2/16/2014
Latitude: 47.618607
Longitude: 122.330374

Spill Information

Incident Date: 2/16/2014
Latitude: 47.618607
Longitude: 122.330374

Spill Information

Incident Date: 2/16/2014
Latitude: NULL
Longitude: NULL

Spill Information

Incident Date: 2/16/2014
Latitude: NULL
Longitude: NULL

Spill Information

Incident Date: 2/16/2014
Latitude: NULL
Longitude: NULL

Spill Information

Incident Date: 2/16/2014
Latitude: NULL
Longitude: NULL

Spill Information

Incident Date: 2/16/2014
Latitude: NULL
Longitude: NULL

Spill Details Historical

Material: PETROLEUM - DIESEL FUEL
Qty: 5
Medium: IMPERMEABLE CONTAINMENT
Impact: CONTAMINATED ROADWAY/PARKING LOT
Cause: NULL
Activity: Underway/Transiting/Pipeline in Operation
Source: TRANSPORTATION-VEHICLE TRUCK
Sheen Only: 0
Waterway: NULL
Prp Business Name: SYSCO
Prp First Name: JOHN
Prp Last Name: FRASER

Spill Details Historical

Material: PETROLEUM - DIESEL FUEL
Qty: 5
Medium: IMPERMEABLE CONTAINMENT
Impact: CONTAMINATED ROADWAY/PARKING LOT
Cause: NULL
Activity: Underway/Transiting/Pipeline in Operation
Source: TRANSPORTATION-VEHICLE TRUCK
Sheen Only: 0
Waterway: NULL
Prp Business Name: SYSCO
Prp First Name: JOHN
Prp Last Name: FRASER

Spill Details Historical

Material:	PETROLEUM - DIESEL FUEL	***Source:***	TRANSPORTATION-VEHICLE TRUCK
Qty:	5	***Sheen Only:***	0
Medium:	SURFACE WATER-FRESH	***Waterway:***	NULL
Impact:	CONTAMINATED ROADWAY/PARKING LOT	***Prp Business Name:***	SYSCO
Cause:	NULL	***Prp First Name:***	JOHN
Activity:	Underway/Transiting/Pipeline in Operation	***Prp Last Name:***	FRASER

Spill Details Historical

Material:	PETROLEUM - DIESEL FUEL	***Source:***	TRANSPORTATION-VEHICLE TRUCK
Qty:	5	***Sheen Only:***	0
Medium:	SURFACE WATER-FRESH	***Waterway:***	NULL
Impact:	CONTAMINATED ROADWAY/PARKING LOT	***Prp Business Name:***	SYSCO
Cause:	NULL	***Prp First Name:***	JOHN
Activity:	Underway/Transiting/Pipeline in Operation	***Prp Last Name:***	FRASER

Spill Details Historical

Material:	PETROLEUM - DIESEL FUEL	***Source:***	TRANSPORTATION-VEHICLE TRUCK
Qty:	5	***Sheen Only:***	0
Medium:	IMPERMEABLE CONTAINMENT	***Waterway:***	NULL
Impact:	WATER POLLUTION	***Prp Business Name:***	SYSCO
Cause:	NULL	***Prp First Name:***	JOHN
Activity:	Underway/Transiting/Pipeline in Operation	***Prp Last Name:***	FRASER

Spill Details Historical

Material:	PETROLEUM - DIESEL FUEL	***Source:***	TRANSPORTATION-VEHICLE TRUCK
Qty:	5	***Sheen Only:***	0
Medium:	IMPERMEABLE CONTAINMENT	***Waterway:***	NULL
Impact:	WATER POLLUTION	***Prp Business Name:***	SYSCO
Cause:	NULL	***Prp First Name:***	JOHN
Activity:	Underway/Transiting/Pipeline in Operation	***Prp Last Name:***	FRASER

Spill Details Historical

Material:	PETROLEUM - DIESEL FUEL	***Source:***	TRANSPORTATION-VEHICLE TRUCK
Qty:	5	***Sheen Only:***	0
Medium:	SURFACE WATER-FRESH	***Waterway:***	NULL
Impact:	WATER POLLUTION	***Prp Business Name:***	SYSCO
Cause:	NULL	***Prp First Name:***	JOHN
Activity:	Underway/Transiting/Pipeline in Operation	***Prp Last Name:***	FRASER

Spill Details Historical

Material:	PETROLEUM - DIESEL FUEL	***Source:***	TRANSPORTATION-VEHICLE TRUCK
Qty:	5	***Sheen Only:***	0
Medium:	SURFACE WATER-FRESH	***Waterway:***	NULL
Impact:	WATER POLLUTION	***Prp Business Name:***	SYSCO
Cause:	NULL	***Prp First Name:***	JOHN
Activity:	Underway/Transiting/Pipeline in Operation	***Prp Last Name:***	FRASER

Spill Details Historical

Material:	PETROLEUM - DIESEL FUEL	***Source:***	TRANSPORTATION-VEHICLE TRUCK
Qty:	5	***Sheen Only:***	0
Medium:	IMPERMEABLE CONTAINMENT	***Waterway:***	NULL
Impact:	CONTAMINATED ROADWAY/PARKING LOT	***Prp Business Name:***	SYSCO PORTLAND
Cause:	NULL	***Prp First Name:***	NULL
Activity:	Underway/Transiting/Pipeline in Operation	***Prp Last Name:***	NULL

Spill Details Historical

Material:	PETROLEUM - DIESEL FUEL	***Source:***	TRANSPORTATION-VEHICLE TRUCK

Qty:	5	***Sheen Only:***	0
Medium:	IMPERMEABLE CONTAINMENT	***Waterway:***	NULL
Impact:	CONTAMINATED ROADWAY/PARKING LOT	***Prp Business Name:***	SYSCO PORTLAND
Cause:	NULL	***Prp First Name:***	NULL
Activity:	Underway/Transiting/Pipeline in Operation	***Prp Last Name:***	NULL

Spill Details Historical

Material:	PETROLEUM - DIESEL FUEL	***Source:***	TRANSPORTATION-VEHICLE TRUCK
Qty:	5	***Sheen Only:***	0
Medium:	SURFACE WATER-FRESH	***Waterway:***	NULL
Impact:	CONTAMINATED ROADWAY/PARKING LOT	***Prp Business Name:***	SYSCO PORTLAND
Cause:	NULL	***Prp First Name:***	NULL
Activity:	Underway/Transiting/Pipeline in Operation	***Prp Last Name:***	NULL

Spill Details Historical

Material:	PETROLEUM - DIESEL FUEL	***Source:***	TRANSPORTATION-VEHICLE TRUCK
Qty:	5	***Sheen Only:***	0
Medium:	SURFACE WATER-FRESH	***Waterway:***	NULL
Impact:	CONTAMINATED ROADWAY/PARKING LOT	***Prp Business Name:***	SYSCO PORTLAND
Cause:	NULL	***Prp First Name:***	NULL
Activity:	Underway/Transiting/Pipeline in Operation	***Prp Last Name:***	NULL

Spill Details Historical

Material:	PETROLEUM - DIESEL FUEL	***Source:***	TRANSPORTATION-VEHICLE TRUCK
Qty:	5	***Sheen Only:***	0
Medium:	IMPERMEABLE CONTAINMENT	***Waterway:***	NULL
Impact:	WATER POLLUTION	***Prp Business Name:***	SYSCO PORTLAND
Cause:	NULL	***Prp First Name:***	NULL
Activity:	Underway/Transiting/Pipeline in Operation	***Prp Last Name:***	NULL

Spill Details Historical

Material:	PETROLEUM - DIESEL FUEL	***Source:***	TRANSPORTATION-VEHICLE TRUCK
Qty:	5	***Sheen Only:***	0
Medium:	IMPERMEABLE CONTAINMENT	***Waterway:***	NULL
Impact:	WATER POLLUTION	***Prp Business Name:***	SYSCO PORTLAND
Cause:	NULL	***Prp First Name:***	NULL
Activity:	Underway/Transiting/Pipeline in Operation	***Prp Last Name:***	NULL

Spill Details Historical

Material:	PETROLEUM - DIESEL FUEL	***Source:***	TRANSPORTATION-VEHICLE TRUCK
Qty:	5	***Sheen Only:***	0
Medium:	SURFACE WATER-FRESH	***Waterway:***	NULL
Impact:	WATER POLLUTION	***Prp Business Name:***	SYSCO PORTLAND
Cause:	NULL	***Prp First Name:***	NULL
Activity:	Underway/Transiting/Pipeline in Operation	***Prp Last Name:***	NULL

Site: ***ELLIOTT BAY***
WESTERN AVE SEATTLE WA

SPILLS

Incident ID:	529378	***Location:***	ELLIOTT BAY
Incident Date:	10/2/2002	***Address:***	WESTERN AVE

Latitude:	NULL	***City:***	SEATTLE
Longitude:	NULL	***County:***	KING

Site:

3RD AVENUE SEATTLE WA

SPILLS

Incident ID:	633802	***Location:***	
Incident Date:		***Address:***	3RD AVENUE
Latitude:		***City:***	SEATTLE
Longitude:		***County:***	KING

Spill Information

Incident Date:	5/11/2012
Latitude:	NULL
Longitude:	NULL

Spill Details Historical

Material:	PETROLEUM - OIL OTHER	***Source:***	Other - Vehicle
Qty:	4	***Sheen Only:***	0
Medium:	IMPERMEABLE CONTAINMENT	***Waterway:***	NULL
Impact:	NONE	***Prp Business Name:***	KING COUNTY METRO
Cause:	NULL	***Prp First Name:***	TALON
Activity:	UNKNOWN	***Prp Last Name:***	SWANSON

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ERIS updates databases as set out in ASTM Standard E1527-13 and E1527-21, Section 8.1.8 Sources of Standard Source Information:

"Government information from nongovernmental sources may be considered current if the source updates the information at least every 90 days, or, for information that is updated less frequently than quarterly by the government agency, within 90 days of the date the government agency makes the information available to the public."

Standard Environmental Record Sources

Federal

Formerly Utilized Sites Remedial Action Program: DOE FUSRAP

The U.S. Department of Energy (DOE) established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from the Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations. The DOE Office of Legacy Management (LM) established long-term surveillance and maintenance (LTS&M) requirements for remediated FUSRAP sites. DOE evaluates the final site conditions of a remediated site on the basis of risk for different future uses. DOE then confirms that LTS&M requirements will maintain protectiveness.

Government Publication Date: Mar 4, 2017

National Priority List: NPL

Sites on the United States Environmental Protection Agency (EPA)'s National Priorities List of the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program. The NPL, which EPA is required to update at least once a year, is based primarily on the score a site receives from EPA's Hazard Ranking System. A site must be on the NPL to receive money from the Superfund Trust Fund for remedial action. Sites are represented by boundaries where available in the EPA Superfund Site Boundaries maintained by the Shared Enterprise Geodata and Services (SEGS). Site boundaries represent the footprint of a whole site, the sum of all of the Operable Units and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: May 25, 2022

National Priority List - Proposed: PROPOSED NPL

Sites proposed - by the EPA, the state agency, or concerned citizens - for addition to the NPL due to contamination by hazardous waste and identified by the Environmental Protection Agency (EPA) as a candidate for cleanup because it poses a risk to human health and/or the environment. Sites are represented by boundaries where available in the EPA Superfund Site Boundaries maintained by the Shared Enterprise Geodata and Services (SEGS). Site boundaries represent the footprint of a whole site, the sum of all of the Operable Units and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: May 25, 2022

Deleted NPL: DELETED NPL

Sites deleted from the United States Environmental Protection Agency (EPA)'s National Priorities List. The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate. Sites are represented by boundaries where available in the EPA Superfund Site Boundaries maintained by the Shared Enterprise Geodata and Services (SEGS). Site boundaries represent the footprint of a whole site, the sum of all of the Operable Units and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: May 25, 2022

SEMS List 8R Active Site Inventory: SEMS

The Superfund Program has deployed the Superfund Enterprise Management System (SEMS), which integrates multiple legacy systems into a comprehensive tracking and reporting tool. This inventory contains active sites evaluated by the Superfund program that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The Active Site Inventory Report displays site and location information at active SEMS sites. An active site is one at which site assessment, removal, remedial, enforcement, cost recovery, or oversight activities are being planned or conducted.

Government Publication Date: Jun 30, 2022

Inventory of Open Dumps, June 1985: ODI

The Resource Conservation and Recovery Act (RCRA) provides for publication of an inventory of open dumps. The Act defines "open dumps" as facilities which do not comply with EPA's "Criteria for Classification of Solid Waste Disposal Facilities and Practices" (40 CFR 257).

Government Publication Date: Jun 1985

SEMS List 8R Archive Sites: SEMS ARCHIVE

The Superfund Enterprise Management System (SEMS) Archived Site Inventory displays site and location information at sites archived from SEMS. An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time.

Government Publication Date: Jun 30, 2022

Comprehensive Environmental Response, Compensation and Liability Information System - CERCLIS: CERCLIS

Superfund is a program administered by the United States Environmental Protection Agency (EPA) to locate, investigate, and clean up the worst hazardous waste sites throughout the United States. CERCLIS is a database of potential and confirmed hazardous waste sites at which the EPA Superfund program has some involvement. It contains sites that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The EPA administers the Superfund program in cooperation with individual states and tribal governments; this database is made available by the EPA.

Government Publication Date: Oct 25, 2013

EPA Report on the Status of Open Dumps on Indian Lands: IODI

Public Law 103-399, The Indian Lands Open Dump Cleanup Act of 1994, enacted October 22, 1994, identified congressional concerns that solid waste open dump sites located on American Indian or Alaska Native (AI/AN) lands threaten the health and safety of residents of those lands and contiguous areas. The purpose of the Act is to identify the location of open dumps on Indian lands, assess the relative health and environment hazards posed by those sites, and provide financial and technical assistance to Indian tribal governments to close such dumps in compliance with Federal standards and regulations or standards promulgated by Indian Tribal governments or Alaska Native entities.

Government Publication Date: Dec 31, 1998

CERCLIS - No Further Remedial Action Planned: CERCLIS NFRAP

An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. The Archive designation means that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL). This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Government Publication Date: Oct 25, 2013

CERCLIS Liens: CERCLIS LIENS

A Federal Superfund lien exists at any property where EPA has incurred Superfund costs to address contamination ("Superfund site") and has provided notice of liability to the property owner. A Federal CERCLA ("Superfund") lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. This database is made available by the United States Environmental Protection Agency (EPA). This database was provided by the United States Environmental Protection Agency (EPA). Refer to SEMS LIEN as the current data source for Superfund Liens.

Government Publication Date: Jan 30, 2014

RCRA CORRACTS-Corrective Action: RCRA CORRACTS

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. At these sites, the Corrective Action Program ensures that cleanups occur. EPA and state regulators work with facilities and communities to design remedies based on the contamination, geology, and anticipated use unique to each site.

Government Publication Date: Jun 27, 2022

RCRA non-CORRACTS TSD Facilities: RCRA TSD

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. This database includes Non-Corrective Action sites listed as treatment, storage and/or disposal facilities of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA).

Government Publication Date: Jun 27, 2022

RCRA Generator List: RCRA LQG

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Large Quantity Generators (LQGs) generate 1,000 kilograms per month or more of hazardous waste or more than one kilogram per month of acutely hazardous waste.

Government Publication Date: Jun 27, 2022

RCRA Small Quantity Generators List: RCRA SQG

RCRA Info is the EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Small Quantity Generators (SQGs) generate more than 100 kilograms, but less than 1,000 kilograms, of hazardous waste per month.

Government Publication Date: Jun 27, 2022

RCRA Very Small Quantity Generators List: RCRA VSQG

RCRA Info is the EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Very Small Quantity Generators (VSQG) generate 100 kilograms or less per month of hazardous waste, or one kilogram or less per month of acutely hazardous waste. Additionally, VSQG may not accumulate more than 1,000 kilograms of hazardous waste at any time.

Government Publication Date: Jun 27, 2022

RCRA Non-Generators: RCRA NON GEN

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Non-Generators do not presently generate hazardous waste.

Government Publication Date: Jun 27, 2022

RCRA Sites with Controls: RCRA CONTROLS

List of Resource Conservation and Recovery Act (RCRA) facilities with institutional controls in place. RCRA gives the U.S. Environmental Protection Agency (EPA) the authority to control hazardous waste from the "cradle-to-grave." This includes the generation, transportation, treatment, storage, and disposal of hazardous waste. RCRA also set forth a framework for the management of non-hazardous solid wastes. The 1986 amendments to RCRA enabled EPA to address environmental problems that could result from underground tanks storing petroleum and other hazardous substances.

Government Publication Date: Jun 27, 2022

Federal Engineering Controls-ECs: FED ENG

Engineering controls (ECs) encompass a variety of engineered and constructed physical barriers (e.g., soil capping, sub-surface venting systems, mitigation barriers, fences) to contain and/or prevent exposure to contamination on a property. This database is made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: May 25, 2022

Federal Institutional Controls- ICs: FED INST

Institutional controls are non-engineered instruments, such as administrative and legal controls, that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy. Although it is EPA's (United States Environmental Protection Agency) expectation that treatment or engineering controls will be used to address principal threat wastes and that groundwater will be returned to its beneficial use whenever practicable, ICs play an important role in site remedies because they reduce exposure to contamination by limiting land or resource use and guide human behavior at a site.

Government Publication Date: May 25, 2022

Land Use Control Information System: LUCIS

The LUCIS database is maintained by the U.S. Department of the Navy and contains information for former Base Realignment and Closure (BRAC) properties across the United States.

Government Publication Date: Sep 1, 2006

Institutional Control Boundaries at NPL sites: NPL IC

Boundaries of Institutional Control areas at sites on the United States Environmental Protection Agency (EPA)'s National Priorities List, or Proposed or Deleted, made available by the EPA's Shared Enterprise Geodata and Services (SEGS). United States Environmental Protection Agency (EPA)'s National Priorities List of the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program. Institutional controls are non-engineered instruments such as administrative and legal controls that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy.

Government Publication Date: May 25, 2022

Emergency Response Notification System: ERNS 1982 TO 1986

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1982-1986

Emergency Response Notification System: ERNS 1987 TO 1989

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1987-1989

Emergency Response Notification System: ERNS

Database of oil and hazardous substances spill reports made available by the United States Coast Guard National Response Center (NRC). The NRC fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. These data contain initial incident data that has not been validated or investigated by a federal/state response agency.

Government Publication Date: Jun 5, 2022

The Assessment, Cleanup and Redevelopment Exchange System (ACRES) Brownfield Database: FED BROWNFIELDS

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties protects the environment, reduces blight, and takes development pressures off greenspaces and working lands. This database is made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Aug 20, 2021

FEMA Underground Storage Tank Listing: FEMA UST

The Federal Emergency Management Agency (FEMA) of the Department of Homeland Security maintains a list of FEMA owned underground storage tanks.

Government Publication Date: Dec 31, 2017

Facility Response Plan: FRP

List of facilities that have submitted Facility Response Plans (FRP) to EPA. Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit Facility Response Plans (FRPs). Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments.

Government Publication Date: Dec 31, 2021

Delisted Facility Response Plans: DELISTED FRP

Facilities that once appeared in - and have since been removed from - the list of facilities that have submitted Facility Response Plans (FRP) to EPA. Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit Facility Response Plans (FRPs). Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments.

Government Publication Date: Dec 31, 2021

Historical Gas Stations: HIST GAS STATIONS

This historic directory of service stations is provided by the Cities Service Company. The directory includes Cities Service filling stations that were located throughout the United States in 1930.

Government Publication Date: Jul 1, 1930

Petroleum Refineries: REFN

List of petroleum refineries from the U.S. Energy Information Administration (EIA) Refinery Capacity Report. Includes operating and idle petroleum refineries (including new refineries under construction) and refineries shut down during the previous year located in the 50 States, the District of Columbia, Puerto Rico, the Virgin Islands, Guam, and other U.S. possessions. Survey locations adjusted using public data.

Government Publication Date: Feb 4, 2022

Petroleum Product and Crude Oil Rail Terminals: BULK TERMINAL

List of petroleum product and crude oil rail terminals made available by the U.S. Energy Information Administration (EIA). Includes operable bulk petroleum product terminals located in the 50 States and the District of Columbia with a total bulk shell storage capacity of 50,000 barrels or more, and/or the ability to receive volumes from tanker, barge, or pipeline; also rail terminals handling the loading and unloading of crude oil that were active between 2017 and 2018. Petroleum product terminals comes from the EIA-815 Bulk Terminal and Blender Report, which includes working, shell in operation, and shell idle for several major product groupings. Survey locations adjusted using public data.

Government Publication Date: Feb 4, 2022

LIEN on Property: SEMS LIEN

The EPA Superfund Enterprise Management System (SEMS) provides LIEN information on properties under the EPA Superfund Program.

Government Publication Date: Jun 30, 2022

Superfund Decision Documents: SUPERFUND ROD

This database contains a listing of decision documents for Superfund sites. Decision documents serve to provide the reasoning for the choice of (or) changes to a Superfund Site cleanup plan. The decision documents include Records of Decision (ROD), ROD Amendments, Explanations of Significant Differences (ESD), along with other associated memos and files. This information is maintained and made available by the US EPA (Environmental Protection Agency).

Government Publication Date: Jul 26, 2022

State

Hazardous Sites List: HSL

Washington State Department of Ecology (DEC) records of sites that have been assessed and ranked using the Washington Ranking Method (WARM score) - a number between 1 and 5, where a score of 1 represents the highest level of risk and 5 the lowest. Some factors that enter into site hazard ranking include: the amount and type of contaminants present; how easily contaminants could come into contact with people and the environment; and the level of public concern. This database is state equivalent NPL.

Government Publication Date: Aug 22, 2022

Confirmed and Suspected Contaminated Sites List: CSCSL

Confirmed & Suspected Contaminated Sites List made available by the Washington State Department of Ecology (DEC). This database is state equivalent CERCLIS.

Government Publication Date: Aug 22, 2022

Delisted Confirmed and Suspected Contaminated Sites: DELISTED SHWS

This database contains a list of Confirmed & Suspected Contaminated Sites that were removed from the Washington State Department of Ecology (DEC).

Government Publication Date: Aug 22, 2022

No Further Action Sites List: CSCSL NFA

A list of sites previously on the Washington State Department of Ecology (DEC) Confirmed and Suspected Contaminated Sites List (CSCSL) that have received a No Further Action (NFA) determination.

Government Publication Date: Aug 22, 2022

Solid Waste Facility Database: SWF/LF

List of permitted solid waste and landfill facilities made available by the Washington Department of Ecology (DEC).

Government Publication Date: Sep 8, 2022

Recycling Facilities: RECYCLERS

The Washington State Department of Ecology maintains this database of recycling opportunities available in Washington State.

Government Publication Date: Sep 16, 2020

Solid Waste Tire Facilities: WASTE TIRE

The Washington State Department of Ecology maintains this database of waste tire recycling opportunities available in Washington State.

Government Publication Date: Jun 9, 2020

Leaking Underground Storage Tank (LUST) List: LUST

Leaking Underground Storage Tank (LUST) list made available by the Washington Department of Ecology (DEC) contains information about underground storage tank facilities that require cleanup and their cleanup history.

Government Publication Date: Aug 22, 2022

Petroleum Technical Assistance Program: LUST PTAP

Under the State of Washington's cleanup law, qualifying petroleum contaminated sites can apply for the Pollution Liability Insurance Agency's (PLIA) Petroleum Technical Assistance Program (PTAP). Sites under the PTAP may be provided with informal advice and technical assistance on the requirements of the Model Toxics Control Act (MTCA), which is the state's cleanup law. PLIA also provides written opinions on independent remedial actions on qualifying petroleum cleanup sites: No Further Action (NFA), Further Action (FA), and Partial Sufficiency (PS).

Government Publication Date: Jun 21, 2022

UST Loan and Grant Program: UST LOAN

List of sites that have applied to the Pollution Liability Insurance Agency's (PLIA) UST Loan and Grant Program. PLIA partners with the Washington State Department of Health (DOH) to provide loans or grants to owners or operators of underground storage tank (UST) facilities, who wish to: upgrade/replace infrastructure, clean up contamination, or close a UST. Within the program, PLIA provides oversight and technical assistance, while the DOH operates the lending/repayment process.

Government Publication Date: Nov 12, 2021

Heating Oil Technical Assistance Program: LST HOT

Within the Pollution Liability Insurance Agency's (PLIA) various programs, the Heating Oil Technical Assistance Program (HOTAP) provides assistance to owners and operators of active and abandoned heating oil tanks if there is a suspected release or contamination. PLIA provides services including: written opinions, observations of testing, site assessments, and reviews of the results of reports and other appropriate activities. Information in some records has been redacted by the Pollution Liability Insurance Agency under Washington State Legislature RCW 70.149.080. As of March 4, 2022 the PLIA stopped maintaining this list.

Government Publication Date: Jun 22, 2022

Underground Storage Tanks: UST

List of Underground Storage Tanks (USTs) made available by Washington Department of Ecology (DEC). The DEC regulates tanks at facilities including gas stations, industries, commercial properties and governmental entities. The DEC works to ensure these tanks are installed, managed, and monitored in a manner that prevents releases into the environment.

Government Publication Date: Aug 22, 2022

Delisted Leaking Storage Tanks: DELISTED LST

List of leaking storage tanks made available by the Washington Department of Ecology (DEC). A record would be removed if it violated the Facility Oil Handling Standards. This list contains all the records that been removed from the storage tank list.

Government Publication Date: Aug 22, 2022

Aboveground Storage Tanks: AST

List of aboveground storage tanks (ASTs) made available by the Washington Department of Ecology (DEC). This list includes many of the largest petroleum containing ASTs in Washington state, but there are many ASTs in many different types of services (including, for example, hydrocarbon storage), that are not subject to regulation and are not registered by the DEC. There is no inclusive AST regulation in Washington state, and the Department of Ecology ceased maintenance of this list in December 2015.

Government Publication Date: Dec 14, 2015

Spills Program Regulated Facilities: AST SPL PREV

List of Class 1, 2, 3, and 4 regulated facilities. The Washington Department of Ecology regulates the equipment and oil transfer, storage, and handling at facilities to ensure environmental and public health. Depending on their classification (Class 1 Large facilities such as refineries, refueling terminals, and pipelines; Class 2 and Class 3 facilities that transfer oil; and Class 4 Marinas and other facilities that transfer oil to non-recreation vessels with a fuel capacity of less than 10,500 gallons), these facilities are required to have some type of spill prevention plan.
Government Publication Date: Apr 14, 2022

Delisted Storage Tanks: DELISTED TNK
List of aboveground storage tanks made available by the Washington Department of Ecology (DEC). A record would be removed if it violated the Facility Oil Handling Standards. This list contains all the records that been removed from the storage tank list.
Government Publication Date: Aug 22, 2022

Environmental Covenants Institutional Controls: INST
List of sites that have institutional controls or environmental covenants (64.70 RCW Uniform Environmental Covenants Act) made available by the State of Washington Department of Ecology. Institutional controls are administrative or legal measures used to prevent activities that may compromise the integrity of a cleanup action. They are meant to prevent exposure to contamination remaining on site. Institutional controls may include environmental covenants (also known as 'deed restrictions'), zoning restrictions, public health advisories, or other administrative tools. The most common institutional control is an environmental covenant. Environmental covenants are legal recorded documents that typically limit certain uses of the property.
Government Publication Date: Aug 22, 2022

Voluntary Cleanup Program: VCP
List of sites under the Voluntary Cleanup Program (VCP) made available by the Washington Department of Ecology (DEC). The VCP is an option for cleaning up hazardous waste sites under the state's cleanup law.
Government Publication Date: Aug 22, 2022

Brownfields Program: BROWNFIELDS
List of Brownfields sites made available by the Washington Department of Ecology (DEC). Brownfield sites are abandoned or underused properties where potential liability due to environmental contamination and cleanup costs complicate re-development efforts.
Government Publication Date: Aug 22, 2022

Tribal

Leaking Underground Storage Tanks (LUSTs) on Indian Lands: INDIAN LUST
LUSTs on Tribal/Indian Lands in Region 10, which includes Washington.
Government Publication Date: Apr 20, 2022

Underground Storage Tanks (USTs) on Indian Lands: INDIAN UST
USTs on Tribal/Indian Lands in Region 10, which includes Washington.
Government Publication Date: Apr 20, 2022

Delisted Tribal Leaking Storage Tanks: DELISTED ILST
Leaking Underground Storage Tank facilities which have been removed from the Regional Tribal LUST lists made available by the EPA.
Government Publication Date: Apr 20, 2022

Delisted Tribal Underground Storage Tanks: DELISTED IUST
Underground Storage Tank facilities which have been removed from the Regional Tribal UST lists made available by the EPA.
Government Publication Date: Apr 20, 2022

County

Abandoned Landfill Study in King County: KING HIST LF
List of sites investigated in the King County Abandoned Landfill Study, which was conducted October through December of 1984 by the Health Department's Environmental Health Division for the purpose of determining if any public health problems existed at predetermined sites.
Government Publication Date: April 30, 1985

Abandoned Landfill Study in the City of Seattle: SEA HIST LF

List of sites investigated in the Seattle Abandoned Landfill Study, which was conducted in June and July of 1984 by the Health Department's Environmental Health Division for the purpose of making preliminary assessments of public health hazards.

Government Publication Date: Jul 30, 1984

Seattle-King County Abandoned Landfill Toxicity / Hazard Assessment Project: KING SKLF

The King County Abandoned Landfill Survey was conducted from October through December 1984 by the Health Department's Environmental Health Division at the request of the King County Council for the purpose of making preliminary assessments of public health hazards.

Government Publication Date: Apr 30, 1985

Seattle Underground Storage Tank (UST) - Residential: UST SEATTLE

A list of permits related to decommissioning of a residential heating oil tank made available by the Seattle Fire Department (SFD).

Government Publication Date: Jul 15, 2022

Additional Environmental Record Sources

Federal

Facility Registry Service/Facility Index: FINDS/FRS

The Facility Registry Service (FRS) is a centrally managed database that identifies facilities, sites, or places subject to environmental regulations or of environmental interest. FRS creates high-quality, accurate, and authoritative facility identification records through rigorous verification and management procedures that incorporate information from program national systems, state master facility records, and data collected from EPA's Central Data Exchange registrations and data management personnel. This list is made available by the Environmental Protection Agency (US EPA).

Government Publication Date: Nov 2, 2020

Toxics Release Inventory (TRI) Program: TRIS

The EPA's Toxics Release Inventory (TRI) is a database containing data on disposal or other releases of over 650 toxic chemicals from thousands of U. S. facilities and information about how facilities manage those chemicals through recycling, energy recovery, and treatment. One of TRI's primary purposes is to inform communities about toxic chemical releases to the environment.

Government Publication Date: Aug 24, 2021

Perfluorinated Alkyl Substances (PFAS) Releases: PFAS TRI

List of Toxics Release Inventory (TRI) facilities at which the reported chemical is a Per- or polyfluorinated alkyl substance (PFAS) included in the Environmental Protection Agency (EPA)'s consolidated PFAS Master List of PFAS Substances. The EPA's Toxics Release Inventory (TRI) is a database containing data on disposal or other releases of over 650 toxic chemicals from thousands of U.S. facilities and information about how facilities manage those chemicals through recycling, energy recovery, and treatment.

Government Publication Date: Aug 24, 2021

PFOA/PFOS Contaminated Sites: PFAS NPL

List of National Priorities List (NPL) and related Superfund Alternative Agreement (SAA) sites where PFOA or PFOS contaminants have been found in water and/or soil. The site listing is provided by the Federal Environmental Protection Agency (EPA).

Government Publication Date: Jul 18, 2022

Perfluorinated Alkyl Substances (PFAS) Water Quality: PFAS WATER

The Water Quality Portal (WQP) is a cooperative service sponsored by the United States Geological Survey (USGS), the Environmental Protection Agency (EPA), and the National Water Quality Monitoring Council (NWQMC). This listing includes records from the Water Quality Portal where the characteristic (environmental measurement) is in the Environmental Protection Agency (EPA)'s consolidated PFAS Master List of PFAS Substances.

Government Publication Date: Jul 20, 2020

SSEHRI PFAS Contamination Sites: PFAS SSEHRI

This PFAS Contamination Site Tracker database is compiled by the Social Science Environmental Health Research Institute (SSEHRI) at Northeastern University. According to the SSEHRI, the database records qualitative and quantitative data from each known site of PFAS contamination, including timeline of discovery, sources, levels, health impacts, community response, and government response. The goal of this database is to compile information and support public understanding of the rapidly unfolding issue of PFAS contamination. All data presented was extracted from government websites, news articles, or publicly available documents, and this is cited in the tracker. Disclaimer: The source conveys this database undergoes regular updates as new information becomes available, some sites may be missing and/or contain information that is incorrect or outdated, as well as their information represents all contamination sites SSEHRI is aware of, not all possible contamination sites. This data is not intended to be used for legal purposes. Limited location details are available with this data. Access the following for the most current informations https://pfasproject.com/pfas-contamination-site-tr acker/

Government Publication Date: Dec 12, 2019

National Response Center PFAS Spills: ERNS PFAS

National Response Center (NRC) calls from 1990 to the most recent complete calendar year where there is indication of Aqueous Film Forming Foam (AFFF) usage. NRC calls may reference AFFF usage in the "Material Involved" or "Incident Description" fields. Data made available by the US Environmental Protection Agency (EPA). Disclaimer: dataset may include initial or misidentified incident data not yet validated or investigated by a federal/state response agency.

Government Publication Date: Feb 23, 2022

Hazardous Materials Information Reporting System: HMIRS

US DOT - Department of Transportation Pipeline and Hazardous Materials Safety Administration (PHMSA) Incidents Reports Database taken from Hazmat Intelligence Portal, U.S. Department of Transportation.

Government Publication Date: Sep 1, 2020

National Clandestine Drug Labs: NCDL

The U.S. Department of Justice ("the Department") provides this data as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy.

Government Publication Date: Apr 30, 2022

Toxic Substances Control Act: TSCA

The Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule.

The CDR enables EPA to collect and publish information on the manufacturing, processing, and use of commercial chemical substances and mixtures (referred to hereafter as chemical substances) on the TSCA Chemical Substance Inventory (TSCA Inventory). This includes current information on chemical substance production volumes, manufacturing sites, and how the chemical substances are used. This information helps the Agency determine whether people or the environment are potentially exposed to reported chemical substances. EPA publishes submitted CDR data that is not Confidential Business Information (CBI).

Government Publication Date: Apr 11, 2019

Hist TSCA: HIST TSCA

The Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule.

The 2006 IUR data summary report includes information about chemicals manufactured or imported in quantities of 25,000 pounds or more at a single site during calendar year 2005. In addition to the basic manufacturing information collected in previous reporting cycles, the 2006 cycle is the first time EPA collected information to characterize exposure during manufacturing, processing and use of organic chemicals. The 2006 cycle also is the first time manufacturers of inorganic chemicals were required to report basic manufacturing information.

Government Publication Date: Dec 31, 2006

FTTS Administrative Case Listing: FTTS ADMIN

An administrative case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

FTTS Inspection Case Listing: FTTS INSP

An inspection case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

Potentially Responsible Parties List: PRP

Early in the cleanup process, the Environmental Protection Agency (EPA) conducts a search to find the potentially responsible parties (PRPs). EPA looks for evidence to determine liability by matching wastes found at the site with parties that may have contributed wastes to the site.

Government Publication Date: Jul 26, 2022

State Coalition for Remediation of Drycleaners Listing: SCRD DRYCLEANER

The State Coalition for Remediation of Drycleaners (SCRD) was established in 1998, with support from the U.S. Environmental Protection Agency (EPA) Office of Superfund Remediation and Technology Innovation. Coalition members are states with mandated programs and funding for drycleaner site remediation. Current members are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin. Since 2017, the SCRD no longer maintains this data, refer to applicable state source data where available.

Government Publication Date: Nov 08, 2017

Integrated Compliance Information System (ICIS): ICIS

The Integrated Compliance Information System (ICIS) is a system that provides information for the Federal Enforcement and Compliance (FE&C) and the National Pollutant Discharge Elimination System (NPDES) programs. The FE&C component supports the Environmental Protection Agency's (EPA) Civil Enforcement and Compliance program activities. These activities include Compliance Assistance, Compliance Monitoring and Enforcement. The NPDES program supports tracking of NPDES permits, limits, discharge monitoring data and other program reports.

Government Publication Date: Apr 30, 2022

Drycleaner Facilities: FED DRYCLEANERS

A list of drycleaner facilities from Enforcement and Compliance History Online (ECHO) online search. The Environmental Protection Agency (EPA) tracks facilities that possess NAIC and SIC codes that classify businesses as drycleaner establishments.

Government Publication Date: Jun 25, 2022

Delisted Drycleaner Facilities: DELISTED FED DRY

List of sites removed from the list of Drycleaner Facilities (sites in the EPA's Integrated Compliance Information System (ICIS) with NAIC or SIC codes identifying the business as a drycleaner establishment).

Government Publication Date: Jun 25, 2022

Formerly Used Defense Sites: FUDS

Formerly Used Defense Sites (FUDS) are properties that were formerly owned by, leased to, or otherwise possessed by and under the jurisdiction of the Secretary of Defense prior to October 1986, where the Department of Defense (DoD) is responsible for an environmental restoration. This list is published by the U.S. Army Corps of Engineers.

Government Publication Date: May 26, 2021

Former Military Nike Missile Sites: FORMER NIKE

This information was taken from report DRXTH-AS-IA-83A016 (Historical Overview of the Nike Missile System, 12/1984) which was performed by Environmental Science and Engineering, Inc. for the U.S. Army Toxic and Hazardous Materials Agency Assessment Division. The Nike system was deployed between 1954 and the mid-1970's. Among the substances used or stored on Nike sites were liquid missile fuel (JP-4); starter fluids (UDKH, aniline, and furfuryl alcohol); oxidizer (IRFNA); hydrocarbons (motor oil, hydraulic fluid, diesel fuel, gasoline, heating oil); solvents (carbon tetrachloride, trichloroethylene, trichloroethane, stoddard solvent); and battery electrolyte. The quantities of material a disposed of and procedures for disposal are not documented in published reports. Virtually all information concerning the potential for contamination at Nike sites is confined to personnel who were assigned to Nike sites. During deactivation most hardware was shipped to depot-level supply points. There were reportedly instances where excess materials were disposed of on or near the site itself at closure. There was reportedly no routine site decontamination.

Government Publication Date: Dec 2, 1984

PHMSA Pipeline Safety Flagged Incidents: PIPELINE INCIDENT

A list of flagged pipeline incidents made available by the U.S. Department of Transportation (US DOT) Pipeline and Hazardous Materials Safety Administration (PHMSA). PHMSA regulations require incident and accident reports for five different pipeline system types.

Government Publication Date: Jul 7, 2020

Material Licensing Tracking System (MLTS): MLTS

A list of sites that store radioactive material subject to the Nuclear Regulatory Commission (NRC) licensing requirements. This list is maintained by the NRC. As of September 2016, the NRC no longer releases location information for sites. Site locations were last received in July 2016.

Government Publication Date: May 11, 2021

Historic Material Licensing Tracking System (MLTS) sites: HIST MLTS

A historic list of sites that have inactive licenses and/or removed from the Material Licensing Tracking System (MLTS). In some cases, a site is removed from the MLTS when the state becomes an "Agreement State". An Agreement State is a State that has signed an agreement with the Nuclear Regulatory Commission (NRC) authorizing the State to regulate certain uses of radioactive materials within the State.

Government Publication Date: Jan 31, 2010

Mines Master Index File: MINES

The Master Index File (MIF) is provided by the United State Department of Labor, Mine Safety and Health Administration (MSHA). This file, which was originally created in the 1970's, contained many Mine-IDs that were invalid. MSHA removes invalid IDs from the MIF upon discovery. MSHA applicable data includes the following: all Coal and Metal/Non-Metal mines under MSHA's jurisdiction since 1/1/1970; mine addresses for all mines in the database except for Abandoned mines prior to 1998 from MSHA's legacy system (addresses may or may not correspond with the physical location of the mine itself); violations that have been assessed penalties as a result of MSHA inspections beginning on 1/1/2000; and violations issued as a result of MSHA inspections conducted beginning on 1/1/2000.

Government Publication Date: Aug 3, 2022

Surface Mining Control and Reclamation Act Sites: SMCRA

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by the Office of Surface Mining Reclamation and Enforcement (OSMRE) to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of Abandoned Mine Land (AML) impacts, as well as information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Government Publication Date: Aug 18, 2022

Mineral Resource Data System: MRDS

The Mineral Resource Data System (MRDS) is a collection of reports describing metallic and nonmetallic mineral resources throughout the world. Included are deposit name, location, commodity, deposit description, geologic characteristics, production, reserves, resources, and references. This database contains the records previously provided in the Mineral Resource Data System (MRDS) of USGS and the Mineral Availability System/Mineral Industry Locator System (MAS/MILS) originated in the U.S. Bureau of Mines, which is now part of USGS. The USGS has ceased systematic updates of the MRDS database with their focus more recently on deposits of critical minerals while providing a well-documented baseline of historical mine locations from USGS topographic maps.

Government Publication Date: Mar 15, 2016

Uranium Mill Tailings Radiation Control Act Sites: URANIUM

The Legacy Management Office of the Department of Energy (DOE) manages radioactive and chemical waste, environmental contamination, and hazardous material at over 100 sites across the U.S. The L.M. Office manages this database of sites registered under the Uranium Mill Tailings Control Act (UMTRCA).

Government Publication Date: Mar 4, 2017

Alternative Fueling Stations: ALT FUELS

List of alternative fueling stations made available by the US Department of Energy's Office of Energy Efficiency & Renewable Energy. Includes Biodiesel stations, Ethanol (E85) stations, Liquefied Petroleum Gas (Propane) stations, Ethanol (E85) stations, Natural Gas stations, Hydrogen stations, and Electric Vehicle Supply Equipment (EVSE). The National Renewable Energy Laboratory (NREL) obtains information about new stations from trade media, Clean Cities coordinators, a Submit New Station form on the Station Locator website, and through collaborating with infrastructure equipment and fuel providers, original equipment manufacturers (OEMs), and industry groups.

Government Publication Date: Aug 1, 2022

Superfunds Consent Decrees: CONSENT DECREES

A list of Superfund consent decrees made available by the Department of Justice, Environment & Natural Resources Division (ENRD).

Government Publication Date: May 18, 2022

Air Facility System: AFS

This EPA retired Air Facility System (AFS) dataset contains emissions, compliance, and enforcement data on stationary sources of air pollution. Regulated sources cover a wide spectrum; from large industrial facilities to relatively small operations such as dry cleaners. AFS does not contain data on facilities that are solely asbestos demolition and/or renovation contractors, or landfills. ECHO Clean Air Act data from AFS are frozen and reflect data as of October 17, 2014; the EPA retired this system for Clean Air Act stationary sources and transitioned to ICIS-Air.

Government Publication Date: Oct 17, 2014

Registered Pesticide Establishments: SSTS

List of active EPA-registered foreign and domestic pesticide-producing and device-producing establishments based on data from the Section Seven Tracking System (SSTS). The Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) Section 7 requires that facilities producing pesticides, active ingredients, or devices be registered. The list of establishments is made available by the EPA.
Government Publication Date: Mar 30, 2022

Polychlorinated Biphenyl (PCB) Transformers: PCBT
Locations of Transformers Containing Polychlorinated Biphenyls (PCBs) registered with the United States Environmental Protection Agency. PCB transformer owners must register their transformer(s) with EPA. Although not required, PCB transformer owners who have removed and properly disposed of a registered PCB transformer may notify EPA to have their PCB transformer de-registered. Data made available by EPA.
Government Publication Date: Oct 15, 2019

Polychlorinated Biphenyl (PCB) Notifiers: PCB
Facilities included in the national list of facilities that have notified the United States Environmental Protection Agency (EPA) of Polychlorinated Biphenyl (PCB) activities. Any company or person storing, transporting or disposing of PCBs or conducting PCB research and development must notify the EPA and receive an identification number.
Government Publication Date: Jul 28, 2022

State

Spills Incidents Sites: SPILLS
List of spills and/or releases reported to the Washington Department of Ecology (DEC).
Government Publication Date: Mar 10, 2022

Reported Spills to Water: SPILLS WATER
A list of reported spills to water of one gallon or more made available by the Washington Department of Ecology.
Government Publication Date: Apr 14, 2022

Facility/Site Identification System: ALL SITES
The Facility/Site Identification System made available by the Department of Ecology (DEC) provides a central repository of key information for each facility/site of interest to DEC. The DEC has defined a facility/site as an operation at a fixed location that is of interest to the agency because it has an active or potential impact upon the environment.
Government Publication Date: Jun 2, 2022

Environmental Report Tracking System (ERTS): ERTS
A list of incidents from the Environmental Report Tracking System (ERTS), used by various programs within the Washington Department of Ecology (DEC) to track incidents and activities. This list is made available by the Washington Department of Ecology (DEC).
Government Publication Date: Nov 22, 2021

Independent Cleanup Reports: ICR
List of facilities in remedial action reports received by the Washington Department of Ecology (DEC) from either the owner or operator of the site. These actions have been conducted without department oversight or approval and are not under an order or decree. Independent Cleanup is historical terminology for Voluntary Cleanup; this data is no longer updated, current records can be found in Voluntary Cleanup.
Government Publication Date: Nov 6, 2015

Registered Drycleaners List: DRYCLEANERS
A listing of registered drycleaner facilities maintained by the Department of Ecology.
Government Publication Date: Jul 12, 2022

Delisted Drycleaners: DELISTED DRYCLEANERS
Sites which once appeared on the list of registered drycleaner facilities made available by the Department of Ecology.
Government Publication Date: Jul 12, 2022

Tier 2 Report: TIER 2
List of facilities that report storage of hazardous chemicals or materials to the Department of Ecology's Hazardous Waste and Toxics Reduction Program under the Emergency Planning and Community Right to Know Act (EPCRA).
Government Publication Date: Dec 15, 2021

Clandestine Drug Lab Sites: CDL

A list of Clandestine Drug Lab sites made available by the Washington Department of Health.

Government Publication Date: Sep 8, 2021

Clandestine Drug Lab Sites - Historical Listing: HIST CDL

List of Clandestine Drug Lab sites reported to the Department of Health from local health departments. This list contains sites that are not in the current list.

Government Publication Date: until 2007

Air Permitted Facilities: AIR PERMITS

This list of air emissions inventory is a point source summary of individual inventories from facilities with air operating permits. This list is maintained by the Washington Department of Ecology.

Government Publication Date: Jun 10, 2019

Underground Injection Control Wells: UIC

The Water Quality Program of the Washington State Department of Ecology (DEC) maintains this water quality permit database that includes Underground Injection Control (UIC) wells. According to the DEC, UIC wells are manmade structures used to discharge fluids into the subsurface. Examples are drywells, infiltration trenches with perforated pipe, and any structure deeper than the widest surface dimension. The majority of UIC wells in Washington are used to manage storm water and sanitary waste, return water to the ground, and help clean up contaminated sites. The potential for groundwater contamination from injection wells depends upon well construction and location; quality of the fluids injected; and the geographic and hydrologic settings in which the injection occurs.

Government Publication Date: Oct 15, 2020

Tribal

No Tribal additional environmental record sources available for this State.

County

King County Illegal Drug Lab Cleanup Sites: CDL KING COUNTY

This list of illegal drug labs is maintained by the Seattle-King County Department of Public Health. Illegal drugs such as methamphetamine, ecstasy and methcathinone are made in clandestine labs. These illegal drug labs create a number of health hazards. Most of the drug labs, previously, reported to Public Health were making methamphetamine.

Government Publication Date: Sep 25, 2020

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.